OWNER: PICTON II LTD.
ADDRESS: C/O JET AVIATION
GENEVA AIRPORT CH-1215
PHONE: [redacted]
FAX: [redacted]

OPERATOR: PICTON II LTD.
ADDRESS: C/O JET AVIATION
GENEVA AIRPORT CH-1215
PHONE: [redacted]
FAX: [redacted]

ANALYST: DENNIS RUFFINI
EMAIL: [redacted]
[redacted]
WWW.CAMPSYSTEMS.COM
[redacted]

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

AIRCRAFT **SERIAL/REGNO:** 29273 (YG006)/VP-BBJ **MODEL:** 737-72UBJ REVISION 21 **MANUFACTURER:** BOEING COMPANY

DATES	LAST ACTUALS			CURRENT ACTUAL		
INSERVICE DATE: 08-OCT-1999	3753:19 A/C HRS	as of	30-JUN-2014	_____ A/C HRS	as of	____/____/_____
	922 AFL	as of	30-JUN-2014	_____ AFL	as of	____/____/_____
	3455:18 APH	as of	30-JUN-2014	_____ APH	as of	____/____/_____

APU **SERIAL/PART:** P-5180/3800702-1 **MODEL:** 131-9B **MANUFACTURER:** HONEYWELL

INSTALLED ON 25-JUN-2010	LAST ACTUALS			CURRENT ACTUAL		
3001 APU HRS	3455:18 APU HRS	as of	30-JUN-2014	_____ APU HRS	as of	____/____/_____
2487 APUS	2961 APUS	as of	30-JUN-2014	_____ APUS	as of	____/____/_____

ENGINE NO. 1 **SERIAL/PART:** 874437/CFM56-7B27/B3 **MODEL:** CFM56-7B27/B3 **MANUFACTURER:** CFM INTERNATIONAL, S.A.

INSTALLED ON 05-MAY-2011		LAST ACTUALS			CURRENT ACTUAL		
3556:48 ENG. HRS	3525:36 A/C HRS	3753:19 ENG. HRS	as of	30-JUN-2014	_____ ENG. HRS	as of	____/____/_____
821 ENC		886 ENC	as of	30-JUN-2014	_____ ENC	as of	____/____/_____

ENGINE NO. 2 **SERIAL/PART:** 874438/CFM56-7B27/B3 **MODEL:** CFM56-7B27/B3 **MANUFACTURER:** CFM INTERNATIONAL, S.A.

INSTALLED ON 08-OCT-1999		LAST ACTUALS			CURRENT ACTUAL		
44 ENG. HRS	44 A/C HRS	3753:19 ENG. HRS	as of	30-JUN-2014	_____ ENG. HRS	as of	____/____/_____
15 ENC		886 ENC	as of	30-JUN-2014	_____ ENC	as of	____/____/_____

BOEING AND BBJ ARE TRADEMARKS OF THE BOEING COMPANY

© CAMP SYSTEMS

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 29273 (YG006)/VP-BBJ							
COM M-7200-02-01189	EROS CREW OXYGEN MASK, COMMUNIQUE						
		MOS	- (s)				
COM M-7200-02-01290	INSPECT ENGINE STRUT AFT FAIRING FOR WATER ACCUMULATION, COMMUNIQUE						
		MOS					
		AFL	4000 (s)				
COM M-7200-03-00936	VISUAL INSPECTION FORWARD GRAY WATER DRAIN MAST FOR POSSIBLE FATIGUE CRACKS, COMMUNIQUE						
		MOS	500 (s)				
MC 737-21-1149	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE					SUPERSEDED	
		MOS	-				
MC 737-21-1149 R01	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE						
		MOS	-				
MC 737-21-1149 R02	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE						
		MOS	-				
MC 737-21-1149 R03	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE						
		MOS	-				
MC 737-21-1149 R04	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE						
		MOS	-				
MC 737-21-1149 R05	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE						
		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
MC 737-21-1149 R06	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R07	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R08	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R09	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R10	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R11	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R12	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R13	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC 737-21-1149 R14	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
MC	737-21-1149 R15	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R16	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R18	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R19	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R20	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R21	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R22	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-21-1149 R23	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE CABIN ALTITUDE FROM 8000 FEET TO 6500 FEET AT 41,000 FEET FLIGHT ALTITUDE, MASTER CHANGE	MOS	-				
MC	737-24-1196 R1	ELECTRICAL POWER - STANDBY POWER SYSTEM - CHANGE THE ELECTRICAL POWER SYSTEM TO PROVIDE 60 MINUTES OF STANDBY POWER FOR THE AIRPLANE BASIC STANDBY LOADS IN LIEU OF THE 30 MINUTES (SUPERSEDED BY MC 737-24-1196 R2), MASTER CHANGE	MOS	-			SUPERSEDED	

© Camp Systems

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
MC	737-32-1478	LANDING GEAR - MAIN LANDING GEAR BRAKE - REPLACEMENT OF HONEYWELL STANDARD STEEL BRAKES WITH HONEYWELL HIGH CAPACITY STEEL BRAKES (SUPERSEDED BY MC 737-32-1478 R1), MASTER CHANGE					SUPERSEDED	
			MOS					
				-				
SB	-AP737-34-01	, SERVICE BULLETIN						
			MOS		19-DEC-2000			
				- (s)				
SB	01930-38-1	, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	1153154-47-06 R1	ENVIRONMENTAL CONTROL - NITROGEN GENERATION SYSTEM CONTROLLER (NGSC) - OXYGEN SENSOR INTERFACE CHANGE. MODIFICATION OF PN 1153154-4, PN 1153154-5, AND PN 1153154-6, SERVICE BULLETIN						
			MOS					
	03-FEB-2014			-				
SB	233A3202-28-01	P5-2 FUEL CONTROL MODULE ASSEMBLY MODIFICATION, SERVICE BULLETIN						
			MOS					
	03-MAY-2001			- (s)				
SB	233A3202-28-01 R1	P5-2 FUEL CONTROL MODULE ASSEMBLY MODIFICATION, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	233A3202-28-02	DISTRIBUTION - P5-2 FUEL SYSTEM MODULE - PW ASSEMBLY CIRCUIT BOARD REPLACEMENT, SERVICE BULLETIN						
			MOS					
				-				
SB	233A3202-28-02R1	DISTRIBUTION - P5-2 FUEL SYSTEM MODULE - PW ASSEMBLY CIRCUIT BOARD REPLACEMENT, SERVICE BULLETIN						
			MOS					
	28-FEB-2002			-				
SB	233A3202-28-03	FUEL - DISTRIBUTION - P5-2 CONTROL SYSTEM MODULE ASSEMBLY - CENTER FUEL TANK BOOST PUMP AUTO SHOTOFF MODIFICATION., SERVICE BULLETIN						
			MOS					
	12-JAN-2006			-				
SB	233A3205-24-01	GENERATOR DRIVE AND STANDBY POWER MODULE ASSEMBLY CHANGE, SERVICE BULLETIN						
			MOS					
	26-JUL-2001			-				

© Camp Systems

EFTA00618296

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 233A3209-31-01	MODIFICATION OF THE P5-3 FLIGHT CONTROLS MODULE, SERVICE BULLETIN						COMPLIED WITH
		MOS					
14-NOV-2002			-				
SB 2394-5320-100	, SERVICE BULLETIN						
		MOS					
			- (s)				
SB 28-01	X-RAY INSPECTION CRANE HYDRO-AIRE, SERVICE BULLETIN						
		MOS					
			- (s)				
SB 28-01 R2	X-RAY INSPECTION CRANE HYDRO-AIRE, SERVICE BULLETIN						
		MOS					
			-				
		AFL					
SB 285A1010-27-04	ELEVATOR AND TAB STALL MANAGEMENT YAW DAMPER SOFTWARE CHANGE - COMPONENT, SERVICE BULLETIN						
		MOS					
28-JUN-2001			-				
SB 285A1600-32-01	PROXIMITY SENSOR ELECTRONIC UNIT - UPGRADE FROM -2 TO -3 CONFIGURATION, SERVICE BULLETIN						
		MOS					
11-MAY-2000			-				
SB 285A1600-32-02	PROXIMITY SWITCH ELECTRONICS UNIT CHANGE - COMPONENT, SERVICE BULLETIN						
		MOS					
26-JUL-2001			-				
SB 285A1840-24-02	MODIFICATION OF THE P5-13 ELECTRIC METERS, BATTERY AND GALLEY POWER MODULE ASSEMBLY, SERVICE BULLETIN						
		MOS					
28-AUG-2003			-				
SB 285W0024-23-03 R1	CABIN ATTENDANT HANDSET / FLIGHT DECK HANDSET SHELL REPLACEMENT, SERVICE BULLETIN						
		MOS					
26-JUL-2001			- (s)				
SB 3214446-36-1904	PNEUMATIC - HIGH STAGE VALVE - REWORK THE HIGH STAGE VALVE, PN 3214446-4, SERIES 6 OR PN 3214446-4, SERIES 7 TO PN 3214446-4, SERIES 8 (CHANGE MOD 9), SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
26-JUL-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 3214552-36-1899 R1	PNEUMATIC - PRESSURE REGULATOR AND SHUTOFF VALVE - REWORK PRESSURE REGULATOR AND SHUTOFF VALVE, PN 3214552-6, SERIES 1 TO PN 3214552-6, MOD 1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-AUG-2013			-				
SB 3214552-36-1905	PNEUMATIC - PRESSURE REGULATOR AND SHUTOFF VALVE - REWORK THE PRESSURE REGULATOR AND SHUTOFF VALVE, PN 3214552-5, SERIES 5 TO PN 3214552-5, SERIES 6 (CHANGE MOD 5) AND PN 3214552-6, SERIES 1 AND SERIES 2 TO PN 3214552-6, SERIES 3 (CHANGE MOD 2), SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
26-JUL-2013			-				
SB 3215618-30-1895	ICE AND RAIN PROTECTION - NOSE COWL ANTI-ICE VALVE - REWORK THE NOSE COWL ANTI-ICE VALVE PN 3215618-4 TO PN 3215618-5 (SUPERSEDED BY SB 3215618-30-1895 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 3215618-30-1895 R1	ICE AND RAIN PROTECTION - NOSE COWL ANTI-ICE VALVE - REWORK THE NOSE COWL ANTI-ICE VALVE, PN 3215618-4 TO PN 3215618-5 (SUPERSEDED BY SB 3215618-30-1895 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 3215618-30-1895 R2	ICE AND RAIN PROTECTION - NOSE COWL ANTI-ICE VALVE - REWORK THE NOSE COWL ANTI-ICE VALVE, PN 3215618-4 TO PN 3215618-5, SERVICE BULLETIN					OPTIONAL	
		MOS					
24-JAN-2014			-				
SB 417A6110-23-01	ATTENDANT PANEL INTEGRATED HANDSET CONTROLLER REPLACEMENT, SERVICE BULLETIN						
		MOS					
31-MAY-2001			-				
SB 504443-25-01R3	AMSAFE - INSPECTION OF RESTRAINT SYSTEM END RELEASE BUCKLE, SERVICE BULLETIN						NOT APPLICABLE - TO PN NOT INSTALLED ON AIRCRAFT.
		MOS		18-AUG-2006			
			-	2633:50			
		AFL		633			
SB 65-52801-49-08	AUXILIARY POWER CONTROL UNIT ASSEMBLY MODIFICATION, SERVICE BULLETIN						
		MOS					
			- (s)				
SB 65C16237-32-02	LANDING GEAR, SERVICE BULLETIN						
		MOS					
28-MAR-2002			- (s)				
SB 72-000	COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B SERVICE BULLETINS, SERVICE BULLETIN						
		MOS					
			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 734-16100-52-2 R1	DOORS - AIRSTAIR DOOR LATCH LINEAR ACTUATOR - MODIFY ACTUATOR FROM P/N 734-16100-01 TO P/N 734-16100-02, SERVICE BULLETIN						COMPLIED WITH
		MOS		12-NOV-2010			
	18-MAR-2005		-	3477:55			
		AFL		848			
SB 737-00-1009	ADMINISTRATIVE - GENERAL - AIRCRAFT GENERAL - DAMAGE TOLERANCE INSPECTION DATA - MASTER CHANGE MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	14-APR-2011		-				
SB 737-11-1076	PLACARDS AND MARKINGS - EXTERIOR PLACARDS AND MARKINGS - NACELLE AND POWER PLANT - THRUST REVERSER MAINTENANCE WARNING PLACARD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	06-MAY-1999		- (s)				
SB 737-11-1077	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1077 R1	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1077 R10	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R11), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1077 R11	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R12), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1077 R12	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R13), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1077 R13	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R14), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R14	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R15), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R15	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R16), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R16	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R17), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R17	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R18), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R18	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R19), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R19	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R20), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R2	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R3), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R20	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R21), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R21	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R22), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R22	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R23), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R23	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R24), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R24	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R25), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R25	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R26), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R26	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R27), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R27	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R28), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R28	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R29), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R29	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R30), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R3	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R4), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R30	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R31), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R31	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R32), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R32	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R33), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R33	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R34), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R34	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R35), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R35	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R36), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R36	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R37), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R37	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R38), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R38	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R39), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R39	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R40), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R4	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R5), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R40	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R41), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R41	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R42), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R42	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R43), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R43	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R44), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R44	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R45), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R45	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R46), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R46	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R47), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R47	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R48), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R48	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R49), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R49	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R50), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R5	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R6), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R50	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R51), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R51	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R52), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R52	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R53), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R53	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R54), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R54	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R55), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R55	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R56), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R56	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R57), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R57	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R58), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R58	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R59), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R59	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R60), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R6	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R7), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R60	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R61), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R61	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R62), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R62	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R63), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R63	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R64), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R64	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R65), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R65	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R66), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R66	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R67), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R67	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R68), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R68	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R69), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R69	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R70), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R7	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R8), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-11-1077 R8	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R9), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1077 R9	PLACARDS AND MARKINGS - INTERIOR PLACARDS - CHANGE PLACARD INSTALLATION FOR MAXIMUM TAKEOFF WEIGHT (SUPERSEDED BY SB 737-11-1077 R10), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-11-1125	PLACARDS AND MARKINGS - EXTERIOR PLACARDS AND MARKINGS - APPLICATION OF EXTERIOR DECORATIVE PAINT SYSTEM ON LEFT SIDE AND RIGHT SIDE WINGS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-SEP-2004			-				
SB 737-11-1129	PLACARDS AND MARKINGS - EXTERIOR PLACARDS AND MARKINGS - FORWARD AIRSTAIRDECAL INSTALLATION, SERVICE BULLETIN						
		MOS	60 (s)				
11-NOV-2004							
SB 737-11-1129 R1	PLACARDS AND MARKINGS - EXTERIOR PLACARDS AND MARKINGS - FORWARD AIRSTAIR DECAL INSTALLATION, SERVICE BULLETIN						
		MOS	60 (s)				
11-NOV-2004							
SB 737-11-1156	PLACARD AND MARKINGS - FLIGHT DECK - CHANGE CONTROL COLUMN CHECKLIST PLACARDS, SERVICE BULLETIN						
		MOS					
22-MAR-2007			-				
SB 737-11-1156 R1	PLACARD AND MARKINGS - FLIGHT DECK - CHANGE CONTROL COLUMN CHECKLIST PLACARDS, SERVICE BULLETIN						COMPLIED WITH - IAW THE AD
		MOS			22-AUG-2008		
16-APR-2008			-		3260:48		
		AFL			782		
SB 737-11-1179	PLACARDS AND MARKINGS - INTERIOR PLACARDS - ALTERNATE MAXIMUM TAKEOFF WEIGHT PLACARD INSTALLATION (SUPERSEDED BY SB 737-11-1179 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1179 R1	PLACARDS AND MARKINGS - INTERIOR PLACARDS - ALTERNATE MAXIMUM TAKEOFF WEIGHT PLACARD INSTALLATION (SUPERSEDED BY SB 737-11-1179 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1179 R2	PLACARDS AND MARKINGS - INTERIOR PLACARDS - ALTERNATE MAXIMUM TAKEOFF WEIGHT PLACARD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-DEC-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-11-1201	PLACARDS AND MARKINGS - CARGO COMPARTMENT PLACARDS - FORWARD AND AFT CARGO COMPARTMENTS - REPLACEMENT OF LOAD LIMIT PLACARDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JUL-2010			-				
SB 737-11-1202	PLACARDS AND MARKINGS - CARGO COMPARTMENT PLACARDS - FORWARD AND AFT CARGO COMPARTMENTS - REPLACEMENT OF LOAD LIMIT PLACARDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JUL-2010			-				
SB 737-11-1207	PLACARDS AND MARKINGS - INTERIOR PLACARDS - REMOVAL OF AIRCRAFT FROM ALTERNATE WEIGHT PROGRAM AND CHANGE MAXIMUM TAKEOFF WEIGHT FROM 143,000 POUNDS/ 64,863 KILOGRAMS TO 134,000 POUNDS/ 60,781 KILOGRAMS (SUPERSEDED BY SB 737-11-1207 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-11-1208	PLACARDS AND MARKINGS - INTERIOR PLACARDS - INSTALLATION OF ALTERNATE MAXIMUM TAKEOFF WEIGHT PLACARD AND INCREASE OF MAXIMUM TAKEOFF WEIGHT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-JAN-2011			-				
SB 737-11A1109	PLACARDS AND MARKINGS - INTERIOR PLACARDS - INSTALLATION OF IN-FLIGHT SPEEDBRAKE USAGE LIMITATION MARKER, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - NO ACTION REQUIRED
		MOS			22-AUG-2003		
28-MAR-2002			- (s)		1342		
		AFL			351		
SB 737-11A1109 R1	PLACARDS AND MARKINGS - INTERIOR PLACARDS - INSTALLATION OF IN-FLIGHT SPEEDBRAKE USAGE LIMITATION MARKER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-JAN-2004			-				
SB 737-21-1125	AIR CONDITIONING - DISTRIBUTION - FLIGHT COMPARTMENT CONDITIONED AIR DISTRIBUTION - REPLACE DUCT TAPE JOINTS WITH SLEEVES AND CLAMPS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-APR-2001			- (s)				
SB 737-21-1125 R1	AIR CONDITIONING - DISTRIBUTION - FLIGHT COMPARTMENT CONDITIONED AIR DISTRIBUTION - REPLACE DUCT TAPE JOINTS WITH SLEEVES AND CLAMPS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAY-2009			-				
SB 737-21-1127	AIR CONDITIONING - MAIN AIR DISTRIBUTION - REPLACEMENT OF BULKHEAD FLEX SEAL CLAMP ON ENVIROMENTAL CONTROL SYSTEMS SUPPLY DUCTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-AUG-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-21-1127 R1	AIR CONDITIONING - MAIN AIR DISTRIBUTION - REPLACEMENT OF BULKHEAD FLEX SEAL CLAMP ON ENVIROMENTAL CONTROL SYSTEMS SUPPLY DUCTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUN-2002			- (s)				
SB 737-21-1135	AIR CONDITIONING - PRESSURIZATION CONTROL - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE CABIN PRESSURE CONTROL SYSTEM FOR 750 FEET PER MINUTE RATE OF DESCENT DURING A CARGO COMPARTMENT SMOKE EVENT SERVICE BULLETIN, SERVICE BULLETIN						
		MOS	72 (s)				
12-DEC-2007							
SB 737-21-1135 R1	AIR CONDITIONING - PRESSURIZATION CONTROL - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE CABIN PRESSURE CONTROL SYSTEM FOR 750 FEET PER MINUTE RATE OF DESCENT DURING A CARGO COMPARTMENT SMOKE EVENT, SERVICE BULLETIN						
		MOS	72 (s)				
13-NOV-2008							
SB 737-21-1144	AIR CONDITIONING - PASSENGER CABIN CONDITIONED AIR DUSTRIBUTION SYSTEM - TRANSITION DUCT ASSEMBLIES AND SIDEWALL RISER DUCTS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-APR-2005			-				
SB 737-21-1148	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTIION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-JUL-2005			-				
SB 737-21-1148 R1	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTIION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
26-JAN-2006			-				
SB 737-21-1148 R2	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT., SERVICE BULLETIN						
		MOS					
27-JUL-2006			-				
SB 737-21-1148 R3	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT., SERVICE BULLETIN						
		MOS					
02-NOV-2006			-				
SB 737-21-1148 R4	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
22-AUG-2007			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-21-1148 R5	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT., SERVICE BULLETIN						
		MOS					
06-MAY-2008			-				
SB 737-21-1148 R6	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT. , SERVICE BULLETIN						
		MOS					
11-SEP-2008			-				
SB 737-21-1148 R7	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - RAM AIR INLET SYSTEM COMPONENTS INSPECTION AND REPLACEMENT., SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-JAN-2010			-				
SB 737-21-1155	AIR CONDITIONING - EQUIPMENT COOLING SYSTEM - EQUIPMENT COOLING DUCT INSPECTION AND TAPE INSTALLATION TO PREVENT A RUB CONDITION, SERVICE BULLETIN						
		MOS					
10-NOV-2005			-				
SB 737-21-1155 R1	AIR CONDITIONING - EQUIPMENT COOLING SYSTEM - EQUIPMENT COOLING DUCT INSPECTION AND TAPE INSTALLATION TO PREVENT A RUB CONDITION, SERVICE BULLETIN						
		MOS					
22-DEC-2005			-				
SB 737-21-1155 R2	AIR CONDITIONING - EQUIPMENT COOLING SYSTEM - EQUIPMENT COOLING DUCT INSPECTION AND TAPE INSTALLATION TO PREVENT A RUB CONDITION, SERVICE BULLETIN						
		MOS					
20-JUL-2006			-				
SB 737-21-1155 R3	AIR CONDITIONING - EQUIPMENT COOLING SYSTEM - EQUIPMENT COOLING DUCT INSPECTION AND TAPE INSTALLATION TO PREVENT A RUB CONDITION, SERVICE BULLETIN						
		MOS					
25-MAR-2008			-				
SB 737-21-1155 R4	AIR CONDITIONING - EQUIPMENT COOLING SYSTEM - EQUIPMENT COOLING DUCT INSPECTIONAND TAPE INSTALLATION TO PREVENT A RUB CONDITION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-SEP-2009			-				
SB 737-21-1163	AIR CONDITIONING - PRESSURIZATION CONTROL - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE CABIN PRESSURE CONTROLLERS FOR 750 FEET PER MINUTE RATE OF DESCENT DURING A CARGO COMPARTMENT SMOKE EVENT, SERVICE BULLETIN						
		MOS	72 (s)				
12-DEC-2007							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-21-1163 R1	AIR CONDITIONING - PRESSURIZATION CONTROL - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE CABIN PRESSURE CONTROLLERS FOR 750 FEET PER MINUTE RATE OF DESCENT DURING A CARGO COMPARTMENT SMOKE EVENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	72 (s)				
	17-DEC-2009						
SB 737-21-1165	AIR CONDITIONING - CABIN PRESSURE INDICATION AND WARNING SYSTEM - REDUNDANT PRESSURE SWITCH INSTALLATION (SUPERSEDED BY SB 737-21-1165 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-21-1165 R1	AIR CONDITIONING - CABIN PRESSURE INDICATION AND WARNING SYSTEM - REDUNDANT PRESSURE SWITCH INSTALLATION (SUPERSEDED BY SB 737-21-1165 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-21-1165 R2	AIR CONDITIONING - CABIN PRESSURE INDICATION AND WARNING SYSTEM - REDUNDANT PRESSURE SWITCH INSTALLATION (SUPERSEDED BY SB 737-21-1165 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-21-1165 R3	AIR CONDITIONING - CABIN PRESSURE INDICATION AND WARNING SYSTEM - REDUNDANT PRESSURE SWITCH INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	72 (s)				
	07-NOV-2012						
SB 737-21-1174	AIR CONDITIONING - PACK FLOW CONTROL AND PACK COOLING SYSTEM - REPLACEMENT OF SHAFT ASSEMBLIES AND LINK ARM ASSEMBLIES TO INCREASE THE CLEARANCE FOR THE RAM AIR INLET ACTUATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	23-SEP-2010		-				
SB 737-21-1177	AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE POWER SOURCE TO THE PRESSURIZATION SYSTEM CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	06-JAN-2011		-				
SB 737-21-1178	AIR CONDITIONING - FLIGHT COMPARTMENT CONDITIONED AIR DISTRIBUTION - CHANGE OF THE DUCTS AND PLENUMS TO REDUCE NOISE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	19-AUG-2013		-				
SB 737-21A1139	AIR CONDITIONING - DISTRIBUTION - INSTALLATION OF THE INSULATION AND TAPE ON THE OVERHEAD DUCTS AND PLENUMS (SUPERSEDED BY 737-21A1139 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-21A1139 R1	AIR CONDITIONING - DISTRIBUTION - INSTALLATION OF THE INSULATION AND TAPE ON THE OVERHEAD DUCTS AND PLENUMS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-AUG-2003			-				
SB 737-22-1137	AUTOFLIGHT - AUTOTHROTTLE SYSTEM - ACTIVATION OF FLIGHT MANAGEMENT COMPUTER TRANSITION ALTITUDE SELECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-MAY-2000			- (s)				
SB 737-22-1140	AUTO FLIGHT - AUTOPILOT - AUTOPILOT OPERATION WITH ONE IRU INOPERATIVE RETROFIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JUN-2000			- (s)				
SB 737-22-1153	AUTO FLIGHT - AUTOPILOT - INSTALLATION OF RED NON-DIMMABLE "AUTOLAND" WARNING LIGHTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY -
		MOS					
01-NOV-2001			-				
SB 737-22-1154	AUTO FLIGHT - AUTOPILOT - OPTION/PROGRAM PIN CHANGES TO ACTIVATE FLIGHT CONTROL COMPUTER IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JAN-2002			- (s)				
SB 737-22-1154 R1	AUTO FLIGHT - AUTOPILOT - OPTION/PROGRAM PIN CHANGES TO ACTIVATE FLIGHT CONTROL COMPUTER IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-SEP-2002			-				
SB 737-22-1213	AUTOFLIGHT - YAW DAMPER SYSTEM - DELETION OF A YAW DAMPER INDICATOR (SUPERSEDED BY SB 737-22-1213 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-22-1213 R1	AUTOFLIGHT - YAW DAMPER SYSTEM - DELETION OF A YAW DAMPER INDICATOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-APR-2011			-				
SB 737-22-1216	AUTOFLIGHT - DIGITAL FLIGHT CONTROL SYSTEM - FLIGHT CONTROL COMPUTER DIP SWITCH CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-AUG-2010			-				
SB 737-22-1223	AUTOFLIGHT - AUTOPILOT - INSTALLATION OF LATERAL NAVIGATION MODE AS THE DEFAULT ROLL MODE FOR GO-AROUND IN LIEU OF TRACK HOLD FOR A MISSED APPROACH, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JAN-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-22A1164	AUTOFLIGHT - DIGITAL FLIGHT CONTROL SYSTEM - FLIGHT CONTROL COMPUTER OPERATIONAL PROGRAM SOFTWARE INSTALLATION - P2.0, SERVICE BULLETIN						NOT APPLICABLE
		MOS		28-APR-2006			
20-MAY-2004			- (s)	2606:18			
		AFL		626			
SB 737-22A1211	AUTOFLIGHT - DIGITAL FLIGHT CONTROL SYSTEM - FLIGHT CONTROL COMPUTER SOFTWARE CHANGE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
		DAYS		09-AUG-2010			
13-APR-2010			-	3448:31			
		AFL		841			
SB 737-22A1215	AUTOFLIGHT - AUTOTHROTTLE SYSTEM - AUTOTHROTTLE COMPUTER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	36	(EFF)	**22-NOV-2016**		
22-NOV-2013							
SB 737-22A1224	AUTOFLIGHT - DIGITAL FLIGHT CONTROL SYSTEM - FLIGHT CONTROL COMPUTER SOFTWARE CHANGE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY PN INSTALLED. REFER AD 2012-21-08.
		MOS		16-NOV-2012			
18-MAY-2012			-	3670:04			
		AFL		890			
SB 737-23-1135	PASSENGER ADDRESS AND ENTERTAINMENT - ATTENDANT PANEL REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
31-MAY-2001			- (s)				
SB 737-23-1139	COMMUNICATIONS - PASSENGER ADDRESS AND ENTERTAINMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-FEB-2001			- (s)				
SB 737-23-1139 R1	INSTALATION OF THE PASSENGER ADDRESS AMPLIFIER AND IN-FLIGHT ENTERTAINMENT AUDIO CIRCUT BREAKERS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-JUL-2002			- (s)				
SB 737-23-1172	HF FERRY FLIGHT KIT INSTALLATION/REMOVAL (SUPERSEDED BY SB 737-23-1172 R1), SERVICE BULLETIN						
		MOS					
			-				
SB 737-23-1172 R1	HIGH FREQUENCY (HF) COMMUNICATIONS SYSTEM - HF FERRY FLIGHT KIT INSTALLATION/REMOVAL (SUPERSEDED BY SB 737-23-1172 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-23-1172 R2	COMMUNICATIONS - HIGH FREQUENCY (HF) COMMUNICATIONS SYSTEM - HF FERRY FLIGHT KIT INSTALLATION/REMOVAL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-2012			-				
SB 737-23-1200	AUDIO SELECTOR PANEL RELOCATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-NOV-2001			- (s)				
SB 737-23-1258	COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) - DATA BUS WIRE CHANGES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-SEP-2005			-				
SB 737-23-1266	COMMUNICATIONS - IRIDIUM ANTENNA - INSTALLATION (SUPERSEDED BY SB 737-23-1266 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-23-1266 R1	COMMUNICATIONS - IRIDIUM ANTENNA - INSTALLATION (SUPERSEDED BY SB 737-23-1266 R2) , SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-23-1266 R2	COMMUNICATIONS - IRIDIUM ANTENNA - INSTALLATION (SUPERSEDED BY SB 737-23-1266 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-23-1266 R3	COMMUNICATIONS - IRIDIUM ANTENNA - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-JAN-2011			-				
SB 737-23-1336	COMMUNICATIONS - EMERGENCY LOCATOR TRANSMITTER - INSTALLATION OF A GROUND WIRE, SERVICE BULLETIN						
		MOS					
13-MAY-2010			-				
SB 737-23-1337	COMMUNICATIONS - AUDIO VISUAL MONITORING - COCKPIT DOOR SURVEILLANCE SYSTEM WIRE BUNDLE CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-AUG-2010			-				
SB 737-23-1342	COMMUNICATIONS - LAV A1 CONNECTOR MATE-WITH TAPE - CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-NOV-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-23-1343	COMMUNICATION - HIGH FREQUENCY COMMUNICATION SYSTEM - INSTALL WIRES BETWEEN THE VERY HIGH FREQUENCY TRANSCEIVER 3 AND THE COMMUNICATION MANAGEMENT UNIT OF THE AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JAN-2011			-				
SB 737-23-1397	COMMUNICATIONS - CABIN INTERPHONE SYSTEM - IN-LINE FILTER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-DEC-2013			-				
SB 737-23-1403	COMMUNICATIONS - SATELLITE COMMUNICATIONS SYSTEM - SATELLITE DATA UNIT REPLACEMENT AND AIR DATA INERTIAL REFERENCE UNIT OUTPUT BUS WIRING CHANGES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-FEB-2013			- (s)				
SB 737-23-1410	COMMUNICATIONS - EMERGENCY EVACUATION SYSTEM - ERRONEOUS ACTIVATION OF CABIN CALL LIGHT IN FLIGHT COMPARTMENT CORRECTIVE WIRING CHANGES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-APR-2013			-				
SB 737-23-1419	COMMUNICATIONS - AIRCRAFT COMMUNICATIONS ADDRESSING AND REPORTING SYSTEM (ACARS) - COMMUNICATIONS MANAGEMENT UNIT (CMU) WIRING CHANGE - INSTALL WIRING BETWEEN ACARS CMU AND ENGINE RUNNING SWITCHES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-OCT-2013			-				
SB 737-23-1423	COMMUNICATIONS - VOICE RECORDER SYSTEM - INSTALLATION OF THE NEW L-3 COCKPIT VOICE RECORDER (CVR) CONTROL PANEL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-FEB-2014			-				
SB 737-23-1429	COMMUNICATIONS - VOICE RECORDER SYSTEM - INSTALLATION OF THE COCKPIT VOICE RECORDER INDEPENDENT POWER SUPPLY (RIPS) AND THE RIPS-COMPATIBLE MANUAL ON/AUTO OFF SWITCH OPTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-MAR-2014			-				
SB 737-23A1170	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE (SUPERSEDED BY SB 737-23A1170 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS			10-AUG-2000		
27-APR-2000			-				
SB 737-23A1170 R1	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE (SUPERSEDED BY SB 737-23A1170 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
27-JUL-2000			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-23A1170 R1 PART I	VHF-1 AND VHF-2 ANTENNA INTERCHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUL-2000			-				
SB 737-23A1170 R1 PART II	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUL-2000			-				
SB 737-23A1170 R2	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - REF: PART I PART II DUE 4000 HRS
		MOS		02-MAR-2006			
14-SEP-2000			-	2509:38			
		AFL		609			
SB 737-23A1170 R2 PART I	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		DAYS	10 (s)	02-MAR-2006			
14-SEP-2000				2509:38			
		AFL		609			
SB 737-23A1170 R2 PART II	COMMUNICATIONS - VHF-1 AND VHF-2 ANTENNA INTERCHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2000			4000		**4000**	4000	
SB 737-24-1126	AILERON CONTROL SYSTEM - WIRING BUNDLE SHIELD OVERBRAID INSTALLATION FOR EMI PROTECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-AUG-2002			- (s)				
SB 737-24-1126 R1	AILERON CONTROL SYSTEM - WIRING BUNDLE SHIELD OVERBRAID INSTALLATION FOR EMI PROTECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-NOV-2002			- (s)				
SB 737-24-1128	POWER DISTRIBUTION PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - TERMINATED PCW
		MOS		18-AUG-2006			
28-APR-1999			-	2633:50			
		AFL		633			
SB 737-24-1132	ELECTRICAL POWER - DC GENERATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-JUN-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24-1134	STANDBY POWER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-JUN-2000			- (s)				
SB 737-24-1135	NO.1 AIR TRAFFIC CONTROL SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-APR-2000			- (s)				
SB 737-24-1147	INSTALLATION OF THE INFLIGHT ENTERTAINMENT SYSTEM CIRCUIT BREAKER, RELAYS AND WIRING, SERVICE BULLETIN						
		MOS	60 (s)				
20-NOV-2003							
SB 737-24-1147 R1	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSTALLATION OF THE INFLIGHT ENTERTAINMENT SYSTEM CIRCUIT BREAKER, RELAYS AND WIRING, SERVICE BULLETIN						
		MOS	60 (s)				
01-MAR-2007							
SB 737-24-1147 R2	ELECTRICAL LOAD DISTRIBUTION - INSTALLATION OF THE INFLIGHT ENTERTAINMENT SYSTEM CIRCUIT BREAKER, RELAYS AND WIRING, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
30-JUL-2009							
SB 737-24-1149	CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS (SUPERSEDED BY 737-24-1149 R1), SERVICE BULLETIN					SUPERSEDED	
		DAYS					
01-JAN-2000			-				
SB 737-24-1149 R1	CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (SUPERSEDED BY 737-24-1149 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-JAN-2000			-				
SB 737-24-1149 R2	CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (SUPERSEDED BY 737-24-1149 R3) , SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-JAN-2000			-				
SB 737-24-1149 R3	ELECTRICAL POWER - GENERAL - CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (SUPERSEDED BY 737-24-1149 R4) , SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-JAN-2000			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24-1149 R4	ELECTRICAL POWER - GENERAL - CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL, SERVICE BULLETIN						
		MOS	24 (s)				
07-AUG-2007							
SB 737-24-1154	GUARD INSTALLATION FOR THE CIRCUIT BREAKERS FOR THE OVERWING DOOR FLIGHT LOCKS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-2003			-				
SB 737-24-1155	STANDBY POWER CONTROL UNIT (SPCU) TRAY BRACE AND TRAY STIFFENER ASSEMBLY INSTALLATION., SERVICE BULLETIN					RECOMMENDED	
		MOS					
26-FEB-2004			-				
SB 737-24-1155 R1	STANDBY POWER CONTROL UNIT (SPCU) TRAY BRACE AND TRAY STIFFENER ASSEMBLY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-DEC-2004			-				
SB 737-24-1155 R2	ELECTRICAL POWER - STANDBY POWER CONTROL UNIT (SPCU) TRAY BRACE AND TRAY STIFFENER ASSEMBLY INSTALLATION, SERVICE BULLETIN						
		MOS					
08-SEP-2005			-				
SB 737-24-1155 R3	ELECTRICAL POWER - STANDBY POWER CONTROL UNIT (SPCU) TRAY BRACE AND TRAY STIFFENER ASSEMBLY INSTALLATION, SERVICE BULLETIN						
		MOS					
23-MAR-2006			-				
SB 737-24-1157	INSTALLATION OF CLAMPS BETWEEN THE WIRE BUNDLES AND THE HYDRAULIC TUBES IN THE LEFT MAIN LANDING GEAR WHEEL WELL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-AUG-2003			-				
SB 737-24-1161	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSTALLATION OF PROTECTION GUARDS ON THE P6 AND P18 LOAD CONTROL PANELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-MAR-2005			-				
SB 737-24-1161 R1	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSTALLATION OF PROTECTION GUARDS ON THE P6 AND P18 LOAD CONTROL PANELS, SERVICE BULLETIN						
		MOS					
17-NOV-2005			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24-1161 R2	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSTALLATION OF PROTECTION GUARDS ON THE P6 AND P18 LOAD CONTROL PANELS, SERVICE BULLETIN						
		MOS					
24-JAN-2008			-				
SB 737-24-1162	ELECTRICAL POWER - AC GENERATION SYSTEM - STA 1088 BULKHEAD CATERPILLAR GROMMET, INSPECTION AND INSTALLATION, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
02-JUN-2005			-				
SB 737-24-1165	ELECTRICAL POWER - STANDBY POWER SYSTEM - REMOVAL AND REPLACEMENT OF THE STATIC INVERTER MODULE, SERVICE BULLETIN						
		MOS	42 (s)				
28-APR-2005							
SB 737-24-1165 R1	ELECTRICAL POWER - STANDBY POWER SYSTEM - REMOVAL AND REPLACEMENT OF THE STATIC INVERTER MODULE, SERVICE BULLETIN						COMPLIED WITH
		MOS			29-AUG-2011		
20-OCT-2005			- (s)		3533:32		
		AFL			863		
SB 737-24-1167	ELECTRICAL POWER - GENERAL - REPLACEMENT OF ANTISKID SYSTEM ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELLS, SERVICE BULLETIN						
		MOS					
06-APR-2006			-				
SB 737-24-1167 R1	ELECTRICAL POWER - GENERAL - REPLACEMENT OF ANTISKID SYSTEM ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELLS, SERVICE BULLETIN						
		MOS					
13-NOV-2008			-				
SB 737-24-1169	ELECTRICAL POWER - INSPECTION FOR MISSING FILLET SEAL ON RECEPTACLES IN MAIN LANDING GEAR WHEEL WELLS, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
15-DEC-2006							
SB 737-24-1169 R1	ELECTRICAL POWER - INSPECTION FOR MISSING FILLET SEAL ON RECEPTACLES IN MAIN LANDING GEAR WHEEL WELLS, SERVICE BULLETIN						
		MOS	24 (s)				
06-AUG-2007							
SB 737-24-1169 R2	ELECTRICAL POWER - INSPECTION FOR MISSING FILLET SEAL ON RECEPTACLES IN MAIN LANDING GEAR WHEEL WELLS, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
09-APR-2008			- (s)		3260:48		
		AFL			782		

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24-1171	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE W0018 IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS	24 (s)				
26-MAR-2007							
SB 737-24-1171 R1	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE W0018 IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS	24 (s)				
02-JUL-2007							
SB 737-24-1171 R2	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE W0018 IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS	24 (s)				
18-SEP-2007							
SB 737-24-1171 R3	ELECTRICAL POWER - ELECTRICAL LOAD DISTRIBUTION - INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE W0018 IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS	24 (s)				
08-MAY-2008							
SB 737-24-1171 R4	ELECTRICAL LOAD DISTRIBUTION - INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE W0018 IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS	24 (s)				
30-OCT-2008							
SB 737-24-1172	ELECTRICAL - ELECTRICAL POWER - INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN						
		MOS					
16-MAY-2008			-				
SB 737-24-1172 R1	INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-NOV-2009			-				
SB 1 (A) 737-24-1172 R1 TABLE	REPAIR INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN AS GIVEN IN ACCOMPLISHMENT INSTRUCTIONS OPTION 1					RECOMMENDED	
		MOS	72 (s)				
18-NOV-2009							
SB 1 (B) 737-24-1172 R1 TABLE	INSPECTION INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN OF ELECTRICAL BONDING AS GIVEN IN ACCOMPLISHMENT INSTRUCTIONS OPTION 2					RECOMMENDED	
		MOS	24 (s)				
18-NOV-2009							

© Camp Systems

EFTA00618320

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB (A) 737-24-1172 TABLE 1	REPAIR ELECTRICAL - ELECTRICAL POWER - INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN AS GIVEN IN ACCOMPLISHMENT INSTRUCTIONS OPTION 1	MOS	72 (s)	16-MAY-2008			
SB (B) 737-24-1172 TABLE 1	INSPECTION ELECTRICAL - ELECTRICAL POWER - INSPECTION AND REPAIR OF ELECTRICAL BONDING RESISTANCE AT THE WING-TO-BODY FEED THROUGH RECEPTACLES, SERVICE BULLETIN OF ELECTRICAL BONDING AS GIVEN IN ACCOMPLISHMENT INSTRUCTIONS OPTION 2	MOS	24 (s)	16-MAY-2008			
SB 737-24-1173	ELECTRICAL - ELECTRICAL POWER - REPLACEMENT OF WIRE SUPPORT BRACKET AND INSPECTION OF THE ROD END PLATES ON THE RUDDER FEEL AND CENTERING UNIT, SERVICE BULLETIN	MOS	72 (s)	07-NOV-2007			
SB 737-24-1173 R1	ELECTRICAL - ELECTRICAL POWER - REPLACEMENT OF WIRE SUPPORT BRACKET AND INSPECTION OF THE ROD END PLATES ON THE RUDDER FEEL AND CENTERING UNIT, SERVICE BULLETIN	MOS	72 (s)	27-MAR-2008			
SB 737-24-1173 R2	REPLACEMENT OF WIRE SUPPORT BRACKET AND INSPECTION OF THE ROD END PLATES ON THE RUDDER FEEL AND CENTERING UNIT, SERVICE BULLETIN	MOS	72 (s)	23-APR-2009		RECOMMENDED	
SB 737-24-1176	ELECTRICAL POWER - AC GENERATION SYSTEM - RE-PIN WIRES AT TWO WING-TO-STRUT ELECTRICAL CONNECTORS AT EACH ENGINE STRUT BRACKET, SERVICE BULLETIN	MOS	-	21-FEB-2008			
SB 737-24-1176 R1	ELECTRICAL POWER - AC GENERATION SYSTEM - RE-PIN WIRES AT TWO WING-TO-STRUT ELECTRICAL CONNECTORS AT EACH ENGINE STRUT BRACKET, SERVICE BULLETIN	MOS	-	22-APR-2008			
SB 737-24-1176 R2	AC GENERATION SYSTEM - RE-PIN WIRES AT TWO WING-TO-STRUT ELECTRICAL CONNECTORS AT EACH ENGINE STRUT BRACKET, SERVICE BULLETIN	MOS	-	06-NOV-2008			
SB 737-24-1176 R3	AC GENERATION SYSTEM - INSPECTION AND RE-PIN WIRES AT TWO WING-TO-STRUT ELECTRICAL CONNECTORS AT EACH ENGINE STRUT BRACKET, SERVICE BULLETIN	MOS	-	18-DEC-2008			

© Camp Systems

EFTA00618321

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24-1182	INSPECTION AND CHANGE WIRE BUNDLE ROUTING TO PREVENT CONTACT WITH MAIN BATTERY CHARGER, SERVICE BULLETIN						
		MOS					
20-JAN-2009			-				
SB 737-24-1194	ELECTRICAL POWER - MEDICAL OUTLET SYSTEM - MEDICAL FREQUENCY CONVERTER SUB-TRAY CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2011			-				
SB 737-24-1203	ELECTRICAL POWER - AC EXTERNAL POWER - CHANGE OF THE EXTERNAL POWER RECEPTACLE CONTACTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-DEC-2013			-				
SB 737-24-1205	ELECTRICAL POWER - STANDBY POWER SYSTEM - REPLACEMENT OF THE M9 STATIC INVERTER TERMINAL LUGS., SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-MAR-2014			-				
SB 737-24-1206	ELECTRICAL POWER - GENERAL - E8-1 SHELF ASSEMBLY - VINYL MARKER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-APR-2014			-				
SB 737-24A1141 R1	P5 OVERHEAD PANEL - BRACKET REPLACEMENT AND WIRE INSTALLATION, SERVICE BULLETIN						- REF: R2
		MOS	24 (s)				
23-DEC-2004							
SB 737-24A1141 R2	ELECTRICAL POWER - GENERAL - P5 OVERHEAD PANEL - BRACKET REPLACEMENT AND WIRE INSTALLATION, SERVICE BULLETIN						COMPLIED WITH
		MOS		18-AUG-2006			
01-DEC-2005			- (s)	2633:50			
		AFL		633			
SB 737-24A1141 R3	ELECTRICAL POWER - GENERAL - P5 OVERHEAD PANEL - BRACKET REPLACEMENT AND WIRE INSTALLATION REVISION, SERVICE BULLETIN						COMPLIED WITH - IAW THE AD R2 ALREADY C/W GVBBJ122, AUG 18, 2006.
		MOS		02-DEC-2009			
20-FEB-2008			- (s)	3402:19			
		AFL		824			
SB 737-24A1148	CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (SUPERSEDED BY 737-24A1148 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - INSPECTED AND CLEANED CONNECTORS
		MOS		13-AUG-2004			
06-DEC-2001			- (s)	1785:06			
		AFL		446			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-24A1148 R1	CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2005-18-23
		MOS	12 (s)	03-JUL-2013			
10-JUL-2003				3723:21			
		AFL		908			
SB 737-24A1150	INSPECTION OF THE POWER SUPPLY VOLTAGE TO THE CAPTAIN'S PITOT HEATER, SERVICE BULLETIN					RECOMMENDED	
		DAYS	60 (s)	27-AUG-2002			
11-DEC-2002				1057:48			
		AFL		271			
SB 737-24A1193	ELECTRICAL POWER- AC GENERATOR DRIVE SYSTEM- INCORRECT ELECTRICAL BOND ON GROUND BRACKET FOR LEFT ENGINE GENERATOR, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS					
			-				
SB 737-25-1373	OVERHEAD STOWAGE BIN DOOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JUL-1999			- (s)				
SB 737-25-1376	LAVATORY COMPARTMENT - CHANGE TO AFT CLEVIS SYSTEM AND AFT WALL ON LAVATORY A, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-JUL-2009			-				
SB 737-25-1378	CHANGE ESCAPE SLIDE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-APR-1999			- (s)				
SB 737-25-1378 R1	, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-JAN-2001			- (s)				
SB 737-25-1403	DOOR-MOUNTED ESCAPE SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-MAY-2000			- (s)				
SB 737-25-1403 R1	DOOR MOUNTED ESCAPE SYSTEM - INFLATION CYLINDER TRIGGER HOUSING COVER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-NOV-2001			-				
SB 737-25-1404	ESCAPE SLIDE LATCH ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-MAY-2000			- (s)				

© Camp Systems

EFTA00618323

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1404 R1	EMERGENCY - DOOR-MOUNTED ESCAPE SYSTEM - LATCH ASSEMBLY MODIFICATION (SUPERSEDED BY SB 737-25-1404 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-25-1404 R2	EQUIPMENT/FURNISHINGS - EMERGENCY - DOOR-MOUNTED ESCAPE SYSTEM - LATCH ASSEMBLY MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	36 (s)				
	25-MAY-2000						
SB 737-25-1439 R3	EQUIPMENT/FURNISHINGS - BUFFET/GALLEY - GALLEY WIRE BUNDLE PROTECTIVE WRAP REPLACEMENT, SERVICE BULLETIN						
		MOS	-				
	11-NOV-2004						
SB 737-25-1440	REPLACEMENT OF SPARE BULB STOWAGE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS	- (s)				
	06-DEC-2001						
SB 737-25-1447	INSTALL SECOND OBSERVER'S STATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	- (s)				
	18-OCT-2001						
SB 737-25-1449	AFT CARGO COMPARTMENT - REPLACE INSULATION SUPPORT TRAYS, SERVICE BULLETIN					RECOMMENDED	
		MOS	- (s)				
	08-NOV-2001						
SB 737-25-1449 R1	REPLACE INSLUATION SUPPORT TRAYS, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	01-AUG-2002						
SB 737-25-1475	REPLACE TRIGGER HOUSING ON SLIDE REGULATOR VALVE, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	26-NOV-2002						
SB 737-25-1477	WINDOW NUMBER FOUR SUNSHADE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	- (s)				
	14-NOV-2002						
SB 737-25-1477 R1	WINDOW NUMBER FOUR SUNSHADE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	28-AUG-2003						

© Camp Systems

EFTA00618324

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1491	EQUIPMENT/FURNISHINGS - EMERGENCY - DOOR MOUNTED ESCAPE SYSTEM - CHANGE EVACUATION SLIDE INFLATION VALVE REGULATOR, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY
		MOS		09-AUG-2010			
23-APR-2007			- (s)	3448:31			
		AFL		841			
SB 737-25-1491 R1	EMERGENCY - DOOR MOUNTED ESCAPE SYSTEM - CHANGE EVACUATION SLIDE INFLATION VALVE REGULATOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY 737-25-1491 SLIDE PN INSTALLED: 5A3086-301
		MOS		09-AUG-2010			
23-APR-2007			- (s)	3448:31			
		AFL		841			
SB 737-25-1493	EQUIPMENT/FURNISHINGS - INSULATION BLANKET - MOISTURE REDUCTION OF INSULATION BLANKETS AT THE AUTOMATIC OVERWING EXIT DOORS, SERVICE BULLETIN						
		MOS					
02-MAY-2007			-				
SB 737-25-1493 R1	INSULATION BLANKET - MOISTURE REDUCTION OF INSULATION BLANKETS AT THE AUTOMATIC OVERWING EXIT DOORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-JUL-2009			-				
SB 737-25-1523	EQUIPMENT/FURNISHINGS - FORWARD GALLEY DOOR DOORWAY HEADER PANEL - INSTALLATION OF ATTENDANT SERVICE UNIT (SUPERSEDED BY SB 737-25-1523 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1523 R1	EQUIPMENT/FURNISHINGS - FORWARD GALLEY DOOR DOORWAY HEADER PANEL - INSTALLATION OF ATTENDANT SERVICE UNIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JAN-2011			-				
SB 737-25-1543	EQUIPMENT / FURNISHINGS - FLIGHT COMPARTMENT AND FORWARD CARGO COMPARTMENT - FLIGHT DECK NOISE REDUCTION CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2012			-				
SB 737-25-1544	PASSENGER CABIN PARTITIONS AND COMPARTMENTS - SUPPORT FITTING ASSEMBLY AIR CONDITIONING EXTRUSIONS REPLACEMENT, SERVICE BULLETIN						
		MOS	72 (s)				
04-OCT-2006							
		AFL	36000				
SB 737-25-1544 R1	EQUIPMENT/FURNISHING - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - SUPPORT FITTING ASSEMBLY AIR CONDITIONING EXTRUSIONS REPLACEMENT (SUPERSEDED BY SB SB 737-25-1544 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				

© Camp Systems

EFTA00618325

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1544 R2	EQUIPMENT/FURNISHING - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - SUPPORT FITTING ASSEMBLY AIR CONDITIONING EXTRUSIONS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	72 (s)				
23-MAR-2011							
SB 737-25-1545	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT - MODIFICATION OF THE OXYGEN ACTIVATION MECHANISM WITHIN THE PASSENGER SERVICE UNITS (SUPERSEDED BY SB 737-25-1545 R1), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - PER PN NOT INSTALLED
		MOS		24-AUG-2007			
			- (s)	2968:28			
		AFL		699			
SB 737-25-1545 R1	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT - MODIFICATION OF THE OXYGEN ACTIVATION MECHANISM WITHIN THE PASSENGER SERVICE UNITS (SUPERSEDED BY SB 737-25-1545 R2), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - PER PN NOT INSTALLED
		MOS		24-AUG-2007			
			- (s)	2968:28			
		AFL		699			
SB 737-25-1545 R2	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT - MODIFICATION OF THE OXYGEN ACTIVATION MECHANISM WITHIN THE PASSENGER SERVICE UNITS, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
02-MAY-2007							
SB 737-25-1593	EQUIPMENT/FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - INSTALL OVERHEAD STOWAGE BIN DURABILITY PATCH, SERVICE BULLETIN						
		MOS					
12-MAR-2008			-				
SB 737-25-1602	AUTOMATIC OVERWING EXIT DOOR SURROUND STRUCTURE - CHANGE UPPER AND LOWER DOOR SILLS (SUPERSEDED BY SB 737-25-1602 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1602 R1	EQUIPMENT/FURNISHINGS - AUTOMATIC OVERWING EXIT DOOR SURROUND STRUCTURE - CHANGE UPPER AND LOWER DOOR SILLS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-DEC-2010			-				
SB 737-25-1617	CUP HOLDERS INSTALLATION CHANGE, SERVICE BULLETIN						
		MOS					
11-JUN-2009			-				
SB 737-25-1617 R1	FLIGHT COMPARTMENT - CUP HOLDERS INSTALLATION CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2009			-				

© Camp Systems

EFTA00618326

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1636	EQUIPMENT/FURNISHINGS - PASSENGER SEATS - EMERGENCY EXIT DOOR - ARMREST INSTALLATION, SERVICE BULLETIN						
		MOS					
	21-MAY-2010		-				
SB 737-25-1639	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT - INTERIOR RECONFIGURATION - CHANGE FROM 167 PASSENGER DUAL CLASS CONFIGURATION TO 176 PASSENGER SINGLE CLASS CONFIGURATION WITH PANASONIC IN-FLIGHT ENTERTAINMENT (SUPERSEDED BY SB 737-25-1639 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS					
	09-DEC-2010		-				
SB 737-25-1641	EQUIPMENT / FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - CENTER OVERHEAD STOWAGE BOX WITH LIFERAFT PROVISIONS - 9G TIE ROD ATTACHMENT CHANGE (SUPERSEDED BY SB 737-25-1641 R1), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - BY EFFECTIVITY
		MOS					
			-				
SB 737-25-1641 R1	EQUIPMENT / FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - CENTER OVERHEAD STOWAGE BOX WITH LIFERAFT PROVISIONS - 9G TIE ROD ATTACHMENT CHANGE (SUPERSEDED BY SB 737-25-1641 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1641 R2	EQUIPMENT / FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - CENTER OVERHEAD STOWAGE BOX WITH LIFERAFT PROVISIONS - 9G TIE ROD ATTACHMENT CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
	13-MAY-2011						
SB 737-25-1642	EQUIPMENT / FURNISHINGS - PASSENGER AND CABIN ATTENDANT ACCOMMODATIONS SAM254 SLIDE COVER ASSEMBLY FOR HBL3330 ELECTRICAL OUTLET - CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	22-FEB-2011		-				
SB 737-25-1643	EQUIPMENT/FURNISHINGS - ESCAPE SLIDES, STRAPS AND LANYARDS - CARGO DOOR, PERSONNEL SAFETY NET REPLACEMENT, SERVICE BULLETIN						
		MOS					
			-				
SB 737-25-1645	EQUIPMENT/FURNISHINGS - PASSENGER CABIN FLOORS - SECTIONS 44 - CHANGE SOUND DAMPING MATERIALS OF FLOOR PANELS, SERVICE BULLETIN					RECOMMENDED	
		MOS	12 (s)				
	11-MAY-2012						
SB 737-25-1646	EQUIPMENT / FURNISHINGS - POWER DISTRIBUTION PANEL P92 - CIRCUIT BREAKER C0912, INOP COLLAR AND LABEL INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	02-AUG-2012		-				

© Camp Systems

EFTA00618327

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1647	EQUIPMENT/FURNISHINGS - PASSENGER SEATS - PALLETIZED SEAT PALLET LATCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-OCT-2011			-				
SB 737-25-1648	EQUIPMENT/FURNISHINGS-BUFFET/GALLEY, GALLEY NUMBER 2, FOLDING TROLLEY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-MAY-2011			-				
SB 737-25-1651	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - RIGHT SIDE SIDEWALL AND LITERATURE POCKET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-AUG-2011			-				
SB 737-25-1654	EQUIPMENT/FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - BOEING SKY INTERIOR OVERHEAD STOWAGE BINS, INSTALLATION OF FASTER DEPLOYING BIN RATE CONTROLS FOR THE FORWARD AND AFT, LEFT AND RIGHT TERMINATION BINS (SUPERSEDED BY SB 737-25-1654 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JUL-2012			-				
SB 737-25-1654 R1	EQUIPMENT/FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - BOEING SKY INTERIOR OVERHEAD STOWAGE BINS, INSTALLATION OF FASTER DEPLOYING BIN RATE CONTROLS FOR THE FORWARD AND AFT, LEFT AND RIGHT TERMINATION BINS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAR-2013			-				
SB 737-25-1660	EQUIPMENT/FURNISHINGS- ELECTRICAL EQUIPMENT RACK MOISTURE SHROUD - CHANGE (SUPERSEDED BY SB 737-25-1660 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1660 R1	EQUIPMENT/FURNISHINGS- ELECTRICAL EQUIPMENT RACK MOISTURE SHROUD - CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
26-SEP-2012			-				
SB 737-25-1661	EQUIPMENT / FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - OUTBOARD STOWAGE CLOSET - REPLACEMENT OF FORWARD LEFT FULL HEIGHT CLOSET DOOR ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-OCT-2012			-				
SB 737-25-1663	EQUIPMENT/FURNISHINGS - WINDOW SHADE AND REVEAL ASSEMBLY - BOEING SKY INTERIOR AUTOMATIC OVERWING EXIT DOOR WINDOW SHADE AND REVEAL ASSEMBLY REPLACEMENT (SUPERSEDED BY SB 737-25-1663 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1663 R1	EQUIPMENT/FURNISHINGS - WINDOW SHADE AND REVEAL ASSEMBLY - BOEING SKY INTERIOR AUTOMATIC OVERWING EXIT DOOR WINDOW SHADE, REVEAL ASSEMBLY, AND INSULATION BLANKET REPLACEMENT (SUPERSEDED BY SB 737-25-1663 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1663 R2	EQUIPMENT/FURNISHINGS - WINDOW SHADE AND REVEAL ASSEMBLY - BOEING SKY INTERIOR AUTOMATIC OVERWING EXIT DOOR WINDOW SHADE, REVEAL ASSEMBLY, AND INSULATION BLANKET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-DEC-2013			-				
SB 737-25-1665	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - CHANGE OVERWING EMERGENCY EXIT DOOR MOUNTED ARMREST PADS (SUPERSEDED BY SB 737-25-1665 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-APR-2012			-				
SB 737-25-1665 R1	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - CHANGE OVERWING EMERGENCY EXIT DOOR MOUNTED ARMREST PADS (SUPERSEDED BY SB 737-25-1665 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1665 R2	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - CHANGE OVERWING EMERGENCY EXIT DOOR MOUNTED ARMREST PADS (REPLACED BY SB 737-25-1663 R2), SERVICE BULLETIN					NOT APPLICABLE	
		MOS					
03-DEC-2013			-				
SB 737-25-1667	EQUIPMENT / FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - PARTITIONS - PLACARD REMOVAL NO CHILDREN THIS ROW, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-AUG-2012			-				
SB 737-25-1668	EQUIPMENT/FURNISHINGS - CABIN ATTENDANT STATIONS - REPLACEMENT OF FORWARD ATTENDANT CONTROL PANEL AND SHROUD FOR IMPROVED RELIABILITY - BOEING SKY INTERIOR AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-AUG-2012			-				
SB 737-25-1671	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - SIDEWALL PANEL ASSEMBLY - REPLACEMENT OF SIDEWALL PANEL ASSEMBLY AT GALLEY 2 INTERFACE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-MAR-2012			-				
SB 737-25-1672	EQUIPMENT/FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - INSTALL MEGAPHONES IN THE BOEING SKY INTERIOR LEFT FORWARD AND AFT TERMINATION OVERHEAD STOWAGE BINS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-MAR-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1677	EQUIPMENT / FURNISHINGS - ATTENDANT SEATS AND PANELS - ATTENDANT PANEL ASSEMBLY - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-DEC-2012			-				
SB 737-25-1678	EQUIPMENT / FURNISHINGS - AFT, LEFT SIDE PRIVACY CURTAIN - ENCLOSURE INSTALLATION (SUPERSEDED BY SB 737-25-1678 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-25-1678 R1	EQUIPMENT / FURNISHINGS - AFT, LEFT SIDE PRIVACY CURTAIN - ENCLOSURE INSTALLATION, SERVICE BULLETIN					OPERATORS DISCRETION	
		MOS					
26-AUG-2013			-				
SB 737-25-1679	EQUIPMENT/FURNISHINGS - PASSENGER SEAT - MOVE THE PASSENGER SEATS, CHANGE CARPETS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-MAR-2013			-				
SB 737-25-1680	EQUIPMENT / FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - WINDOW SHADE AND REVEAL ASSEMBLY - CHANGE THE WINDOW SHADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-MAR-2013			-				
SB 737-25-1681	EQUIPMENT/FURNISHING - PASSENGER CABIN LINING AND PANELS - SIDEWALL PANEL ASSEMBLY - CHANGE MEDICAL OUTLET PLACARD, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-SEP-2012			-				
SB 737-25-1682	EQUIPMENT / FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - WINDOW SHADE AND REVEAL ASSEMBLY - CHANGE THE WINDOW SHADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-MAR-2013			-				
SB 737-25-1684	EQUIPMENT/FURNISHINGS - PASSENGER COMPARTMENT - BOEING SKY INTERIOR OVERWING EXIT DOOR LINER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-MAY-2013			-				
SB 737-25-1685	EQUIPMENT/FURNISHINGS - PASSENGER CABIN LININGS AND PANELS - INSTALLATION OF ALUMINUM FOIL TAPE ON BACK SIDE OF SIDEWALL PANELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAR-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-25-1689	EQUIPMENT / FURNISHINGS - LAVATORIES - MODULAR LAVATORY A - REPLACE LAVATORY A THRESHOLD LIGHT WITH STRIKE PLATE (SUPERSEDED BY SB 737-25-1689 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-25-1689 R1	EQUIPMENT / FURNISHINGS - LAVATORIES - MODULAR LAVATORY A - REPLACE LAVATORY A THRESHOLD LIGHT WITH STRIKE PLATE, SERVICE BULLETIN					RECOMMENDED	
09-JUL-2014		MOS	- (s)				
SB 737-25-1691	EQUIPMENT/FURNISHINGS - PASSENGER CABIN PARTITIONS AND COMPARTMENTS - BOEING SKY INTERIOR OVERHEAD STOWAGE BINS - INSPECTION AND CHANGE OF THE THRESHOLD TRIM ASSEMBLY, SERVICE BULLETIN					OPERATORS DISCRETION	
04-SEP-2013		MOS	-				
SB 737-25-1693	EQUIPMENT / FURNISHINGS - PARTITIONS - REPLACEMENT OF JOGGLED CLASS DIVIDERS, SERVICE BULLETIN					RECOMMENDED	
28-JUN-2013		MOS	-				
SB 737-25-1702	EQUIPMENT/FURNISHINGS - DETACHABLE EMERGENCY EQUIPMENT - AFT RIGHT SIDE TERMINATION STOWAGE BIN CHANGE PORTABLE OXYGEN BOTTLES INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
23-JUN-2014		MOS	- (s)				
SB 737-25-1703	EQUIPMENT / FURNISHINGS- PASSENGER COMPARTMENT- PASSENGER SERVICE UNIT - REPLACE 12 MINUTE OXYGEN GENERATORS WITH 22 MINUTE OXYGEN GENERATORS, SERVICE BULLETIN					RECOMMENDED	
06-DEC-2013		MOS	-				
SB 737-25-1706	EQUIPMENT/FURNISHINGS - PASSENGER COMPARTMENT - SIDEWALL - AFT EMERGENCY EXIT, AUTOMATIC OVERWING (AOE) EXIT DOOR - LEFT AND RIGHT SIDE, SEAT INTRUSION CONTROL BLOCK INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
13-JUN-2014		MOS	-				
SB 737-25A1372	FLIGHT COMPUTER FWD INSTRUMENT PANEL ACCESS PANEL FASTENER INTERFERENCE, SERVICE BULLETIN						
20-MAY-1999		MOS	- (s)				
SB 737-25A1383 R1	RUDDER PEDAL COVER FASTENER INTERFERENCE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
02-DEC-1999		MOS	- (s)	13-SEP-1999			
SB 737-25A1626	EQUIPMENT/FURNISHINGS - ELECTRICAL EQUIPMENT RACK MOISTURE SHROUD - LIQUID CONTAMINATION PROTECTION IMPROVEMENTS ON THE E5 ELECTRONIC RACK DRIPSHIELD EQUIPMENT, SERVICE BULLETIN					RECOMMENDED	
25-MAR-2010		MOS	60	(EFF)	**25-MAR-2015**	25-MAR-2015	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	737-26-1112	CORROSION PROTECTION OF THE FENWAL CONNECTORS, SERVICE BULLETIN						
			MOS	6 (s)	(EFF)			
	06-DEC-2001							
SB	737-26-1112 R1	CORROSION PROTECTION OF THE FENWAL CONNECTORS, SERVICE BULLETIN						
			MOS	6 (s)				
	06-FEB-2003							
SB	737-26-1121	FIRE PROTECTION - LOWER CARGO COMPARTMENT SMOKE DETECTION - INSTALLATION OF FORWARD CARGO COMPARTMENT SMOKE PENETRATION SEALING PROVISIONS (SUPERSEDED BY 737-26-1121 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS					
	13-DEC-2007			- (s)				
+ SB	737-26-1121 R1	FIRE PROTECTION - LOWER CARGO COMPARTMENT SMOKE DETECTION - INSTALLATION OF FORWARD CARGO COMPARTMENT SMOKE PENETRATION SEALING PROVISIONS, SERVICE BULLETIN					RECOMMENDED	
			MOS	72 (s)				
	13-DEC-2007							
SB	737-26-1122	FIRE PROTECTION - LOWER CARGO COMPARTMENT SMOKE DETECTION - FORWARD CARGO COMPARTMENT SMOKE PENETRATION ELECTRICAL CHANGES (SUPERSEDED BY 737-26-1122 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS					
	13-DEC-2007			- (s)				
SB	737-26-1122 R1	LOWER CARGO COMPARTMENT SMOKE DETECTION - FORWARD CARGO COMPARTMENT SMOKE PENETRATION ELECTRICAL CHANGES, SERVICE BULLETIN					RECOMMENDED	
			MOS	72 (s)				
	13-AUG-2009							
SB	737-26-1123	REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	18-JAN-2005			-				
SB	737-26-1123 R1	FIRE PROTECTION - ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES, SERVICE BULLETIN						
			MOS					
	21-MAR-2005			-				
SB	737-26-1123 R2	FIRE PROTECTION - ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES, SERVICE BULLETIN						
			MOS					
	16-AUG-2007			-				
SB	737-26-1123 R3	FIRE PROTECTION - ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES, SERVICE BULLETIN						
			MOS					
	28-FEB-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-26-1123 R4	ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES, SERVICE BULLETIN						
		MOS					
20-AUG-2008			-				
SB 737-26-1123 R5	ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES (SUPERSEDED BY 737-26-1123 R6), SERVICE BULLETIN					SUPERSEDED	
		MOS					
27-APR-2009			-				
SB 737-26-1123 R6	FIRE PROTECTION - ENGINE FIRE DETECTION - REPLACEMENT OF THE LEFT AND RIGHT ENGINE CORE FIRE DETECTION HARNESSES (SUPERSEDED BY SB 737-26-1123 R7), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-26-1124	FIRE PROTECTION - WHEEL WELL, WING AND LOWER AFT BODY OVERHEAT DETECTION SYSTEM - MAIN WHEEL WELL CONNECTOR CORROSION PREVENTION, SERVICE BULLETIN						
		MOS					
12-JAN-2006			-				
SB 737-26-1131	FIRE PROTECTION - WHEEL WELL, WING, AND LOWER AFT BODY OVERHEAT DETECTION SYSTEM - DUCT LEAK OVERHEAT DETECTOR SUPPORT INSTALLATION (SUPERSEDED BY SB 737-26-1131 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-26-1131 R1	FIRE PROTECTION - WHEEL WELL, WING, AND LOWER AFT BODY OVERHEAT DETECTION SYSTEM - DUCT LEAK OVERHEAT DETECTOR SUPPORT INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-OCT-2011			-				
SB 737-26-1133	FIRE PROTECTION - CARGO FIRE EXTINGUISHING SYSTEM - INSTALLATION OF SECOND FIRE BOTTLE FOR EXTENDED RANGE TWIN ENGINE OPERATIONS (SUPERSEDED BY SB 737-26-1133 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-26A1099	ENGINE FIRE EXTINGUISHING BOTTLES, SERVICE BULLETIN					RECOMMENDED	
		DAYS	90 (s)		17-JAN-2001		
01-NOV-2000					634		
		AFL			175		
SB 737-26A1108 R1	ENGINES AND CARGO COMPARTMENT FIRE EXTINGUISHING BOTTLE HOSES INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	12 (s)				
27-JUN-2002							

© Camp Systems

EFTA00618333

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-26A1109	ENGINES, APU AND CARGO COMPARTMENT FIRE EXTINGUISHING BOTTLE HOSES AND WING-TO-STRUT ENGINE FUEL SUPPLY HOSES INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY
		MOS					
15-NOV-2001			- (s)				
SB 737-26A1109 R1	ENGINES, APU AND CARGO COMPARTMENT FIRE EXTINGUISHING BOTTLE HOSES AND WING-TO-STRUT ENGINE FUEL SUPPLY HOSES INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY
		MOS	18 (s)				
07-NOV-2002							
SB 737-26A1109 R2	ENGINES, APU AND CARGO COMPARTMENT FIRE EXTINGUISHING BOTTLE HOSES AND WING-TO-STRUT ENGINE FUEL SUPPLY HOSES INSPECTION AND REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY SERIAL NUMBER
		MOS		30-NOV-2005			
15-NOV-2001			- (s)	2338:24			
		AFL		573			
SB 737-26A1109 R3	ENTINGUISHING - ENGINES, APU AND CARGO COMPARTMENT FIRE EXTINGUISHING BOTTLE HOSES AND WING-TO-STRUT ENGINE FUEL SUPPLY HOSES INSPECTION AND REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - NO REWORK REQUIRED FOUND SB 737-26A1109 R2 ALREADY COMPLIED WITH AS NOT APPLICABLE 30-NOV-2005 (2338:24 HRS, 573 CYC) REF WO GUBBJ111-0202
		MOS		05-APR-2007			
29-SEP-2005			-	2871:09			
		AFL		676			
SB 737-26A1118	FIRE PROTECTION-ENGINE FIRE EXTINGUISHING BOTTLES-GROUNDS INSPECTION/CHECK, SERVICE BULLETIN					RECOMMENDED	
		DAYS	90 (s)				
17-OCT-2002							
SB 737-26A1118 R1	FIRE PROTECTION-ENGINE FIRE EXTINGUISHING BOTTLES-GROUNDS INSPECTION/CHECK, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY VARIABLE NUMBER.
		MOS		22-DEC-2004			
08-APR-2004			-	1951:36			
		AFL		476			
SB 737-26A1137	FIRE PROTECTION - CARGO BAY SMOKE DETECTION - EQUIPMENT COOLING SYSTEM SMOKE CLEARANCE MODE OPERATIONAL TEST FOR CARGO SMOKE PROTECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-MAY-2014			- (s)				
SB 737-26A1137 TABLE 1.1 CNF 1	PERFORM FIRE PROTECTION - CARGO BAY SMOKE DETECTION - EQUIPMENT COOLING SYSTEM SMOKE CLEARANCE MODE OPERATIONAL TEST FOR CARGO SMOKE PROTECTION, SERVICE BULLETIN A SMOKE CLEARANCE MODE - OPERATIONAL TEST (GROUP 1, CONFIGURATION 1 AIRPLANES)					RECOMMENDED	
		MOS	51 (s)				
22-MAY-2014							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-26A1137 TABLE 1.2 CNF 2	PERFORM FIRE PROTECTION - CARGO BAY SMOKE DETECTION - EQUIPMENT COOLING SYSTEM SMOKE CLEARANCE MODE OPERATIONAL TEST FOR CARGO SMOKE PROTECTION, SERVICE BULLETIN A SMOKE CLEARANCE MODE - OPERATIONAL TEST (GROUP 1, CONFIGURATION 2, GROUP 2 AND GROUP 3 AIRPLANES)						
		MOS	- (s)				
SB 737-26A1137 TABLE 1.3	PERFORM FIRE PROTECTION - CARGO BAY SMOKE DETECTION - EQUIPMENT COOLING SYSTEM SMOKE CLEARANCE MODE OPERATIONAL TEST FOR CARGO SMOKE PROTECTION, SERVICE BULLETIN A SYSTEM FAULT ISOLATION (IF THE SMOKE CLEARANCE MODE - OPERATIONAL TEST RESULT IS NOT SATISFACTORY)					RECOMMENDED	
22-MAY-2014		MOS	BF/F (s)				
SB 737-27-1210	HORIZ STAB-REPLACEMENT OF STAB TRIM ACTUATOR, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
28-OCT-1999			- (s)		3260:48		
		AFL			782		
SB 737-27-1210 R1	HORIZONTAL STABILIZER REPLACEMENT OF STABILIZER TRIM ACTUATOR, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS			22-AUG-2008		
01-JUN-2000			4500 (s)		3260:48		
		AFL			782		
SB 737-27-1215	FLIGHT CONTROLS - ELEVATOR AND TAB - INSTALLATION OF A 10-SECOND DELAY FOR THE RIGHT ELEVATOR ANTI-BALANCE TAB, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-APR-1999			- (s)				
SB 737-27-1215 R1	FLIGHT CONTROLS - ELEVATOR TAB - INSTALLATION OF A TAB, SERVICE BULLETIN			10-SECOND DELAY,RIGHT ELEVATOR ANTI-BALANCE		RECOMMENDED	
		MOS					
07-DEC-2000			- (s)				
SB 737-27-1224	AILERON & AILERON TRIM CONTROL SYSTEM, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS			19-JAN-2000		
21-OCT-1999			3200 (s)				
SB 737-27-1232	ELEVATOR AND TAB CONTROL SYSTEM TEST, SERVICE BULLETIN						
		MOS					
28-FEB-2002			- (s)				
SB 737-27-1240	MAIN WHEEL WELL AFT BULKHEAD STANDBY SHUT-OFF VALVE GROUND WIRE INSTALLATION MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	18 (s)				
10-MAY-2001			6000				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1242	FLIGHT CONTROLS - LIFT AUGMENTING - LEADING EDGE - CRUISE DEPRESSURIZATION VALVE MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-MAR-2001			- (s)				
SB 737-27-1242 R1	LIFT AUGMENTING - LEADING EDGE - CRUISE DEPRESSURIZATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-SEP-2002			- (s)				
SB 737-27-1244	ELEVATOR FEEL COMPUTER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-JUN-2001			- (s)				
SB 737-27-1247 R1	WIRE PROVISIONS FOR RUDDEER SYSTEM ENHANCEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - IAW THE SB REV.1 N/A FOR AIRCRAFT REV 00 ALREADY C/W.
		MOS			13-AUG-2007		
25-JUL-2002			- (s)		1785:05		
		AFL			446		
SB 737-27-1247 R2	RUDDER AND RUDDER TRIM CONTROL SYSTEM - WIRE PROVISIONS FOR RUDDER SYSTEM ENHANCEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
26-NOV-2008			- (s)				
SB 737-27-1248	FLIGHT CONTROLS - ELEVATOR PITOT-STATIC SYSTEM - TURN THE PITOT PROBE DOWN, SERVICE BULLETIN						
		MOS					
24-JAN-2002			- (s)				
SB 737-27-1251	STALL MANAGEMENT YAW DAMPER (SMYD)-REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JUL-2002			- (s)				
SB 737-27-1251 R1	STALL MANAGEMENT YAW DAMPERS(SMYD) REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-FEB-2003			-				
SB 737-27-1253	INSTALLATION OF AN ENHANCED RUDDER CONTROL SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-JAN-2003			-				
SB 737-27-1253 R1	INSTALLATION OF AN ENHANCED RUDDER CONTROL SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-MAR-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1253 R2	INSTALLATION OF AN ENHANCED RUDDER CONTROL SYSTEM (RSEP), SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-OCT-2004			-				
SB 737-27-1253 R3	FLIGHT CONTROLS - RUDDER AND RUDDER TRIM CONTROL SYSTEM - INSTALLATION OF AN ENHANCED RUDDER CONTROL SYSTEM (RSEP), SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
12-MAY-2006			- (s)	3260:48			
		AFL		782			
SB 737-27-1253 R4	RUDDER AND RUDDER TRIM CONTROL SYSTEM - INSTALLATION OF AN ENHANCED RUDDER CONTROL SYSTEM (RSEP) - TEST, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAY-2009			-				
SB 737-27-1254	FLIGHT CONTROLS-CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING (SUPERSEDED BY 737-27-1254 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
31-OCT-2002			- (s)				
SB 737-27-1254 E. 1	INSPECT FLIGHT CONTROLS-CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING (SUPERSEDED BY 737-27-1254 R1), SERVICE BULLETIN UNPROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING					RECOMMENDED	
		MOS				RECURRING	
31-OCT-2002			-				
SB 737-27-1254 E. 2	INSPECT FLIGHT CONTROLS-CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING (SUPERSEDED BY 737-27-1254 R1), SERVICE BULLETIN PROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING					RECOMMENDED	
		MOS				RECURRING	
31-OCT-2002			-				
SB 737-27-1254 R1	CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING-INSPECTION AND REPLACEMENT (SUPERSEDED BY 737-27-1254 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
14-APR-2003			-				
SB 737-27-1254 R1 E. 1	INSPECT CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING-INSPECTION AND REPLACEMENT (SUPERSEDED BY 737-27-1254 R2), SERVICE BULLETIN UNPROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING					RECOMMENDED	
		MOS				RECURRING	
14-APR-2003			-				
SB 737-27-1254 R1 E. 2	INSPECT CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING-INSPECTION AND REPLACEMENT (SUPERSEDED BY 737-27-1254 R2), SERVICE BULLETIN PROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING					RECOMMENDED	
		MOS				RECURRING	
14-APR-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1254 R1 E. 3	REPLACE CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING-INSPECTION AND REPLACEMENT (SUPERSEDED BY 737-27-1254 R2), SERVICE BULLETIN CONTROL CABLE ASSEMBLIES						
		MOS	24 (s)				
17-APR-2003							
SB 737-27-1254 R2	CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING - INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
02-JUL-2008			-				
SB 737-27-1254 R2 E.1	INSPECT CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING - INSPECTION AND REPLACEMENT, SERVICE BULLETIN UNPROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING						
		MOS	9 (s)				
02-JUL-2008							
SB 737-27-1254 R2 E.2	INSPECT CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PROTECTED CONTROL CABLE ASSEMBLIES WITH "LOW ZINC" COATING						
		MOS	12 (s)				
02-JUL-2008							
SB 737-27-1254 R2 E.3	REPLACE CONTROL CABLE ASSEMBLIES WITH LOW ZINC COATING - INSPECTION AND REPLACEMENT, SERVICE BULLETIN CONTROL CABLE ASSEMBLIES						
		MOS	24 (s)				
02-JUL-2008							
SB 737-27-1262	RUDDER AND RUDDER TRIM CONTROL SYSTEM-REPLACEMENT OF THE P5-3 PANEL (RSEP)., SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY
		MOS			22-AUG-2008		
19-DEC-2002			- (s)		3260:48		
		AFL			782		
SB 737-27-1262 R1	RUDDER AND RUDDER TRIM CONTROL SYSTEM - REPLACEMENT OF THE P5-3 PANEL (RSEP), SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAY-2009			-				
SB 737-27-1268	FLIGHT CONTROLS - HORIZONTAL STABLIZER TRIM CONTROL SYSTEM - STABLIZER TRIM AND LIMIT SWITCHES WIRE BUNDLE PROTECTION, SERVICE BULLETIN						- INFORMATION REF TO R1
		MOS					
12-OCT-2006			-				
SB 737-27-1268 R1	HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - STABILIZER TRIM AND LIMIT SWITCHES WIRE BUNDLE PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - GROUP 1 A/C WIRE BUNDLES INSPECTED. IAW SB737-27-1268 R1 FIGURE 1, GROUP 2 A/C WIRE BUNDLES INSPECTED IAW SB 737-27-1268 R1 FIGURE 2., IAW SB 737-27-1268 R1 FIGURE 3
		MOS			29-AUG-2011		
26-MAR-2009			-		3533:32		
		AFL			863		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1270	RUDDER FEEL AND CENTERING UNIT-CAM ROLLER BOLT TO FLANGE CLEARANCE-INSPECTION AND REWORK, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-OCT-2003			-				
SB 737-27-1273	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS		24-AUG-2007			
29-SEP-2005			-	2968:28			
		AFL		699			
SB 737-27-1273 PART 1	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS	24 (s)	24-AUG-2007			
29-SEP-2005			8000	2968:28			
		AFL		699			
SB 737-27-1273 PART 2	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS	12 (s)	24-AUG-2007			
29-SEP-2005			4000	2968:28			
		AFL		699			
SB 737-27-1273 R1	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS		24-AUG-2007			
19-DEC-2006			-	2968:28			
		AFL		699			
SB 1 737-27-1273 R1 PART	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS	24 (s)	24-AUG-2007			
19-DEC-2006			8000	2968:28			
		AFL		699			
SB 2 737-27-1273 R1 PART	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS	12 (s)	24-AUG-2007			
19-DEC-2006			4000	2968:28			
		AFL		699			
SB 737-27-1273 R2	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2006-21-01 PART 1 AND PART 2
		MOS		03-JUL-2013			
23-APR-2007			-	3723:21			
		AFL		908			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1273 R2 PART 1	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2006-21-01 PART 1
		MOS	24 (s)	03-JUL-2013			
23-APR-2007			8000	3723:21			
		AFL		908			
SB 737-27-1273 R2 PART 2	FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - AILERON BALANCE TAB FREEPLAY CHECK AND LUBRICATION, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2006-21-01 PART 2
		MOS	12 (s)	03-JUL-2013			
23-APR-2007			4000	3723:21			
		AFL		908			
SB 737-27-1282	FLIGHT CONTROLS - RUDDER AND RUDDER TRIM CONTROL SYSTEM - WIRE BUNDLE W443 AND LEFT FORWARD RUDDER QUADRANT CLEARANCE INSPECTION (SUPERSEDED BY 737-27-1282 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
15-MAR-2007			- (s)				
SB 737-27-1282 R1	FLIGHT CONTROLS - RUDDER AND RUDDER TRIM CONTROL SYSTEM - WIRE BUNDLE W443 AND LEFT FORWARD RUDDER QUADRANT CLEARANCE INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
14-JUN-2010							
SB 737-27-1284	FLIGHT CONTROLS - ELEVATOR AND TAB - LEFT AND RIGHT ELEVATOR TAB PUSHRODS REPLACEMENT, SERVICE BULLETIN						
		MOS	48 (s)				
28-NOV-2007							
SB 737-27-1284 R1	ELEVATOR AND TAB - LEFT AND RIGHT ELEVATOR TAB PUSHRODS REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS		29-AUG-2011			
28-NOV-2007			- (s)	3533:32			
		AFL		863			
SB 737-27-1289	737 STABILIZER TAKEOFF WARNING SWITCHES - TEST OF THE TAKEOFF WARNING INDICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		DAYS		29-AUG-2011		RECURRING	
07-APR-2010			750	3533:32	**4283:32**		
		AFL		863			
SB 737-27-1290	TRAILING EDGE FLAP SYSTEM - FLAP LIMIT SWITCH AND FLAP LANDING WARNING SWITCH REPLACEMENT (SUPERSEDED BY SB 737-27-1290 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-27-1290 R1	FLIGHT CONTROLS - TRAILING EDGE FLAP SYSTEM - FLAPS UP LIMIT SWITCH AND FLAP LANDING WARNING LIMIT SWITCH REPLACEMENT (SUPERSEDED BY SB 737-27-1290 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27-1290 R2	FLIGHT CONTROLS - TRAILING EDGE FLAP SYSTEM - FLAPS UP AND FLAP LANDING WARNING LIMIT SWITCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-OCT-2011			-				
SB 737-27-1290 R3	FLIGHT CONTROLS - TRAILING EDGE FLAP SYSTEM - FLAPS UP AND FLAP LANDING WARNING LIMIT SWITCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-APR-2012			-				
SB 737-27-1290 R4	FLIGHT CONTROLS - TRAILING EDGE FLAP SYSTEM - FLAPS UP AND FLAP LANDING WARNING LIMIT SWITCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-NOV-2012			-				
SB 737-27-1291	LEADING EDGE FLAP AND SLAT CONTROL SYSTEM - LEADING EDGE SLATS - TITANIUM PROXIMITY SENSOR PROVISIONAL INSTALLATION (SUPERSEDED BY SB 737-27-1291 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-27-1291 R1	LEADING EDGE FLAP AND SLAT CONTROL SYSTEM - LEADING EDGE SLATS - TITANIUM PROXIMITY SENSOR PROVISIONAL INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-NOV-2010			-				
SB 737-27-1298	FLIGHT CONTROLS - CENTRAL WARNING SYSTEM - SPEEDBRAKE TAKEOFF WARNING SWITCH, S651 - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-AUG-2010			-				
SB 737-27-1300	FLIGHT CONTROLS - ELEVATOR AND TAB - ELEVATOR TAB CONTROL MECHANISM - AFT ATTACH LUG MODIFICATION (SUPERSEDED BY SB 737-27-1300 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-27-1300 R1	FLIGHT CONTROLS - ELEVATOR AND TAB - ELEVATOR TAB CONTROL MECHANISM - AFT ATTACH LUG MODIFICATION, SERVICE BULLETIN						
		MOS					
			-				
SB 737-27-1303	FLIGHT CONTROLS - FLIGHT SPOILER CONTROL SYSTEM - LEFT AND RIGHT WING FLIGHT SPOILERS SHORT FIELD PERFORMANCE POWER CONTROL UNIT REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-JUN-2012			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1219	FLAP/SLAT ELECTRONICS UNIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-SEP-1998			- (s)				
SB 737-27A1222	MAIN RUDDER POWER CONTROL UNIT (SUPERSEDED BY SB 737-27A1222 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - C/W
		MOS		13-SEP-1999			
			- (s)				
SB 737-27A1222 R1	MAIN RUDDER POWER CONTROL UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		13-SEP-1999			
28-JAN-1999			- (s)				
SB 737-27A1228	TRAILING EDGE FLAP AND HORIZONTAL STABILIZER TRIM SYSTEMS (SUPERSEDED BY SB 737-27A1228 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		13-SEP-1999			
			- (s)				
SB 737-27A1228 R1	TRAILING EDGE FLAP AND HORIZONTAL STABILIZER TRIM SYSTEMS (SUPERSEDED BY SB 737-27A1228 R2), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - C/W
		MOS		13-SEP-1999			
			- (s)				
SB 737-27A1228 R2	TRAILING EDGE FLAP AND HORIZONTAL STABILIZER TRIM SYSTEMS (SUPERSEDED BY SB 737-27A1228 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-27A1228 R3	TRAILING EDGE FLAP AND HORIZONTAL STABILIZER TRIM SYSTEMS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		13-SEP-1999			
18-NOV-1999			300 (s)	23:30			
		AFL		21			
SB 737-27A1234	ELEVATOR-PCU RETENTION BRACKET AND BOLT (SUPERSEDED BY SB 737-27A1234 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-27A1234 R1	ELEVATOR-PCU RETENTION BRACKET AND BOLT, SERVICE BULLETIN					RECOMMENDED	
		DAYS	7 (s)	22-NOV-2001			
10-AUG-2000				854:54			
		AFL		225			
SB 737-27A1239	FLIGHT CONTROLS - RUDDER AND RUDDER TRIM CONTROL SYSTEM - RELOCATION OF WIRE BUNDLES AWAY FROM THE RUDDER FEEL AND CENTERING UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
11-JAN-2001			- (s)	3260:48			
		AFL		782			

© Camp Systems

EFTA00618342

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1245	EXCESSIVE FREEPLAY IN THE TAB CONTROL (SUPERSEDED BY SB 737-27A1245 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - C/W
		MOS		26-APR-2001			
			- (s)				
SB 737-27A1245 R1	EXCESSIVE FREEPLAY IN THE TAB CONTROL (SUPERSEDED BY SB 737-27A1245 R2) , SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-27A1245 R2	EXCESSIVE FREEPLAY IN THE TAB CONTROL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-AUG-2002			- (s)				
SB 737-27A1259	RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-MAY-2002			- (s)				
SB 737-27A1259 PART A	INSPECT/REPLACE RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN SPRING ASEMBLY					RECOMMENDED	
		DAYS	10 (s)				
30-MAY-2002							
SB 737-27A1259 PART B	INSPECT/REPLACE RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN SPRING ASSEMBLY					RECOMMENDED	
		DAYS	90 (s)				
30-MAY-2002							
SB 737-27A1259 R1	RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-DEC-2002			-				
SB A 737-27A1259 R1 PART	INSPECT RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		DAYS	10 (s)				
19-DEC-2002							
SB B 737-27A1259 R1 PART	REPLACE RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		DAYS	90 (s)				
19-DEC-2002							
SB 737-27A1260	REPLACEMENT OF COMPENSATORS, SERVICE BULLETIN						
		DAYS	180 (s)				
07-OCT-2002							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1271	ELEVATOR INPUT TORQUE TUBE MODIFICATION (SUPERSEDED BY SB 737-27A1271 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
			-	3260:48			
		AFL		782			
SB 737-27A1271 R1	FLIGHT CONTROLS - ELEVATOR AND TAB - ELEVATOR INPUT TORQUE TUBE - MODIFICATION, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY 737-27A1271
		MOS					
			-				
SB 737-27A1277	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION, LUBRICATION AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - PAC 1(1) INSPECTION - NEX DUE 15/AUG/2009 - 9368HRS / PAC 1(2) LUBRICATION NEXT DUE 15/AUG/2008 - 4568 HRS / HSTA REPLACEMENT DUE 25,0000 AFL/CYC TO BE ACCOMPLISHED IN REV 1 OF THIS SB
		MOS		24-AUG-2007			
			-	2968:28			
		AFL		699			
SB 737-27A1277 PAC 1 (1)	DETAILED INSPECTION FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION, LUBRICATION AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - PAC 1(1) INSPECTION - NEX DUE 15/AUG/2009 - 9368HRS IN REV.1
		MOS	24 (s)	24-AUG-2007			
21-JUL-2005			2000	2968:28			
		AFL		699			
SB 737-27A1277 PAC 1 (2)	LUBRICATE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION, LUBRICATION AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - NEXT DUE 15/AUG/2008 - 4568 HRS IN REV 1 OF THIS SB
		MOS	12 (s)	24-AUG-2007			
21-JUL-2005			1600	2968:28			
		AFL		699			
SB 737-27A1277 PAC 2	REPLACE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION, LUBRICATION AND REPAIR/OVERHAUL, SERVICE BULLETIN BALL NUT TUBE RETAINERS						- REF: REV.1
		MOS					
21-JUL-2005			25000 (s)				
SB 737-27A1277 PAC 3	REPLACE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION, LUBRICATION AND REPAIR/OVERHAUL, SERVICE BULLETIN HORIZONTAL STABILIZER TRIM ACTUATOR						- REF: REV.1
		MOS					
21-JUL-2005			25000 (s)				
SB 737-27A1277 R1	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - PAC 1 (1) INSPECTION AND PAC 1 (2) LUBERICATION REFER NEXT TO REV.2
		MOS		28-SEP-2009			
25-JUL-2007			-	3378:04			
		AFL		812			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB (1) 737-27A1277 R1 PAC 1	DETAIL INSPECTION FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - REFER NEXT COMPLIANCE IN REV.2
		MOS	24 (s)	28-SEP-2009			
27-JUL-2007			6400	3378:04			
		AFL		812			
SB (2) 737-27A1277 R1 PAC 1	LUBRICATE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN						COMPLIED WITH - REFER NEXT COMPLIANCE IN REV.2
		MOS	12 (s)	28-SEP-2009			
25-JUL-2007			1600	3378:04			
		AFL		812			
SB 737-27A1277 R1 PAC 2	REPLACE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN BALL NUT TUBE RETAINERS						- INFORMATION REFER TO REV.2
		MOS					
25-JUL-2007			25000 (s)				
SB 737-27A1277 R1 PAC 3	REPLACE FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN HORIZONTAL STABILIZER TRIM ACTUATOR						COMPLIED WITH - REPLACEMENT PER 737-27-1210/R1 PN 251A4510-6 TSO "0". UPDATED COMPONENT TASK 27-108-00 WITH THE COMPLETION DATE OF THIS S/B. FURTURE TRACKING OF THIS S/B WILL BE ACCOMPLISHED PER 27-108-00
		MOS		22-AUG-2008			
25-JUL-2007			-	3260:48			
		AFL		782			
SB 737-27A1277 R2	HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - INSPECTION AND LUBRICATION I.A.W. AD 2011-27-03
		MOS		03-JUL-2013			
08-JAN-2010			-	3723:21			
		AFL		908			
SB (1) 737-27A1277 R2 PAC 1	DETAIL INSPECTION HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - I.A.W. AD 2011-27-03
		MOS	24 (s)	03-JUL-2013			
08-JAN-2010			6400	3723:21			
		AFL		908			
SB (2) 737-27A1277 R2 PAC 1	LUBRICATE HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - I.A.W. AD 2011-27-03
		MOS	12 (s)	03-JUL-2013			
08-JAN-2010			1600	3723:21			
		AFL		908			
SB 737-27A1277 R2 PAC 2	REPLACE HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN BALL NUT TUBE RETAINERS					RECOMMENDED	- INFO REFERENCE TO AD 2011-27-03
		MOS					
19-DEC-2002			25000 (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1277 R2 PAC 3	REPLACE HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND BALL NUT INSPECTION , LUBRICATION, AND REPAIR/OVERHAUL, SERVICE BULLETIN HORIZONTAL STABILIZER TRIM ACTUATOR					RECOMMENDED	- INFORMATION REFERENCE REV.1 PREVIOUSLY CW 22-AUG-2008 REPLACEMENT PER 737-27-1210/R1 PN 251A4510-6 TSO "0". UPDATED COMPONENT TASK 27-108-00 WITH THE COMPLETION DATE OF THIS S/B. FURTURE TRACKING OF THIS S/B WILL BE ACCOMPLISHED PER 27-108-00
		MOS					
19-DEC-2002			-				
SB 737-27A1279	RUDDER - RUDDER AND RUDDER TRIM CONTROL SYSTEM - MAIN RUDDER POWER CONTROL UNIT INPUT CONTROL RODS AND STANDBY RUDDER POWER CONTROL UNIT INPUT CONTROL ROD - REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY N/A BY LINE NO.
		MOS		28-OCT-2007			
			-				
SB 737-27A1279 R1	MAIN RUDDER POWER CONTROL UNIT INPUT CONTROL RODS AND STANDBY RUDDER POWER CONTROL UNIT INPUT CONTROL ROD - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY YG091–YG096 EFFECTED AIRCRAFT
		MOS					
11-JAN-2010			-				
SB 737-27A1280	RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN						NOT APPLICABLE - NO PCU CONTROL RODS PREVIOUSLY CHANGED.
		MOS		08-DEC-2006			
25-MAY-2006			-	2785:43			
		AFL		661			
SB 737-27A1280 R1	RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
24-MAY-2007			-	3260:48			
		AFL		782			
SB 737-27A1280 R1 TABLE 1	MONITOR TEST RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN RUDDER MAIN POWER CONTROL UNIT (PCU) FORCE FLIGHT						
		DAYS	90 (s)				
24-MAY-2007							
SB 737-27A1280 R1 TABLE 2	OPERATIONAL TEST RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN OF THE STANDBY HYDRAULIC ACTUATION SYSTEM						
		DAYS	60 (s)				
16-FEB-2007							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1280 TABLE 1	MONITOR TEST RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN RUDDER MAIN POWER CONTROL UNIT (PCU) FORCE FLIGHT						NOT APPLICABLE - NO PCU CONTROL RODS PREVIOUSLY CHANGED.
		DAYS		08-DEC-2006			
25-MAY-2006			6000 (s)	2785:43			
		AFL		661			
SB 737-27A1280 TABLE 2	OPERATIONAL TEST RUDDER AND RUDDER TRIM CONTROL SYSTEM - OPERATIONAL TEST OF THE STANDBY HYDRAULIC ACTUATION SYSTEM AND RUDDER MAIN POWER CONTROL UNIT FORCE FIGHT MONITOR TEST - TEST FREQUENCY CHANGE, SERVICE BULLETIN OF THE STANDBY HYDRAULIC ACTUATION SYSTEM						NOT APPLICABLE - NO PCU CONTROL RODS PREVIOUSLY CHANGED.
		DAYS		08-DEC-2006			
25-MAY-2006			500 (s)	2785:43			
		AFL		661			
SB 737-27A1283	FLIGHT CONTROLS - SPOILER, DRAG DEVICES, AND VARIABLE AERODYNAMIC FAIRINGS - LEFT AND RIGHT WING FLIGHT SPOILERS SHORT FIELD PERFORMANCE ACTUATOR REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY APPLICABLE TO 737-800 SERIES AIRCRFAT ONLY.
		MOS		18-OCT-2007			
03-APR-2007			-				
SB 737-27A1287	RUDDER FEEL AND CENTERING UNIT - INSPECTION AND REPLACEMENT OF SPRING ASSEMBLY, SERVICE BULLETIN						- N/A BY LINE NO.
		MOS		03-NOV-2009			
16-APR-2008			-	3391			
		AFL		817			
SB 737-27A1296	ELAVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - IAW THE AD
		MOS		19-MAY-2010			
			-	3438:54			
		AFL		835			
SB 737-27A1296 R1	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-27A1297	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-27A1297 R1	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1297 R1 TABLE 1.03	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R2), SERVICE BULLETIN OF THE LEFT SIDE ELEVATOR TAB CONTROL MECHANISM (GROUP 3)					RECOMMENDED	COMPLIED WITH
		DAYS	180 (s)		28-FEB-2011		
02-AUG-2010			1800		3525:36		
		AFL			857		
SB 737-27A1297 R1 TABLE 1.04	REPLACE FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R2), SERVICE BULLETIN THE LEFT SIDE ELEVATOR TAB CONTROL MECHANISM AND DO DETAILED INSPECTION BEFORE AND AFTER INSTALLING IT (IF ELEVATOR TAB CONTROL MECHANISM IS FOUND TO BE DISCREPANT OR REPLACEMENT ELEVATOR TAB CONTROL MECHANISM IS FOUND TO BE DISCREPANT)					RECOMMENDED	
		MOS					
			BF/F				
SB 737-27A1297 R1 TABLE 2.03	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R2), SERVICE BULLETIN OF THE RIGHT SIDE ELEVATOR TAB CONTROL MECHANISM (GROUP 3)					RECOMMENDED	COMPLIED WITH
		DAYS	180 (s)		28-FEB-2011		
02-AUG-2010			1800		3525:36		
		AFL			857		
SB 737-27A1297 R1 TABLE 2.04	REPLACE FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION (SUPERSEDED BY SB 737-27A1297 R2), SERVICE BULLETIN THE RIGHT SIDE ELEVATOR TAB CONTROL MECHANISM AND DO DETAILED INSPECTION BEFORE AND AFTER INSTALLING IT (IF ELEVATOR TAB CONTROL MECHANISM IS FOUND TO BE DISCREPANT OR REPLACEMENT ELEVATOR TAB CONTROL MECHANISM IS FOUND TO BE DISCREPANT)					RECOMMENDED	
		MOS					
			BF/F				
SB 737-27A1297 R2	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-APR-2012			-				
SB 737-27A1297 R2 TABLE (1)	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION, SERVICE BULLETIN OF THE LEFT SIDE ELEVATOR TAB CONTROL MECHANISM					RECOMMENDED	
		MOS				RECURRING	
			1800	(EFF)	**5325:36 M**		
SB 737-27A1297 R2 TABLE (2)	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION, SERVICE BULLETIN OF THE RIGHT SIDE ELEVATOR TAB CONTROL MECHANISM					RECOMMENDED	
		MOS				RECURRING	
			1800	(EFF)	**5325:36 M**		
SB 737-27A1299	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION AND BEARING RETAINER INSTALLATION (SUPERSEDED BY SB 737-27A1299 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-27A1299 R1	FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION AND BEARING RETAINER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS		(EFF)			
16-APR-2012			-				
SB 737-27A1299 R1 TABLE 1	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION AND BEARING RETAINER INSTALLATION, SERVICE BULLETIN THE ELEVATOR TAB CONTROL MECHANISM ALL AIRPLANES AND REPORT ALL INITIAL INSPECTION RESULTS AND DATE OF BEARING RETAINER INSTALLATION TO BOEING					RECOMMENDED	
		DAYS	30 (s)				
SB 737-27A1299 R1 TABLE 2 INSP	DETAILED INSPECTION FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION AND BEARING RETAINER INSTALLATION, SERVICE BULLETIN OF THE BEARING RETAINERS AND THE ELEVATOR TAB CONTROL MECHANISM WITH BEARING RETAINERS INSTALLED.					RECOMMENDED	
		MOS	800 (s)				
		AFL	400				
SB 737-27A1299 R1 TABLE 2 REPORT	REPORT FLIGHT CONTROLS - ELEVATOR TAB CONTROL MECHANISM DETAILED INSPECTION AND BEARING RETAINER INSTALLATION, SERVICE BULLETIN ALL DISCREPANT MECHANISM FINDINGS FROM REPEAT INSPECTIONS TO BOEING INCLUDING WHICH REPEAT THE FAILED INSPECTION OCCURRED FOR ALL AIRPLANES: AFTER THE DETAILED INSPECTION					RECOMMENDED	
		DAYS	30 (s)				
SB 737-28-1152	P5-2 FUEL CONTROL MODULE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-MAY-2001			- (s)				
SB 737-28-1155	CENTER FUEL TANK SCAVENGE SYSTEM, SERVICE BULLETIN						
		MOS					
19-OCT-2000			-				
SB 737-28-1160	SPARE VALVE DUAL WIRE VERIFICATION TEST, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-JUN-2000			- (s)				
SB 737-28-1160 R1	ENGINE FUEL FEED SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)		31-AUG-2001		
26-OCT-2000					793:18		
		AFL			212		
SB 737-28-1172	INTEGRAL FUEL TANKS - ALIGNMENT OF CENTER TANK BOOST PUMP INLETS AND FUEL PUMP ALIGNMENT BRACKETRY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-APR-2002			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1172 R1	FUEL - STORAGE - INTEGRAL FUEL TANKS - ALIGNMENT OF CENTER TANK BOOST PUMP INLETS AND FUEL PUMP ALIGNMENT BRACKETRY, SERVICE BULLETIN						
		MOS					
04-JUN-2007			-				
SB 737-28-1173	APU FUEL FEED LINE SHROUD, INSPECTION FOR ADEQUATE CLEARANCE AND REPAIR, SERVICE BULLETIN						
		MOS					
17-JAN-2002			- (s)				
SB 737-28-1173 R1	APU FUEL FEED LINE SHROUD, INSPECTION FOR ADEQUATE CLEARANCE AND REPAIR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-NOV-2004			-				
SB 737-28-1173 R2	FUEL SYSTEM - DISTRIBUTION - APU FUEL FEED LINE SHROUD, INSPECTION FOR ADEQUATE CLEARANCE AND REPAIR, SERVICE BULLETIN						
		MOS					
23-FEB-2006			-				
SB 737-28-1179	P5-2 FUEL SYSTEM MODULE REMOVAL AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS			27-AUG-2002		
31-JAN-2002			-		1057:50		
		AFL			271		
SB 737-28-1179 R1	P5-2 FUEL SYSTEM MODULE REMOVAL AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
28-FEB-2002			- (s)				
SB 737-28-1179 R2	P5-2 FUEL SYSTEM MODULE REMOVAL AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-DEC-2004			-				
SB 737-28-1190	FUEL-FUEL QUANTITY INDICATING SYSTEM (FQIS)-CENTER FUEL TANK WIRE SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	18 (s)				
16-JAN-2003							
SB 737-28-1190 R1	FUEL-FUEL QUANTITY INDICATING SYSTEM (FQIS)-CENTER FUEL TANK WIRE SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS			18-AUG-2006		
27-MAR-2003			- (s)		2633:50		
		AFL			633		
SB 737-28-1194	RELOCATION OF CONNECTOR PINS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-FEB-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1194 R1	RELOCATION OF CONNECTOR PINS AT WING/BODY CONNECTORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
31-JUL-2003			-				
SB 737-28-1194 R2	RELOCATION OF CONNECTOR PINS AT WING/BODY CONNECTORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-JAN-2004			-				
SB 737-28-1194 R3	FUEL - FUEL BOOST PUMP - RELOCATION OF CONNECTOR PINS AT WING/BODY CONNECTORS, SERVICE BULLETIN						
		MOS					
18-SEP-2007			-				
SB 737-28-1199	ENGINE FUEL SHUTOFF VALVE WIRE AND CONDUIT ASSEMBLY REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS		18-AUG-2006			
09-SEP-2004			- (s)	2633:50			
		AFL		633			
SB 737-28-1199 R1	FUEL - ENGINE FUEL FEED SYSTEM - ENGINE FUEL SHOUTOFF VALVE WIRE AND CONDUIT ASSEMBLY REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS		18-AUG-2006			
15-DEC-2005			- (s)	2633:50			
		AFL		633			
SB 737-28-1199 R2	FUEL - ENGINE FUEL FEED SYSTEM - ENGINE FUEL SHUTOFF VALVE WIRE AND CONDUIT ASSEMBLY REPLACEMENT, SERVICE BULLETIN						
		MOS	36 (s)				
17-JUL-2006							
SB 737-28-1200	INSPECTION FOR WIRE CHAFING BEHIND P15 REFUEL PANEL, SERVICE BULLETIN						COMPLIED WITH - NO CHAFING FOUND
		MOS	24 (s)	01-JUN-2007			
10-JUL-2003				2955:24			
		AFL		691			
SB 737-28-1200 R1	FUEL - PRESSURE FUELING SYSTEM - INSPECTION FOR WIRE CHAFING BEHIND P15 REFUEL PANEL, SERVICE BULLETIN						COMPLIED WITH - NO CHAFING FOUND
		MOS		01-JUN-2007			
28-JUL-2005			- (s)	2955:24			
		AFL		691			
SB 737-28-1209	FUEL - INDICATING - WING CENTER TANK WIRE BUNDLES INSTALLATION CHANGE (SUPERSEDED BY SB 737-28-1209 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		18-AUG-2006			
			- (s)	2633:50			
		AFL		633			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1209 R1	FUEL - INDICATING - WING CENTER TANK WIRE BUNDLES INSTALLATION CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
21-DEC-2005							
SB 737-28-1225	FUEL - DISTRIBUTION - ENGINE FUEL FEED SYSTEM - INSPECTION/REPAIR OF THE ELECTRICAL BOND BETWEEN THE BULKHEAD FITTING AND THE WING FRONT SPAR, SERVICE BULLETIN						NOT APPLICABLE - REF: TO R1
		MOS		22-AUG-2008			
12-JAN-2006			- (s)	3260:48			
		AFL		782			
SB 737-28-1225 R1	FUEL - DISTRIBUTION - ENGINE FUEL FEED SYSTEM - INSPECTION/REPAIR OF THE ELECTRICAL BOND BETWEEN THE BULKHEAD FITTING AND THE WING FRONT SPAR, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
30-OCT-2006			- (s)	3260:48			
		AFL		782			
SB 737-28-1251	FUEL - BOOST PUMP CONTROL RELAY - GROUND MODULE INSPECTION AND REPLACEMENT IF NECESSARY, SERVICE BULLETIN						- INFORMATION REF COMPLIANCE OF 737-28-1257
		DAYS	90 (s)				
20-OCT-2005							
SB 737-28-1251 R1	FUEL - ENGINE FUEL FEED SYSTEM - GROUND MODULE INSPECTION AND REPLACEMENT, SERVICE BULLETIN						- INFORMATION REF COMPLIANCE OF 737-28-1257
		DAYS	90 (s)				
27-APR-2006							
SB 737-28-1251 R2	FUEL - ENGINE FUEL FEED SYSTEM - GROUND MODULE INSPECTION AND REPLACEMENT, SERVICE BULLETIN						- INFORMATION REF COMPLIANCE OF 737-28-1257
		DAYS	90 (s)				
26-OCT-2006							
SB 737-28-1257	FUEL - ENGINE FUEL FEED SYSTEM - BOOST PUMP CONTROL RELAY GROUND LOCATION CHANGE, SERVICE BULLETIN						COMPLIED WITH
		MOS		14-FEB-2008			
26-FEB-2007			- (s)	3151:22			
		AFL		746			
SB 737-28-1257 R1	FUEL - ENGINE FUEL FEED SYSTEM - BOOST PUMP CONTROL RELAY GROUND LOCATION CHANGE, SERVICE BULLETIN						COMPLIED WITH
		MOS		14-FEB-2008			
28-NOV-2007			- (s)	3151:22			
		AFL		746			
SB 737-28-1272	ENGINE FUEL FEED SYSTEM - MAIN TANKS ENGINE FUEL SPAR VALVE BODY REPLACEMENT (SUPERSEDED BY SB 737-28-1272 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS		29-AUG-2011			
			-	3533:32			
		AFL		863			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1272 R1	FUEL - ENGINE FUEL FEED SYSTEM - MAIN TANKS ENGINE FUEL SPAR VALVE BODY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
18-FEB-2010							
SB 737-28-1283	FUEL QUANTITY INDICATING SYSTEM - FUEL QUANTITY PROCESSOR UNIT REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-FEB-2009			-				
SB 737-28-1303	FUEL - GENERAL - LEFT ENVIRONMENTAL CONTROL SYSTEMS BAY WIRE CLAMP - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
26-APR-2012							
SB 737-28-1312	FUEL - GENERAL - LEFT AND RIGHT ENVIRONMENTAL CONTROL SYSTEMS BAY WIRE CLAMP - INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 737-28-1312 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS		(EFF)			
			-				
SB 737-28-1312 R1	FUEL - GENERAL - LEFT AND RIGHT ENVIRONMENTAL CONTROL SYSTEMS BAY WIRE CLAMP - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-APR-2013			-				
SB 737-28-1318	FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-APR-2014			-				
SB 737-28-1318 TABLE 1.1	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN A MAINTENANCE RECORDS CHECK TO SEE IF ANY OF THE FOUR FUEL VALVE ADAPTER SHAFT ASSEMBLIES HAVE A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A. (ALL AIRPLANES)						
		MOS					
			-				
SB 737-28-1318 TABLE 1.2	FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN NO MORE WORK IS NECESSARY IF CONDITION 1: ALL FUEL VALVE ADAPTER SHAFT ASSEMBLIES THAT DO NOT HAVE A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A.					RECOMMENDED	
		MOS					
03-APR-2014			-				
SB 737-28-1318 TABLE 1.3.1	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 1: FUEL VALVE ADAPTER SHAFT ASSEMBLY - OPEN ACCESS (IF CONDITION 2: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT HAS A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A)						
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1318 TABLE 1.3.2	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 3: FUEL VALVE ADAPTER SHAFT ASSEMBLY - REPLACEMENT (IF CONDITION 2: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT HAS A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A)	MOS	- (s)				
SB 737-28-1318 TABLE 1.3.3	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 4: FUEL VALVE ADAPTER SHAFT ASSEMBLY - CLOSE ACCESS (IF CONDITION 2: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT HAS A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A)	MOS	- (s)				
SB 737-28-1318 TABLE 1.4.1	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 1: FUEL VALVE ADAPTER SHAFT ASSEMBLY - OPEN ACCESS (IF CONDITION 3: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY WHERE THE SERIAL NUMBER CANNOT BE IDENTIFIED IN THE MAINTENANCE RECORDS)	MOS	- (s)				
SB 737-28-1318 TABLE 1.4.2	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 2: FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION - TO SEE IF THE SERIAL NUMBER IS SPECIFIED IN APPENDIX A (IF CONDITION 3: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY WHERE THE SERIAL NUMBER CANNOT BE IDENTIFIED IN THE MAINTENANCE RECORDS)	MOS	- (s)				
SB 737-28-1318 TABLE 1.5	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 4: FUEL VALVE ADAPTER SHAFT ASSEMBLY - CLOSE ACCESS (IF CONDITION 4: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT DOES NOT HAVE A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A)	MOS	-		03-APR-2014	RECOMMENDED	
SB 737-28-1318 TABLE 1.6.1	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 3: FUEL VALVE ADAPTER SHAFT ASSEMBLY - REPLACEMENT (IF CONDITION 5: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT HAS A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A, OR THAT CANNOT BE DETERMINED)	MOS	- (s)				
SB 737-28-1318 TABLE 1.6.2	DO FUEL - ENGINE FUEL FEED SYSTEM - FUEL VALVE ADAPTER SHAFT ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN PART 4: FUEL VALVE ADAPTER SHAFT ASSEMBLY - CLOSE ACCESS (IF CONDITION 5: EACH FUEL VALVE ADAPTER SHAFT ASSEMBLY THAT HAS A SERIAL NUMBER THAT IS SPECIFIED IN APPENDIX A, OR THAT CANNOT BE DETERMINED)	MOS	- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28-1323	FUEL - DISTRIBUTION - LEFT WING TANK WATER SCAVENGE SYSTEM - PERFORMANCE IMPROVEMENT EVALUATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JUL-2014			-				
SB 737-28A1142	IMPROVED FUELING FLOAT SWITCH AND WIRING PROVISION INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
07-FEB-2002							
SB 737-28A1142 R1	IMPROVED FUELING FLOAT SWITCH AND WIRING PROVISION INSTALLATION, SERVICE BULLETIN						
		MOS	24 (s)				
17-JUN-2002							
SB 737-28A1142 R2	IMPROVED FUELING FLOAT SWITCH AND WIRING PROVISION INSTALLATION, SERVICE BULLETIN						
		MOS	24 (s)	21-AUG-2002			
07-FEB-2002				1057:48			
		AFL		271			
SB 737-28A1142 R3	IMPROVED FUELING FLOAT SWITCH AND WIRING PROVISION INSTALLATION, SERVICE BULLETIN						
		MOS	24 (s)	21-AUG-2002			
21-AUG-2003				1057:48			
		AFL		271			
SB 737-28A1142 R4	IMPROVED FUELING FLOAT SWITCH AND WIRING PROVISION INSTALLATION, SERVICE BULLETIN						
		MOS	24 (s)	21-AUG-2002			
15-JUL-2004				1057:48			
		AFL		271			
SB 737-28A1148	TANK FUEL BOOST PUMP, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY REV 2 DOESN'T AFFECT A/C
		MOS	6 (s)	09-JAN-2004			
14-SEP-2000				1547:30			
		AFL		391			
SB 737-28A1148 R1	AFT BOOST PUMP WIRING SUPPORT BRACKET INSTALLATION, SERVICE BULLETIN						
		MOS	6 (s)				
22-AUG-2002							
SB 737-28A1148 R2	AFT BOOST PUMP WIRING SUPPORT BRACKET INSTALLATION (SUPERSEDED BY SB 737-28A1148 R3), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - PREVIOUSLY DONE WITH SB 737-28A1148 IN AUG 14.8.01
		MOS		16-DEC-2004			
			- (s)	1951:36			
		AFL		476			

© Camp Systems

EFTA00618355

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28A1148 R3	ENGINE FUEL FEED SYSTEM - TANK FUEL BOOST PUMP - AFT BOOST PUMP WIRING SUPPORT BRACKET INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)				
13-JUL-2004							
SB 737-28A1184	FUEL BOOST AND OVERRIDE PUMP MOTOR-IMPELLAR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2000			-				
SB 737-28A1188	AFT FUEL BOOST PUMP GROUND SHIELD WIRE CHANGE, SERVICE BULLETIN						COMPLIED WITH
		MOS	18 (s)	13-AUG-2004			
06-MAR-2003				1785:06			
		AFL		446			
SB 737-28A1188 IN 01	FUEL BOOST PUMP - AFT FUEL BOOST PUMP GROUND SHIELD WIRE CHANGE, SERVICE BULLETIN						
		MOS					
12-JUN-2006			-				
SB 737-28A1188 R1	AFT FUEL BOOST PUMP GROUND SHIELD WIRE CHANGE., SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY
		MOS		30-NOV-2005			
18-MAR-2004			-	2338:24			
		AFL		573			
SB 737-28A1197	FUEL PUMP MOTOR-IMPELLER INSPECTION (SUPERSEDED BY 737-28A1197 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
23-SEP-2002			- (s)				
SB 737-28A1197 R1	FUEL PUMP MOTOR-IMPELLER INSPECTION (SUPERSEDED BY 737-28A1197 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-MAY-2003			-				
SB 737-28A1197 R2	FUEL - DISTRIBUTION - FUEL PUMP MOTOR-IMPELLER INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
25-AUG-2005			-				
SB 737-28A1201	FUEL - ENGINE FUEL FEED SYSTEM - FUEL PUMP CONTROL GROUND FAULT INTERRUPTER (GFI) RELAY INSTALLATION (SUPERSEDED BY 737-28A1201 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-28A1201 R1	FUEL - ENGINE FUEL FEED SYSTEM - FUEL PUMP CONTROL GROUND FAULT INTERRUPTER (GFI) RELAY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		29-AUG-2011			
28-MAY-2009			-	3533:32			
		AFL		863			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28A1206	FUEL - DISTRIBUTION - CENTER FUEL TANK BOOST PUMP AUTO SHUTOFF AND MASTER CAUTION LOGIC CHANGE, SERVICE BULLETIN						
		MOS					
11-JAN-2006			-				
SB 737-28A1206 R1	FUEL - DISTRIBUTION - CENTER FUEL TANK BOOST PUMP AUTO SHUTOFF AND MASTER CAUTION LOGIC CHANGE, SERVICE BULLETIN						
		MOS					
11-JAN-2006			-				
SB 737-28A1206 R2	CENTER FUEL TANK BOOST PUMP AUTO SHUTOFF AND MASTER CAUTION LOGIC CHANGE (SUPERSEDED BY SB 737-28A1206 R3), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		29-AUG-2011			
			-	3533:32			
		AFL		863			
SB 737-28A1206 R3	FUEL - DISTRIBUTION - CENTER FUEL TANK BOOST PUMP AUTO SHUTOFF AND MASTER CAUTION LOGIC CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS	36	(EFF)	**30-SEP-2014**	30-SEP-2014	
30-SEP-2011							
SB 737-28A1207	FUEL - ENGINE FUEL FEED SYSTEM - MOTOR OPERATED VALVE - ACTUATOR REPLACEMENT (SUPERSEDED BY 737-28A1207 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
15-FEB-2007			-				
SB 737-28A1207 R1	FUEL - ENGINE FUEL FEED SYSTEM - MOTOR OPERATED VALVE - ACTUATOR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		29-AUG-2011			
19-APR-2010			- (s)	3533:32			
		AFL		863			
SB 737-28A1221	FUEL - INDICATING - HOT SHORT PROTECTOR INSTALLATION FOR FQIS FUEL DENSITOMETER, SERVICE BULLETIN						
		MOS	60 (s)				
14-JAN-2007							
SB 737-28A1221 R1	FUEL - INDICATING - HOT SHORT PROTECTOR INSTALLATION FOR FQIS FUEL DENSITOMETER (SUPERSEDED BY SB 737-28A1221 R2), SERVICE BULLETIN						NOT APPLICABLE - N/A BY EFFECTIVITY
		MOS		29-AUG-2011			
09-NOV-2007			- (s)	3533:32			
		AFL		863			
SB 737-28A1221 R2	FUEL - INDICATING - HOT SHORT PROTECTOR INSTALLATION FOR FQIS FUEL DENSITOMETER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY EFFECTIVITY
		MOS		29-AUG-2011			
14-JAN-2007			- (s)	3533:32			
		AFL		863			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-28A1248	FUEL - ENGINE FUEL FEED SYSTEM - CENTER FUEL TANK, FUEL PUMPS - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED PUMP ON) - RELAYS INSTALLATION (SUPERSEDED BY 737-28A1248 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-28A1248 R1	FUEL - ENGINE FUEL FEED SYSTEM - CENTER FUEL TANK, FUEL PUMPS - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED PUMP ON) - RELAYS INSTALLATION (SUPERSEDED BY 737-28A1248 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-28A1248 R2	ENGINE FUEL FEED SYSTEM - CENTER FUEL TANK, FUEL PUMPS - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED PUMP ON) - RELAYS INSTALLATION (SUPERSEDED BY SB 737-28A1248 R3), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - WO BVBBJ006
		MOS			29-AUG-2011		
			-		3533:32		
		AFL			863		
SB 737-28A1248 R3	FUEL - ENGINE FUEL FEED SYSTEM - CENTER FUEL TANK, FUEL PUMPS - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED PUMP ON) - RELAYS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
30-SEP-2011							
SB 737-29-1077	, SERVICE BULLETIN						COMPLIED WITH - C/W
		MOS			23-SEP-1999		
			- (s)				
SB 737-29-1083	HYDRAULIC POWER - PARKING BRAKE SHUTOFF VALVE (NON-SENSITIVE LOCATIONS) REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JAN-2001			- (s)				
SB 737-29-1084	HYDRAULIC POWER TRANSFER UNIT SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-JUN-2000			- (s)				
SB 737-29-1090	HYDRAULIC POWER - DC MOTOR OPERATED SHUTOFF VALVE (ALL LOCATIONS) REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JAN-2001			- (s)				
SB 737-29-1094	MODIFICATION OF THE RESERVOIR PRESSURIZATION MODULE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-MAR-2001			- (s)				
SB 737-29-1094 R1	MODIFICATION OF THE HYDRAULIC RESERVOIR PRESSURIZATION MODULE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-MAR-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-29-1106	HYDRAULIC POWER-HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM-REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						- REF:REV.4
		MOS					
23-DEC-2002			- (s)				
SB 737-29-1106 R1	HYDRAULIC POWER-HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM-REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						- REF:REV.4
		MOS					
15-MAY-2003			- (s)				
SB 737-29-1106 R2	REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						- REF: REV.4
		MOS					
05-FEB-2004			- (s)				
SB 737-29-1106 R3	REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN					RECOMMENDED	- REF:REV.4
		MOS					
28-JUL-2005			- (s)				
SB 737-29-1106 R4	REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						COMPLIED WITH
		MOS			24-AUG-2007		
23-JUN-2006			- (s)		2968:28		
		AFL			699		
SB 737-29-1106 R5	HYDRAULIC POWER - HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						- INFORMATION REFER TO. REV.6
		MOS					
16-JAN-2008			- (s)				
SB 737-29-1106 R6	HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES (SUPERSEDED BY SB 737-29-1106 R7), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS			28-SEP-2009		
			- (s)		3378:04		
		AFL			812		
SB 737-29-1106 R7	HYDRAULIC POWER - HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES (SUPERSEDED BY SB 737-29-1106 R8), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-29-1106 R8	HYDRAULIC POWER - HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - REMOVAL OF THE RESERVOIR PRESSURIZATION MODULE AND DEPRESSURIZATION VALVES, SERVICE BULLETIN						
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-29-1110	HYDRAULIC POWER - HYDRAULIC RESERVOIR - OVERFILL WARNING MARKER INSTALLATION, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008			
28-NOV-2007			- (s)	3260:48			
		AFL		782			
SB 737-29-1110 R1	HYDRAULIC RESERVOIR - OVERFILL WARNING MARKER INSTALLATION, SERVICE BULLETIN						
		MOS	60 (s)				
30-OCT-2008							
SB 737-29-1111	HYDRAULIC SYSTEMS A AND B ENGINE DRIVEN PUMP - SUPPORT BRACKET CHANGE FOR THE HYDRAULIC PRESSURE HOSE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-JUL-2009			-				
SB 737-29-1113	HYDRAULIC POWER - RIGHT MAIN LANDING GEAR WHEEL WELL - WIRE BUNDLE AND HYDRAULIC TUBING - INSPECTION, REPAIR AND NEW CLAMPS INSTALLATION (SUPERSEDED BY SB 737-29-1113 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
23-MAR-2011							
SB 737-29-1113 R1	HYDRAULIC POWER - RIGHT MAIN LANDING GEAR WHEEL WELL - WIRE BUNDLE AND HYDRAULIC TUBING - INSPECTION, REPAIR AND NEW CLAMPS INSTALLATION, SERVICE BULLETIN						
		MOS					
			-				
SB 737-29-1114	HYDRAULIC POWER - MAIN - HYDRAULIC SYSTEMS A AND B PRESSURE MODULE CHECK VALVE INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
			- (s)				
SB 737-29-1114 R1	HYDRAULIC POWER - MAIN - HYDRAULIC SYSTEMS A AND B PRESSURE MODULE CHECK VALVE INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)	(EFF)			
10-SEP-2012							
SB 737-29A1073	HYD POWER - DC MOTOR OPERATED S/O INSP., SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-1997			- (s)				
SB 737-29A1073 R2	DC MOTOR OPERATED SHUTOFF VALVE, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)	08-OCT-1999			
01-JUL-1999							
SB 737-29A1073 R3	HYDRAULIC POWER - DC MOTOR OPERATED SHUTOFF VALVE INSPECTION, SERVICE BULLETIN						
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-29A1077	HYDRAULIC SYSTEM B ELECTRIC MOTOR-DRIVEN PUMP CASE DRAIN HOSE AND WIRE BUNDLE CLAMP INSTALLATION (SUPERSEDED BY SB 737-29A1077 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-29A1077 R1	MAIN - HYDRAULIC SYSTEM B ELECTRIC MOTOR-DRIVEN PUMP (SUPERSEDED BY SB 737-29A1077 R2), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS	- (s)	09-SEP-1999			
SB 737-29A1077 R2	HYDRAULIC POWER - MAIN - HYDRAULIC SYSTEM B ELECTRIC MOTOR-DRIVEN PUMP CASE DRAIN HOSE, PRESSURE HOSE AND WIRE BUNDLE INSPECTION AND CLAMP INSTALLATION (SUPERSEDED BY SB 737-29A1077 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-29A1077 R3	HYDRAULIC POWER - MAIN - HYDRAULIC SYSTEM B ELECTRIC MOTOR-DRIVEN PUMP CASE DRAIN HOSE, PRESSURE HOSE AND WIRE BUNDLE INSPECTION AND CLAMP INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
07-APR-2010		MOS	-				
SB 737-29A1078	DC MOTOR OPERATED SHUTOFF VALVE (SENSITIVE LOCATIONS) REPLACEMENT, SERVICE BULLETIN						
		MOS	- (s)				
SB 737-29A1081	DC MOTOR OPERATED SHUTOFF VALVE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
02-DEC-1999		MOS	6 (s)	01-NOV-2001 822:06			
		AFL		220			
SB 737-29A1081 R1	HYDRAULIC POWER - DC MOTOR OPERATED SHUTOFF VALVE INSPECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-OCT-2001		MOS	6 (s)	01-NOV-2001 822:06			
		AFL		220			
SB 737-29A1082	HYDRAULIC POWER - DC MOTOR OPERATED SHUTOFF VALVE (SENSITIVE LOCATIONS) REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
07-DEC-2000		MOS	- (s)	01-NOV-2001 822:06			
		AFL		220			
SB 737-30-1054	WINDSHIELD WIPER MOTOR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-MAY-2002		MOS	- (s)	18-AUG-2006 2633:50			
		AFL		633			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-30-1054 R1	WINDSHIELD WIPER MOTOR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		18-AUG-2006			
06-MAR-2003			- (s)	2633:50			
		AFL		633			
SB 737-30-1056	ICE AND RAIN PROTECTION - WATER AND DRAIN LINE HEATERS - CHANGE - GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION, SERVICE BULLETIN						
		MOS	60 (s)				
28-FEB-2007							
SB 737-30-1056 R1	ICE AND RAIN PROTECTION - WATER AND DRAIN LINE HEATERS - CHANGE - GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008			
25-OCT-2007			- (s)	3260:48			
		AFL		782			
SB 737-30-1056 R2	ICE AND RAIN PROTECTION - WATER AND DRAIN LINE HEATERS - CHANGE - GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
27-MAY-2008							
SB 737-30-1056 R3	WATER AND DRAIN LINE HEATERS - CHANGE - GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
27-MAY-2008							
SB 737-30-1058	ICE AND RAIN PROTECTION - CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS					
27-JUL-2006			-				
SB 737-30-1058 R1	ICE AND RAIN PROTECTION - CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN						
		MOS					
18-JUN-2007			-				
SB 737-30-1058 R2	CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT 9SUPERSEDED BY 737-30-1058 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
13-FEB-2009			-				
SB 737-30-1058 R3	ICE AND RAIN PROTECTION - CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT (SUPERSEDED BY SB 737-30-1058 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-30-1058 R4	ICE AND RAIN PROTECTION - CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT (SUPERSEDED BY SB 737-30-1058 R5), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-30-1058 R5	ICE AND RAIN PROTECTION - CONTROL CABIN WINDOW ANTI-ICING SYSTEM - COIL CORD ASSEMBLY REPLACEMENT ON THE NUMBER 2 WINDOWS IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	
24-APR-2013		MOS	- (s)				
SB 737-30-1070	ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS (SUPERSEDED BY SB 737-30-1070 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-30-1070 R1	ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION TO ADDRESS UN-ANNUNCIATED FAILURE OF PITOT PROBE HEATERS, SERVICE BULLETIN					RECOMMENDED	
04-JUN-2014		MOS	- (s)				
SB 737-30A1049	WINDOWS, WINDSHIELDS AND DOORS, WINDSHIELD WIPER SYSTEM, WIRING CHANGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS			10-AUG-2000		
01-JUN-2000			- (s)				
SB 737-30A1049 R1	WINDOWS, WINDSHIELDS AND DOORS, WINDSHIELD WIPER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
12-OCT-2000		MOS	- (s)				
SB 737-30A1049 R1 LEFT SIDE	CHANGE WINDOWS, WINDSHIELDS AND DOORS, WINDSHIELD WIPER SYSTEM, SERVICE BULLETIN WIRING					RECOMMENDED	
		DAYS	90 (s)				
12-OCT-2000							
SB 737-30A1049 R1 RIGHT SIDE	CHANGE WINDOWS, WINDSHIELDS AND DOORS, WINDSHIELD WIPER SYSTEM, SERVICE BULLETIN WIRING					RECOMMENDED	
		MOS					
12-OCT-2000			5000 (s)				
SB 737-30A1057	ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINSHIELD WIPER MOTOR (SUPERSEDED BY 737-30A1057 R1, SERVICE BULLETIN					SUPERSEDED	- INFORMATION REFER TO REV.1 I.A.W. AD 2008-24-05
		MOS					
06-OCT-2006			- (s)				

© Camp Systems

EFTA00618363

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-30A1057 R1	ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINDSHIELD WIPER MOTOR (SUPERSEDED BY SB 737-30A1057 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-30A1057 R2	ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINDSHIELD WIPER MOTOR (SUPERSEDED BY 737-30A1057 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-30A1057 R3	ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINDSHIELD WIPER MOTOR, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2008-24-05
		MOS		11-SEP-2013			
31-OCT-2011			-				
SB 737-30A1057 R3 TABLE 1 (001.1)	VERIFY ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINDSHIELD WIPER MOTOR, SERVICE BULLETIN THE LH WINDSHIELD WIPER MOTOR PART NUMBER AND SERIAL NUMBER (REFERRED TO AS"MODEL NUMBER" IN THE GOODRICH SERVICE BULLETIN 2313M-347/2313M-348-30-01) OF THE WINDSHIELD WIPER MOTORS AS GIVEN IN WORK PACKAGE 1 OF THE ACCOMPLISHMENT INSTRUCTIONS FOR ALL AIRPLANES / REPLACE OR CHANGE GOODRICH PART NUMBER AS NEEDED.					RECOMMENDED	COMPLIED WITH - CHANGE LH: PN 10-61329-39 TO P/N 10-1329-41
		MOS		11-SEP-2013			
30-DEC-2008			-				
SB 737-30A1057 R3 TABLE 1 (001.2)	VERIFY ICE AND RAIN PROTECTION - WINDSHIELD WIPER SYSTEM - CHANGE THE WINDSHIELD WIPER MOTOR, SERVICE BULLETIN THE RH WINDSHIELD WIPER MOTOR PART NUMBER AND SERIAL NUMBER (REFERRED TO AS"MODEL NUMBER" IN THE GOODRICH SERVICE BULLETIN 2313M-347/2313M-348-30-01) OF THE WINDSHIELD WIPER MOTORS AS GIVEN IN WORK PACKAGE 1 OF THE ACCOMPLISHMENT INSTRUCTIONS FOR ALL AIRPLANES / REPLACE OR CHANGE GOODRICH PART NUMBER AS NEEDED.					RECOMMENDED	COMPLIED WITH - CHANGE PN TO 2313M348-4 / SN 00338
		MOS		11-SEP-2013			
30-DEC-2008			-				
SB 737-30A1063	ICE AND RAIN PROTECTION - PITOT AND STATIC - AIR DATA PROBE ANTI-ICING SYSTEM - AIR DATA PROBE HEAT AUTOMATION INSTALLATION (SUPERSEDED BY SB 737-30A1063 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS		(EFF)			
			-				
SB 737-30A1063 R1	ICE AND RAIN PROTECTION - PITOT AND STATIC - AIR DATA PROBE ANTI-ICING SYSTEM - AIR DATA PROBE HEAT AUTOMATION INSTALLATION (SUPERSEDED BY SB 737-30A1063 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS		(EFF)			
			-				
SB 737-30A1063 R2	ICE AND RAIN PROTECTION - PITOT AND STATIC - AIR DATA PROBE ANTI-ICING SYSTEM - AIR DATA PROBE HEAT AUTOMATION INSTALLATION, SERVICE BULLETIN					MANDATORY	
		MOS	24	(EFF)	**14-JAN-2015**		
14-JAN-2013							
SB 737-31-1124	ADDITION OF THE RUDDER PEDAL FORCE TRANSDUCER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-MAY-1999			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-31-1124 R1	ADDITION OF THE RUDDER PEDAL FORCE TRANSDUCER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-JUN-2000			- (s)				
SB 737-31-1150	INDICATING/RECORDING SYSTEMS - CENTRAL DISPLAY SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-APR-2000			- (s)				
SB 737-31-1153	OPERATIONAL PROGRAM CONFIGURATION (OPC) SOFTWARE UPGRADE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JAN-2000			- (s)				
SB 737-31-1153 R1	, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-JUN-2000			- (s)				
SB 737-31-1153 R2	INDICATING AND RECORDING SYSTEM - COMMON DISPLAY SYSTEMS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-AUG-2000			- (s)				
SB 737-31-1169	SOFTWARE CHANGE TO DISPLAY THE FLIGHT DIRECTOR COMMAND AS SPLIT AXIS COMMAND BARS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-JUN-2000			-				
SB 737-31-1169 R3	SOFTWARE CHANGE TO DISPLAY THE FLIGHT DIRECTOR COMMAND AS SPLIT AXIS COMMAND BARS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-MAY-2002			-				
SB 737-31-1170	INDICATING/RECORDING - FLIGHT DATA RECORDER SYSTEM - PARAMETER ADDITION TO RECORD STANDBY RUDDER SYSTEM ENGAGED (ON-OFF) STATUS, SERVICE BULLETIN						
		MOS					
21-MAR-2002			- (s)				
SB 737-31-1170 R1	INDICATING/RECORDING - FLIGHT DATA RECORDER SYSTEM - PARAMETER ADDITION TO RECORD STANDBY RUDDER SYSTEM ENGAGED (ON-OFF) STATUS, SERVICE BULLETIN						
		MOS					
18-SEP-2007			-				
SB 737-31-1205	OPERATIONAL PROGRAM SOFTWARE (OPS) UPGRADE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-FEB-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-31-1246	INDICATING AND RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - DISPLAY ELECTRONIC UNIT OPERATIONAL PROGRAM SOFTWARE CHANGE, SERVICE BULLETIN						
		MOS					
05-MAY-2005			-				
SB 737-31-1284	INDICATING/RECORDING SYSTEMS - MASTER CAUTION - ADDITION OF QUICK DISCONNECTS TO THE MASTER CAUTION AND FIRE WARNING SWITCHLIGHT WIRES, SERVICE BULLETIN						
		MOS					
23-FEB-2006			-				
SB 737-31-1284 R1	INDICATING/RECORDING SYSTEMS - MASTER CAUTION - ADDITION OF QUICK DISCONNECTS TO THE MASTER CAUTION AND FIRE WARNING SWITCHLIGHT WIRES, SERVICE BULLETIN						
		MOS					
01-MAR-2007			-				
SB 737-31-1293	COMMON DISPLAY SYSTEM - UPDATED PHASE 3 DISPLAY UNIT DATABASE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-AUG-2009			-				
SB 737-31-1295	INDICATING AND RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - DISPLAY ELECTRONIC UNIT OPERATIONAL PROGRAM SOFTWARE CHANGE, SERVICE BULLETIN						
		MOS					
27-OCT-2005			-				
SB 737-31-1327	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM (CDS) - CHANGE THE OPERATIONAL PROGRAM SOFTWARE (OPS) FOR THE CDS DISPLAY ELECTRONIC UNIT (DEU), SERVICE BULLETIN						
		MOS					
14-DEC-2006			-				
SB 737-31-1327 R1	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM (CDS) - CHANGE THE OPERATIONAL PROGRAM SOFTWARE (OPS) FOR THE CDS DISPLAY ELECTRONIC UNIT (DEU), SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS			22-AUG-2008		
10-OCT-2007			-		3260:48		
		AFL			782		
SB 737-31-1449	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER SYSTEM - GROUND WIRE CHANGE (SUPERSEDED BY SB 737-31-1449 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-31-1449 R1	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER SYSTEM - GROUND WIRE CHANGE (SUPERSEDED BY SB 737-31-1449 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-31-1449 R2	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER SYSTEM - GROUND WIRE CHANGE (SUPERSEDED BY SB 737-31-1449 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-31-1449 R3	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER SYSTEM - GROUND WIRE CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-JUL-2013			-				
SB 737-31-1471	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - INSTALLATION OF PHASE 3A DISPLAY UNIT AND DATABASE SOFTWARE (SUPERSEDED BY SB 737-31-1471 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-31-1471 R1	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - INSTALLATION OF PHASE 3A DISPLAY UNIT AND DATABASE SOFTWARE, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
29-NOV-2012							
SB 737-31-1472	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - INSTALLATION OF FLIGHT DIRECTOR COMMAND DISPLAY AS A SPLIT AXIS COMMAND BAR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-JAN-2011			-				
SB 737-31-1475	INDICATING / RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - REMOVAL OF OPTIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-JAN-2011			-				
SB 737-31-1506	INDICATING/RECORDING SYSTEMS - FLIGHT DATA RECORDER SYSTEM - DIGITAL FLIGHT DATA ACQUISITION UNIT LOADABLE SOFTWARE CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-OCT-2011			-				
SB 737-31-1552	INDICATING/RECORDING SYSTEMS - COMMON DISPLAY SYSTEM - SOFTWARE CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-MAR-2013			-				
SB 737-31A1332	INDICATING / RECORDING SYSTEMS - AURAL WARNING SYSTEM - INSTALLATION OF THE CABIN ALTITUDE WARNING SYSTEM AND TAKEOFF CONFIGURATION WARNING SYSTEM LIGHTS (SUPERSEDED BY SB 737-31A1332 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-31A1332 R1	INDICATING / RECORDING SYSTEMS - AURAL WARNING SYSTEM - INSTALLATION OF THE CABIN ALTITUDE WARNING SYSTEM AND TAKEOFF CONFIGURATION WARNING SYSTEM LIGHTS (SUPERSEDED BY SB 737-31A1332 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-	(EFF)			
SB 737-31A1332 R2	INDICATING / RECORDING SYSTEMS - AURAL WARNING SYSTEM - INSTALLATION OF THE CABIN ALTITUDE WARNING SYSTEM AND TAKEOFF CONFIGURATION WARNING SYSTEM LIGHTS (SUPERSEDED BY SB 737-31A1332 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS	-	(EFF)			
SB 737-31A1332 R3	INDICATING / RECORDING SYSTEMS - AURAL WARNING SYSTEM - INSTALLATION OF THE CABIN ALTITUDE WARNING SYSTEM AND TAKEOFF CONFIGURATION WARNING SYSTEM LIGHTS (SUPERSEDED BY SB 737-31A1332 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS	-	(EFF)			
SB 737-31A1332 R4	INDICATING / RECORDING SYSTEMS - AURAL WARNING SYSTEM - INSTALLATION OF THE CABIN ALTITUDE WARNING SYSTEM AND TAKEOFF CONFIGURATION WARNING SYSTEM LIGHTS, SERVICE BULLETIN					RECOMMENDED	
06-MAR-2013		MOS	36	(EFF)	**06-MAR-2016** 06-MAR-2016		
SB 737-32-1305	NOSE LANDING GEAR AFT LOCK LINK REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	- (s)				
SB 737-32-1305 R1	NOSE LANDING GEAR AFT LOCK LINK REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
13-MAR-2003		MOS	-				
SB 737-32-1311	LANDING GEAR - WHEELS AND BRAKES - HYDRAULIC BRAKE SYSTEM, SERVICE BULLETIN					RECOMMENDED	
19-AUG-1999		MOS	- (s)				
SB 737-32-1312	SHIMMY DAMPER ADDITION, SERVICE BULLETIN					RECOMMENDED	
24-FEB-1999		MOS	- (s)				
SB 737-32-1312 R1	SHIMMY DAMPER ADDITION, SERVICE BULLETIN					RECOMMENDED	
01-APR-1999		MOS	- (s)				
SB 737-32-1312 R2	MLG SHIMMY DAMPER ADDITION, SERVICE BULLETIN					RECOMMENDED	
15-JUL-1999		MOS	- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1312 R3	SHIMMY DAMPER ADDITION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-SEP-2000			- (s)				
SB 737-32-1317	LANDING GEAR - POSITION AND WARNING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-SEP-1999			- (s)				
SB 737-32-1317 R1	LANDING GEAR - POSITION AND WARNING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JAN-2001			- (s)				
SB 737-32-1330	MAIN LANDING GEAR (STRUCTURE), SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-JUN-2000			- (s)				
SB 737-32-1332	NOSE GEAR EXTENSION AND RETRACTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY NO WORK NECCESSARY REF: GVBBJ039-0220 -2 KIT USED FOR ORIGINAL COMPLIANCE
		MOS		24-AUG-2007			
07-FEB-2000			- (s)	2968:28			
		AFL		699			
SB 737-32-1332 R1	LANDING GEAR, NOSE GEAR EXTENSION & RETRACTION, RELOCATION OF THE NOSE GEAR EXTEND FUSE, SERVICE BULLETIN					RECOMMENDED	- REF: R0
		MOS					
08-JUN-2000			- (s)				
SB 737-32-1332 R2	RELOCATION OF THE NOSE GEAR EXTEND FUSE, SERVICE BULLETIN						- REF: R0
		MOS					
28-FEB-2002			- (s)				
SB 737-32-1342	LANDING GEAR-STEERING-INSPECTION AND MODIFICATION TO THE NOSE LANDING GEAR STEERING COLLAR AND STEERING PLATE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-MAY-2000			- (s)				
SB 737-32-1342 R1	LANDING GEAR - STEERING - INSPECTION AND MODIFICATION TO THE NOSE LANDING GEAR STEERING COLLAR AND STEERING PLATE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-2001			-				
SB 737-32-1362	CHANGE THE LOWER BEARING SEAL RETAINER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-FEB-2000			-				

© Camp Systems

EFTA00618369

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1362 R1	LANDING GEAR - NOSE LANDING GEAR - CHANGE THE LOWER BEARING SEAL RETAINER., SERVICE BULLETIN						
		MOS					
26-JAN-2006			-				
SB 737-32-1368	LEFT AND RIGHT MAIN LANDING GEAR SHIMMY DAMPER ASSEMBLY REPAIRS AND SEALS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-SEP-2004			-				
SB 737-32-1368 R1	LEFT AND RIGHT MAIN LANDING GEAR SHIMMY DAMPER ASSEMBLY REPAIRS AND SEALS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUN-2009			-				
SB 737-32-1369	RETRACT ACTUATOR CYLINDER ASSEMBLY MODIFICATION OR REPLACEMENT, SERVICE BULLETIN						
		MOS					
01-APR-2004							
		AFL	3000 (s)				
SB 737-32-1369 R1	LANDING GEAR - MAIN LANDING GEAR EXTENSION AND RETRACTION - RETRACT ACTUATOR CYLINDER ASSEMBLY MODIFICATION OR REPLACEMENT, SERVICE BULLETIN						
		MOS					
09-AUG-2006							
		AFL	3000 (s)				
SB 737-32-1369 R2	LANDING GEAR - MAIN LANDING GEAR EXTENSION AND RETRACTION - RETRACT ACTUATOR CYLINDER ASSEMBLY MODIFICATION OR REPLACEMENT, SERVICE BULLETIN						
		MOS					
16-AUG-2007							
		AFL	3000 (s)				
SB 737-32-1369 R3	LANDING GEAR - MAIN LANDING GEAR EXTENSION AND RETRACTION - RETRACT ACTUATOR CYLINDER ASSEMBLY MODIFICATION OR REPLACEMENT (SUPERSEDED BY SB 737-32-1369 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-32-1369 R4	LANDING GEAR - MAIN LANDING GEAR EXTENSION AND RETRACTION - RETRACT ACTUATOR CYLINDER ASSEMBLY MODIFICATION OR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		AFL	1000 (s)				
SB 737-32-1376	INSPECT, LUBRICATE, REPAIR OR REPLACE MAIN LANDING GEAR- FORWARD TRUNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS					
12-MAY-2005			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1376 R1	INSPECT, LUBRICATE, REPAIR OR REPLACE MAIN LANDING GEAR- FORWARD TRUNION PIN INSPECTION AND REPLACEMENT., SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS	- (s)				
SB 737-32-1376 R2	MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS		16-FEB-2010			
06-AUG-2008			-	3417:51			
		AFL		829			
SB 737-32-1393	LANDING GEAR - MAIN GEAR AND DOORS - OUTER CYLINDER WALKING BEAM CLEVIS BUSHING AND RETRACT ACTUATOR CLEVIS BUSHING REPLACEMENT, SERVICE BULLETIN						
		MOS					
02-JUL-2007			-				
SB 737-32-1393 R1	MAIN GEAR AND DOORS - OUTER CYLINDER WALKING BEAM CLEVIS BUSHING AND RETRACT ACTUATOR CLEVIS BUSHING REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-JAN-2010			-				
SB 737-32-1394	LANDING GEAR - NOSE LANDING GEAR EXTENSION AND RETRACTION - GEAR LOCK ACTUATOR TRUNNION SEALS REPLACEMENT, SERVICE BULLETIN						
		MOS					
16-NOV-2006			-				
SB 737-32-1402	MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 737-32-1402 R1), SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS		02-FEB-2010			
06-AUG-2008			-	3411:56			
		AFL		827			
SB 737-32-1402 R1	LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-FEB-2013			- (s)				
SB 737-32-1402 R1 TABLE 1.1 & 1.2	LUBRICATE LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN THE MLG FORWARD TRUNNION PIN					RECOMMENDED	
		DAYS	30 (s)				
07-FEB-2013							
SB 737-32-1402 R1 TABLE 1.3 & 1.4	DETAILED INSPECTION LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN OF THE TRANSITION RADIUS LOCATION (IN-SITU)					RECOMMENDED	
		MOS	6 (s)				
07-FEB-2013							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1402 R1 TABLE 1.5	REPAIR LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN THE FINISH FOR AIRPLANES WITH FINISH DAMAGE (SCRAPES OR SCRATCHES THROUGH THE FULL THICKNESS OF THE PRIMER OR AREAS OF MISSING PRIMER) FOUND IN THE TRANSITION RADIUS LOCATION, AND NO CORROSION, NO PITTING, AND NO BASE METAL SCRATCHES & DO A DETAILED INSPECTION OF THE TRANSITION RADIUS LOCATION (IN-SITU)					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-32-1402 R1 TABLE 2.1 & 2.2	LUBRICATE LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN LUBRICATE THE MLG FOR WARD TRUNNION PIN					RECOMMENDED	
		DAYS	30 (s)				
07-FEB-2013							
SB 737-32-1402 R1 TABLE 2.3 & 2.4	DETAILED INSPECTION LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN OF THE TRANSITION RADIUS LOCATION (IN-SITU)					RECOMMENDED	
		MOS	6 (s)				
07-FEB-2013							
SB 737-32-1402 R1 TABLE 2.5	REPAIR LANDING GEAR - MAIN LANDING GEAR - FORWARD TRUNNION PIN INSPECTION AND REPLACEMENT, SERVICE BULLETIN THE FINISH FOR AIRPLANES WITH FINISH DAMAGE (SCRAPES OR SCRATCHES THROUGH THE FULL THICKNESS OF THE PRIMER OR AREAS OF MISSING PRIMER) FOUND IN THE TRANSITION RADIUS LOCATION AND NO CORROSION, NO PITTING, AND NO BASE METAL SCRATCHES & DO DETAILED INSPECTION OF THE TRANSITION RADIUS LOCATION (IN-SITU)					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-32-1408	WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI CARBON BRAKES AND WHEELS (SUPERSEDED BY 737-32-1408 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
09-SEP-2009							
SB 737-32-1408 R1	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI CARBON BRAKES AND WHEELS FOR 737-700 AIRPLANES (SUPERSEDED BY SB 737-32-1408 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1408 R2	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI CARBON BRAKES AND WHEELS FOR 737-700 AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JUN-2011			-				
SB 737-32-1410	LANDING GEAR - MAIN LANDING GEAR - WIRE BUNDLE AND HANGER LINK ASSEMBLY INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
20-FEB-2008			-		3260:48		
		AFL			782		

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1410 R1	MAIN LANDING GEAR - WIRE BUNDLE AND HANGER LINK ASSEMBLY INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN	MOS	-	20-NOV-2008			
SB 737-32-1410 R2	MAIN LANDING GEAR - WIRE BUNDLE AND HANGER LINK ASSEMBLY INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN	MOS	-	29-SEP-2009		RECOMMENDED	
SB 737-32-1418	LANDING GEAR - EXTENSION AND RETRACTION - MAIN LANDING GEAR RETRACT ACTUATOR CHANGE OR REPLACEMENT (SUPERSEDED BY SB 737-32-1418 R1), SERVICE BULLETIN	MOS	-	13-JUL-2010		RECOMMENDED	
SB 737-32-1418 R1	LANDING GEAR - EXTENSION AND RETRACTION - MAIN LANDING GEAR RETRACT ACTUATOR CHANGE OR REPLACEMENT, SERVICE BULLETIN	MOS	-	05-APR-2013		RECOMMENDED	
SB 737-32-1422	LANDING GEAR - EXTENSION AND RETRACTION - CONTROL SYSTEM AFT CONTROL QUADRANT CLEARANCE MEASUREMENT AND REPLACEMENT, SERVICE BULLETIN	MOS	-	29-JAN-2010		RECOMMENDED	
SB 737-32-1429	REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES (SUPERSEDED BY SB 737-32-1429 R1), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-32-1429 R1	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES (SUPERSEDED BY SB 737-32-1429 R2), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-32-1429 R2	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI-DOWTY CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES (SUPERSEDED BY SB 737-32-1429 R3), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-32-1429 R3	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH MESSIER-BUGATTI-DOWTY CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES, SERVICE BULLETIN	MOS	-	09-AUG-2012		RECOMMENDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1430	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO MESSIER-BUGATTI CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900ER AIRPLANES (SUPERSEDED BY SB 737-32-1430 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1430 R1	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO MESSIER-BUGATTI CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900ER AIRPLANES (SUPERSEDED BY SB 737-32-1430 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1430 R2	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO MESSIER-BUGATTI-DOWTY CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900ER AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-JAN-2012			-				
SB 737-32-1433	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-700 AIRPLANES (SUPERSEDED BY SB 737-32-1433 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1433 R1	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-700 AIRPLANES (SUPERSEDED BY SB 737-32-1433 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1433 R2	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-700 AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-APR-2012			-				
SB 737-32-1440	LANDING GEAR - EXTENSION AND RETRACTION - NOSE LANDING GEAR RETRACT ACTUATOR CHANGE OR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-JUL-2011			-				
SB 737-32-1441	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES (SUPERSEDED BY SB 737-32-1441 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-32-1441 R1	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES (SUPERSEDED BY SB 737-32-1441 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1441 R2	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-800 AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-AUG-2012			-				
SB 737-32-1442	LANDING GEAR - STEERING - NOSE WHEEL STEERING SYSTEM MECHANISM COMPONENT CHANGE (SUPERSEDED BY SB SB 737-32-1442 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1442 R1	LANDING GEAR - STEERING - NOSE WHEEL STEERING SYSTEM MECHANISM COMPONENT CHANGE (SUPERSEDED BY SB 737-32-1442 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1442 R2	LANDING GEAR - STEERING - NOSE WHEEL STEERING SYSTEM MECHANISM COMPONENT CHANGE (SUPERSEDED BY SB 737-32-1442 R3), SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-AUG-2011			-				
SB 737-32-1442 R3	LANDING GEAR - STEERING - NOSE WHEEL STEERING SYSTEM MECHANISM COMPONENT CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-MAR-2013			-				
SB 737-32-1442 R4	LANDING GEAR - STEERING - NOSE WHEEL STEERING SYSTEM MECHANISM COMPONENT CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-JUL-2013			-				
SB 737-32-1443	LANDING GEAR - EXTENSION AND RETRACTION - MANUAL EXTENSION CONTROL MECHANISM ACCESS DOOR SWITCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-NOV-2011			-				
SB 737-32-1443 R1	LANDING GEAR - EXTENSION AND RETRACTION - MANUAL EXTENSION CONTROL MECHANISM ACCESS DOOR SWITCH REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-AUG-2013			-				
SB 737-32-1444	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR INBOARD WHEEL HALF INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-APR-2010			-				
SB 737-32-1445	LANDING GEAR - MAIN LANDING GEAR GLAND NUT INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	737-32-1448	LANDING GEAR - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INSPECTION AND CHANGE, SERVICE BULLETIN						
			MOS	-				
SB	737-32-1448 TABLE 1.1	LUBRICATE LANDING GEAR - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INSPECTION AND CHANGE, SERVICE BULLETIN THE MLG FORWARD AND AFT TRUNNION PIN ASSEMBLIES FOR ALL AIRPLANES					RECOMMENDED	COMPLIED WITH
			DAYS	30 (s)	13-JUN-2014			
	19-MAY-2011				3749:42			
			AFL		920			
SB 1.10	737-32-1448 TABLE	INSTALL LANDING GEAR - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INSPECTION AND CHANGE, SERVICE BULLETIN IMPROVED MLG OUTER CYLINDER TRUNNION BUSHINGS, IMPROVED AFT TRUNNION BEARING ASSEMBLY, NEW FORWARD TRUNNION PIN CROSS BOLT BUSHINGS (GROUP 1 ONLY) AND AFT TRUNNION PIN CROSS BOLT BUSHINGS FOR ALL AIRPLANES					RECOMMENDED	
			MOS	120 (s)				
	19-MAY-2011							
SB	737-32-1448 TABLE 1.2	PERFORM LANDING GEAR - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INSPECTION AND CHANGE, SERVICE BULLETIN A GENERAL VISUAL INSPECTION OF THE MLG FORWARD AND AFT TRUNNION PIN ASSEMBLIES WITH THE MLG NOT REMOVED FOR SIGNS OF CORROSION AND/OR CHROME PLATING DAMAGE FOR ALL AIRPLANES					RECOMMENDED	COMPLIED WITH
			MOS	18	09-AUG-2011	**09-FEB-2013**	RECURRING	
	19-MAY-2011				3533:32			
			AFL		863			
SB	737-32-1449	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-900ER AIRPLANES (SUPERSEDED BY SB 737-32-1449 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS	-				
SB	737-32-1449 R1	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-900ER AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	15-SEP-2011			-				
SB	737-32-1449 R2	LANDING GEAR - WHEELS AND BRAKES - REPLACE STEEL BRAKES AND WHEELS WITH GOODRICH CARBON BRAKES AND WHEELS FOR 737-900ER AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	08-AUG-2012			-				
SB	737-32-1456	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO MESSIER-BUGATTI CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900 AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	13-JUN-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32-1457	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO GOODRICH CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900 AIRPLANES (SUPERSEDED BY SB 737-32-1457 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-OCT-2011			-				
SB 737-32-1457 R1	LANDING GEAR - WHEELS AND BRAKES - MAIN LANDING GEAR STEEL BRAKES AND RELATED WHEELS TO GOODRICH CARBON BRAKES AND RELATED WHEELS REPLACEMENT FOR 737-900 AIRPLANES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-FEB-2013			-				
SB 737-32-1458	LANDING GEAR - TIRES AND WHEELS - REPLACEMENT OF WHEEL WELL BLADE SEALS, LOWER FAIRING ASSEMBLIES, AND 43.5 INCH DIAMETER TIRES WITH 44.5 INCH DIAMETER TIRES (SUPERSEDED BY SB 737-32-1458 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1470	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR RADIAL PLY TIRES IN SERVICE EVALUATION FOR AIRPLANES WITH GOODRICH CARBON BRAKES (SUPERSEDED BY SB 737-32-1470 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1470 R1	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR RADIAL PLY TIRES IN SERVICE EVALUATION FOR AIRPLANES WITH GOODRICH CARBON BRAKES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-AUG-2013			-				
SB 737-32-1471	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR RADIAL PLY TIRES IN SERVICE EVALUATION FOR AIRPLANES WITH MESSIER-BUGATTI-DOWTY CARBON BRAKES (SUPERSEDED BY SB 737-32-1471 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1471 R1	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR RADIAL PLY TIRES IN SERVICE EVALUATION FOR AIRPLANES WITH MESSIER-BUGATTI-DOWTY CARBON BRAKES (SUPERSEDED BY SB 737-32-1471 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-32-1471 R2	LANDING GEAR - TIRES AND WHEELS - MAIN LANDING GEAR RADIAL PLY TIRES IN SERVICE EVALUATION FOR AIRPLANES WITH MESSIER-BUGATTI-DOWTY CARBON BRAKES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JUL-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-32A1343	REPLACEMENT OF THE PROXIMITY SWITCH ELECTRONICS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY UNK - PART INSTALLED: P/N 285A1600-4 SN D01197 REF: COMPONENT CODE 311051
		MOS		09-NOV-2005			
26-JUL-2001			-	2281			
		AFL		563			
SB 737-33-1116	PASSENGER SERVICE UNIT NO-SMOKING FASTEN SEAT BELT SIGN-WIRING CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-DEC-1999			-				
SB 737-33-1121 R2	LIGHTS - FLIGHT COMPARTMENTS - AUDIO CONTROL PANEL LAMP TEST WIRING INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-MAR-2011			-				
SB 737-33-1128	LIGHTS - EXTERIOR - REPLACE POSITION LIGHT TRANSFORMERS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JAN-2001			- (s)				
SB 737-33-1130	PASSENGER COMPARTMENT LIGHTS - REPLACE THE 115VAC ATM CONNECTORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JAN-2002			- (s)				
SB 737-33-1130 R1	LIGHTS - PASSENGER COMPARTMENT LIGHTS - REPLACE THE 115VAC ATM CONNECTORS, SERVICE BULLETIN						
		MOS					
02-MAR-2006			-				
SB 737-33-1133	MASTER DIMMER AND TEST- SUPPLY TEST GROUND SIGNAL WIRING SEPERATION, SERVICE BULLETIN						
		MOS	12 (s)				
19-DEC-2002							
SB 737-33-1133 R1	MASTER DIMMER AND TEST- SUPPLY TEST GROUND SIGNAL WIRING SEPERATION, SERVICE BULLETIN						
		MOS	12 (s)				
17-APR-2003							
SB 737-33-1133 R2	MASTER DIMMER AND TEST- SUPPLY TEST GROUND SIGNAL WIRING SEPERATION, SERVICE BULLETIN						
		MOS	30 (s)				
04-DEC-2003							
SB 737-33-1133 R3	LIGHTS - MASTER DIM AND TEST - SUPPLY TEST GROUND SIGNAL WIRING SEPARATION, SERVICE BULLETIN						COMPLIED WITH - IAW THE AD AD 2006-15-18
		MOS		09-AUG-2010			
08-SEP-2005			- (s)	3448:31			
		AFL		841			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-33-1133 R4	MASTER DIM AND TEST - SUPPLY TEST GROUND SIGNAL WIRING SEPARATION (SUPERSEDED BY SB 737-33-1133 R5), SERVICE BULLETIN					SUPERSEDED	- INFORMATION NO MORE WORK IS NECESSARY ON AIRPLANES CHANGED AS SHOWN IN THE REVISION 3 OF THIS SERVICE BULLETIN
		MOS	- (s)				
SB 737-33-1133 R5	LIGHTS - MASTER DIM AND TEST - SUPPLY TEST GROUND SIGNAL WIRING SEPARATION, SERVICE BULLETIN					RECOMMENDED	
05-SEP-2006		MOS	48 (s)				
SB 737-33-1146	LIGHTS - STROBE POSITION LIGHTS - LIGHTNING PROTECTION OF THE TAIL STROBE LIGHT SYSTEM WIRING (SUPERSEDED BY SB 737-33-1146 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-33-1146 R1	LIGHTS - STROBE POSITION LIGHTS - LIGHTNING PROTECTION OF THE TAIL STROBE LIGHT AND SYSTEM WIRING, SERVICE BULLETIN					RECOMMENDED	
02-NOV-2011		MOS	72 (s)				
SB 737-33-1151	LIGHTS - EMERGENCY LIGHTING - MID-CABIN CENTER-AISLE EXIT SIGN INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
27-JAN-2011		MOS	-				
SB 737-33-1152	LIGHTS - RETRACTABLE LANDING LIGHT - REPLACEMENT OF RETRACTABLE LANDING LIGHTS AND WIRE CONNECTORS, SERVICE BULLETIN					RECOMMENDED	
29-AUG-2011		MOS	-				
SB 737-33-1153	LIGHTS - FLIGHT CREW LIGHTS - CAPTAIN'S AND FIRST OFFICER'S UTILITY LIGHT LOCATION CHANGES, SERVICE BULLETIN					RECOMMENDED	
13-OCT-2011		MOS	-				
SB 737-34-1496	NAVIGATION-HEAD UP DISPLAY SYSTEM, SERVICE BULLETIN					RECOMMENDED	
01-JUL-1999		MOS	- (s)				
SB 737-34-1496 R1	NAVIGATION-HEAD UP DISPLAY SYSTEM, SERVICE BULLETIN					RECOMMENDED	
30-SEP-1999		MOS	- (s)				
SB 737-34-1503	FLIGHT MANAGEMENT COMPUTER SYSTEM SOFTWARE VERSION U10.3 UPDATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
27-JUL-2000		MOS	- (s)		08-NOV-2000		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-1503 R1	FLIGHT MANAGEMENT COMPUTER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JAN-2001			- (s)				
SB 737-34-1522	FLIGHT MANAGEMENT COMPUTING - UPDATE SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS		13-SEP-1999			
03-JUN-1999			- (s)				
SB 737-34-1538	FLIGHT MANAGEMENT COMPUTING-DUST COVER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-NOV-1999			- (s)				
SB 737-34-1539	COLLISION AVOIDANCE-TCAS WIRING CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUL-2000			- (s)				
SB 737-34-1540	ALTERNATE NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUL-1999			- (s)				
SB 737-34-1540 R1	ALTERNATE NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-SEP-1999			- (s)				
SB 737-34-1540 R2	ALTERNATE NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-DEC-2000			- (s)				
SB 737-34-1545 R7	REPLACEMENT OF THE ROCKWELL/COLLINS TCAS COMPUTER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-NOV-2001			- (s)				
SB 737-34-1545 R8	REPLACEMENT OF THE ROCKWELL/COLLINS TCAS COMPUTER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-FEB-2002			-				
SB 737-34-1545 R9	REPLACEMENT OF ROCKWELL/COLLINS TCAS COMPUTER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-MAY-2004			-				
SB 737-34-1551	UPGRADE DATA LINK-NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-AUG-2000			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-1551 R1	UPGRADE DATA LINK-NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-OCT-2000			- (s)				
SB 737-34-1551 R2	UPGRADE DATA LINK-NAVIGATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-DEC-2000			- (s)				
SB 737-34-1562	FLIGHT MANAGEMENT COMPUTING - UPGRADE SOFTWARE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-OCT-1999			- (s)				
SB 737-34-1566	FLIGHT MANAGEMENT COMPUTER-SOFTWARE CHANGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS		08-NOV-2000			
03-AUG-2000			- (s)				
SB 737-34-1567	GROUND PROXIMITY WARNING SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-APR-2000			- (s)				
SB 737-34-1572	FLIGHT MANAGEMENT COMPUTER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2000			- (s)				
SB 737-34-1572 R1	FLIGHT MANAGEMENT COMPUTER SYSTEM INSTALLATION OF HEADING REFERENCE SWITCH FOR POLAR NAVIGATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JAN-2001			- (s)				
SB 737-34-1607	UPDATE FLIGHT MANAGEMENT COMPUTER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-SEP-2001			- (s)				
SB 737-34-1616	NAVIGATION - INDEPENDENT POSITION DETERMINING - ENHANCED GROUND PROXIMITY WARNING COMPUTER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JAN-2001			- (s)				
SB 737-34-1634 R1	INSTALLATION OF AN ALTERNATE NAVIGATION SYSTEM AND DATA LINK, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-NOV-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-1650	NAVIGATION-FLIGHT MANAGEMENT COMPUTER (FMC) SYSTEM- UPDATE THE FMC SOFTWARE TO VERSION 10.5, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-FEB-2003			-				
SB 737-34-1650 R1	UPDATE THE FMC SOFTWARE TO VERSION 10.5, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-FEB-2003			-				
SB 737-34-1652	SOFTWARE CHANGE TO ACTIVATE FMCS AND DEU FEATURES., SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-OCT-2001			- (s)				
SB 737-34-1656	FLIGHT MANAGEMENT COMPUTER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-MAY-2002			- (s)				
SB 737-34-1666	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - UPDATE THE FMC SOFTWARE TO VERSION 10.4A, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-APR-2002			- (s)				
SB 737-34-1672	INSTALL FMC OPC SOFTWARE FOR THE "MISSED APPROACH ON MAP IN CYAN" OPTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-DEC-2002			-				
SB 737-34-1720	INTEGRATED STANDBY FLIGHT DISPLAY (ISFD) REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-APR-2003			-				
SB 737-34-1721	AIR DATA INERTIAL REFERENCE SYSTEM (ADIRS)-WIRING CHANGE TO ACTIVATE 2005 MAGVAR TABLE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-APR-2003			-				
SB 737-34-1762 R3	REPLACEMENT OF ATC TRANSPONDERS, AND ACTIVATION OF ELEMENTARY SURVEILLANCE (ELS), ENHANCED SURVEILLANCE (EHS) AND EXTENDED SQUITTER (ES) PARAMETERS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JAN-2005			-				
SB 737-34-1768	NAVIGATION - FLIGHT MANAGEMENT COMPUTER (FMC) SYSTEM - UPDATE THE FMC SOFTWARE TO VERSION 10.6, SERVICE BULLETIN						COMPLIED WITH
		MOS			11-MAY-2006		
11-AUG-2005			-		2619:10		
		AFL			629		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-1811	NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN	MOS	24 (s)				
SB 737-34-1811 R1	NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN	MOS	-	05-OCT-2006			
SB 737-34-1811 R1 E1	INSTALL NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN GROUND PLATE, STUD, AND JUMPER AS SHOWN IN WORK PACKAGE 1 OF THIS SERVICE BULLETIN.	MOS	30 (s)	05-OCT-2006			
SB 737-34-1811 R1 E3	REPLACE NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN THE NUTPLATES WITH CRES NUTPLATES AND SOLID ALUMINUM RIVETS AS SHOWN IN WORK PACKAGE 2 OF THIS SERVICE BULLETIN.	MOS	60 (s)	05-OCT-2006			
SB 737-34-1811E1	MEASURE NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN PITOT PROBE RESISTANCE AS SHOWN IN WORK PACKAGE 1	MOS	18 (s)	25-AUG-2005			
SB 737-34-1811E2	GENERAL VISUAL INSPECTION NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN OF THE PITOT PROBE MOUNTING PLATE NUTPLATES FOR PULL-TYPE/HOLLOW RIVETS AND CORROSION ON THE FASTNER THREADS AND IN THE NUTPLATES.	MOS	30 (s)	25-AUG-2005			
SB 737-34-1811E3	INSTALL NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN GROUND PLATE, STUD AND JUMPER AS SHOWN IN WORK PACKAGE 3	MOS	30 (s)	25-AUG-2005			
SB 737-34-1811E4	REPLACE NAVIGATION - FLIGHT ENVIRONMENT DATA - PITOT STATIC PROBE BOND INSPECTION AND GROUNDING PLATE INSTALLATION, SERVICE BULLETIN THE NUTPLATES WITH CRES NUTPLATES AND SOLID ALUMINUM RIVETS AS SHOWN IN WORK PACKAGE 4	MOS	72 (s)	25-AUG-2005			
SB 737-34-1844	WIRING PROVISIONS FOR FUTURE ACTIVATION OF ELEMENTARY SURVEILLANCE, ENHANCED SURVEILLANCE AND EXTENDED SQUITTER PARAMETERS, SERVICE BULLETIN	MOS	-	29-NOV-2004		RECOMMENDED	

© Camp Systems

EFTA00618383

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-1875	NAVIGATION - INDEPENDENT POSITION DETERMINING - ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-SEP-2005			-				
SB 737-34-1885	ANTENNA WATER WICKING, SERVICE BULLETIN						
		MOS					
09-JUN-2005			-				
SB 737-34-1918	FLIGHT MANAGEMENT COMPUTER (FMC) SYSTEM - UPDATE THE FMC SOFTWARE TO VERSION 10.7, SERVICE BULLETIN						
		MOS					
27-MAR-2007			-				
SB 737-34-1918 R1	NAVIGATION - FLIGHT MANAGEMENT COMPUTER (FMC) SYSTEM - UPDATE THE FMC SOFTWARE TO VERSION 10.7, SERVICE BULLETIN						
		MOS					
14-MAR-2008			-				
SB 737-34-2138	AIR DATA INERTIAL REFERENCE UNIT - STATIC SOURCE ERROR CORRECTION TABLE WIRING CHANGE (SUPERSEDED BY SB 737-34-2138 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34-2138 R1	NAVIGATION - AIR DATA INERTIAL REFERENCE UNIT - STATIC SOURCE ERROR CORRECTION TABLE WIRING CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-FEB-2014			-				
SB 737-34-2155	NAVIGATION - HEAD-UP DISPLAY (HUD) SYSTEM - COMBINER MOUNTING BRACKET CHANGE (SUPERSEDED BY SB 737-34-2155 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34-2155 R1	NAVIGATION - HEAD-UP DISPLAY (HUD) SYSTEM - COMBINER MOUNTING BRACKET CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-AUG-2011			-				
SB 737-34-2284	NAVIGATION - GROUND PROXIMITY WARNING SYSTEM - ENHANCED GROUND PROXIMITY WARNING SYSTEM ALTITUDE CALLOUTS MENU ID 23, SMART 500 CALLOUT, LOW VOLUME FOR ALTITUDE CALLOUTS, AND PEAKS AND OBSTACLES SELECTION CHANGE (SUPERSEDED BY SB 737-34-2284 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

EFTA00618384

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-2284 R1	NAVIGATION - GROUND PROXIMITY WARNING SYSTEM - ENHANCED GROUND PROXIMITY WARNING SYSTEM ALTITUDE CALLOUTS MENU ID 23, SMART 500 CALLOUT, LOW VOLUME FOR ALTITUDE CALLOUTS, AND PEAKS AND OBSTACLES SELECTION CHANGE (SUPERSEDED BY SB 737-34-2284 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34-2286	NAVIGATION - GLOBAL POSITIONING SYSTEM - CHANGE AND DEACTIVATION OF CATEGORY I APPROACH CAPABILITY OF THE GLOBAL NAVIGATION SATELLITE SYSTEM LANDING SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-JAN-2011			-				
SB 737-34-2287 R1	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - AUTOFLIGHT, FLIGHT MANAGEMENT COMPUTER SYSTEM, COMMON DISPLAY SYSTEM, FUEL QUANTITY INDICATION SYSTEM - CHANGE OPTIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JAN-2011			-				
SB 737-34-2290	NAVIGATION - AUTOMATIC DIRECTION FINDER SYSTEM - INSTALLATION OF SECOND AUTOMATIC DIRECTION FINDER INTO EXISTING PROVISIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-DEC-2010			-				
SB 737-34-2293	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - CHANGE OPERATION FROM FAA TO JAA/EASA FLIGHT RULES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-DEC-2010			-				
SB 737-34-2294	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - CHANGE OPERATION FROM FAA TO JAA/EASA FLIGHT RULES (SUPERSEDED BY SB 737-34-2294 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34-2296	NAVIGATION - AUTOMATIC DIRECTION FINDER SYSTEM - INSTALLATION OF SECOND AUTOMATIC DIRECTION FINDER INTO EXISTING PROVISIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-JAN-2011			-				
SB 737-34-2297	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - CHANGE OPERATION FROM FEDERAL AVIATION ADMINISTRATION TO JOINT AVIATION AUTHORITIES/EUROPEAN AVIATION SAFETY AGENCY FLIGHT RULES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JAN-2011			-				
SB 737-34-2298	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - CHANGE FROM JOINT AVIATION AUTHORITIES TO FEDERAL AVIATION ADMINISTRATION FLIGHT RULES AND DUAL AIRPLANE FLIGHT MANUAL FORMAT SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-JAN-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34-2300	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - CHANGE OPERATION FROM JOINT AVIATION AUTHORITIES/EUROPEAN AVIATION SAFETY AGENCY TO FEDERAL AVIATION ADMINISTRATION FLIGHT RULES (SUPERSEDED BY SB 737-34-2300 R1), SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JAN-2011			-				
SB 737-34-2327	NAVIGATION - FLIGHT MANAGEMENT COMPUTING - DIP SWITCH POSITION CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-DEC-2011			-				
SB 737-34-2384	NAVIGATION - WEATHER RADAR SYSTEM - INSPECTION AND REPLACEMENT OF WEATHER RADAR ANTENNA WIRE BUNDLE W8489, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-NOV-2012			-				
SB 737-34-2395	NAVIGATION - LOW RANGE RADIO ALTIMETER - INSTALLATION OF THE ANTENNA GASKETS (SUPERSEDED BY SB 737-34-2395 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34-2395 R1	NAVIGATION - LOW RANGE RADIO ALTIMETER - INSTALLATION OF THE ANTENNA GASKETS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-OCT-2013			-				
SB 737-34-2413	NAVIGATION - STANDBY ATTITUDE REFERENCE SYSTEM - INTEGRATED STANDBY FLIGHT DISPLAY BACK COURSE PROGRAM PIN CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-OCT-2012			-				
SB 737-34-2432	NAVIGATION - GROUND PROXIMITY WARNING SYSTEM - INTEGRATED AREA NAVIGATION TURNED OFF BY WIRING CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-NOV-2012			-				
SB 737-34-2454	NAVIGATION - AIR DATA SYSTEM - ALTIMETRY SYSTEM TEST, SERVICE BULLETIN						
		MOS					
			-				
SB 737-34-2461	NAVIGATION - ATC SYSTEM - ROCKWELL COLLINS AIR TRAFFIC CONTROL TRANSPONDER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-MAY-2013			-				
SB 737-34A1502	FLIGHT MANAGEMENT COMPUTER SYSTEM (SUPERSEDED BY SB 737-34A1502 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-34A1502 R1	FLIGHT MANAGEMENT COMPUTER SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-MAY-1999			- (s)				
SB 737-34A1801	CHANGE THE OPERATIONAL PROGRAM SOFTWARE TO VERSION 10.5A, SERVICE BULLETIN						COMPLIED WITH
		DAYS		11-MAY-2006			
15-JUL-2004			-	2619:10			
		AFL		629			
SB 737-34A2104	FLIGHT MANAGEMENT COMPUTER SYSTEM - FLIGHT MANAGEMENT COMPUTER OPERATIONAL PROGRAM SOFTWARE U10.8 INSTALLATION (SUSPENDED BY 737-34A2104 N1), SERVICE BULLETIN					SUPERSEDED	- INFO: THIS SOFTWARE WAS SUPERSEDED BY U10.8A SOFTWARE WHICH WAS RECENTLY INSTALLED.
		MOS					
			-				
SB 737-34A2216	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - FLIGHT MANAGEMENT COMPUTER OPERATIONAL PROGRAM SOFTWARE U10.8A SOFTWARE INSTALLATION (SUPERSEDED BY SB 737-34A2216 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-34A2216 R1	NAVIGATION - FLIGHT MANAGEMENT COMPUTER SYSTEM - FLIGHT MANAGEMENT COMPUTER OPERATIONAL PROGRAM SOFTWARE U10.8A SOFTWARE INSTALLATION , SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		16-MAY-2012			
09-JUN-2010			-	3634:25			
		AFL		882			
SB 737-34A2292	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM - AIR SPEED LOW ALERT CHANGES, SERVICE BULLETIN					RECOMMENDED	
		MOS	12 (s)				
27-APR-2012							
SB 737-35-1049	PURITAN-BENETT OXYGEN MASKS, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS		06-JAN-2007			
			- (s)				
SB 737-35-1077	OXYGEN GENERATOR FIRING PIN LOCATION, SERVICE BULLETIN					RECOMMENDED	
		DAYS	90 (s)				
01-MAR-2001							
SB 737-35-1080	OXYGEN - FLIGHT CREW OXYGEN SYSTEM - INSTALLATION OF HOSE SEPARATION SUPPORT FOR REMOTE FILL TUBING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
07-JUL-2005			-				

© Camp Systems

EFTA00618387

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-35-1107	OXYGEN - PASSENGER OXYGEN SYSTEM - CHANGE 22 MINUTE OXYGEN GENERATOR RETENTION IN THE PASSENGER SERVICE UNITS, SERVICE BULLETIN						
		MOS	60 (s)				
04-JAN-2008							
SB 737-35A1058	CREW OXYGEN - HOSE REPLACEMENT (SUPERSEDED BY SB 737-35A1058 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-35A1058 R1	CREW OXYGEN - HOSE REPLACEMENT (SUPERSEDED BY SB 737-35A1058 R2), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - AND REPLACED PARTS I.A.W. AD 2010-16-06
		MOS		27-AUG-2010			
			- (s)	3448:31			
		AFL		841			
SB 737-35A1058 R2	OXYGEN - CREW OXYGEN - CREW OXYGEN SYSTEM LOW PRESSURE FLEX HOSE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - DURING COMPLIED WITH 737-35A1058 R1 REPLACED PILOT & CO PILOT FLEX HOSES BY P/N 60B50059-61B. REPLACED FIRST OBSERVER FLEX HOSE BY P/N 60B50056-614 NO MORE ACTION REQUIRED
		MOS		21-FEB-2013			
09-SEP-2010			-	3702:13			
		AFL		897			
SB 737-35A1121	CREW OXYGEN MASK STOWAGE BOX UNIT -INSPECT/REPLACE (SUPERSEDED BY SB 737-35A1121 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS		(EFF)			
			-				
SB 737-35A1121 R1	OXYGEN - CREW OXYGEN SYSTEM - CREW OXYGEN MASK STOWAGE BOX UNIT - INSPECT/REPLACE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - DUE TO VARIABLE NUMBER OF THE A/C YG006
		MOS		19-JAN-2012			
14-DEC-2009			-	3609:52			
		AFL		879			
SB 737-35A1126	CREW AND PASSENGER GASEOUS OXYGEN SYSTEMS - OXYGEN CYLINDER INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER INSTALLED
		DAYS		16-FEB-2010			
29-OCT-2009			-	3417:51			
		AFL		829			
SB 737-36-1019	ENGINE BLEED AIR DISTRIBUTION SYSTEM - CLAMP INSTALLATION ON ENGINE SENSE TUBES FOR THE PNEUMATIC SYSTEM FLEX LINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-36-1019 R1	CLAMP INSTALLATION ON ENGINE SENSE TUBES FOR THE PNEUMATIC SYSTEM FLEX LINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-FEB-2010			-				
SB 737-36-1020	DISTRIBUTION - PNEUMATIC MANIFOLD SYSTEM - REPLACEMENT OF AUXILIARY POWER UNIT PNEUMATIC DUCTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JAN-2011			-				
SB 737-36-1021	PNEUMATIC - BLEED AIR PRECOOLER SYSTEM - CHANGE TO THE AIRCRAFT CONDITION MONITORING SYSTEM TO GIVE MORE INPUTS TO THE DIGITAL FLIGHT DATA ACQUISITION UNIT FOR EASIER ENVIRONMENTAL CONTROL SYSTEM TROUBLESHOOTING (SUPERSEDED BY SB 737-36-1021 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-36-1021 R1	PNEUMATIC - BLEED AIR PRECOOLER SYSTEM - CHANGE TO THE AIRCRAFT CONDITION MONITORING SYSTEM TO GIVE MORE INPUTS TO THE DIGITAL FLIGHT DATA ACQUISITION UNIT FOR EASIER ENVIRONMENTAL CONTROL SYSTEM TROUBLESHOOTING (SUPERSEDED BY SB 737-36-1021 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-36-1021 R2	PNEUMATIC - BLEED AIR PRECOOLER SYSTEM - CHANGE TO THE AIRCRAFT CONDITION MONITORING SYSTEM TO GIVE MORE INPUTS TO THE DIGITAL FLIGHT DATA ACQUISITION UNIT FOR EASIER ENVIRONMENTAL CONTROL SYSTEM TROUBLESHOOTING (SUPERSEDED BY SB 737-36-1021 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-36-1021 R3	PNEUMATIC - BLEED AIR PRECOOLER SYSTEM - CHANGE TO THE AIRCRAFT CONDITION MONITORING SYSTEM TO GIVE MORE INPUTS TO THE DIGITAL FLIGHT DATA ACQUISITION UNIT FOR EASIER ENVIRONMENTAL CONTROL SYSTEM TROUBLESHOOTING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-OCT-2013			-				
SB 737-38-1046	POTABLE WATER - ADDITION OF INSULATION TO THE WATER SUPPLY LINES, SERVICE BULLETIN						
		MOS					
07-MAR-2002			- (s)				
SB 737-38-1048	WATER/WASTE-WASTE DISPOSAL-DRAIN MAST-INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY (REPLACED BY 737-38-1053), SERVICE BULLETIN					RECOMMENDED	- SUPERSEDED BY S/B 737-38-1053
		MOS					
16-JAN-2003			500 (s)				
SB 737-38-1048 R1	WATER/WASTE - WASTE DISPOSAL - DRAIN MAST - INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY (SUPERSEDED BY 737-38-1053), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

EFTA00618389

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-38-1053	WATER/WASTE - WASTE DISPOSAL - DRAIN MAST - INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY, SERVICE BULLETIN						
		MOS					
15-SEP-2005			500 (s)				
SB 737-38-1053 R1	WASTE DISPOSAL - DRAIN MAST - INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2009			-				
SB 737-38-1053 R1.1	GENERAL VISUAL INSPECTION WASTE DISPOSAL - DRAIN MAST - INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY, SERVICE BULLETIN OF THE FORWARD DRAIN MAST ASSEMBLY					RECOMMENDED	
		MOS					
14-SEP-2009			500 (s)				
SB 737-38-1053 R1.2	REPLACE WASTE DISPOSAL - DRAIN MAST - INSPECTION FOR FATIGUE CRACKS/REPLACEMENT OF A CRACKED FORWARD DRAIN MAST ASSEMBLY, SERVICE BULLETIN WITH ALUMINUM DRAIN MAST ASSEMBLY					RECOMMENDED	
		MOS	60 (s)				
14-SEP-2009							
SB 737-38-1057	POTABLE WATER - PASSENGER WATER SYSTEM - HOSE AND FITTING REPLACEMENT, FITTING HEATER AND SHROUD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-FEB-2010			-				
SB 737-44-1001	CABIN SYSTEMS - INFLIGHT ENTERTAINMENT SYSTEM - INSTALLATION OF LATCH PLATES ON THE AFT AUDIO DISTRIBUTION BOX, SERVICE BULLETIN						
		MOS					
07-JUN-2010			-				
SB 737-44-1006	CABIN SYSTEMS - PASSENGER AUDIO/VIDEO ENTERTAINMENT SYSTEM - IN-FLIGHT ENTERTAINMENT SYSTEM AUDIO HUM NOISE CORRECTIVE WIRING CHANGES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-JUL-2013			-				
SB 737-44-1007	CABIN SYSTEMS - CREW PANELS - GROMMET INSTALLATION FOR IN-FLIGHT ENTERTAINMENT SYSTEM CONTROL PANEL STOWAGE BOX, SERVICE BULLETIN					RECOMMENDED	
		MOS					
03-DEC-2013			-				
SB 737-46-1009	CREW INFORMATION SYSTEM - ELECTRONIC FLIGHT BAG HARDWARE AND SOFTWARE REPLACEMENT, SERVICE BULLETIN						
		MOS					
08-JAN-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-46-1011	INFORMATION SYSTEMS - CREW INFORMATION SYSTEM - ELECTRONIC FLIGHT BAG HARDWARE AND SOFTWARE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-OCT-2010			-				
SB 737-46-1013	INFORMATION SYSTEMS - CREW INFORMATION SYSTEM - ELECTRONIC FLIGHT BAG SOFTWARE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-NOV-2012			-				
SB 737-47-1002	INERT GAS SYSTEM - INSTALLATION OF THE PROVISIONS FOR NITROGEN GENERATION SYSTEM (SUPERSEDED BY SB 737-47-1002 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-47-1002 R1	INERT GAS SYSTEM - INSTALLATION OF THE PROVISIONS FOR NITROGEN GENERATION SYSTEM (SUPERSEDED BY SB 737-47-1002 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-47-1002 R2	INERT GAS SYSTEM - INSTALLATION OF THE PROVISIONS FOR NITROGEN GENERATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-NOV-2013			-				
SB 737-47-1003	INERT GAS SYSTEM - INSTALLATION OF THE NITROGEN GENERATION SYSTEM (SUPERSEDED BY SB 737-47-1003 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-47-1003 R1	INERT GAS SYSTEM - INSTALLATION OF THE NITROGEN GENERATION SYSTEM (SUPERSEDED BY SB 737-47-1003 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-47-1003 R2	INERT GAS SYSTEM - INSTALLATION OF THE NITROGEN GENERATION SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-SEP-2013			-				
SB 737-47-1006	NITROGEN GENERATION SYSTEM - INSTALLATION OF OXYGEN SENSOR, REPLACEMENT OF EQUIPMENT AND WIRE BUNDLES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-FEB-2010			-				
SB 737-47-1011	INERT GAS SYSTEM - AIR SEPARATION UNIT - AIR SEPARATION MODULE HIGH FLOW VALVE CONNECTOR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-OCT-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-47-1012	INERT GAS SYSTEM - AIR SEPARATION UNIT - INSPECTION OF TUBES AND CLAMP INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-APR-2012			-				
SB 737-49-1119	APU - ELECTRONIC CONTROL UNIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JUN-1999			- (s)				
SB 737-49-1133	AIRBORNE AUXILIARY POWER - AUXILARY POWER UNIT AIR INLET - AUXILARY POWER UNIT FLAP AND VORTEX GENERATOR ASSEMBLY MOSIFICATION, SERVICE BULLETIN						
		MOS					
22-SEP-2005			-				
SB 737-49-1133 R1	AIRBORNE AUXILIARY POWER - AUXILIARY POWER UNIT AIR INLET - AUXILIARY POWER UNIT FLAP AND VORTEX GENERATOR ASSEMBLY MODIFICATION, SERVICE BULLETIN						
		MOS					
21-SEP-2007			-				
SB 737-49-1133 R2	AUXILIARY POWER UNIT FLAP AND VORTEX GENERATOR ASSEMBLY MODIFICATION, SERVICE BULLETIN						
		MOS					
26-JAN-2009			-				
SB 737-49-1134	AIRBORNE AUXILIARY POWER - APU AIR INLET - INLET PLENUM REPLACEMENT, SERVICE BULLETIN						
		MOS					
16-OCT-2007			-				
SB 737-49-1139	AIRBORNE AUXILIARY POWER - COWL DOOR INSULATION PANEL AND AFT BULKHEAD SEAL REPLACEMENT (SUPERSEDED BY SB 737-49-1139 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-49-1139 R1	AIRBORNE AUXILIARY POWER - COWL DOOR INSULATION PANEL AND AFT BULKHEAD SEAL REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-OCT-2012			-				
SB 737-51-1017 R1	E1/E5 MOISTURE SHROUD SEAL INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-MAR-2002			-				
SB 737-51-1018	CARGO DOORWAY STOP PAD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-APR-2002			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-51-1019	STRUCTURES - WIRE SHIELD ASSEMBLY INSTALLATION UNDER THE E5-2 SHELF, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-APR-2002			-				
SB 737-51-1019 R1	STRUCTURES - WIRE SHIELD ASSEMBLY INSTALLATION UNDER THE E5-2 SHELF, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-DEC-2003			-				
SB 737-52-1136	EMERGENCY EXIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-JUN-2000			- (s)				
SB 737-52-1137	DOORS - CONTROL CABIN EMERGENCY EXIT PANEL, SERVICE BULLETIN						
		MOS					
			- (s)				
SB 737-52-1138	ELECTRONIC EQUIPMENT ACCESS DOOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-JUL-1999			- (s)				
SB 737-52-1140	FORWARD ENTRY - UPPER AFT CORNER DOOR STOP REPLACEMENT, SERVICE BULLETIN						
		MOS					
20-AUG-2001							
		AFL	18000 (s)				
SB 737-52-1142	AFT GALLEY SERVICE DOOR, SERVICE BULLETIN					RECOMMENDED	
		MOS	4 (s)				
22-FEB-2001							
SB 737-52-1148	HORIZONTAL AIRSTAIRS MOISTURE SHROUD INSTALATION SUPPORT RAIL REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-DEC-2002			-				
SB 737-52-1148 R1	FUSELAGE - HORIZONTAL AIRSTAIRS MOISTURE SHROUD INSTALLATION - SUPPORT RAIL REPLACEMENT, SERVICE BULLETIN						
		MOS					
11-MAY-2006			-				
SB 737-52-1152	DOORS - FORWARD AIRSTAIR DOOR RELIABILITY IMPROVEMENT - REPLACE DOOR LOCKPIN ACTUATORS, OPEN LIMIT/WARNING SWITCH BRACKETS, AND RACEWAY COVER ASSEMBLY, SERVICE BULLETIN						
		MOS					
08-SEP-2005			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-52-1156	DOORS - FORWARD AIRSTAIR AND DOOR - FORWARD AIRSTAIR SPEEDUP AND SLOWDOWN SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
01-DEC-2005			-				
SB 737-52-1157	ENTRANCE STAIRS - FORWARD AIRSTAIR - AIRSTAIR HANDRAIL SAFETY IMPROVEMENTS (SUPERSEDED BY SB 737-52-1157 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-52-1157 R1	DOORS - ENTRANCE STAIRS - FORWARD AIRSTAIR - AIRSTAIR HANDRAIL SAFETY IMPROVEMENTS, SERVICE BULLETIN						
		MOS					
			-				
SB 737-52-1159	DOORS - DOOR WARNING SYSTEM - FORWARD ENTRY DOOR LATCH SWITCH AND WIRING INSTALLATION AND MODIFICATION, SERVICE BULLETIN						
		MOS					
26-NOV-2007			-				
SB 737-52-1159 R1	DOOR WARNING SYSTEM - FORWARD ENTRY DOOR LATCH SWITCH AND WIRING INSTALLATION AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-SEP-2009			-				
SB 737-52-1164	FORWARD AND AFT CARGO DOORS - LANYARD ASSEMBLY REPLACEMENT, SERVICE BULLETIN						
		MOS					
20-JAN-2009			-				
SB 737-52-1165	AFT ENTRY AND AFT GALLEY SERVICE DOOR - DOOR SNUBBER STOP LINK ASSEMBLY CHANGE, SERVICE BULLETIN						
		MOS					
29-JUL-2008			-				
SB 737-52-1165 R1	AFT ENTRY AND AFT GALLEY SERVICE DOOR - DOOR SNUBBER STOP LINK ASSEMBLY CHANGE, SERVICE BULLETIN						
		MOS					
15-JAN-2009			-				
SB 737-52-1169	DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN						
		MOS					
13-DEC-2011			-				
SB 737-52-1169 TABLE 1	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN A GENERAL VISUAL INSPECTION OF THE INBOARD MLG DOOR FOR IDENTIFICATION					RECOMMENDED	
		MOS					
13-DEC-2011							
		AFL	5500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-52-1169 TABLE 2.1L	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN A DETAILED INSPECTION OF THE LEFT INBOARD MLG DOOR FOR ANY CRACKS	MOS			13-DEC-2011	RECOMMENDED	
		AFL	5500 (s)				
SB 737-52-1169 TABLE 2.1R	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN A DETAILED INSPECTION OF THE RIGHT INBOARD MLG DOOR FOR ANY CRACKS	MOS			13-DEC-2011	RECOMMENDED	
		AFL	5500 (s)				
SB 737-52-1169 TABLE 2.2L	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN APPLICABLE SRM REPAIR WITHIN THE ALLOWABLE DAMAGE 1 LIMITS (ANY PART-THROUGH CRACK IS FOUND.) LEFT MLG INBOARD DOOR	MOS			BF/F (s)	RECOMMENDED	
SB 737-52-1169 TABLE 2.2R	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN APPLICABLE SRM REPAIR WITHIN THE ALLOWABLE DAMAGE 1 LIMITS (ANY PART-THROUGH CRACK IS FOUND.) RIGHT MLG INBOARD DOOR	MOS			BF/F (s)	RECOMMENDED	
SB 737-52-1169 TABLE 2.3L	REPLACE DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN THE LEFT INBOARD MLG DOOR AND PREFORM A DETAILED INSPECTION OF THE INBOARD MLG DOOR FOR ANY CRACKS	MOS			BF/F (s)	RECOMMENDED	
SB 737-52-1169 TABLE 2.3R	REPLACE DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN THE RIGHT INBOARD MLG DOOR AND PREFORM A DETAILED INSPECTION OF THE INBOARD MLG DOOR FOR ANY CRACKS	MOS			BF/F (s)	RECOMMENDED	
SB 737-52-1169 TABLE 3.1L	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN A DETAILED INSPECTION OF THE LEFT INBOARD MLG DOOR FOR ANY CRACKS	MOS			13-DEC-2011	RECOMMENDED	
		AFL	5500 (s)				
SB 737-52-1169 TABLE 3.1R	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN A DETAILED INSPECTION OF THE RIGHT INBOARD MLG DOOR FOR ANY CRACKS	MOS			31-DEC-2011	RECOMMENDED	
		AFL	5500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-52-1169 TABLE 3.2L	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN APPLICABLE SRM REPAIR WITHIN THE ALLOWABLE DAMAGE 1 LIMITS AND DETAILED INSPECTION OF THE LEFT INBOARD MLG DOOR					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-52-1169 TABLE 3.2R	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN APPLICABLE SRM REPAIR WITHIN THE ALLOWABLE DAMAGE 1 LIMITS AND DETAILED INSPECTION OF THE RIGHT INBOARD MLG DOOR					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-52-1169 TABLE 3.3L	REPLACE DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN THE LEFT INBOARD MLG DOOR DOOR WITH INBOARD MLG DOOR MADE FROM MACHINED ALUMINUM, 113A8335-( ), OR INBOARD MLG DOOR MADE FROM CAST ALUMINUM, 113A8331-( ), AND DETAILED INSPECTION					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-52-1169 TABLE 3.3R	REPLACE DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOORS - INSPECTION AND REPAIR, SERVICE BULLETIN THE RIGHT INBOARD MLG DOOR DOOR WITH INBOARD MLG DOOR MADE FROM MACHINED ALUMINUM, 113A8335-( ), OR INBOARD MLG DOOR MADE FROM CAST ALUMINUM, 113A8331-( ), AND DETAILED INSPECTION					RECOMMENDED	
		MOS	BF/F (s)				
SB 737-52-1170	DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-JUL-2014			-				
SB 737-52-1170 TBL 1.1	DETAILED INSPECTION DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN OF MLG CENTER DOOR ASSEMBLY ATTACHMENTS (PART 2) FOR ANY LOOSE, MISSING, DAMAGED OR BOTTOMED OUT BOLTS, OR ANY WEAR TO THE RETENTION CLIP ASSEMBLIES, OR IF RETENTION CLIP ASSEMBLIES ARE NOT INSTALLED, FOR ANY LOOSE, MISSING OR DAMAGED BOLTS (ALL AIRPLANES)					RECOMMENDED	
		MOS					
		AFL	12000 (s)				
SB 737-52-1170 TBL 1.2	DO DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN PART 4: MLG CENTER DOOR ASSEMBLY ATTACHMENTS - REMOVAL / PART 5: MLG CENTER DOOR ASSEMBLY RETENTION CLIP ASSEMBLIES - MODIFICATION / REPEAT PART - 2 (IF CONDITION 1: NO LOOSE, MISSING, DAMAGED OR BOTTOMED OUT BOLTS AND NO WEAR TO THE RETENTION CLIP ASSEMBLIES)					RECOMMENDED	
		MOS					
29-JUL-2014			BF/F				

© Camp Systems

EFTA00618396

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-52-1170 TBL 1.3	DO DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN PART 3: MLG CENTER DOOR ASSEMBLY ATTACHMENTS - REMOVAL AND BUSHING DETAILED INSPECTION/MEASUREMENT FOR EXCESSIVE WEAR, GALLING AND CRACKS (IF CONDITION 2: ANY LOOSE, MISSING, DAMAGED OR BOTTOMED OUT BOLTS, OR ANY WEAR TO THE RETENTION CLIP ASSEMBLIES)					RECOMMENDED	
		MOS					
29-JUL-2014			BF/F				
SB 737-52-1170 TBL 1.4	DO DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN PART 7: BUSHING REMOVAL/ REPAIR, LUG MAGNETIC PARTICLE INSPECTION/ REPAIR / PART 5: MLG CENTER DOOR ASSEMBLY RETENTION CLIP ASSEMBLIES - MODIFICATION / PART 7: BUSHING REMOVAL/ REPAIR, LUG MAGNETIC PARTICLE INSPECTION/ REPAIR / PART 6: MLG CENTER DOOR ASSEMBLY BOLTS AND RETENTION CLIP ASSEMBLIES - REPLACEMENT / REPEAT PART 2 (IF CONDITION 3: ANY EXCESSIVE WEAR FOUND IN THE INTERNAL DIAMETER OF THE BUSHING OR ANY GALLING FOUND OR ANY CRACK FOUND)					RECOMMENDED	
		MOS					
29-JUL-2014			BF/F				
SB 737-52-1170 TBL 1.5	DO DOORS - LANDING GEAR CENTER DOOR ASSEMBLY ATTACHMENTS - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN PART 5: MLG CENTER DOOR RETENTION CLIP ASSEMBLIES - MODIFICATION / PART 6: MLG CENTER DOOR ASSEMBLY BOLTS AND RETENTION CLIP ASSEMBLIES - REPLACEMENT / REPEAT PART 2 (IF CONDITION 4: NO EXCESSIVE WEAR FOUND IN THE INTERNAL DIAMETER OF THE BUSHING AND NO GALLING AND NO CRACKS FOUND)					RECOMMENDED	
		MOS					
29-JUL-2014			BF/F				
SB 737-52-1173	FORWARD AIRSTAIR - STAIR TREAD - ANTI-SLIP MATERIAL EDGE SEAL MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JUN-2014			- (s)				
SB 737-52A1167	DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOOR HINGE FITTINGS - INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS		(EFF)			
01-DEC-2011			-				
SB 737-52A1167 TABLE 1 LMLG	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOOR HINGE FITTINGS - INSPECTION AND REPLACEMENT, SERVICE BULLETIN DETAILED INSPECTION OR HFEC INSPECTION OF THE LEFT INBOARD MLG DOOR HINGE FITTINGS FOR CRACKS FOR AIRPLANES					RECOMMENDED	
		MOS					
		AFL	10000		**10000**		
SB 737-52A1167 TABLE 1 RMLG	PERFORM DOORS - LANDING GEAR DOORS - INBOARD MAIN LANDING GEAR DOOR HINGE FITTINGS - INSPECTION AND REPLACEMENT, SERVICE BULLETIN DETAILED INSPECTION OR SURFACE HFEC INSPECTION OF THE RIGHT INBOARD MLG DOOR HINGE FITTINGS FOR CRACKS					RECOMMENDED	
		MOS					
		AFL	10000		**10000**		

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1217	SECTION 43 AND SECTION 47 - STR 17 SKIN CRACKS AT STA 364-371 AND STA 890-900, SERVICE BULLETIN					RECOMMENDED	
09-AUG-2001		MOS					
		AFL	36000 (s)				
SB 737-53-1219	FUSELAGE SECTION 44 - S18A WEB FITTING FLANGE CRACKS, INSPECTION AND REPAIR, SERVICE BULLETIN					RECOMMENDED	
16-AUG-2001		MOS					
		AFL	30000		**30000**		
SB 737-53-1222	FUSELAGE - SECTION 41 CAB - POINT D SPLICE FITTING REPLACEMENT (SUPERSEDED BY 737-53A1222 R1), SERVICE BULLETIN					SUPERSEDED	
06-JUN-2002		MOS	-				
SB 737-53-1223	MAIN LANDING GEAR FAIRING REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
29-NOV-2001		MOS	- (s)				
SB 737-53-1227	NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN					RECERTIFY	- INFORMATION REF TO R2
03-OCT-2002		MOS	- (s)				
SB 737-53-1227 R1	NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN						- INFORMATION REF TO R2
26-AUG-2006		MOS	-				
SB 737-53-1227 R2	FUSELAGE - WHEEL WELLS - NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - TERMINATED
		MOS		22-AUG-2008			
14-NOV-2007			-	3260:48			
		AFL		782			
SB D 737-53-1227 R2 PARA	REPLACE FUSELAGE - WHEEL WELLS - NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN BUSHINGS					REPLACE	COMPLIED WITH - REPLACEMENT
		MOS		22-AUG-2008			
14-NOV-2007			-	3260:48			
		AFL		782			
SB E 737-53-1227 R2 PARA	INSPECT FUSELAGE - WHEEL WELLS - NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - MIGRATION FOUND / REPLACEMENT PERFORMED TERMINATING ACTION
		MOS		22-AUG-2008			
			-	3260:48			
		AFL		782			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1227 R3	NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
18-NOV-2009		MOS	-				
SB 737-53-1227 R3 PARA E (DT INS)	DETAILED INSPECTION NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN FOR CORROSION OF THE FITTINGS						
		MOS	3 (s)				
SB 737-53-1227 R3 PARA E (I INSP)	INITIAL INSPECTION NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
18-NOV-2009		MOS					
		AFL	2000 (s)				
SB 737-53-1227 R3 PARA E (RPL)	REPLACE NOSE WHEEL DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN BUSHING					REPLACE	
18-NOV-2009		MOS	12 (s)				
SB 737-53-1232	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTATIVE MODIFICATION (SUPERSEDED BY 737-53-1232 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-53-1232 R1	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTATIVE MODIFICATION (SUPERSEDED BY SB 737-53-1232 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-53-1232 R1 TABLE 1	DETAILED INSPECTION FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTATIVE MODIFICATION (SUPERSEDED BY SB 737-53-1232 R2), SERVICE BULLETIN AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKS IN THE FUSELAGE SKIN AT THE CHEM-MILLED STEPS AT SPECIFIED LOCATIONS					RECOMMENDED	
		MOS					
		AFL	35000		**35000**		
SB 737-53-1232 R2	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
26-JUL-2013		MOS	-				
SB 737-53-1232 R2 TABLE 1.01	EXTERNAL - DETAILED INSPECTION FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN AND AN EXTERNAL NDI (EXT.MFEC/MOI/C-SCAN/EXT.UTPA) FOR CRACKS IN THE FUSELAGE SKIN AT THE CHEM-MILLED STEPS AT SPECIFIED LOCATIONS (FOR AIRPLANES WITHOUT THE PREVENTATIVE MODIFICATION, TIME-LIMITED REPAIR OR PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)						
		MOS	-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1232 R2 TABLE 1.02	REPAIR FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN ANY CRACK THAT IS FOUND IN THE SKIN	MOS	-				
SB 737-53-1232 R2 TABLE 1A.01	INSPECT FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN FOR CRACKS IN THE FUSELAGE SKIN AT THE CHEM-MILLED STEPS AT THE SPECIFIED LOCATIONS (FOR AIRPLANES WITH PREVENTATIVE MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SB AT OR BEFORE 30,000 TOTAL FC)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 1A.02	INSPECT FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN FOR CRACKS IN THE FUSELAGE SKIN AT THE CHEM-MILLED STEPS AT THE SPECIFIED LOCATIONS (FOR AIRPLANES WITH PREVENTATIVE MODIFICATION THAT WERE INSTALLED IN ACCORDANCE WITH THIS SB AFTER 30,000 TOTAL FC)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 1A.03	CONTACT FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN BOEING AND ACCOMPLISH THE WORK INSTRUCTED (IF ANY CRACK IS FOUND IN THE SKIN)	MOS	-				
SB 737-53-1232 R2 TABLE 1B.01.1	HFEC FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN INSPECTION FOR CRACKS (IF PREVENTATIVE MODIFICATION INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 1B.01.2	DEATILED INSPECTION FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN FOR CRACKS AND ANY LOOSE OR MISSING FASTENERS (IF PREVENTATIVE MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 1B.02	CONTACT FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN BOEING AND ACCOMPLISH THE WORK INSTRUCTED (IF ANY CRACK FOUND IN THE SKIN)	MOS	-				
SB 737-53-1232 R2 TABLE 1B.03	REPLACE FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN THE LOOSE OR MISSING FASTENER	MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1232 R2 TABLE 2.01.1.1	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN SKIN INSPECTION OPTION 1 - EXTERNAL LFEC FOR CRACKS (FOR AIRPLANES WITH THE PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 2.01.1.2	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN SKIN INSPECTION OPTION 1 - DOUBLER INSPECTION: EXTERNAL LFEC FOR CRACKS AND AN EXTERNAL DETAILED INSPECTION FOR CRACKS AND LOOSE/MISSING FASTENERS (FOR AIRPLANES WITH THE PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 2.01.2.1	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN SKIN INSPECTION OPTION 2 - EXTERNAL LFEC FOR CRACKS (FOR AIRPLANES WITH THE PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 2.01.2.2	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN SKIN INSPECTION OPTION 2 - INTERNAL MFEC FOR CRACKS (FOR AIRPLANES WITH THE PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 2.01.2.3	FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN SKIN INSPECTION OPTION 2 - DOUBLER INSPECTION: EXTERNAL LFEC FOR CRACKS AND AN EXTERNAL DETAILED INSPECTION FOR CRACKS AND LOOSE/MISSING FASTENERS (FOR AIRPLANES WITH THE PERMANENT REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)	MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 2.02	REPAIR FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN ANY CRACK FOUND (IF ANY CRACK IS FOUND IN THE SKIN)	MOS	-				
SB 737-53-1232 R2 TABLE 2.03	REPLACE FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN LOOSE AND MISSING FASTENERS (IF ANY LOOSE OR MISSING FASTENER)	MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1232 R2 TABLE 3.01.1	INTERNAL FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN / EXTERNAL DETAILED INSPECTION OF A TIME-LIMITED REPAIR FOR CRACKS AND LOOSE OR MISSING FASTENERS (FOR AIRPLANES WITH THE TIME-LIMITED REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)						
		MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 3.01.2	REPLACE FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN THE TIME-LIMITED REPAIR WITH THE PERMANENT REPAIR (FOR AIRPLANES WITH THE TIME-LIMITED REPAIR INSTALLED IN ACCORDANCE WITH THIS SB)						
		MOS	-				
		AFL					
SB 737-53-1232 R2 TABLE 3.02	REPAIR FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN ANY CRACK FOUND IN THE SKIN						
		MOS	-				
SB 737-53-1232 R2 TABLE 3.03	REPLACE FUSELAGE - SKIN - CHEMICALLY MILLED STEPS - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN LOOSE AND MISSING FASTENERS						
		MOS	-				
SB 737-53-1232 TABLE 1	AIRPLANES WITH/WITHOUT THE PREVENTATIVE MODIFICATION INSTALLED. (SUPERSEDED BY 737-53-1232 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-53-1232 TABLE 2	AIRPLANES WITH THE PERMANENT REPAIR INSTALLED. (SUPERSEDED BY 737-53-1232 R1), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
		MOS	- (s)				
SB 737-53-1232 TABLE 3	AIRPLANES WITH THE TIME-LIMITED REPAIR INSTALLED. INTERNAL/EXTERNAL DETAILED INSPECTION OF A TIME-LIMITED REPAIR FOR CRACKS AND LOOSE OR MISSING FASTENERS AS GIVEN IN "PART IV - TIME-LIMITED REPAIR"., SERVICE BULLETIN						NOT APPLICABLE
02-APR-2007		MOS					
		AFL	2500 (s)				
SB 737-53-1233	INSPECTION AND REPLACEMENT OF KEEL BEAM LOWER CHORD FORWARD SPLICE AT STATION 535, SERVICE BULLETIN						
		DAYS	30 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1233 R1	INSPECTION AND REPLACEMENT OF KEEL BEAM LOWER CHORD FORWARD SPLICE AT STATION 535, SERVICE BULLETIN						COMPLIED WITH - REPLACEMENT
		MOS	18 (s)	25-JUL-2002			
28-FEB-2002				1057:48			
		AFL		271			
SB 737-53-1236	AIRSTAIR DOORSTOP INTERCOSTAL - INSPECTION AND FASTENER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JUL-2002							
		AFL	24000 (s)				
SB 737-53-1236 R1	FUSELAGE - AIRSTAIR DOORSTOP INTERCOSTAL - INSPECTION AND FASTENER REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS		29-AUG-2011			
10-NOV-2005			- (s)	3533:32			
		AFL		863			
SB 737-53-1237	FASTENER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-DEC-2003			-				
SB 737-53-1237 R1	FUSELAGE - WING TO BODY FAIRING - WHEEL WELL - BONDED PANEL (BOW-TIE PANEL) - FASTENER REPLACEMENT, SERVICE BULLETIN						
		MOS					
07-DEC-2006			-				
SB 737-53-1239	KEEL CHORD SPLICE WASHERS, BOLTS AND NUTS REPLACEMENT, SERVICE BULLETIN						
		MOS					
22-AUG-2002			-				
SB 737-53-1239 R1	KEEL CHORD SPLICE WASHERS, BOLTS, AND NUTS REPLACEMENT, SERVICE BULLETIN						
		MOS	6 (s)				
14-AUG-2003							
SB 737-53-1239 R2	FUSELAGE - KEEL BEAM LOWER CHORDS - FORWARD AND AFT SPLICES AT STATIONS 540 AND 727 - KEEL CHORD SPLICE WASHERS, BOLTS, AND NUTS REPLACEMENT, SERVICE BULLETIN						
		MOS	6 (s)				
28-APR-2005							
SB 737-53-1239(A)	INSPECT KEEL CHORD SPLICE WASHERS, BOLTS AND NUTS REPLACEMENT, SERVICE BULLETIN						
		MOS	6 (s)				
22-AUG-2002							
SB 737-53-1239(E)	REPLACE KEEL CHORD SPLICE WASHERS, BOLTS AND NUTS REPLACEMENT, SERVICE BULLETIN						
		MOS	6 (s)				
22-AUG-2002							

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	737-53-1243	AUTOMATIC OVERWING EXIT DOUBLERS (BEARSTRAPS) INSPECTION INTERVAL CHANGE, SERVICE BULLETIN					RECOMMENDED	
	26-SEP-2002		MOS					
			AFL	75000 (s)				
SB	737-53-1244	PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN						
			MOS	-				
SB	737-53-1244 R1	PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN						
			MOS	-				
SB	737-53-1244 R1 (B)2	REPLACE PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND FASTENERS						
			MOS					
			AFL	10000 (s)				
SB	737-53-1244 R2	PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN						
	15-MAR-2007		MOS	12 (s)				
SB	737-53-1244 R2 (B)1	INSPECT PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND FASTNERS						
	15-MAR-2007		MOS					
			AFL	3000 (s)				
SB	737-53-1244 R2 (B)2	REPLACE PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND FASTNERS						
	15-MAR-2007		MOS					
			AFL	10000 (s)				
SB	737-53-1244 R4	FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE (SUPERSEDED BY SB 737-53-1244 R5), SERVICE BULLETIN					SUPERSEDED	
			MOS	-				
SB	737-53-1244 R5	FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN						
	27-JUL-2011		MOS	-				
SB 1.1	737-53-1244 R5 TABLE	INSTALL FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN NEW PIVOT LINK - NO CHANGES TO PIVOT LINK STRUCTURE AND PASSENGER SEATS HAVE NOT BEEN MOVED AFTER AIRPLANE DELIVERY					RECOMMENDED	
	17-APR-2003		MOS	12 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1244 R5 TABLE 1.2	ACCOMPLISH FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN MOVE THE SEATS - NO CHANGES TO PIVOT LINK STRUCTURE AND PASSENGER SEATS HAVE NOT BEEN MOVED AFTER AIRPLANE DELIVERY					RECOMMENDED	
17-APR-2003		MOS	12 (s)				
SB 737-53-1244 R5 TABLE 1.3	INSTALL FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND CENTERLINE FASTNERS IN THE SEAT TRACK					RECOMMENDED	
17-APR-2003		MOS	12 (s)				
SB 737-53-1244 R5 TABLE 1.3.1	INSPECT FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND FASTENERS					RECOMMENDED	
		MOS					
		AFL	3000 (s)				
SB 737-53-1244 R5 TABLE 1.3.2	REPLACE FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN BLIND FASTENERS WITH SOLID FASTENERS					RECOMMENDED	
		MOS					
		AFL	10000 (s)				
SB 737-53-1244 R5 TABLE 1.4	INSTALL FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN SOLID CENTERLINE FASTNERS IN THE SEAT TRACK					RECOMMENDED	
17-APR-2003		MOS	12 (s)				
SB 737-53-1244 R5 TABLE 1.5	INSTALL FUSELAGE - PASSENGER CABIN FLOORS - STATION 520 TO 540 - PIVOT LINK ASSEMBLY REPAIR/REPLACE, SERVICE BULLETIN NEW PIVOT LINK					RECOMMENDED	
27-JUL-2011		MOS	60 (s)				
SB 737-53-1245	HIGH PRESSURE DOOR AND DOUBLER-REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
05-AUG-2004		MOS	-				
SB 737-53-1249	FUSELAGE - FRAMES AND BULKHEADS - BODY STATION 1016 AFT PRESSURE BULKHEAD - VERTICAL FIN ATTACHMENT FITTINGS - BOLT HOLE INSPECTION AND REPAIR, SERVICE BULLETIN						
16-NOV-2006		MOS					
		AFL	36000 (s)				
SB 737-53-1251	AFT PRESSURE BULKHEAD APEX INSPECTION, SERVICE BULLETIN						COMPLIED WITH
03-JUN-2004		MOS			22-AUG-2008 3260:48		
		AFL	4000 (s)		782		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1252	FUSELAGE - STABILIZER CENTER SECTION FRONT SPAR - SLIDING SEAL AND TRACK MODIFICATION, SERVICE BULLETIN						
		MOS					
13-OCT-2005			-				
SB 737-53-1252 R1	FUSELAGE - STABILIZER CENTER SECTION FRONT SPAR - SLIDING SEAL AND TRACK MODIFICATION., SERVICE BULLETIN						
		MOS					
15-FEB-2007			-				
SB 737-53-1256	CHEMICAL MILL PITTING AT S-4 LAP SPLICE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-SEP-2003			-				
SB 737-53-1264	FUSELAGE - FILLET FAIRINGS - AFT WING-TO-BODY FAIRING - INBOARD FLAP PRIMARY TORQUE TUBE INSPECTION/REPAIR AND AFT WING-TO-BODY FAIRING MODIFICATION, SERVICE BULLETIN						
		MOS					
04-MAY-2006			-				
SB 737-53-1264 R1	FUSELAGE - FILLET FAIRINGS - AFT WING-TO-BODY FAIRING - INBOARD FLAP PRIMARY TORQUE TUBE INSPECTION/REPAIR AND AFT WING-TO-BODY FAIRING MODIFICATION, SERVICE BULLETIN						
		MOS					
24-JAN-2008			-				
SB 737-53-1276	FUSELAGE - FORWARD AND AFT CARGO COMPARTMENT - CORROSION PREVENTION MODIFICATION (SUPERSEDED BY SB 737-53-1276 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-53-1276 R1	FUSELAGE - FORWARD AND AFT CARGO COMPARTMENT - CORROSION PREVENTION MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-AUG-2014			- (s)				
SB 737-53-1277	FUSELAGE - STRUCTURE ATTACHMENT FITTINGS - NOSE WHEEL WELL RETRACT ACTUATOR SUPPORT FITTING INSPECTION AND MODIFICATION (SUPERSEDED BY 737-53-1277 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
14-NOV-2007			-				
SB 737-53-1277 R1	FUSELAGE - STRUCTURE ATTACHMENT FITTINGS - NOSE WHEEL WELL RETRACT ACTUATOR SUPPORT FITTING INSPECTION AND MODIFICATION, SERVICE BULLETIN						
		MOS					
14-MAY-2010			-				
SB 737-53-1280	FUSELAGE - FILLET FAIRINGS - AFT OUTBOARD WING TO BODY FAIRING MODIFICATION, SERVICE BULLETIN						
		MOS					
22-MAY-2008			-				

© Camp Systems

EFTA00618406

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1280 OPTION 1	INSTALL FUSELAGE - FILLET FAIRINGS - AFT OUTBOARD WING TO BODY FAIRING MODIFICATION, SERVICE BULLETIN MODIFICATION AS GIVEN IN PARAGRAPH 3.B., WORK INSTRUCTIONS						
		MOS	24 (s)				
22-MAY-2008							
SB (A) 737-53-1280 OPTION 2	INSPECT FUSELAGE - FILLET FAIRINGS - AFT OUTBOARD WING TO BODY FAIRING MODIFICATION, SERVICE BULLETIN AS GIVEN IN PARAGRAPH 3.B., WORK INSTRUCTIONS						
		MOS	24 (s)				
22-MAY-2008							
SB (B) 737-53-1280 OPTION 2	INSTALL FUSELAGE - FILLET FAIRINGS - AFT OUTBOARD WING TO BODY FAIRING MODIFICATION, SERVICE BULLETIN MODIFICATION AS GIVEN IN PARAGRAPH 3.B., WORK INSTRUCTIONS						
		MOS	72 (s)				
22-MAY-2008							
SB 737-53-1282	FUSELAGE - WHEEL WELL - NOSE WHEEL UPPER DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN						
		MOS					
14-NOV-2007			-				
SB 737-53-1282 R1	FUSELAGE - WHEEL WELL - NOSE WHEEL UPPER DRAG BRACE AND TRUNNION BUSHING REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
14-MAR-2008			-		3260:48		
		AFL			782		
SB 737-53-1285	FUSELAGE - PASSENGER CABIN FLOORS - SECTIONS 41 AND 47 - ADDITION OF GEL TAPE TO PREVENT CORROSION OF PASSENGER CABIN FLOOR PANEL SUPPORT STRUCTURE (SUPERSEDED BY SB 737-53-1285 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-53-1285 R1	FUSELAGE - PASSENGER CABIN FLOORS - SECTIONS 41 AND 47 - ADDITION OF GEL TAPE TO PREVENT CORROSION OF PASSENGER CABIN FLOOR PANEL SUPPORT STRUCTURE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-JUL-2014			-				
SB 737-53-1294	FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-53-1294 R1	FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN					RECOMMENDED	
		MOS			(EFF)		
12-JUN-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 1.1 737-53-1294 R1 TABLE	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN AND A HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION OF THE SKIN FOR CRACKS IN THE AREA AROUND THE EIGHT FASTENERS SECURING THE STA 540 BULKHEAD CHORDS BETWEEN STRINGER S-22 AND S-23 (AIRPLANES WITH LESS THAN 27,500 TOTAL FLIGHT CYCLES AS OF THE ORIGINAL ISSUE DATE OF THIS SERVICE BULLETIN)	MOS	-			
SB 1.2 737-53-1294 R1 TABLE	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN AND A HFEC INSPECTION OF THE SKIN FOR CRACKS IN THE AREA AROUND THE EIGHT FASTENERS SECURING THE STA 540 BULKHEAD CHORDS BETWEEN STRINGER S-22 AND S-23 (AIRPLANES WITH 27,500 OR MORE TOTAL FLIGHT CYCLES AS OF THE ORIGINAL ISSUE DATE OF THIS SERVICE BULLETIN)	MOS	-			
SB 1.3 737-53-1294 R1 TABLE	REPAIR FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN THE CRACKING ON LEFT SIDE (AND) DO THE PREVENTIVE MODIFICATION ON THE RIGHT SIDE (IF ANY CRACK IS FOUND IN THE SKIN ON THE LEFT SIDE OF THE AIRPLANE AND NO CRACK IS FOUND ON THE RIGHT SIDE OF THE AIRPLANE)	MOS	-			
SB 1.4 737-53-1294 R1 TABLE	REPAIR FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN THE CRACKING ON RIGHT SIDE (AND) DO THE PREVENTIVE MODIFICATION ON THE LEFT SIDE (IF ANY CRACK IS FOUND IN THE SKIN ON THE RIGHT SIDE OF THE AIRPLANE AND NO CRACK IS FOUND ON THE LEFT SIDE OF THE AIRPLANE)	MOS	-			
SB 1.5 737-53-1294 R1 TABLE	REPAIR FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN THE CRACKS (IF ANY CRACK IS FOUND IN THE SKIN ON BOTH SIDES OF THE AIRPLANE)	MOS	-			
SB 2.1.1 737-53-1294 R1 TABLE	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN OF THE SKIN SURROUNDING THE FILLER UNDER THE DRAG LINK ASSEMBLY FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE)	MOS	-			
SB 2.1.2 737-53-1294 R1 TABLE	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN EXTERNAL LOW FREQUENCY EDDY CURRENT (LFEC) INSPECTION OF THE SKIN AND DOUBLER AND AN EXTERNAL HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION OF THE TRIPLER FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE)	MOS	-			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1294 R1 TABLE 2.1.3	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN INTERNAL HFEC INSPECTION OF THE SKIN FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.1.4	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN INTERNAL HFEC INSPECTION OF THE SPLICE PLATE AND STA 540 BULKHEAD OUTER CHORD FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.2.1	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN OF THE SKIN SURROUNDING THE FILLER UNDER THE DRAG LINK ASSEMBLY FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.2.2	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN EXTERNAL LFEC INSPECTION OF THE SKIN AND DOUBLER AND AN EXTERNAL HFEC INSPECTION OF THE TRIPLER FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.2.3	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN INTERNAL HFEC INSPECTION OF THE SKIN FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.2.4	ACCOMPLISH FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN INTERNAL HFEC INSPECTION OF THE SPLICE PLATE AND STA 540 BULKHEAD OUTER CHORD FOR CRACKING (ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE)	MOS	-				
SB 737-53-1294 R1 TABLE 2.3	CONTACT FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR, SERVICE BULLETIN BOEING FOR INSTRUCTIONS AND DO THE WORK (ANY CRACK IS FOUND)	MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1294 TABLE 1.1	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN AND A HFEC INSPECTION OF THE SKIN FOR CRACKS IN THE AREA AROUND THE EIGHT FASTENERS SECURING THE STA 540 BULKHEAD CHORDS BETWEEN STRINGER S-22 AND S-23 FOR AIRPLANES WITH LESS THAN 27,500 TOTAL FLIGHT CYCLES AS OF THE ORIGINAL ISSUE DATE OF THIS SERVICE BULLETIN					RECOMMENDED	
		MOS					
					31-MAR-2011		
		AFL	2000 (s)				
SB 737-53-1294 TABLE 1.2	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN AND A HFEC INSPECTION OF THE SKIN FOR CRACKS IN THE AREA AROUND THE EIGHT FASTENERS SECURING THE STA 540 BULKHEAD CHORDS BETWEEN STRINGER S-22 AND S-23 FOR AIRPLANES WITH 27,500 OR MORE TOTAL FLIGHT CYCLES AS OF THE ORIGINAL ISSUE DATE OF THIS SERVICE BULLETIN.					RECOMMENDED	
		MOS					
					31-MAR-2011		
		AFL	750 (s)				
SB 737-53-1294 TABLE 2.1.1	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN OF THE SKIN SURROUNDING THE FILLER UNDER THE DRAG LINK ASSEMBLY FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	2500 (s)				
SB 737-53-1294 TABLE 2.1.2	HFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN EXTERNAL INSPECTION OF THE SKIN AND DOUBLER AND AN EXTERNAL HFEC INSPECTION OF THE TRIPLER FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53-1294 TABLE 2.1.3	HFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN INTERNAL INSPECTION OF THE SKIN FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53-1294 TABLE 2.1.4	HFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN INTERNAL INSPECTION OF THE SPLICE PLATE AND STA 540 BULKHEAD OUTER CHORD FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE LEFT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1294 TABLE 2.2.1	DETAILED INSPECTION FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN OF THE SKIN SURROUNDING THE FILLER UNDER THE DRAG LINK ASSEMBLY FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	2500 (s)				
SB 737-53-1294 TABLE 2.2.2	LFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN EXTERNAL INSPECTION OF THE SKIN AND DOUBLER AND AN EXTERNAL HFEC INSPECTION OF THE TRIPLER FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53-1294 TABLE 2.2.3	HFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN INTERNAL INSPECTION OF THE SKIN FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53-1294 TABLE 2.2.4	HFEC FUSELAGE - SKIN - LOWER BULKHEAD CHORDS AT BODY STATION 540 - SKIN INSPECTION, CHORD SPLICE INSTALLATION AND SKIN REPAIR (SUPERSEDED BY SB 737-53-1294 R1), SERVICE BULLETIN INTERNAL INSPECTION OF THE SPLICE PLATE AND STA 540 BULKHEAD OUTER CHORD FOR CRACKING FOR ALL AIRPLANES THAT HAVE DONE THE SKIN REPAIR ON THE RIGHT SIDE OF THE AIRPLANE					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53-1295 R1	FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT (SUPERSEDED BY SB 737-53-1295 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-53-1295 R2	FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JUN-2013			-				
SB 737-53-1295 R2 TABLE 1.1.1	EXTERNAL - DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN OF THE CROWN SKIN FOR CORROSION (GROUP 1, CONFIGURATION 6; GROUP 2, CONFIGURATION 4) (ALL AIRPLANES)						
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1295 R2 TABLE 1.1.2	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN FOR CORROSION AND INSTALL NEW FASTENERS (GROUP 1, CONFIGURATION 6; GROUP 2, CONFIGURATION 4) (ALL AIRPLANES)	MOS	- (s)				
SB 737-53-1295 R2 TABLE 1.2	CONTACT FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED (IF CORROSION IS FOUND)	MOS	-				
SB 737-53-1295 R2 TABLE 2.1	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN FOR CORROSION AND INSTALL NEW FASTENERS (ALL AIRPLANES)	MOS	- (s)				
SB 737-53-1295 R2 TABLE 2.2	CONTACT FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED (IF CORROSION IS FOUND)	MOS	-				
SB 737-53-1296	FUSELAGE - PASSENGER CABIN FLOORS - STATION 727B SPLICE STRAP INSTALLATION, SERVICE BULLETIN	MOS	-		11-JAN-2011		
SB 737-53-1296 TABLE 1.1	REPLACE FUSELAGE - PASSENGER CABIN FLOORS - STATION 727B SPLICE STRAP INSTALLATION, SERVICE BULLETIN SEAT TRACK BOLTS FOR ALL AIRPLANES	MOS	24 (s)		11-JAN-2011	RECOMMENDED	
SB 737-53-1296 TABLE 1.2	DETAILED INSPECTION FUSELAGE - PASSENGER CABIN FLOORS - STATION 727B SPLICE STRAP INSTALLATION, SERVICE BULLETIN AND HFEC INSPECTION OF SPLICE STRAP AND FORWARD SEAT TRACK FOR ALL AIRPLANES	MOS	24 (s)		11-JAN-2011	RECOMMENDED	
SB 737-53-1297	FUSELAGE - EQUIPMENT ATTACHMENT FITTINGS - AFT CARGO WASTE TANK ENCLOSURE - STANCHION MODIFICATION, SERVICE BULLETIN	MOS	-		03-SEP-2010	RECOMMENDED	
SB 737-53-1298	FUSELAGE - SKIN - DORSAL FIN SEAL RETAINER AND FUSELAGE SKIN STATION 847 TO 1007 - INSPECTION, SERVICE BULLETIN	MOS	-		27-AUG-2010		

© Camp Systems

EFTA00618412

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1298 TABLE 1.1/2	INSPECTION FUSELAGE - SKIN - DORSAL FIN SEAL RETAINER AND FUSELAGE SKIN STATION 847 TO 1007 - INSPECTION, SERVICE BULLETIN OF THE DORSAL FIN LOWER SEAL RETAINERS FOR CONTACT WITH THE FUSELAGE SKIN BETWEEN STA 847 AND STA 1007 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 1 FOR ALL AIRPLANES					RECOMMENDED	
		MOS	24 (s)				
27-AUG-2010							
		AFL	4000				
SB 737-53-1298 TABLE 1.6	MODIFY FUSELAGE - SKIN - DORSAL FIN SEAL RETAINER AND FUSELAGE SKIN STATION 847 TO 1007 - INSPECTION, SERVICE BULLETIN THE LOWER AND VERTICAL SEALS IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5 FOR AIRPLANES THAT HAVE NOT MODIFIED THE LOWER AND VERTICAL SEALS OR, REPLACED THE LOWER SEAL IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4.					RECOMMENDED	
		MOS	24 (s)				
27-AUG-2010							
		AFL	4000				
SB 737-53-1303	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION (SUPERSEDED BY SB 737-53-1303 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-53-1303 R1	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-MAY-2014			-				
SB 737-53-1303 R1 TBL 1.1	HIGH FREQUENCY EDDY CURRENT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN (HFEC) INSPECTION OF THE AFFECTED NUMBER 3 WINDOW FRAME FASTENER HOLES FOR CRACKS, COLD WORK AND INSTALL FREEZE PLUGS IN AFFECTED NUMBER 3 WINDOW FRAME HOLES						
		MOS					
			-				
		AFL					
SB 737-53-1303 R1 TBL 1.2	INSTALL FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN TEMPORARY REPAIR STRAP OR INSTALL THE NUMBER 3 WINDOW FRAME PERMANENT REPAIR (ANY CRACK INDICATION FOUND)					RECOMMENDED	
		MOS					
06-MAY-2014			BF/F				
SB 737-53-1303 R1 TBL 1.3	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN THE NUMBER 3 WINDOW FRAME OR INSTALL THE NUMBER 3 WINDOW FRAME PERMANENT REPAIR (IF ANY CRACK FOUND BEYOND THE TEMPORARY REPAIR STRAP INSTALLATION LIMITS)					RECOMMENDED	
		MOS					
06-MAY-2014			BF/F				

© Camp Systems

EFTA00618413

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1303 R1 TBL 1.4.1	EXTERNAL - DETAILED INSPECTION FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN OF THE TEMPORARY REPAIR STRAP FOR CORROSION AND ANY OTHER NICKS, GAPS, LOOSE FASTENERS OR MISSING SEALANT (IF TEMPORARY REPAIR STRAP INSTALLED)	MOS	- (s)				
SB 737-53-1303 R1 TBL 1.4.2	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN THE NUMBER 3 WINDOW FRAME (IF TEMPORARY REPAIR STRAP INSTALLED)	MOS	- (s)				
SB 737-53-1303 R1 TBL 1.5.1	EXTERNAL - DETAILED INSPECTION FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN OF THE TEMPORARY REPAIR STRAP FOR CORROSION AND ANY OTHER NICKS, GAPS, LOOSE FASTENERS OR MISSING SEALANT (IF TEMPORARY REPAIR STRAP OPTION 2 WITH STRAIGHT LINE FASTENER PATTERN INSTALLED)	MOS	- (s)				
SB 737-53-1303 R1 TBL 1.5.2	INSTALL FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN THE NUMBER 3 WINOW FRAME PERMANENT REPAIR OR REPLACE THE NUMBER 3 WINDOW FRAME (IF TEMPORARY REPAIR STRAP OPTION 2 WITH STRAIGHT LINE FASTENER PATTERN INSTALLED)	MOS	- (s)				
SB 737-53-1303 R1 TBL 1.6	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION, SERVICE BULLETIN THE NUMBER 3 WINDOW FRAME OR INSTALL THE NUMBER 3 WINDOW FRAME PERMANENT REPAIR (IF ANY CRACK FOUND AROUND THE NUMBER 3 WINDOW FRAME REPAIR FASTENERS COMMON TO THE TEMPORARY REPAIR STRAP)	MOS	BF/F		06-MAY-2014	RECOMMENDED	
SB 737-53-1303 TABLE 1.1	HFEC FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION (SUPERSEDED BY SB 737-53-1303 R1), SERVICE BULLETIN INSPECTION OF THE AFFECTED NUMBER 3 WINDOW FRAME FASTENER HOLES FOR CRACKS, COLD WORK AND INSTALL FREEZE PLUGS IN AFFECTED NUMBER 3 WINDOW FRAME HOLES FOR ALL AIRPLANES	MOS	- (s)			SUPERSEDED	
SB 737-53-1303 TABLE 1.4.1	HFEC FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION (SUPERSEDED BY SB 737-53-1303 R1), SERVICE BULLETIN - INTERNAL INSPECTION OF THE NUMBER 3 WINDOW FRAME AROUND THE REPAIR FASTENERS COMMON TO THE TEMPORARY REPAIR STRAP FOR CRACKS AND DO A GENERAL VISUAL INSPECTION OF THE TEMPORARY REPAIR STRAP FOR TEMPORARY REPAIR STRAP INSTALLED AIRPLANES	MOS	- (s)			SUPERSEDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1303 TABLE 1.4.2	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - INSPECTION AND FREEZE PLUG INSTALLATION (SUPERSEDED BY SB 737-53-1303 R1), SERVICE BULLETIN THE NUMBER 3 WINDOW FRAME					SUPERSEDED	
		MOS	- (s)				
SB 737-53-1307	FUSELAGE - FILLET FAIRINGS - AFT WING TO BODY FAIRING - PANEL 194E AND AFT CENTER WHEEL WELL PANEL 193D - INSPECTION AND REWORK, SERVICE BULLETIN					RECOMMENDED	
12-JAN-2012		MOS	-				
SB 737-53-1307 TABLE 1.1	PERFORM FUSELAGE - FILLET FAIRINGS - AFT WING TO BODY FAIRING - PANEL 194E AND AFT CENTER WHEEL WELL PANEL 193D - INSPECTION AND REWORK, SERVICE BULLETIN A GENERAL VISUAL INSPECTION OF THE LOWER AFT WING TO BODY FAIRING PANEL AND SUPPORT STRUCTURE					RECOMMENDED	
12-JAN-2012		MOS	24 (s)				
SB 737-53-1307 TABLE 1.4	PERFORM FUSELAGE - FILLET FAIRINGS - AFT WING TO BODY FAIRING - PANEL 194E AND AFT CENTER WHEEL WELL PANEL 193D - INSPECTION AND REWORK, SERVICE BULLETIN THE PANEL AND SUPPORT STRUCTURE REWORK					RECOMMENDED	
12-JAN-2012		MOS	72 (s)				
SB 737-53-1310	FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN					RECOMMENDED	
20-OCT-2011		MOS	-				
SB 737-53-1310 TABLE 1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL DETAILED INSPECTION AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEPS AT SPECIFIED LOCATIONS OPTION 1 OR OPTION 2 FOR ALL AIRPLANES					RECOMMENDED	
20-OCT-2011		MOS					
		AFL	1500 (s)				
SB 737-53-1310 TABLE 2.1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN INSPECTION OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION DOUBLER OPTION 1 OR OPTION 2 FOR ALL EXTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	
		MOS					
		AFL	50000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1310 TABLE 2.2	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL INSPECTION OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION FILLER OPTION 1 OR OPTION 2 FOR ALL INTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 3	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL INSPECTION OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION FILLER OPTION 1 OR OPTION 2 FOR ALL INTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 4	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL INSPECTION OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION FILLER OPTION 1 OR OPTION 2 FOR ALL INTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 5.1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN BEFORE 32,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 5.2	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 31,999 TOTAL FLIGHT CYCLES BUT BEFORE 43,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	43000 (s)				
SB 737-53-1310 TABLE 5.3	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NDI - FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 42,999 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	5500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1310 TABLE 6.1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN BEFORE 32,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 6.2	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 31,999 TOTAL FLIGHT CYCLES BUT BEFORE 43,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	5500 (s)				
SB 737-53-1310 TABLE 6.3	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN DO AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 42,999 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	5500 (s)				
SB 737-53-1310 TABLE 7.1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN BEFORE 32,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53-1310 TABLE 7.2	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 31,999 TOTAL FLIGHT CYCLES BUT BEFORE 43,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	5500 (s)				
SB 737-53-1310 TABLE 7.3	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION , SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 42,999 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS					
		AFL	5500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1311	FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN						NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			-	3714:04			
		AFL		900			
SB 737-53-1311 TABLE 1	EXTERNAL - DETAILED INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEPS AT SPECIFIED LOCATIONS FOR ALL AIRPLANES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			- (s)	3714:04			
		AFL		900			
SB 737-53-1311 TABLE 2	EXTERNAL - DETAILED INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) OF THE FUSELAGE SKIN FOR CRACKING AT THE CHEM-MILL STEPS COMMON TO SHEAR WRINKLE AREAS FOR ALL AIRPLANES, GROUP 2, 5-6					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			- (s)	3714:04			
		AFL		900			
SB 737-53-1311 TABLE 3.1	NON DESTRUCTIVE FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN INSPECTION OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION DOUBLER FOR ALL EXTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
			- (s)	3714:04			
		AFL		900			
SB 737-53-1311 TABLE 3.2	EXTERNAL INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION FILLER FOR ALL INTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
			- (s)	3714:04			
		AFL		900			
SB 737-53-1311 TABLE 4.1	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN BEFORE 32,000 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
				3714:04			
		AFL	5500 (s)	900			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1311 TABLE 4.2	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 31,999 TOTAL FLIGHT CYCLES BUT BEFORE 43,000 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
				3714:04			
		AFL	5500 (s)	900			
SB 737-53-1311 TABLE 4.3	PERFORM FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 42,999 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
				3714:04			
		AFL	5500 (s)	900			
SB 737-53-1312	FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN						NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			-	3714:04			
		AFL		900			
SB 737-53-1312 R1	FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
14-MAR-2012			-	3714:04			
		AFL		900			
SB 737-53-1312 TABLE 1	EXTERNAL - DETAILED INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEPS AT SPECIFIED LOCATIONS AND OPTION 1 (OR) OPTION 2 FOR ALL AIRPLANES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			- (s)	3714:04			
		AFL		900			
SB 737-53-1312 TABLE 2	EXTERNAL - DETAILED INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN AND AN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) OF THE FUSELAGE SKIN FOR CRACKING AT THE CHEM-MILL STEPS AT SPECIFIED LOCATIONS AND OPTION 1 (OR) OPTION 2 FOR ALL AIRPLANES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013			
21-OCT-2011			- (s)	3714:04			
		AFL		900			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1312 TABLE 3	EXTERNAL INSPECTION FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN OF THE FUSELAGE SKIN FOR CRACKING AT THE OUTER ROW OF FASTENERS COMMON TO THE MODIFICATION FILLER AND OPTION 1 (OR) OPTION 2 FOR ALL INTERNAL MODIFICATIONS INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS	- (s)	28-MAY-2013 3714:04			
		AFL		900			
SB 737-53-1312 TABLE 4.1	ACCOMPLISH FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN EXTERNAL NON DESTRUCTIVE INSPECTION (NDI) FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN BEFORE 32,000 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013 3714:04			
		AFL	5500 (s)	900			
SB 737-53-1312 TABLE 4.2	ACCOMPLISH FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 31,999 TOTAL FLIGHT CYCLES BUT BEFORE 43,000 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013 3714:04			
		AFL	5500 (s)	900			
SB 737-53-1312 TABLE 4.3	ACCOMPLISH FUSELAGE - SKIN - CHEM-MILL STEPS IN CROWN SKINS AT SPECIFIED LOCATIONS - INSPECTION AND MODIFICATION, SERVICE BULLETIN EXTERNAL NDI FOR CRACKING IN THE FUSELAGE SKIN AT THE CHEM-MILL STEP AT THE SPECIFIED LOCATIONS FOR ALL INTERNAL MODIFICATIONS THAT WERE INSTALLED IN ACCORDANCE WITH THIS SERVICE BULLETIN AFTER 42,999 TOTAL FLIGHT CYCLES					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
		MOS		28-MAY-2013 3714:04			
		AFL	5500 (s)	900			
SB 737-53-1316	FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT (SUPERSEDED BY SB 737-53-1316 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-53-1316 R1	FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN					RECOMMENDED	
03-JUL-2013		MOS	-				
SB 1.1.1 737-53-1316 R1 TABLE	EXTERNAL - DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN OF THE CROWN SKIN FOR CORROSION FOR ALL AIRPLANES (GROUP 1, CONFIGURATION 6)						
		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1316 R1 TABLE 1.1.2	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN FOR CORROSION AND INSTALL NEW FASTENERS FOR ALL AIRPLANES (GROUP 1, CONFIGURATION 6)	MOS	-				
SB 737-53-1316 R1 TABLE 1.2	CONTACT FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IF CORROSION IS FOUND (GROUP 1, CONFIGURATION 6)	MOS	-				
SB 737-53-1316 R1 TABLE 2.1	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN FOR CORROSION AND INSTALL NEW FASTENERS FOR ALL AIRPLANES (GROUP 1, CONFIGURATION 5)	MOS	-				
SB 737-53-1316 R1 TABLE 2.2	CONTACT FUSELAGE - FRAMES AND BULKHEADS - NUMBER 1 WINDOW FRAME AND WINDSHIELD ASSEMBLY REPLACEMENT AND HEAD UP DISPLAY REALIGNMENT, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IF CORROSION IS FOUND (GROUP 1, CONFIGURATION 5)	MOS	-				
SB 737-53-1326	FUSELAGE - CARGO COMPARTMENT SIDEWALL LININGS - INSPECTION AND REPAIR, SERVICE BULLETIN	MOS	-		26-OCT-2012	RECOMMENDED	
SB 737-53-1326 TABLE 1.1	INSPECTION FUSELAGE - CARGO COMPARTMENT SIDEWALL LININGS - INSPECTION AND REPAIR, SERVICE BULLETIN OF THE FORWARD AND AFT CARGO COMPARTMENTS SIDEWALL PANELS FOR ALL AIRPLANES	MOS	24 (s)		26-OCT-2012	RECOMMENDED	
SB 737-53-1326 TABLE 1.2	REMOVE FUSELAGE - CARGO COMPARTMENT SIDEWALL LININGS - INSPECTION AND REPAIR, SERVICE BULLETIN AND REPLACE ALUMINUM SIDEWALL LININGS	MOS	60 (s)		26-OCT-2012	RECOMMENDED	
SB 737-53-1330	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN	MOS	-		26-FEB-2013	RECOMMENDED	
SB 737-53-1330 R1	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN	MOS	-		10-JUN-2013	RECOMMENDED	

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1330 TABLE 1 (1.1.1)	DO FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN A HFEC INSPECTION OF THE CRACK IN THE NUMBER 1 WINDOW FRAME TO DETERMINE IF THE CRACK HAS GROWN BEYOND THE ALLOWABLE STOP DRILL REGION AND STOP DRILL THE CRACK IF WITHIN THE ALLOWABLE STOP DRILL REGION					RECOMMENDED	
		MOS	BF/F				
SB 737-53-1330 TABLE 1 (1.1.2)	DO FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN A HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION ABOVE AND BELOW THE CRACKED NUMBER 1 WINDOW FRAME AROUND THE FASTENERS THAT HOLD THE NUMBER 1 AND NUMBER 2 WINDOW FRAMES TOGETHER					RECOMMENDED	
		MOS	BF/F				
SB 737-53-1330 TABLE 1 (1.1.3)	DO FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN A DETAILED INSPECTION OF THE AREA TWO INCHES ABOVE AND BELOW THE CRACK					RECOMMENDED	
		MOS	BF/F				
SB 737-53-1330 TABLE 1 (1.1.4)	INSTALL FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN THE TEMPORARY REPAIR DOUBLER ON THE NUMBER 1 WINDOW FRAME					RECOMMENDED	
		MOS	BF/F				
SB 737-53-1330 TABLE 1 (1.2)	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING, FOR CRACK FOUND OUTSIDE OF THE UPPER AFT CORNER AREA OF THE NUMBER 1 WINDOW FRAME					RECOMMENDED	
		MOS	BF/F				
SB 737-53-1330 TABLE 1 (1.3.1)	DO FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN AN EXTERNAL DETAILED INSPECTION FOR CORROSION AND ANY OTHER NICKS, GAPS, LOOSE FASTENERS OR MISSING SEALANT FOR TEMPORARY REPAIR DOUBLER INSTALLED					RECOMMENDED	
		MOS	6 (s)				
SB 737-53-1330 TABLE 1 (1.3.2)	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN THE NUMBER 1 WINDOW FRAME FOR TEMPORARY REPAIR DOUBLER INSTALLED					RECOMMENDED	
		MOS	24 (s)				
		AFL	6000				
SB 737-53-1330 TABLE 1 (1.4)	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME CRACKING - TEMPORARY REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING FOR ANY CRACK FOUND AROUND THE NUMBER 1 WINDOW FRAME FASTENERS COMMON TO THE TEMPORARY REPAIR DOUBLER					RECOMMENDED	
		MOS	BF/F				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1334	FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-AUG-2014			- (s)				
SB 737-53-1334 TBL 1.1.1	DO FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN PART 2: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - HIGHER STRESS LOCATIONS (ALL AIRPLANES) (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	7500 (s)				
SB 737-53-1334 TBL 1.1.2	DO FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN PART 3: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - LOWER STRESS LOCATIONS (ALL AIRPLANES) (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	10000 (s)				
SB 737-53-1334 TBL 1.3	CONTACT FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR/ REPEAT PART 2: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - HIGHER STRESS LOCATIONS (IF CONDITION 2: ANY CRACK FOUND (DURING PART 2 MFEC INSPECTION OF HIGHER STRESS LOCATIONS)) (GROUP 1-5)					RECOMMENDED	
		MOS					
04-AUG-2014			BF/F (s)				
SB 737-53-1334 TBL 1.5	CONTACT FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR/ REPEAT PART 3: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - LOWER STRESS LOCATIONS (IF CONDITION 2: ANY CRACK FOUND (DURING PART 3 MFEC INSPECTION OF LOWER STRESS LOCATIONS)) (GROUP 1-5)					RECOMMENDED	
		MOS					
04-AUG-2014			BF/F (s)				
SB 737-53-1334 TBL 2.1.1	DO FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN PART 2: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - HIGHER STRESS LOCATIONS (ALL AIRPLANES) (GROUP 6)					RECOMMENDED	
		MOS					
		AFL	7500 (s)				
SB 737-53-1334 TBL 2.1.2	DO FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN PART 3: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - LOWER STRESS LOCATIONS (ALL AIRPLANES) (GROUP 6)					RECOMMENDED	
		MOS					
		AFL	20000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1334 TBL 2.3	CONTACT FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN THE BOEING COMPANY REPAIR INSTRUCTIONS AND DO THE REPAIR/REPEAT PART 2: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC)INSPECTION - HIGHER STRESS LOCATIONS (B)					RECOMMENDED	
		MOS					
04-AUG-2014			BF/F (s)				
SB 737-53-1334 TBL 2.5	CONTACT FUSELAGE - CROWN SKIN - CHEM MILL POCKET TROUGH INSPECTIONS, SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR/ REPEAT PART 3: CROWN SKIN PANEL ASSEMBLY - EXTERNAL MEDIUM FREQUENCY EDDY CURRENT (MFEC) INSPECTION - LOWER STRESS LOCATIONS (IF CONDITION 3: ANY CRACK FOUND (DURING PART 3 MFEC INSPECTION OF LOWER STRESS LOCATIONS)) (GROUP 6)					RECOMMENDED	
		MOS					
04-AUG-2014			BF/F (s)				
SB 737-53-1335	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
31-JUL-2013			-				
SB 737-53-1335 TABLE 1.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN NUMBER 1 WINDOW FRAME DETAILED AND HFEC INSPECTION FOR ANY CRACK INDICATION (FOR ALL AIRPLANES) (GROUP 1, CONFIGURATION 1-3)						
		MOS					
			-				
		AFL					
SB 737-53-1335 TABLE 1.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN NUMBER 1 WINDOW FRAME PREVENTIVE MODIFICATION DOUBLER INSTALLATION (IF NO CRACK INDICATION FOUND) (GROUP 1, CONFIGURATION 1-3)						
		MOS					
			-				
		AFL					
SB 737-53-1335 TABLE 1.3	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN NUMBER 1 WINDOW FRAME TEMPORARY REPAIR INSTALLATION OR REPLACEMENT (IF ANY CRACK INDICATION FOUND) (GROUP 1, CONFIGURATION 1-3)						
		MOS					
			-				
SB 737-53-1335 TABLE 2.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN POST PREVENTIVE MODIFICATION DOUBLER INSTALLATION SEALANT INSPECTION (FOR AIRPLANES WITH THE PREVENTIVE MODIFICATION DOUBLER INSTALLED) (GROUP 1, CONFIGURATION 1-3)						
		MOS					
			-				
		AFL					
SB 737-53-1335 TABLE 2.3	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN SEALANT APPLICATION (IF SEALANT CRACKS, EROSION, SPLITS, LOOSE BEADS OR MISSING SECTIONS FOUND) (GROUP 1, CONFIGURATION 1-3)						
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1335 TABLE 3.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN POST PREVENTIVE MODIFICATION DOUBLER INSTALLATION WINDOW FRAME DETAILED AND HFEC INSPECTION (FOR AIRPLANES WITH THE PREVENTIVE MODIFICATION DOUBLER INSTALLED) (GROUP 1, CONFIGURATION 1-3)						
		MOS	-				
		AFL					
SB 737-53-1335 TABLE 3.3	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - MODIFICATION, SERVICE BULLETIN BOEING (IF ANY CRACK INDICATION FOUND) (GROUP 1, CONFIGURATION 1-3)						
		MOS	-				
SB 737-53-1336	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	23-OCT-2013						
SB 737-53-1336 TABLE 1.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN PART 12: POST PERMANENT REPAIR INSTALLATION NUMBER 1 WINDOW FRAME AND PERMANENT REPAIR TRIPLER HFEC INSPECTION (AIRPLANES WITH THE PERMANENT REPAIR DOUBLER AND TRIPLER INSTALLED)						
		MOS	-				
		AFL					
SB 737-53-1336 TABLE 1.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN PART 12: POST PERMANENT REPAIR INSTALLATION NUMBER 1 WINDOW FRAME AND PERMANENT REPAIR TRIPLER HFEC INSPECTION (CONDITION 1: NO CRACK INDICATION FOUND)						
		MOS	-				
		AFL					
SB 737-53-1336 TABLE 1.3	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (CONDITION 2: ANY CRACK INDICATION FOUND)						
		MOS	-				
SB 737-53-1336 TABLE 2.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN PART 13: POST PERMANENT REPAIR INSTALLATION FUSELAGE SKIN LFEC INSPECTION (AIRPLANES WITH THE PERMANENT REPAIR DOUBLER AND TRIPLER INSTALLED)						
		MOS	-				
		AFL					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1336 TABLE 2.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN PART 13: POST PERMANENT REPAIR INSTALLATION FUSELAGE SKIN LFEC INSPECTION (CONDITION 1: NO CRACK INDICATION FOUND)	MOS	-				
		AFL					
SB 737-53-1336 TABLE 2.3	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 1 WINDOW FRAME - PERMANENT REPAIR, SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (CONDITION 2: ANY CRACK INDICATION FOUND)	MOS	-				
SB 737-53-1341	FUSELAGE - MISCELLANEOUS EXTERIOR SERVICE DOORS - EXTERNAL POWER RECEPTACLE DOOR - BONDING JUMPER INSPECTION AND REPLACEMENT (SUPERSEDED BY SB 737-53-1341 R1), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-53-1341 R1	FUSELAGE - MISCELLANEOUS EXTERIOR SERVICE DOORS - EXTERNAL POWER RECEPTACLE DOOR - BONDING JUMPER INSPECTION AND REPLACEMENT, SERVICE BULLETIN	MOS	-		11-APR-2014	RECOMMENDED	
SB 737-53-1345	FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN	MOS	-		05-NOV-2013	RECOMMENDED	
SB 737-53-1345 TABLE 1.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 1: NUMBER 3 WINDOW FRAME INSPECTION, COLD WORKING AND FREEZE PLUG INSTALLATION (AIRPLANES THAT COULD NOT BE REPAIRED WITH THE MAXIMUM FREEZE PLUG DIAMETER ALLOWED IN ACCORDANCE WITH BOEING SERVICE BULLETIN 737-53-1303)	MOS	-				
		AFL					
SB 737-53-1345 TABLE 1.2.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 2: NUMBER 3 WINDOW FRAME SEPARATION (CONDITION 1: CRACK IN SECOND LOWER CORNER FASTENER HOLE THAT CANNOT BE REMOVED WITH A 0.450 INCH DIAMETER FREEZE PLUG)	MOS	-				
SB 737-53-1345 TABLE 1.2.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 3: NUMBER 3 WINDOW FRAME CUTTING (CONDITION 1: CRACK IN SECOND LOWER CORNER FASTENER HOLE THAT CANNOT BE REMOVED WITH A 0.450 INCH DIAMETER FREEZE PLUG)	MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1345 TABLE 1.2.3	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 4: NUMBER 3 WINDOW FRAME PERMANENT REPAIR INSTALLATION (CONDITION 1: CRACK IN SECOND LOWER CORNER FASTENER HOLE THAT CANNOT BE REMOVED WITH A 0.450 INCH DIAMETER FREEZE PLUG)	MOS	-				
SB 737-53-1345 TABLE 1.2.4	REPLACE FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN THE NUMBER 3 WINDOW FRAME (CONDITION 1: CRACK IN SECOND LOWER CORNER FASTENER HOLE THAT CANNOT BE REMOVED WITH A 0.450 INCH DIAMETER FREEZE PLUG)	MOS	-				
SB 737-53-1345 TABLE 1.3	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 4: NUMBER 3 WINDOW FRAME PERMANENT REPAIR INSTALLATION (CONDITION 2: CRACK IN SECOND LOWER CORNER FASTENER HOLE THAT CAN BE REMOVED WITH A 0.450 INCH DIAMETER FREEZE PLUG)	MOS	-				
SB 737-53-1345 TABLE 2.1.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 5: POST PERMANENT REPAIR INSTALLATION PERMANENT REPAIR TRIPLER HFEC INSPECTION (AIRPLANES WITH THE PERMANENT REPAIR DOUBLER AND TRIPLER INSTALLED)	MOS	-				
		AFL					
SB 737-53-1345 TABLE 2.1.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 6: POST PERMANENT REPAIR INSTALLATION NUMBER 3 WINDOW FRAME HFEC INSPECTION (AIRPLANES WITH THE PERMANENT REPAIR DOUBLER AND TRIPLER INSTALLED)	MOS	-				
		AFL					
SB 737-53-1345 TABLE 2.2.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 5: POST PERMANENT REPAIR INSTALLATION PERMANENT REPAIR TRIPLER HFEC INSPECTION (CONDITION 1: NO CRACK INDICATION FOUND)	MOS	-				
		AFL					
SB 737-53-1345 TABLE 2.2.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 6: POST PERMANENT REPAIR INSTALLATION NUMBER 3 WINDOW FRAME HFEC INSPECTION (CONDITION 1: NO CRACK INDICATION FOUND)	MOS	-				
		AFL					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53-1345 TABLE 2.3	CONTACT FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (CONDITION 2: ANY CRACK INDICATION FOUND)	MOS	-				
SB 737-53-1345 TABLE 3.1	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 7: POST PERMANENT REPAIR INSTALLATION REPAIR DOUBLER LFEC INSPECTION (AIRPLANES WITH THE PERMANENT REPAIR DOUBLER AND TRIPLER INSTALLED)	MOS AFL	- -				
SB 737-53-1345 TABLE 3.2	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN PART 7: POST PERMANENT REPAIR INSTALLATION REPAIR DOUBLER LFEC INSPECTION (CONDITION 1: NO CRACK INDICATION FOUND)	MOS AFL	- -				
SB 737-53-1345 TABLE 3.3	ACCOMPLISH FUSELAGE - STRUCTURE AROUND OPENINGS - NUMBER 3 WINDOW FRAME - PERMANENT REPAIR , SERVICE BULLETIN THE BOEING COMPANY FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (CONDITION 2: ANY CRACK INDICATION FOUND)	MOS	-				
SB 737-53A1222 R1	POINT D SPLICE FITTING REPLACEMENT (SUPERSEDED BY 737-53A1222 R2), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-53A1222 R2	FUSELAGE - SECTION 41 CAB - POINT D SPLICE FITTING REPLACEMENT (SUPERSEDED BY 737-53A1222 R3), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-53A1222 R3	FUSELAGE - SECTION 41 CAB - POINT D SPLICE FITTING REPLACEMENT (SUPERSEDED BY 737-53A1222 R4), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-53A1222 R4	FUSELAGE - SECTION 41 CAB - POINT D SPLICE FITTING REPLACEMENT, SERVICE BULLETIN	MOS AFL	20-OCT-2005 13500 (s)			RECOMMENDED	
SB 737-53A1238	FUSELAGE - SECTION 48 - STRUCTURE - INSPECTION (SUPERSEDED BY SB 737-53A1238 R1), SERVICE BULLETIN	MOS	- (s)			SUPERSEDED	

© Camp Systems

EFTA00618428

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1238 R1	FUSELAGE - SECTION 48 - STRUCTURE - INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		DAYS	30 (s)				
10-OCT-2002							
SB 737-53A1242	SEALING AROUND VERTICAL FIN LUGS, SERVICE BULLETIN						
		MOS	18 (s)				
17-OCT-2002							
		AFL	2500				
SB 737-53A1242 R1	FUSELAGE - STRUCTURE ATTACHMENT FITTINGS - INADEQUATE SEALING AROUND VERTICAL FIN LUGS, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY
		MOS	18 (s)	13-OCT-2006			
28-APR-2005				2686:29			
		AFL	2500	644			
SB 737-53A1242 R2	FUSELAGE - STRUCTURE ATTACHMENT FITTINGS-INADEQUATE SEALING AROUND VERTICAL FIN LUGS, SERVICE BULLETIN						COMPLIED WITH - IAW THE AD
		MOS		22-AUG-2008			
23-APR-2007			- (s)	3260:48			
		AFL		782			
SB 737-53A1248	NDT INSPECTION OF WEB AT "Y" CHORD-ABOVE STR 15L AND 15R (STR 5L TO 7L AND STR 5R TO 9R), SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-SEP-2004			-				
SB 737-53A1248 E(A)1	INSPECT (NON-DESTRUCTIVE TEST) NDT INSPECTION OF WEB AT "Y" CHORD-ABOVE STR 15L AND 15R (STR 5L TO 7L AND STR 5R TO 9R), SERVICE BULLETIN (STR 5L TO 7L AND STR 5R TO 9R)					RECOMMENDED	
		MOS					
09-SEP-2004							
		AFL	25000 (s)				
SB 737-53A1248 E(A)2	INSPECT (NON-DESTRUCTIVE TEST) NDT INSPECTION OF WEB AT "Y" CHORD-ABOVE STR 15L AND 15R (STR 5L TO 7L AND STR 5R TO 9R), SERVICE BULLETIN (ABOVE STR 15L AND 15R EXCEPT 5L TO 7L AND 5R TO 9R)					RECOMMENDED	
		MOS					
09-SEP-2004							
		AFL	25000 (s)				
SB 737-53A1248 E(B)	INSPECT (NON-DESTRUCTIVE TEST) NDT INSPECTION OF WEB AT "Y" CHORD-ABOVE STR 15L AND 15R (STR 5L TO 7L AND STR 5R TO 9R), SERVICE BULLETIN "Y" CHORD BELOW S-15L/R					RECOMMENDED	
		MOS					
09-SEP-2004							
		AFL	66000 (s)				
SB 737-53A1248 R1	FUSELAGE - BODY STATION 1016 AFT PRESSURE BULKHEAD WEB - INSPECTION FOR WEB CRACKS AT THE Y-CHORD, SERVICE BULLETIN						
		MOS					
10-SEP-2007			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1248 R1 E (A) 1	INSPECTION FUSELAGE - BODY STATION 1016 AFT PRESSURE BULKHEAD WEB - INSPECTION FOR WEB CRACKS AT THE Y-CHORD, SERVICE BULLETIN - NDT - OF WEB AT "Y" CHORD STR 15L AND 15R (STR 5L TO 7L AND STR 5R TO 9R)						
10-SEP-2007		MOS					
		AFL	25000 (s)				
SB 737-53A1248 R1 E (A) 2	INSPECTION FUSELAGE - BODY STATION 1016 AFT PRESSURE BULKHEAD WEB - INSPECTION FOR WEB CRACKS AT THE Y-CHORD, SERVICE BULLETIN - NDT - OF WEB AT "Y" CHORD (ABOVE STR 15L AND 15R EXCEPT 5L TO 7L AND 5R TO 9R)						
10-SEP-2007		MOS					
		AFL	25000 (s)				
SB 737-53A1248 R1 E (B)	INSPECTION FUSELAGE - BODY STATION 1016 AFT PRESSURE BULKHEAD WEB - INSPECTION FOR WEB CRACKS AT THE Y-CHORD, SERVICE BULLETIN - NDT - OF WEB AT "Y" CHORD - BELOW S-15L/R						
10-SEP-2007		MOS					
		AFL	66000 (s)				
SB 737-53A1253	FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING (SUPERSEDED BY SB 737-53A1253 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - TABLE 1 I.A.W. AD 2007-25-03 / TABLE 2 & 3 ARE N/A TO A/C
		MOS			22-AUG-2008		
			-		3260:48		
		AFL			782		
SB 737-53A1253 R1	FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN						
		MOS			(EFF)		
13-MAY-2011			-				
SB 737-53A1253 R1 TABLE 1.1	GENERAL VISUAL INSPECTION FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN FOR OIL CAN CONDITIONS OR BULGES FOR ALL AIRPLANES					MANDATORY	
		MOS				RECURRING	
		AFL	15000		**15000**		
SB 737-53A1253 R1 TABLE 1.2	PERFORM FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN OPTION A: STEP 1 OF 2 OR STEP 2 OF 2 OR OPTION B					MANDATORY	
		MOS					
			BF/F (s)				
SB 737-53A1253 R1 TABLE 2.1	GENERAL VISUAL INSPECTION FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN TO IDENTIFY REPAIRS TO THE GORE WEB & VERIFY THAT THEY HAVE FOLLOW-ON INSPECTIONS (SRM SECTION 53-80-08-2R) FOR ALL AIRPLANES					MANDATORY	
		MOS					
		AFL	15000		**15000**		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1253 R1 TABLE 2.2	DETERMINE FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN FAA APPROVED FOLLOW-ON INSPECTION PROCEDURES, THRESHOLDS, AND REPEAT INTERVALS AND INCORPORATE INTO MAINTENANCE PROGRAM IF A REPAIR IS FOUND THAT DOES NOT HAVE FOLLOW-ON SUPPLEMENTAL INSPECTIONS					MANDATORY	
		MOS	12 (s)				
SB 737-53A1253 R1 TABLE 3	FAA FUSELAGE - GENERAL - STATION 1016 AFT PRESSURE BULKHEAD - INSPECTION FOR WEB OIL CANNING, SERVICE BULLETIN APPROVED REPAIR INSPECTION PROCEDURES					MANDATORY	
		MOS					
		AFL	36000 (s)				
SB 737-53A1253 TABLE 1	PERFORM A GENERAL VISUAL INSPECTION FOR OIL CAN CONDITIONS OR BULGES AS GIVEN IN ACCOMPLISHMENT INSTRUCTIONS, 3.B.2 OR 3.B.3, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008			
18-MAY-2007				3260:48			
		AFL	10000 (s)	782			
SB 737-53A1253 TABLE 2	GENERAL VISUAL INSPECTION TO IDENTIFY REPAIRS TO THE GORE WEB & VERIFY THAT THEY HAVE FOLLOW-ON INSPECTIONS (SRM SECTION 53-80-08-2R), SERVICE BULLETIN						NOT APPLICABLE
		MOS		22-AUG-2008			
18-MAY-2007			- (s)	3260:48			
		AFL		782			
SB 737-53A1253 TABLE 3	FAA APPROVED REPAIR INSPECTION PROCEDURES, SERVICE BULLETIN						NOT APPLICABLE
		MOS		22-AUG-2008			
18-MAY-2007				3260:48			
		AFL	24000 (s)	782			
SB 737-53A1289	INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
		AFL					
SB 737-53A1289 R1	INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-NOV-2009			-				
SB 737-53A1289 R1 TABLE (1.1)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.1. PART 1 -SKIN LAP JOINT - ZONE 1 INSPECTION (GROUP 1-5)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (1.10)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN , HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10.A. PART 10 - LRTS PROGRAM INSPECTION.IN ZONE 17 (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	40000 (s)				
SB 737-53A1289 R1 TABLE (1.11)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10.B. PART 10 -LRTS PROGRAM INSPECTION. IN ZONE 18 (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53A1289 R1 TABLE (1.12)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10.C. PART 10 -LRTS PROGRAM INSPECTION. IN ZONE 19 (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53A1289 R1 TABLE (1.14)	CONTACT INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN BOEING FOR ADDITIONAL INSPECTIONS OR REPAIR (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	75000 (s)				
SB 737-53A1289 R1 TABLE (1.2)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.2. PART 2 -SKIN LAP JOINT - ZONE 2 INSPECTION (GROUP 1-5)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (1.4)	PERFORM INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN INSPECTIONS AS NEEDED IF ANY SCRIBE LINE IS FOUND (GROUP 1-5)					RECOMMENDED	
		MOS					
			BF/F (s)				
SB 737-53A1289 R1 TABLE (1.7)	HFEC INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN AND UT INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.9. PART 9 - SCRIBE LINE INSPECTION. IN ZONE 1 (GROUP 1-5)					RECOMMENDED	
		MOS					
		AFL	40000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (1.8)	HFEC INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN INSPECTION AND UT INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.9. PART 9 - SCRIBE LINE IN ZONE 2 (GROUP 1-5) INSPECTION.					RECOMMENDED	
		MOS					
		AFL	50000 (s)				
SB 737-53A1289 R1 TABLE (10.1)	DETERMINE INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN THE THICKNESS OF THE PARENT SKIN IN THE AREA OF THE EXTERNAL APPROVED REPAIR BETWEEN STA 360 AND STA 1016 AND BELOW S-10L AND S-10R WHICH IS 20 INCHES OR LONGER IN THE FORE AND AFT DIRECTION WITH NO CIRCUMFERENTIAL LIMITATIONS					RECOMMENDED	
		MOS					
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (10.11)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM EXTERNAL APPROVED REPAIR REPEAT INSPECTION.(G) SCRIBE LINE IS FOUND COMMON TO EXTERNAL APPROVED REPAIR WITH PARENT SKIN THICKNESS 0.040 - 0.044 INCH AND WITHIN THE LIMITS OF A TYPICAL SCRIBE LINE WITH NO CRACK INDICATION					RECOMMENDED	
		MOS					
		AFL	1500 (s)				
SB 737-53A1289 R1 TABLE (10.12)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM EXTERNAL APPROVED REPAIR REPEAT INSPECTION.(G) SCRIBE LINE IS FOUND COMMON TO EXTERNAL APPROVED REPAIR WITH PARENT SKIN THICKNESS 0.045 - 0.049 INCH AND WITHIN THE LIMITS OF A TYPICAL SCRIBE LINE WITH NO CRACK INDICATION					RECOMMENDED	
		MOS					
		AFL	2000 (s)				
SB 737-53A1289 R1 TABLE (10.13)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM EXTERNAL APPROVED REPAIR REPEAT INSPECTION.(G) SCRIBE LINE IS FOUND COMMON TO EXTERNAL APPROVED REPAIR WITH PARENT SKIN THICKNESS 0.050 - 0.055 INCH AND WITHIN THE LIMITS OF A TYPICAL SCRIBE LINE WITH NO CRACK INDICATION.					RECOMMENDED	
		MOS					
		AFL	3000 (s)				
SB 737-53A1289 R1 TABLE (10.15)	CONTACT INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN BOEING FOR ADDITIONAL INSPECTIONS OR REPAIR ALL AIRPLANES WITH SCRIBE LINE USING A LRTS PROGRAM INSPECTION					RECOMMENDED	
		MOS					
		AFL	75000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (10.2)	DETERMINE INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN THE THICKNESS OF THE PARENT SKIN IN THE AREA OF THE EXTERNAL APPROVED REPAIR EXISTING EXTERNAL APPROVED REPAIR LOCATED BETWEEN STA 360 AND STA 1016 AND ABOVE S-10L AND S-10R WHICH IS 20 INCHES OR LONGER IN THE FORE AND AFT DIRECTION OR WIDER THAN 12 INCHES CIRCUMFERENTIALLY. (B)					RECOMMENDED	
		MOS					
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (10.3)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AROUND THE EDGE OF THE REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.5. PART 5 - EXTERNAL APPROVED REPAIR - INSPECTION PARENT SKIN THICKNESS 0.040 - 0.044 INCH IN THE AREA OF THE EXTERNAL APPROVED REPAIR					RECOMMENDED	
		MOS					
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (10.4)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AROUND THE EDGE OF THE REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.5. PART 5 - EXTERNAL APPROVED REPAIR - INSPECTION PARENT SKIN THICKNESS 0.045 - 0.049 INCH IN THE AREA OF THE EXTERNAL APPROVED REPAIR.					RECOMMENDED	
		MOS			18-NOV-2009		
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (10.5)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AROUND THE EDGE OF THE REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.5. PART 5 - EXTERNAL APPROVED REPAIR - INSPECTION (A)(B) PARENT SKIN THICKNESS 0.050 - 0.055 INCH IN THE AREA OF THE EXTERNAL APPROVED REPAIR					RECOMMENDED	
		MOS			18-NOV-2009		
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (11.1)	DETERMINE INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN THE THICKNESS OF THE PARENT SKIN IN THE AREA OF THE INTERNAL APPROVED REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.6. PART 6 - INTERNAL APPROVED REPAIR - INSPECTION.EXISTING INTERNAL APPROVED REPAIR LOCATED BETWEEN STA 360 AND STA 1016 AND BELOW S-10L AND S-10R AND THE SKIN CUTOUT IS GREATER THAN 20 INCHES LONG IN THE FORE AND AFT DIRECTION WITH NO CIRCUMFERENTIAL LIMITATIONS.					RECOMMENDED	
		MOS			18-NOV-2009		
		AFL	4000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (11.10)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM INTERNAL APPROVED REPAIR REPEAT INSPECTION SCRIBE LINE IS FOUND COMMON TO INTERNAL APPROVED REPAIR WITH PARENT SKIN THICKNESS 0.040 - 0.044 INCH AND WITHIN THE LIMITS OF A TYPICAL SCRIBE LINE WITH NO CRACK INDICATION					RECOMMENDED	
		MOS					
		AFL	2000 (s)				
SB 737-53A1289 R1 TABLE (11.11)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN HFEC INSPECTION AND UT INSPECTION OR UT PHASED ARRAY INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM INTERNAL APPROVED REPAIR REPEAT INSPECTION SCRIBE LINE IS FOUND COMMON TO INTERNAL APPROVED REPAIR WITH PARENT SKIN THICKNESS 0.045 - 0.049 INCH AND WITHIN THE LIMITS OF A TYPICAL SCRIBE LINE WITH NO CRACK INDICATION					RECOMMENDED	
		MOS					
		AFL	2500 (s)				
SB 737-53A1289 R1 TABLE (11.12)	CONTACT INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN BOEING FOR ADDITIONAL INSPECTIONS OR REPAIR. ALL AIRPLANES WITH SCRIBE LINE USING A LRTS PROGRAM INSPECTION					RECOMMENDED	
		MOS					
		AFL	75000 (s)				
SB 737-53A1289 R1 TABLE (11.2)	DETERMINE INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN THE THICKNESS OF THE PARENT SKIN IN THE AREA OF THE INTERNAL APPROVED REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.6. PART 6 - INTERNAL APPROVED REPAIR - INSPECTION EXISTING INTERNAL APPROVED REPAIR LOCATED BETWEEN STA 360 AND STA 1016 AND ABOVE S-10L AND S-10R AND THE SKIN CUTOUT IS GREATER THAN 20 INCHES LONG IN THE FORE AND AFT DIRECTION OR WIDER THAN 12 INCHES CIRCUMFERENTIALLY					RECOMMENDED	
		MOS			18-NOV-2009		
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (11.3)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN ANY SCRIBE LINE AROUND THE EDGE OF THE REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.6. PART 6 - INTERNAL APPROVED REPAIR - INSPECTION PARENT SKIN THICKNESS 0.040 - 0.044 INCH INCHES IN THE AREA OF THE INTERNAL APPROVED REPAIR.					RECOMMENDED	
		MOS			18-NOV-2009		
		AFL	4000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (11.4)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AROUND THE EDGE OF THE REPAIR IN ACCORDANCE WITH ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.6. PART 6 - INTERNAL APPROVED REPAIR - INSPECTION PARENT SKIN THICKNESS 0.045 - 0.049 INCH IN THE AREA OF THE INTERNAL APPROVED REPAIR	MOS				RECOMMENDED	
18-NOV-2009		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (3.1)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN OF CIRCUMFERENTIAL BUTT JOINT STA 887 BETWEEN S-10L AND S-10R FOR ANY SCRIBE LINE IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.3. PART 3-CIRCUMFERENTIAL BUTT JOINT -INSPECTION. (GROUP 1-3,5-8,10)	MOS				RECOMMENDED	
		AFL	40000 (s)				
SB 737-53A1289 R1 TABLE (3.11)	CONTACT INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN BOEING FOR ADDITIONAL INSPECTIONS OR REPAIR FOR ALL AIRPLANES WITH SCRIBE LINE USING A LRTS PROGRAM INSPECTION. (GROUP 1-3,5-8, 10)	MOS				RECOMMENDED	
		AFL	75000 (s)				
SB 737-53A1289 R1 TABLE (3.2)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN OF CIRCUMFERENTIAL BUTT JOINT STA 360 BETWEEN S-10L AND S-10R FOR ANY SCRIBE LINE IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.3. PART 3 -CIRCUMFERENTIAL BUTT JOINT -INSPECTION. (GROUP 1-3,5-8,10)	MOS				RECOMMENDED	
		AFL	45000 (s)				
SB 737-53A1289 R1 TABLE (3.4)	ACCOMPLISH INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN INSPECTIONS AS NEED FOR ANY SCRIBE LINE FOUND	MOS				RECOMMENDED	
			BF/F (s)				
SB 737-53A1289 R1 TABLE (3.8)	LFEC INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN - EXTERNAL - SLIDING PROBE INSPECTION OR AN INTERNAL MFEC INSPECTION OR AN EXTERNAL HFEC PENCIL PROBE INSPECTION OR AN INTERNAL HFEC INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS (GROUP 1-3,5-8, 10) PARAGRAPH 3.B.10.D. PART 10 - LRTS PROGRAM CIRCUMFERENTIAL BUTT JOINT - REPEAT INSPECTION STATION 360 (GROUP 1-3,5-8,10)	MOS				RECOMMENDED	
		AFL	45000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (3.9)	LFEC INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN - EXTERNAL - SLIDING PROBE INSPECTION OR AN INTERNAL MFEC INSPECTION OR AN EXTERNAL HFEC PENCIL PROBE INSPECTION OR AN INTERNAL HFEC INSPECTION OF THE SCRIBE LINE FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10.D. PART 10 - LRTS PROGRAM CIRCUMFERENTIAL BUTT JOINT -REPEAT INSPECTION. STATION 887 (GROUP 1-3,5-8, 10)					RECOMMENDED	
		MOS					
		AFL	40000 (s)				
SB 737-53A1289 R1 TABLE (6.1)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 -DECAL - INSPECTION. IN ZONE 6 (GROUP 2,7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (6.12)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN AND HFEC INSPECTION OF THE SCRIBE LINES FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM REPEAT INSPECTION. (A)IN ZONE 6 (GROUP 2, 7)					RECOMMENDED	
		MOS					
		AFL	10000 (s)				
SB 737-53A1289 R1 TABLE (6.13)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN AND HFEC INSPECTION OF THE SCRIBE LINES FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM REPEAT INSPECTION. IN ZONE 7 (GROUP 2, 7)					RECOMMENDED	
		MOS					
		AFL	5000 (s)				
SB 737-53A1289 R1 TABLE (6.14)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN AND HFEC INSPECTION OF THE SCRIBE LINES FOR ANY CRACK IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.10. PART 10 - LRTS PROGRAM REPEAT INSPECTION IN ZONE 8 (GROUP 2,7)					RECOMMENDED	
		MOS					
		AFL	2500 (s)				
SB 737-53A1289 R1 TABLE (6.16)	CONTACT INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN BOEING FOR FOR ADDITIONAL INSPECTIONS OR REPAIR.ALL AIRPLANES WITH SCRIBE LINE USING A LRTS PROGRAM INSPECTION (GROUP 2, 7)					RECOMMENDED	
		MOS					
		AFL	75000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1289 R1 TABLE (6.2)	ACCOMPLISH INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN EXTERNAL GENERAL VISUAL INSPECTIONFOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 - DECAL - INSPECTION.IN ZONE 6 (GROUP 2, 7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (6.3)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 - DECAL - INSPECTION. IN ZONE 7 (GROUP 2, 7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (6.4)	PERFORM INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN AN EXTERNAL GENERAL VISUAL INSPECTION FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 - DECAL -INSPECTION. IN ZONE 7 (GROUP 2, 7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (6.5)	EXTERNAL - DETAILED INSPECTION INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 -DECAL - INSPECTION. IN ZONE 8 (GROUP 2, 7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1289 R1 TABLE (6.6)	ACCOMPLISH INSPECTION OF THE SKIN FOR SCRIBE LINES, SERVICE BULLETIN EXTERNAL GENERAL VISUAL INSPECTION FOR ANY SCRIBE LINE AT THE LOCATIONS IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS PARAGRAPH 3.B.4. PART 4 - DECAL -INSPECTION IN ZONE 8 (GROUP 2, 7)					RECOMMENDED	
		MOS					
18-NOV-2009							
		AFL	4000 (s)				
SB 737-53A1325	FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN					MANDATORY	
		MOS					
03-DEC-2013			-				
SB 737-53A1325 TABLE 1.01 LH	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE LEFT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE LEFT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1 (FOR ALL AIRPLANES) (GROUP 1)						
		MOS					
			-				
		AFL					

© Camp Systems

EFTA00618438

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 1.01 RH	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1 (FOR ALL AIRPLANES) (GROUP 1)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 1.02 LH	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE LEFT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE LEFT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.J. (IF NO CRACK FOUND ON BOTH THE LEFT AND RIGHT SIDES) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 1.02 RH	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.J. (IF NO CRACK FOUND ON BOTH THE LEFT AND RIGHT SIDES) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 1.03	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 1 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.A. (IF ANY CRACK FOUND, ON THE LEFT SIDE, LESS THAN OR EQUAL TO 0.18 INCHES) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.04	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 1 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.B. (ANY CRACK FOUND, ON THE RIGHT SIDE, LESS THAN OR EQUAL TO 0.18 INCHES) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.05	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 2 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.C (IF ANY CRACK FOUND, ON THE LEFT SIDE, GREATER THAN 0.18 INCHES AND LESS THAN OR EQUAL TO 1.50 INCHES IN LENGTH, THAT DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 1)	MOS	-				

© Camp Systems

EFTA00618439

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 1.06	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 2 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.D. (IF ANY CRACK FOUND, ON THE RIGHT SIDE, GREATER THAN 0.18 INCHES AND LESS THAN OR EQUAL TO 1.50 INCHES IN LENGTH, THAT DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.07	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 3 IN ACCOR DANCE WITH PARAGRAPH 3.B.,WORK INSTRUCTIONS, PART 2, STEP 1.E. (IF ANY CRACK FOUND, ON THE LEFT SIDE, GREATER THAN 0.18 INCHES, THAT EXTENDS INTO THE FLANGE OF THE INNER CHORD) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.08	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 3 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.F. (IF ANY CRACK FOUND, ON THE RIGHT SIDE, GREATER THAN 0.18 INCHES, THAT EXTENDS INTO THE FLANGE OF THE INNER CHORD) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.09	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING. (IF ANY CRACK FOUND GREATER THAN 1.50 INCHES IN LENGTH AND DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.10	ACCOMPLISH FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN PREVENTIVE MODIFICATION ON THE LEFT SIDE IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.H. (IF NO CRACK FOUND ON THE LEFT SIDE AND A REPAIR WAS ACCOMPLISHED ON THE RIGHT SIDE) (GROUP 1)	MOS	-				
SB 737-53A1325 TABLE 1.11	ACCOMPLISH FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN PREVENTIVE MODIFICATION ON THE RIGHT SIDE IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 1.I. (IF NO CRACK FOUND ON THE RIGHT SIDE AND A REPAIR WAS ACCOMPLISHED ON THE LEFT SIDE) (GROUP 1)	MOS	-				

© Camp Systems

EFTA00618440

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 2.01	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2 (ALL AIRPLANES) (GROUP 2)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 2.02	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.E. (NO CRACK FOUND ON THE RIGHT SIDE) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 2.03	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 1 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.A. (ANY CRACK FOUND LESS THAN OR EQUAL TO 0.18 INCHES) (GROUP 2)	MOS	-				
SB 737-53A1325 TABLE 2.04	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 2 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.B. (ANY CRACK FOUND GREATER THAN 0.18 INCHES AND LESS THAN OR EQUAL TO 1.50 INCHES IN LENGTH, THAT DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 2)	MOS	-				
SB 737-53A1325 TABLE 2.05	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 3 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.C. (ANY CRACK FOUND GREATER THAN 0.18 INCHES, THAT EXTENDS INTO THE FLANGE OF THE INNER CHORD) (GROUP 2)	MOS	-				
SB 737-53A1325 TABLE 2.06	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ANY CRACK FOUND GREATER THAN 1.50 INCHES IN LENGTH AND DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 2)	MOS	-				

© Camp Systems

EFTA00618441

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 2.07	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR LEFT SIDE INSPECTION AND MODIFICATION INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ALL AIRPLANES) (GROUP 2)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 3.01	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2 (ALL AIRPLANES) (GROUP 3)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 3.02	DETAILED INSPECTION FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN OF THE RIGHT SIDE LOWER FRAME WEB AND INNER CHORD AND AN OPEN HOLE HFEC INSPECTION OF THE RIGHT SIDE LOWER FRAME WEB IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2. (NO CRACK FOUND) (GROUP 3)	MOS	- (s)				
SB 737-53A1325 TABLE 3.03	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 1 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.A. (ANY CRACK FOUND LESS THAN OR EQUAL TO 0.18 INCHES) (GROUP 3)	MOS	-				
SB 737-53A1325 TABLE 3.04	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 2 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.B. (ANY CRACK FOUND GREATER THAN 0.18 INCHES AND LESS THAN OR EQUAL TO 1.50 INCHES IN LENGTH, THAT DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 3)	MOS	-				
SB 737-53A1325 TABLE 3.05	REPAIR FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN 3 IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 2, STEP 2.C. (ANY CRACK FOUND GREATER THAN 0.18 INCHES, THAT EXTENDS INTO THE FLANGE OF INNER CHORD) (GROUP 3)	MOS	-				

© Camp Systems

EFTA00618442

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 3.06	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ANY CRACK FOUND GREATER THAN 1.50 INCHES IN LENGTH AND DOES NOT EXTEND INTO THE FLANGE OF THE INNER CHORD) (GROUP 3)	MOS	-				
SB 737-53A1325 TABLE 4.01.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 2.A. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.01.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 2.B. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.02.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 5.A. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.02.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 5.B. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.03.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.A. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.03.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.B. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				

© Camp Systems

EFTA00618443

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 4.04.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.A. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.04.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.B. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.05	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 3. (AIRPLANES WITH REPAIR 2 ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.06	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 3. (AIRPLANES WITH REPAIR 2 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.07	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 4. (AIRPLANES WITH REPAIR 3 ACCOMPLISHED, ON THE LEFT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.08	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 4. (AIRPLANES WITH REPAIR 3 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 1)	MOS	- (s)				
SB 737-53A1325 TABLE 4.09	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ANY CRACK FOUND) (GROUP 1)	MOS	-				

© Camp Systems

EFTA00618444

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 5.01.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.A. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.01.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.B. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.02.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.A. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.02.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.B. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.03	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 3. (AIRPLANES WITH REPAIR 2 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.04	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 4. (AIRPLANES WITH REPAIR 3 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 2)	MOS	- (s)				
SB 737-53A1325 TABLE 5.05	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ANY CRACK FOUND) (GROUP 2)	MOS	-				

© Camp Systems

EFTA00618445

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 6.01.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE LEFT SIDE FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 6.A. (ALL AIRPLANES) (GROUP 3)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 6.01.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE LEFT SIDE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 4, STEP 6.B. (ALL AIRPLANES) (GROUP 3)	MOS	-				
		AFL					
SB 737-53A1325 TABLE 6.02.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.A. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)	MOS	- (s)				
SB 737-53A1325 TABLE 6.02.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 2.B. (AIRPLANES WITH THE REPAIR 1 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)	MOS	- (s)				
SB 737-53A1325 TABLE 6.03.1	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF FRAME WEB AND FRAME INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.A. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)	MOS	- (s)				
SB 737-53A1325 TABLE 6.03.2	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 5.B. (AIRPLANES WITH THE PREVENTIVE MODIFICATION ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)	MOS	- (s)				
SB 737-53A1325 TABLE 6.04	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 3. (AIRPLANES WITH REPAIR 2 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)	MOS	- (s)				

© Camp Systems

EFTA00618446

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-53A1325 TABLE 6.05	HFEC FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN INSPECTION OF THE FRAME WEB AND INNER CHORD IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 5, STEP 4. (AIRPLANES WITH REPAIR 3 ACCOMPLISHED, ON THE RIGHT SIDE, IN ACCORDANCE WITH THIS SB) (GROUP 3)						
		MOS	- (s)				
SB 737-53A1325 TABLE 6.06	CONTACT FUSELAGE - FRAMES AND BULKHEADS - BODY STATION (STA) 727 BULKHEAD LOWER FRAME WEB AND INNER CHORD - INSPECTION, PREVENTIVE MODIFICATION AND REPAIR, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING (ANY CRACK FOUND) (GROUP 3)						
		MOS	-				
SB 737-54-1039	STRUT - APPLICATION OF SEALANT AT BULKHEAD/DIAGONAL BRACE INTERFACE, SERVICE BULLETIN						
		MOS	18 (s)				
13-JUN-2002			800				
SB 737-54-1039 R1	APPLICATION OF SEALANT AT BULKHEAD/DIAGONAL BRACE INTERFACE, SERVICE BULLETIN						COMPLIED WITH
		MOS	18 (s)		11-MAY-2006		
10-OCT-2002					2619:10		
		AFL	3500		629		
SB 737-54-1040	GENERAL VISUAL INSPECTION OF SEALANT ON ENGINE STRUT STRUCTURE, SERVICE BULLETIN						
		MOS	18 (s)				
14-NOV-2002							
		AFL	3500				
SB 737-54-1040 R1	APPLICATION OF SEALANT ON ENGINE STRUT STRUCTURE, SERVICE BULLETIN						COMPLIED WITH
		MOS	18 (s)		18-AUG-2006		
14-NOV-2002					2633:50		
		AFL	3500		633		
SB 737-54-1040 R2	APPLICATION OF SEALANT ON ENGINE STRUT STRUCTURE, SERVICE BULLETIN						
		MOS	18 (s)				
07-NOV-2006							
		AFL	3500				
SB 737-54-1040 R3	APPLICATION OF SEALANT ON ENGINE STRUT STRUCTURE, SERVICE BULLETIN						
		MOS	18 (s)				
14-NOV-2002							
		AFL	3500				
SB 737-54-1041	ENGINE STRUT AFT FAIRING, SERVICE BULLETIN						COMPLIED WITH
		MOS			24-AUG-2007		
22-JAN-2004			A/R		2968:28		
		AFL			699		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-54-1041 PART I&II	INSPECT ENGINE STRUT AFT FAIRING, SERVICE BULLETIN FOR FLUID ACCUMULATION						COMPLIED WITH
		MOS	30 (s)	24-AUG-2007			
22-JAN-2004				2968:28			
		AFL	4000	699			
SB 737-54-1041 PART III&IV	MODIFY ENGINE STRUT AFT FAIRING, SERVICE BULLETIN SEALS						COMPLIED WITH
		MOS		24-AUG-2007			
22-JAN-2004				2968:28			
		AFL	9000 (s)	699			
SB 737-54-1041 R1	ENGINE STRUT AFT FAIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - IAW THE AD AD 2006-07-04 //PARTS I,II AND III MOD SB 737-54-1041R1 REF (R2) - IN 02)
		MOS		24-AUG-2007			
01-DEC-2005			-	2968:28			
		AFL		699			
SB 737-54-1041 R1 PART I&II	INSPECT ENGINE STRUT AFT FAIRING, SERVICE BULLETIN FOR FLUID ACCUMULATION						COMPLIED WITH
		MOS	30 (s)	24-AUG-2007			
01-DEC-2005				2968:28			
		AFL	4000	699			
SB 737-54-1041 R1 PART III&IV	MODIFY ENGINE STRUT AFT FAIRING, SERVICE BULLETIN SEALS					RECOMMENDED	COMPLIED WITH
		MOS		24-AUG-2007			
12-JAN-2005			- (s)	2968:28			
		AFL		699			
SB 737-54-1041 R2	NACELLES / PYLONS - AFT FAIRING - FLUID ACCUMULATION IN ENGINE STRUT AFT FAIRING -INSTALLATION OF NEW ENGINE STRUT AFT FAIRING SEALS, SERVICE BULLETIN						
		MOS					
03-OCT-2007			-				
SB 737-54-1041 R2 PART I&II	INSPECT NACELLES / PYLONS - AFT FAIRING - FLUID ACCUMULATION IN ENGINE STRUT AFT FAIRING -INSTALLATION OF NEW ENGINE STRUT AFT FAIRING SEALS, SERVICE BULLETIN FOR FLUID ACCUMULATION						
		MOS	30 (s)				
03-OCT-2007							
		AFL	4000				
SB 737-54-1041 R2 PART III & IV	MODIFY NACELLES / PYLONS - AFT FAIRING - FLUID ACCUMULATION IN ENGINE STRUT AFT FAIRING -INSTALLATION OF NEW ENGINE STRUT AFT FAIRING SEALS, SERVICE BULLETIN SEALS						
		MOS					
03-OCT-2007							
		AFL	9000 (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-54-1042	ENGINE STRUT UPPER LINK-INSPECTION MODIFICATION, SERVICE BULLETIN						
		MOS	30 (s)				
12-FEB-2004							
SB 737-54-1042 R1	ENGINE STRUT UPPER LINK - INSPECTION / MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	30 (s)				
30-JUL-2009							
SB 737-54-1043	NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASSEMBLY REPLACEMENT., SERVICE BULLETIN						
		MOS	60 (s)				
02-MAY-2007							
SB 737-54-1043 R1	STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASSEMBLY REPLACEMENT.(SUPPERSEDED BY 737-54-1043 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-54-1043 R2	NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASSEMBLY REPLACEMENT (SUPERSEDED BY SB 737-54-1043 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-54-1043 R3	NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
31-DEC-2012							
SB 737-54-1045	NACELLES/PYLONS - HEAT INSULATION BLANKETS - REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS			29-AUG-2011		
25-JUL-2007			- (s)		3533:32		
		AFL			863		
SB 737-54-1046	NACELLES/PYLONS - STRUT TO WING FAIRINGS - THUMBNAIL FAIRING EDGE SEAL REPLACEMENT (SUPERSEDED BY SB 737-54-1046 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-54-1046 R1	NACELLES/PYLONS - STRUT TO WING FAIRINGS - THUMBNAIL FAIRING EDGE SEAL REPLACEMENT, SERVICE BULLETIN						
		MOS					
			-				
SB 737-54-1047	NACELLES/PYLONS - STRUT AFT FAIRING HEAT SHIELD ASSEMBLY AND INSULATION BLANKET INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-SEP-2012			-				

© Camp Systems

EFTA00618449

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-54-1049	NACELLES/PYLONS- STRUT DRAINS AND SEALS - STRUT SEAL PLANE ACCESS PANELS LEAK INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-SEP-2012			-				
SB 737-54-1049 TABLE 1.1	DETAILED INSPECTION NACELLES/PYLONS- STRUT DRAINS AND SEALS - STRUT SEAL PLANE ACCESS PANELS LEAK INSPECTION, SERVICE BULLETIN OF THE STRUT SEAL PLANE ACCESS PANELS FOR ANY LEAK (GROUP 1 AIRPLANES)					RECOMMENDED	
		MOS	30 (s)				
		AFL	9000				
SB 737-54-1049 TABLE 1.2	DETAILED INSPECTION NACELLES/PYLONS- STRUT DRAINS AND SEALS - STRUT SEAL PLANE ACCESS PANELS LEAK INSPECTION, SERVICE BULLETIN OF THE STRUT SEAL PLANE ACCESS PANELS FOR ANY LEAK (GROUP 2 AIRPLANES)					RECOMMENDED	
		MOS	36 (s)				
SB 737-55-1062	LEADING EDGE RIB, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-AUG-2000			- (s)				
SB 737-55-1063	TAB MAST FITTING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS			13-SEP-1999		
01-JUL-1999			- (s)				
SB 737-55-1063 R1	TAB MAST FITTING, SERVICE BULLETIN					RECOMMENDED	
		MOS	18 (s)				
14-SEP-2000							
		AFL	4000				
SB 737-55-1067	ELEVATOR HINGE PLATES, SERVICE BULLETIN						NOT APPLICABLE - NO ACTION REQUIRED
		MOS			22-AUG-2003		
			-		1342		
		AFL			351		
SB 737-55-1069	LOWER CLOSURE RIB & RUDDER HINGE PLATE NUT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
31-AUG-2000			- (s)				
SB 737-55-1074	INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERMANENT REPAIR, PART 3 OF SB.
		MOS			09-AUG-2010		
15-AUG-2000			-		3448:31		
		AFL			841		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1074 PART 1	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS, SERVICE BULLETIN INSPECTION						COMPLIED WITH - PERMANENT REPAIR, PART 3 OF SB.
		MOS	18 (s)	09-AUG-2010			
15-AUG-2002				3448:31			
		AFL		841			
SB 737-55-1074 PART 2	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS, SERVICE BULLETIN INTERIM REPAIR						COMPLIED WITH
		MOS	18 (s)	22-AUG-2008			
				3260:48			
		AFL		782			
SB 737-55-1074 PART 3	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS, SERVICE BULLETIN PERMANENT REPAIR						COMPLIED WITH - PERMANENT REPAIR, PART 3 OF SB.
		MOS		09-AUG-2010			
			- (s)	3448:31			
		AFL		841			
SB 737-55-1074 R1	INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZONTAL STABILIZERS AND THE HORIZONTAL STABILIZER CENTER SECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERMANENT REPAIR
		MOS		29-AUG-2011			
18-DEC-2003			-	3533:32			
		AFL		863			
SB 737-55-1074 R1 PART 1	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZONTAL STABILIZERS AND THE HORIZONTAL STABILIZER CENTER SECTION, SERVICE BULLETIN INSPECTION						COMPLIED WITH
		MOS	18 (s)	29-AUG-2011			
18-DEC-2003				3533:32			
		AFL		863			
SB 737-55-1074 R1 PART 2	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZONTAL STABILIZERS AND THE HORIZONTAL STABILIZER CENTER SECTION, SERVICE BULLETIN INTERIM REPAIR					RECOMMENDED	
		MOS	18 (s)				
12-DEC-2003							
SB 737-55-1074 R1 PART 3	ACCOMPLISH INSPECTION AND REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZONTAL STABILIZERS AND THE HORIZONTAL STABILIZER CENTER SECTION, SERVICE BULLETIN PERMANENT REPAIR					RECOMMENDED	COMPLIED WITH
		MOS		29-AUG-2011			
09-SEP-2004			- (s)	3533:32			
		AFL		863			
SB 737-55-1086	INSPECTION OF THE PINS AND BOLTS THAT ATTACH THE HORIZONTAL STABILIZER TO THE HORIZONTAL STABLIZER CENTER SECTION (SUPERSEDED BY SB 737-55-1086 R1), SERVICE BULLETIN						- IAW THE SB
		MOS		22-AUG-2008			
11-DEC-2003			-	3260:48			
		AFL		782			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1086 R1	INSPECTION OF THE PINS AND BOLTS THAT ATTACH THE HORIZONTAL STABILIZER TO THE HORIZONTAL STABLIZER CENTER SECTION (SUPERSEDED BY SB 737-55-1086 R2), SERVICE BULLETIN						- INFORMATION REF TO IR AND REV.2 (REPLACEMENT)
		MOS					
16-DEC-2004			-				
SB 737-55-1086 R2	STABILIZERS - HORIZONTAL STABILIER - INSPECTION OF THE PINS AND BOLTS THAT ATTACH THE HORIZONTAL STABILIZER TO THE HORIZONTAL STABILIZER CENTER SECTION (SUPERSEDED BY SB 737-55-1086 R3), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS			29-AUG-2011		
			-		3533:32		
		AFL			863		
SB 737-55-1086 R3	STABILIZERS - HORIZONTAL STABILIZER - INSPECTION OF THE PINS AND BOLTS THAT ATTACH THE HORIZONTAL STABILIZER TO THE HORIZONTAL STABILIZER CENTER SECTION, SERVICE BULLETIN					RECOMMENDED	
		DAYS	90 (s)				
13-JUN-2012							
SB 737-55-1089	HORIZONTAL STABILIZER - TRAILING EDGE PANEL, CONDUCTIVE STRIP AND TIP CAP ASSEMBLY - CHANGE (SUPERSEDED BY SB 737-55-1089 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-55-1089 R1	STABILIZERS - HORIZONTAL STABILIZER - TRAILING EDGE PANEL, CONDUCTIVE STRIP AND TIP CAP ASSEMBLY - CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-SEP-2011			-				
SB 737-55-1090	STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR TERMINATION FITTING - INSPECTION, SERVICE BULLETIN					MANDATORY	
		MOS					
30-MAR-2011			-				
SB 737-55-1090 TABLE 1.1	INSPECTION STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR TERMINATION FITTING - INSPECTION, SERVICE BULLETIN OF THE LEFT AND RIGHT SIDE HORIZONTAL STABILIZER IDENTIFICATION PLATE FOR A SERIAL NUMBER THAT START WITH SAIC FOR ALL AIRPLANES					MANDATORY	
		MOS	12 (s)				
30-MAR-2011							
SB 737-55-1090 TABLE 1.2	DETAILED INSPECTION STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR TERMINATION FITTING - INSPECTION, SERVICE BULLETIN OF THE HORIZONTAL STABILIZER TERMINATION FITTING FASTENERS FOR INCORRECT BOLT PROTRUSION AND CHAMFER FOR HORIZONTAL STABILIZERS IDENTIFICATION PLATES WHICH HAVE A SERIAL NUMBER STARTING WITH SAIC.					MANDATORY	
		MOS	12 (s)				
30-MAR-2011							
SB 737-55-1090 TABLE 1.6	HFEC STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR TERMINATION FITTING - INSPECTION, SERVICE BULLETIN AND UT INSPECTIONS OF THE TERMINATION FITTING FOR CRACKS FOR NEW BACB30US14K( ) BOLT IS INSTALLED					MANDATORY	
		MOS	12 (s)				
30-MAR-2011							

© Camp Systems

EFTA00618452

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1093	STABILIZERS - HORIZONTAL STABILIZER - REPLACEMENT OF REAR SPAR ATTACH PINS WITH UNAPPROVED SURFACE COATING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	09-APR-2012						
		AFL	3000 (s)				
SB 737-55-1096	STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	22-MAR-2013		-				
SB 737-55-1096 TABLE 1(01.1)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN DO A DETAILED INSPECTION OF THE SKIN, MODIFICATION SKIN AND SPAR DOUBLERS FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(01.2)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN AN EDDY CURRENT INSPECTION OF THE SKIN, MODIFICATION SKIN, SPLICE DOUBLERS AND SPAR LOWER CHORDS FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(01.3)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A LOW FREQUENCY EDDY CURRENT (LFEC) INSPECTION OF THE FRONT SPAR UPPER CHORD AFT FLANGE, FROM STAB STA 66.50 TO STAB TIP, FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(01.4)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION OF THE FRONT SPAR UPPER CHORD FORWARD FLANGE, FROM STAB STA 66.50 TO STAB TIP, FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(01.5)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A LFEC INSPECTION OF THE FRONT SPAR UPPER CHORD WEB FLANGE, FROM STAB STA 66.50 TO STAB STA 175.5 AND FROM STAB STA 258.28 TO STAB TIP, FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1096 TABLE 1(01.6)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HFEC INSPECTION OF THE FRONT SPAR UPPER CHORD WEB FLANGE, FROM STAB STA 66.50 TO STAB STA 175.5 AND FROM STAB STA 258.28 TO STAB TIP, FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(01.7)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HFEC INSPECTION OF THE FRONT SPAR UPPER CHORD FORWARD FLANGE, FROM STAB STA 175.5 TO STAB STA 258.28, FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(02.1)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IN ANY CRACK FOUND IN THE SKIN, MODIFICATION SKIN, SPAR DOUBLERS, SPLICE DOUBLERS OR SPAR LOWER CHORDS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
SB 737-55-1096 TABLE 1(03.1)	REMOVE STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN THE CRACK DAMAGE IF ANY CRACK FOUND IN THE FRONT SPAR UPPER CHORD FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
SB 737-55-1096 TABLE 1(04.1)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A DETAILED INSPECTION OF THE SKIN, MODIFICATION SKIN AND SPAR DOUBLERS FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(04.2)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN AN EDDY CURRENT INSPECTION OF THE SKIN, MODIFICATION SKIN, SPLICE DOUBLERS AND SPAR LOWER CHORDS FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1096 TABLE 1(04.3)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A LFEC INSPECTION OF THE FRONT SPAR UPPER CHORD AFT FLANGE, FROM STAB STA 66.50 TO STAB TIP, FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(04.4)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HFEC INSPECTION OF THE FRONT SPAR UPPER CHORD FORWARD FLANGE, FROM STAB STA 66.50 TO STAB TIP, FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(04.5)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A LFEC INSPECTION OF THE FRONT SPAR UPPER CHORD WEB FLANGE, FROM STAB STA 66.50 TO STAB STA 175.5 AND FROM STAB STA 258.28 TO STAB TIP, FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(04.6)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HFEC INSPECTION OF THE FRONT SPAR UPPER CHORD WEB FLANGE, FROM STAB STA 66.50 TO STAB STA 175.5 AND FROM STAB STA 258.28 TO STAB TIP, FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(04.7)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A HFEC INSPECTION OF THE FRONT SPAR UPPER CHORD FORWARD FLANGE, FROM STAB STA 175.5 TO STAB STA 258.28, FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(05.1)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IF ANY CRACK FOUND IN THE SKIN, MODIFICATION SKIN, SPAR DOUBLERS, SPLICE DOUBLERS OR SPAR LOWER CHORDS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				

© Camp Systems

EFTA00618455

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1096 TABLE 1(06.1)	REMOVE STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN THE CRACK DAMAGE IF ANY CRACK FOUND IN THE FRONT SPAR UPPER CHORD FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED BEFORE 56,000 TOTAL FLIGHT CYCLES	MOS	-				
SB 737-55-1096 TABLE 1(07.1)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A DETAILED INSPECTION OF THE SKIN, MODIFICATION SKIN AND SPAR DOUBLERS FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(07.2)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN AN EDDY CURRENT INSPECTION OF THE SKIN, MODIFICATION SKIN, SPLICE DOUBLERS AND SPAR LOWER CHORDS FOR CRACKS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(07.3)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR ADDITIONAL POST MODIFICATION INSPECTIONS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES	MOS	-			RECOMMENDED	
SB 737-55-1096 TABLE 1(08.1)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IF ANY CRACK FOUND IN THE SKIN, MODIFICATION SKIN, SPAR DOUBLERS, SPLICE DOUBLERS OR SPAR LOWER CHORDS FOR LEFT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES	MOS	-				
SB 737-55-1096 TABLE 1(09.1)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN A DETAILED INSPECTION OF THE SKIN, MODIFICATION SKIN AND SPAR DOUBLERS FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES	MOS	-				
		AFL					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55-1096 TABLE 1(09.2)	DO STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN AN EDDY CURRENT INSPECTION OF THE SKIN, MODIFICATION SKIN, SPLICE DOUBLERS AND SPAR LOWER CHORDS FOR CRACKS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
		AFL					
SB 737-55-1096 TABLE 1(09.3)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR ADDITIONAL POST MODIFICATION INSPECTIONS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES					RECOMMENDED	
		MOS	-				
SB 737-55-1096 TABLE 1(10.1)	CONTACT STABILIZERS - HORIZONTAL STABILIZER - LOWER SKIN CRACKING AND MODIFICATION, SERVICE BULLETIN BOEING FOR REPAIR INSTRUCTIONS AND DO THE WORK INSTRUCTED BY BOEING IF ANY CRACK FOUND IN THE SKIN, MODIFICATION SKIN, SPAR DOUBLERS, SPLICE DOUBLERS OR SPAR LOWER CHORDS FOR RIGHT SIDE HORIZONTAL STABILIZER LOWER SKIN MODIFICATION INSTALLED AT OR AFTER 56,000 TOTAL FLIGHT CYCLES						
		MOS	-				
SB 737-55A1064	ELEVATOR BALANCE PANEL ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
15-OCT-1998		MOS	250 (s)	44			
SB 737-55A1064 R1	ELEVATOR BALANCE PANEL ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER
07-DEC-2000		MOS	- (s)	20-APR-2001 697:54			
		AFL		188			
SB 737-55A1066	FRONT SPAR HINGE FITTING REPLACEMENT-HINGE 3-8, SERVICE BULLETIN						NOT APPLICABLE - NO ACTION REQUIRED
19-SEP-2002		MOS	24 (s)	22-AUG-2003 1342			
		AFL	18000	351			
SB 737-55A1066 R1	FRONT SPAR HINGE FITTING REPLACEMENT-HINGES 3-8, SERVICE BULLETIN						- 737-55A1080R1
19-SEP-2002		MOS	24 (s)				
		AFL	18000				
SB 737-55A1068	ELEVATOR TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
09-JUN-1999		MOS	- (s)	13-SEP-1999			
SB 737-55A1068 R1	ELEVATOR TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
11-JUN-1999		MOS	-				

© Camp Systems

EFTA00618457

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55A1068 R2	ELEVATOR TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		DAYS	15 (s)				
24-FEB-2000							
		AFL	100				
SB 737-55A1072 PKG 1	STABILIZERS - ELEVATOR - TAB ASSEMBLY - INSPECTION OF ELEVATOR TAB HINGE AND ELEVATOR TAB CONTROL MECHANISM, SERVICE BULLETIN						
		MOS					
28-DEC-2000			- (s)				
SB 737-55A1072 PKG 2	STABILIZERS - ELEVATOR - TAB ASSEMBLY - INSPECTION OF ELEVATOR TAB HINGE AND ELEVATOR TAB CONTROL MECHANISM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-DEC-2000							
		AFL	750 (s)				
SB 737-55A1072 PKG 3	STABILIZERS - ELEVATOR - TAB ASSEMBLY - INSPECTION OF ELEVATOR TAB HINGE AND ELEVATOR TAB CONTROL MECHANISM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-DEC-2000			1500 (s)				
		AFL	750				
SB 737-55A1072 R1	ELEVATOR HINGE AND TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JAN-2001			- (s)				
SB 737-55A1072 R1 PKG 1	INSPECT ELEVATOR HINGE AND TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS			20-APR-2001		
11-JAN-2001					702:24		
		AFL	250 (s)		188		
SB 737-55A1072 R1 PKG 2	INSPECT ELEVATOR HINGE AND TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JAN-2001							
		AFL	750 (s)				
SB 737-55A1072 R1 PKG 3	INSPECT ELEVATOR HINGE AND TAB ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JAN-2001			1500 (s)				
		AFL	750				
SB 737-55A1076	ELEVATOR TAB HINGE FASTNER REPLACEMENT, SERVICE BULLETIN						
		MOS	24 (s)				
		AFL	4500				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-55A1079	ELEVATOR TAB, SPEEDBRAKE RESTRICTION, PLACARD INSTALLATION, SERVICE BULLETIN						
		MOS	1 (s)				
19-JUL-2001							
SB 737-55A1079 R1	ELEVATOR TAB, SPEEDBREAK RESTRICTION, PLACARD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	1 (s)				
16-MAY-2002							
SB 737-55A1080	ELEVATOR AND ELEVATOR TAB REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY REF. AD 2003-03-22 / 737-55A1080R1
		MOS	24 (s)	18-AUG-2006			
19-SEP-2002				2633:50			
		AFL	18000	633			
SB 737-55A1080 R1	ELEVATOR AND ELEVATOR TAB REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2003			
19-SEP-2002			-	1342			
		AFL		351			
SB 737-55A1082	ELEVATOR MODIFICATION, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY
		MOS	24 (s)	22-AUG-2003			
19-SEP-2002				1342			
		AFL	18000	351			
SB 737-55A1082 R1	MODIFICATION TO IMPROVE THE STRUCTURAL DAMPING CHARACTERISTICS AND ENHANCE THE WEAR CHARACTERISTICS OF THE ELEVATOR TAB, SERVICE BULLETIN						- 737-55A1080R1
		MOS	24 (s)				
19-SEP-2002							
		AFL	18000				
SB 737-55A1084	HORIZONTAL STABILIZER - TRAILING EDGE - ELEVATOR BALANCE BAY PANEL SEAL TRIM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAR-2002			- (s)				
SB 737-55A1084 R1	HORIZONTAL STABILIZER - ELEVATOR BALANCE BAY PANEL SEAL TRIM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JUN-2002			- (s)				
SB 737-56-1011	DRAIN OPENABLE WINDOWS INSTALLATIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-NOV-1998			- (s)				
SB 737-56-1011 R1	DRAIN OPENABLE WINDOWS INSTALLATIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-JUN-2000			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-56-1014	INSPECTION AND REPLACEMENT OF NO. 3 FLIGHT COMPARTMENT WINDOWS, SERVICE BULLETIN						
		MOS					
26-APR-2001							
		AFL	2000 (s)				
SB 737-56-1016	WINDOWS - CONTROL CABIN SLIDING WINDOWS - NUMBER 2 OPENABLE WINDOW - HOLD OPEN LATCH ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN						
		MOS					
11-AUG-2005			-				
SB 737-56-1017	WINDOWS - FLIGHT COMPARTMENT - CONTROL CABIN FIXED WINDOWS - DELEATION OF NUMBER 4 AND NUMBER 5 WINDOWS (SUPERSEDED BY 737-56-1017 R1), SERVICE BULLETIN						
		MOS					
17-MAY-2006			-				
SB 737-56-1017 R1	WINDOWS - FLIGHT COMPARTMENT - CONTROL CABIN FIXED WINDOWS - DELETION OF NUMBER 4 AND NUMBER 5 WINDOWS. (SUPERSEDED BY SB 737-56-1017 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-56-1017 R2	WINDOWS - FLIGHT COMPARTMENT - CONTROL CABIN FIXED WINDOWS - DELETION OF NUMBER 4 AND NUMBER 5 WINDOWS., SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-JAN-2011			-				
SB 737-56-1024	WINDOWS - CONTROL CABIN SLIDING WINDOWS - LEFT SIDE AND RIGHT SIDE NUMBER 2 WINDOW FRAME REPAIR AND MODIFICATION, SERVICE BULLETIN						
		MOS					
21-SEP-2007			-				
SB 737-56-1025	FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2 WINDOW PANE - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JAN-2010			-				
SB 737-56-1025 (LH)	REPLACE FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2 WINDOW PANE - REPLACEMENT, SERVICE BULLETIN LEFT FLIGHT DECK NUMBER 2 (SLIDING) WINDOW					RECOMMENDED	
		MOS					
			-				
SB 737-56-1025 (RH)	REPLACE FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2 WINDOW PANE - REPLACEMENT, SERVICE BULLETIN RIGHT FLIGHT DECK NUMBER 2 (SLIDING) WINDOW					RECOMMENDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-56A1022	WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION (SUPERSEDED BY 737-56A1022 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - INSPECTIONS TABLES 2 & 3 FOR THE #4 AND #5 WINDOWS ONLY I.A.W. AD 2008-11-08 FOUND SATSFACTORY
18-JUL-2007		MOS	-	16-FEB-2010 3417:51			
		AFL		829			
SB 737-56A1022 R1	WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - DETAIL INSPECTION I.A.W. AD 2008-11-08 (F) FLIGHT DECK NO.2, NO.4 AND NO.5 WINDOWS
12-MAR-2010		MOS	-	12-FEB-2014 3743:34			
		AFL		917			
SB 737-56A1022 R1 TABLE 1.01	DETAILED INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN OF THE LEFT AND RIGHT FLIGHT DECK NUMBER 2 WINDOW (GROUP 1-2)					RECOMMENDED	COMPLIED WITH - DETAIL INSPECTION
12-MAR-2010		MOS	36 (s) 7500	12-FEB-2014 3743:34			
		AFL		917			
SB 737-56A1022 R1 TABLE 1.02	REPLACE WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN THE LEFT AND RIGHT FLIGHT DECK NUMBER 2 WINDOW AND PERFORM A DETAILED INSPECTION (GROUP 1-2)					RECOMMENDED	
12-MAR-2010		MOS	-				
SB 737-56A1022 R1 TABLE 2.01	DETAILED INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN OF FLIGHT DECK NUMBER 4 WINDOW (GROUP 1, CONFIGURATION 1)					RECOMMENDED	COMPLIED WITH - DETAIL INSPECTION
12-MAR-2010		MOS	24 (s) 6000	12-FEB-2014 3743:34			
		AFL		917			
SB 737-56A1022 R1 TABLE 2.02	REPLACE WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN THE FLIGHT DECK NUMBER 4 WINDOW AND PERFORM DETAILED INSPECTION (GROUP 1, CONFIGURATION 1)					RECOMMENDED	
12-MAR-2010		MOS	BF/F (s)				
SB 737-56A1022 R1 TABLE 3.01	DETAILED INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN OF THE FLIGHT DECK NUMBER 5 WINDOW (GROUP 1, CONFIGURATION 1)					RECOMMENDED	COMPLIED WITH - DETAIL INSPECTION
12-MAR-2010		MOS	24 (s) 6000	12-FEB-2014 3743:34			
		AFL		917			
SB 737-56A1022 R1 TABLE 3.02	REPLACE WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION, SERVICE BULLETIN THE FLIGHT DECK NUMBER 5 WINDOW (GROUP 1, CONFIGURATION 1)					RECOMMENDED	
12-MAR-2010		MOS	BF/F (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-56A1022 TABLE 1	DETAIL INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION (SUPERSEDED BY 737-56A1022 R1), SERVICE BULLETIN OF FLIGHT DECK NUMBER 2 WINDOW FOR GROUP 1 AND 2						- INSPECTION
		MOS	36 (s)	14-FEB-2008			
18-JUL-2007			7500	3151:22			
		AFL		746			
SB 737-56A1022 TABLE 2	DETAIL INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION (SUPERSEDED BY 737-56A1022 R1), SERVICE BULLETIN OF FLIGHT DECK NUMBER 4 WINDOW FOR GROUP 1 CONFIGURATION 1						
		MOS	24 (s)	16-FEB-2010			
18-JUL-2007			6000	3417:51			
		AFL		829			
SB 737-56A1022 TABLE 3	DETAIL INSPECTION WINDOWS - FLIGHT COMPARTMENT - FLIGHT DECK NUMBER 2, NUMBER 4 AND NUMBER 5 WINDOWS - INSPECTION (SUPERSEDED BY 737-56A1022 R1), SERVICE BULLETIN OF FLIGHT DECK NUMBER 5 WINDOW FOR GROUP 1 CONFIGURATION 1						
		MOS	24 (s)	16-FEB-2010			
18-JUL-2007			6000	3417:51			
		AFL		829			
SB 737-57-1250	INSPECTION OF SECONDARY FUEL VAPOR-BARRIER APPLICATION ON THE WING CENTER SECTION, SERVICE BULLETIN						
		MOS	48 (s)				
07-FEB-2002							
SB 737-57-1250 R1	INSPECTION OF THE SECONDARY FUEL VAPOR-BARRIER APPLICATION ON THE WING CENTER SECTION TOP PANEL AND FRONT SPAR, SERVICE BULLETIN						COMPLIED WITH
		MOS	48 (s)	28-SEP-2009			
04-SEP-2003				3378:04			
		AFL		812			
SB 737-57-1250 R2	INSPECTION OF THE SECONDARY FUEL VAPOR-BARRIER APPLICATION ON THE WING CENTER SECTION TOP PANEL AND FRONT SPAR, SERVICE BULLETIN						COMPLIED WITH
		MOS		28-SEP-2009			
28-NOV-2006			- (s)	3378:04			
		AFL		812			
SB 737-57-1253	CENTER WING REAR SPAR - STIFFENER MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-DEC-1999							
		AFL	4500 (s)				
SB 737-57-1253 R1	CENTER WING REAR SPAR - STIFFENER MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-JAN-2001							
		AFL	4500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57-1255	WING - LEFT SIDE MIDSPAR LOWER PANEL REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-JUN-2001			- (s)				
SB 737-57-1255 R1	LEFT SIDE MIDSPAR LOWER PANEL REPLACEMENT, SERVICE BULLETIN						
		MOS					
11-MAR-2004			-				
SB 737-57-1264	FLAP CARRIAGE BUSHING REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-MAY-2001			- (s)				
SB 737-57-1268	WINGS-LOWER WING SKIN PANELS-INSTALLATION OF THE RUB STRIPS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-JUN-2002			- (s)				
SB 737-57-1268 R1	WING LOWER SKIN PANELS INSTALLATION OF THE RUB STRIPS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-OCT-2002			- (s)				
SB 737-57-1272	OUTBOARD KRUEGER FLAP INSPECTION, REPAIR, AND PREVENTIVE MODIFICATION, SERVICE BULLETIN						
		MOS					
24-JUN-2004			- (s)				
SB 737-57-1272 PART 1	INSPECT OUTBOARD KRUEGER FLAP INSPECTION, REPAIR, AND PREVENTIVE MODIFICATION, SERVICE BULLETIN						
		MOS					
24-JUN-2004			3000 (s)				
SB 737-57-1272 PART 2	MODIFICATION OUTBOARD KRUEGER FLAP INSPECTION, REPAIR, AND PREVENTIVE MODIFICATION, SERVICE BULLETIN / REPLACEMENT						
		MOS					
24-JUN-2004			-				
SB 737-57-1275	LOWER WING SKIN PANEL - NACELLE SUPPORT FITTINGS ATTACHMENT FASTENERS INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-SEP-2003			30000 (s)				
		AFL	30000				
SB 737-57-1275 R1	LOWER WING SKIN PANEL - NACELLE SUPPORT FITTINGS ATTACHMENT FASTENERS INSPECTION AND REPLACEMENT, SERVICE BULLETIN						- REF: REV.3
		MOS					
18-AUG-2005			30000 (s)				
		AFL	30000				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57-1275 R2	LOWER WING SKIN PANEL - NACELLE SUPPORT FITTINGS ATTACHMENT FASTENERS INSPECTION AND REPLACEMENT, SERVICE BULLETIN						- REF: REV.3
		MOS					
12-JUL-2006			- (s)				
SB 737-57-1275 R3	LOWER WING SKIN PANEL - NACELLE SUPPORT FITTINGS ATTACHMENT FASTENERS INSPECTION AND REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - IAW THE AD 2005-24-03R1
		MOS			24-AUG-2007		
17-OCT-2006			- (s)		2968:28		
		AFL			699		
SB 737-57-1278	OUTBOARD FLAP BELLCRANK ASSEMBLY INSPECTION AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-DEC-2004			-				
SB 737-57-1278 R1	WINGS - TRAILING EDGE AND TRAILING EDGE DEVICES - OUTBOARD FLAP BELLCRANK ASSEMBLY INSPECTION AND MODIFICATION., SERVICE BULLETIN						
		MOS					
21-SEP-2006			-				
SB 737-57-1278 R2	WINGS - TRAILING EDGE AND TRAILING EDGE DEVICES - OUTBOARD FLAP BELLCRANK ASSEMBLY INSPECTION AND MODIFICATION., SERVICE BULLETIN						
		MOS					
04-JUN-2007			-				
SB 737-57-1281	REPAIR OF INBOARD MAIN FLAP UPPER SKIN AND MODIFICATION OF NUTPLATE STRIP ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JUL-2004			-				
SB 737-57-1284	WINGS - TRAILING EDGE AND TRAILING EDGE DEVICES - INSPECTION, REPAIR / MODIFICATION - WING BUTTOCK LINE 147 TO WING BUTTOCK LINE 201, SERVICE BULLETIN						
		MOS					
09-APR-2007			-				
SB 737-57-1285	WINGS - WING STRINGERS - INSTALL STRINGERS 7 AND 9 REINFORCEMENT, SERVICE BULLETIN						
		MOS					
			-				
SB 737-57-1285 R1	WINGS - WING STRINGERS - INSTALL STRINGERS 7 AND 9 REINFORCEMENT, SERVICE BULLETIN						
		MOS					
			-				
SB 737-57-1286	WINGS - CENTER - REAR SPAR VAPOR BARRIER - INSPECTION, REPAIR AND MODIFICATION., SERVICE BULLETIN						- INFORMATION REFER TO REV.1
		MOS					
03-APR-2006							
		AFL	5500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57-1286 R1	WINGS - CENTER WING - REAR SPAR VAPOR BARRIER - INSPECTION, REPAIR AND MODIFICATION, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY GENERAL
		MOS		28-SEP-2009		RECURRING	
26-JUL-2007				3378:04			
		AFL	5500	812	**6312**		
SB 737-57-1288	TRAILING EDGE FLAP - NUMBER 3 AND NUMBER 6 TAILCONE ASSEMBLIES - INSPECTION AND REPAIR, SERVICE BULLETIN						
		MOS					
30-MAR-2007							
		AFL	5000 (s)				
SB 737-57-1288 R1	WINGS - TRAILING EDGE FLAP - NUMBER 3 AND NUMBER 6 TAILCONE ASSEMBLIES - INSPECTION AND REPAIR, SERVICE BULLETIN						
		MOS					
03-JUN-2008							
		AFL	5000 (s)				
SB 737-57-1293	LEADING EDGE AND LEADING EDGE DEVICES - FUEL DRAIN PATH MODIFICATION, SERVICE BULLETIN						
		MOS	24 (s)				
13-NOV-2008							
SB 737-57-1293 R1	LEADING EDGE AND LEADING EDGE DEVICES - FUEL DRAIN PATH MODIFICATION (SUPERSEDED BY SB 737-57-1293 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-57-1293 R2	WINGS - LEADING EDGE AND LEADING EDGE DEVICES - FUEL DRAIN PATH MODIFICATION (SUPERSEDED BY SB 737-57-1293 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-57-1293 R3	WINGS - LEADING EDGE AND LEADING EDGE DEVICES - FUEL DRAIN PATH MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
28-SEP-2011							
SB 737-57-1295	WINGS - TRAILING EDGE AND TRAILING EDGE DEVICES - WING INBOARD FIXED TRAILING EDGE UPPER PANEL BULB SEAL CHAFING ON WING-TO-BODY FAIRING PANEL - INSPECTION, REPAIR AND MODIFICATION., SERVICE BULLETIN						
		MOS	12 (s)				
04-JUN-2007			4500				
SB 737-57-1300	WINGS - TRAILING EDGE FLAPS - INBOARD FLAPS - INBOARD MAIN FLAP TRACKS, #4 AND #5 - INSPECTION AND EXCHANGE PROGRAM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-JUN-2007			-				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57-1300 NO 4 FLAP	DETAILED INSPECTION WINGS - TRAILING EDGE FLAPS - INBOARD FLAPS - INBOARD MAIN FLAP TRACKS, #4 AND #5 - INSPECTION AND EXCHANGE PROGRAM, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
03-FEB-2010							
		AFL	5500				
SB 737-57-1300 NO 5 FLAP	DETAILED INSPECTION WINGS - TRAILING EDGE FLAPS - INBOARD FLAPS - INBOARD MAIN FLAP TRACKS, #4 AND #5 - INSPECTION AND EXCHANGE PROGRAM, SERVICE BULLETIN					RECOMMENDED	
		MOS	24 (s)				
03-FEB-2010							
		AFL	5500				
SB 737-57-1306	INBOARD FLAPS - INBOARD MAIN FLAP TRACKS, #4 AND #5 - SUPER D-GUN COATING, DETAILED INSPECTION AND EXCHANGE PROGRAM, SERVICE BULLETIN						
		MOS	24 (s)				
26-SEP-2008							
		AFL	5500				
SB 737-57-1309	WINGS - CENTER WING BOX - FRONT SPAR SHEAR FITTING - INSPECTION, REPAIR AND PREVENTIVE MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-JAN-2011			-				
SB 737-57-1310	WINGS - CENTER WING - WING SPARS - FORWARD TRUNNION SUPPORT FITTING - FUSE PIN BORES - INSPECTION FOR CORROSION (SUPERSEDED BY SB 737-57-1310 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-57-1310 R1	WINGS - CENTER WING - WING SPARS - FORWARD TRUNNION SUPPORT FITTING - FUSE PIN BORES - INSPECTION FOR CORROSION (SUPERSEDED BY SB 737-57-1310 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-57-1310 R2	WINGS - CENTER WING - WING SPARS - FORWARD TRUNNION SUPPORT FITTING - FUSE PIN BORES - INSPECTION FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	
		MOS	120 (s)				
SB 737-57-1312	WINGS - OUTER WING - WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION, REPLACE TFE-4X WITH TFE-2X SLEEVE, SERVICE BULLETIN					RECOMMENDED	
		MOS	60 (s)				
07-SEP-2010							
SB 737-57-1316	WINGS - SPOILERS - INSTALLATION OF POLYURETHANE PROTECTIVE TAPE ON LOWER SKIN SURFACE OF INBOARD GROUND SPOILER NUMBER 6 AND 7, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-SEP-2012			-				

© Camp Systems

EFTA00618466

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1279	WINGS - CENTER AND OUTER WING - FASTENER SEALING AND WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION (SUPERSEDED BY 737-57A1279 R1), SERVICE BULLETIN					SUPERSEDED	
24-JAN-2007		MOS	-				
SB 737-57A1279 R1	CENTER AND OUTER WING - FASTENER SEALING AND WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION (SUPERSEDED BY 737-57A1279 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-	(EFF)			
SB 737-57A1279 R2	WINGS - CENTER AND OUTER WING - FASTENER SEALING AND WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION (SUPERSEDED BY SB 737-57A1279 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-57A1279 R3	WINGS - CENTER AND OUTER WING - FASTENER SEALING AND WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION, SERVICE BULLETIN						
15-FEB-2011		MOS	-	(EFF)			
SB 737-57A1279 R3 TABLE 1	PERFORM WINGS - CENTER AND OUTER WING - FASTENER SEALING AND WIRE BUNDLE SUPPORT GENERAL VISUAL INSPECTION, SERVICE BULLETIN ACTIONS REQUIRED FOR FASTENER SEALEANT IN THE FUEL TANK AND WIRE CLAMP FOR GROUP 1, 4 AIRPLANES					RECOMMENDED	
24-JAN-2007		MOS	60 (s)				
SB 737-57A1294	WINGS - WING CENTER SECTION - UPPER AND LOWER STRINGERS - DRILL START INSPECTION AND REPAIR, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY SB FOUND TO BE NA BY VARTABLE NUMBER (YG006)
		MOS		16-FEB-2010			
23-APR-2007			-	3417:51			
		AFL		829			
SB 737-57A1294 TABLE 1	DETAILED INSPECTION WINGS - WING CENTER SECTION - UPPER AND LOWER STRINGERS - DRILL START INSPECTION AND REPAIR, SERVICE BULLETIN OF THE WING CENTER SECTION LOWER AND UPPER STRINGERS TO MINIMIZE CRACK SIZE.						
23-APR-2007		MOS					
		AFL	9000		**9000**		
SB 737-57A1294 TABLE2	DETAILED INSPECTION WINGS - WING CENTER SECTION - UPPER AND LOWER STRINGERS - DRILL START INSPECTION AND REPAIR, SERVICE BULLETIN OF THE WING CENTER SECTION LOWER STRINGERS FOR SAFETY						
23-APR-2007		MOS					
		AFL	18000		**18000**		

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1302	LEADING EDGE SLATS- MAIN TRACK DOWN STOP MODIFICATION AND DETAILED INSPECTION (SUPERSEDED BY SB 737-57A1302 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-57A1302 R1	WINGS - LEADING EDGE SLATS- MAIN TRACK DOWN STOP MODIFICATION AND DETAILED INSPECTION, SERVICE BULLETIN						COMPLIED WITH - I.A.W. AD 2011-06-05 PARA (I) DETAILED INSPECTION AND MODIFICATION REPLACED ALL DOWN STOP ASSEMBLY HARDWARE-
		MOS		12-FEB-2014			
18-OCT-2010			-	3743:34			
		AFL		917			
SB 737-57A1302 R1 TABLE 1 A	REPLACE WINGS - LEADING EDGE SLATS- MAIN TRACK DOWN STOP MODIFICATION AND DETAILED INSPECTION, SERVICE BULLETIN DOWN STOP ASSEMBLY HARDWARE WITH NEW DOWN STOP ASSEMBLY HARDWARE AND DO A DETAILED INSPECTION OF THE SLAT CANS AND SLAT MAIN TRACKS FOR DEBRIS IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, STEP 2, AT ALL 16 SLAT MAIN TRACK LOCATIONS.(A) FOR ALL AIRPLANES					RECOMMENDED	COMPLIED WITH - DETAILED INSPECTION AND MODIFICATION REPLACED ALL DOWN STOP ASSEMBLY HARDWARE
		MOS		12-FEB-2014			
15-DEC-2008			- (s)	3743:34			
		AFL		917			
SB 737-57A1302 R1 TABLE 1 B	REPLACE WINGS - LEADING EDGE SLATS- MAIN TRACK DOWN STOP MODIFICATION AND DETAILED INSPECTION, SERVICE BULLETIN AFT SIDE GUIDE BOLTS WITH NEW AFT SIDE GUIDE BOLTS IN ACCORDANCE WITH PARAGRAPH 3.B., WORK INSTRUCTIONS, STEP 2, AT ALL 16 SLAT MAIN TRACK LOCATIONS.(A) FOR ALL AIRPLANES					RECOMMENDED	COMPLIED WITH - DETAILED INSPECTION AND MODIFICATION REPLACED ALL DOWN STOP ASSEMBLY HARDWARE
		MOS		12-FEB-2014			
15-DEC-2008			- (s)	3743:34			
		AFL		917			
SB 737-57A1308 R1	OUTER WING - SKINS - LOWER WING SKIN AT FUEL TANK ACCESS DOOR CUTOUT KEYWAY - INSPECTION AND CHANGE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-OCT-2009			-				
SB 737-57A1308 R1 TABLE 1.1	PERFORM OUTER WING - SKINS - LOWER WING SKIN AT FUEL TANK ACCESS DOOR CUTOUT KEYWAY - INSPECTION AND CHANGE, SERVICE BULLETIN A ONE TIME INSPECTION FOR A KEYWAY IN THE FUEL TANK ACCESS DOOR 531BB AND 631BB CUTOUTS					RECOMMENDED	
		MOS					
01-OCT-2009							
		AFL	7500 (s)				
SB 737-57A1308 R1 TABLE 1.2	PERFORM OUTER WING - SKINS - LOWER WING SKIN AT FUEL TANK ACCESS DOOR CUTOUT KEYWAY - INSPECTION AND CHANGE, SERVICE BULLETIN A ONE TIME HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION OF THE FUEL TANK ACCESS DOOR 531BB CUTOUT KEYWAY AND FUEL TANK ACCESS DOOR 631BB CUTOUT KEYWAY ON THE LEFT AND RIGHT WING					RECOMMENDED	
		MOS					
01-OCT-2009							
		AFL	7500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1314	WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-57A1314 R1	WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JUL-2014			- (s)				
SB 737-57A1314 R1 TBL 1.1 LH	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN FOR LOOSE FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (ALL AIRPLANES)					RECOMMENDED	
		MOS					
		AFL	32000 (s)				
SB 737-57A1314 R1 TBL 1.1 RH	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN FOR LOOSE FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (ALL AIRPLANES)					RECOMMENDED	
		MOS					
		AFL	32000 (s)				
SB 737-57A1314 R1 TBL 1.2 LH	RETORQUE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT / ACCOMPLISH THE MODIFICATION (IF ANY LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE LEFT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 1.3 RH	RETORQUE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT / ACCOMPLISH THE MODIFICATION (IF ANY LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE RIGHT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 1.4 LH	DO WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN ONE OF THE OPTIONS THAT FOLLOW: OPTION 1: ACCOMPLISH THE MODIFICATION / OPTION 2: RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (IF NO LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE LEFT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				

© Camp Systems

EFTA00618469

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1314 R1 TBL 1.5 RH	DO WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN ONE OF THE OPTIONS THAT FOLLOW: OPTION 1: ACCOMPLISH THE MODIFICATION / OPTION 2: RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (IF NO LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE RIGHT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 1.6	REPLACE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN EACH PART THAT HAS A CRACK OR WEAR OR CONTACT BOEING FOR A REPAIR AND DO THE REPAIR (IF ANY CRACK OR WEAR FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION THAT CANNOT BE REMOVED BY OVERSIZING THE TORQUE TUBE ATTACHMENT HOLE TO SECOND OVERSIZE)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 1.8	REPLACE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE INBOARD CARRIAGE OR CONTACT BOEING FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (IF ANY CHAFING OR FRETTING FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3 B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION THAT IS DEEPER THAN 0.020 INCH)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 1.9	WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN BLEND THE INBOARD CARRIAGE TO REMOVE THE CHAFING AND FRETTING (IF ANY CHAFING OR FRETTING FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION UP TO A MAXIMUM DEPTH OF 0.020 INCH)					RECOMMENDED	
		MOS					
15-JUL-2014			BF/F (s)				
SB 737-57A1314 R1 TBL 2.01 LH	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN FOR LOOSE FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (ALL AIRPLANES)					RECOMMENDED	
		MOS					
		AFL	11000 (s)				
SB 737-57A1314 R1 TBL 2.01 RH	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN FOR LOOSE FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (ALL AIRPLANES)					RECOMMENDED	
		MOS					
		AFL	11000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1314 R1 TBL 2.02 LH	DETAIL INSPECTION WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN OF THE INBOARD CARRIAGE FOR CHAFING AND FRETTING / RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT / ACCOMPLISH THE MODIFICATION (IF ANY LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE LEFT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				
SB 737-57A1314 R1 TBL 2.03 LH	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE MODIFICATION (IF ANY CHAFING OR FRETTING FOUND BY DETAILED INSPECTION OF INBOARD CARRIAGE OF THE LEFT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				
SB 737-57A1314 R1 TBL 2.05 RH	DETAIL INSPECTION WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN OF THE INBOARD CARRIAGE FOR CHAFING AND FRETTING / RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT / ACCOMPLISH THE MODIFICATION (IF ANY LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE RIGHT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				
SB 737-57A1314 R1 TBL 2.06 RH	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE MODIFICATION (IF ANY CHAFING OR FRETTING FOUND BY DETAILED INSPECTION OF INBOARD CARRIAGE OF THE RIGHT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				
SB 737-57A1314 R1 TBL 2.08 LH	DO WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN ONE OF THE OPTIONS THAT FOLLOW: OPTION 1: ACCOMPLISH THE MODIFICATION / OPTION 2: RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (IF NO LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE LEFT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				
SB 737-57A1314 R1 TBL 2.09 RH	DO WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN ONE OF THE OPTIONS THAT FOLLOW: OPTION 1: ACCOMPLISH THE MODIFICATION / OPTION 2: RE-TORQUE THE INBOARD FOUR FASTENERS AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT (IF NO LOOSE FASTENER FOUND AT THE INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT OF THE RIGHT WING INBOARD FLAP ASSEMBLY)					RECOMMENDED	
		MOS					
	15-JUL-2014		BF/F (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2.10 737-57A1314 R1 TBL	REPLACE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN EACH PART THAT HAS A CRACK OR WEAR OR CONTACT BOEING FOR A REPAIR AND DO THE REPAIR (IF ANY CRACK OR WEAR FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION THAT CANNOT BE REMOVED BY OVERSIZING THE TORQUE TUBE ATTACHMENT HOLE TO SECOND OVERSIZE)	MOS			15-JUL-2014	RECOMMENDED	
			BF/F (s)				
SB 2.12 737-57A1314 R1 TBL	REPLACE WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN THE INBOARD CARRIAGE OR CONTACT BOEING FOR REPAIR INSTRUCTIONS AND DO THE REPAIR (IF ANY CHAFING OR FRETTING FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION THAT IS DEEPER THAN 0.020 INCH)	MOS			15-JUL-2014	RECOMMENDED	
			BF/F (s)				
SB 2.13 737-57A1314 R1 TBL	WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION, SERVICE BULLETIN BLEND THE INBOARD CARRIAGE TO REMOVE THE CHAFING AND FRETTING (IF ANY CHAFING OR FRETTING FOUND DURING ACCOMPLISHMENT OF PARAGRAPH 3.B., WORK INSTRUCTIONS, PART 6 - LEFT WING - MODIFICATION OR PART 7 - RIGHT WING - MODIFICATION UP TO A MAXIMUM DEPTH OF 0.020 INCH)	MOS			15-JUL-2014	RECOMMENDED	
			BF/F (s)				
SB 1.1 737-57A1314 TABLE	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN (REQUIRED MINIMUM FOR SAFETY)	MOS				SUPERSEDED	
			- (s)				
SB 1.2 737-57A1314 TABLE	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN THE MODIFICATION FOR LEFT WING (REQUIRED MINIMUM FOR SAFETY)	MOS				SUPERSEDED	
			- (s)				
SB 1.3 737-57A1314 TABLE	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN THE MODIFICATION FOR RIGHT WING (REQUIRED MINIMUM FOR SAFETY)	MOS				SUPERSEDED	
			- (s)				
SB 2.1 737-57A1314 TABLE	TORQUE CHECK WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN (RECOMMENDED ECONOMIC INSPECTION)	MOS				SUPERSEDED	
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-57A1314 TABLE 2.2	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN THE MODIFICATION FOR LEFT WING (RECOMMENDED ECONOMIC INSPECTION)	MOS	- (s)			SUPERSEDED	
SB 737-57A1314 TABLE 2.4	ACCOMPLISH WINGS - TRAILING EDGE FLAPS - INBOARD FLAP ASSEMBLY - INBOARD CARRIAGE TO TORQUE TUBE ATTACHMENT - INSPECTION AND MODIFICATION (SUPERSEDED BY SB 737-57A1314 R1), SERVICE BULLETIN THE MODIFICATION FOR RIGHT WING (RECOMMENDED ECONOMIC INSPECTION)	MOS	- (s)			SUPERSEDED	
SB 737-71-1422	CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN	MOS	- (s)	17-OCT-2000	21-JUN-1999	RECOMMENDED	COMPLIED WITH - C/W
SB 737-71-1422 R1	CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN	MOS	- (s)		02-NOV-2000	RECOMMENDED	
SB 737-71-1422 R2	CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN	MOS	- (s)		15-FEB-2001	RECOMMENDED	
SB 737-71-1422 R3	CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN	MOS	- (s)		12-FEB-2002		
SB 737-71-1464	DRAIN TUBE REPLACEMENT, ENGINE FUEL PUMP PAD, SERVICE BULLETIN	MOS	-		02-OCT-2003	RECOMMENDED	
SB 737-71-1551 R1	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES (SUPERSEDED BY SB 737-71-1551 R2), SERVICE BULLETIN	MOS	-			SUPERSEDED	
SB 737-71-1582	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC/3 TECHNOLOGY INSERTION PROGRAM BASE ENGINES (SUPERSEDED BY SB 737-71-1582 R1), SERVICE BULLETIN	MOS	-			SUPERSEDED	

© Camp Systems

EFTA00618473

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71-1582 R1	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC/3 TECHNOLOGY INSERTION PROGRAM BASE ENGINES (SUPERSEDED BY SB 737-71-1582 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1582 R2	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC/3 TECHNOLOGY INSERTION PROGRAM BASE ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS	-		13-JAN-2012		
SB 737-71-1588	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN						
		MOS	-		02-AUG-2007		
SB 737-71-1588 R1	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN						
		MOS	-		15-AUG-2007		
SB 737-71-1588 R2	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN						
		MOS	-		17-DEC-2007		
SB 737-71-1588 R3	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN						
		MOS	-		24-DEC-2007		
SB 737-71-1588 R4	INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN						
		MOS	-		18-JUL-2008		

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71-1588 R5	INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES (SUPERSEDED BY SB 737-71-1588 R6), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1588 R6	POWER PLANT - GENERAL - INTERMIX ONE OR SUBSTITUTE ANY COMBINATION OF CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC)/3 TECHNOLOGY INSERTION PROGRAM ENGINES OR CFM56-7B HIGH PRESSURE COMPRESSOR AND/OR HIGH PRESSURE TURBINE TECHNOLOGY INSERTION KIT ENGINES FOR THE TWO CFM56-7B SAC BASE ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	07-DEC-2011						
SB 737-71-1603	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF THE CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B26/3 TO 7B27/3 BUMP AND RETURN TO 7B26/3 (SUPERSEDED BY SB 737-71-1603 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1603 R1	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF THE CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B26/3 TO 7B27/3 BUMP AND RETURN TO 7B26/3 (SUPERSEDED BY SB 737-71-1603 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1603 R2	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF THE CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B26/3 TO 7B27/3 BUMP AND RETURN TO 7B26/3 (SUPERSEDED BY SB 737-71-1603 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1603 R3	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF THE CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B26/3 TO 7B27/3 BUMP AND RETURN TO 7B26/3 (SUPERSEDED BY SB 737-71-1603 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1603 R4	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF THE CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B26/3 TO 7B27/3 BUMP AND RETURN TO 7B26/3 (SUPERSEDED BY SB 737-71-1603 R5), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-71-1608	INSPECTION AND REPAIR OF THE ENGINE BUILD UP BRACKETS TO PREVENT DAMAGE TO THE ENGINE FAN CASE, SERVICE BULLETIN					RECOMMENDED	
		MOS	-				
	02-OCT-2009						

© Camp Systems

EFTA00618475

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71-1625	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF CFM56-7B ENGINES FROM CFM56-7B24 TO CFM56-7B26/B2 THRUST RATING OR FROM CFM56-7B24/3 TO CFM56-7B26/3B2 OR CFM56-7B26/3B2F THRUST RATING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	28-JUL-2010		-				
SB 737-71-1634	POWER PLANT - GENERAL - CHANGE THE OPERATIONAL THRUST RATING OF CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B27/3 TO 7B24/3 OR 7B26/3, OR FROM 7B26/3 TO 7B24/3 (SUPERSEDED BY SB 737-71-1634 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1634 R1	POWER PLANT - GENERAL - CHANGE THE OPERATIONAL THRUST RATING OF CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B27/3 TO 7B24/3 OR 7B26/3, OR FROM 7B26/3 TO 7B24/3 (SUPERSEDED BY SB 737-71-1634 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1634 R2	POWER PLANT - GENERAL - CHANGE THE OPERATIONAL THRUST RATING OF CFM56-7B SAC/3 (TECH INSERTION) ENGINES FROM 7B27/3 TO 7B24/3 OR 7B26/3, OR FROM 7B26/3 TO 7B24/3, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	15-DEC-2010		-				
SB 737-71-1658	POWER PLANT - CHANGE ONE OR TWO CFM56-7BE ENGINES FOR ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES (SUPERSEDED BY SB 737-71-1658 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1658 R1	POWER PLANT - CHANGE ONE OR TWO CFM56-7BE ENGINES FOR ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES (SUPERSEDED BY SB 737-71-1658 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1658 R2	POWER PLANT - CHANGE ONE OR TWO CFM56-7BE ENGINES FOR ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	08-DEC-2011		-				
SB 737-71-1673	POWER PLANT - CHANGE ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES FOR ONE OR TWO CFM56-7BE ENGINES (SUPERSEDED BY SB 737-71-1673 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				

© Camp Systems

EFTA00618476

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71-1673 R1	POWER PLANT - CHANGE ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES FOR ONE OR TWO CFM56-7BE ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-DEC-2011			-				
SB 737-71-1674	POWER PLANT - CHANGE ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES FOR ONE OR TWO CFM56-7BE ENGINES (SUPERSEDED BY SB 737-71-1674 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1674 R1	POWER PLANT - CHANGE ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES FOR ONE OR TWO CFM56-7BE ENGINES (SUPERSEDED BY SB 737-71-1674 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1674 R2	POWER PLANT - CHANGE ONE OR ANY COMBINATION OF TWO CFM56-7B SINGLE ANNULAR COMBUSTOR (SAC) ENGINES OR CFM56-7B/3 SAC ENGINES FOR ONE OR TWO CFM56-7BE ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-DEC-2011			-				
SB 737-71-1675	POWER PLANT - CHANGE TWO CFM56-7B/2 DUAL ANNULAR COMBUSTOR (DAC) ENGINES FOR TWO CFM56-7BE ENGINES (SUPERSEDED BY SB 737-71-1675 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1675 R1	POWER PLANT - CHANGE TWO CFM56-7B/2 DUAL ANNULAR COMBUSTOR (DAC) ENGINES FOR TWO CFM56-7BE ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-DEC-2011			-				
SB 737-71-1682	POWER PLANT - POWER PLANT - B1 FLANGE INSPECTION (SUPERSEDED BY SB 737-71-1682 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1682 R1	POWER PLANT - POWER PLANT - B1 FLANGE INSPECTION (SUPERSEDED BY SB 737-71-1682 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1682 R2	POWER PLANT - POWER PLANT - B1 FLANGE INSPECTION (SUPERSEDED BY SB 737-71-1682 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-71-1682 R3	POWER PLANT - POWER PLANT - B1 FLANGE INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-MAR-2014			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71-1708	POWER PLANT - POWER PLANT - CHANGE OPERATIONAL THRUST RATING OF CFM56-7B ENGINES FROM 7B22 TO 7B24 AND RETURN TO 7B22, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-DEC-2010			-				
SB 737-71-1709	POWER PLANT - POWER PLANT - CHANGE THE OPERATIONAL THRUST RATING OF TWO CFM56-7B ENGINES FROM 7B26 TO 7B27 AND RETURN TO 7B26, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-JAN-2011			-				
SB 737-71-1717	POWER PLANT - ENGINE COWLING - HEAT RESISTANT ALUMINIZED PRIMER INSTALLATION TO THE LIPSKIN OF THE ENGINE INLET COWL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-SEP-2013			-				
SB 737-71-1725	POWER PLANT - POWER PLANT - INSTALLATION OF ENGINE OWNERSHIP PLACARD, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-NOV-2011			-				
SB 737-71A1462	AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION, SERVICE BULLETIN						
		DAYS	60 (s)				
29-AUG-2002							
SB 737-71A1462 R1	POWER PLANT-ENGINE MOUNTS-AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION, SERVICE BULLETIN						
		DAYS	90 (s)				
29-AUG-2002							
SB 737-71A1462 R2	AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-MAY-2003			-				
SB 1 737-71A1462 R2 PART	INSPECT AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN FOR CORRECT INSTALLATION					RECOMMENDED	
		MOS					
29-MAY-2003			-				
SB 2 737-71A1462 R2 PART	APPLY AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN PERMANENT MARKINGS					RECOMMENDED	
		MOS					
29-MAY-2003			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-71A1462 R3	AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN						COMPLIED WITH - PERFORMED UNDER WO GVBBJ206
		MOS		26-OCT-2011			
20-MAY-2004			-	3573:06			
		AFL		872			
SB 737-71A1462 R3 PART 1	INSPECT AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN FOR CORRECT INSTALLATION						COMPLIED WITH - PERFORMED UNDER WO GVBBJ206
		MOS		26-OCT-2011			
20-MAY-2004			-	3573:06			
		AFL		872			
SB 737-71A1462 R3 PART 2	INSTALL AFT ENGINE MOUNT, CENTER LINK ASSEMBLY INSTALLATION INSPECTION AND IDENTIFICATION OF PARTS, SERVICE BULLETIN PERMANENTLY MARKED MOUNT						COMPLIED WITH - PERFORMED UNDER WO GVBBJ206
		MOS		26-OCT-2011			
20-MAY-2004			-	3573:06			
		AFL		872			
SB 737-73-1014	ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W
		MOS		13-SEP-1999			
01-JUL-1999			- (s)				
SB 737-73-1014 R1	ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUL-2000			- (s)				
SB 737-73A-026	, SERVICE BULLETIN						
		MOS		13-SEP-1999			
			- (s)				
SB 737-73A1011	ENGINE FUEL SUPPLY HOSE (SUPERSEDED BY SB 737-73A1011 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-73A1011 R1	ENGINE FUEL SUPPLY HOSE (SUPERSEDED BY SB 737-73A1011 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-73A1011 R2	ENGINE FUEL SUPPLY HOSE, SERVICE BULLETIN					RECOMMENDED	
		MOS		19-APR-2002			
13-JUL-2000			-	988:36			
		AFL		250			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-73A1016	ELECTRONIC ENGINE CONTROL SOFTWARE CHANGE, SERVICE BULLETIN						COMPLIED WITH
		MOS	6 (s)	22-AUG-2003			
20-FEB-2003				1342			
		AFL		351			
SB 737-73A1016 R1	ELECTRONIC ENGINE CONTROL-SOFTWARE CHANGE, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2003			
08-MAY-2003			-	1342			
		AFL		351			
SB 737-77-1056	AIRBORNE VIBRATION MONITORING SYSTEM UNIVERSAL SIGNAL CONDITIONER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-AUG-2001			- (s)				
SB 737-77-1069 R2	AIRBORNE VIBRATION MONITORING (AVM) SYSTEM - REPLACE CONDITIONER UNIT FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
10-DEC-2008			-				
SB 737-78-1063 R2	EXHAUST - THRUST REVERSER - INNER WALL BLANKET INSULATION CHANGE, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS		28-MAR-2014			
07-OCT-1999			-				
SB 737-78-1067	THRUST REVERSER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-AUG-2000			3000 (s)	44			
		AFL	2100	38			
SB 737-78-1069	EXHAUST - THRUST REVERSER - INSULATION BLANKET MODIFICATION, SERVICE BULLETIN						
		MOS					
28-FEB-2002			- (s)				
SB 737-78-1069 R1	EXHAUST - THRUST REVERSER - INSULATION BLANKET MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JUN-2002			-				
SB 737-78-1069 R2	INSULATION BLANKET MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-FEB-2003			-				
SB 737-78-1069 R3	INSULATION BLANKET MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-AUG-2004			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1069 R4	EXHAUST - THRUST REVERSER - INSULATION BLANKET MODIFICATION, SERVICE BULLETIN						
		MOS					
16-JUN-2005			-				
SB 737-78-1071	REPLACE THRUST REVERSER EXHAUST FASTNERS FOR TRACKING SEALS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-DEC-2001			- (s)				
SB 737-78-1071 R1	THRUST REVERSER - REPLACE FASTNERS FOR TRACK FAIRING SEALS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-MAY-2002			- (s)				
SB 737-78-1072	EXHAUST - THRUST REVERSER - INSPECT/CHANGE CASCADE SUPPORT RING TO CORRECTLY INSTALL BARREL NUTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-MAR-2002			- (s)				
SB 737-78-1073	INSPECTION AND MODIFICATION OR REPLACEMNT OF BUSHINGS IN THE ATTACH FITTING ASSEMBLIES FOR THE DRAG LINKS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS			07-SEP-2005		
09-DEC-2004			-		2202:21		
		AFL			541		
SB 737-78-1073 R1	EXHAUST - THRUST REVERSER - BLOCKED DOORS - INSPECTION AND MODIFICATION OR REPLACEMENT OF BUSHINGS IN THE ATTACH FITTING ASSEMBLIES FOR THE DRAG LINKS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-APR-2005			-				
SB 737-78-1073 R2	EXHAUST - THRUST REVERSER - BLOCKERS DOORS - INSPECTION AND MODIFICATION OR REPLACEMENT OF BUSHINGS IN THE ATTACH FITTING ASSEMBLIES FOR THE DRAG LINKS, SERVICE BULLETIN						
		MOS					
12-JAN-2006			-				
SB 737-78-1073 R3	EXHAUST - THRUST REVERSER - BLOCKER DOORS - INSPECTION AND MODIFICATION OR REPLACEMENT OF BUSHINGS IN THE ATTACH FITTING ASSEMBLIES FOR THE DRAG LINKS, SERVICE BULLETIN						
		MOS					
20-JUL-2006			-				
SB 737-78-1073 R4	EXHAUST - THRUST REVERSER - BLOCKER DOORS - INSPECTION AND MODIFICATION OR REPLACEMENT OF BUSHINGS IN THE ATTACH FITTING ASSEMBLIES FOR THE DRAG LINKS, SERVICE BULLETIN						
		MOS					
16-NOV-2006			-				
SB 737-78-1074	EXHAUST - THRUST REVERSER - BLOCKER DOOR AERO/FIRE SEAL REPLACEMENT, SERVICE BULLETIN						
		MOS	24 (s)				
07-APR-2005							
		AFL	4000				

© Camp Systems

EFTA00618481

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1074 R1	EXHAUST - THRUST REVERSER - BLOCKER DOOR AERO/FIRE SEAL REPLACEMENT, SERVICE BULLETIN						
		MOS	60 (s)				
15-SEP-2005							
		AFL	8200				
SB 737-78-1075	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND REPLACEMENT OF THE FIRE SEAL ON EACH THRUST REVERSER HALF (SUPERSEDED BY SB 737-78-1075 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-78-1075 R1	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND REPLACEMENT OF THE FIRE SEAL ON EACH THRUST REVERSER HALF (REPLACED BY 737-78-1086 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-78-1076 R1	EXHAUST - THRUST REVERSER SYSTEM - REPLACEMENT OF CASCADE ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-MAR-2010			-				
SB 737-78-1078	EXHAUST - THRUST REVERSER INDICATING SYSTEM - ADDITION OF A RESISTOR TO THE THRUST REVERSER SYNC LOCK TIME DELAY CIRCUIT, SERVICE BULLETIN						
		MOS					
17-AUG-2006			-				
SB 737-78-1078 R1	EXHAUST - THRUST REVERSER INDICATING SYSTEM - ADDITION OF A RESISTOR TO THE THRUST REVERSER SYNC LOCK TIME DELAY CIRCUIT, SERVICE BULLETIN						
		MOS					
30-MAY-2007			-				
SB 737-78-1078 R2	EXHAUST - THRUST REVERSER INDICATING SYSTEM - ADDITION OF A RESISTOR TO THE THRUST REVERSER SYNC LOCK TIME DELAY CIRCUIT, SERVICE BULLETIN						
		MOS					
19-FEB-2008			-				
SB 737-78-1078 R3	THRUST REVERSER INDICATING SYSTEM - ADDITION OF A RESISTOR TO THE THRUST REVERSER SYNC LOCK TIME DELAY CIRCUIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-OCT-2009			-				
SB 737-78-1079	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION, REPAIR, AND COOLING HOLE MODIFICATION, SERVICE BULLETIN						
		MOS					
06-AUG-2007			-				

© Camp Systems

EFTA00618482

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1079 R1	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION, REPAIR, AND COOLING HOLE MODIFICATION 9SUPERSEDED BY 737-78-1079 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
17-DEC-2007			-				
SB 737-78-1079 R2	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION, REPAIR, AND COOLING HOLE MODIFICATION (SUPERSEDED BY SB 737-78-1079 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-78-1079 R3	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION, REPAIR, AND COOLING HOLE MODIFICATION, SERVICE BULLETIN						
		MOS					
			-				
SB 737-78-1082	EXHAUST - THRUST REVERSER - INSTALLATION OF A COOLING HOLE AND BUSHING, APPLY SEALANT AND INSTALL FLANGE INSULATION ASSEMBLIES ON THE THRUST REVERSERS (SUPERSEDED BY SB 737-78-1082 R1), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - I.A.W. AD 2012-05-02 PARA (G) - FOUND SATISFACTORY - TOP KIT RETROFIT THR / 002A0004-16
		MOS			12-FEB-2014		
			- (s)		3743:34		
		AFL			917		
SB 737-78-1082 R1	EXHAUST - THRUST REVERSER - INSTALLATION OF A COOLING HOLE AND BUSHING, APPLY SEALANT AND INSTALL FLANGE INSULATION ASSEMBLIES ON THE THRUST REVERSERS, SERVICE BULLETIN					RECOMMENDED	DECLINED - NO MORE WORK IS NECESSARY ON THE AIRPLANE(S) CHANGED IN ACCORDANCE WITH THE ORIGINAL ISSUE OF THIS SERVICE BULLETIN.
		MOS			12-FEB-2014		
10-MAY-2012			- (s)		3743:34		
		AFL			917		
SB 737-78-1083	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS (SUPERSEDED BY SB 737-78-1083 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				
SB 737-78-1083 R1	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS (SUPERSEDED BY SB 737-78-1083 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 1 737-78-1083 R1 TABLE	DEATILED INSPECTION EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS (SUPERSEDED BY SB 737-78-1083 R2), SERVICE BULLETIN OF THE THRUST REVERSER HYDRAULIC ACTUATOR ROD ENDS AND ACTUATOR ATTACH FITTINGS					SUPERSEDED	
		MOS					
01-JAN-2000			- (s)				

© Camp Systems

EFTA00618483

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1083 R2	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
	13-JUN-2014		-				
SB 737-78-1083 R2 TBL 1.01	DETAILED INSPECTION EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN FOR DAMAGE ON THE HYDRAULIC ACTUATOR ROD END ASSEMBLIES AND A DETAILED INSPECTION FOR DAMAGE ON THE ACTUATOR ATTACH FITTINGS (FOR ALL AIRPLANES) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	30-JUN-2010		7500 (s)				
SB 737-78-1083 R2 TBL 1.03	DO EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN DETAILED INSPECTIONS FOR DAMAGE ON THE HYDRAULIC ACTUATOR ROD END ASSEMBLIES (IF ANY DAMAGE FOUND ON THE HYDRAULIC ACTUATOR ROD END ASSEMBLIES) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	13-JUN-2014		BF/F				
SB 737-78-1083 R2 TBL 1.04	REPAIR EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN OR REPLACE THE HYDRAULIC ACTUATOR ROD END BODY (IF ANY DAMAGE FOUND ON HYDRAULIC ACTUATOR ROD END BODY AND THE DAMAGE IS LESS THAN OR EQUAL TO THE REPAIR LIMITS) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	13-JUN-2014		BF/F				
SB 737-78-1083 R2 TBL 1.05	REPLACE EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN HYDRAULIC ACTUATOR ROD END ASSEMBLY (IF ANY DAMAGE FOUND ON HYDRAULIC ACTUATOR ROD END BODY AND THE DAMAGE IS GREATER THAN THE REPAIR LIMITS) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	13-JUN-2014		BF/F				
SB 737-78-1083 R2 TBL 1.06	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN RETURN SPHERICAL BEARING TO SERVICE (IF WEAR LESS THAN OR EQUAL TO SERVICEABLE LIMITS FOUND ON SPHERICAL BEARING ON THE HYDRAULIC ACTUATOR ROD END) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	13-JUN-2014		BF/F				
SB 737-78-1083 R2 TBL 1.07	REPLACE EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN THE SPHERICAL BEARING (IF WEAR GREATER THAN SERVICEABLE LIMITS FOUND ON SPHERICAL BEARING ON THE HYDRAULIC ACTUATOR ROD END) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
	13-JUN-2014		BF/F				

© Camp Systems

EFTA00618484

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 1.08 737-78-1083 R2 TBL	INSTALL EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN SPACER (IF NO DAMAGE FOUND ON AN ACTUATOR ATTACH FITTING) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
13-JUN-2014			BF/F				
SB 1.09 737-78-1083 R2 TBL	REPAIR EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN FITTING AND INSTALL SPACER (IF ANY DAMAGE FOUND ON ACTUATOR ATTACH FITTING AND THE DAMAGE IS LESS THAN OR EQUAL TO 0.020 INCH IN DEPTH) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
13-JUN-2014			BF/F				
SB 1.10 737-78-1083 R2 TBL	REPLACE EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN FITTING (IF ANY DAMAGE FOUND ON ACTUATOR ATTACH FITTING AND THE DAMAGE IS GREATER THAN 0.020 INCH IN DEPTH) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
13-JUN-2014			BF/F				
SB 1.11 737-78-1083 R2 TBL	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN CHANGE THE SCHEDULED MAINTENANCE PROGRAM (FOR AIRPLANES WITH WEAR SPACERS INSTALLED ON THE ACTUATOR ATTACH FITTINGS) (GROUP 1 - 2, CNF 2)					RECOMMENDED	
		MOS					
			20000 (s)				
SB 2.1 737-78-1083 R2 TBL	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION AND CHANGE TO OR REPLACEMENT OF THE THRUST REVERSER ACTUATOR ATTACH FITTING AND ACTUATOR ROD ENDS, SERVICE BULLETIN CHANGE THE SCHEDULED MAINTENANCE PROGRAM (FOR ALL AIRPLANES WITH WEAR SPACERS INSTALLED ON THE ACTUATOR ATTACH FITTINGS) (GROUP 1 - 2, CNF 1)					RECOMMENDED	
		MOS	12 (s)				
13-JUN-2014							
SB 737-78-1085	EXHAUST - THRUST REVERSER SYSTEM - CHANGE TO THE INSULATION BLANKETS ON THE THRUST REVERSERS (SUPERSEDED BY SB 737-78-1085 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-78-1085 R1	EXHAUST - THRUST REVERSER SYSTEM - CHANGE TO THE INSULATION BLANKETS ON THE THRUST REVERSERS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-DEC-2011			-				
SB 737-78-1086	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION OF THE FIRE SEAL AND INSTALLATION OF A NEW FIRE SEAL BRACKET ON THE THRUST REVERSER (SUPERSEDED BY SB 737-78-1086 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1086 R1	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION OF THE FIRE SEAL AND INSTALLATION OF A NEW FIRE SEAL BRACKET ON THE THRUST REVERSER (SUPERSEDED BY SB 737-78-1086 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-78-1086 R2	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION OF THE FIRE SEAL AND INSTALLATION OF A NEW FIRE SEAL BRACKET ON THE THRUST REVERSER , SERVICE BULLETIN						
		MOS	-				
SB 737-78-1087	REPLACEMENT OF THE LOCKOUT HANDLE ASSEMBLY ON THE THRUST REVERSER ACTUATORS (SUPERSEDED BY SB 737-78-1087 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-78-1087 R1	EXHAUST - THRUST REVERSER SYSTEM - REPLACEMENT OF THE LOCKOUT HANDLE ASSEMBLY ON THE THRUST REVERSER ACTUATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS			29-MAY-2013		
SB 737-78-1088	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION AND REPAIR (SUPERSEDED BY SB 737-78-1088 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	- (s)				
SB 737-78-1088 R1	EXHAUST - THRUST REVERSER - THRUST REVERSER INNER WALL INSPECTION AND REPAIR, SERVICE BULLETIN						
		MOS	-				
SB 737-78-1089	EXHAUST - ENGINE PRIMARY EXHAUST NOZZLE AND PLUG ASSEMBLY INSTALLATION (SUPERSEDED BY SB 737-78-1089 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS	-				
SB 737-78-1089 R1	EXHAUST - ENGINE PRIMARY EXHAUST NOZZLE AND PLUG ASSEMBLY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
		MOS			25-OCT-2013		
SB 737-78-1090	EXHAUST - THRUST REVERSER SYSTEM - INSPECTION FOR AND REMOVAL OF THE THRUST REVERSER INNER WALL COOLING HOLE BLOCKAGE, SERVICE BULLETIN						
		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 737-78-1092	EXHAUST - TURBINE EXHAUST SYSTEM - REWORK OF INTERFERENCE CONDITION AT EXHAUST NOZZLE FORWARD LABYRINTH, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-JAN-2013			-				
SB 737-SL-21-056	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-OCT-2002			- (s)				
SB 737-SL-28-044	AIRCRAFT USE OF DYED FUELS (SUPERSEDED BY SL 737-SL-28-044 REV. A), SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
SB 737-SL-30-020	WINDOW HEAT CONTROL UNIT MODIFICATION TO CORRECT A4 CIRCUIT BOARD CORROSION, SERVICE BULLETIN						
		MOS					
01-MAR-2006			-				
SB 737-SL-31-034	TAKEOFF CONFIGURATION WARNING- ALTERNATE METHOD OF COMPLIANCE A.D., SERVICE BULLETIN					OPTIONAL	
		MOS					
			-				
SB 737-SL-32-129 REV. A	NOSE GEAR LOCK VALVE MANIFOLD DUPLICATE SERIAL NUMBERS, SERVICE BULLETIN						
		MOS					
10-JUL-2006			-				
SB 737-SL-32-134 REV. A	NLG SHOCK STRUT ALTERNATE DYNAMIC SEAL, SERVICE BULLETIN						
		MOS					
10-JUL-2006			-				
SB 737-SL-32-154	MAIN LANDING GEAR ACTUATOR BARREL CRACKS FOLLOWING REPAIR PER SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-FEB-2009							
		AFL	500 (s)				
SB 737-SL-34-187	LOSS OF RELIABLE AIR DATA DUE TO ICING OF STATIC PORTS - SRP 34-0111, SERVICE BULLETIN						
		MOS					
04-JUN-2007			-				
SB 737-SL-52-046	AUXILIARY POWER UNIT (APU) ACCESS DOOR SKIN LATCH CUTOUTS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-APR-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 920-34-25	ROCKWELL COLLINS - SB 25 - GLU-920 GLOBAL LANDING UNIT (CPN 822-1152-001/002/003) GNSS RECEIVER CIRCUIT CARD A8 (CPN 828-2940-302) REDUCE OCCURRENCE OF INCORRECT GPS DATE, SERVICE BULLETIN						COMPLIED WITH
		MOS		23-FEB-2009			
03-OCT-2008			-	3353:18			
		AFL		804			
SB 964-0452-23-39	COMMUNICATION - XK516D HF RADIO SYSTEM - UNIT MODIFICATION (MOD) 48 TO XK516D1 HF TRANSCEIVER (HF TRANSCEIVER), PN 964-0452-012, -042, OR -052; INSPECTION AND REPLACEMENT OF HIGH FREQUENCY (HF) MODEM NON-CONFORMING INTEGRATED CIRCUIT (VOICE BAND ANALOG INTERFACE), SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-NOV-2013			-				
SB R1 965-0976-0XXX-34-38	, SERVICE BULLETIN						
		MOS					
			- (s)				
SB A001-25-96	, SERVICE BULLETIN						- IPECO SEATS
		MOS		13-SEP-1999			
			- (s)				
SB BBJ 28-13B	INSTALLATION OF COMPONENT IDENTIFICATIONS PLACARDS, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-25-34	REMOVAL OF CARGO COMPARTMENT LOWER BILGE INSULATION BLANKETS, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-001-K	ST00936NY-D-28-SB-001- K SFAR 88 AFS INTERNAL FUEL CELL MODIFICATION AND VALVE PLATE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH
		MOS		28-SEP-2009			
			-	3378:04			
		AFL		812			
SB BBJ-28-02	MODIFICATION OF THE FORWARD HALF TANK, INBOARD SUPPORT RAIL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-AUG-1999			- (s)				
SB BBJ-28-021-K	ST00936NY-D-28-SB-021-_K SFAR88 {AND FAR 25.981 (A) (B) (C1) (AMENDMENT 102)} AUXILIARY FUEL SYSTEM UPGRADE FOR PATS MODIFIED AIRCRAFT SERVICE BULLETIN, SERVICE BULLETIN						COMPLIED WITH
		MOS		28-SEP-2009			
			-	3378:04			
		AFL		812			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-02A	MODIFICATION OF THE FORWARD HALF TANK, INBOARD SUPPORT RAIL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-AUG-1999			- (s)				
SB BBJ-28-02B	MODIFICATION OF THE FORWARD HALF TANK, INBOARD SUPPORT RAIL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-OCT-1999			- (s)				
SB BBJ-28-02C	MODIFICATION OF THE FORWARD HALF TANK, INBOARD SUPPORT RAIL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-NOV-1999			- (s)				
SB BBJ-28-03	MODIFICATION OF THE AUXILIARY FUEL ELECTRICAL SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JUN-1999			- (s)				
SB BBJ-28-04	MODIFICATION OF THE AUXILIARY FUEL SYSTEM PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-04A	MODIFICATION OF THE AUXILIARY FUEL SYSTEM PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-AUG-1999			- (s)				
SB BBJ-28-04B	MODIFICATION OF THE AUXILIARY FUEL SYSTEM PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-APR-2000			- (s)				
SB BBJ-28-05	INSTALLATIONOF AUXILIARY FUEL SHROUD DRAIN SYSTEM FLOW RESTRICTOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JUN-1999			- (s)				
SB BBJ-28-06	MODIFICATION TO ADDED ELECTRONICS RACK FOR INCREASED LOAD CAPACITY, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-09	CONVERSION FROM AN EXISTING NINE (4FWD, 5 AFT) AFS CONFIGURATION 2-G TO AN EIGHT CELL (3 FWD, 5 AFT) AFS, CONFIGURATION 2-F, SERVICE BULLETIN						
		MOS					
			-				
SB BBJ-28-09B	CONVERSION FROM AN EXISTING NINE (4FWD, 5 AFT) AFS CONFIGURATION 2-G TO AN EIGHT CELL (3 FWD, 5 AFT) AFS, CONFIGURATION 2-F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-AUG-1999			- (s)				

© Camp Systems

EFTA00618489

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	BBJ-28-09F	CONVERSION FROM AN EXISTING NINE (4FWD, 5 AFT) AFS CONFIGURATION 2-G TO AN EIGHT CELL (3 FWD, 5 AFT) AFS, CONFIGURATION 2-F, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	29-OCT-2001			- (s)				
SB	BBJ-28-10	RELOCATION OF HOSE SHROUD CHECK VALVES, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	10-JUN-1999			- (s)				
SB	BBJ-28-108-A	AUXILIARY FUEL SYSTEM (AFS) CONVERSION FROM AN EXISTING (2M) 1 FWD 5 AFT CELL CONFIGURATION TO A (3A) 0 FWD 3 AFT CELL CONFIGURATION, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	08-MAR-2004			-				
SB	BBJ-28-11	INSTALLATION OF CARGO NET ATTACH PROVISIONS (FORWARD), SERVICE BULLETIN						
			MOS					
				- (s)				
SB	BBJ-28-13	INSTALLATION: COMPONENT IDENTIFICATION PLACARDS, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	BBJ-28-13	, SERVICE BULLETIN						- PATS SB
			MOS			13-SEP-1999		
				- (s)				
SB	BBJ-28-13A	INSTALLATION: COMPONENT IDENTIFICATION PLACARDS, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	09-AUG-1999			- (s)				
SB	BBJ-28-13B	INSTALLATION OF COMPONENT IDENTIFICATIONS PLACARDS, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	BBJ-28-16	MODIFICATION OF THE AUX FUEL HALF TANK INBOARD SUPPORT RAIL, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	BBJ-28-16A	MOUNTING OF THE AFT HALF FUEL CELL INBOARD SUPPORT RAIL AND THE ADDITION OF THE FASTENERS IN THE FLOOR BEAM REINFORCEMENT STRAPS, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	31-AUG-1999			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-18	INSPECTION/MODIFICATION OF FASTENERS ON RAIL AND FLOOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
31-AUG-1999			- (s)				
SB BBJ-28-19	MODIFICATION OF THE WIRING OF THE AUX FUEL PROCESSING UNIT, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-19A	MODIFICATION OF THE WIRING OF THE AUX FUEL PROCESSING UNIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-JUL-2001			- (s)				
SB BBJ-28-21	FUEL MIGRATION PREVENTION, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-21A	FUEL MIGRATION PREVENTION., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-21B	FUEL MIGRATION PREVENTION., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-21C	FUEL MIGRATION PREVENTION., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-21D	FUEL MIGRATION PREVENTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		28-AUG-2009			
07-SEP-2000			- (s)	3378:04			
		AFL		812			
SB BBJ-28-23	MODIFICATION TO PREVENT BATTERY DRAINING, SERVICE BULLETIN						
		MOS					
01-JAN-2000			- (s)				
SB BBJ-28-23A	MODIFICATION TO PREVENT BATTERY DRAIN, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-DEC-1999			- (s)				
SB BBJ-28-24	THE INSTALLATION OF A CLIP ASSEMBLY IN THE FORWARD CARGO COMPARTMENT TO ALLOW FOR THE PROPER REINSTALLATION OF THE FORWARD MOST CARGO NET AT THE CARGO BAY DOOR., SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-JAN-2000			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-25	INSTALLATION OF A PLATE & CHANNEL IN THE FORWARD CARGO COMPARTMENT TO ALLOW FOR THE PROPER REINSTALLATION OF THE AFT MOST CARGO NET AT THE CARGO BAY DOOR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-JAN-2000			- (s)				
SB BBJ-28-26A	CONVERSION: FROM (2 WD 5 FT) TO (1FWD 5 AFT) 6 TANK., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-26B	CONVERSION: FROM (2 WD 5 FT) TO (1FWD 5 AFT) 6 TANK., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-26C	CONVERSION: FROM A 7 TANK (2 WD 5 FT) TO A 6 TANK. (FWD 5 AFT), SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-JUN-2000			- (s)				
SB BBJ-28-30	CONVERSION OF A SEVEN TANK FUEL SYSTEM TO A SIXTANK FUEL SYSTEM, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-39E	EIGHT CELL TO SEVEN CELL CONVERSION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-JUL-2001			- (s)				
SB BBJ-28-39F	CONVERSION FROM AN EXISTING 8 TANK (3 FWD, 5 AFT) TO A 7 TANK (2 FWD, 5 AFT) AFS, CONFIGURATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
04-OCT-2001			-				
SB BBJ-28-40A	MODIFICATION TO FWD BLEED AIR., SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-40B	MODIFICATION TO FORWARD BLEED AIR, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-SEP-2000			- (s)				
SB BBJ-28-43B	FUEL LINE BRACKET MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
29-SEP-2000			- (s)				
SB BBJ-28-45A	RELOCATION OF CHECK VALVE IN MIX BAY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-SEP-2000			- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-45B	RELOCATION OF CHECK VALVE IN MIX BAY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-JUL-2001			- (s)				
SB BBJ-28-47F	CONVERSION FROM 5 TANK(1 FWD 4 AFT) TO A 4 TANK (0 FWD 4AFT) CONFIGURATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-AUG-2001			- (s)				
SB BBJ-28-56	REPLACEMENT OF THE BBJ FUELING PLACARDS, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-28-58	REPLACEMENT OF THE BBJ CARGO LOADING PLACARDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-JUL-2001			- (s)				
SB BBJ-28-61	CONVERSION FROM AN EXISTING EIGHT CELL (3 FWD 5AFT) AFS, CONFIGURATION 2-F TO A SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 2-M, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-APR-2001			- (s)				
SB BBJ-28-63C	CONVERSION FROM AN EXISTING SIX CELL (2 FWD, 4 AFT) AFS, CONFIGURATION 2-D TO A EIGHT CELL (3 FWD, 5 AFT) AFS, CONFIGURATION 2-F WITH AFT STRUCTURAL PROVISIONS PREVIOUSLY INSTALLED, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2001			-				
SB BBJ-28-67	CONVERSION FROM AN EXISTING SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 2-M TO A SEVEN CELL (2 FWD 5 AFT) AFS, CONFIGURATION 2-E., SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-DEC-2001			- (s)				
SB BBJ-28-6A	MODIFICATION TO ADDED ELECTRONICS RACK FOR INCREASED LOAD CAPACITY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-SEP-1999			- (s)				
SB BBJ-28-70	MODIFICATION OF THE EQUIPMENT EQUIPMENT RACK INSTALLED IN THE FORWARD CARGO COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-JAN-2002			-				
SB BBJ-28-73A	RELOCATION OF THE AFQP INSTALLED ON THE ELECTRICAL EQUIPMENT RACK IN THE FORWARD CARGO COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-MAY-2002			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-78-D	CONVERSION UPDATE TO SOFTWARE 2.1, SERVICE BULLETIN						COMPLIED WITH
		MOS		28-SEP-2009			
			-	3378:04			
		AFL		812			
SB BBJ-28-78A	AIRCRAFT CONVERSION TO UPDATE TO SOFTWARE 2.1 (STC: ST00936NY), SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-JUN-2002			- (s)				
SB BBJ-28-78B	AIRCRAFT CONVERSION TO UPDATE TO SOFTWARE 2.1 (AFCU/AFDU), SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-NOV-2002			- (s)				
SB BBJ-28-84A	INSTALLATION OF PRESSURE EQUALIZATION PANELS INTO EXISTING AUXILIARY FUEL SYSTEM (AFS) CONFIGURATIONS WITH ONE TANK FORWARD AND/OR TWO, THREE AND FOUR TANKS AFT., SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-OCT-2002			- (s)				
SB BBJ-28-84B	INSTALLATION OF PRESSURE EQUALIZATION PANELS, SERVICE BULLETIN						
		MOS					
31-DEC-2003			- (s)				
SB BBJ-28-84C	INSTALLATION OF PRESSURE EQUALIZATION PANELS INTO EXISTING AUXILIARY FUEL SYSTEM (AFS) CONFIGURATION WITH ONE TANK FORWARD AN/OR TWO, THREE, AND FOUR TANKS AFT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-FEB-2003			-				
SB BBJ-28-86	CONVERSION FROM AN EXISTING SIX CELL (1FWD 5 AFT), CONFIGURATION 2-M TO A NINE CELL (4 FWD 5 AFT) AFS, CONFIGURATION 2-G WITH STRUCTURAL PROVISIONS PREVIOUSLY INSTALLED. (STC: ST00936NY AMENDED JUNE 17, 2002), SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-AUG-2002			- (s)				
SB BBJ-28-86A	CONVERSION FROM AN EXISTING SIX CELL (1 FWD 5 AFT), CONFIGURATION 3-M TO A NINE CELL (4 FWD 5 AFT) AFS, CONFIGURATION 3-G WITH STRUCTURAL PROVISIONS PREVIOUSLY INSTALLED., SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-SEP-2002			- (s)				
SB BBJ-28-89D	ADDING ADDITIONAL PROVISIONS ONLY TO AN EXISITING THREE CELL (0 FWD 3 AFT) AFS, CONFIGURATION 3-A, FOR FUTURE INSTALLATION OF 2 FWD TANKS FOR A FIVE CELL (2 FWD 3 AFT) AFS, CPNFIGURATION 3-C, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JAN-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-89E	ADDING ADDITIONAL PROVISIONS ONLY TO AN EXISITING THREE CELL (0 FWD 3 AFT) AFS, CONFIGURATION 3-A, FOR FUTURE INSTALLATION OF 2 FWD TANKS FOR A FIVE CELL (2 FWD 3 AFT) AFS, CPNFIGURATION 3-C, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-FEB-2003			-				
SB BBJ-28-89F	CONVERSION OF EXISTING CONFIGURATION 3-A A THREE CELL (0 FWD 3 AFT) AFS PER STC ST00936NY TO A CONFIGURATION 3-C A FIVE CELL (2 FWD 3 AFT) AFS ALSO PER STC ST00936NY., SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-APR-2003			-				
SB BBJ-28-90	CONVERSION TO CONFIGURATION TO A FIVE CELL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-NOV-2002			-				
SB BBJ-28-90A	CONVERSION FROM AN EXISTING SEVEN CELL (2 FWD, 5 AFT) AFS, CONFIGURATION 2-E TO A FIVE CELL (1 FWD, 4 AFT) AFS, CONFIGURATION 3-K, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-DEC-2002			-				
SB BBJ-28-92	CONVERSION FROM AN EXISTING SIX CELL (1 FWD, 5 AFT) AFS, CONFIGURATION 2-M TO A SEVEN CELL (2 FWD, 5 AFT) AFS, CONFIGURATION 3-E, SERVICE BULLETIN					RECOMMENDED	
		MOS					
22-NOV-2002			-				
SB BBJ-28-92B	CONVERSION FROM AN EXISTING SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 3-M TO A SEVEN CELL (2 FWD 5 AFT) AFS, CONFIGURATION 3-E., SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-NOV-2003			-				
SB BBJ-28-92C	CONVERSION FROM AN EXISTING SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 3-M TO A SEVEN CELL (2 FWD 5 AFT) AFS, CONFIGURATION 3-E., SERVICE BULLETIN					RECOMMENDED	
		MOS					
02-DEC-2003			-				
SB BBJ-28-93	IN AUX FUEL MODIFIED AIRPLANES, TO RELOCATE EXPOSED TEST PLUG IN THE AFT CARGO COMPARTMENT & STOW THE FUEL CONNECTOR PLUG IN THE FWD CARGO TO A PROTECTED AREA, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-JAN-2003			-				
SB BBJ-28-94A	CONVERSION OF PREVIOUS CONFIGURATION: FROM AN EXISTING SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 2-M TO A EIGHT CELL (3 FWD 5 AFT) AFS, CONFIGURATION 3-F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-APR-2003			-				

© Camp Systems

EFTA00618495

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BBJ-28-95	CHANGE THE FUEL QUANTITY INDICATING SYSTEM FROM KILOGRAMS TO POUNDS STC: ST00936NY AMENDED JUNE 17, 2002, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-MAR-2003			-				
SB BBJ-33-37A	DE-ACTIVATION/REACTIVATION OF CARGO LIGHTING ABOVE AUX FUEL TANKS, SERVICE BULLETIN						
		MOS					
			- (s)				
SB BBJ-33-37B	DE-ACTIVATION / REACTIVATION OF CARGO LIGHTING ABOVE AUX FUEL TANKS., SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-NOV-2000			- (s)				
SB BBJ-34-79	REMOVAL OF EXISTING ARINC 740 MILTOPE COCKPIT PRINTER AND AND REPLACE WITH ALLIED SIGNAL PRINTER, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-MAR-2003			-				
SB BBJ-53-38A	IMPROVED MIX BAY ACCESS., SERVICE BULLETIN					RECOMMENDED	
		MOS					
06-JUL-2001			- (s)				
SB BBJ2-28-08A	AIRCRAFT CONVERSION TO UPDATE TO SOFTWARE 2.1 (STC SA01384NY), SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-JUN-2002			- (s)				
SB BBJ2-28-11A	CONVERSION FROM AN EXISTING SEVEN CELL (2 FWD 5 AFT) AFS, CONFIGURATION 1-G TO A SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 1-D, SERVICE BULLETIN					RECOMMENDED	
		MOS					
08-JAN-2003			-				
SB BBJ2-28-11B	CONVERSION FROM AN EXISTING SEVEN CELL (2 FWD 5 AFT) AFS, CONFIGURATION 1-G TO A SIX CELL (1 FWD 5 AFT) AFS, CONFIGURATION 1-D, SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-APR-2003			-				
SB BBJ2-28-15	CONVERSION FROM AN EXISITNG SIX CELL (2 FWD 4 AFT) AFS, CONFIGURATION 1-F TO A FIVE CELL (1 FWD 4 AFT) AFS, CONFIGURATION 1-C, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-FEB-2003			-				
SB BBJ2-28-17A	CHANGE FUEL QUANITY INDICATING SYSTEM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
21-FEB-2003			-				

© Camp Systems

EFTA00618496

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	BBJ2-28-91A	CHANGE FUEL QUANITY INDICATING SYSTEM, SERVICE BULLETIN						
			MOS					
				-				
SB	CFM56-7BSB80-005	, SERVICE BULLETIN						COMPLIED WITH - C/W
			MOS		10-AUG-2000			
				- (s)				
SB	CFMI-SB72-168	, SERVICE BULLETIN						
			MOS		17-OCT-2000			
				- (s)				
SB	S-0380-34-02	, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	S-0380-34-03	, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	SB-17	, SERVICE BULLETIN						
			MOS					
				- (s)				
SB	TPR-901-34-10R2	ROCKWELL COLLINS - ELIMINATE OCCURANCE OF ERRANT MODE A CODE (0607) AND IMPROVE DESENDE RECOVERY TIMING, SERVICE BULLETIN						COMPLIED WITH
			MOS		20-DEC-2006			
				-	2785:43			
			AFL		661			
SIL	920-08-1	ROCKWELL COLLINS - GLU-920 GLOBAL LANDING UNIT (CPN 822-1152-001/002/003/220) GPS DATE CODE - 08-1, SERVICE INFORMATION LETTER						COMPLIED WITH
			MOS		23-FEB-2009			
	26-AUG-2008			-	3353:18			
			AFL		804			
SIL	D200808000008 R5	HONEYWELL HAS ISSUED A SPECIAL PRICE FOR THE PARTS NECESSARY FOR THE ATA 36 UPGRADES FOR 737, SERVICE INFORMATION LETTER						
			MOS					
	07-AUG-2013			-				
SIL	D201103000023 R1	INTRODUCTION OF WHEEL HUB ULTRASONIC INSPECTION KIT, PN 7416886, SERVICE INFORMATION LETTER					RECOMMENDED	
			MOS					
	27-NOV-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SIL D201104000050 R2	RE-INTRODUCTION OF VACUUM BLOWER, PN 606802-2, IN PLACE OF VACUUM BLOWER, PN 645172-1, -2, SERVICE INFORMATION LETTER					OPERATORS DISCRETION	
		MOS					
28-JUN-2013			-				
SIL D201311000043	POSSIBLE INCORRECT PACK DISCHARGE OVERHEAT SWITCH INSTALLED ON CERTAIN BOEING MODEL 737-800/-900/-900ER AIRCRAFT (SUPERSEDED BY SIL D201311000043 R1), SERVICE INFORMATION LETTER					SUPERSEDED	
		MOS					
			-				
SIL D201311000043 R1	POSSIBLE INCORRECT PACK DISCHARGE OVERHEAT SWITCH INSTALLED ON CERTAIN BOEING MODEL 737-800/-900/-900ER AIRCRAFT, SERVICE INFORMATION LETTER					RECOMMENDED	
		MOS					
15-JAN-2014			-				
SIL D201312000067	MK V ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS), PN 965-0976-003-XXX-XXX, PN 965-0976-020-XXX-XXX, PN 965-0976-040-XXX-XXX, PN 965-0976-060-XXX-XXX, PN 965-1676-00X, AND PN 965-1690-05X; END OF PRODUCTION ANNOUNCEMENT DUE TO PARTS OBSOLESCENCE, SERVICE INFORMATION LETTER					RECOMMENDED	
		MOS					
20-DEC-2013			-				
SIL D201401000052	BOEING 737 LIGHT EMITTING DIODE (LED) WINGLET ANTICOLLISION LIGHT SYSTEM - WINGLET STROBE NOT FLASHING, SERVICE INFORMATION LETTER					RECOMMENDED	
		MOS					
13-MAR-2014			-				
SIL D201402000030	INSPECTION OF THE LEVER, PN 3177656-1 OR PN 63000974-1, AND ADAPTER ASSEMBLY, PN 3177635-2 OR -3, ON THE PRECOOLER CONTROL VALVE (PCCV), PN 3289562-6, -7, SERVICE INFORMATION LETTER					RECOMMENDED	
		MOS					
26-FEB-2014			-				
SL 737-SL-00-014 REV. A	LOADABLE SOFTWARE MEDIA BINDERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-SEP-2001			- (s)				
SL 737-SL-00-015	FLIGHT DECK FAULT INDICATIONS AND NUISANCES MESSAGES, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JUN-1999			- (s)				
SL 737-SL-00-016	SOFTWARE STORAGE ON DISKETTE SET, OTHER MEDIA SET, AND MASS STORAGE DEVICES, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-SEP-1999			- (s)				
SL 737-SL-00-017	AVAILABILITY OF BOEING DISKETTE COPY PROCESS AND TOOL SET. (SUPERSEDED BY SL 737-SL-00-017 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-00-017 REV. A	AVAILABILITY OF BOEING DISKETTE COPY PROCESS AND TOOL SET, SERVICE LETTER					RECOMMENDED	
17-OCT-2012		MOS	-				
SL 737-SL-00-019	SUSPECT DISCREPANCY REPORT PROCESS (SUPERSEDED BY SL 737-SL-00-019 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-00-019 REV. A	SUSPECT DISCREPANCY REPORT PROCESS, SERVICE LETTER					RECOMMENDED	
13-NOV-2012		MOS	-				
SL 737-SL-00-020	PROCEDURES FOR SEEKING ALTERNATE METHOD OF COMPLIANCE APPROVAL, SERVICE LETTER					INFORMATIONAL	
24-JAN-2007		MOS	-				
SL 737-SL-00-022	BOEING REVIEW PROCESS OF REQUESTS FOR AIRPLANE SYSTEMS AND FLIGHT OPERATIONS NO TECHNICAL OBJECTION (NTO), ACCEPTABLE, AND APPROVED (8100-9) DATA, SERVICE LETTER					INFORMATIONAL	
10-JAN-2008		MOS	-				
SL 737-SL-00-022 REV. A	BOEING REVIEW PROCESS OF REQUESTS FOR AIRPLANE SYSTEMS AND FLIGHT OPERATIONS NO TECHNICAL OBJECTION (NTO), ACCEPTABLE, AND APPROVED (8100-9) DATA, SERVICE LETTER					INFORMATIONAL	
12-MAR-2008		MOS	-				
SL 737-SL-00-022 REV. B	BOEING REVIEW PROCESS OF REQUESTS FOR AIRPLANE SYSTEMS AND FLIGHT OPERATIONS NO TECHNICAL OBJECTION (NTO), ACCEPTABLE, AND APPROVED (8100-9) DATA (SUPERSEDED BY SL 737-SL-00-022 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-00-022 REV. C	BOEING REVIEW PROCESS OF REQUESTS FOR AIRPLANE SYSTEMS AND FLIGHT OPERATIONS NO TECHNICAL OBJECTIONS, FAA 8100-9 FORMS, AND REPAIR AND DEVIATION RECORDS (SUPERSEDED BY SL 737-SL-00-022 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-00-022 REV. D	BOEING REVIEW PROCESS OF REQUESTS FOR AIRPLANE SYSTEMS AND FLIGHT OPERATIONS NO TECHNICAL OBJECTIONS, FAA 8100-9 FORMS, AND REPAIR AND DEVIATION RECORDS, SERVICE LETTER					RECOMMENDED	
16-JUL-2013		MOS	-				

© Camp Systems

EFTA00618499

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-00-023	SMOKE AND BURNING ODOR (SBO) EVENT SUMMARY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	22-FEB-2008			-				
SL	737-SL-00-023 REV. A	SMOKE AND BURNING ODOR (SBO) EVENT SUMMARY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	24-NOV-2008			-				
SL	737-SL-00-023 REV. B	SMOKE AND BURNING ODOR (SBO) EVENT SUMMARY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	17-DEC-2009			-				
SL	737-SL-00-024	BOEING TECHNICAL COMMUNICATIONS (SUPERSEDED BY SL 737-SL-00-024 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-00-024 REV. A	BOEING TECHNICAL COMMUNICATIONS, SERVICE LETTER					RECOMMENDED	
			MOS					
	11-APR-2011			-				
SL	737-SL-00-025	DISCONTINUED USE OF 3.5 INCH FLOPPY DISKETTES FOR ONBOARD LOADABLE LRU'S (SUPERSEDED BY SL 737-SL-00-025 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-00-025 REV. A	DISCONTINUED USE OF 3.5 INCH FLOPPY DISKETTES FOR ON-BOARD LOADABLE LRU'S (SUPERSEDED BY SL 737-SL-00-025 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-00-025 REV. B	DISCONTINUED USE OF 3.5 INCH FLOPPY DISKETTES FOR ON BOARD LOADABLE LRU'S (SUPERSEDED BY SL 737-SL-00-025 REV. C), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-00-025 REV. C	DISCONTINUED USE OF 3.5 INCH FLOPPY DISKETTES FOR ON-BOARD LOADABLE LRU'S, SERVICE LETTER					RECOMMENDED	
			MOS					
	23-JUL-2014			-				
SL	737-SL-00-026	OPERATOR CORRECTION OF ERRORS IN THE LIFE LIMITED PART LIST AND AIRCRAFT READINESS LOG, SERVICE LETTER					RECOMMENDED	
			MOS					
	17-JAN-2014			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-02-002	IN-FIGHT AIRFRAME VIBRATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-JUL-1987			- (s)				
SL 737-SL-02-002 REV. A	IN-FIGHT AIRFRAME VIBRATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-AUG-1995			- (s)				
SL 737-SL-02-002 REV. B	IN-FIGHT AIRFRAME VIBRATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-SEP-1996			- (s)				
SL 737-SL-02-002 REV. C	IN-FIGHT AIRFRAME VIBRATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-APR-1999			- (s)				
SL 737-SL-02-002 REV. D	IN FLIGHT AIRFRAME VIBRATION., SERVICE LETTER					INFORMATIONAL	
		MOS					
03-JUL-2001			- (s)				
SL 737-SL-02-008	PASSENGER CARRY ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
04-JUL-1993			- (s)				
SL 737-SL-02-008 REV. A	PASSENGER CARRY ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-02-008 REV. B	PASSENGER CARRY ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-02-008 REV. C	PASSENGER CARRY ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-02-008 REV. D	PASSENGER CARRY-ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. E), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-02-008 REV. E	PASSENGER CARRY-ON ELECTRONIC DEVICES (SUPERSEDED BY SL 737-SL-02-008 REV. F), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-02-008 REV. F	PASSENGER CARRY-ON ELECTRONIC DEVICES, SERVICE LETTER					RECOMMENDED	
		MOS					
31-JUL-2014			-				
SL 737-SL-02-017	REDUCED VERTICAL SEPERATION MINIMUM (RVSM) QUALIFICATION., SERVICE LETTER					INFORMATIONAL	
		MOS					
10-FEB-1998			- (s)				
SL 737-SL-02-017 REV. A	REDUCED VERTICAL SEPERATION MINIMUM (RVSM) QUALIFICATION., SERVICE LETTER					INFORMATIONAL	
		MOS					
25-SEP-1998			- (s)				
SL 737-SL-02-017 REV. B	REDUCED VERTICAL SEPERATION MINIMUM (RVSM) QUALIFICATION., SERVICE LETTER					INFORMATIONAL	
		MOS					
23-SEP-1998			- (s)				
SL 737-SL-02-017 REV. C	REDUCED VERTICAL SEPERATION MINIMUM (RVSM) QUALIFICATION., SERVICE LETTER					INFORMATIONAL	- INFORMATION COMPLIED WITH RVSM QUALIFICATION RENEWAL. CONTINUE IN REV.G
		MOS		27-JAN-2006			
21-MAR-2001			-	2484:18			
		AFL		596			
SL 737-SL-02-017 REV. D	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) QUALIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
06-OCT-2003			-				
SL 737-SL-02-017 REV. G	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) QUALIFICATION, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - FOUND A/C ALREADY RVSM CERTIFIED
		MOS		24-AUG-2007			
02-JUL-2004			-	2968:28			
		AFL		699			
SL 737-SL-02-018	COMPLIANCE GUIDANCE TO EUROPEAN JOINT AVIATION AUTHORITY REQUIREMENTS FOR OPERATIONS, (JAR-OPS 1 EUROPEAN), SERVICE LETTER					INFORMATIONAL	
		MOS					
26-MAR-1998			- (s)				
SL 737-SL-02-019	EXTENDED RANGE OPERATIONS WITH ETOPS A/P CONFIGURATION CMP DOC, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-JAN-1999			- (s)				
SL 737-SL-02-020	BASIC AND PRECISION AREA NAVIGATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-JUN-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-02-020 REV. A	BASIC AND PRECISION AREA NAVIGATION, SERVICE LETTER						
		MOS					
03-NOV-2005			-				
SL 737-SL-02-020 REV. B	BASIC AND PRECISION AREA NAVIGATION, SERVICE LETTER						
		MOS					
11-SEP-2006			-				
SL 737-SL-02-020 REV. C	BASIC AND PRECISION AREA NAVIGATION, SERVICE LETTER						
		MOS					
12-FEB-2007			-				
SL 737-SL-02-021	UPDATE 10.5 INCORPORATION OF 2005 MAGNETIC VARIATION DATA, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-MAR-2004			-				
SL 737-SL-02-022	STATEMENT OF AIRCRAFT CAPABILITY IN REFERENCE TO TERMINAL AND EN-ROUTE AREA NAVIGATION IN UNITED STATES NATIONAL AIRSPACE, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-AUG-2005			-				
SL 737-SL-02-022 REV. A	STATEMENT OF AIRCRAFT CAPABILITY IN REFERENCE TO TERMINAL AND EN-ROUTE NAVIGATION IN UNITED STATES NATIONAL AIRSPACE, SERVICE LETTER						
		MOS					
22-SEP-2005			-				
SL 737-SL-02-022 REV. B	STATEMENT OF AIRCRAFT CAPABILITY IN REFERENCE TO TERMINAL AND EN-ROUTE AREA NAVIGATION IN UNITED STATES NATIONAL AIRSPACE, SERVICE LETTER						
		MOS					
29-JUN-2006			-				
SL 737-SL-02-022 REV. C	STATEMENT OF AIRCRAFT CAPABILITY IN REFERENCE TO TERMINAL AND EN-ROUTE AREA NAVIGATION IN UNITED STATES NATIONAL AIRSPACE (SUPERSEDED BY 737-SL-02-022 REV.D), SERVICE LETTER					SUPERSEDED	
		MOS					
17-JUL-2007			-				
SL 737-SL-02-022 REV. D	STATEMENT OF AIRCRAFT CAPABILITY IN REFERENCE TO TERMINAL AND EN-ROUTE AREA NAVIGATION IN UNITED STATES NATIONAL AIRSPACE, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2012			-				
SL 737-SL-02-023	TRANSPORT OF LIQUID CARGO, SERVICE LETTER					RECOMMENDED	
		MOS					
15-DEC-2010			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-02-024	LITHIUM BATTERY FIRE FIGHTING RECOMMENDATIONS (SUPERSEDED BY SL 737-SL-02-024 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-02-024 REV. A	LITHIUM BATTERY FIRE FIGHTING RECOMMENDATIONS, SERVICE LETTER					RECOMMENDED	
			MOS					
	28-APR-2014			-				
SL	737-SL-03-004	AVIOD USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES, SERVICE LETTER						
			MOS					
	16-AUG-2005			-				
SL	737-SL-03-004 REV. A	AVOID USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES (SUPERSEDED BY SL 737-SL-03-004 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-03-004 REV. B	AVOID USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-JUL-2011			-				
SL	737-SL-03-004 REV. C	AVOID USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES (SUPERSEDED BY SL 737-SL-03-004 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-03-004 REV. D	AVOID USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES (SUPERSEDED BY SL 737-SL-03-004 REV. E), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-03-004 REV. E	AVOID USE OF DRY CHEMICAL FIRE EXTINGUISHERS ON AIRPLANES, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-FEB-2014			-				
SL	737-SL-05-011	REPORTING PARTS DEPARTING AIRPLANE, SERVICE LETTER					RECOMMENDED	
			MOS					
	31-JUL-2009			-				
SL	737-SL-05-012	CONTROL AND ELIMINATION OF CIMICIDAE (BED BUGS) ON AIRPLANES, SERVICE LETTER					RECOMMENDED	
			MOS					
	24-MAY-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-05-013	REPORTING FUEL IMBALANCE EXCEEDANCES TO BOEING, SERVICE LETTER					RECOMMENDED	
		MOS					
13-MAR-2014			-				
SL 737-SL-05-014	CONTROL AND ELIMINATION OF RODENTS ON AIRPLANES, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JAN-2014			-				
SL 737-SL-09-002	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-09-002 REV. A	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-09-002 REV. B	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-09-002 REV. C	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-09-002 REV. D	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. E), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-09-002 REV. E	TOWBARLESS TOWING (SUPERSEDED BY SL 737-SL-09-002 REV. F), SERVICE LETTER					RECOMMENDED	
		MOS					
16-OCT-2009			-				
SL 737-SL-09-002 REV. F	TOWBARLESS TOWING, SERVICE LETTER					RECOMMENDED	
		MOS					
18-DEC-2013			-				
SL 737-SL-09-003	737 NOSE GEAR COLLAPSE POTENTIAL DURING TOWING/PUSHBACK, SERVICE LETTER						
		MOS					
12-JUL-2007			-				
SL 737-SL-09-003 REV. A	737 NOSE GEAR COLLAPSE POTENTIAL DURING TOWING/PUSHBACK, SERVICE LETTER						
		MOS					
17-JAN-2008			-				

© Camp Systems

EFTA00618505

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-11-005	RED CROSS PLACARDS, SERVICE LETTER					INFORMATIONAL	
	11-MAR-1998		MOS	- (s)				
SL	737-SL-11-005 REV. A	RED CROSS PLACARDS, SERVICE LETTER					INFORMATIONAL	
	06-MAY-1998		MOS	- (s)				
SL	737-SL-11-005 REV. B	RED CROSS PLACARDS, SERVICE LETTER					INFORMATIONAL	
	04-AUG-1998		MOS	- (s)				
SL	737-SL-11-007	PASSENGER ENTRY DOOR HANDLE ARROW PLACARD MODIFICATION., SERVICE LETTER					INFORMATIONAL	
	08-OCT-1999		MOS	- (s)				
SL	737-SL-11-009	EXTERNAL POWER PANEL-INCORRECT VOLTAGE MARKING, SERVICE LETTER					INFORMATIONAL	
	31-MAY-2000		MOS	- (s)				
SL	737-SL-11-010	LOWER CARGO COMPARTMENT LINER AND FLOOR PANEL REPLACEMENT., SERVICE LETTER					INFORMATIONAL	
	01-JUN-2001		MOS	- (s)				
SL	737-SL-11-010 REV. A	EXTERIOR PLACARDS PEELING FROM AIRPLANE, SERVICE LETTER					INFORMATIONAL	
	15-APR-2003		MOS	-				
SL	737-SL-11-011 REV. A	OWNER NAMEPLATE-INSPECTION AND REWORK, SERVICE LETTER					INFORMATIONAL	
	10-FEB-2004		MOS	-				
SL	737-SL-11-013	P18-2 CIRCUIT BREAKER MARKER WITH INCORRECT NOMENCLATURE, SERVICE LETTER						
	26-SEP-2008		MOS	-				
SL	737-SL-11-013 REV. A	P18-2 CIRCUIT BREAKER MARKER WITH INCORRECT NOMENCLATURE, SERVICE LETTER					RECOMMENDED	
	15-JUL-2009		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-11-013 REV. B	P18-2 CIRCUIT BREAKER MARKER WITH INCORRECT NOMENCLATURE, SERVICE LETTER						
		MOS					
21-AUG-2009			-				
SL 737-SL-11-014	E/E BAY ACCESS DOOR STENCILS, SERVICE LETTER					RECOMMENDED	
		MOS					
23-AUG-2013			-				
SL 737-SL-11-015	FORWARD AND AFT DOOR SILL DRAIN SYSTEM STENCIL REPLACEMENTS (SUPERSEDED BY SL 737-SL-11-015 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-11-015 REV. A	FORWARD AND AFT DOOR SILL DRAIN SYSTEM STENCIL REPLACEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
02-JUN-2014			- (s)				
SL 737-SL-12-011	AIRPLANE HIGH PRESSURE WASHING VIDEO, SERVICE LETTER					INFORMATIONAL	
		MOS					
25-JUN-1993			- (s)				
SL 737-SL-12-011 REV. A	AIRPLANE HIGH PRESSURE WASHING VIDEO, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-APR-1999			- (s)				
SL 737-SL-12-011 REV. B	AIRPLANE HIGH PRESSURE WASHING VIDEO (SUPERSEDED BY 737-SL-12-011 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
18-MAY-1999			- (s)				
SL 737-SL-12-011 REV. C	AIRPLANE HIGH PRESSURE WASHING VIDEO, SERVICE LETTER					RECOMMENDED	
		MOS					
08-JUL-2010			-				
SL 737-SL-12-014	DEICING/ANTI-ICING FLUID RESIDUE REHYDRATION AND FREEZING., SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JAN-2000			- (s)				
SL 737-SL-12-015	RECOMMENDED INTERVALS FOR TIRE PRESSURE CHECKS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2001			- (s)				
SL 737-SL-12-015 REV. A	RECOMMENDED INTERVALS FOR TIRE PRESSURE CHECKS, SERVICE LETTER						
		MOS					
17-JUL-2007			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-12-015 REV. B	RECOMMENDED INTERVALS FOR TIRE PRESSURE CHECKS, SERVICE LETTER						
		MOS					
26-SEP-2007			-				
SL 737-SL-12-016	INTRODUCTION OF RE-BRANDED NAMES FOR APPROVED OILS, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-OCT-2001			- (s)				
SL 737-SL-12-017	CLEANING OF DEICING/ANTI-ICING FLUID RESIDUE FROM ELEVATOR BALANCE PANEL CAVITY AREA, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-APR-2002			- (s)				
SL 737-SL-12-017 REV. A	CLEANING OF DEICING/ANIT-ICING FLUID RESIDUE FROM ELEVATOR BALANCE PANEL CAVITY AREA, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-MAY-2002			- (s)				
SL 737-SL-12-018	LANDING GEAR MAINTENANCE DURING COLD WEATHER OPERATION, SERVICE LETTER						
		MOS					
13-OCT-2006			-				
SL 737-SL-12-018 REV. A	LANDING GEAR MAINTENANCE DURING COLD WEATHER OPERATION, SERVICE LETTER					RECOMMENDED	
		MOS					
18-MAR-2013			-				
SL 737-SL-12-019	DEICING/ANTI-ICING FLUID RESIDUES CAUSING FLIGHT CONTROL RESTRICTIONS, SERVICE LETTER						
		MOS					
14-NOV-2006			-				
SL 737-SL-12-019 REV. A	DEICING/ANTI-ICING FLUID RESIDUES CAUSING FLIGHT CONTROL RESTRICTIONS, SERVICE LETTER						
		MOS					
28-AUG-2007			-				
SL 737-SL-12-020	LANDING GEAR WASHING AND CLEANING PRACTICES (SUPERSEDED BY SL 737-SL-12-020 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-12-020 REV. A	LANDING GEAR WASHING AND CLEANING PRACTICES, SERVICE LETTER					RECOMMENDED	
		MOS					
05-JUN-2014			-				

© Camp Systems

EFTA00618508

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-12-022	IATA GUIDANCE MATERIAL ON STANDARD INTO-PLANE FUELING PROCEDURES, SERVICE LETTER					RECOMMENDED	
			MOS					
	20-JAN-2011			-				
SL	737-SL-12-022 REV. A	IATA GUIDANCE MATERIAL ON STANDARD INTO-PLANE FUELING PROCEDURES, SERVICE LETTER					RECOMMENDED	
			MOS					
	27-JAN-2011			-				
SL	737-SL-156-A	UNPROTECTED WIRE BUNDLES IN P8 & P9 PANELS, SERVICE LETTER						
			MOS					
				- (s)				
SL	737-SL-20-005	APPROVAL OF VENDOR MATERIALS FOR USE IN GENERAL AIRCRAFT MAINTENANCE (SUPERSEDED BY SL 737-SL-20-005 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-20-005 REV. A	APPROVAL OF VENDOR MATERIALS FOR USE IN GENERAL AIRCRAFT MAINTENANCE (SUPERSEDED BY SL 737-SL-20-005 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-20-005 REV. B	APPROVAL OF VENDOR MATERIALS FOR USE IN GENERAL AIRCRAFT MAINTENANCE (SUPERSEDED BY SL 737-SL-20-005 REV. C), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-20-005 REV. C	APPROVAL OF VENDOR MATERIALS FOR USE IN GENERAL AIRCRAFT MAINTENANCE (SUPERSEDED BY SL 737-SL-20-005 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-20-005 REV. D	APPROVAL OF VENDOR MATERIALS FOR USE IN GENERAL AIRCRAFT MAINTENANCE, SERVICE LETTER					RECOMMENDED	
			MOS					
	14-JAN-2014			-				
SL	737-SL-20-012	QUICK REPAIR FUEL TANK SEALANT., SERVICE LETTER					INFORMATIONAL	
			MOS					
	11-MAR-1987			- (s)				
SL	737-SL-20-012 REV. A	QUICK REPAIR FUEL TANK SEALANT., SERVICE LETTER					INFORMATIONAL	
			MOS					
	04-MAY-1987			-				

© Camp Systems

EFTA00618509

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-012 REV. B	QUICK REPAIR FUEL TANK SEALANT., SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-1992			- (s)				
SL 737-SL-20-012 REV. C	QUICK REPAIR FUEL TANK SEALANT., SERVICE LETTER					INFORMATIONAL	
		MOS					
05-FEB-2001			-				
SL 737-SL-20-014 REV. B	CONTROL CABLE CHANGE TO IMPROVE TENSION STABILITY, SERVICE LETTER						
		MOS					
20-OCT-2008			-				
SL 737-SL-20-025 REV. A	EVALUATION OF GENERAL PURPOSE GREASES FOR ROUTINE RELUBRICATION DURING AIRPLANE MAINTENANCE, SERVICE LETTER					RECOMMENDED	
		MOS					
26-MAR-2009			-				
SL 737-SL-20-027 REV. C	SUMMARY OF MOST COMMONLY USED GREASES ON BOEING AIRCRAFT, SERVICE LETTER						
		MOS					
16-NOV-2001			- (s)				
SL 737-SL-20-027 REV. D	SUMMARY OF MOST COMMONLY USED GREASES ON BOEING AIRPLANES (SUPERSEDED BY SL 737-SL-20-027 REV. E), SERVICE LETTER						
		MOS					
05-AUG-2008			-				
SL 737-SL-20-027 REV. E	SUMMARY OF MOST COMMONLY USED GREASES ON BOEING AIRPLANES (SUPERSEDED BY 737-SL-20-027 REV. F), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-20-027 REV. F	SUMMARY OF MOST COMMONLY USED GREASES ON BOEING AIRPLANES, SERVICE LETTER					RECOMMENDED	
		MOS					
26-JUN-2013			-				
SL 737-SL-20-029 REV. A	AIRPLANE STATIC/ELECTRICAL GROUNDING RECOMMENDATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-MAY-2003			-				
SL 737-SL-20-029 REV. B	AIRPLANE STATIC/ELECTRICAL GROUNDING RECOMMENDATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-JUL-2003			-				

© Camp Systems

EFTA00618510

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-029 REV. C	AIRPLANE STATIC/ELECTRICAL GROUNDING RECOMMENDATIONS, SERVICE LETTER						
01-MAR-2005		MOS	-				
SL 737-SL-20-032 REV. A	BMS 3-33 GENERAL PURPOSE AIRCRAFT GREASE, SERVICE LETTER					INFORMATIONAL	
14-AUG-2001		MOS	- (s)				
SL 737-SL-20-032 REV. B	BMS 3-33 GENERAL PURPOSE AIRCRAFT GREASE, SERVICE LETTER					RECOMMENDED	
26-MAR-2009		MOS	-				
SL 737-SL-20-034	CONTROL CABLE TENSION INSPECTION, SERVICE LETTER					INFORMATIONAL	
03-MAY-1991		MOS	- (s)				
SL 737-SL-20-034 REV. A	WIRE BUNDLE/COAXIAL CABLE ORDERING/FABRICATING PROCEDURE, SERVICE LETTER					INFORMATIONAL	
16-JUN-1997		MOS	- (s)				
SL 737-SL-20-034 REV. B	WIRE BUNDLE/COAXIAL CABLE ORDERING/FABRICATING PROCEDURE, SERVICE LETTER					INFORMATIONAL	
16-JUL-1999		MOS	- (s)				
SL 737-SL-20-035	AS HOSE INTERCHANGEABILITY FOR POTABLE AND GREY WATER, SERVICE LETTER					INFORMATIONAL	
20-JUL-1998		MOS	- (s)				
SL 737-SL-20-036	NAS1611, NAS1612, NAS1613SEAL AND SEAL MATERIAL CHANGES, SERVICE LETTER						
04-JUN-1999		MOS	- (s)				
SL 737-SL-20-037	LOW BREAKAWAY TORQUE ON KAYNAR NAS 1805-5L., SERVICE LETTER					INFORMATIONAL	
30-MAY-2000		MOS	- (s)				
SL 737-SL-20-038	CONTROL CABLE TENSION INSPECTION, SERVICE LETTER					INFORMATIONAL	
31-OCT-2000		MOS	- (s)				
SL 737-SL-20-038 REV. A	CONTROL CABLE TENSION INSPECTION, SERVICE LETTER					INFORMATIONAL	
22-OCT-2002		MOS	-				

© Camp Systems

EFTA00618511

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-038 REV. B	CONTROL CABLE TENSION INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-JUL-2003			-				
SL 737-SL-20-040	PART MARKING., SERVICE LETTER					INFORMATIONAL	
		MOS					
30-MAY-2001			-				
SL 737-SL-20-041	OVERHAUL OF HIGH STRENGTH STEEL COMPONENTS - CADMIUM STRIP REQUIRED, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-MAR-2002			- (s)				
SL 737-SL-20-042 REV. A	MATERIAL REVIEW BOARD ACTION ON TILEFLEX STANDARD HOSES SHIPPED AS SPARES, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-JAN-2003			-				
SL 737-SL-20-043	DEFERRED APPLICATION OF AERO-SEALANT, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-AUG-2002			-				
SL 737-SL-20-043 REV. A	DEFERRED APPLICATION OF AERO-SEALANT IN ANTENNA INSTALLATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-MAY-2003			-				
SL 737-SL-20-043 REV. B	DEFERRED APPLICATION OF AERO-SEALANT IN ANTENNA INSTALLATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-NOV-2003			-				
SL 737-SL-20-043 REV. C	DEFERRED APPLICATION OF AERO-SEALANT IN ANTENNA INSTALLATIONS, SERVICE LETTER						
		MOS					
11-JUN-2007			-				
SL 737-SL-20-044	ESCAPEMENT OF NON-CONFORMING FIELD EFFECT TRANSISTOR (FET) P/N S182-10802-5 (SUPERSEDED BY SL 737-SL-20-044 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-20-044 REV. A	ESCAPEMENT OF NON-CONFORMING FIELD EFFECT TRANSISTOR (FET) P/N S182-10802-5 (SUPERSEDED BY 737-SL-20-044 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-20-044 REV. B	ESCAPEMENT OF NON-CONFORMING FIELD EFFECT TRANSISTOR (FET) P/N S182-10802-5, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUN-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-045	GASKET IN LIEU OF SEALANT FOR ANTENNA INSTALLATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-AUG-2003			-				
SL 737-SL-20-045 REV. A	USE OF GASKET IN LIEU OF SEALANT FOR THE FOLLOWING ANTENNA INSTALLATION (SUPERSEDED BY SL 737-SL-20-045 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-20-045 REV. B	USE OF GASKET IN LIEU OF SEALANT FOR THE FOLLOWING ANTENNA INSTALLATIONS: AIR TRAFFIC CONTROL (ATC), DISTANCE MEASURING EQUIPMENT (DME), LOW RANGE RADIO ALTIMETER (LRRA), MARKER BEACON (MB), TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS), AND VERY HIGH FREQUENCY (VHF) COMMUNICATION ANTENNAS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-NOV-2013			-				
SL 737-SL-20-047	CIRCUIT BREAKER RELIABILITY, SERVICE LETTER						
		MOS					
07-JAN-2005			-				
SL 737-SL-20-048	NAS1611-XXXA CODE O-RING STATIC SEALS - HYDRULIC FLUID EXTERNAL LEAKAGE LOW TEMPERATURES, SERVICE LETTER						
		MOS					
19-DEC-2005			-				
SL 737-SL-20-048 REV. A	NAS1611-XXXA CODE O-RING STATIC SEALS - HYDRAULIC FLUID EXTERNAL LEAKAGE AT LOW TEMPERATURES, SERVICE LETTER						
		MOS					
21-MAR-2006			-				
SL 737-SL-20-048 REV. B	NAS1611-XXXA CODE O-RING STATIC SEALS - HYDRAULIC FLUID EXTERNAL LEAKAGE AT LOW TEMPERATURES, SERVICE LETTER						
		MOS					
22-SEP-2006			-				
SL 737-SL-20-048 REV. C	NAS1611-XXXA CODE O-RING STATIC SEALS - HYDRAULIC FLUID EXTERNAL LEAKAGE AT LOW TEMPERATURES, SERVICE LETTER						
		MOS					
29-JUN-2007			-				
SL 737-SL-20-048 REV. D	NAS1611-XXXA CODE O-RING STATIC SEALS - HYDRAULIC FLUID EXTERNAL LEAKAGE AT LOW TEMPERATURES, SERVICE LETTER						
		MOS					
09-APR-2008			-				

© Camp Systems

EFTA00618513

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-049	BACC10KB( ) CONNECTOR BACKSHELL CHAFE, SERVICE LETTER						
		MOS					
14-NOV-2006			-				
SL 737-SL-20-049 REV. A	BACC10KB( ) CONNECTOR BACKSHELL CHAFE, SERVICE LETTER						
		MOS					
21-NOV-2007			-				
SL 737-SL-20-050	REPAINTING AIRPLANES THAT EXHIBIT FUSELAGE DECORATIVE PAINT PEELING FROM RIVET HEADS - "RIVET RASH", SERVICE LETTER						
		MOS					
15-FEB-2007			-				
SL 737-SL-20-051	POSSIBLE INCORRECT WIRING BRACKET LOCATION, SERVICE LETTER					RECOMMENDED	
		MOS					
15-JUL-2009			-				
SL 737-SL-20-051 REV. A	POSSIBLE INCORRECT WIRING BRACKET LOCATION (SUPERSEDED BY SL 737-SL-20-051 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-20-051 REV. B	POSSIBLE INCORRECT WIRING BRACKET LOCATION, SERVICE LETTER						
		MOS					
15-JUL-2010			-				
SL 737-SL-20-052	WIRE BUNDLE SUPPORT BRACKETS IN NOSE GEAR E/E BAY INCORRECTLY INSTALLED, SERVICE LETTER					RECOMMENDED	
		MOS					
13-AUG-2009			-				
SL 737-SL-20-052 REV. A	WIRE BUNDLE SUPPORT BRACKETS IN NOSE GEAR E/E BAY INCORRECTLY INSTALLED, SERVICE LETTER					RECOMMENDED	
		MOS					
02-OCT-2009			-				
SL 737-SL-20-053	ELECTRICAL CONNECTOR CORROSION IN UNPRESSURIZED AREAS, SERVICE LETTER					RECOMMENDED	
		MOS					
04-NOV-2009			-				
SL 737-SL-20-054	SEVEN CONNECTORS WITH POTENTIALLY INCORRECT PLATING (SUPERSEDED BY SL 737-SL-20-054 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-20-054 REV. A	SEVEN CONNECTORS WITH POTENTIALLY INCORRECT PLATING, SERVICE LETTER					RECOMMENDED	
		MOS					
30-SEP-2010			-				
SL 737-SL-20-055	GROUND BLOCK CORROSION, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JAN-2012			-				
SL 737-SL-20-056	INSPECTION FOR CORRECT LABELING OF THE TERMINAL BLOCKS IN THE J38 JUNCTION BOX, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAR-2011			-				
SL 737-SL-20-057	SAFETY WIRE (LOCKWIRE) MATERIAL SELECTION AND USAGE INTERCHANGEABILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
04-SEP-2013			-				
SL 737-SL-21-033 REV. D	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS, SERVICE LETTER						
		MOS					
28-MAY-2008			-				
SL 737-SL-21-033 REV. E	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS, SERVICE LETTER						
		MOS					
01-AUG-2008			-				
SL 737-SL-21-033 REV. F	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS (SUPERSEDED BY SL 737-SL-21-033 REV. G), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-033 REV. G	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS (SUPERSEDED BY SL 737-SL-21-033 REV. H), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-033 REV. H	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS (SUPERSEDED BY SL 737-SL-21-033 REV. I), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-033 REV. I	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS (SUPERSEDED BY SL 737-SL-21-033 REV. J), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-033 REV. J	RECOMMENDED ALLOWABLE DRY ICE CARRIAGE LIMITS, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAY-2014			-				
SL 737-SL-21-044	DIGITAL CABIN PRESSURE SYSTEM - CABIN PRESSURE EXCURSION DUE TO EMI (SUPERSEDED BY SL 737-SL-21-044 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-044 REV. A	DIGITAL CABIN PRESSURE SYSTEM - CABIN PRESSURE EXCURSION DUE TO EMI (SUPERSEDED BY SL 737-SL-21-044 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-044 REV. B	DIGITAL CABIN PRESSURE SYSTEM - CABIN PRESSURE EXCURSION DUE TO EMI (SUPERSEDED BY SL 737-SL-21-044 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-044 REV. C	DIGITAL CABIN PRESSURE SYSTEM-CABIN PRESSURE EXCURSIONS DUE TO EMI (SUPERSEDED BY SL 737-SL-21-044 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-044 REV. D	DIGITAL CABIN PRESSURE SYSTEM - CABIN PRESSURE EXCURSION DUE TO EMI, SERVICE LETTER					RECOMMENDED	
		MOS					
18-JUL-2011			-				
SL 737-SL-21-045	SINGLE PACK DISPATCHABILITY CONFIDENCE CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-SEP-1998			- (s)				
SL 737-SL-21-045 REV. A	SINGLE PACK DISPATCHABILITY CONFIDENCE CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-APR-1999			- (s)				
SL 737-SL-21-045 REV. B	SINGLE PACK DISPATCHABILITY CONFIDENCE CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-OCT-1999			- (s)				
SL 737-SL-21-045 REV. C	SINGLE PACK DISPATCHABILITY CONFIDENCE (DISCO) CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-JUN-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-045 REV. D	SINGLE PACK DISPATCHABILITY CONFIDENCE (DISCO) CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-AUG-2003			-				
SL 737-SL-21-045 REV. E	SINGLE PACK DISPATCHABILITY CONFIDENCE (DISCO) CHECK, SERVICE LETTER						
		MOS					
22-AUG-2007			-				
SL 737-SL-21-045 REV. F	SINGLE PACK DISPATCHABILITY CONFIDENCE (DISCO) CHECK, SERVICE LETTER						
		MOS					
02-JUN-2008			-				
SL 737-SL-21-045 REV. G	SINGLE PACK DISPATCHABILITY CONFIDENCE (DISCO) CHECK, SERVICE LETTER					RECOMMENDED	
		MOS					
27-OCT-2009			-				
SL 737-SL-21-046	PASSENGER CABIN TEMPERATURE SENSOR INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-OCT-1998			- (s)				
SL 737-SL-21-050	MODIFICATION OF THE AFT CABIN ZONE TEMPERATURE INDICATION SYSTEM WIRING., SERVICE LETTER					INFORMATIONAL	
		MOS					
29-OCT-1999			- (s)				
SL 737-SL-21-051	DIGITAL CABIN PRESSURE CONTROLLER-SOFTWARE UPGRADE, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-OCT-1999			- (s)				
SL 737-SL-21-052	AIR CYCLE MACHINE FAN DESIGN IMPROVEMENT., SERVICE LETTER					INFORMATIONAL	
		MOS					
02-FEB-2000			- (s)				
SL 737-SL-21-053	USE OF GROUND SOURCE CONDITIONED AIR IN LIEU OF AIRPLANES ECS AIR CONDITIONING PACKS (SUPERSEDED BY SL 737-SL-21-053 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-21-053 REV. A	USE OF GROUND SOURCE CONDITIONED AIR IN LIEU OF AIRPLANE ECS AIR CONDITIONING PACKS, SERVICE LETTER					RECOMMENDED	
		MOS					
17-OCT-2011			-				

© Camp Systems

EFTA00618517

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-055	NEW RECIRCULATION AIR FILTER, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-JAN-2003			-				
SL 737-SL-21-056 REV. A	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-MAY-2004			-				
SL 737-SL-21-056 REV. C	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE LETTER						
		MOS					
02-DEC-2005			-				
SL 737-SL-21-056 REV. D	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE LETTER						
		MOS					
30-MAR-2006			-				
SL 737-SL-21-056 REV. E	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE LETTER						
		MOS					
23-MAR-2007			-				
SL 737-SL-21-056 REV. F	RAM AIR INLET DUCT CLIP ASSEMBLY REPLACEMENT, SERVICE LETTER						
		MOS					
10-JUL-2007			-				
SL 737-SL-21-058	SIDEWALL RISER DUCTS SEPARATE FROM THE DISTRIBUTION MANIFOLD, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-JUL-2003			-				
SL 737-SL-21-058 REV. B	SIDEWALL RISER DUCTS SEPARATE FROM THE DISTRIBUTION MANIFOLD, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-JUN-2004			-				
SL 737-SL-21-058 REV. C	SIDEWALL RISER DUCTS SEPARATE FROM THE DISTRIBUTION MANIFOLD, SERVICE LETTER						
		MOS					
03-APR-2007			-				
SL 737-SL-21-059	AIR-CONDITIONING HIGH PRESSURE WATER SEPERATOR DRAIN MANIFOLD INSPECTION, SERVICE LETTER						
		MOS					
18-JUL-2003			-				
SL 737-SL-21-060	RECOMMENDED CLEANING INTERVALS AND PROCEDURES FOR IN-FLIGHT ENTERTAINMENT (IFE) SYSTEM COMPONENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
25-SEP-2003			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-060 REV. A	CLEAN RECOMMENDED CLEANING INTERVALS AND PROCEDURES FOR IN-FLIGHT ENTERTAINMENT (IFE) SYSTEM COMPONENTS, SERVICE LETTER COOLING SYSTEM					RECOMMENDED	
		MOS					
25-SEP-2003			-				
SL 737-SL-21-060 REV. B	INSPECT RECOMMENDED CLEANING INTERVALS AND PROCEDURES FOR IN-FLIGHT ENTERTAINMENT (IFE) SYSTEM COMPONENTS, SERVICE LETTER IFE EQUIPMENT					RECOMMENDED	
		MOS					
25-SEP-2003			800 (s)				
SL 737-SL-21-062 REV. B	OPTIONAL PART FOR RIGHT AIR CYCLE MACHINE (ACM) SENSE LINE, SERVICE LETTER						
		MOS					
16-APR-2007			-				
SL 737-SL-21-062 REV. C	AIR CYCLE MACHINE (ACM) SENSE LINES, SERVICE LETTER						
		MOS					
16-JAN-2009			-				
SL 737-SL-21-063	NUISANCE PACK/ZONE TEMP LIGHT ILLUMINATION ON RECALL THAT RESETS - CONTROLLER INPROVEMENT, SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY -
		MOS					
30-SEP-2004			-				
SL 737-SL-21-064	OUTFLOW VALVE SOFTWARE UPGRADE AND EMI ENHANCEMENT, SERVICE LETTER						
		MOS					
04-NOV-2004			-				
SL 737-SL-21-065	AIR CONDITIONING FLEX HOSE SEPARATION AT THE OVERHEAD DISTRIBUTION TAPED JOINTS, SERVICE LETTER						
		MOS					
15-MAR-2005			-				
SL 737-SL-21-065 REV. A	AIR CONDITIONING FLEX HOSE SEPARATION AT THE OVERHEAD DISTRIBUTION TAPED JOINTS, SERVICE LETTER						
		MOS					
23-AUG-2007			-				
SL 737-SL-21-066	COOLING PACK AIR CYCLE MACHINE TURBINE TORUS EROSION, SERVICE LETTER						
		MOS					
19-JUL-2005			-				
SL 737-SL-21-067	FLIGHT DECK MUFFLER REPLACEMENT, SERVICE LETTER						
		MOS					
07-DEC-2005			-				

© Camp Systems

EFTA00618519

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-068	AIRPLANE PRESSURIZATION - GUIDANCE TO UNDERSTANDING, SERVICE LETTER						
		MOS					
20-MAR-2006			-				
SL 737-SL-21-070	OUTFLOW VALVE MODIFICATION, SERVICE LETTER						
		MOS					
13-DEC-2006			-				
SL 737-SL-21-071	MISSING BOND JUMPER CABLE ON A/C PACK, SERVICE LETTER						
		MOS					
30-NOV-2006			-				
SL 737-SL-21-071 REV. A	MISSING BOND JUMPER CABLE ON A/C PACK, SERVICE LETTER						
		MOS					
08-FEB-2007			-				
SL 737-SL-21-071 REV. B	MISSING BOND JUMPER CABLE ON A/C PACK, SERVICE LETTER						
		MOS					
09-APR-2007			-				
SL 737-SL-21-072	DIGITAL CABIN PRESSURE CONTROL SYSTEM - CONTROLLER SOFTWARE UPDATE, SERVICE LETTER						
		MOS					
23-FEB-2007			-				
SL 737-SL-21-072 REV. A	DIGITAL CABIN PRESSURE CONTROL SYSTEM - CONTROLLER SOFTWARE UPDATE, SERVICE LETTER						
		MOS					
02-MAR-2007			-				
SL 737-SL-21-073	PRESSURIZATION TROUBLESHOOTING GUIDANCE, SERVICE LETTER						
		MOS					
24-JAN-2007			-				
SL 737-SL-21-074	COMPONENT INTERCHANGEABILITY - DIGITAL CABIN PRESSURIZATION SYSTEM (SUPERSEDED BY SL 737-SL-21-074 REV. A), SERVICE LETTER						
		MOS					
20-APR-2007			-				
SL 737-SL-21-074 REV. A	COMPONENT INTERCHANGEABILITY - DIGITAL CABIN PRESSURIZATION SYSTEM (SUPERSEDED BY SL 737-SL-21-074 REV. B), SERVICE LETTER						
		MOS					
23-DEC-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-074 REV. B	COMPONENT INTERCHANGEABILITY - DIGITAL CABIN PRESSURIZATION SYSTEM (SUPERSEDED BY SL 737-SL-21-074 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-074 REV. C	COMPONENT INTERCHANGEABILITY - DIGITAL CABIN PRESSURIZATION SYSTEM (SUPERSEDED BY SL 737-SL-21-074 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-074 REV. D	COMPONENT INTERCHANGEABILITY - DIGITAL CABIN PRESSURIZATION SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
24-JAN-2014			-				
SL 737-SL-21-075	DIAGNOSTIC CHECK OF THE AIR CONDITIONING PACK, SERVICE LETTER						
		MOS					
01-MAY-2007			-				
SL 737-SL-21-075 REV. A	DIAGNOSTIC CHECK OF THE AIR CONDITIONING PACK, SERVICE LETTER						
		MOS					
09-NOV-2007			-				
SL 737-SL-21-075 REV. B	DIAGNOSTIC CHECK OF THE AIR CONDITIONING PACK, SERVICE LETTER						
		MOS					
30-APR-2008			-				
SL 737-SL-21-077	AIR-CONDITIONING HIGH PRESSURE WATER SEPARATOR DRAIN MANIFOLD PLUG (SUPERSEDED BY SL 737-SL-21-077 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-077 REV. A	AIR-CONDITIONING HIGH PRESSURE WATER SEPARATOR DRAIN MANIFOLD PLUG, SERVICE LETTER					RECOMMENDED	
		MOS					
24-JUN-2014			-				
SL 737-SL-21-078	FORWARD DOOR HEAT SYSTEM DUCT KINKING, SERVICE LETTER						
		MOS					
20-FEB-2008			-				
SL 737-SL-21-078 REV. A	FORWARD DOOR HEAT SYSTEM FLEXIBLE DUCT KINKING, SERVICE LETTER						
		MOS					
31-JUL-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-078 REV. B	FORWARD DOOR HEAT SYSTEM FLEXIBLE DUCT KINKING, SERVICE LETTER					RECOMMENDED	
		MOS					
02-APR-2009			-				
SL 737-SL-21-079	E/E COOLING IN P5 PANEL - POTENTIAL WIRE CHAFING AGAINST HOSE CLAMP, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-21-080	AIR-CONDITIONING DUCT CLAMP ASSEMBLY TORQUE, SERVICE LETTER					RECOMMENDED	
		MOS					
23-JAN-2009			-				
SL 737-SL-21-080 REV. A	AIR-CONDITIONING DUCT CLAMP ASSEMBLY TORQUE, SERVICE LETTER					RECOMMENDED	
		MOS					
31-MAR-2009			-				
SL 737-SL-21-081	CABIN ALTITUDE AND DIFFERENTIAL PRESSURE INDICATOR INSPECTION, SERVICE LETTER					RECOMMENDED	
		DAYS	90 (s)				
24-APR-2009							
SL 737-SL-21-082	CABIN ALTITUDE AND DIFFERENTIAL PRESSURE INDICATOR REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-21-083	PROTECTIVE CAPS NOT REMOVED FROM MIX MANIFOLD TEMPERATURE SENSORS, SERVICE LETTER					RECOMMENDED	
		MOS					
08-OCT-2009			-				
SL 737-SL-21-084	TRANSPORTATION OF CRYOGENIC LIQUIDS (SUPERSEDED BY SL 737-SL-21-084 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-084 REV. A	TRANSPORTATION OF CRYOGENIC LIQUIDS (SUPERSEDED BY SL 737-SL-21-084 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-084 REV. B	TRANSPORTATION OF CRYOGENIC LIQUIDS, SERVICE LETTER					RECOMMENDED	
		MOS					
18-JUL-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-086	DIGITAL CABIN SELECTOR PANEL - VALVE POSITION INDICATION REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
23-DEC-2009			-				
SL 737-SL-21-087	DIGITAL CABIN PRESSURE CONTROLLER - P/N 7121-19971-01XX ON-WING SERVICE LIFE, SERVICE LETTER					RECOMMENDED	
		MOS					
15-FEB-2010			-				
SL 737-SL-21-088	DIGITAL CABIN PRESSURE CONTROLLER - SOFTWARE FOR DOWNLOAD AND ANALYSIS OF NON-VOLATILE MEMORY, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUL-2010			-				
SL 737-SL-21-089	OUTFLOW VALVE; ATTACHMENT CLAMP;BOLT-INTERFERENCE CONDITION (SUPERSEDED BY SL 737-SL-21-089 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
26-JUL-2011			-				
SL 737-SL-21-089 REV. A	OUTFLOW VALVE; ATTACHMENT CLAMP;BOLT-INTERFERENCE CONDITION, SERVICE LETTER					RECOMMENDED	
		MOS					
19-MAR-2013			-				
SL 737-SL-21-091	AIR CONDITIONING TEMPERATURE CONTROL VALVE IMPROVEMENT (SUPERSEDED BY SL 737-SL-21-091 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-091 REV. A	AIR CONDITIONING TEMPERATURE CONTROL VALVE IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
04-SEP-2013			-				
SL 737-SL-21-092	CABIN ENVIRONMENTAL QUALITY - INFECTION CONTROL GUIDELINES, SERVICE LETTER					RECOMMENDED	
		MOS					
10-DEC-2012			-				
SL 737-SL-21-094	CABIN PRESSURE CONTROLLER, ADDITIONAL LAYER OF TAPE (ALOP) FOR COPPER TAPE PROTECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
30-MAY-2013			-				
SL 737-SL-21-095	ACMS "USER GUIDE" FOR ENHANCED PRESSURIZATION SYSTEM TROUBLESHOOTING AND HEALTH MANAGEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
02-APR-2014			-				

© Camp Systems

EFTA00618523

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-21-096	PACK DISCHARGE OVERHEAT SWITCH - POSSIBLE WRONG PART NUMBER INSTALLED, SERVICE LETTER					RECOMMENDED	
		MOS					
17-OCT-2013			-				
SL 737-SL-21-097	POSSIBLE UNDER-TORQUE OF THE GROUNDING JUMPER TO THE RAM AIR INLET ACTUATOR, SERVICE LETTER					RECOMMENDED	
		MOS					
03-MAR-2014			-				
SL 737-SL-21-099	SMART RAM AIR DOOR ACTUATOR (SRADA) - RAM AIR DOOR STATUS LIGHT ILLUMINATION - SUSPECT CONNECTOR BUILD (SUPERSEDED BY SL 737-SL-21-099 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-21-099 REV. A	SMART RAM AIR DOOR ACTUATOR (SRADA) - RAM AIR DOOR STATUS LIGHT ILLUMINATION - SUSPECT CONNECTOR BUILD, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUL-2014			-				
SL 737-SL-22-040	AUTOPILOT FLIGHT CONTROL COMPUTER IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-JAN-1999			- (s)				
SL 737-SL-22-040 REV. A	AUTOPILOT FLIGHT CONTROL COMPUTER IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-FEB-1999			- (s)				
SL 737-SL-22-040 REV. B	AUTOPILOT FLIGHT CONTROL COMPUTER IMPROVEMENTS., SERVICE LETTER					INFORMATIONAL	
		MOS					
10-FEB-2000			- (s)				
SL 737-SL-22-043	737 AUTO THROTTLE COMPUTER, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-MAR-2000			- (s)				
SL 737-SL-22-044	FCC SOFTWARE UPDATE (-705), SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAY-2000			- (s)				
SL 737-SL-22-045	AUTOTHROTTLE COMPUTER MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-SEP-2000			- (s)				
SL 737-SL-22-046	FCC HARDWARE UPDATE (P/N 10-62038-8)., SERVICE LETTER					INFORMATIONAL	
		MOS					
13-NOV-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-22-046 REV. A	FCC HARDWARE UPDATE (P/N 10-62038-8) (SUPERSEDED BY SL 737-SL-22-046 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-22-046 REV. B	FCC HARDWARE UPDATE (P/N 10-62038-8), SERVICE LETTER					RECOMMENDED	
		MOS					
21-OCT-2011			-				
SL 737-SL-22-047	FCC SOFTWARE UPDATE (-708), SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2001			- (s)				
SL 737-SL-22-048	AUTO THROTTLE COMPUTER MODIFICATION (-54), SERVICE LETTER					INFORMATIONAL	
		MOS					
05-MAR-2002			- (s)				
SL 737-SL-22-051	FCC SOFTWARE UPDATE(-709), SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JUN-2002			-				
SL 737-SL-22-052 REV. B	COLLINS ENHANCED DIGITAL FLIGHT CONTROL SYSTEM (SUPERSEDED BY SL 737-SL-22-052 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-22-052 REV. C	COLLINS ENHANCED DIGITAL FLIGHT CONTROL SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUL-2010			-				
SL 737-SL-22-053	COLLINS FCC SOFTWARE UPDATE (-120), SERVICE LETTER					INFORMATIONAL	
		MOS					
09-FEB-2004			-				
SL 737-SL-22-054	POTENTIAL CHAFFING OF W3397 WIRE BUNDLE TO M1020 ELEVATOR CONTROL "A", SERVICE LETTER					INFORMATIONAL	
		MOS					
17-JUN-2004			-				
SL 737-SL-22-054 REV. A	POTENTIAL CHAFFING OF W3397 WIRE BUNDLE TO M1020 ELEVATOR CONTROL "A", SERVICE LETTER					INFORMATIONAL	
		MOS					
02-JUL-2004			-				
SL 737-SL-22-054 REV. B	POTENTIAL CHAFFING OF W3397 WIRE BUNDLE TO M1020 ELEVATOR CONTROL "A", SERVICE LETTER					INFORMATIONAL	
		MOS					
03-NOV-2004			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-22-056 REV. A	COLLINS FCC SOFTWARE UPDATE (-130), SERVICE LETTER						
		MOS					
18-APR-2005			-				
SL 737-SL-22-056 REV. B	COLLINS FCC SOFTWARE UPDATE (-130), SERVICE LETTER					INFORMATIONAL	
		MOS					
21-SEP-2005			-				
SL 737-SL-22-057	COLLINS FCC SOFTWARE UPDATE (-140), SERVICE LETTER						
		MOS					
04-AUG-2006			-				
SL 737-SL-22-058	HONEYWELL FCC SOFTWARE UPDATE (-710), SERVICE LETTER						COMPLIED WITH
		MOS		22-AUG-2008			
09-AUG-2007			-	3260:48			
		AFL		782			
SL 737-SL-22-059	COLLINS FCC SOFTWARE UPDATE (P5.0), SERVICE LETTER						
		MOS					
29-JUN-2007			-				
SL 737-SL-22-060	CAT IIIB AUTOPILOT ROLLOUT RUDDER POSITION TRANSMITTER - MISSING LOCKWIRE, SERVICE LETTER						
		MOS					
19-FEB-2008			-				
SL 737-SL-22-061	FIRST OFFICER'S PITCH CONTROL WHEEL STEERING FORCE TRANSDUCER WIRE CONTACTING NEARBY WIRE BUNDLE CLAMP HARDWARE, SERVICE LETTER					RECOMMENDED	
		MOS					
04-MAY-2011			-				
SL 737-SL-22-062	COLLINS FCC SOFTWARE UPDATE (P7.0) (SUPERSEDED BY SL 737-SL-22-062 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-22-062 REV. A	COLLINS FCC SOFTWARE UPDATE (P7.0), SERVICE LETTER					RECOMMENDED	
		MOS					
17-OCT-2012			-				
SL 737-SL-22-063	ROCKWELL COLLINS FCC HARDWARE UPDATE - P/N'S 822-1604-102 AND -152, SERVICE LETTER					RECOMMENDED	
		MOS					
05-FEB-2013			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-22-064	AUTOTHROTTLE COMPUTER MODIFICATION (P/N 10-62017-55) (SUPERSEDED BY 737-SL-22-064 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-22-064 REV. A	AUTOTHROTTLE COMPUTER MODIFICATION (P/N 10-62017-55), SERVICE LETTER						
			MOS					
				-				
SL	737-SL-23-01	PASSENGER ADDRESS AMPLIFIER MODIFICATION , SERVICE LETTER						
			MOS					
	16-MAY-1990			-				
SL	737-SL-23-020	VHF 8.33 KHZ CHANNEL SPACING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	16-SEP-1997			- (s)				
SL	737-SL-23-020 REV. A	VHF 8.33 KHZ CHANNEL SPACING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	16-DEC-1997			- (s)				
SL	737-SL-23-020 REV. B	VHF 8.33 KHZ CHANNEL SPACING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	28-MAY-1998			- (s)				
SL	737-SL-23-020 REV. C	VHF 8.33 KHZ CHANNEL SPACING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	28-MAY-1998			- (s)				
SL	737-SL-23-021	HF ANTENNA COUPLER RELIABILITY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-MAR-1998			- (s)				
SL	737-SL-23-021 REV. A	HF ANTENNA COUPLER RELIABILITY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	09-APR-1998			- (s)				
SL	737-SL-23-021 REV. B	HF ANTENNA COUPLER RELIABILITY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	02-NOV-1998			- (s)				

© Camp Systems

EFTA00618527

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-23-023	RADIO COMMUNICATION COMPLIANT PINS, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-DEC-1998			- (s)				
SL 737-SL-23-024	COMMUNICATIONS-HF AUDIO DISTORTION ON OPPOSITE HF, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-MAR-1999			- (s)				
SL 737-SL-23-024 REV. A	COMMUNICATIONS-HF AUDIO DISTORTION ON OPPOSITE HF, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-MAY-1999			- (s)				
SL 737-SL-23-025	COMMANDED FREQUENCY CHANGE, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-APR-2000			- (s)				
SL 737-SL-23-025 REV. A	COMMANDED FREQUENCY CHANGE., SERVICE LETTER					INFORMATIONAL	
		MOS					
23-JAN-2001			- (s)				
SL 737-SL-23-026	LOSS OF ESSENTIAL LEVELS VHF COMMUNICATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-APR-1999			- (s)				
SL 737-SL-23-026 REV. A	LOSS OF ESSENTIAL LEVELS VHF COMMUNICATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-MAY-1999			- (s)				
SL 737-SL-23-026 REV. B	LOSS OF ESSENTIAL LEVELS VHF COMMUNICATIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-AUG-1999			- (s)				
SL 737-SL-23-027	SEAT ELECTRONICS BOX (SEB) MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
05-AUG-1999			- (s)				
SL 737-SL-23-028	VHF ANTENNA CONNECTION CHANGE, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2001			- (s)				
SL 737-SL-23-028 REV. A	VHF ANTENNA CONNECTION CHANGE, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2001			- (s)				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-23-029	INTERPHONE SYSTEM - REMOTE ELECTRONICS UNIT MODIFICATION, SERVICE LETTER					INFORMATIONAL	
	15-AUG-2000		MOS	- (s)				
SL	737-SL-23-030	BOEING RADIO COMMUNICATIONS PANEL UPGRADE TO P/N 285U0037-61X, SERVICE LETTER					INFORMATIONAL	
	21-SEP-2000		MOS	- (s)				
SL	737-SL-23-030 REV. B	COMMUNICATIONS - BOEING RADIO COMMUNICATIONS PANEL (RCP) UPGRADE TO P/N 285U0037-61X, SERVICE LETTER					INFORMATIONAL	
	10-AUG-2001		MOS	- (s)				
SL	737-SL-23-031	CABIN ATTENDANT HANDSET/FLIGHT DECK HANDSET, P/N 285W0024, SHELL REPLACEMENT., SERVICE LETTER					INFORMATIONAL	
	04-DEC-2000		MOS	- (s)				
SL	737-SL-23-031 REV. A	CABIN ATTENDANT HANDSET/FLIGHT DECK HANDSET, P/N 285W0024, SHELL REPLACEMENT., SERVICE LETTER					INFORMATIONAL	
	04-APR-2001		MOS	- (s)				
SL	737-SL-23-032 REV. A	AUDIO - REMOTE ELECTRONICS UNIT (REU) P/N 10-62090-121 (AVTECH P/N 5340-1-1), SERVICE LETTER					INFORMATIONAL	
	19-OCT-2001		MOS	- (s)				
SL	737-SL-23-032 REV. B	AUDIO-REMOTE ELECTRONICS UNIT P/N 10-62090-121 (AVTECH P/N 5340-1-1), SERVICE LETTER					INFORMATIONAL	
	27-NOV-2002		MOS	-				
SL	737-SL-23-032 REV. C	AUDIO-REMOTE ELECTRONICS UNIT P/N 10-62090-121 (AVTECH P/N 5340-1-1), SERVICE LETTER					INFORMATIONAL	
	15-OCT-2003		MOS	-				
SL	737-SL-23-033	AUDIO CONTROL PANEL, P5-15, INTERFERENCE WITH SCREW, SERVICE LETTER					INFORMATIONAL	
	01-APR-2002		MOS	- (s)				
SL	737-SL-23-033 REV. A	AUDIO CONTROL PANEL, P5-15, INTERFERENCE WITH SCREW, SERVICE LETTER					INFORMATIONAL	
	26-NOV-2002		MOS	-				
SL	737-SL-23-035	HIGH FREQUENCY TRANSCEIVER, SERVICE LETTER					INFORMATIONAL	
	16-JUL-2002		MOS	- (s)				

© Camp Systems

EFTA00618529

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-23-036	MULTI-INPUT INTERACTIVE DISPLAY UNIT (MIDU) P/N 964-0443-002/-003 MODIFICATION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	19-SEP-2003			-				
SL	737-SL-23-037	GABLES NEW RADIO TUNING PANEL (RTP) P/N G7404-12X, SERVICE LETTER					INFORMATIONAL	
			MOS					
	15-OCT-2003			-				
SL	737-SL-23-037 REV. B	GABLES NEW RADIO TUNING PANEL (RTP) P/N G7404-12X, SERVICE LETTER						
			MOS					
	09-JAN-2009			-				
SL	737-SL-23-038	ARINC EUROPEAN VHF REQUENCY CHANGE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	10-SEP-2004			-				
SL	737-SL-23-038 REV. A	ARINC EUROPEAN VHF FREQUENCY CHANGE, SERVICE LETTER						COMPLIED WITH
			MOS			28-APR-2006		
	10-MAY-2005			-		2606:18		
			AFL			626		
SL	737-SL-23-038 REV. B	ARINC EUROPEAN VHF FREQUENCY CHANGE, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-AUG-2009			-				
SL	737-SL-23-039	UNCOMMANDED CHANGE OF VHF COMMUNICATIONS FREQUENCY, SERVICE LETTER					INFORMATIONAL	
			MOS					
	03-NOV-2004			-				
SL	737-SL-23-040	PASSENGER ADDRESS (PA) POPPING/CRACKLING SOUND, SERVICE LETTER						
			MOS					
	28-FEB-2005			-				
SL	737-SL-23-041	VHF NUMBER TWO ANTENNA CONNECTORS DISCONNECTING, SERVICE LETTER						
			MOS					
	11-OCT-2006			-				
SL	737-SL-23-042	VHF-2100 COM TRANSCEIVER - KEY EVENT SIGNAL LEVEL CORRECTION, SERVICE LETTER						
			MOS					
	21-SEP-2007			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-23-043	VHF-920 DATA RADIO (822-1250-002) - MODE LOCK-UP CONDITION, SERVICE LETTER						
		MOS					
12-JAN-2009			-				
SL 737-SL-23-043 REV. A	VHF-920 DATA RADIO (822-1250-002) - MODE LOCK-UP CONDITION, SERVICE LETTER					RECOMMENDED	
		MOS					
09-JUL-2009			-				
SL 737-SL-23-044	NOISE ON SERVICE INTERPHONE, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JAN-2010			-				
SL 737-SL-23-044 REV. A	NOISE ON SERVICE INTERPHONE (SUPERSEDED BY 737-SL-23-044-B), SERVICE LETTER					SUPERSEDED	
		MOS					
26-JAN-2010			-				
SL 737-SL-23-044 REV. B	NOISE ON SERVICE INTERPHONE, SERVICE LETTER						
		MOS					
13-MAY-2010			-				
SL 737-SL-23-045	MISWIRING OF TERMINAL BLOCKS IN CVR SELF-TEST WIRING, SERVICE LETTER					RECOMMENDED	
		MOS					
22-DEC-2010			-				
SL 737-SL-23-046	BOEING SKY INTERIOR ATTENDANT CONTROL PANEL SOFTWARE IMPROVEMENTS-LOCK UPS AND UN-COMMANDED LIGHT CHANGES (SUPERSEDED BY SL 737-SL-23-046 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-23-046 REV. A	BOEING SKY INTERIOR ATTENDANT CONTROL PANEL SOFTWARE IMPROVEMENTS-LOCK UPS AND UN-COMMANDED LIGHT CHANGES, SERVICE LETTER					RECOMMENDED	
		MOS					
18-OCT-2011			-				
SL 737-SL-23-047	INTERPHONE (INT) SYSTEM NOISE, SERVICE LETTER					RECOMMENDED	
		MOS					
17-JUL-2013			-				
SL 737-SL-23-048	POSSIBLE INCORRECT ORIENTATION OF GROUND CREW CALL HORN, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAY-2014			-				

© Camp Systems

EFTA00618531

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-111 REV. A	MAIN WHEEL WELL JUNCTION BOX, SERVICE LETTER					INFORMATIONAL	
08-SEP-2000		MOS	- (s)				
SL 737-SL-24-111 REV. B	MAIN WHEEL WELL JUNCTION BOX WIRE CHAFING, SERVICE LETTER					INFORMATIONAL	
16-JAN-2001		MOS	- (s)				
SL 737-SL-24-111 REV. C	MAIN WHEEL WELL JUNCTION BOX WIRE CHAFING, SERVICE LETTER					INFORMATIONAL	
22-AUG-2001		MOS	- (s)				
SL 737-SL-24-111 REV. D	MAIN WHEEL WELL JUNCTION BOX WIRE CHAFING, SERVICE LETTER					INFORMATIONAL	
28-NOV-2001		MOS	- (s)				
SL 737-SL-24-111 REV. E	MAIN WHEEL WELL JUNCTION BOX WIRE CHAFING (SUPERSEDED BY SL 737-SL-24-111 REV. F), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-24-111 REV. F	MAIN WHEEL WELL JUNCTION BOX WIRE CHAFING, SERVICE LETTER					RECOMMENDED	
21-AUG-2012		MOS	-				
SL 737-SL-24-125	CHECK SCREWS ATTACHING FEEDER TERMINALS TO RIGID BUS IN POWER DISTRIBUTION PANELS, SERVICE LETTER					INFORMATIONAL	
05-NOV-1998		MOS	- (s)				
SL 737-SL-24-125 REV. A	CHECK SCREWS ATTACHING FEEDER TERMINALS TO RIGID BUS IN POWER DISTRIBUTION PANELS, SERVICE LETTER					INFORMATIONAL	
05-JAN-1999		MOS	- (s)				
SL 737-SL-24-133	FUELING VALVE WIRE CHAFING, SERVICE LETTER					INFORMATIONAL	
23-FEB-1999		MOS	- (s)				
SL 737-SL-24-136 REV. A	INSPECTION FOR WIRE CHAFING CONDITION IN P5 PANEL, SERVICE LETTER					INFORMATIONAL	
30-AUG-1999		MOS	- (s)				
SL 737-SL-24-136 REV. B	P-5 PANEL WIRE CHAFING INSPECTION/PROTECTION, SERVICE LETTER					INFORMATIONAL	
17-NOV-2000		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-136 REV. C	INSPECTION FOR WIRE CHAFING CONDITION IN P5 PANEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-JUN-2001			- (s)				
SL 737-SL-24-137	WIRE BUNDLE RIDING FLAP CONTROL CABLE., SERVICE LETTER					INFORMATIONAL	
		MOS					
26-APR-1999			- (s)				
SL 737-SL-24-139	BATTERY CHARGER MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-MAY-1999			- (s)				
SL 737-SL-24-140	SPARE CONNECTOR CAVITIES NOT SEALED, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JUN-1999			- (s)				
SL 737-SL-24-141	POWER FEEDER WIRE BUNDLE CHAFED AGAINST FILTER ON ENGINE, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JUN-1999			- (s)				
SL 737-SL-24-141 REV. A	POWER FEEDER WIRE BUNDLE CHAFED AGAINST FILTER ON ENGINE, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-OCT-1999			- (s)				
SL 737-SL-24-142	STANDOFF NOT INSTALLED IN MAIN WHEEL WELL, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JUN-1999			- (s)				
SL 737-SL-24-143	, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JUN-1999			- (s)				
SL 737-SL-24-143 REV. A	, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-SEP-1999			- (s)				
SL 737-SL-24-143 REV. B	WIRE BUNDLE RIDING IN LEFT WING STINT, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-DEC-1999			- (s)				
SL 737-SL-24-144	DUAL BATTERY AND STATIC INVERTER REMOTE CONTROLLED CIRCUIT BREAKER INSTALLATION ERRORS, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JUN-1999			- (s)				

© Camp Systems

EFTA00618533

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-145	WIRE BUNDLE RIDESACOUSTIC FIBER, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-AUG-1999			- (s)				
SL 737-SL-24-146	POWER DISTRIBUTION PANEL, P92, INSPECTION & MODIFICATION OF RIGID BUS ASSEMBLY, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-SEP-1999			- (s)				
SL 737-SL-24-146 REV. A	POWER DISTRIBUTION PANEL, P92, INSPECTION & MODIFICATION OF RIGID BUS ASSEMBLY, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-SEP-1999			- (s)				
SL 737-SL-24-147	BPCU MODIFICATION TO PREVENT POTENTIAL LOSS OF POWER TO A TRANSFER BUS WHEN CONNECTING GROUND POWER, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-SEP-1999			- (s)				
SL 737-SL-24-147 REV. A	BUS POWER CONTROL UNIT (BPCU) MODIFICATION TO PREVENT POTENTIAL LOSS OF POWER TO A TRANSFER BUS WHEN CONNECTING GROUND POWER, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JUL-2002			- (s)				
SL 737-SL-24-149	DUAL BATTERY CABLE LENGTH, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-OCT-1999			- (s)				
SL 737-SL-24-150	WIRE BUNDLES RIDING P15 REFUELING PANEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-OCT-1999			- (s)				
SL 737-SL-24-152	RIDING CONDITION OF THE COAXIAL CABLE ON THE KEEL BEAM STRUCTURE, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-NOV-1999			- (s)				
SL 737-SL-24-153	FUEL SHUTOFF VALVE WIRE CHAFING AGAINST THE RIGHT HYDRAULIC ACOUSTIC FILTER BRACKET BOLT IN THE WHEEL WELL., SERVICE LETTER					INFORMATIONAL	
		MOS					
16-NOV-1999			- (s)				
SL 737-SL-24-153 REV. A	FUEL SHUTOFF VALVE WIRE CHAFING AGAINST THE RIGHT HYDRAULIC ACOUSTIC FILTER BRACKET BOLT IN THE WHEEL WELL., SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JAN-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-154 REV. B	BATTERY CHARGER INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-SEP-2002			-				
SL 737-SL-24-156	UNPROTECTED WIRE BUNDLES IN P8 & P9 PANELS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-DEC-1999			- (s)				
SL 737-SL-24-156 REV. A	UNPROTECTED WIRE BUNDLES IN P8 & P9 PANELS, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-APR-2000			- (s)				
SL 737-SL-24-157 REV. A	WIRE BUNDLES RIDING HYDRAULIC TUBE IN WHEEL WELL, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-OCT-2000			- (s)				
SL 737-SL-24-158	LANDING GEAR DOWN LOCK SENSOR- POTENTIAL WIRE CHAFING, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-JAN-2000			- (s)				
SL 737-SL-24-162	POTENTIAL WIRE INTERFERENCE WITH HYDRAULIC LINE IN THE REFUELING PANEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-JUL-2000			- (s)				
SL 737-SL-24-163	POTENTIAL WIRE RIDING CONDITION IN NOSE GEAR WHEEL WELL AREA, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-AUG-2000			- (s)				
SL 737-SL-24-164	EXTERNAL POWER RECEPTACLE - IMPROVED RETENTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-OCT-2001			- (s)				
SL 737-SL-24-165	STATIC INVERTER MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-OCT-2000			- (s)				
SL 737-SL-24-165 REV. A	STATIC INVERTER MODIFICATION TO REDUCE THE POTENTIAL FOR OVERHEATING, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-MAY-2003			-				
SL 737-SL-24-165 REV. B	STATIC INVERTER MODIFICATION TO REDUCE THE POTENTIAL FOR OVERHEATING (SUPERSEDED BY THE LATEST REVISION OF 737-SL-24-183), SERVICE LETTER					SUPERSEDED	
		MOS					
03-APR-2007			-				

© Camp Systems

EFTA00618535

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-167	STANDBY POWER CONTROL UNIT (SPCU) IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-APR-2001			- (s)				
SL 737-SL-24-168	GROUND SERVICE BUS 28VAC TRANSFORMER WIRES-POTENTAL CHAFING ON FRAME, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-MAY-2001			- (s)				
SL 737-SL-24-168 REV. A	GROUND SERVICE BUS 28VAC TRANSFORMER WIRES - POTENTIAL CHAFING ON FRAME, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-DEC-2001			- (s)				
SL 737-SL-24-169	INTEGRATED DRIVE GENERATOR (IDG) RETENTION LANYARDS CHAFING (SUPERSEDED BY SL 737-SL-24-169 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-24-169 REV. A	INTEGRATED DRIVE GENERATOR (IDG) RETENTION LANYARDS CHAFING, SERVICE LETTER						
		MOS					
			-				
SL 737-SL-24-170	WIRE BUNDLE RIDING AIRSTAIR RAIL, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-SEP-2001			- (s)				
SL 737-SL-24-171	CORROSION PROTECTION OF ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL. (SUPERSEDED BY 737-SL-24-171 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
31-OCT-2001			- (s)				
SL 737-SL-24-171 REV. A	CORROSION PROTECTION OF ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (SUPERSEDED BY 737-SL-24-171 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
21-AUG-2003			- (s)				
SL 737-SL-24-171 REV. B	CORROSION PROTECTION OF ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL, SERVICE LETTER						
		MOS	24 (s)				
24-JUN-2005							
SL 737-SL-24-175	INTERGRATED DRIVE GENERATOR-MAIN ROTOR, EXCITER ROTOR, CHARGE RELIEF VALVE, AND INPUT SHAFT SEAL IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-NOV-2002			- (s)				

© Camp Systems

EFTA00618536

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-176	WINGTIP WIRING CHAFING-INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2002			-				
SL 737-SL-24-176 REV. B	WINGTIP WIRING CHAFING - INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-DEC-2003			-				
SL 737-SL-24-177	BATTERY RESTORATION REQUIREMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-MAY-2003			-				
SL 737-SL-24-178	INSTALLATION MODIFICATION TO PREVENT LANYARD CHAFING, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-JUL-2003			-				
SL 737-SL-24-178 REV. A	INTEGRATED DRIVE GENERATOR - INSTALLATION MODIFICATION TO PREVENT LANYARD CHAFING, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-JAN-2004			-				
SL 737-SL-24-179	FLIGHT DECK P5 OVERHEAD RUBBER SWITCH TIP P/N'S, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-AUG-2003			-				
SL 737-SL-24-180	INTEGRATED DRIVE GENERATOR-MAIN STATOR SHORT CIRCUIT, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-OCT-2003			-				
SL 737-SL-24-181	WIRE BUNDLE CHAFING AT STATION 671 AILERON CONTROL QUADRANT, SERVICE LETTER						
		MOS					
23-FEB-2004			-				
SL 737-SL-24-181 REV. A	WIRE BUNDLE CHAFING AT STATION 671 SPOILER CONTROL QUADRANT, SERVICE LETTER						
		MOS					
13-SEP-2004			-				
SL 737-SL-24-182	STANDBY POWER CONTROL UNIT (SPCU) K1 & K8 RELAY IMPROVEMENTS, SERVICE LETTER						
		MOS					
12-JAN-2006			-				
SL 737-SL-24-183	STATIC INVERTER MODIFICATION TO REDUCE THE POTENTIAL FOR OVERHEATING, SERVICE LETTER						
		MOS					
09-DEC-2005			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-183 REV. A	STATIC INVERTER MODIFICATION TO REDUCE THE POTENTIAL FOR OVERHEATING, SERVICE LETTER						
		MOS					
03-APR-2007			-				
SL 737-SL-24-184	STATIC INVERTER TRANSISTOR REPLACEMENT, SERVICE LETTER						
		MOS					
09-FEB-2006			-				
SL 737-SL-24-185	UPGRADE OF MAIN WHEEL WELL ELECTRICAL CONNECTORS, SERVICE LETTER						
		MOS					
27-MAR-2006			-				
SL 737-SL-24-185 REV. A	UPGRADE OF MAIN WHEEL WELL ELECTRICAL CONNECTORS, SERVICE LETTER						
		MOS					
22-MAY-2006			-				
SL 737-SL-24-185 REV. B	UPGRADE OF MAIN WHEEL WELL ELECTRICAL CONNECTORS, SERVICE LETTER						
		MOS					
11-SEP-2006			-				
SL 737-SL-24-186	LEACH TIME DELAY RELAY DISCLOSURE, SERVICE LETTER					RECOMMENDED	
		MOS					
09-MAR-2012			-				
SL 737-SL-24-187	CIC NOT APPLIED TO CONNECTOR D46038P, SERVICE LETTER						
		MOS					
09-JAN-2007			-				
SL 737-SL-24-188	DRAIN MAST HEATER WIRE CHAFING, SERVICE LETTER						
		MOS					
09-APR-2007			-				
SL 737-SL-24-188 REV. A	DRAIN MAST HEATER WIRE CHAFING, SERVICE LETTER						COMPLIED WITH
		MOS		29-AUG-2011			
18-MAY-2007			-	3533:32			
		AFL		863			
SL 737-SL-24-189	INTEGRATED DRIVE GENERATOR - DIFFERENTIAL PRESSURE INDICATOR CHECK - ALTERNATE PROCEDURE, SERVICE LETTER						
		MOS					
03-DEC-2007			-				
SL 737-SL-24-190	NON-CONFORMING KINGS COAX CONNECTORS, SERVICE LETTER						
		MOS					
17-JAN-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-190 REV. A	NON-CONFORMING KINGS COAX CONNECTORS, SERVICE LETTER						
		MOS					
15-JUL-2008			-				
SL 737-SL-24-192	W1022/W1032 WIRE BUNDLE CHAFING NEAR FLAP TRACK BEAM, SERVICE LETTER						
		MOS					
24-JAN-2008			-				
SL 737-SL-24-192 REV. A	W1022/W1032 WIRE BUNDLE CHAFING NEAR FLAP TRACK BEAM, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-24-193	ELECTRICAL BRACKET ASSEMBLY INSTALLED INCORRECTLY, SERVICE LETTER						
		MOS					
28-JAN-2009			-				
SL 737-SL-24-194	BACC65BL EXTERNAL POWER RECEPTACLE - CONTACTS BREAKING (SUPERSEDED BY SL 737-SL-24-194 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-24-194 REV. A	BACC65BL EXTERNAL POWER RECEPTACLE - CONTACTS BREAKING, SERVICE LETTER					RECOMMENDED	
		MOS					
13-SEP-2011			-				
SL 737-SL-24-195	CIRCUIT BREAKER TERMINAL SCREWS INSPECTION AND REPLACEMENT (SUPERSEDED BY 737-SL-24-195-A), SERVICE LETTER					SUPERSEDED	
		MOS					
15-FEB-2010			-				
SL 737-SL-24-195 REV. A	CIRCUIT BREAKER TERMINAL SCREWS INSPECTION AND REPLACEMENT (SUPERSEDED BY SL 737-SL-24-195 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-24-195 REV. B	CIRCUIT BREAKER TERMINAL SCREWS INSPECTION AND REPLACEMENT, SERVICE LETTER						
		MOS					
15-JUL-2010			-				
SL 737-SL-24-196	EXTERNAL POWER RECEPTACLE CRACKING (SUPERSEDED BY SL 737-SL-24-196 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-196 REV. A	EXTERNAL POWER RECEPTACLE CRACKING, SERVICE LETTER					RECOMMENDED	
		MOS					
05-OCT-2011			-				
SL 737-SL-24-197	ELECTRIC MOTOR DRIVEN HYDRAULIC CIRCUIT BREAKER TRIPPING (SUPERSEDED BY SL 737-SL-24-197 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-24-197 REV. A	ELECTRIC MOTOR DRIVEN HYDRAULIC CIRCUIT BREAKER TRIPPING, SERVICE LETTER					RECOMMENDED	
		MOS					
20-MAR-2012			-				
SL 737-SL-24-198	POTENTIALLY INCORRECT CIRCUIT BREAKERS INSTALLED FOR STICK SHAKER AND MACH WARNING SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
28-JAN-2011			-				
SL 737-SL-24-200	FIRE PANEL WIRE INSTALLATION (SUPERSEDED BY SL 737-SL-24-200 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-24-200 REV. A	FIRE PANEL WIRE INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
13-SEP-2011			-				
SL 737-SL-24-201	POWER DISTRIBUTION PANEL - P91, UNUSED WIRE TERMINAL SLEEVES, SERVICE LETTER					RECOMMENDED	
		MOS					
08-DEC-2011			-				
SL 737-SL-24-202	GEN DRIVE STANDBY POWER TOGGLE SWITCH GUARD IS FOUND NOT FULLY ENGAGED TO AUTO POSITION, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAR-2012			-				
SL 737-SL-24-204	POSSIBLE MISLOCATED WIRE BUNDLE CLAMPS IN MAIN WHEEL WELL (SUPERSEDED BY SL 737-SL-24-204 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-24-204 REV. A	POSSIBLE MISLOCATED WIRE BUNDLE CLAMPS IN MAIN WHEEL WELL (SUPERSEDED BY SL 737-SL-24-204 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-24-204 REV. B	POSSIBLE MISLOCATED WIRE BUNDLE CLAMPS IN MAIN WHEEL WELL, SERVICE LETTER					RECOMMENDED	
		MOS					
27-AUG-2013			-				
SL 737-SL-24-205	IDG LANYARD ADJUSTMENT TO PREVENT CHAFING ON IDG SERVICING ACCESS DOOR, SERVICE LETTER					RECOMMENDED	
		MOS					
16-NOV-2012			-				
SL 737-SL-24-206	STANDBY POWER CONTROL UNIT - K1 AND K8 RELAY IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
26-JUN-2013			-				
SL 737-SL-24-207	ENVIRONMENTAL PROTECTION OF ELECTRICAL COMPONENTS IN WHEEL WELL AND WING, SERVICE LETTER					RECOMMENDED	
		MOS					
08-JUL-2013			-				
SL 737-SL-24-208	IDG BARE BORE BLOCKS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-AUG-2013			-				
SL 737-SL-24-209	STATIC INVERTER INSTALLATION - TERMINAL TORQUE, SERVICE LETTER					RECOMMENDED	
		MOS					
17-MAR-2014			-				
SL 737-SL-25-051 REV. D	LOWER CARGO COMPARTMENT LINER REPAIRS, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-DEC-2001			- (s)				
SL 737-SL-25-051 REV. E	LOWER CARGO COMPARTMENT LINER REPAIRS, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-MAR-2002			- (s)				
SL 737-SL-25-051 REV. F	LOWER CARGO COMPARTMENT LINER REPAIRS, SERVICE LETTER						
		MOS					
05-NOV-2004			-				
SL 737-SL-25-073	OVERHEAD STOWAGE BIN SYSTEM CONTENT RETENTION., SERVICE LETTER					INFORMATIONAL	
		MOS					
12-MAR-1997			- (s)				
SL 737-SL-25-073 REV. A	OVERHEAD STOWAGE BIN SYSTEM CONTENT RETENTION., SERVICE LETTER					INFORMATIONAL	
		MOS					
23-JUN-1997			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-073 REV. B	OVERHEAD STOWAGE BIN SYSTEM CONTENT RETENTION., SERVICE LETTER					INFORMATIONAL	
		MOS					
26-MAR-1999			- (s)				
SL 737-SL-25-076	INSTALLATION OF FELT TO PREVENT WATER DRIPPAGE INTO THE PASSENGER CABIN, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-JAN-1998			- (s)				
SL 737-SL-25-077	PREVENTING CONTAMINATION THAT AFFECTS FLAMMABILITY OF INSULATION BLANKETS, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-MAR-1998			- (s)				
SL 737-SL-25-078 REV. A	RESCU 406 EMERGENCY LOCATOR TRANSMITTER (ELT) INSTALLATION, SERVICE LETTER						
		MOS					
03-JUN-2008			-				
SL 737-SL-25-079	GALLEY OVEN MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-JUL-1998			- (s)				
SL 737-SL-25-082	EMI FILTER REPLACEMENT B/E AEROSPACE AIR CHILLERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-DEC-1998			- (s)				
SL 737-SL-25-082 REV. A	EMI FILTER REPLACEMENT B/E AEROSPACE AIR CHILLERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-JAN-1999			- (s)				
SL 737-SL-25-082 REV. B	EMI FILTER REPLACEMENT B/E AEROSPACE AIR CHILLERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
06-AUG-1999			- (s)				
SL 737-SL-25-084	JAMCO GALLEY ELECTRICAL WIRE TERMINAL FASTENERS INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
05-MAR-1999			- (s)				
SL 737-SL-25-085	IMPROVED OVERHEAD STOW BIN LATCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-APR-1999			- (s)				
SL 737-SL-25-087	FLIGHT CREW SEAT ADJUSTMENT HANDLE, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-JUL-1999			- (s)				

© Camp Systems

EFTA00618542

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-088	LAV BI-FOLD DOOR IMPROVEMENTS TO EASE EMERGENCY REMOVAL, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JUL-1999			- (s)				
SL 737-SL-25-089	AVIO INTERIORS PASSENGER SEAT TRAC REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-MAR-1999			- (s)				
SL 737-SL-25-089 REV. A	AVIO INTERIORS PASSENGER SEAT TRAC REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-AUG-1999			- (s)				
SL 737-SL-25-092 REV. A	OVERHEAD STOWAGE BIN DOOR STRIKE ASSEMBLY MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-JUL-2000			- (s)				
SL 737-SL-25-093 REV. B	LAVATORY DOOR LATCH IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-AUG-2000			- (s)				
SL 737-SL-25-094 REV. B	CARGO NET USE - LOWER LOBE, SERVICE LETTER						
		MOS					
27-OCT-2006			-				
SL 737-SL-25-094 REV. C	CARGO NET USE - LOWER LOBE, SERVICE LETTER						
		MOS					
24-JUL-2007			-				
SL 737-SL-25-096	LOWER CARGO COMPARTMENT LINER AND FLOOR PANEL REPLACEMENT., SERVICE LETTER					INFORMATIONAL	
		MOS					
26-APR-2001			- (s)				
SL 737-SL-25-096 REV. A	LOWER CARGO COMPARTMENT LINER AND FLOOR PANEL REPLACEMENT., SERVICE LETTER					INFORMATIONAL	
		MOS					
05-JUN-2001			- (s)				
SL 737-SL-25-096 REV. B	LOWER CARGO COMPARTMENT LINER AND FLOOR PANEL REPLACEMENT (SUPERSEDED BY SL 737-SL-25-096 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-096 REV. C	LOWER LOBE CARGO COMPARTMENT LINER AND FLOOR PANEL REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
10-MAR-2011			-				

© Camp Systems

EFTA00618543

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-097	REMOVAL OF FUSELAGE CARGO COMPARTMENT INSULATION BLANKETS, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-AUG-2001			- (s)				
SL 737-SL-25-098	FLIGHT DECK SUITCASE RESTRAINT STRAP CLIP INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-JUL-2001			- (s)				
SL 737-SL-25-099	FLIGHT DECK NO.2 SLIDING WINDOW LINING ASSEMBLY INTERFERENCE WITH CIRCUIT BREAKER PANEL, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-AUG-2001			- (s)				
SL 737-SL-25-100	FORWARD CARGO LOADING/UNLOADING PRECAUTIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-SEP-2001			- (s)				
SL 737-SL-25-100 REV. A	FORWARD CARGO LOADING/UNLOADING PERCAUTIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-OCT-2003			-				
SL 737-SL-25-100 REV. B	FORWARD CARGO LOADING/UNLOADING PRECAUTIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-OCT-2003			-				
SL 737-SL-25-100 REV. D	CARGO LOADING/UNLOADING PRECAUTIONS, SERVICE LETTER						
		MOS					
25-SEP-2007			-				
SL 737-SL-25-101	ESCAPE ROPE "SHELLING", SERVICE LETTER					INFORMATIONAL	
		MOS					
24-SEP-2001			- (s)				
SL 737-SL-25-103	SLIDING CARPET LOADING SYSTEM (SCLS) RAMP SEALING, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-JUN-2002			- (s)				
SL 737-SL-25-104	ATTENDANT SEAT MOUNTING BOLT MATERIAL, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-MAY-2002			- (s)				
SL 737-SL-25-104 REV. A	ATTENDANT SEAT MOUNTING BOLT MATERIAL, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JUL-2002			- (s)				

© Camp Systems

EFTA00618544

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-106	OUTBOARD GLARESHIELD LIGHTSHADE ASSEMBLY BREAKAGE., SERVICE LETTER					INFORMATIONAL	
		MOS					
03-OCT-2002			- (s)				
SL 737-SL-25-107	CLOSE OUT SEAL RETAINER, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-SEP-2002			-				
SL 737-SL-25-107 REV. A	CLOSE OUT SEAL RETAINER REPLACEMENT ON INTERIOR MONUMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-OCT-2002			-				
SL 737-SL-25-108	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE BIN AND FULL HEIGHT MONUMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-DEC-2002			-				
SL 737-SL-25-108 REV. A	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE BIN AND FULL HEIGHT MONUMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-APR-2003			-				
SL 737-SL-25-109	CABIN SIDEWALL AIR RETURN GRILLE INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-MAY-2003			-				
SL 737-SL-25-109 REV. A	CABIN SIDEWALL AIR RETURN GRILLE INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-JUL-2003			-				
SL 737-SL-25-111	FLIGHT DECK DRIP-SHIELD DRAIN TUBE INTERFERENCE WITH THE NUMBER 2 WINDOW, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-OCT-2003			-				
SL 737-SL-25-111 REV. A	FLIGHT DECK DRIP-SHIELD DRAIN TUBE INTERFERENCE WITH THE NUMBER 2 WINDOW, SERVICE LETTER						
		MOS					
01-FEB-2008			-				
SL 737-SL-25-112	AFT CARGO COMPARTMENT BLOWOUT PANEL REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
30-MAR-2004			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-114 REV. A	ATTENDANT SEAT RUBSTRIPS, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-2004			-				
SL 737-SL-25-115 REV. B	CARGO COMPARTMENT LINER TAPE AND FASTENERS, SERVICE LETTER						
		MOS					
11-JUL-2007			-				
SL 737-SL-25-116 REV. A	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE BINS, SERVICE LETTER						
		MOS					
16-DEC-2005			-				
SL 737-SL-25-116 REV. B	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE BINS, SERVICE LETTER						
		MOS					
30-MAR-2006			-				
SL 737-SL-25-117 REV. A	FORWARD CARGO CEILING PANEL PERMANENT REPAIR OPTIONS, SERVICE LETTER						
		MOS					
04-JAN-2005			-				
SL 737-SL-25-118	AVAILABILITY OF IMPROVED OXYGEN GENERATOR RELEASE PIN, SERVICE LETTER					INFORMATIONAL	
		MOS					
30-NOV-2004			-				
SL 737-SL-25-119 REV. A	OVERHEAD STOWAGE BIN LATCH BEZEL CRACKING, SERVICE LETTER					INFORMATIONAL	NOT APPLICABLE - -
		MOS					
23-MAR-2005			-				
SL 737-SL-25-120	IMPROVED CROWN INSULATION BLANKETS AT ANTENNA/LIGHT PENETRATIONS, SERVICE LETTER						
		MOS					
29-MAR-2005			-				
SL 737-SL-25-120 REV. B	IMPROVED CROWN INSULATION BLANKETS AT ANTENNA/LIGHT PENETRATIONS, SERVICE LETTER						
		MOS					
07-DEC-2005			-				
SL 737-SL-25-121	DUST CONTAMINATION - LRU CLEANING PROCEDURES, SERVICE LETTER						
		MOS					
12-JUL-2005			-				
SL 737-SL-25-122	ATTENDANT SEAT FASTENERS, SERVICE LETTER						NOT APPLICABLE
		MOS					
23-AUG-2005			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-25-123 REV. B	AIR STAIRS HANDRAIL FITTING ATTACHMENT TO YRC FWD LAVATORY, SERVICE LETTER						
			MOS	24 (s)				
	13-DEC-2005							
SL	737-SL-25-124	NEW FLAMMABILITY REQUIREMENT FOR THERMAL/ACOUSTIC INSULATION MATERIALS, SERVICE LETTER						
			MOS					
	06-JAN-2006			-				
SL	737-SL-25-124 REV. A	NEW FLAMMABILITY REQUIREMENT FOR THERMAL/ACOUSTIC INSULATION MATERIALS, SERVICE LETTER						
			MOS					
	13-APR-2006			-				
SL	737-SL-25-125	GALLEY AIR CHILLER RELIABILITY IMPROVEMENTS, SERVICE LETTER						
			MOS					
	28-APR-2006			-				
SL	737-SL-25-125 REV. A	GALLEY AIR CHILLER RELIABILITY IMPROVEMENTS, SERVICE LETTER						
			MOS					
	30-AUG-2006			-				
SL	737-SL-25-126	IMPROVING GALLEY REFRIGERATION PERFORMANCE AND RELIABILITY BEST PRACTICES, SERVICE LETTER						
			MOS					
	15-MAR-2007			-				
SL	737-SL-25-127	OVERHEAD STOWAGE BIN DOOR IMPROVEMENTS, SERVICE LETTER						
			MOS					
	01-OCT-2007			-				
SL	737-SL-25-128	CARGO COMPARTMENT BILGE TRAY - FUSELAGE SKIN DAMAGE, SERVICE LETTER						
			MOS					
	27-MAR-2008			-				
SL	737-SL-25-130	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE AND FULL HEIGHT MONUMENTS, SERVICE LETTER						
			MOS					
	08-DEC-2008			-				
SL	737-SL-25-130 REV. A	CLOSE OUT SEAL REPLACEMENT BETWEEN OVERHEAD STOWAGE AND FULL HEIGHT MONUMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	27-FEB-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-131	POSSIBLE DAMAGE TO E4-1 RACK SHROUD DRAIN TUBE, SERVICE LETTER						
		MOS					
24-OCT-2008			-				
SL 737-SL-25-132	GALLEY OVEN MODIFICATION, SERVICE LETTER						
		MOS					
19-DEC-2008			-				
SL 737-SL-25-132 REV. A	GALLEY OVEN MODIFICATION, SERVICE LETTER						
		MOS					
17-FEB-2009			-				
SL 737-SL-25-133	IMPROVED OXYGEN GENERATOR FITTING FOR 417N3011-SERIES PASSENGER SERVICE UNITS (SUPERSEDED BY SL 737-SL-25-133 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-133 REV. A	IMPROVED OXYGEN GENERATOR FITTING FOR 417N3011-SERIES PASSENGER SERVICE UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
10-SEP-2010			-				
SL 737-SL-25-134	GOODRICH 2110-SERIES FLIGHT ATTENDANT SEATBACK CRACKING, SERVICE LETTER						
		MOS					
21-AUG-2009			-				
SL 737-SL-25-135	INSULATION BLANKET REPAIR PROCEDURES - NEW THERMAL-ACOUSTIC INSULATION BLANKETS FOR FUSELAGE BURNTHROUGH STANDARDS, SERVICE LETTER					RECOMMENDED	
		MOS					
31-AUG-2009			-				
SL 737-SL-25-135 REV. A	INSULATION BLANKET REPAIR PROCEDURES - NEW THERMAL-ACOUSTIC INSULATION BLANKETS FOR FUSELAGE BURNTHROUGH STANDARDS, SERVICE LETTER					RECOMMENDED	
		MOS					
06-OCT-2009			-				
SL 737-SL-25-136	SELL OVEN INTERCHANGEABILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
23-SEP-2009			-				
SL 737-SL-25-137	FLIGHT DECK SIDE GRILLE MODIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
23-SEP-2009			-				

© Camp Systems

EFTA00618548

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-137 REV. A	FLIGHT DECK SIDE GRILLE MODIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-SEP-2009			-				
SL 737-SL-25-138	RESTRAINT SYSTEM WITH INERTIA REEL - MANUAL LOCK MAY BE INOPERABLE, SERVICE LETTER					RECOMMENDED	
		MOS					
19-OCT-2009			-				
SL 737-SL-25-138 REV. A	RESTRAINT SYSTEM WITH INERTIA REEL - MANUAL LOCK MAY BE INOPERABLE, SERVICE LETTER					RECOMMENDED	
		MOS					
11-NOV-2009			-				
SL 737-SL-25-139	DRIESSEN G1 GALLEY SHROUD COVER MODIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
27-OCT-2009			-				
SL 737-SL-25-140	RESCU 406(S) ELT ANTENNA RADIATION ISSUE, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-DEC-2009			-				
SL 737-SL-25-141	FOLD DOWN TABLE ASSEMBLY MECHANICAL LINKAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
30-JUL-2010			-				
SL 737-SL-25-142	737NG ESCAPE SLIDE VALISE RELEASE CABLE AND ASPIRATOR (SUPERSEDED BY SL 737-SL-25-142 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-142 REV. A	737NG ESCAPE SLIDE VALISE RELEASE CABLE AND ASPIRATOR, SERVICE LETTER					RECOMMENDED	
		MOS					
22-DEC-2010			-				
SL 737-SL-25-143	LRU EQUIPMENT DECALS SWAPPED ON E1-5 SHELF FOR VHF NO. 2 TRANSCEIVER AND DME NO.2 INTERROGATOR, SERVICE LETTER					RECOMMENDED	
		MOS					
23-DEC-2010			-				
SL 737-SL-25-144	ATTENDANT SERVICE UNIT - OXYGEN DOOR PANEL ASSEMBLY DESIGN IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
03-DEC-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-145	737 BSI OVERHEAD STOWAGE BIN BUCKET LATCH END ASSEMBLY FASTENERS, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2011			-				
SL 737-SL-25-146	RETENTION OF OXYGEN DOOR LATCH ACTUATOR FOR 417N3011-SERIES PASSENGER SERVICE UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2012			-				
SL 737-SL-25-148	EUROPEAN UNION (EU) RESTRICTION ON IMPORT OF CADMIUM IN PLASTICS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-DEC-2011			-				
SL 737-SL-25-149	BSI PIVOT STOWAGE BIN TORQUE TUBE COVER FASTENERS (SUPERSEDED BY SL SL737-SL-25-149 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-149 REV. A	BSI PIVOT STOWAGE BIN TORQUE TUBE COVER FASTENERS (SUPERSEDED BY SL 737-SL-25-149 REV. B), SERVICE LETTER					RECOMMENDED	
		MOS					
18-DEC-2012			-				
SL 737-SL-25-149 REV. B	BSI PIVOT STOWAGE BIN TORQUE TUBE COVER FASTENERS, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAR-2013			-				
SL 737-SL-25-150	HORIZONTAL BATWING TRIM DIS-BONDING BSI STOW BINS, SERVICE LETTER					RECOMMENDED	
		MOS					
06-AUG-2012			-				
SL 737-SL-25-152	FLIGHT DECK DRIP-SHIELD DRAIN TUBE INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAR-2013			-				
SL 737-SL-25-153	BOEING SKY INTERIOR (BSI) - SEAT ROW MARKER (SUPERSEDED BY SL 737-SL-25-153 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-153 REV. A	BOEING SKY INTERIOR (BSI) - SEAT ROW MARKER, SERVICE LETTER					RECOMMENDED	
		MOS					
22-MAY-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-25-155	YRC (YOKOHAMA RUBBER COMPANY) TOILET DOOR HANDLE MISSING LOCTITE, SERVICE LETTER					RECOMMENDED	
		MOS					
06-JUN-2013			-				
SL 737-SL-25-156	2ND OBSERVERS SEAT; REPLACEMENT OF THE FWD ATTACH BOLTS AND THE ATTACHMENT SCREWS IN THE FLT DECK CLOSET (SUPERSEDED BY 737-SL-25-156 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-156 REV. A	2ND OBSERVERS SEAT; REPLACEMENT OF THE FWD ATTACH BOLTS AND THE ATTACHMENT SCREWS IN THE FLT DECK CLOSET, SERVICE LETTER					RECOMMENDED	
		MOS					
30-JAN-2014			-				
SL 737-SL-25-157	CONNECTOR BACKSHELL POTENTIALLY RIDING BSI CEILING PANEL, SERVICE LETTER					RECOMMENDED	
		MOS					
02-JUN-2014			- (s)				
SL 737-SL-25-159	INTRODUCTION OF IMPROVED SIDEWALL WINDOW SHADES (SUPERSEDED BY SL 737-SL-25-159 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-25-159 REV. A	INTRODUCTION OF IMPROVED SIDEWALL WINDOW SHADES, SERVICE LETTER					RECOMMENDED	
		MOS					
16-MAY-2014			-				
SL 737-SL-25-160	BOEING SKY INTERIOR (BSI) - PASSENGER WINDOW REVEAL SHARP EDGE, SERVICE LETTER					RECOMMENDED	
		MOS					
03-MAR-2014			-				
SL 737-SL-26-037	FORWARD ATTENDANT PANEL - LAVATORY SMOKE DETECTOR MODULE IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-AUG-2000			- (s)				
SL 737-SL-26-037 REV. A	FORWARD ATTENDANT PANEL - LAVATORY SMOKE DETECTOR MODULE IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
07-DEC-2000			- (s)				
SL 737-SL-26-038	CFM56-7B FIRE DETECTION HARNESS IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
14-MAR-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-26-040	PORTABLE WATER FIRE EXTINGUISHERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-APR-2002			- (s)				
SL 737-SL-26-042	PORTABLE WATER FIRE EXTINGUISHERS MISSING PIERCER, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUN-2002			- (s)				
SL 737-SL-26-043	RECALL OF KIDDE AEROSPACE PORTABLE HALON 1211 FIRE EXTINGUISHERS-P/N 898052, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
		MOS		15-FEB-2004			
05-NOV-2002			- (s)	1579:18			
		AFL		398			
SL 737-SL-26-044	INCORRECT INSTALLATION OF ENGINE FIRE EXTINGUISHING HOSE MAY PREVENT AGENT FLOW TO ENGINE, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
		MOS		15-FEB-2004			
17-DEC-2003			-	1579:18			
		AFL		398			
SL 737-SL-26-045	CARGO COMPARTMENT FIRE SUPPRESSION BOTTLE REQUIREMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-AUG-2004			-				
SL 737-SL-26-046	LAVATORY FIRE EXTINGUISHER EXTINGUISHING AGENT REPLACEMENT, SERVICE LETTER						
		MOS					
20-SEP-2006			-				
SL 737-SL-26-046 REV. A	LAVATORY FIRE EXTINGUISHER EXTINGUISHING AGENT REPLACEMENT, SERVICE LETTER						
		MOS					
27-FEB-2007			-				
SL 737-SL-26-047	ENGINE FIRE LIGHT ILLUMINATION, SERVICE LETTER						
		MOS					
27-NOV-2006			-				
SL 737-SL-26-048	CARGO FIRE EXTINGUISHER -METERING ASSEMBLY/DRIER DISC RUPTURE, SERVICE LETTER						
		MOS					
09-NOV-2007			-				
SL 737-SL-26-049	IMPROPERLY TORQUED APU LOWER FIRE DETECTOR SENSOR, SERVICE LETTER						
		MOS					
14-NOV-2007			-				

© Camp Systems

EFTA00618552

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-26-049 REV. A	IMPROPERLY TORQUED APU LOWER FIRE DETECTOR SENSOR, SERVICE LETTER						
		MOS					
24-JAN-2008			-				
SL 737-SL-26-050	CARD CONTAMINATION IN FIRE DETECTION MODULES, SERVICE LETTER						
		MOS					
03-DEC-2008			-				
SL 737-SL-26-051	CONTAMINATED HALON 1211 FIRE EXTINGUISHERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-DEC-2009			-				
SL 737-SL-26-051 REV. A	CONTAMINATED HALON 1211 FIRE EXTINGUISHERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-FEB-2010			-				
SL 737-SL-26-052	WASHERS ON APU FIRE DETECTOR CLAMPS INADVERTENTLY OMITTED (SUPERSEDED BY SL SL 737-SL-26-052 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-26-052 REV. A	WASHERS ON APU FIRE DETECTOR CLAMPS INADVERTENTLY OMITTED, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JAN-2011			-				
SL 737-SL-26-054	POSSIBLE OVERHEAT SENSOR BRACKET DISCREPANCY, SERVICE LETTER					RECOMMENDED	
		MOS					
14-MAY-2012			-				
SL 737-SL-26-055	WING/BODY OVERHEAT FAULTS DUE TO FENWAL CONNECTORS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JUN-2012			-				
SL 737-SL-26-056	APU FIRE DETECTOR PART MARK INCORRECT, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAY-2013			-				
SL 737-SL-27-079 REV. A	MACH TRIM FLAPS UP, AND LANDING WARNING SWITCH IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-APR-2003			-				
SL 737-SL-27-079 REV. F	NEW S138 LAND WARNING, S245 FLAP POSITION, S290 MACH TRIM WARNING, AND S1051 FLAPS UP SWITCHES, SERVICE LETTER						
		MOS					
08-FEB-2005			-				

© Camp Systems

EFTA00618553

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-124	STALL MANAGEMENT / YAW DAMPER MODULE ASSY MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-FEB-1999			- (s)				
SL 737-SL-27-126 REV. A	PERIODIC OPERATIONAL VERIFICATION OF THE ELEVATOR TAB CONTROL SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
13-NOV-2000			- (s)				
SL 737-SL-27-130 REV. A	STABILIZER TRIM ACTUATOR CMR RETROFIT PROCEDURE, SERVICE LETTER					INFORMATIONAL	
		MOS					
06-AUG-1999			- (s)				
SL 737-SL-27-131	ELEVATOR TAB ROD HI-LOK INTERFERENCE WITH STRUCTURE, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-DEC-1998			- (s)				
SL 737-SL-27-131 REV. A	ELEVATOR TAB ROD HI-LOK INTERFERENCE WITH STRUCTURE, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-JUN-1999			- (s)				
SL 737-SL-27-132	INSPECTION OF FLEXIBLE HOSES BETWEEN ELEVATOR FEEL PITOT PROBES AND RIGID METAL TUBING, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-DEC-1998			- (s)				
SL 737-SL-27-133	ELEVATOR TAB CONTROL ROD NUT REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-JAN-1999			- (s)				
SL 737-SL-27-134 REV. A	TRAILING EDGE FLAP ALTERNATE DRIVE MOTOR DESIGN IMPROVEMENTS, SERVICE LETTER						
		MOS					
27-MAR-2007			-				
SL 737-SL-27-136	ELEVATOR CONTROL CABLE CLEARANCE INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-1999			- (s)				
SL 737-SL-27-137 REV. B	ELEVATOR TAB PIVOT BOLT WASHER OMISSION, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-NOV-2000			- (s)				
SL 737-SL-27-138	AILERON TAB CONTROL ROD CONNECTING BARREL, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-1999			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-139	ELEVATOR CONTROLS-FORWARD QUADRANT INTERFERENCE, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-APR-1999			- (s)				
SL 737-SL-27-140	FLIGHT CONTROLS-ELEVATOR BUSS INSTALLATION-RIVET INTERFERENCE, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - C/W
		MOS		13-SEP-1999			
23-APR-1999			- (s)				
SL 737-SL-27-140 REV. A	FLIGHT CONTROLS-ELEVATOR BUSS INSTALLATION-RIVET INTERFERENCE, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-MAY-1999			- (s)				
SL 737-SL-27-140 REV. B	FLIGHT CONTROLS-ELEVATOR BUSS INSTALLATION-RIVET INTERFERENCE, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-JUN-1999			- (s)				
SL 737-SL-27-141	AILERON WING CONTROL CABLE ROUTING INSPECTION, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - C/W
		MOS	18 (s)	13-SEP-1999			
13-JUL-1999							
		AFL	4000				
SL 737-SL-27-142	ELEVATOR FEEL COMPUTER DISCREPANT O RINGS, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUL-1999			- (s)				
SL 737-SL-27-143	AILERON SPRING CARTRIDGE BOLTINTERFERENCE, SERVICE LETTER					RECOMMENDED	
		MOS					
07-SEP-1999			- (s)				
SL 737-SL-27-147 REV. A	RUDDER CONTROL AFT QUADRANT ATTACHMENT FASTENERS UNDERTORQUED., SERVICE LETTER					RECOMMENDED	
		MOS					
08-DEC-1999			- (s)				
SL 737-SL-27-148	INABILITY TO MOVE WING LEADING EDGE DEVICE, SERVICE LETTER					RECOMMENDED	
		MOS					
21-DEC-1999			- (s)				
SL 737-SL-27-148 REV. A	INABILITY TO MOVE WING LEADING EDGE DEVICES, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-MAR-2005			-				
SL 737-SL-27-149	RUDDER CONTROL AFT QUADRANT ATTACHMENT FASTENERS UNDERTORQUED., SERVICE LETTER					RECOMMENDED	
		MOS					
11-JUN-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-149 REV. A	CONTROLS-AILERON CABLE PULLEY INSTALLATION-INTERFERNCE, SERVICE LETTER					RECOMMENDED	
21-FEB-2000		MOS	- (s)				
SL 737-SL-27-150	ELEVATOR POWER CONTROL UNIT LINKAGE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - C/W
14-FEB-2000		MOS	- (s)	17-APR-2000			
SL 737-SL-27-150 REV. A	ELEVATOR POWER CONTROL UNIT LINKAGE INSPECTION, SERVICE LETTER						
14-FEB-2001		MOS	- (s)				
SL 737-SL-27-150 REV. B	ELEVATOR POWER CONTROL UNIT LINKAGE- INSPECTION., SERVICE LETTER					INFORMATIONAL	
12-MAY-2000		MOS	- (s)				
SL 737-SL-27-152	STABILIZER TRIM MOTOR IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
27-JUL-2000		MOS	- (s)				
SL 737-SL-27-153	TRAILING EDGE FLAP TORQUE TUBE COUPLING AND U-JOINT LUBRICATION, SERVICE LETTER					INFORMATIONAL	
03-OCT-2000		MOS	- (s)				
SL 737-SL-27-154	REPLACEMENT OF ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					INFORMATIONAL	
13-OCT-2000		MOS	- (s)				
SL 737-SL-27-154 REV. A	REPLACEMENT OF ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					INFORMATIONAL	
17-NOV-2000		MOS	- (s)				
SL 737-SL-27-154 REV. B	REPLACEMENT OF ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					INFORMATIONAL	
18-APR-2001		MOS	- (s)				
SL 737-SL-27-154 REV. C	REPLACEMENT OF ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					INFORMATIONAL	
27-APR-2001		MOS	- (s)				
SL 737-SL-27-154 REV. D	ELEVATOR CONTROL SYSTEM - ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER						
16-NOV-2001		MOS	- (s)				

© Camp Systems

EFTA00618556

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-154 REV. E	ELEVATOR CONTROL SYSTEM - ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER						
		MOS					
15-OCT-2007			-				
SL 737-SL-27-154 REV. F	ELEVATOR CONTROL SYSTEM - ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					RECOMMENDED	
		MOS					
27-OCT-2009			-				
SL 737-SL-27-154 REV. G	ELEVATOR CONTROL SYSTEM - ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING (SUPERSEDED BY SL 737-SL-27-154 REV. H), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-154 REV. H	ELEVATOR CONTROL SYSTEM - ELEVATOR OUTPUT TORQUE TUBE CONTROL CRANK BEARING, SERVICE LETTER					RECOMMENDED	
		MOS					
13-JUL-2011			-				
SL 737-SL-27-155	ELEVATOR TAB SOLENOID VALVE REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-NOV-2000			- (s)				
SL 737-SL-27-155 REV. A	ELEVATOR TAB SOLENOID VALVE REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-APR-2001			- (s)				
SL 737-SL-27-156	STABILIZER TRIM CABLE GUARD INTERFERENCE WITH AUTOTHROTTLE MECHANISMMOUNTING FLANGE, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-DEC-2000			- (s)				
SL 737-SL-27-159	STANDBY RUDDER PCU REACTION BEARING INCORRECTLY SWAGED, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-JAN-2001			- (s)				
SL 737-SL-27-160	AILERON POWER CONTROL SUPPORT ARM INTERFERENCE WITH HYDRAULIC HOSE, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-MAY-2001			- (s)				
SL 737-SL-27-162	STALL MANAGEMENT / YAW DAMPER MODULE ASSEMBLY MODIFICATION, M01747 NO.1, M01748 NO.2, P/N 285A1010, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-OCT-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-162 REV. A	STALL MANAGEMENT / YAW DAMPER MODULE ASSEMBLY MODIFICATION, M01747 NO.1, M01748 NO.2, P/N 285A1010, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-APR-2002			- (s)				
SL 737-SL-27-162 REV. B	STALL MANAGEMENT/YAW DAMPER MODULE ASSEMBLY MODIFICATION, M01747 NO.1, M01748 NO.2, P/N 285A1010, SERVICE LETTER					INACTIVE	
		MOS					
08-MAR-2004			-				
SL 737-SL-27-164	INSPECTION FOR BENT CLEVIS ON ELEVATOR FEEL AND CENTERING BRACKET SUPPORT, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-MAY-2002			- (s)				
SL 737-SL-27-164 REV. A	INSPECTION FOR BENT CLEVIS ON ELEVATOR FEEL AND CENTERING BRACKET SUPPORT, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-DEC-2004			-				
SL 737-SL-27-165	P2-3 LANDING GEAR PANEL ASSEMBLIES - DISCREPANT FLAP PLACARD SPEEDS, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-APR-2002			- (s)				
SL 737-SL-27-167	CONTROL COLUMN NEEDLE BEARING CORROSION, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-DEC-2002			-				
SL 737-SL-27-169	LUBRICATION OMITTED FROM THE ROD END ASSEMBLY FOR THE FLIGHT SPOILER ACTUATOR, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-DEC-2002			-				
SL 737-SL-27-169 REV. A	LUBRICATION OMITTED FROM THE ROD END ASSEMBLY FOR THE FLIGHT SPOILER ACTUATOR, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-OCT-2003			-				
SL 737-SL-27-170	TRAILING EDGE FLAP AND SPOILER HANDLE-LUBRICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-DEC-2002			-				
SL 737-SL-27-171	ELEVATOR CONTROL CABLE INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-JAN-2003			-				
SL 737-SL-27-171 REV. A	ELEVATOR CONTROL CABLE INSPECTION-INSUFFICIENT CLEARANCE, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-SEP-2003			-				

© Camp Systems

EFTA00618558

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-27-172	MOUNTING BRACKET FASTENERS INCORRECTLY INSTALLED, SERVICE LETTER					INFORMATIONAL	
			MOS					
	02-JAN-2003			-				
SL	737-SL-27-173	ELEVATOR CABLE PULLEY NUT AND BOLT INSTALLATION-POTENTIAL FOR LOW TORQUE VALUE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	01-AUG-2003			-				
SL	737-SL-27-174	AILERON AND SPEED BRAKE CONTROL CABLE LOW TENSION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-AUG-2003			-				
SL	737-SL-27-175	AUTOPILOT ACTUATOR MOUNTING BOLTS-TORQUE INSPECTION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	07-JUL-2003			-				
SL	737-SL-27-175 REV. A	AUTOPILOT ACTUATOR MOUNTING BOLTS-TORQUE INSPECTION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	23-DEC-2003			-				
SL	737-SL-27-176	AILERON CONTROL CABLE HIGH TENSION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	13-JAN-2004			-				
SL	737-SL-27-177 REV. A	AILERON SPRING CARTRIDGE ANOMALIES, SERVICE LETTER					INFORMATIONAL	
			MOS					
	23-MAR-2004			-				
SL	737-SL-27-178 REV. B	TRAILING EDGE FLAP POWER DRIVE UNIT (PDU) GEARBOX-NEW RETAINER WITH EXCLUDER SEAL, SERVICE LETTER					INFORMATIONAL	
			MOS					
	30-SEP-2004			-				
SL	737-SL-27-178 REV. C	TRAILING EDGE FLAP POWER DRIVE UNIT (PDU) GEARBOX - NEW RETAINER WITH EXCLUDER SEAL (SUPERSEDED BY SL 737-SL-27-178 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-27-178 REV. D	TRAILING EDGE FLAP POWER DRIVE UNIT (PDU) GEARBOX-NEW EXCLUDER SEAL, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-NOV-2012			-				
SL	737-SL-27-179 REV. A	LEADING EDGE SLAT POSITION SENSOR INSTALLATION-POSSIBLE MIS-ORIENTATION ALLOWS WIRE BUNDLE CHAFING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	15-JUL-2004			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-179 REV. B	LEADING EDGE SLAT POSITION SENSOR INSTALLATION-POSSIBLE MIS-ORIENTATION ALLOWS WIRE BUNDLE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUL-2004			-				
SL 737-SL-27-179 REV. C	LEADING EDGE SLAT POSITION SENSOR INSTALLATION - POSSIBLE MIS-ORIENTATION ALLOWS WIRE BUNDLE CHAFING., SERVICE LETTER						
		MOS					
26-APR-2005			-				
SL 737-SL-27-180	FLIGHT SPOILER PCU LEAKAGE DUE TO INCORRECT PISTON ROD SEAL, SERVICE LETTER						
		MOS					
04-AUG-2004			-				
SL 737-SL-27-181	RUDDER SYSTEM ENHANCEMENT PROGRAM SERVICE BULLETIN-INCORRECT WIRE IN KIT, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2004			-				
SL 737-SL-27-181 REV. A	RUDDER SYSTEM ENHANCEMENT PROGRAM SERVICE BULLETIN - INCORRECT WIRE IN KIT, SERVICE LETTER						
		MOS					
25-MAY-2006			-				
SL 737-SL-27-182	ELEVATOR FEEL SHIFT MODULE FILLET SEAL INSPECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-OCT-2004			-				
SL 737-SL-27-183	ELEVATOR FEEL COMPUTER DISCLOSURE - OVERTORQUED FASTENERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-DEC-2004			-				
SL 737-SL-27-184	FLIGHT CONTROLS IN MAIN WHEEL WELL - CHANGES TO THE FINISH OF CADMIUM PLATED COMPONENTS., SERVICE LETTER						
		MOS					
27-MAY-2005			-				
SL 737-SL-27-184 REV. A	FLIGHT CONTROLS IN MAIN WHEEL WELL - CHANGES TO THE FINISH OF CADMIUM PLATED COMPONENTS, SERVICE LETTER						
		MOS					
13-DEC-2007			-				
SL 737-SL-27-184 REV. B	FLIGHT CONTROLS IN MAIN WHEEL WELL - CHANGES TO THE FINISH OF CADMIUM PLATED COMPONENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JAN-2010			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-27-185	RUDDER PEDAL ADJUSTMENT SHAFT, SERVICE LETTER						
			MOS					
	07-DEC-2005			-				
SL	737-SL-27-185 REV. A	RUDDER PEDAL ADJUSTMENT SHAFT, SERVICE LETTER						
			MOS					
	07-AUG-2006			-				
SL	737-SL-27-186	TRAILING EDGE FLAP HANDLE HARD TO ROTATE - PULLEY AND CABLE CHECK, SERVICE LETTER					INFORMATIONAL	
			MOS					
	29-AUG-2005			-				
SL	737-SL-27-186 REV. A	TRAILING EDGE FLAP HANDLE HARD TO ROTATE - PULLEY AND CABLE CHECK, SERVICE LETTER						
			MOS					
	09-APR-2007			-				
SL	737-SL-27-186 REV. B	TRAILING EDGE FLAP HANDLE HARD TO ROTATE - PULLEY AND CABLE CHECK, SERVICE LETTER						COMPLIED WITH
			MOS			22-AUG-2008		
	19-JUN-2007			-		3260:48		
			AFL			782		
SL	737-SL-27-186 REV. C	TRAILING EDGE FLAP HANDLE HARD TO ROTATE - PULLEY AND CABLE CHECK, SERVICE LETTER					RECOMMENDED	
			MOS					
	01-APR-2009			-				
SL	737-SL-27-188	AILERON CONTROL CABLE TENSION INSPECTION (SUPERSEDED BY 737-SL-27-188 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-27-188 REV. A	AILERON CONTROL CABLE TENSION INSPECTION, SERVICE LETTER						
			MOS					
				-				
SL	737-SL-27-189	TRAILING EDGE FLAP BALLSCREW - MIXED GREASE, SERVICE LETTER						
			MOS					
	09-JAN-2006			-				
SL	737-SL-27-190	STABILIZER TRIM MOTOR - EMI FILTER SUPPLIER CHANGE, SERVICE LETTER						
			MOS					
	09-FEB-2006			-				

© Camp Systems

EFTA00618561

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-191	SUSPECT CONTROL COLUMN WIRE BUNDLES, SERVICE LETTER						
		MOS					
09-MAR-2006			-				
SL 737-SL-27-191 REV. A	SUSPECT CONTROL COLUMN WIRE BUNDLES, SERVICE LETTER						
		MOS					
06-JUN-2006			-				
SL 737-SL-27-191 REV. B	SUSPECT CONTROL COLUMN WIRE BUNDLES, SERVICE LETTER						
		MOS					
22-MAR-2007			-				
SL 737-SL-27-191 REV. C	SUSPECT CONTROL COLUMN WIRE BUNDLES, SERVICE LETTER						
		MOS					
27-AUG-2007			-				
SL 737-SL-27-192	INSPECTION OF MACH TRIM TORQUE TUBE FOR OVERSIZED FASTENER HOLES OR EXCESSIVE FREEPLAY, SERVICE LETTER						
		MOS					
17-JUL-2006			-				
SL 737-SL-27-192 REV. A	INSPECTION OF MACH TRIM TORQUE TUBE FOR OVERSIZED FASTENER HOLES OR EXCESSIVE FREEPLAY, SERVICE LETTER						
		MOS					
01-SEP-2006			-				
SL 737-SL-27-192 REV. B	INSPECTION OF MACH TRIM TORQUE TUBE FOR OVERSIZED FASTENER HOLES OR EXCESSIVE FREEPLAY, SERVICE LETTER						
		MOS					
22-MAR-2007			-				
SL 737-SL-27-192 REV. C	INSPECTION OF MACH TRIM TORQUE TUBE FOR OVERSIZED FASTENER HOLES OR EXCESSIVE FREEPLAY, SERVICE LETTER						
		MOS					
10-APR-2007			-				
SL 737-SL-27-192 REV. D	INSPECTION OF MACH TRIM TORQUE TUBE FOR OVERSIZED FASTENER HOLES OR EXCESSIVE FREEPLAY, SERVICE LETTER						
		MOS					
24-JUL-2007			-				
SL 737-SL-27-193	STALL MANAGEMENT / YAW DAMPER MODULE ASSEMBLY MODIFICATION, M01747 NO. 1, M01748 NO. 2, P/N 285A1010, SERVICE LETTER						
		MOS					
10-AUG-2006			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-27-193 REV. A	STALL MANAGEMENT / YAW DAMPER MODULE ASSEMBLY MODIFICATION, M01747 NO. 1, M01748 NO. 2, P/N 285A1010, SERVICE LETTER						
			MOS					
	27-JUL-2007			-				
SL	737-SL-27-195	ELEVATOR FEEL COMPUTER INPUT ROD WASHER INSTALLATION DISCREPANCY, SERVICE LETTER						
			MOS					
	16-NOV-2006			-				
SL	737-SL-27-195 REV. A	ELEVATOR FEEL COMPUTER INPUT ROD WASHER INSTALLATION DISCREPANCY, SERVICE LETTER						COMPLIED WITH - IAW THE SB
			MOS			22-AUG-2008		
	24-JUL-2007			-		3260:48		
			AFL			782		
SL	737-SL-27-196	TRAILING EDGE FLAP POSITION TRANSMITTER AND SKEW SENSOR CONNECTOR - WATER INGRESS, SERVICE LETTER						
			MOS					
	22-FEB-2007			-				
SL	737-SL-27-196 REV. A	TRAILING EDGE FLAP POSITION TRANSMITTER AND SKEW SENSOR CONNECTOR - WATER INGRESS, SERVICE LETTER						
			MOS					
	09-APR-2007			-				
SL	737-SL-27-196 REV. B	TRAILING EDGE FLAP POSITION TRANSMITTER AND SKEW SENSOR CONNECTOR - WATER INGRESS, SERVICE LETTER						
			MOS					
	15-FEB-2008			-				
SL	737-SL-27-198	NOSE DOWN STAB TAKE-OFF WARNING SWITCH (S-546) PLACARD AND STAB NOSE DOWN LIMIT SWITCH (S-145) PLACARD INSTALLED INCORRECTLY, SERVICE LETTER						
			MOS					
	10-APR-2007			-				
SL	737-SL-27-199	RUDDER TRIM INDICATOR - ERRATIC OR STUCK NEEDLE, SERVICE LETTER						
			MOS					
	05-NOV-2007			-				
SL	737-SL-27-200	WSA1 SPOILER CABLE MAY HAVE A MINIMAL RIDING CONDITION ON THE UPPER SIDE OF THE LOWER PULLEY OF THE 251A1411-6 SPOILER TURNAROUND PULLEY BRACKET, SERVICE LETTER						
			MOS					
	19-OCT-2007			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-201	LATERAL TRIM - AIRPLANE CONFIGURATION HISTORY AND CORRECTION, SERVICE LETTER	MOS	-	24-JAN-2008			
SL 737-SL-27-202	ELEVATOR FEEL COMPUTER - INSPECTION FOR FEEL COMPUTER RETURN SPRING, SERVICE LETTER	MOS	-	24-JAN-2008			
SL 737-SL-27-203	TROUBLESHOOTING FOR HIGH CONTROL WHEEL AND COLUMN FORCES, SERVICE LETTER	MOS	-	24-JAN-2008			
SL 737-SL-27-203 REV. A	TROUBLESHOOTING FOR HIGH CONTROL WHEEL AND COLUMN FORCES (SUPERSEDED BY SL 737-SL-27-203 REV. B), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-27-203 REV. B	TROUBLESHOOTING FOR HIGH CONTROL WHEEL AND COLUMN FORCES, SERVICE LETTER	MOS	-	16-NOV-2012		RECOMMENDED	
SL 737-SL-27-204	SPEEDBRAKE GROUND PROXIMITY SENSOR ADJUSTMENT, SERVICE LETTER	MOS	-	27-MAR-2008			
SL 737-SL-27-205	ELEVATOR FEEL COMPUTER INPUT ROD FASTENER INSTALLATION DISCREPANCY, SERVICE LETTER	MOS	-	18-JUL-2008			
SL 737-SL-27-206	POSSIBLE CONTAMINATION OF STANDBY RUDDER PCU, SERVICE LETTER	MOS	-	18-AUG-2009		RECOMMENDED	
SL 737-SL-27-207	SPEED BRAKE BRACKET ASSEMBLY - CABLE RETAINER BOLTS - TORQUE INSPECTION, SERVICE LETTER	MOS	-	20-OCT-2008			
SL 737-SL-27-208	SPOILER BRACKET MOUNTING BOLTS - TORQUE INSPECTION, SERVICE LETTER	MOS	-	20-OCT-2008			

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-27-209	ELEVATOR POSITION SENSOR INSTALLATION - IMPROPER FASTENER TORQUE (SUPERSEDED BY SL 737-SL-27-209 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-27-209 REV. A	ELEVATOR POSITION SENSOR INSTALLATION - IMPROPER FASTENER TORQUE, SERVICE LETTER	MOS	-		22-MAR-2011	RECOMMENDED	
SL	737-SL-27-210	POSSIBLE CONTAMINATION OF AILERON/ELEVATOR PCU, SERVICE LETTER	MOS	-		19-AUG-2009	RECOMMENDED	
SL	737-SL-27-211	AIRPLANE PITCH UPSETS DURING MANUAL REVERSION TEST FLIGHTS DUE TO INCORRECT ADJUSTMENT OF ELEVATOR TAB PUSHRODS, SERVICE LETTER	MOS	-		08-MAY-2009	RECOMMENDED	
SL	737-SL-27-212	HORIZONTAL STABILIZER LIMIT AND WARNING SWITCH INSTALLATION (SUPERSEDED BY SL 737-SL-27-212 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-27-212 REV. A	HORIZONTAL STABILIZER LIMIT AND WARNING SWITCH INSTALLATION (SUPERSEDED BY SL 737-SL-27-230 AND SL 737-SL-31-057), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-27-214	HORIZONTAL STABILIZER TRIM ACTUATOR - LOWER PLUG ASSEMBLY - OVER-SIZED O-RING GROOVE, SERVICE LETTER	MOS	-		30-JUN-2009	RECOMMENDED	
SL	737-SL-27-215	LEAKAGE OF ELEVATOR TAB LOCK ACTUATORS ON RECENTLY DELIVERED AIRPLANES (SUPERSEDED BY SL 737-SL-27-215 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-27-215 REV. A	LEAKAGE OF ELEVATOR TAB LOCK ACTUATORS ON RECENTLY DELIVERED AIRPLANES, SERVICE LETTER	MOS	-		04-DEC-2013	RECOMMENDED	
SL	737-SL-27-216	STABILIZER POSITION SENSOR INPUT ROD WASHER INSTALLATION DISCREPANCY, SERVICE LETTER	MOS	-		05-NOV-2009	RECOMMENDED	

© Camp Systems

EFTA00618565

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-217	ELEVATOR SYSTEM COMPONENTS FASTENERS UNDERTORQUED, SERVICE LETTER					RECOMMENDED	
		MOS					
08-DEC-2009			-				
SL 737-SL-27-218	GROUND SPOILER INTERLOCK VALVE END PLATE ASSEMBLY INSTALLED UPSIDE DOWN, SERVICE LETTER					RECOMMENDED	
		MOS					
07-JAN-2010			-				
SL 737-SL-27-219	737NG FLAP/SLAT ELECTRONICS UNIT (FSEU) (M01746) - HISTORY, APPLICABILITY AND INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
07-MAY-2010			-				
SL 737-SL-27-220	AILERON CENTERING MECHANISM PIN DELIVERED WITHOUT REQUIRED SURFACE COATING, SERVICE LETTER					RECOMMENDED	
		MOS					
26-JUL-2010			-				
SL 737-SL-27-221	INCORRECT USE OF CAD PLATED SCREWS WITH TITANIUM PROXIMITY SENSOR P/N 80-207-01 ON WING LEADING EDGE, SERVICE LETTER					RECOMMENDED	
		MOS					
20-AUG-2010			-				
SL 737-SL-27-222	AILERON CENTERING MECHANISM LEVER DELIVERED WITH MINOR ASSEMBLY DAMAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
20-SEP-2010			-				
SL 737-SL-27-223	GROUND SPOILER INTERLOCK VALVE IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
14-OCT-2010			-				
SL 737-SL-27-224	RUDER PCU - DAMAGE SUMMING LEVER BOLTS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-NOV-2010			-				
SL 737-SL-27-225	6355C0001-01 STABILIZER TRIM MOTOR - MODIFICATION HISTORY (SUPERSEDED BY 737-SL-27-225 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-225 REV. A	6355C0001-01 STABILIZER TRIM MOTOR - MODIFICATION HISTORY, SERVICE LETTER					RECOMMENDED	
		MOS					
30-JAN-2014			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-226	STICK SHAKER MOTOR GROUND TERMINAL INSPECTION (SUPERSEDED BY SL 737-SL-27-226 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-226 REV. A	STICK SHAKER MOTOR GROUND TERMINAL INSPECTION (SUPERSEDED BY SL 737-SL-27-226 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-226 REV. B	STICK SHAKER MOTOR GROUND TERMINAL INSPECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
08-JUN-2012			-				
SL 737-SL-27-227	RUDDER FEEL AND CENTERING INSTALLATION - FASTENERS UNDERTORQUED, SERVICE LETTER					RECOMMENDED	
		MOS					
17-NOV-2010			-				
SL 737-SL-27-228	TRAILING EDGE FLAP BALLSCREWS-IN-SERVICE WEAR, SERVICE LETTER					RECOMMENDED	
		MOS					
15-NOV-2010			-				
SL 737-SL-27-229	737NG LEADING EDGE CRUISE DEPRESSURIZATION VALVE (V00163), INCORRECTLY APPLIED INSTALLATION SEALANT, SERVICE LETTER					RECOMMENDED	
		MOS					
16-DEC-2010			-				
SL 737-SL-27-230	HORIZONTAL STABILIZER LIMIT SWITCH INSTALLATION (SUPERSEDED BY SL 737-SL-27-230 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
31-MAR-2011			-				
SL 737-SL-27-230 REV. A	HORIZONTAL STABILIZER LIMIT SWITCH INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2013			-				
SL 737-SL-27-231	GROUND STUD DECAL GD1086ST INCORRECTLY LABELED (SUPERSEDED BY SL 737-SL-27-231 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-231 REV. A	GROUND STUD DECAL GD1086ST INCORRECTLY LABELED (SUPERSEDED BY SL 737-SL-27-231 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-27-231 REV. B	GROUND STUD DECAL GD1086ST INCORRECTLY LABELED, SERVICE LETTER					RECOMMENDED	
		MOS					
09-DEC-2011			-				
SL 737-SL-27-232	AUTO SPEEDBRAKE ACTUATOR IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
24-AUG-2011			-				
SL 737-SL-27-233	WIRE BUNDLE W1032 POSSIBLE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
09-DEC-2011			-				
SL 737-SL-27-234 REV. A	CORROSION PROTECTION FOR S138, S245, AND S1051 FLAP POSITION SWITCH CONNECTORS, SERVICE LETTER					RECOMMENDED	
		MOS					
13-AUG-2013			-				
SL 737-SL-27-235	GROUND STUD DECAL GD236ST POTENTIALLY LOCATED INCORRECTLY, SERVICE LETTER					RECOMMENDED	
		MOS					
18-SEP-2012			-				
SL 737-SL-27-236	S245 FLAP SWITCH CONNECTOR - POSSIBLE IMPROPER ASSEMBLY OF BACKSHELL CLAMP (SUPERSEDED BY SL 737-SL-27-236 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-27-236 REV. A	S245 FLAP SWITCH CONNECTOR - POSSIBLE IMPROPER ASSEMBLY OF BACKSHELL CLAMP, SERVICE LETTER					RECOMMENDED	
		MOS					
27-SEP-2012			-				
SL 737-SL-27-238	INADVERTENT ACTIVATION OF RUDDER TRIM, SERVICE LETTER					RECOMMENDED	
		MOS					
19-SEP-2012			-				
SL 737-SL-27-239	RUDDER CENTERING UNIT SPRING ASSEMBLY - INCORRECT SPRING SEAT MATERIAL, SERVICE LETTER					RECOMMENDED	
		MOS					
05-FEB-2013			-				
SL 737-SL-27-240	TRAILING EDGE FLAP - ALTERNATE ELECTIC MOTOR - POSSIBILITY OF NO LUBRICATION FLUID, SERVICE LETTER					RECOMMENDED	
		MOS					
16-NOV-2012			-				
SL 737-SL-27-241	FLIGHT CONTROL DAMAGE CAUSED BY EXTREME WINDS, SERVICE LETTER					RECOMMENDED	
		MOS					
19-DEC-2012			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-27-242	POTENTIAL OF WIRES SHORTING TO GROUND ON STAB TRIM SWITCHES (SUPERSEDED BY SL 737-SL-27-242 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-27-242 REV. A	POTENTIAL OF WIRES SHORTING TO GROUND ON STAB TRIM SWITCHES (SUPERSEDED BY SL 737-SL-27-242 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-27-242 REV. B	POTENTIAL OF WIRES SHORTING TO GROUND ON STAB TRIM SWITCHES, SERVICE LETTER					RECOMMENDED	
			MOS					
	05-AUG-2013			-				
SL	737-SL-27-243	POSSIBLE ELECTRO-HYDRAULIC SERVO VALVE (EHSV) GASKET PLATE LEAKAGE ON PARKER AEROSPACE RUDDER POWER CONTROL UNITS (PCU), SERVICE LETTER					RECOMMENDED	
			MOS					
	21-JUN-2013			-				
SL	737-SL-27-244	POSSIBLE DISCREPANT FLOW LIMITER ASSEMBLIES, SERVICE LETTER					RECOMMENDED	
			MOS					
	06-SEP-2013			-				
SL	737-SL-27-245	SHOULDER BOLT AND SLAT TORSION ROD CLEARANCE, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-SEP-2013			-				
SL	737-SL-27-246	POSSIBLE EXTERNAL LEAKAGE FROM AILERON/ELEVATOR POWER CONTROL UNIT (PCU) CRANK ASSEMBLY (SUPERSEDED BY SL 737-SL-27-246 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-27-246 REV. A	POSSIBLE EXTERNAL LEAKAGE FROM AILERON/ELEVATOR POWER CONTROL UNIT (PCU) CRANK ASSEMBLY, SERVICE LETTER					RECOMMENDED	
			MOS					
	02-JUN-2014			-				
SL	737-SL-27-247	HORIZONTAL STABILIZER TRIM ACTUATOR - INPUT CAM ASSEMBLY - IMPROPERLY CARBURIZED, SERVICE LETTER					RECOMMENDED	
			MOS					
	21-APR-2014			-				
SL	737-SL-27-248	FLIGHT SPOILER PCU RELIABILITY IMPROVEMENTS ON SHORT FIELD PERFORMANCE AIRPLANES, SERVICE LETTER					RECOMMENDED	
			MOS					
	11-JUN-2014			-				

© Camp Systems

EFTA00618569

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-28-015 REV. D	FUEL TANKS OPEN AND PURGED, ELECTRICAL POWER APPLICATION (SUPERSEDED 737-SL-28-082), SERVICE LETTER					SUPERSEDED	
		MOS					
13-APR-2010			-				
SL 737-SL-28-039 REV. B	FUEL LEAK DETECTION AND REPAIR OVERVIEW VIDEO, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-JAN-2002			- (s)				
SL 737-SL-28-044 REV. A	AIRCRAFT USE OF DYED FUELS (SUPERSEDED BY SL 737-SL-28-044 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-044 REV. B	AIRCRAFT USE OF DYED FUELS, SERVICE LETTER					RECOMMENDED	
		MOS					
02-APR-2012			-				
SL 737-SL-28-053	AIRCRAFT USE OF FUELS CONTAMINATED WITH DYE (SUPERSEDED BY SL 737-SL-28-053 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-28-053 REV. A	AIRCRAFT USE OF FUELS CONTAMINATED WITH DYE, SERVICE LETTER					RECOMMENDED	
		MOS					
16-APR-2012			-				
SL 737-SL-28-055	DESIGN IMPROVEMENT FOR PITCH AND ROLL INCLINOMETERS TO PREVENT CRACKING OF GLASS TUBE, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-JUN-1999			- (s)				
SL 737-SL-28-055 REV. A	DESIGN IMPROVEMENT FOR PITCH AND ROLL INCLINOMETERS TO PREVENT CRACKING OF GLASS TUBE, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-JAN-2003			-				
SL 737-SL-28-056	FUEL QUANITITY PROCESSOR UNIT (FQPU) SOFTWARE IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-DEC-1999			- (s)				
SL 737-SL-28-057	NEW SCAVENGE PUMP INLET AND SCREEN., SERVICE LETTER					INFORMATIONAL	
		MOS					
15-AUG-2000			- (s)				

© Camp Systems

EFTA00618570

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-28-060	SHORT SCREWS INSTALLED ON ENGINE FUEL SHUTOFF VALVES, CROSSFEED VALVE, AND DEFUEL VALVE, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-OCT-2001			-				
SL	737-SL-28-060 REV. A	SHORT SCREWS INSTALLED ON ENGINE FUEL SHUTOFF VALVES, CROSSFEED VALVE, AND DEFUEL VALVE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	28-NOV-2001			- (s)				
SL	737-SL-28-060 REV. B	SHORT SCREWS INSTALLED ON ENGINE FUEL SHUTOFF VALVES, CROSSFEED VALVE, AND DEFUEL VALVE, SERVICE LETTER						
			MOS					
	15-OCT-2007			-				
SL	737-SL-28-061	ESTIMATION OF FREEZING POINTS OF JET A/JET A-1 FUEL BLENDS(SUPERSEDED BY SL 737-SL-28-061 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-28-061 REV. A	ESTIMATION OF FREEZING POINTS OF JET A/JET A-1 FUEL BLENDS(SUPERSEDED BY SL 737-SL-28-061 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-28-061 REV. B	ESTIMATION OF FREEZING POINTS OF JET A/JET A-1 FUEL BLENDS (SUPERSEDED BY SL 737-SL-28-061 REV. C), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-28-061 REV. C	ESTIMATION OF FREEZING POINTS OF JET A/JET A-1 FUEL BLENDS, SERVICE LETTER					RECOMMENDED	
			MOS					
	28-NOV-2011			-				
SL	737-SL-28-062	POSSIBLE MISS-LOCATION OF FUEL TANK VENT TUBE CLIMB PORT, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-JUN-2003			-				
SL	737-SL-28-062 REV. A	POSSIBLE MISS-LOCATION OF FUEL TANK VENT TUBE CLIMB PORT, SERVICE LETTER					INFORMATIONAL	
			MOS					
	15-SEP-2003			-				
SL	737-SL-28-062 REV. B	POSSIBLE MISS - LOCATION OF FUEL TANK VENT TUBE CLIMB PORT, SERVICE LETTER					RECOMMENDED	
			MOS					
	20-JUN-2005			-				

© Camp Systems

EFTA00618571

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-28-063	APU FUEL LINE SHROUD DRAIN MAST DAMAGE PROTECTION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	19-NOV-2003			-				
SL	737-SL-28-063 REV. A	APU FUEL LINE SHROUD DRAIN MAST DAMAGE PROTECTION, SERVICE LETTER						
			MOS					
	18-MAR-2005			-				
SL	737-SL-28-063 REV. B	APU FUEL LINE SHROUD DRAIN MAST DAMAGE PROTECTION, SERVICE LETTER						
			MOS					
	07-AUG-2006			-				
SL	737-SL-28-065	POTENTIAL FUEL LEAKS IN THE OUTBOARD DRYBAY ON 737NG AIRPLANE RETROFITTED WITH BLENDED WINGLETS, SERVICE LETTER						
			MOS					
	28-JUN-2004			-				
SL	737-SL-28-065 REV. A	POTENTIAL FUEL LEAKS IN THE OUTBOARD DRYBAY ON 737NG AIRPLANE RETROFITTED WITH BLENDED WINGLETS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	01-AUG-2005			-				
SL	737-SL-28-066	SPECIAL FEDERAL AVIATION REGULATION (SFAR) 88 DESIGN, OPERATION, AND MAINTENANCE TRAINING INFORMATION, SERVICE LETTER						
			MOS					
	13-FEB-2007			-				
SL	737-SL-28-066 REV. A	SPECIAL FEDERAL AVIATION REGULATION (SFAR) 88 DESIGN, OPERATION, AND MAINTENANCE TRAINING INFORMATION, SERVICE LETTER						
			MOS					
	17-JUN-2008			-				
SL	737-SL-28-067	SUSPECT FUELING FLOAT SWITCHES, SERVICE LETTER						
			MOS					
	05-APR-2007			-				
SL	737-SL-28-067 REV. A	SUSPECT FUELING FLOAT SWITCHES, SERVICE LETTER						
			MOS					
	13-DEC-2007			-				
SL	737-SL-28-069	FUEL SYSTEM MOTOR OPERATED VALVE ACTUATORS, SERVICE LETTER						
			MOS					
	21-MAY-2007			-				

© Camp Systems

EFTA00618572

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-28-069 REV. A	FUEL SYSTEM MOTOR OPERATED VALVE ACTUATORS, SERVICE LETTER	MOS	-				
05-DEC-2008							
SL 737-SL-28-070	GROUND FAULT INTERRUPT (GFI) RELAYS FOR THE FUEL BOOST PUMP, SERVICE LETTER	MOS	-				
24-JUL-2007							
SL 737-SL-28-070 REV. A	GROUND FAULT INTERRUPT (GFI) RELAYS FOR THE FUEL BOOST PUMP, SERVICE LETTER	MOS	-				
27-MAR-2008							
SL 737-SL-28-071	AVIATION FUELS SPECIFICATION, SERVICE LETTER	MOS	-				
18-JAN-2008							
SL 737-SL-28-071 REV. A	AVIATION FUELS SPECIFICATION, SERVICE LETTER	MOS	-				
19-FEB-2008							
SL 737-SL-28-071 REV. B	AVIATION FUELS SPECIFICATION, SERVICE LETTER	MOS	-				
31-JUL-2008							
SL 737-SL-28-071 REV. C	AVIATION FUELS SPECIFICATION (SUPERSEDED BY SL 737-SL-28-071 REV. D), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-28-071 REV. D	AVIATION FUELS SPECIFICATION (SUPERSEDED BY SL 737-SL-28-071 REV. E), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-28-071 REV. E	AVIATION FUELS SPECIFICATION, SERVICE LETTER	MOS	-			RECOMMENDED	
27-JUN-2012							
SL 737-SL-28-072	WIRE BUNDLE W1126 POSSIBLE CHAFING, SERVICE LETTER	MOS	-				
18-JUL-2008							
SL 737-SL-28-072 REV. A	WIRE BUNDLE W1126 POSSIBLE CHAFING, SERVICE LETTER	MOS	-				
24-OCT-2008							

© Camp Systems

EFTA00618573

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-28-073	INTRODUCTION OF IMPROVED SPAR, DEFUEL AND CROSSFEED VALVE DISK, SERVICE LETTER						COMPLIED WITH
			MOS		29-AUG-2011			
	18-FEB-2009			- (s)	3533:32			
			AFL		863			
SL	737-SL-28-073 REV. A	INTRODUCTION OF IMPROVED SPAR, DEFUEL AND CROSSFEED VALVE DISK (SUPERSEDED BY SL 737-SL-28-073 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-28-073 REV. B	INTRODUCTION OF IMPROVED SPAR, DEFUEL AND CROSSFEED VALVE DISK (SUPERSEDED BY SL 737-SL-28-073 REV. C), SERVICE LETTER					SUPERSEDED	COMPLIED WITH
			MOS		29-AUG-2011			
				-	3533:32			
			AFL		863			
SL	737-SL-28-073 REV. C	INTRODUCTION OF IMPROVED SPAR, DEFUEL AND CROSSFEED VALVE DISK, SERVICE LETTER					RECOMMENDED	
			MOS					
	25-JUL-2012			-				
SL	737-SL-28-074	CENTER TANK REFUEL TUBE LOCATED IN THE RIGHT WING P/N 344A2202-8 MAY BE INSTALLED BACKWARDS, SERVICE LETTER					RECOMMENDED	
			MOS					
	14-MAY-2009			-				
SL	737-SL-28-075	POTENTIAL FOR FOREIGN OBJECTS LEFT IN THE FUEL TANK AFTER REWORK PRIOR TO AIRPLANE DELIVERY, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-AUG-2009			-				
SL	737-SL-28-076	POSSIBLE OVER-TWISTED LOCKWIRE ON THE MAIN TANK FUEL BOOST PUMPS, SERVICE LETTER					RECOMMENDED	
			MOS					
	24-NOV-2009			-				
SL	737-SL-28-077	POSSIBLE OVER-TWISTED LOCKWIRE ON THE CENTER TANK FUEL BOOST PUMP DRAIN PLUG, SERVICE LETTER					RECOMMENDED	
			MOS					
	24-NOV-2009			-				
SL	737-SL-28-078	POSSIBLE LACK OF SEALANT ON THE FUEL PUMP PRESSURE SWITCH SPAR PENETRATIONS FOR THE LEFT AND RIGHT FORWARD MAIN-TANK PUMPS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	22-DEC-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-28-079	POSSIBLE LACK OF SEALANT ON THE FUEL PUMP PRESSURE SWITCH SPAR PENETRATIONS FOR THE LEFT AND RIGHT CENTER-TANK OVERRIDE-PUMPS, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-DEC-2009			-				
SL 737-SL-28-080	POTENTIAL UNDER-TORQUED FUEL SUMP DRAIN AND AN UNDER-TORQUED BULKHEAD FITTING NUT (SUPERSEDED BY 737-SL-28-080-A), SERVICE LETTER					SUPERSEDED	
		MOS					
15-FEB-2010			-				
SL 737-SL-28-080 REV. A	POTENTIAL UNDER-TORQUED FUEL SUMP DRAIN AND AN UNDER-TORQUED BULKHEAD FITTING NUT, SERVICE LETTER						
		MOS					
09-JUN-2010			-				
SL 737-SL-28-081	CONNECTOR D01828 HAS INCORRECT PLATING, SERVICE LETTER					RECOMMENDED	
		MOS					
25-MAR-2010			-				
SL 737-SL-28-082	AIRCRAFT MAINTENANCE WITH FUEL CELLS OPEN, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-APR-2010			-				
SL 737-SL-28-082 REV. A	AIRCRAFT MAINTENANCE WITH FUEL CELLS OPEN (SUPERSEDED BY 737-SL-28-082 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
22-APR-2010			-				
SL 737-SL-28-082 REV. B	AIRCRAFT MAINTENANCE WITH FUEL CELLS OPEN (SUPERSEDED BY SL 737-SL-28-082 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-082 REV. C	AIRCRAFT MAINTENANCE WITH FUEL CELLS OPEN, SERVICE LETTER					RECOMMENDED	
		MOS					
27-JUN-2011			-				
SL 737-SL-28-083	POTENTIALLY MIS-INSTALLED LOCKWIRE FOR THE RH MAIN TANK FUEL QUANTITY INDICATING SYSTEM(FQIS) BULKHEAD CONNECTOR, SERVICE LETTER						
		MOS					
17-JUN-2010			-				
SL 737-SL-28-085	WIRE BUNDLE CONTACTS P-15 REFUELING PANEL (SUPERSEDED BY SL 737-SL-28-085 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-28-085 REV. A	WIRE BUNDLE CONTACTS P-15 REFUELING PANEL, SERVICE LETTER					RECOMMENDED	
		MOS					
31-JAN-2012			-				
SL 737-SL-28-086	P/N 343A2212-3/-4 WATER SCAVENGE TUBE CLEARANCE (SUPERSEDED BY SL 737-SL-28-086 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-086 REV. A	P/N 343A2212-3/-4 WATER SCAVENGE TUBE CLEARANCE (SUPERSEDED BY SL 737-SL-28-086 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-086 REV. B	P/N 343A2212-3/-4 WATER SCAVENGE TUBE CLEARANCE (SUPERSEDED BY SL 737-SL-28-086 REV. C), SERVICE LETTER					RECOMMENDED	
		MOS					
18-APR-2012			-				
SL 737-SL-28-086 REV. C	P/N 343A2212-3/-4 WATER SCAVENGE TUBE CLEARANCE (SUPERSEDED BY SL 737-SL-28-086 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-086 REV. D	P/N 343A2212-3/-4 WATER SCAVENGE TUBE CLEARANCE, SERVICE LETTER					RECOMMENDED	
		MOS					
25-MAR-2014			-				
SL 737-SL-28-087	FUEL QUANTITY INDICATION SYSTEM (FQIS) FUEL TANK UNITS WITH PLASTIC CLAMPS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-MAY-2011			-				
SL 737-SL-28-088	SHIELD GROUND WIRES NOT CONNECTED TO GROUND STUD (SUPERSEDED BY SL 737-SL-28-088 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-088 REV. A	SHIELD GROUND WIRES NOT CONNECTED TO GROUND STUD, SERVICE LETTER					RECOMMENDED	
		MOS					
14-NOV-2011			-				
SL 737-SL-28-089	MOTOR OPERATED VALVE (MOV) ACTUATOR IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
19-DEC-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-28-090	REFUELING PANEL LAMP MOD, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUL-2012			-				
SL 737-SL-28-091	MISSING GROMMET FOR THE CENTER FUEL TANK SUMP DRAIN VALVE (SUPERSEDED BY SL 737-SL-28-091 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-28-091 REV. A	MISSING GROMMET FOR THE CENTER FUEL TANK SUMP DRAIN VALVE, SERVICE LETTER					RECOMMENDED	
		MOS					
13-JUN-2012			-				
SL 737-SL-28-092	POTENTIAL MISSING WASHER AT FUEL TANK VENT TUBE DRAIN, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUL-2012			-				
SL 737-SL-28-093	MAIN TANK REFUEL TUBE ASSEMBLY, 344A2201-12, MAY BE INSTALLED INCORRECTLY, SERVICE LETTER					RECOMMENDED	
		MOS					
06-MAR-2013			-				
SL 737-SL-28-094	FUEL TEMPERATURE SENSOR WIRE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JUN-2013			-				
SL 737-SL-28-095	ENGINE FUEL SUCTION FEED TEST - ENGINE PARAMETER CHANGES , SERVICE LETTER					RECOMMENDED	
		MOS					
13-AUG-2013			-				
SL 737-SL-28-096	ENGINE FUEL SHUTOFF VALVE WIRE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
10-DEC-2013			-				
SL 737-SL-28-098	FUEL BOOST PUMP BACKSHELL CHAFING WIRES, SERVICE LETTER					RECOMMENDED	
		MOS					
24-JUN-2014			-				
SL 737-SL-28-099	POSSIBLE MISSING FINISH ON APU DRAIN MAST TUBE, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUL-2014			-				
SL 737-SL-29-069	HYDRAULIC PRESSURE SWITCH REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-AUG-1996			- (s)				

© Camp Systems

EFTA00618577

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-29-069 REV. A	HYDRAULIC PRESSURE SWITCH REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
30-JAN-1997			- (s)				
SL 737-SL-29-069 REV. B	HYDRAULIC PRESSURE SWITCH REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-APR-1999			- (s)				
SL 737-SL-29-069 REV. C	HYDRAULIC PRESSURE SWITCH REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
24-MAY-2010			-				
SL 737-SL-29-074	HYDRAULIC PRESSURE TRANSDUCER IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-JUN-1998			- (s)				
SL 737-SL-29-075	IMPROVED HYDRAULIC STANDBY SYSTEM MODULAR PACKAGE HOUSING, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-AUG-1998			- (s)				
SL 737-SL-29-076	CHAFING OF HYDRAULIC SYSTEM A ELECTRIC MOTOR-DRIVEN PUMP PRESSURE HOSE ON RETURN FILTER V-BAND CLAMP, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-NOV-1998			- (s)				
SL 737-SL-29-076 REV. A	CHAFING OF HYDRAULIC SYSTEM A ELECTRIC MOTOR-DRIVEN PUMP PRESSURE HOSE ON RETURN FILTER V-BAND CLAMP, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JUN-1999			- (s)				
SL 737-SL-29-078	HYDRAULIC FLUID NEW FORMULATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-JUL-1999			- (s)				
SL 737-SL-29-079	INSUFFICIENT SWAGE ON THRUST REVERSER HYDRAULIC HOSES. P/N AS115-06H0152, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-DEC-1999			- (s)				
SL 737-SL-29-080	CROSS CONNECTION OF LANDING GEAR HYDRAULIC LINES, SERVICE LETTER					INFORMATIONAL	
		MOS					
05-JUL-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-29-081	IMPROVED ENGINE DRIVEN HYDRAULIC PUMP HOSE QUICK-DISCONNECTS, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - -ACCOMPLISHED ON AAC WO 1828 AW040 CLOSED 06/15/01. CONSTITUTES TERMINATING ACTION.
		MOS		23-JUL-2001			
	03-NOV-2000		500 (s)	320			
		AFL		127			
SL 737-SL-29-082	NEW ELEVATOR TAB LOCK ACTUATOR HOSE, SERVICE LETTER					INFORMATIONAL	
		MOS					
	17-NOV-2000		- (s)				
SL 737-SL-29-082 REV. A	NEW ELEVATOR TAB LOCK ACTUATOR HOSE, SERVICE LETTER					INFORMATIONAL	
		MOS					
	21-DEC-2000		- (s)				
SL 737-SL-29-082 REV. B	NEW ELEVATOR TAB LOCK ACTUATOR HOSE, SERVICE LETTER					INFORMATIONAL	
		MOS					
	23-MAR-2004		-				
SL 737-SL-29-083 REV. A	POSSIBLE IMPROPERLY TORQUED JAM NUTS ON BULKHEAD HYDRAULIC FITTINGS, SERVICE LETTER					INFORMATIONAL	
		MOS					
	12-OCT-2001		- (s)				
SL 737-SL-29-084	POSSIBLE THIN-WALL CONDITION ON PARKER ABEX ELECRTIC MOTOR-DRIVEN PUMPS, SERVICE LETTER						
		MOS	24 (s)				
	08-OCT-2001						
SL 737-SL-29-084 REV. A	POSSIBLE THIN-WALL CONDITION ON PARKER ABEX ELECRTIC MOTOR-DRIVEN PUMPS, SERVICE LETTER						
		MOS	24 (s)				
	08-OCT-2001						
SL 737-SL-29-085	LOOSE JAM NUT ON ENGINE STRUT HYDRAULIC FITTING, SERVICE LETTER						
		MOS					
	21-AUG-2002		-				
		AFL					
SL 737-SL-29-085 REV. A	LOOSE JAM NUT ON ENGINE STRUT HYDRAULIC FITTING, SERVICE LETTER					INFORMATIONAL	
		MOS					
	03-JUN-2003		-				
SL 737-SL-29-085 REV. B	LOSE JAM NUT ON ENGINE STRUT HYDRAULIC FITTING (SUPERSEDED BY SL 737-SL-29-085 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-29-085 REV. C	LOOSE JAM NUT ON ENGINE STRUT HYDRAULIC FITTING, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JUN-2011			-				
SL 737-SL-29-086	ELECTRIC MOTOR OPERATED HYDRAULIC SHUTOFF VALVE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2002			-				
SL 737-SL-29-087	TITEFLEX DISCLOSURE,IMPROPER HEAT TREATMENT ON HOSE B-NUTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-APR-2003			-				
SL 737-SL-29-088	DRUCK HYDRAULIC PRESSURE TRANSDUCER DISCREPANCY, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-JAN-2003			-				
SL 737-SL-29-089	ENGINE DRIVEN PUMP(EDP) AND AIR DRIVEN PUMP (ADP) - REPLACEMENT OF DISCREPANT WEAR PLATE, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-MAR-2003			-				
SL 737-SL-29-090	FLIGHT CONTROLS HYDRAULIC MODULAR PACKAGE REPLACEMENT - INTERCHANGEABILITY (SUPERSEDED BY SL 737-SL-29-090 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-29-090 REV. A	FLIGHT CONTROLS HYDRAULIC MODULAR PACKAGE REPLACEMENT-INTERCHANGEABILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
23-NOV-2011			-				
SL 737-SL-29-091	METHODS TO HELP REDUCE OR ELIMINATE PRELOAD WHEN REPLACING FRACTURED HYDRAULIC PRESSURE TUBE P/N 312A2110-2 IN 737NG STRUTS, SERVICE LETTER						
		MOS					
24-MAR-2005			-				
SL 737-SL-29-092 REV. A	RECOMMENDED ACTION TO RESOLVE CORROSION OF HYDRAULIC TUBES IN THE WHEEL WELLS CAUSED BY EXPOSURE TO POTASSIUM-CONTAINING RUNWAY DEICING FLUIDS, SERVICE LETTER						
		MOS					
22-AUG-2005			-				
SL 737-SL-29-092 REV. B	RECOMMENDED ACTION TO RESOLVE CORROSION OF HYDRAULIC TUBES IN THE WHEEL WELLS CAUSED BY EXPOSURE TO POTASSIUM-CONTAINING RUNWAY DEICING FLUIDS, SERVICE LETTER						
		MOS					
21-MAR-2006			-				

© Camp Systems

EFTA00618580

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-29-095	HYDRAULIC FLUID EXTERNAL LEAKAGE - RELIABILITY IMPROVEMENTS (SUPERSEDED BY SL 737-SL-29-095 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-095 REV. A	HYDRAULIC FLUID EXTERNAL LEAKAGE - RELIABILITY IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	22-DEC-2010			-				
SL	737-SL-29-096	INCORRECT SEALS IN HYDRAULIC SYSTEM A HEAT EXCHANGER FITTINGS, SERVICE LETTER						
			MOS					
	12-APR-2007			-				
SL	737-SL-29-097	INCORRECT SADDLE-TYPE TUBE CLAMPS INSTALLED, SERVICE LETTER						
			MOS					
	24-JUL-2007			-				
SL	737-SL-29-099	CORROSION-RESISTANT HYDRAULIC FUSES (SUPERSEDED BY 737-SL-29-099-A), SERVICE LETTER					SUPERSEDED	
			MOS					
	28-AUG-2007			-				
SL	737-SL-29-099 REV. A	CORROSION-RESISTANT HYDRAULIC FUSES, SERVICE LETTER						
			MOS					
	07-JUN-2010			-				
SL	737-SL-29-100	TROUBLESHOOTING OF REPEATED ENGINE-DRIVEN PUMP FAILURES, SERVICE LETTER						
			MOS					
	10-OCT-2007			-				
SL	737-SL-29-100 REV. A	TROUBLESHOOTING OF REPEATED ENGINE-DRIVEN PUMP FAILURES, SERVICE LETTER						
			MOS					
	17-OCT-2007			-				
SL	737-SL-29-101	FILTER ELEMENTS WITH INCORRECT EPOXY OR INCORRECTLY MACHINED O-RING GROOVES, SERVICE LETTER						
			MOS					
	17-DEC-2007			-				
SL	737-SL-29-101 REV. A	FILTER ELEMENTS WITH INCORRECT EPOXY OR INCORRECTLY MACHINED O-RING GROOVES, SERVICE LETTER						
			MOS					
	20-FEB-2008			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-29-102	STANDBY HYDRAULIC SYSTEM CASE DRAIN FILTER / CHECK VALVE INSTALLED REVERSED, SERVICE LETTER						
			MOS					
	20-JUN-2008			-				
SL	737-SL-29-102 REV. A	STANDBY HYDRAULIC SYSTEM CASE DRAIN FILTER / CHECK VALVE INSTALLED REVERSED, SERVICE LETTER						COMPLIED WITH
			MOS		28-SEP-2009			
	23-JAN-2009			-	3378:04			
			AFL		812			
SL	737-SL-29-103	HYDRAULIC FLUID - NEW FORMULATION, SERVICE LETTER						
			MOS					
	26-JUN-2008			-				
SL	737-SL-29-103 REV. A	HYDRAULIC FLUID - NEW FORMULATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	07-MAY-2012			-				
SL	737-SL-29-104	EXCESS SLACK IN WIRE W8538 CAUSES CHAFING AGAINST FAIRING PANEL, SERVICE LETTER						
			MOS					
	29-AUG-2008			-				
SL	737-SL-29-104 REV. A	EXCESS SLACK IN WIRE W8538 CAUSES CHAFING AGAINST FAIRING PANEL (SUPERSEDE BY SL 737-SL-29-104 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-104 REV. B	EXCESS SLACK IN WIRE W8538 CAUSES CHAFING AGAINST FAIRING PANEL, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-MAY-2011			-				
SL	737-SL-29-105	HYDRAULIC RESERVOIR DRAIN VALVE LEAKAGE, SERVICE LETTER						
			MOS					
	11-AUG-2008			-				
SL	737-SL-29-106	RECOMMENDED HANDLING AND STORAGE PRACTICES FOR HYDRAULIC COMPONENTS USING BMS 3-11, SERVICE LETTER						
			MOS					
	17-FEB-2009			-				
SL	737-SL-29-107	CRACKING OF HYDRAULIC STANDBY SYSTEM RESERVOIR BOSS—AVAILABILITY OF NEW TUBE, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-MAY-2009			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-29-108	HYDRAULIC PRESSURE MODULE CARTRIDGE CHECK VALVE FRACTURES, SERVICE LETTER					RECOMMENDED	
			MOS					
	07-JUL-2009			-				
SL	737-SL-29-108 REV. B	HYDRAULIC PRESSURE MODULE CARTRIDGE CHECK VALVE FRACTURES, SERVICE LETTER					INFORMATIONAL	
			MOS					
	15-MAR-2010			-				
SL	737-SL-29-108 REV. C	HYDRAULIC PRESSURE MODULE CARTRIDGE CHECK VALVE FRACTURES (SUPERSEDED BY SL 737-SL-29-108 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-108 REV. D	POTENTIAL PERSONAL HAZARD - HYDRAULIC PRESSURE MODULE CARTRIDGE CHECK VALVE FRACTURES (SUPERSEDED BY SB 737-SL-29-108 REV. E), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-108 REV. E	POTENTIAL PERSONAL HAZARD - HYDRAULIC PRESSURE MODULE CARTRIDGE CHECK VALVE FRACTURES, SERVICE LETTER					RECOMMENDED	
			MOS					
	12-JUL-2013			-				
SL	737-SL-29-109	INTRODUCTION OF AXIALLY SWAGED PERMANENT HYDRAULIC FITTING AND TUBE INSTALLATIONS TO THE MAIN LANDING GEAR (MLG) WHEEL WELL (SUPERSEDED BY SL 737-SL-29-109 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-109 REV. A	INTRODUCTION OF AXIALLY SWAGED PERMANENT HYDRAULIC FITTING AND TUBE INSTALLATIONS TO THE MAIN LANDING GEAR (MLG) WHEEL WELL (SUPERSEDED BY SL 737-SL-29-109 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-109 REV. B	INTRODUCTION OF AXIALLY SWAGED PERMANENT HYDRAULIC FITTING AND TUBE INSTALLATIONS TO THE MAIN LANDING GEAR (MLG) WHEEL WELL, SERVICE LETTER					RECOMMENDED	
			MOS					
	11-JAN-2012			-				
SL	737-SL-29-110	HYDRAULIC FLUID - NEW FORMULATION-SKYDROL-PE-5, SERVICE LETTER						
			MOS					
	18-JUN-2010			-				
SL	737-SL-29-111	POSSIBLE HYDRAULIC TUBE INSUFFICIENT CLEARANCE, MAIN WHEEL WELL (SUPERSEDED BY SL 737-SL-29-111 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-29-111 REV. A	POSSIBLE HYDRAULIC TUBE INSUFFICIENT CLEARANCE, MAIN WHEEL WELL, SERVICE LETTER					RECOMMENDED	
			MOS					
	28-SEP-2011			-				
SL	737-SL-29-112	RETURN FILTER MODULE IMPROVEMENTS – SYSTEM-A AND SYSTEM-B HYDRAULIC POWER (SUPERSEDED BY SL 737-SL-29-112 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-112 REV. A	RETURN FILTER MODULE IMPROVEMENTS – SYSTEM-A AND SYSTEM-B HYDRAULIC POWER (SUPERSEDED BY SL 737-SL-29-112 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-112 REV. B	RETURM FILTER MODULE IMPROVEMENTS - SYSTEN-A AND SYSTEM-B HYDRAULIC POWER, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-JUL-2012			-				
SL	737-SL-29-113	POTENTIAL INSUFFICIENT CLEARANCE BETWEEN HYDRAULIC TUBE AND FILTER MODULE, SERVICE LETTER					RECOMMENDED	
			MOS					
	16-SEP-2011			-				
SL	737-SL-29-114	MISSING PACKING IN FUSE ASSEMBLY P/N 2-7680-2 (SUPERSEDED BY SL 737-SL-29-114 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-114 REV. A	MISSING PACKING IN FUSE ASSEMBLY P/N 2-7680-2, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-APR-2012			-				
SL	737-SL-29-115	GROUND STUD DECALS GD304DC & GD304ST (SUPERSEDED BY SL 737-SL-29-115 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-29-115 REV. A	GROUND STUD DECALS GD304DC & GD304ST (SUPERSEDED BY 737-SL-29-115 REV. B), SERVICE LETTER					RECOMMENDED	
			MOS					
	08-AUG-2012			-				
SL	737-SL-29-115 REV. B	GROUND STUD DECALS GD304DC & GD304ST, SERVICE LETTER					RECOMMENDED	
			MOS					
	06-MAR-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-29-116	POSSIBLE INSUFFICIENTLY TIGHTENED HYDRAULIC TUBE CONNECTIONS – LEFT AND RIGHT INBOARD WING REAR SPAR INSTALLATIONS (SUPERSEDED BY SL 737-SL-29-116 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-29-116 REV. A	POSSIBLE INSUFFICIENTLY TIGHTENED HYDRAULIC TUBE CONNECTIONS ? LEFT AND RIGHT INBOARD WING REAR SPAR INSTALLATIONS, SERVICE LETTER					RECOMMENDED	
13-APR-2012		MOS	-				
SL 737-SL-29-117	IMPROVED EDP PRESSURE HOSE QUICK-DISCONNECTS, SERVICE LETTER					RECOMMENDED	
30-JUL-2012		MOS	-				
SL 737-SL-29-118	DETERMINE INSTALLATION TORQUE FOR TUBES/FITTINGS/HOSES, SERVICE LETTER					RECOMMENDED	
30-NOV-2012		MOS	-				
SL 737-SL-29-119	TROUBLESHOOTING HYDRAULIC TUBE/FITTING/HOSE LEAKAGE, SERVICE LETTER					RECOMMENDED	
02-APR-2013		MOS	-				
SL 737-SL-29-120	PREMATURE LEAKAGE OF SHAFT SEAL ON PARKER HYDRAULIC EDP AND PTU, SERVICE LETTER					RECOMMENDED	
10-DEC-2013		MOS	-				
SL 737-SL-29-121	INCORRECT ORIENTATION OF POWER TRANSFER UNIT (PTU) PRESSURE FILTER ASSEMBLY, SERVICE LETTER					RECOMMENDED	
03-APR-2014		MOS	-				
SL 737-SL-30-017	COWL THERMAL ANT-ICE VALVE IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
13-OCT-2000		MOS	- (s)				
SL 737-SL-30-019	INTRODUCTION OF IMPROVED NOSE COWL THERMAL ANTI-ICE VALVE (SUPERSEDED BY SL 737-SL-30-019 REV. A), SERVICE LETTER					SUPERSEDED	
28-JUL-2003		MOS	-				
SL 737-SL-30-019 REV. A	INTRODUCTION OF IMPROVED NOSE COWL THERMAL ANTI-ICE VALVES, SERVICE LETTER						
20-SEP-2013		MOS	-				

© Camp Systems

EFTA00618585

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-30-021	WINDOW HEAT CONTROL UNIT - DUST CONTAMINATION CLEANING PROCEDURES, SERVICE LETTER						COMPLIED WITH
			MOS		28-SEP-2009			
	29-AUG-2006			-	3378:04			
			AFL		812			
SL	737-SL-30-024	IDENTIFICATION OF DRAIN MAST MATERIAL, SERVICE LETTER					INFORMATIONAL	
			MOS					
	28-APR-2010			-				
SL	737-SL-30-025	POTENTIAL IMPROPERLY TORQUED NUTS ON THE WING ANTI-ICE DUCT SUPPORT CLAMP (SUPERSEDED BY SL 737-SL-30-025 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-30-025 REV. A	POTENTIAL IMPROPERLY TORQUED NUTS ON THE WING ANTI-ICE DUCT SUPPORT CLAMP, SERVICE LETTER					RECOMMENDED	
			MOS					
	12-AUG-2013			-				
SL	737-SL-31-038	COMMON DISPLAY SYSTEM (CDS) SOFTWARE UPDATE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	08-DEC-1998			- (s)				
SL	737-SL-31-039	COMMON DISPLAY SYSTEM (CDS) AND AIRPLANE INFORMATION MANAGEMENT SYSTEM (AIMS) NORMALLY WHITE (NW) DISPLAY UNIT (DU) INCORPORATION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	10-MAR-1999			- (s)				
SL	737-SL-31-039 REV. A	COMMON DISPLAY SYSTEM (CDS) AND AIRPLANE INFORMATION MANAGEMENT SYSTEM (AIMS) NORMALLY WHITE (NW) DISPLAY UNIT (DU) INCORPORATION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-DEC-2000			- (s)				
SL	737-SL-31-040	STICK SHAKEN SPEED DIFFERENCES INFORMATION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	05-APR-1999			- (s)				
SL	737-SL-31-041	COMMON DISPLAY SYSTEM(CDS) BLOCK POINT 99 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	24-DEC-1999			- (s)				
SL	737-SL-31-042	DISPLAYS: INCORPORATION OF PHASE II NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	17-SEP-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-31-042 REV. A	DISPLAYS: INCORPORATION OF PHASE II NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER						
		MOS					
07-NOV-2007			-				
SL 737-SL-31-043	RUDDER PEDAL POSITION SENSOR COTTER PIN INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-NOV-2001			- (s)				
SL 737-SL-31-044	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-FEB-2003			-				
SL 737-SL-31-044 REV. A	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-MAR-2003			-				
SL 737-SL-31-044 REV. B	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-JUN-2003			-				
SL 737-SL-31-044 REV. C	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-JUL-2003			-				
SL 737-SL-31-044 REV. D	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-AUG-2003			-				
SL 737-SL-31-044 REV. E	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-OCT-2003			-				
SL 737-SL-31-044 REV. F	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 02 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-DEC-2003			-				
SL 737-SL-31-045	OPTICAL QUICK ACCESS RECORDER (OQAR) P/N D52000 SERIES MODIFICATION, SERVICE LETTER						
		MOS					
02-FEB-2005			-				
SL 737-SL-31-046	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 04 SOFTWARE RELEASE, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-MAR-2005			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-31-046 REV. A	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 04 SOFTWARE RELEASE, SERVICE LETTER						
		MOS					
28-JUN-2005			-				
SL 737-SL-31-046 REV. B	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 04A SOFTWARE RELEASE, SERVICE LETTER						
		MOS					
16-NOV-2005			-				
SL 737-SL-31-047	GPS CLOCK REPLACEMENT, P/N 9010-1-3, SERVICE LETTER						
		MOS					
16-JAN-2006			-				
SL 737-SL-31-048	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 06 SOFTWARE RELEASE, SERVICE LETTER						
		MOS					
19-SEP-2006			-				
SL 737-SL-31-048 REV. A	COMMON DISPLAY SYSTEM (CDS) BLOCK POINT 06 SOFTWARE RELEASE, SERVICE LETTER						COMPLIED WITH
		MOS		22-AUG-2008			
18-SEP-2007			-	3260:48			
		AFL		782			
SL 737-SL-31-049	CDS INHIBITION OF PFD TIME CRITICAL ALERTS, SERVICE LETTER						
		MOS					
15-MAR-2007			-				
SL 737-SL-31-050	COMMON DISPLAY SYSTEM (CDS) DISPLAY ELECTRONIC UNIT (DEU-II), SERVICE LETTER						
		MOS					
12-SEP-2007			-				
SL 737-SL-31-050 REV. A	COMMON DISPLAY SYSTEM (CDS) DISPLAY ELECTRONIC UNIT (DEU-II), SERVICE LETTER						
		MOS					
05-MAY-2008			-				
SL 737-SL-31-051	DISPLAYS: INCORPORATION OF PHASE 3 NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER						
		MOS					
09-JAN-2009			-				
SL 737-SL-31-051 REV. A	DISPLAYS: INCORPORATION OF PHASE 3 NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
26-MAR-2009			-				

© Camp Systems

EFTA00618588

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-31-051 REV. B	DISPLAYS: INCORPORATION OF PHASE 3 NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
26-JUN-2009			-				
SL 737-SL-31-051 REV. C	DISPLAYS: INCORPORATION OF PHASE 3 NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
10-SEP-2009			-				
SL 737-SL-31-052	AURAL WARNING MODULE P/N 69-78214-4, SERVICE LETTER					RECOMMENDED	
		MOS					
01-MAY-2009			-				
SL 737-SL-31-052 REV. A	AURAL WARNING MODULE P/N 69-78214-4, SERVICE LETTER					RECOMMENDED	
		MOS					
16-SEP-2009			-				
SL 737-SL-31-052 REV. B	AURAL WARNING MODULE P/N 69-78214-4, SERVICE LETTER					RECOMMENDED	
		MOS					
14-DEC-2009			-				
SL 737-SL-31-053	COMMON DISPLAY SYSTEM (CDS) DISPLAY ELECTRONIC UNIT (DEU-II) MOD A, SERVICE LETTER					RECOMMENDED	
		MOS					
11-SEP-2009			-				
SL 737-SL-31-055	P8 AISLE STAND STAB TRIM LIGHTPLATE WITH INCORRECT NOMENCLATURE , SERVICE LETTER					RECOMMENDED	
		MOS					
22-FEB-2010			-				
SL 737-SL-31-056	NEW S651 SPEEDBRAKE LEVER TAKEOFF WARNING SWITCH ANOMALIES (SUPERSEDED BY SL 737-SL-31-056 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-31-056 REV. A	NEW S651 SPEEDBRAKE LEVER TAKEOFF WARNING SWITCH ANOMALIES, SERVICE LETTER					RECOMMENDED	
		MOS					
19-MAY-2011			-				
SL 737-SL-31-057	HORIZONTAL STABILIZER TAKEOFF WARNING SWITCH INSTALLATION (SUPERSEDED BY SL 737-SL-31-057 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-31-057 REV. A	HORIZONTAL STABILIZER TAKEOFF WARNING SWITCH INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2013			-				
SL 737-SL-31-058	P1-3 AND P3-1 PANEL MODIFICATION; VENDOR SERVICE BULLETINS FOR THE CABIN ALTITUDE AND TAKE-OFF WARNING LIGHTS (SUPERSEDED BY SL 737-SL-31-058 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-31-058 REV. A	P1-3 AND P3-1 PANEL MODIFICATION; VENDOR SERVICE BULLETINS FOR THE CABIN ALTITUDE AND TAKE-OFF WARNING LIGHTS, SERVICE LETTER					RECOMMENDED	
		MOS					
06-AUG-2012			-				
SL 737-SL-31-059	DISPLAYS: INCORPORATION OF PHASE 3A NORMALLY WHITE DISPLAY UNITS, SERVICE LETTER					RECOMMENDED	
		MOS					
17-SEP-2012			-				
SL 737-SL-32-074	PROXIMITY SWITCH ELECTRONIC UNIT, P/N Z85A1600, BITE MODULE CASKET MODIFICATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JAN-2000			- (s)				
SL 737-SL-32-075	IMPROPERLY TORQUED NOSE WHEEL STEERING TILLER NUT, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-MAR-1999			- (s)				
SL 737-SL-32-075 REV. A	IMPROPERLY TORQUED NOSE WHEEL STEERING TILLER NUT, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-NOV-2000			- (s)				
SL 737-SL-32-076	MLG BRAKE HOUSING CORROSION AT HYDRAULIC DISCONNECT, SERVICE LETTER					RECOMMENDED	
		MOS					
17-SEP-2001			- (s)				
SL 737-SL-32-076 REV. B	MAIN LANDING GEAR BRAKE HOUSING CORROSION AT THE HYDRAULIC DISCONNECT COUPLING, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-SEP-2001			- (s)				
SL 737-SL-32-077	MLG TIRE SHOULDER WEAR, SERVICE LETTER					RECOMMENDED	
		MOS					
05-MAY-1999			- (s)				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-32-078	ANTISKID/AUTOBRAKE CONTROL UNIT UPGRADE, SERVICE LETTER					RECOMMENDED	
	02-JUL-1999		MOS	- (s)				
SL	737-SL-32-079	APPROVED LG TIRE SUPPLIER P/NS (SUPERSEDED BY SL 737-SL-32-079 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS	- (s)				
SL	737-SL-32-079 REV. A	APPROVED LG TIRE SUPPLIER P/NS (SUPERSEDED BY SL 737-SL-32-079 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS	- (s)				
SL	737-SL-32-079 REV. B	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR (SUPERSEDED BY SL 737-SL-32-079 REV. C), SERVICE LETTER					SUPERSEDED	
			MOS	- (s)				
SL	737-SL-32-079 REV. C	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-32-079 REV. F	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. G), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-32-079 REV. G	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. H), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-32-079 REV. H	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. I), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-32-079 REV. I	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. J), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-32-079 REV. J	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES (SUPERSEDED BY SL 737-SL-32-079 REV. K), SERVICE LETTER					SUPERSEDED	
			MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-079 REV. K	APPROVED SUPPLIER PART NUMBERS FOR LANDING GEAR TIRES, SERVICE LETTER					RECOMMENDED	
		MOS					
26-AUG-2013			-				
SL 737-SL-32-080	INVESTIGATING TIRE TREAD LOSSES, SERVICE LETTER					RECOMMENDED	
		MOS					
06-AUG-1999			- (s)				
SL 737-SL-32-081 REV. A	NOSE GEAR STEERING METERING VALVE HYDRAULIC FLUID LEAKAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
26-APR-2000			- (s)				
SL 737-SL-32-082	MLG DOWN LOCK PROXIMITY SENSOR GROUND JUMPER INSTALLATION., SERVICE LETTER					RECOMMENDED	
		MOS					
17-NOV-1999			- (s)				
SL 737-SL-32-085	MLG FLEX CONDUIT CHAFING ON TORSION LINK APEX NUT., SERVICE LETTER					RECOMMENDED	
		MOS					
22-DEC-1999			- (s)				
SL 737-SL-32-086	LANDING GEAR RETRACTION DIFFICULITIES CAUSED BY MANUAL EXTENSION SYSTEM SWITCH, SERVICE LETTER					RECOMMENDED	
		MOS					
17-JAN-2000			- (s)				
SL 737-SL-32-086 REV. A	LANDING GEAR RETRACTION DIFFICULITIES CAUSED BY MANUAL EXTENSION SYSTEM SWITCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-AUG-2000			- (s)				
SL 737-SL-32-086 REV. B	LANDING GEAR RETRACTION DIFFICULTIES CAUSED BY MANUAL EXTENTION SYSTEM SWITCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-OCT-2002			-				
SL 737-SL-32-086 REV. D	LANDING GEAR RETRACTION DIFFICULTIES CAUSED BY MANUAL EXTENSION SYSTEM SWITCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-JUN-2003			-				
SL 737-SL-32-086 REV. F	LANDING GEAR RETRACTION DIFFICULTIES CAUSED BY MANUAL EXTENTION SYSTEM SWITCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-MAR-2004			-				
SL 737-SL-32-087 REV. A	NOSE GEAR TORSIN LINK APEX PIN REPLACEMENT, 162A1310-1, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-FEB-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-088	PROXIMITY SWITCH ELECTRONIC UNIT UPGRADE TO PIN 285A1600-3, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-FEB-2000			- (s)				
SL 737-SL-32-088 REV. A	PROXIMITY SWITCH ELECTRONIC UNIT UPGRADE TO P/N 285A1600-3, SERVICE LETTER					RECOMMENDED	
		MOS					
16-MAY-2000			- (s)				
SL 737-SL-32-089 REV. A	INABILITY TO EXTEND NOSE GEAR ON THE FIRST ATTEMPT, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-AUG-2000			- (s)				
SL 737-SL-32-090	USE 737 STEERING LOCKOUT PINS., SERVICE LETTER					RECOMMENDED	
		MOS					
17-APR-2000			- (s)				
SL 737-SL-32-090 REV. A	USE 737 STEERING LOCKOUT PINS., SERVICE LETTER					RECOMMENDED	
		MOS					
31-JUL-2000			- (s)				
SL 737-SL-32-091	NOSE GEAR FLEXIBLE CONDUIT P/N 287A6212-21 DAMAGED, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2000			- (s)				
SL 737-SL-32-091 REV. A	NOSE GEAR FLEXIBLE CONDUIT P/N 287A6212-21 DAMAGED, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUN-2000			- (s)				
SL 737-SL-32-091 REV. B	NOSE GEAR FLEXIBLE CONDUIT P/N 287A6212-21/-26 DAMAGE, SERVICE LETTER						
		MOS					
04-MAY-2006			-				
SL 737-SL-32-092	LEFT ALTERNATE BRAKE PRESSURE TRANSMITTER SEALANT MISSING, SERVICE LETTER					RECOMMENDED	
		MOS					
03-MAY-2000			- (s)				
SL 737-SL-32-094	COTTER PINS MISSING FROM RUDDER PEDAL STEERING INTERCONNECT MECHANISM, SERVICE LETTER					RECOMMENDED	
		MOS					
15-MAY-2000			- (s)				
SL 737-SL-32-094 REV. A	COTTER PINS MISSING FROM RUDDER PEDAL STEERING INTERCONNECT MECHANISM SERVICE LETTER, SERVICE LETTER					RECOMMENDED	
		MOS					
28-JUL-2000			- (s)				

© Camp Systems

EFTA00618593

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-094 REV. B	COTTER PINS MISSING FROM RUDDER PEDAL STEERING INTERCONNECT MECHANISM, SERVICE LETTER					RECOMMENDED	
16-AUG-2000		MOS	- (s)				
SL 737-SL-32-095	PROXIMITY SENSOR 10-61226-29 IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
20-JUL-2000		MOS	- (s)				
SL 737-SL-32-096	NOSE LANDING GEAR STEERING ACTUATOR, SERVICE LETTER					INFORMATIONAL	
23-AUG-2000		MOS	- (s)				
SL 737-SL-32-096 REV. A	NOSE LANDING GEAR STEERING ACTUATOR, SERVICE LETTER					RECOMMENDED	
22-SEP-2000		MOS	- (s)				
SL 737-SL-32-097 REV. B	PREMATURE WEAR ON 737NG NOSE GEAR STEERING COLLAR, SERVICE LETTER					INFORMATIONAL	
12-OCT-2001		MOS	- (s)				
SL 737-SL-32-097 REV. C	PREMATURE WEAR ON 737NG NOSE GEAR STEERING COLLAR, SERVICE LETTER					INFORMATIONAL	
06-MAR-2002		MOS	- (s)				
SL 737-SL-32-097 REV. D	PREMATURE WEAR ON 737NG NOSE GEAR STEERING COLLAR, SERVICE LETTER					SUPERSEDED	
17-MAR-2003		MOS	-				
SL 737-SL-32-098	LANDING GEAR BRAKE METERING VALVE CONTROL CRANK BOLT INSPECTION, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
03-OCT-2000		MOS	- (s)		19-DEC-2000		
SL 737-SL-32-100	MAIN LANDING GEAR SHIMMY DAMPER INSTALLATION AND SHIMMY INSPECTIONS, SERVICE LETTER					INFORMATIONAL	
12-APR-2002		MOS	- (s)				
SL 737-SL-32-101	LANDING GEAR WHEEL, BRAKE AND TIRE INTERCHANGEABILITY INFORMATION, SERVICE LETTER					INFORMATIONAL	
15-JUN-2001		MOS	- (s)				
SL 737-SL-32-101 REV. A	LANDING GEAR WHEEL, BRAKE AND TIRE INTERCHANGEABILITY INFORMATION, SERVICE LETTER						
13-MAY-2005		MOS	-				

© Camp Systems

EFTA00618594

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-32-101 REV. B	WHEEL, BRAKE AND TIRE INTERCHANGEABILITY INFORMATION, SERVICE LETTER						
			MOS					
	16-AUG-2007			-				
SL	737-SL-32-101 REV. C	LANDING GEAR WHEEL BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SL 737-SL-32-101 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-101 REV. D	LANDING GEAR WHEEL BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SL 737-SL-32-101 REV. E), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-101 REV. E	LANDING GEAR WHEEL BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SL 737-SL-32-101 REV. F), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-101 REV. F	LANDING GEAR WHEEL BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SL 737-SL-32-101 REV. G), SERVICE LETTER					RECOMMENDED	
			MOS					
	13-APR-2012			-				
SL	737-SL-32-101 REV. G	LANDING GEAR WHEEL BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SB 737-SL-32-101 REV. H), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-101 REV. H	LANDING GEAR WHEEL, BRAKE AND TIRE INTERCHANGEABILITY INFORMATION (SUPERSEDED BY SL 737-SL-32-101 REV. I), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-101 REV. I	LANDING GEAR WHEEL, BRAKE AND TIRE INTERCHANGEABILITY INFORMATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-MAR-2014			-				
SL	737-SL-32-103	ADDITION OF ANTI-ROTATION WASHERS TO PREVENT STEERING ACTUATOR ROD END CHAFING, SERVICE LETTER					RECOMMENDED	
			MOS					
	17-SEP-2001			- (s)				
SL	737-SL-32-103 REV. A	ADDITION OF ANTI-ROTATION WASHERS TO PREVENT STEERING ACTUATOR ROD END CHAFING, SERVICE LETTER						
			MOS					
	19-MAR-2002			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-103 REV. B	ADDITION OF ANTI-ROTATION WASHERS TO PREVENT STEERING ACTUATOR ROD END CHAFING, SERVICE LETTER						
		MOS					
05-NOV-2002			-				
		AFL					
SL 737-SL-32-104	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) UPGRADE TO P/N 285A1600-4, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-SEP-2001			- (s)				
SL 737-SL-32-105 REV. A	LANDING GEAR COMPONENT INTERCHANGEABILITY AND SAFE LIFE COMPONENT INFORMATION, SERVICE LETTER						
		MOS					
10-MAY-2005			-				
SL 737-SL-32-105 REV. B	LANDING GEAR COMPONENT INTERCHANGEABILITY AND SAFE LIFE COMPONENT INFORMATION, SERVICE LETTER						
		MOS					
28-AUG-2007			-				
SL 737-SL-32-105 REV. C	LANDING GEAR COMPONENT INTERCHANGEABILITY AND SAFE LIFE COMPONENT INFORMATION (SUPERSEDED BY SL 737-SL-32-105 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-105 REV. D	LANDING GEAR COMPONANT INTERCHANGEABILITY AND SAFE LIFE COMPONENT INFORMATION, SERVICE LETTER					RECOMMENDED	
		MOS					
21-SEP-2010			-				
SL 737-SL-32-106	REWORK OF MLG SIDE STRUT PIN P/N 161A2331 PROTECTIVE EPOXY PRIMER, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2001			- (s)				
SL 737-SL-32-107	TIE BOLT NUTS FOUND CRACKED ON HONEYWELL (BENDIX) NOSE WHEELS SERVICE LETTER, SERVICE LETTER					RECOMMENDED	
		MOS					
23-OCT-2001			-				
SL 737-SL-32-107 REV. A	TIE BOLT NUTS FOUND CRACKED ON HONEYWELL (BENDIX) NOSE WHEELS, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-NOV-2001			- (s)				
SL 737-SL-32-108	MAIN GEAR TORSION LINK APEX NUT FOUND LOOSE, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-NOV-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-110	NLG STEERING - INTERCONNECT - EXCESSIVE GAP BETWEEN CABLE QUADRANT AND CABLE KEEPER PIN, SERVICE LETTER						
		MOS					
22-FEB-2002			- (s)				
SL 737-SL-32-111 REV. A	ESTABLISHING A LIFE LIMIT FOR WHEEL TIE BOLTS ON BENDIX (HONEYWELL) 737 WHEELS (SUPERSEDED BY SL 737-SL-32-111 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-111 REV. B	ESTABLISHING A LIFE LIMIT FOR WHEEL TIE BOLTS ON BENDIX (HONEYWELL) 737 WHEELS, SERVICE LETTER					RECOMMENDED	
		MOS					
27-SEP-2012			-				
SL 737-SL-32-112 REV. A	OVERHAUL OF STEEL COMPONENTS - CADMIUM STRIP REQUIRED, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-JAN-2002			- (s)				
SL 737-SL-32-113	MAIN GEAR EXTENSION PROBLEMS CAUSED BY DOWNLOCK ACTUATOR MANUFACTURING DISCREPANCY, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-APR-2002			- (s)				
SL 737-SL-32-113 REV. A	MAIN GEAR EXTENTION PROBLEMS CAUSED BY DOWNLOCK ACUTATOR MANUFACTURING DISCREPANCY, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-JUN-2003			-				
SL 737-SL-32-116	CRACKS FOUND ON MAIN LANDING GEAR SYSTEM SUPPORT TRAYS (SUPERSEDED BY SL 737-SL-32-116 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
30-OCT-2002			- (s)				
SL 737-SL-32-116 REV. A	CRACKS FOUND ON MAIN LANDING GEAR SYSTEM SUPPORT TRAYS (SUPERSEDED BY SL 737-SL-32-116 REV. B), SERVICE LETTER					INFORMATIONAL	
		MOS					
27-MAY-2003			-				
SL 737-SL-32-116 REV. B	CRACKS FOUND ON MAIN LANDING GEAR SYSTEM SUPPORT TRAYS (SUPERSEDED BY SL 737-SL-32-116 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-116 REV. C	CRACKS FOUND ON MAIN LANDING GEAR SYSTEM SUPPORT TRAYS, SERVICE LETTER					RECOMMENDED	
		MOS					
08-JUN-2012			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-119	MAIN GEAR ACTUATOR INTERNAL LEAKAGE CHECK, SERVICE LETTER					RECOMMENDED	
		MOS					
03-FEB-2003							
		AFL	3000 (s)				
SL 737-SL-32-119 REV. A	MAIN GEAR ACTUATOR INTERNAL LEAKAGE CHECK, SERVICE LETTER					INFORMATIONAL	
		MOS				RECURRING	
21-JAN-2004			A/R				
SL 737-SL-32-119 REV. B	MAIN GEAR ACTUATOR INTERNAL LEAKAGE CHECK, SERVICE LETTER						
		MOS					
27-OCT-2005			-				
SL 737-SL-32-119 REV. D	MAIN GEAR ACTUATOR INTERNAL LEAKAGE CHECK, SERVICE LETTER					RECOMMENDED	
		MOS					
13-OCT-2010			-				
SL 737-SL-32-121	LANDING GEAR CONTROL LEVER IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-APR-2003			-				
SL 737-SL-32-121 REV. A	LANDING GEAR CONTROL LEVER IMPROVEMENTS, SERVICE LETTER						
		MOS					
06-OCT-2005			-				
SL 737-SL-32-121 REV. B	LANDING GEAR CONTROL LEVER IMPROVEMENTS (SUPERSEDED BY SL 737-SL-32-121 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-121 REV. C	LANDING GEAR CONTROL LEVER IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
04-OCT-2011			-				
SL 737-SL-32-122 REV. A	LANDING GEAR WHEEL INSTALLATION, SPACER AND RETENTION WASHER, SERVICE LETTER						
		MOS					
04-MAY-2006			-				
SL 737-SL-32-123	MAIN LANDING GEAR UPLOCK SPRING FRACTURES, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-DEC-2003			-				
SL 737-SL-32-124	IMPROVED STEERING METERING VALVE FOR NOSE LANDING GEAR, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-MAR-2004			-				

© Camp Systems

EFTA00618598

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-125	MLG OUTER CYLINDER RETRACT ACTUATOR AND WALKING BEAM ATTACH LUG BUSHING MIGRATION AND FILLET SEAL CRACKS, SERVICE LETTER						
		MOS					
27-APR-2006			-				
SL 737-SL-32-126	NOSE LANDING GEAR FLEXIBLE CONDUIT P/N 287A6212-25 REPLACEMENT, SERVICE LETTER						
		MOS					
03-FEB-2005			-				
SL 737-SL-32-128	TIRE RETREADING RECOMMENDATIONS, SERVICE LETTER						
		MOS					
16-MAY-2005			-				
SL 737-SL-32-129	NOSE GEAR LOCK VALVE MANIFOLD DUPLICATE SERIAL NUMBERS, SERVICE LETTER						NOT APPLICABLE
		MOS					
30-AUG-2005			-				
SL 737-SL-32-130	MAIN LANDING GEAR UPLOCK PINS MAY NOT HAVE BEEN PROPERLY PREPARED PRIOR TO CHROME PLATE APPLICATION, SERVICE LETTER						
		MOS					
09-DEC-2005			-				
SL 737-SL-32-130 REV. A	MAIN LANDING GEAR UPLOCK PINS MAY NOT HAVE BEEN PROPERLY PREPARED PRIOR TO CHROME PLATE APPLICATION, SERVICE LETTER						
		MOS					
21-MAR-2006			-				
SL 737-SL-32-131	MAIN LANDING GEAR ACTUATOR - LOOSE LOCKNUT & BROKEN SAFETY WIRE, SERVICE LETTER						
		MOS					
06-OCT-2005			-				
SL 737-SL-32-131 REV. A	MAIN LANDING GEAR RETRACT ACTUATOR - LOOSE LOCKNUT & BROKEN SAFETY WIRE, SERVICE LETTER						
		MOS					
19-APR-2006			-				
SL 737-SL-32-131 REV. B	MAIN LANDING GEAR RETRACT ACTUATOR - LOOSE LOCKNUT & BROKEN SAFETY WIRE, SERVICE LETTER					RECOMMENDED	
		MOS					
26-MAY-2009			-				
SL 737-SL-32-132	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) UPGRADE OF P/N 285A1600-4 T0 MOD A, SERVICE LETTER						
		MOS					
09-NOV-2005			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-133	LANDING GEAR CONTROL CABLE HIGH TENSION, SERVICE LETTER						
		MOS					
30-MAR-2006			-				
SL 737-SL-32-134	NLG SHOCK STRUT ALTERNATE DYNAMIC SEAL, SERVICE LETTER						
		MOS					
03-APR-2006			-				
SL 737-SL-32-134 REV. B	NLG SHOCK STRUT ALTERNATE DYNAMIC SEAL, SERVICE LETTER						
		MOS					
11-AUG-2008			-				
SL 737-SL-32-135	SHIMMY DAMPER MOUNTING BOLTS - GRIP LENGTH, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-APR-2006			-				
SL 737-SL-32-135 REV. A	SHIMMY DAMPER MOUNTING BOLTS - GRIP LENGTH (SUPERSEDED BY SL 737-SL-32-135 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-135 REV. B	SHIMMY DAMPER MOUNTING BOLTS - GRIP LENGTH, SERVICE LETTER					RECOMMENDED	
		MOS					
08-SEP-2011			-				
SL 737-SL-32-137	STEERING METERING VALVE TOW LEVER STUCK IN TOW POSITION, SERVICE LETTER						
		MOS					
14-JUN-2006			-				
SL 737-SL-32-137 REV. A	STEERING METERING VALVE TOW LEVER STUCK IN TOW POSITION, SERVICE LETTER						
		MOS					
30-OCT-2006							
		AFL	50 (s)				
SL 737-SL-32-138	SUGGESTED SHOP MAINTENANCE PROCEDURES FOR WHEEL AND TIRE ASSEMBLIES (SUPERSEDED BY SL 737-SL-32-138 REV. A), SERVICE LETTER						
		MOS					
10-JUL-2006			-				
SL 737-SL-32-138 REV. A	SUGGESTED SHOP MAINTENANCE PROCEDURES FOR WHEEL AND TIRE ASSEMBLIES (SUPERSEDED BY SL 737-SL-32-138 REV. B), SERVICE LETTER						
		MOS					
06-DEC-2006			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-138 REV. B	SUGGESTED SHOP MAINTENANCE PROCEDURES FOR WHEEL AND TIRE ASSEMBLIES, SERVICE LETTER					RECOMMENDED	
		MOS					
29-APR-2013			-				
SL 737-SL-32-140	BRAKE METERING VALVE STATIC SEAL LEAKAGE, SERVICE LETTER						
		MOS					
05-OCT-2006			-				
SL 737-SL-32-141	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) P/N 285A1600-5, SERVICE LETTER						
		MOS					
17-NOV-2006			-				
SL 737-SL-32-141 REV. A	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU)P/N 285A1600-5, SERVICE LETTER					INFORMATIONAL	
		MOS					
23-MAR-2010			-				
SL 737-SL-32-143	FATALITY OF A MAINTENANCE WORKER DUE TO WHEEL/TIRE OVERPRESSURIZATION, SERVICE LETTER						
		MOS					
09-JUL-2007			-				
SL 737-SL-32-143 REV. A	FATALITY OF A MAINTENANCE WORKER DUE TO WHEEL/TIRE OVERPRESSURIZATION, SERVICE LETTER					RECOMMENDED	
		MOS					
01-MAY-2009			-				
SL 737-SL-32-144 REV. A	LANDING GEAR LIFE LIMITED PART RECORDKEEPING REQUIREMENTS, SERVICE LETTER						
		MOS					
19-FEB-2008			-				
SL 737-SL-32-145	NOSE LANDING GEAR VIBRATION, SERVICE LETTER						
		MOS					
17-JUL-2007			-				
SL 737-SL-32-145 REV. A	NOSE LANDING GEAR VIBRATION (SUPERSEDED BY SL 737-SL-32-145 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-145 REV. B	NOSE LANDING GEAR VIBRATION (SUPERSEDED BY SL 737-SL-32-145 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-145 REV. C	NOSE LANDING GEAR VIBRATION, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JUL-2012			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-146	NOSE WHEEL STEERING INTERCONNECT MECHANISM - LOOSE NUT FOUND, SERVICE LETTER	MOS					
28-AUG-2007			-				
SL 737-SL-32-147	CLARIFICATION CONCERNING MOBIL AVIATION WHEEL BEARING GREASE NAMES, SERVICE LETTER	MOS					
26-SEP-2007			-				
SL 737-SL-32-149	POSSIBLE CAUSES OF LANDING GEAR WHEEL LOSSES AND WHEEL BEARING FAILURES (SUPERSEDED BY SL 737-SL-32-149 REV. A), SERVICE LETTER	MOS				SUPERSEDED	
			-				
SL 737-SL-32-149 REV. A	POSSIBLE CAUSES OF LANDING GEAR WHEEL LOSSES AND WHEEL BEARING FAILURES, SERVICE LETTER	MOS				RECOMMENDED	
12-SEP-2013			-				
SL 737-SL-32-150	NLG INNER CYLINDER AXLE INSPECTIONS, SERVICE LETTER	MOS					
27-NOV-2007			-				
SL 737-SL-32-150 REV. A	NLG INNER CYLINDER AXLE INSPECTIONS, SERVICE LETTER	MOS					
28-FEB-2008			-				
SL 737-SL-32-150 REV. B	NLG INNER CYLINDER AXLE INSPECTIONS, SERVICE LETTER	MOS					
25-JUL-2008			-				
SL 737-SL-32-151	NOSE LANDING GEAR MANUAL EXTENSION SPRING, SERVICE LETTER	MOS					
08-FEB-2008			-				
SL 737-SL-32-152	IMPROVED NOSE LANDING GEAR ACTUATOR ROD ATTACH CLAMP-UP BUSHING, SERVICE LETTER	MOS					
30-APR-2008			-				
SL 737-SL-32-152 REV. A	IMPROVED NOSE LANDING GEAR ACTUATOR ROD ATTACH CLAMP-UP BUSHING, SERVICE LETTER	MOS				RECOMMENDED	
21-AUG-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-152 REV. B	IMPROVED NOSE LANDING GEAR ACTUATOR ROD ATTACH CLAMP-UP BUSHING, SERVICE LETTER					RECOMMENDED	
		MOS					
03-MAR-2010			-				
SL 737-SL-32-153	ANTISKID VALVE CONNECTOR MISSING POTTING, SERVICE LETTER						
		MOS					
04-APR-2008			-				
SL 737-SL-32-154 REV. A	MAIN LANDING GEAR ACTUATOR BARREL CRACKS FOLLOWING REPAIR PER SERVICE BULLETIN, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-32-154 REV. B	MAIN LANDING GEAR ACTUATOR BARREL CRACKS FOLLOWING REPAIR PER SERVICE BULLETIN, SERVICE LETTER					RECOMMENDED	
		MOS					
04-AUG-2009			-				
SL 737-SL-32-154 REV. C	MAIN LANDING GEAR ACTUATOR BARREL CRACKS FOLLOWING REPAIR PER SERVICE BULLETIN, SERVICE LETTER					RECOMMENDED	
		DAYS	7 (s)				
02-OCT-2009							
SL 737-SL-32-156	EFFECTS OF ALKALI METAL (ORGANIC SALT) RUNWAY DEICERS ON CARBON BRAKES, SERVICE LETTER						
		MOS					
26-JAN-2009			-				
SL 737-SL-32-157	BRAKE METERING VALVE SHAFT SEAL LEAKAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
05-FEB-2009			-				
SL 737-SL-32-157 REV. A	BRAKE METERING VALVE SHAFT SEAL LEAKAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JUN-2009			-				
SL 737-SL-32-157 REV. B	BRAKE METERING VALVE SHAFT SEAL LEAKAGE, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-MAR-2010			-				
SL 737-SL-32-158	INCORRECT PART NUMBER ON NOSE GEAR DOWN LINE HYDRAULIC FUSE, SERVICE LETTER					RECOMMENDED	
		MOS					
31-MAR-2009			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-32-159	MESSIER-BUGATTI MAIN GEAR WHEEL - SPECIAL INSPECTIONS (SUPERSEDED BY SL 737-SL-32-159 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-159 REV. A	MESSIER-BUGATTI MAIN GEAR WHEEL - SPECIAL INSPECTIONS (SUPERSEDED BY SL 737-SL-32-159 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-159 REV. B	MESSIER-BUGATTI MAIN GEAR WHEEL - SPECIAL INSPECTIONS, SERVICE LETTER					RECOMMENDED	
			MOS					
	22-FEB-2011			-				
SL	737-SL-32-160	MAIN LANDING GEAR SIDE STRUT APEX PIN FINISH CHANGES, SERVICE LETTER					RECOMMENDED	
			MOS					
	02-JUL-2009			-				
SL	737-SL-32-161	RIDING CONDITION FOUND ON BRAKE PEDAL BUS, SERVICE LETTER					RECOMMENDED	
			MOS					
	26-AUG-2009			-				
SL	737-SL-32-162	INBOARD HUB FRACTURES ON HONEYWELL MAIN GEAR WHEELS, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-AUG-2009			-				
SL	737-SL-32-162 REV. A	INBOARD HUB FRACTURES ON HONEYWELL MAIN GEAR WHEELS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	04-MAY-2010			-				
SL	737-SL-32-163	LANDING GEAR LEVER DOES NOT DROP INTO "OFF" DETENT, SERVICE LETTER					RECOMMENDED	
			MOS					
	02-OCT-2009			-				
SL	737-SL-32-164	LANDING GEAR ALTERNATE EXTENSION SYSTEM SWITCH DAMAGED (SUPERSEDED BY 737-SL-32-164-A), SERVICE LETTER					SUPERSEDED	
			MOS					
	12-OCT-2009			-				
SL	737-SL-32-164 REV. A	LANDING GEAR ALTERNATE EXTENSION SYSTEM SWITCH DAMAGE, SERVICE LETTER						
			MOS					
	07-JUN-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-165	737NG LANDING GEAR RESTORATION REQUIREMENTS (SUPERSEDED BY SL 737-SL-32-165 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-165 REV. A	737NG LANDING GEAR RESTORATION REQUIREMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
15-JUL-2010			-				
SL 737-SL-32-166	INSTALLATION/REMOVAL OF THE MAIN LANDING GEAR, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-MAR-2010			-				
SL 737-SL-32-167	INSTALLATION OF TITANIUM PROXIMITY SENSOR P/N 80-207-01 ON WING LEADING EDGE AND LANDING GEAR (SUPERSEDED BY SL 737-SL-32-167 REV. A), SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-2010			-				
SL 737-SL-32-167 REV. A	INSTALLATION OF TITANIUM PROXIMITY SENSOR P/N 80-207-01 ON WING LEADING EDGE AND LANDING GEAR, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-APR-2013			-				
SL 737-SL-32-168	POTENTIALLY INCORRECT MAIN LANDING GEAR AXLE INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
16-JUL-2010			-				
SL 737-SL-32-169	POTENTIALLY INCORRECT MAIN LANDING GEAR LOWER TORSION LINK INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
15-JUL-2010			-				
SL 737-SL-32-170	LANDING GEAR CONTROL CABLE LOW TENSION, SERVICE LETTER					RECOMMENDED	
		MOS					
15-JUL-2010			-				
SL 737-SL-32-171	NOSE LANDING GEAR AXLE INSPECTIONS DUE TO POSSIBLE CHROME GRINDING DAMAGE DURING PRODUCTION (SUPERSEDED BY SL 737-SL-32-171 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-171 REV. A	NOSE LANDING GEAR AXLE INSPECTIONS DUE TO POSSIBLE CHROME GRINDING DAMAGE DURING PRODUCTION, SERVICE LETTER					RECOMMENDED	
		MOS					
07-APR-2014			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-32-172	LANDING GEAR BEARING CARRIER REFINISH OPTION, SERVICE LETTER					RECOMMENDED	
			MOS					
	25-MAY-2011			-				
SL	737-SL-32-173	MAIN LANDING GEAR UPLOCK SPRING FRACTURES (SUPERSEDED BY SL 737-SL-32-173 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
	09-FEB-2011			-				
SL	737-SL-32-173 REV. A	MAIN LANDING GEAR UPLOCK SPRING FRACTURES (SUPERSEDED BY SL 737-SL-32-173 REV. B) , SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-173 REV. B	MAIN LANDING GEAR UPLOCK SPRING FRACTURES, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-JUL-2011			-				
SL	737-SL-32-174	LANDING GEAR SHOCK STRUT DYNAMIC SEAL INSTALLATION TOOLING, SERVICE LETTER					RECOMMENDED	
			MOS					
	03-FEB-2011			-				
SL	737-SL-32-175	LANDING GEAR LOWER BEARING CARRIER REFINISH OPTION, SERVICE LETTER					RECOMMENDED	
			MOS					
	25-MAY-2011			-				
SL	737-SL-32-176	POTENTIALLY INCORRECT MAIN LANDING GEAR UPPER TORSION LINK PIN INSTALLATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-MAY-2011			-				
SL	737-SL-32-178	DIGITAL LANDING GEAR SHOCK STRUT AND TIRE PRESSURE GAUGE (SUPERSEDED BY SL 737-SL-32-178 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-178 REV. A	DIGITAL LANDING GEAR SHOCK STRUT AND TIRE PRESSURE GAUGE, SERVICE LETTER					RECOMMENDED	
			MOS					
	17-OCT-2012			-				
SL	737-SL-32-179	HYDRAULIC LINE RIDING W8224 WIRE BUNDLE 9SUPERSEDED BY SL 737-SL-32-179 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-179 REV. A	HYDRAULIC LINE RIDING W8224 WIRE BUNDLE (SUPERSEDED BY SL 737-SL-32-179 REV. B), SERVICE LETTER					RECOMMENDED	
			MOS					
	14-FEB-2012			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-179 REV. B	HYDRAULIC LINE RIDING W8224 WIRE BUNDLE, SERVICE LETTER					RECOMMENDED	
		MOS					
27-APR-2012			-				
SL 737-SL-32-180	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) P/N 285A1600-6 (SUPERSEDED BY SL 737-SL-32-180 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-180 REV. A	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) P/N 285A1600-6 (SUPERSEDED BY SL 737-SL-32-180 REV. B), SERVICE LETTER					RECOMMENDED	
		MOS					
18-SEP-2012			-				
SL 737-SL-32-180 REV. B	PROXIMITY SWITCH ELECTRONIC UNIT (PSEU) P/N 285A1600-6, SERVICE LETTER					RECOMMENDED	
		MOS					
02-APR-2013			-				
SL 737-SL-32-181	"737NG NOSE LANDING GEAR NON-CONFORMING STEERING SYSTEM STRUCTURAL COMPONENTS" (SUPERSEDED BY SL 737-SL-32-181 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-181 REV. A	737NG NOSE LANDING GEAR NON-CONFORMING STEERING SYSTEM STRUCTURAL COMPONENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
03-OCT-2012			-				
SL 737-SL-32-182	COLD SPRAY REPAIR OF P/N 287A6115 MLG WIRE BUNDLE SUPPORT BRACKET, SERVICE LETTER					RECOMMENDED	
		MOS					
21-JUN-2012			-				
SL 737-SL-32-183	THERMAL SPRAY REPAIR OF TITANIUM LANDING GEAR BEARING CARRIERS, SERVICE LETTER					RECOMMENDED	
		MOS					
26-APR-2012			-				
SL 737-SL-32-184	REPAIR OF TITANIUM LANDING GEAR BEARING CARRIERS USING THE LASER DEPOSITION PROCESS, SERVICE LETTER					RECOMMENDED	
		MOS					
11-MAY-2012			-				
SL 737-SL-32-185	WIRE BUNDLE W8224 - POSSIBLE MISSING CLAMP IN MAIN GEAR WHEEL WELL, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUN-2012			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-32-186	MLG OUTER CYLINDER TRUNNIONS LUBRICATION SERVICING AND REMOVED DECALS, SERVICE LETTER					RECOMMENDED	
			MOS					
	03-OCT-2012			-				
SL	737-SL-32-187	MAIN LANDING GEAR OUTBOARD DOWNLOCK SPRING PIN, SERVICE LETTER					RECOMMENDED	
			MOS					
	26-OCT-2012			-				
SL	737-SL-32-188	SHIMMY DAMPER COMPENSATOR MOUNTING BOLTS (SUPERSEDED BY SL 737-SL-32-188 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
	22-JUL-2013			-				
SL	737-SL-32-188 REV. A	SHIMMY DAMPER COMPENSATOR MOUNTING BOLTS (SUPERSEDED BY SL 737-SL-32-188 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-188 REV. B	SHIMMY DAMPER COMPENSATOR MOUNTING BOLTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	09-MAY-2014			-				
SL	737-SL-32-189	NOSE WHEEL STEERING CABLE - POTENTIAL CHAFING CONDITION WITH A WIRE BUNDLE, SERVICE LETTER					RECOMMENDED	
			MOS					
	08-FEB-2013			-				
SL	737-SL-32-190	ANTISKID/AUTOBRAKE CONTROL UNIT (AACU) - REPLACEMENT OF UNAUTHORIZED TRANSISTORS, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-FEB-2013			-				
SL	737-SL-32-191	MLG SHOCK STRUT ALTERNATE DYNAMIC SEAL, SERVICE LETTER					RECOMMENDED	
			MOS					
	16-APR-2013			-				
SL	737-SL-32-192	BRAKE CONTROL CABLE TENSION CHECK (SUPERSEDED BY SL 737-SL-32-192 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-32-192 REV. A	BRAKE CONTROL CABLE TENSION CHECK, SERVICE LETTER					RECOMMENDED	
			MOS					
	07-FEB-2014			-				
SL	737-SL-32-193	NLG ALTERNATE EXTENSION MECHANISM BINDING, SERVICE LETTER					RECOMMENDED	
			MOS					
	12-JUN-2013			-				

© Camp Systems

EFTA00618608

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-32-194	LANDING GEAR LIFE LIMITED PARTS IN THE AIRCRAFT READINESS LOG (SUPERSEDED BY SL 737-SL-32-194 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-194 REV. A	LANDING GEAR LIFE LIMITED PARTS IN THE AIRCRAFT READINESS LOG (REPLACED BY SL 737-SL-00-026), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-32-195	USE OF SMARTSTEM TIRE PRESSURE SENSOR ON DELIVERED AIRPLANES, SERVICE LETTER					RECOMMENDED	
		MOS					
10-OCT-2013			-				
SL 737-SL-32-196	PROXIMITY SENSOR MAINTENANCE/REMOVAL BEST PRACTICES AND SUPPLIER RELIABILITY IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
31-MAR-2014			-				
SL 737-SL-33-029	PRESS-TO-TEST ANNUNCIATORSDISCREPANT PRINTED CIRCUIT ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
01-APR-1999			- (s)				
SL 737-SL-33-029 REV. A	PRESS-TO-TEST ANNUNCIATORSDISCREPANT PRINTED CIRCUIT ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
14-MAY-2001			- (s)				
SL 737-SL-33-030	FLORESCENT LIGHT LAMP DAMPENERS, SERVICE LETTER					RECOMMENDED	
		MOS					
12-JUL-1999			- (s)				
SL 737-SL-33-032 REV. A	FORWARD POSITION LIGHT LENS CRACKING - INTERIM CORRECTION ACTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-JAN-2000			- (s)				
SL 737-SL-33-033	LIGHTED PUSHBUTTON SWITCHES AND ANUNCIATORS - KORRY - EMITTING DIODE (LED) REPLACEMENTS FOR INCANDESCENT LIGHTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-OCT-1999			- (s)				
SL 737-SL-33-034	RETRACTABLE LANDING LIGHT (RLL) DRAIN HOLE., SERVICE LETTER					RECOMMENDED	
		MOS					
16-JUL-2001			- (s)				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-33-035	EMERGENCY LIGHTING BATTERY PACK SCHEDULED MAINTENANCE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	17-JUL-2001			- (s)				
SL	737-SL-33-037	RETRACTABLE LANDING LIGHT (RLL) WIRE HARNESS REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
			MOS					
	05-NOV-2001			- (s)				
SL	737-SL-33-038	RETRACTABLE LANDING LIGHT (RLL) CURVED LENS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	05-NOV-2001			- (s)				
SL	737-SL-33-039	BOEING PHOTOLUMINESCENT EMERGENCY FLOOR PROXIMITY LIGHTING SYSTEMS OPERATIONL PROCEDURES, SERVICE LETTER						
			MOS					
	31-JAN-2002			- (s)				
SL	737-SL-33-041	WIRE CRIMP TOOL OUT OF CALIBRATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	23-JUL-2003			-				
SL	737-SL-33-041 REV. A	WIRE CRIMP TOOL OUT OF CALIBRATION, SERVICE LETTER					INFORMATIONAL	
			MOS					
	23-JUL-2003			- (s)				
SL	737-SL-33-042	SIDEWALL LIGHTING COMPONENTS-CASE GROUNDING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-OCT-2002			-				
SL	737-SL-33-042 REV. A	SIDEWALL LIGHTING COMPONENTS-CASE GROUNDING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	04-AUG-2003			-				
SL	737-SL-33-043	KORRY LIGHTED PUSHBUTTON SWITCHES-NEW PART NUMBER WITH "CONFIGURATION D" MASTER MODULE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	27-MAR-2003			-				
SL	737-SL-33-044	BALLAST DAMAGE DUE TO AIRCRAFT VOLTAGE SPIKES, SERVICE LETTER					INFORMATIONAL	
			MOS					
	17-NOV-2003			-				
SL	737-SL-33-045	AUXILIARY DIM AND TEST MODULE-DIODE OVERHEAT, SERVICE LETTER					INFORMATIONAL	
			MOS					
	11-MAY-2004			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-33-046	OVERWING EMERGENCY LIGHT - DECAL MISSING, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-OCT-2004			-				
SL 737-SL-33-047	RETRACTABLE LANDING LIGHT (RLL) - MOTOR CONNECTOR TIGHTENING, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-SEP-2005			-				
SL 737-SL-33-048	RETRACTABLE LANDING LIGHT (RLL) IMPROVEMENTS, SERVICE LETTER						
		MOS					
14-SEP-2006			-				
SL 737-SL-33-048 REV. A	RETRACTABLE LANDING LIGHT (RLL) IMPROVEMENTS, SERVICE LETTER						
		MOS					
22-MAR-2007			-				
SL 737-SL-33-049	ANTI-COLLISION LIGHT POWER SUPPLY BRACKET - FILLET SEAL APPLICATION (SUPERSEDED BY SL 737-SL-33-049 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
11-MAY-2007			-				
SL 737-SL-33-049 REV. A	ANTI-COLLISION LIGHT POWER SUPPLY BRACKET - FILLET SEAL APPLICATION , SERVICE LETTER					RECOMMENDED	
		MOS					
06-MAY-2011			-				
SL 737-SL-33-050	SEALING OF TAILCONE AND ANTI-COLLISION LIGHT INTERFACES, SERVICE LETTER						COMPLIED WITH
		MOS		22-AUG-2008			
17-AUG-2007			-	3260:48			
		AFL		782			
SL 737-SL-33-051	NEW CHART LIGHT BRACKET ASSEMBLY, SERVICE LETTER						
		MOS					
28-AUG-2007			-				
SL 737-SL-33-052	REFUELING PANEL FLOODLIGHT INSTALLATION, SERVICE LETTER						
		MOS					
30-OCT-2007			-				
SL 737-SL-33-052 REV. A	REFUELING PANEL FLOODLIGHT INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-MAR-2010			-				

© Camp Systems

EFTA00618611

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-33-053	ANTI-COLLISION LIGHT POWER SUPPLY & BRACKET- FAYING SEAL APPLICATION, SERVICE LETTER						
			MOS					
	20-OCT-2008			-				
SL	737-SL-33-053 REV. A	ANTI-COLLISION LIGHT POWER SUPPLY & BRACKET- FAYING SEAL APPLICATION, SERVICE LETTER						
			MOS					
	11-DEC-2008			-				
SL	737-SL-33-053 REV. B	ANTI-COLLISION LIGHT POWER SUPPLY & BRACKET- FAYING SEAL APPLICATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	01-MAY-2009			-				
SL	737-SL-33-053 REV. C	ANTI-COLLISION LIGHT POWER SUPPLY & BRACKET- FAYING SEAL APPLICATION, SERVICE LETTER					RECOMMENDED	
			MOS					
	26-JUN-2009			-				
SL	737-SL-33-055	RETRACTABLE LANDING LIGHT CONNECTORS BURNED, SERVICE LETTER					RECOMMENDED	
			MOS					
	17-SEP-2010			-				
SL	737-SL-33-056	RETRACTABLE LANDING LIGHT IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	31-AUG-2011			-				
SL	737-SL-33-057	LOWER ANTI-COLLISION LIGHT - SEALANT POSSIBLY OMITTED BETWEEN SKIN PANELS, SERVICE LETTER					RECOMMENDED	
			MOS					
	04-SEP-2013			-				
SL	737-SL-33-058	POSSIBLE WIRE RIDING CONDITION IN EMERGENCY WING LIGHTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-MAY-2012			-				
SL	737-SL-33-059	WINGLET FORWARD POSITION LIGHT LENS REPLACEMENT GUIDELINES (SUPERSEDED BY SL 737-SL-33-059 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-33-059 REV. A	WINGLET FORWARD POSITION LIGHT LENS REPLACEMENT GUIDELINES, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-MAY-2012			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-33-060	R427 SIDEWALL LIGHT RELAY IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
24-AUG-2012			-				
SL 737-SL-33-061	CONFIGURATION DATABASE TOOL - CHANGING AVAILABLE SCENES ON THE BOEING SKY INTERIOR (BSI) LIGHTING SYSTEM (SUPERSEDED BY SL 737-SL-33-061 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-33-061 REV. A	CONFIGURATION DATABASE TOOL - CHANGING AVAILABLE SCENES ON THE BOEING SKY INTERIOR (BSI) LIGHTING SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
12-NOV-2012			-				
SL 737-SL-33-062	IMPROVED WIRE ATTACHMENT FOR BSI CENTER OVERHEAD STOWAGE (COS) AREA EMERGENCY LIGHTING, SERVICE LETTER					RECOMMENDED	
		MOS					
12-DEC-2012			-				
SL 737-SL-33-063	FAIRED ANTICOLLISION LENS - SEALANT BLOCKING SKIN PANEL DRAIN HOLE, SERVICE LETTER					RECOMMENDED	
		MOS					
29-APR-2013			-				
SL 737-SL-33-064	LOWER ANTI-COLLISION LIGHT CABLE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
22-MAY-2013			-				
SL 737-SL-33-065	WINGLET LED (LIGHT EMITTING DIODE) POSITION LIGHTS AND ANTI-COLLISION LIGHTS, SERVICE LETTER					RECOMMENDED	
		MOS					
27-JAN-2014			-				
SL 737-SL-33-066	BOEING SKY INTERIOR (BSI) LED LIGHTING IMPROVEMENTS (REFERRED TO AS GENERATION 2 LED LIGHTS), SERVICE LETTER					RECOMMENDED	
		MOS					
25-OCT-2013			-				
SL 737-SL-33-067	MEMORY DEVICE DESIGN IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
20-FEB-2014			-				
SL 737-SL-33-068	EMERGENCY LIGHTS WIRE BUNDLE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
28-JAN-2014			-				

© Camp Systems

EFTA00618613

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-33-069	BOEING SKY INTERIOR LIGHTING - DARK SHADOW EFFECT, SERVICE LETTER					RECOMMENDED	
		MOS					
27-MAR-2014			-				
SL 737-SL-33-070	EMERGENCY LIGHTING - WIRE W3142-0522-20 POSSIBLE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
25-MAR-2014			-				
SL 737-SL-33-071	WINGLET ANTICOLLISION LIGHT STEP DOWN CONVERTER BOX - R11 AND INDUCTOR IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
25-APR-2014			-				
SL 737-SL-34-131	DATA LOADER INCOMPATIBILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAR-1997			- (s)				
SL 737-SL-34-131 REV. A	DATA LOADER INCOMPATIBILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
08-SEP-1998			- (s)				
SL 737-SL-34-140	AIR DATA INERTIAL REFERENCE UNIT (ADIRU) UPDATE, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAR-1998			- (s)				
SL 737-SL-34-140 REV. A	AIR DATA INERTIAL REFERENCE UNIT (ADIRU) UPDATE, SERVICE LETTER					RECOMMENDED	
		MOS					
25-SEP-1998			- (s)				
SL 737-SL-34-143	FLIGHT MANAGEMENT COMPUTER 0 UPDATE 10.1 AND 10.2, SERVICE LETTER					RECOMMENDED	
		MOS					
13-NOV-1998			- (s)				
SL 737-SL-34-144	INTRODUCTION OF ENHANCED GROUND PROXIMITY WARNING SYSTEM AND PREDICTIVE WINDSHEAR SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
15-DEC-1998			- (s)				
SL 737-SL-34-144 REV. A	INTRODUCTION OF ENHANCED GROUND PROXIMITY WARNING SYSTEM AND PREDICTIVE WINDSHEAR SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
19-MAY-1999			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-145	FLIGHT MANAGEMENT COMPUTER UPDATE 10.2A, SERVICE LETTER					RECOMMENDED	
		MOS					
18-DEC-1998			- (s)				
SL 737-SL-34-146	GABLES VHF NAV CONTROL PANEL UPGRADE, SERVICE LETTER					RECOMMENDED	
		MOS					
30-APR-1999			- (s)				
SL 737-SL-34-147	ROCKWELL COLLINS WEATHER RADAR TRANSCEIVER UPGRADE, SERVICE LETTER					RECOMMENDED	
		MOS					
25-MAY-1999			- (s)				
SL 737-SL-34-150	ALLIEDSIGNAL WEATHER RADAR TRANSCEIVER UPGRADE, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-OCT-1999			- (s)				
SL 737-SL-34-152	AIRSPEED SPLITS DURING TAKEOFF ROLL CAUSED BY STICKING ANGLE OF ATTACK SENSOR, SERVICE LETTER					RECOMMENDED	
		MOS					
19-MAY-2000			- (s)				
SL 737-SL-34-152 REV. A	AIRSPEED SPLITS DURING TAKEOFF ROLL CAUSED BY STICKING ANGLE OF ATTACK SENSOR, SERVICE LETTER					RECOMMENDED	
		MOS					
09-DEC-2000			- (s)				
SL 737-SL-34-152 REV. B	AIRSPEED SPLITS DURING TAKEOFF ROLL CAUSED BY STICKING ANGLE OF ATTACK SENSOR, SERVICE LETTER					RECOMMENDED	
		MOS					
30-APR-2001			- (s)				
SL 737-SL-34-152 REV. C	AIRSPEED SPLITS DURING TAKEOFF ROLL CAUSED BY STICKING ANGLE OF ATTACK SENSOR, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUN-2001			- (s)				
SL 737-SL-34-152 REV. D	AIRSPEED SPLITS DURING TAKEOFF ROLL CAUSED BY STICKING ANGLE OF ATTACK SENSOR, SERVICE LETTER					INFORMATIONAL	
		DAYS	180 (s)				
06-OCT-2003							
SL 737-SL-34-153 REV. A	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.3, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-AUG-2000			- (s)				
SL 737-SL-34-154	AIR DATA INTERIAL REFERENCE UNIT (ADIRU) UPDATE TO PART NUMBER S242A101-004, SERVICE LETTER					RECOMMENDED	
		MOS					
10-NOV-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-154 REV. A	AIR DATA INERTIAL REFERENCE UNIT (ADIRU) UPDATE TO PART NUMBER S242A101-004, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-NOV-2003			-				
SL 737-SL-34-155	MISSING "2500 FEET" ALTITUDE CALLOUT DUE TO SUDDEN ANOMALOUS DROP IN RADIO ALTITUDE, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-AUG-2000			- (s)				
SL 737-SL-34-156	ENHANCED GROUND PROXIMITY WARNING SYSTEM TERRAIN ALERTS AREA DISPLAY SHIFT, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-AUG-2000			- (s)				
SL 737-SL-34-159	MARKER BEACON ANTENNA ENHANCEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
02-MAR-2001			- (s)				
SL 737-SL-34-160	AIR DATA INTERIAL REFERENCE UNIT (ADIRU) UPDATE TO PART NUMBER S242A101-005, SERVICE LETTER					RECOMMENDED	
		MOS					
01-JUN-2001			- (s)				
SL 737-SL-34-161	P/N S242A101-006 AIR DATA INERTIAL REFERENCE UNIT (ADIRU), SERVICE LETTER					INFORMATIONAL	
		MOS					
27-AUG-2001			- (s)				
SL 737-SL-34-161 REV. B	P/N S242A101-006 AIR DATA INERTIAL REFERENCE UNIT (ADIRU), SERVICE LETTER					INFORMATIONAL	
		MOS					
18-APR-2002			- (s)				
SL 737-SL-34-161 REV. C	P/N S242A101-006 AIR DATA INERTIAL REFERENCE UNIT (ADIRU), SERVICE LETTER					INFORMATIONAL	
		MOS					
21-FEB-2003			-				
SL 737-SL-34-162	FLIGHT MANAGEMENT COMPUTER - 4 MODULAR CONCEPT UNIT P/N 10-62225-004, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-SEP-2001			- (s)				
SL 737-SL-34-163	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.4, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-SEP-2001			- (s)				
SL 737-SL-34-164	ACTIVATION OF "PEAKS" AND "OBSTACLES" IN HONEYWELL'S ENHANCED GROUND PROXIMITY WARNING COMPUTER (EGWPS), SERVICE LETTER					INFORMATIONAL	
		MOS					
26-MAR-2002			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-165	ANGLE OF ATTACK INSTALLATION CALIBRATION PROCEDURES, SERVICE LETTER						
15-FEB-2002		MOS	- (s)				
SL 737-SL-34-166	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.4A, SERVICE LETTER					INFORMATIONAL	
17-MAY-2002		MOS	- (s)				
SL 737-SL-34-168	ENHANCED GROUND PROXIMITY WARNING COMPUTER UPGRADE, SERVICE LETTER					INFORMATIONAL	
22-OCT-2002		MOS	-				
SL 737-SL-34-169	HONEYWELL TCAS COMPUTER CHANGE-CORRECTION FOR NUISANCE TRAFFIC ADVISORIES ON GROUND TARGETS., SERVICE LETTER					INFORMATIONAL	
14-OCT-2002		MOS	- (s)				
SL 737-SL-34-169 REV. A	HONEYWELL TCAS COMPUTER CHANGE-CORRECTION FOR NUISANCE TRAFFIC ADVISORIES ON GROUND TARGETS, SERVICE LETTER					INFORMATIONAL	
30-OCT-2002		MOS	- (s)				
SL 737-SL-34-169 REV. B	HONEYWELL TCAS COMPUTER CHANGE-CORRECTION FOR NUISANCE TRAFFIC ADVISORIES ON GROUND TARGETS, SERVICE LETTER					INFORMATIONAL	
27-OCT-2003		MOS	-				
SL 737-SL-34-170	REPLACEMENT OF PITOT PROBE, SERVICE LETTER					INFORMATIONAL	
20-FEB-2003		MOS	-				
SL 737-SL-34-170 REV. A	REPLACEMENT OF PITOT PROBE, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
10-APR-2003		MOS	-	11-JAN-2005 1965:18			
		AFL		482			
SL 737-SL-34-171	PITOT STATIC PROBE HOSE FIRE, SERVICE LETTER						
29-MAY-2001		MOS	18 (s)				
SL 737-SL-34-171 REV. A	PITOT STATIC PROBE HOSE FIRE, SERVICE LETTER						
22-JUL-2005		MOS	-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-34-172	FLIGHT MANAGEMENT COMPUTER-UPDATE 10.5, SERVICE LETTER					INFORMATIONAL	
			MOS					
	10-FEB-2003			-				
SL	737-SL-34-174	NEW STANDBY MAGNETIC COMPASS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	02-JUL-2003			-				
SL	737-SL-34-175	AIR TRAFFIC CONTROL (ATC) SYSTEM ELEMENTARY SURVEILLANCE , ENHANCED SURVEILLANCE , AND EXTENDED SQUITTER UPGRADE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	18-DEC-2003			-				
SL	737-SL-34-178	ROCKWELL COLLINS TCAS COMPUTER CHANGE-ELIMINATION POTENTIAL NUISANCE RESOLUTION AND TRAFFIC ADVISORIES ON THE GROUND OR AT LOW ALTITUDE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	19-JUL-2004			-				
SL	737-SL-34-180 REV. A	NEW HONEYWELL MULTI-MODE RECEIVER - P/N 066-50029-1201, SERVICE LETTER					INFORMATIONAL	
			MOS					
	01-FEB-2005			-				
SL	737-SL-34-180 REV. B	NEW HONEYWELL MULTI-MODE RECEIVER - P/N 066-50029-1201, SERVICE LETTER						
			MOS					
	10-MAY-2005			-				
SL	737-SL-34-181	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.6, SERVICE LETTER					INFORMATIONAL	
			MOS					
	09-MAR-2005			-				
SL	737-SL-34-181 REV. A	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.6, SERVICE LETTER						COMPLIED WITH
			MOS			11-MAY-2006		
	13-JUL-2005			-		2619:10		
			AFL			629		
SL	737-SL-34-182	NEW MASTER CAUTION UNIT - P/N 69-37399-13, SERVICE LETTER					INFORMATIONAL	
			MOS					
	10-MAR-2005			-				
SL	737-SL-34-184	AIR TRAFFIC CONTROL ANTENNA CONNECTOR CHANGE - INSTALLATION INSTRUCTIONS, SERVICE LETTER						
			MOS					
	26-APR-2006			-				

© Camp Systems

EFTA00618618

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-185	STANDBY ALTIMETER/AIRSPEED INDICATOR IMPROVEMENTS (WL102AMS SERIES), SERVICE LETTER						
		MOS					
29-AUG-2006			-				
SL 737-SL-34-186	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.7, SERVICE LETTER						
		MOS					
10-APR-2007			-				
SL 737-SL-34-187 REV. A	LOSS OF RELIABLE AIR DATA DUE TO ICING OF STATIC PORTS - SRP 34-0111, SERVICE LETTER						
		MOS					
20-JUL-2007			-				
SL 737-SL-34-188	HONEYWELL WEATHER RADAR TRANSCEIVER MODIFICATION FOR P/N 066-50008-0406 (SUPERSEDED BY SL 737-SL-34-188 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-188 REV. A	HONEYWELL WEATHER RADAR TRANSCEIVER MODIFICATION FOR P/N 066-50008-0406, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUN-2012			-				
SL 737-SL-34-189	HONEYWELL WEATHER RADAR TRANSCEIVER MODIFICATION FOR P/N 066-50008-0408 (SUPERSEDED BY SL 737-SL-34-189 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-189 REV. A	HONEYWELL WEATHER RADAR TRANSCEIVER MODIFICATION FOR P/N 066-50008-0408, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUN-2012			-				
SL 737-SL-34-191	MASTER CAUTION UNIT P/N 69-37399-13 ANOMALY, SERVICE LETTER						
		MOS					
09-JUL-2008			-				
SL 737-SL-34-192	HEAD-UP GUIDANCE SYSTEM - DESIGN ENHANCEMENTS TO ADDRESS DISPLAY SYMBOLOGY JITTER (SUPERSEDED BY SL 737-SL-34-192 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-192 REV. A	HEAD-UP GUIDANCE SYSTEM - DESIGN ENHANCEMENT TO ADDRESS DISPLAY SYMBOLOGY JITTER, SERVICE LETTER					RECOMMENDED	
		MOS					
17-NOV-2010			-				

© Camp Systems

EFTA00618619

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-193	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.8, SERVICE LETTER						
		MOS					
30-JAN-2009			-				
SL 737-SL-34-193 REV. A	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.8, SERVICE LETTER						
		MOS					
18-FEB-2009			-				
SL 737-SL-34-194	AIR DATA INERTIAL REFERENCE SYSTEM (ADIRS) FAULT ISOLATION MANUAL IMPROVEMENTS, SERVICE LETTER						
		MOS					
04-NOV-2008			-				
SL 737-SL-34-195	AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADSB) OUT IMPLEMENTATION AND EUROPEAN AVIATION SAFETY AGENCY (EASA) AMC 20-24 COMPLIANCE, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAR-2009			-				
SL 737-SL-34-195 REV. A	AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADSB) OUT IMPLEMENTATION AND EUROPEAN AVIATION SAFETY AGENCY (EASA) AMC 20-24 COMPLIANCE, SERVICE LETTER					RECOMMENDED	
		MOS					
06-JUL-2009			-				
SL 737-SL-34-195 REV. B	AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT IMPLEMENTATION AND EUROPEAN AVIATION SAFETY AGENCY (EASA) AMC 20-24 COMPLIANCE, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-MAR-2010			-				
SL 737-SL-34-196	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.8A (SUPERSEDED BY SL 737-SL-34-196 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-196 REV. A	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.8A (SUPERSEDED BY SL 737-SL-34-196 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-196 REV. B	FLIGHT MANAGEMENT COMPUTER - UPDATE 10.8A, SERVICE LETTER					RECOMMENDED	
		MOS					
17-JAN-2012			-				
SL 737-SL-34-198	NEW ENHANCED GROUND PROXIMITY WARNING COMPUTER (EGPWC) UPGRADE TO SUPPORT RAAS AND ADD AIRSPEED LOW CALLOUT, SERVICE LETTER					RECOMMENDED	
		MOS					
27-OCT-2010			-				

© Camp Systems

EFTA00618620

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-199	NEW FLIGHT MANAGEMENT COMPUTER DISPLAY UNIT, SERVICE LETTER					RECOMMENDED	
		MOS					
04-NOV-2010			-				
SL 737-SL-34-201	INTEGRATED STANDBY FLIGHT DISPLAY (ISFD) - NEW INSTRUMENT CLAMP, SERVICE LETTER					RECOMMENDED	
		MOS					
06-APR-2011			-				
SL 737-SL-34-202	FLIGHT MANAGEMENT COMPUTER (FMC) DISPLAY UNIT ? AVAILABILITY OF AN ALTERNATE KEYBOARD WITH KEY GUARDS AND WIDE HOLD HANDLE (SUPERSEDED BY SL 737-SL-34-202 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-202 REV. A	FLIGHT MANAGEMENT COMPUTER (FMC) DISPLAY UNIT – AVAILABILITY OF AN ALTERNATE KEYBOARD WITH KEY GUARDS AND WIDE HOLD HANDLE, SERVICE LETTER					RECOMMENDED	
		MOS					
06-JUL-2011			-				
SL 737-SL-34-203	LOW RANGE RADIO ALTIMETER (LRRA) REPLACEMENT - THALES ERT-550 TRANSCEIVER P/N 9599-607-19996, SERVICE LETTER					RECOMMENDED	
		MOS					
20-SEP-2011			-				
SL 737-SL-34-204	LOW RANGE RADIO ALTIMETER REPLACEMENT - HONEYWELL ALA-52B TRANSCEIVER P/N 066-50007-0531 , SERVICE LETTER					RECOMMENDED	
		MOS					
28-NOV-2011			-				
SL 737-SL-34-205	NEW FLIGHT MANAGEMENT COMPUTER CONTROL DISPLAY UNIT OPERATIONAL SOFTWARE - U3.1 (SUPERSEDED BY SL 737-SL-34-205 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-34-205 REV. A	NEW FLIGHT MANAGEMENT COMPUTER CONTROL DISPLAY UNIT OPERATIONAL SOFTWARE - U3.1, SERVICE LETTER					RECOMMENDED	
		MOS					
09-APR-2012			-				
SL 737-SL-34-206	PITOT PROBE FLEXIBLE HOSE CONFIGURATIONS, SERVICE LETTER					RECOMMENDED	
		MOS					
23-NOV-2011			-				
SL 737-SL-34-207	DEFERRED APPLICATION OF AERO-SEALANT IN AIR DATA SENSOR INSTALLATIONS, SERVICE LETTER					RECOMMENDED	
		MOS					
10-NOV-2011			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-34-208	NEW FLIGHT MANAGEMENT COMPUTER (FMC) DISPLAY UNIT PART NUMBERS (P/N) S242A600-1003,S242A600-2003,S242A600-3003, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAR-2012			-				
SL 737-SL-34-210	LOW RANGE RADIO ALTIMETER (LRRA) ANTENNA GEL GASKET INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JAN-2013			-				
SL 737-SL-34-211	NEW SUPPLIER AND PART NUMBER OF STANDBY MAGNETIC COMPASS, SERVICE LETTER					RECOMMENDED	
		MOS					
18-DEC-2012			-				
SL 737-SL-34-212	P5 PANEL BONDING JUMPER - FASTENER NUT NOT PROPERLY TORQUED, SERVICE LETTER					RECOMMENDED	
		MOS					
22-FEB-2013			-				
SL 737-SL-34-213	NEW SENSOR SYSTEMS LOW RANGE RADIO ALTIMETER (LRRA) ANTENNA PART NUMBER, SERVICE LETTER					RECOMMENDED	
		MOS					
27-FEB-2013			-				
SL 737-SL-34-215	P/N S242A101-009 AIR DATA INERTIAL REFERENCE UNIT (ADIRU) (HONEYWELL P/N HG2050AC11) MAG VAR UPDATE, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAY-2014			-				
SL 737-SL-34-216	ENHANCED GROUND PROXIMITY WARNING COMPUTER (EGPWC) UPGRADE FROM MK V TO MK V-A, SERVICE LETTER					RECOMMENDED	
		MOS					
30-APR-2014			-				
SL 737-SL-34-217	NEW ENHANCED GROUND PROXIMITY WARNING COMPUTER (EGPWC) - P/N 69000940-102, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JUN-2014			-				
SL 737-SL-35-003 REV. C	PASSENGER OXYGEN MASK ASSEMBLY, TUBE DETERIORATION., SERVICE LETTER					RECOMMENDED	
		MOS					
30-MAR-2000			- (s)				
SL 737-SL-35-003 REV. D	PASSENGER OXYGEN MASK ASSEMBLY, TUBE DETERIORATION, SERVICE LETTER						
		MOS					
22-AUG-2001			- (s)				

© Camp Systems

EFTA00618622

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-35-015	MODIFICATION OF THE MXPH10 CREW OXYGEN MASK STOWAGE BOX, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUN-1999			- (s)				
SL 737-SL-35-016	POTENTIALLY OVERSIZED 115 SCF STEEL OXYGEN CYLINDERS, SERVICE LETTER					RECOMMENDED	
		MOS					
16-SEP-1999			- (s)				
SL 737-SL-35-016 REV. A	POTENTIALLY OVERSIZED 115 SCF STEEL OXYGEN CYLINDERS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-NOV-1999			- (s)				
SL 737-SL-35-018	B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT USEFUL LIFE CHANGE AND NECK SEAL IMPROVEMENT, SERVICE LETTER						
		MOS					
01-FEB-2002			- (s)				
SL 737-SL-35-019	MAINTAINING OXYGEN SYSTEM CLEANLINESS, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-OCT-2003			-				
SL 737-SL-35-019 REV. A	MAINTAINING OXYGEN SYSTEM CLEANLINESS, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-MAR-2004			-				
SL 737-SL-35-020	OXYGEN CYLINDER SERVICING, SERVICE LETTER					RECOMMENDED	
		MOS					
23-JUN-2009			-				
SL 737-SL-35-021	B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
26-MAY-2011			-				
SL 737-SL-35-022	CREW OXYGEN MASK INFLATABLE HARNESS LEAKAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
13-JUN-2011			-				
SL 737-SL-35-023	CREW OXYGEN SYSTEM - TOTAL LOSS OF OXYGEN, SERVICE LETTER					RECOMMENDED	
		MOS					
30-APR-2012			-				
SL 737-SL-35-026	CREW OXYGEN MASK REGULATORS SET INCORRECTLY BY SUPPLIER REPAIR STATION, SERVICE LETTER					RECOMMENDED	
		MOS					
09-JAN-2013			-				

© Camp Systems

EFTA00618623

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-35-027	CREW OXYGEN - FLEX HOSE AND WIRE BUNDLE INSTALLATION , SERVICE LETTER					RECOMMENDED	
		MOS					
31-OCT-2013			-				
SL 737-SL-35-028	SMOKE HOOD USE, DISPOSAL AND IMPROVEMENT (SUPERSEDED BY SL 737-SL-35-028 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-35-028 REV. A	SMOKE HOOD USE, DISPOSAL AND IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
16-JUN-2014			-				
SL 737-SL-36-010	APU DUCT BOOT CLAMP T-BOLT NUT TORQUE INSPECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUL-1999			- (s)				
SL 737-SL-36-010 REV. A	APU DUCT BOOT CLAMP T-BOLT NUT TORQUE INSPECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
13-OCT-1999			- (s)				
SL 737-SL-36-010 REV. B	APU DUCT BOOT CLAMP T-BOLT NUT TORQUE INSPECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
20-OCT-2000			- (s)				
SL 737-SL-36-011	SEPARATION BETWEEN AN ENGINE WIRE BUNDLE AND A PNEUMATIC SENSE LINE, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-MAR-2004			-				
SL 737-SL-36-011 REV. A	SEPARATION BETWEEN AN ENGINE WIRE BUNDLE AND A PNEUMATIC SENSE LINE, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-JUN-2004			-				
SL 737-SL-36-011 REV. B	SEPARATION BETWEEN AN ENGINE WIRE BUNDLE AND A PNEUMATIC SENSE LINE, SERVICE LETTER						
		MOS					
05-JUL-2005			-				
SL 737-SL-36-012	IMPROVED CABIN PRESSURE SEAL FLANGE ON THE APU DUCT ASSEMBLY, SERVICE LETTER						
		MOS					
15-MAR-2005			-				

© Camp Systems

EFTA00618624

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-36-012 REV. A	IMPROVED CABIN PRESSURE SEAL FLANGE ON THE APU DUCT ASSEMBLY, SERVICE LETTER						
		MOS					
31-AUG-2005			-				
SL 737-SL-36-012 REV. B	IMPROVED CABIN PRESSURE SEAL FLANGE ON THE APU DUCT ASSEMBLY, SERVICE LETTER						
		MOS					
08-OCT-2007			-				
SL 737-SL-36-013	MINIMUM SERVICEABLE PNEUMATIC DUCT PRESSURE, SERVICE LETTER						
		MOS					
20-APR-2007			-				
SL 737-SL-36-013 REV. A	MINIMUM SERVICEABLE PNEUMATIC DUCT PRESSURE, SERVICE LETTER						
		MOS					
21-MAY-2007			-				
SL 737-SL-36-013 REV. B	MINIMUM SERVICEABLE PNEUMATIC DUCT PRESSURE, SERVICE LETTER						
		MOS					
04-FEB-2008			-				
SL 737-SL-36-014	BLEED AIR REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
31-AUG-2006			-				
SL 737-SL-36-014 REV. A	BLEED AIR REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
19-DEC-2006			-				
SL 737-SL-36-014 REV. B	BLEED AIR REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
10-JUL-2007			-				
SL 737-SL-36-014 REV. C	BLEED AIR REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
19-SEP-2007			-				
SL 737-SL-36-014 REV. D	BLEED AIR REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
09-JAN-2008			-				
SL 737-SL-36-016	HIGH STAGE REGULATOR MODIFICATION, SERVICE LETTER						
		MOS					
10-APR-2007			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-36-017	HIGH STAGE BLEED AIR VALVE, SERVICE LETTER						
			MOS					
	21-FEB-2008			-				
SL	737-SL-36-018	BLEED AIR SYSTEM 390 AND 450 TEMPERATURE SENSOR IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-MAR-2009			-				
SL	737-SL-36-019	PRESSURE REGULATOR SHUTOFF VALVE (PRSOV) IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-MAR-2009			-				
SL	737-SL-36-020	NEW PRSOV FLEX LINE, SERVICE LETTER					RECOMMENDED	
			MOS					
	07-OCT-2009			-				
SL	737-SL-36-021	FIFTH STAGE BLEED AIR CHECK VALVE INSPECTION (SUPERSEDED BY SL 737-SL-36-021 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-36-021 REV. A	FIFTH STAGE BLEED AIR CHECK VALVE INSPECTION, SERVICE LETTER					RECOMMENDED	
			MOS					
	21-JAN-2011			-				
SL	737-SL-36-022	FIFTH STAGE BLEED AIR CHECK VALVE - BUSHING BRAZING (SUPERSEDED BY SL 737-SL-36-022 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-36-022 REV. A	FIFTH STAGE BLEED AIR CHECK VALVE - BUSHING BRAZING, SERVICE LETTER					RECOMMENDED	
			MOS					
	22-MAY-2012			-				
SL	737-SL-36-023	BLEED AIR PRECOOLER CONTROL VALVE(PCCV) IMPROVEMENTS, SERVICE LETTER						
			MOS					
	21-JUL-2010			-				
SL	737-SL-36-024	ACMS 'USER GUIDE' FOR ENHANCED ECS TROUBLESHOOTING AND HEALTH MANAGEMENT (SUPERSEDED BY SL 737-SL-36-024 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-36-024 REV. A	ACMS 'USER GUIDE' FOR ENHANCED ECS TROUBLESHOOTING AND HEALTH MANAGEMENT (SUPERSEDED BY SL 737-SL-36-024 REV. B), SERVICE LETTER					RECOMMENDED	
		MOS					
13-SEP-2011			-				
SL 737-SL-36-024 REV. B	ACMS "USER GUIDE" FOR ENHANCED PNEUMATIC SYSTEM TROUBLESHOOTING AND HEALTH MANAGEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
18-MAR-2013			-				
SL 737-SL-36-025	PRECOOLER CONTROL VALVE KISS SEAL IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
29-OCT-2010			-				
SL 737-SL-36-026	ENGINE BLEED SYSTEM MAINTENANCE PROCEDURES DESCRIPTION TABLES, SERVICE LETTER					RECOMMENDED	
		MOS					
06-DEC-2010			-				
SL 737-SL-36-029	CIRCUIT BREAKERS LABEL-INCORRECT NOMENCLATURE (SUPERSEDED BY SL 737-SL-36-029 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-36-029 REV. A	CIRCUIT BREAKERS LABEL-INCORRECT NOMENCLATURE (SUPERSEDED BY SL 737-SL-36-029 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-36-029 REV. B	CIRCUIT BREAKERS LABEL-INCORRECT NOMENCLATURE (SUPERSEDED BY SL 737-SL-36-029 REV. C), SERVICE LETTER					RECOMMENDED	
		MOS					
12-APR-2013			-				
SL 737-SL-36-029 REV. C	CIRCUIT BREAKERS LABEL-INCORRECT NOMENCLATURE, SERVICE LETTER					RECOMMENDED	
		MOS					
22-MAY-2013			-				
SL 737-SL-36-030	PRE-COOLER INSTALLATION, INCORRECT SAFETY WIRE INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
03-MAY-2013			-				
SL 737-SL-36-031	PRSOV AND HIGH STAGE VALVE IMPROVMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
10-DEC-2013			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-38-009	WASTE WATER DRAIN SYSTEM BLOCKAGE PREVENTION (SUPERSEDED BY SL 737-SL-38-009 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-009 REV. A	WASTE WATER DRAIN SYSTEM BLOCKAGE PREVENTION (SUPERSEDED BY SL 737-SL-38-009 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-009 REV. B	WASTE WATER DRAIN SYSTEM BLOCKAGE PREVENTION (SUPERSEDED BY SL 737-SL-38-009 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-009 REV. C	WASTE WATER DRAIN SYSTEM BLOCKAGE PREVENTION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-NOV-2012			-				
SL 737-SL-38-015 REV. B	GREY WATER DRAIN CLEANING INFORMATION AND FREQUENCY, SERVICE LETTER					RECOMMENDED	
		MOS					
19-NOV-2012			-				
SL 737-SL-38-016	IN SITU CHEMICAL CLEANING PROCEDURE FOR VACUUM WASTE TUBES, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-APR-2007			- (s)				
SL 737-SL-38-016 REV. A	IN SITU CHEMICAL CLEANING PROCEDURE FOR VACUUM WASTE TUBES, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-MAR-2006			- (s)				
SL 737-SL-38-016 REV. B	IN SITU CHEMICAL CLEANING PROCEDURES FOR VACUUM WASTE TUBES, SERVICE LETTER						
		MOS					
31-MAR-2006			-				
SL 737-SL-38-018	IN SITU CHEMICAL CLEANING PROCEDURE FOR VACUUM WASTE TUBES, SERVICE LETTER					RECOMMENDED	
		MOS					
26-NOV-1996			- (s)				
SL 737-SL-38-018 REV. A	IN SITU CHEMICAL CLEANING PROCEDURE FOR VACUUM WASTE TUBES, SERVICE LETTER					RECOMMENDED	
		MOS					
25-NOV-1997			- (s)				

© Camp Systems

EFTA00618628

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-38-018 REV. B	IN SITU CHEMICAL CLEANING PROCEDURE FOR VACUUM WASTE TUBES, SERVICE LETTER					INFORMATIONAL	
		MOS					
28-MAY-1999			- (s)				
SL 737-SL-38-018 REV. C	IN-SITU PRESSURE CLEANING PROCEDURE OF VACUUM WASTE TUBES (SUPERSEDED BY SL 737-SL-38-018 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-018 REV. D	IN SITU PRESSURE CLEANING PROCEDURE OF VACUUM WASTE TUBES (SL REPORTED AS ATA 3832-90), SERVICE LETTER					RECOMMENDED	
		MOS					
15-OCT-2012			-				
SL 737-SL-38-019	VACUUM WASTE SYSTEM MAINTENANCE RECOMMENDATIONS, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JUL-1997			- (s)				
SL 737-SL-38-019 REV. A	VACUUM WASTE SYSTEM MAINTENANCE RECOMMENDATIONS (SUPERSEDED BY SL 737-SL-38-019 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			- (s)				
SL 737-SL-38-019 REV. B	VACUUM WASTE SYSTEM MAINTENANCE RECOMMENDATIONS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-NOV-2012			-				
SL 737-SL-38-020	VACUUM WASTE TANK IMPROVE AIR/WATER SEPARATOR, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JAN-1999			- (s)				
SL 737-SL-38-022	LAVATORY POTABLE WATER SELECTOR VALVE ADAPTER REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
27-MAY-1999			- (s)				
SL 737-SL-38-023	INSPECT FOR POTENTIAL MISSING CLAMPS FROM FORWARD GRAY WATER DRAIN LINE TUBE INSTL, SERVICE LETTER					RECOMMENDED	
		MOS					
16-AUG-1999			- (s)				
SL 737-SL-38-024	WASTE SERVICE PANEL COVER FASTENER INSPECTION AND POTENTIAL REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
28-SEP-1999			- (s)				

© Camp Systems

EFTA00618629

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-38-026	POTABLE WATER CABLE ASSEMBLY IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-NOV-1999			- (s)				
SL 737-SL-38-026 REV. A	POTABLE WATER CABLE ASSEMBLY IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
		MOS					
14-JUL-2000			- (s)				
SL 737-SL-38-028 REV. A	AVAILABILITY OF POTABLE WATER TANK WITH IMPROVED LINER AND WINDING MATERIAL, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-AUG-2000			- (s)				
SL 737-SL-38-031 REV. B	VACUUM WASTE LINE BLOCKAGE "KINETIC WATER RAM" REMOVAL TOOL AND USAGE (SUPERSEDED BY SL 737-SL-38-031 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-031 REV. C	VACUUM WASTE LINE BLOCKAGE 'KINETIC WATER RAM' REMOVAL TOOL AND USAGE, SERVICE LETTER					RECOMMENDED	
		MOS					
29-OCT-2012			-				
SL 737-SL-38-032	VACUUM WASTE CLEANING METHODS, SERVICE LETTER						
		MOS					
22-JUN-2007			-				
SL 737-SL-38-032 REV. A	VACUUM WASTE CLEANING METHODS, SERVICE LETTER						
		MOS					
11-MAR-2008			-				
SL 737-SL-38-032 REV. B	VACUUM WASTE CLEANING METHODS (SUPERSEDED BY 737-SL-38-019-C), SERVICE LETTER					SUPERSEDED	
		MOS					
10-SEP-2009			-				
SL 737-SL-38-032 REV. C	VACUUM WASTE CLEANING METHODS (SUPERSEDED BY SL 737-SL-38-032 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-032 REV. D	VACUUM WASTE CLEANING METHODS (SUPERSEDED BY SL 737-SL-38-032 REV. E), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-032 REV. E	VACUUM WASTE CLEANING METHODS (SUPERSEDED BY SL 737-SL-38-032 REV. F), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-38-032 REV. F	VACUUM WASTE CLEANING METHODS (SUPERSEDED BY SL 737-SL-38-032 REV. G), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-38-032 REV. G	VACUUM WASTE CLEANING METHODS, SERVICE LETTER					RECOMMENDED	
		MOS					
01-APR-2014			-				
SL 737-SL-38-033	FORWARD DOOR SILL DRAIN VALVE REPLACEMENT, SERVICE LETTER						
		MOS					
10-FEB-2010			-				
SL 737-SL-38-034	VACUUM WASTE SYSTEM BLOWER REPLACEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JUN-2011			-				
SL 737-SL-38-035	VACUUM WASTE SYSTEM MAINTENANCE PRACTICES, SERVICE LETTER					RECOMMENDED	
		MOS					
25-NOV-2013			-				
SL 737-SL-45-001	READINESS OF BOEING MODELS FOR Y2K, SERVICE LETTER					RECOMMENDED	
		MOS					
23-DEC-1998			- (s)				
SL 737-SL-45-001 REV. A	READINESS OF BOEING MODELS FOR Y2K, SERVICE LETTER					RECOMMENDED	
		MOS					
28-APR-1999			- (s)				
SL 737-SL-45-001 REV. B	READINESS OF BOEING MODELS FOR Y2K, SERVICE LETTER					RECOMMENDED	
		MOS					
03-JAN-2000			- (s)				
SL 737-SL-46-001 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.0 (PHASE 1) AND EFB DISPLAY UNIT UPDATE, SERVICE LETTER						
		MOS					
08-JUN-2007			-				
SL 737-SL-46-002	ELECTRONIC FLIGHT BAG DISPLAY UNIT PART NUMBER 197800-5/-51 BRIGHTNESS CONTROL CORRECTION, SERVICE LETTER						
		MOS					
08-JUN-2007			-				
SL 737-SL-46-003	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER						
		MOS					
01-JUL-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-46-003 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER	MOS	-				
10-NOV-2008							
SL 737-SL-46-003 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER	MOS	-			RECOMMENDED	
24-MAR-2009							
SL 737-SL-46-003 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER	MOS	-			RECOMMENDED	
13-APR-2009							
SL 737-SL-46-003 REV. D	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER	MOS	-			RECOMMENDED	
16-JUL-2009							
SL 737-SL-46-003 REV. E	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.3, SERVICE LETTER	MOS	-				
10-FEB-2010							
SL 737-SL-46-004	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.4, SERVICE LETTER	MOS	-				
05-NOV-2008							
SL 737-SL-46-004 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.4, SERVICE LETTER	MOS	-				
21-APR-2009							
SL 737-SL-46-004 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.4, SERVICE LETTER	MOS	-			RECOMMENDED	
08-JUL-2009							
SL 737-SL-46-004 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.4, SERVICE LETTER	MOS	-			RECOMMENDED	
23-NOV-2009							
SL 737-SL-46-004 REV. D	ELECTRONIC FLIGHT BAG (EFB)BLOCKPOINT 3.4 (SUPERSEDED BY SL 737-SL-46-004 REV. E), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-46-004 REV. E	ELECTRONIC FLIGHT BAG (EFB)BLOCKPOINT 3.4, SERVICE LETTER	MOS	-			RECOMMENDED	
06-AUG-2010							

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-46-004 REV. F	ELECTRONIC FLIGHT BAG (EFB)BLOCKPOINT 3.4, SERVICE LETTER					RECOMMENDED	
		MOS					
14-FEB-2011			-				
SL 737-SL-46-005 REV. A	ELECTRONIC FLIGHT BAG (EFB) ELECTRONIC UNIT (EU) HARDWARE UPGRADE, SERVICE LETTER						
		MOS					
29-OCT-2008			-				
SL 737-SL-46-006 REV. A	BLOCKPOINT 4 ELECTRONIC FLIGHT BAG (EFB) HARDWARE AND EFB BP 4.0 SOFTWARE (SUPERSEDED BY SL 737-SL-46-006 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-006 REV. B	BLOCKPOINT 4 ELECTRONIC FLIGHT BAG(EFB)HARDWARE AND EFB BP 4.0 SOFTWARE (SUPERSEDED BY SL 737-SL-46-006 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-006 REV. C	BLOCKPOINT 4 ELECTRONIC FLIGHT BAG(EFB)HARDWARE AND EFB BP 4.0 SOFTWARE, SERVICE LETTER					RECOMMENDED	
		MOS					
17-JUN-2011			-				
SL 737-SL-46-007	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 1, SERVICE LETTER					RECOMMENDED	
		MOS					
01-DEC-2009			-				
SL 737-SL-46-007 REV. A	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 1, SERVICE LETTER					RECOMMENDED	
		MOS					
16-DEC-2009			-				
SL 737-SL-46-008	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.2 (SUPERSEDED BY SL 737-SL-46-008 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-008 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.2 (SUPERSEDED BY SL 737-SL-46-008 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-008 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.2 (SUPERSEDED BY SL 737-SL-46-008 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-46-008 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.2 (SUPERSEDED BY SL 737-SL-46-008 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-008 REV. D	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.2, SERVICE LETTER					RECOMMENDED	
		MOS					
27-JUL-2012			-				
SL 737-SL-46-009	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.5 (SUPERSEDED BY SL 737-SL-46-009 REV. A) , SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-009 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.5 (SUPERSEDED BY SL 737-SL-46-009 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-009 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.5 (SUPERSEDED BY SL 737-SL-46-009 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-009 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.5, SERVICE LETTER					RECOMMENDED	
		MOS					
10-NOV-2011			-				
SL 737-SL-46-010	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 2 (SUPERSEDED BY SL 737-SL-46-010 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-010 REV. A	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 2 (SUPERSEDED BY SL 737-SL-46-010 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-010 REV. B	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 2, SERVICE LETTER					RECOMMENDED	
		MOS					
04-NOV-2011			-				
SL 737-SL-46-013	WIRE BUNDLE DISCONNECT BRACKET AB366 INCORRECTLY LABELED (SUPERSEDED BY SL 737-SL-46-013 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-46-013 REV. A	WIRE BUNDLE DISCONNECT BRACKET AB366 INCORRECTLY LABELED, SERVICE LETTER					RECOMMENDED	
		MOS					
19-APR-2012			-				
SL 737-SL-46-014	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) (SUPERSEDED BY SL 737-SL-46-014 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-014 REV. A	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) (SUPERSEDED BY SL 737-SL-46-014 REV. B) , SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-014 REV. B	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 2.0 (SUPERSEDED BY SL 737-SL-46-014 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-014 REV. C	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 2.0, SERVICE LETTER					RECOMMENDED	
		MOS					
21-NOV-2013			-				
SL 737-SL-46-015	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3, SERVICE LETTER					RECOMMENDED	
		MOS					
12-DEC-2011			-				
SL 737-SL-46-016	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-016 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-46-016 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. C), SERVICE LETTER					RECOMMENDED	
		MOS					
20-AUG-2012			-				
SL 737-SL-46-016 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. D) , SERVICE LETTER					RECOMMENDED	
		MOS					
18-FEB-2013			-				

© Camp Systems

EFTA00618635

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-46-016 REV. D	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. E), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-016 REV. E	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7 (SUPERSEDED BY SL 737-SL-46-016 REV. F), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-016 REV. F	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.7, SERVICE LETTER	MOS	-			RECOMMENDED	
	10-MAR-2014							
SL	737-SL-46-017	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4 (SUPERSEDED BY SL 737-SL-46-017 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-017 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4 (SUPERSEDED BY SL 737-SL-46-017 REV. B), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-017 REV. B	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4 (SUPERSEDED BY SL 737-SL-46-017 REV. C), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-017 REV. C	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4 (SUPERSEDED BY SL 737-SL-46-017 REV. D), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-017 REV. D	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4 (SUPERSEDED BY SL 737-SL-46-017 REV. E), SERVICE LETTER	MOS	-			SUPERSEDED	
SL	737-SL-46-017 REV. E	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.4, SERVICE LETTER	MOS	-			RECOMMENDED	
	10-MAR-2014							
SL	737-SL-46-018	GOODRICH SERVICE INFORMATION LETTER (SIL) – CAMERA INTERFACE UNIT (CIU) UPGRADE, SERVICE LETTER	MOS	-			RECOMMENDED	
	22-AUG-2012							
SL	737-SL-46-019	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 3.1, SERVICE LETTER	MOS	-			RECOMMENDED	
	25-FEB-2013							

© Camp Systems

EFTA00618636

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-46-020	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.8 (SUPERSEDED 737-SL-46-020 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-46-020 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.8, SERVICE LETTER					RECOMMENDED	
			MOS					
	21-NOV-2013			-				
SL	737-SL-46-021	ELECTRONIC FLIGHT BAG (EFB) BLOCK POINT 4.5 (SUPERSEDED BY SL 737-SL-46-021 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-46-021 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.5, SERVICE LETTER					RECOMMENDED	
			MOS					
	10-MAR-2014			-				
SL	737-SL-46-022	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.0 (SUPERSEDED BY SL 737-SL-46-022 REV. A), SERVICE LETTER					RECOMMENDED	
			MOS					
	13-DEC-2012			-				
SL	737-SL-46-022 REV. A	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 3.0, SERVICE LETTER					RECOMMENDED	
			MOS					
	29-APR-2013			-				
SL	737-SL-46-023	PORTABLE MAINTENANCE DEVICE MALWARE PREVENTION, DISCOVERY, AND OPERATOR GUIDANCE FOR EVENT HANDLING, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-AUG-2013			-				
SL	737-SL-46-024	CLASS 2 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.0, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-MAR-2014			-				
SL	737-SL-46-025	BOEING CLASS 1 ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT (BP) 4.0, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-MAR-2014			-				
SL	737-SL-46-026	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.6/4.6E (SUPERSEDED BY SL 737-SL-46-026 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-46-026 REV. A	ELECTRONIC FLIGHT BAG (EFB) BLOCKPOINT 4.6/4.6E, SERVICE LETTER					RECOMMENDED	
			MOS					
	09-MAY-2014			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-46-027 REV. A	AIRCRAFT NETWORK SECURITY PROGRAM (ANSP) REGULATORY REQUIREMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUN-2014			-				
SL 737-SL-47-001	POSSIBLE INCORRECT TEE-FITTING ON THE NGS SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS	24 (s)				
11-NOV-2009							
SL 737-SL-47-001 REV. A	POSSIBLE INCORRECT TEE-FITTING ON THE NGS SYSTEM (SUPERSEDED BY SL 737-SL-47-001 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-47-001 REV. B	POSSIBLE INCORRECT TEE-FITTING ON THE NGS SYSTEM, SERVICE LETTER					RECOMMENDED	
		MOS					
23-SEP-2010			-				
SL 737-SL-47-002	INCORRECT MATING TEETH ON NGS ELECTRICAL CONNECTIONS, SERVICE LETTER					RECOMMENDED	
		MOS					
16-FEB-2010			-				
SL 737-SL-47-002 REV. A	INCORRECT MATING TEETH ON NGS ELECTRICAL CONNECTIONS, SERVICE LETTER					INFORMATIONAL	
		MOS					
18-MAR-2010			-				
SL 737-SL-47-004	NGS NEADS TUBE CHAFING, SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-47-004 REV. A	NGS NEADS TUBE CHAFING, SERVICE LETTER					RECOMMENDED	
		MOS					
16-DEC-2011			-				
SL 737-SL-47-006	ENVIRONMENTAL CONTROL - NGS BITE DISPLAY UNIT (BDU) - CRACKED CAPACITORS ON BDU, SERVICE LETTER					RECOMMENDED	
		MOS					
17-DEC-2013			-				
SL 737-SL-49-058	FALSE APU MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					RECOMMENDED	
		MOS					
19-DEC-1997			- (s)				
SL 737-SL-49-058 REV. A	FALSE APU MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					RECOMMENDED	
		MOS					
19-MAR-1999			- (s)				

© Camp Systems

EFTA00618638

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-49-058 REV. B	FALSE AUXILIARY POWER UNIT (APU) MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					RECOMMENDED	
		MOS					
23-JUL-2001			- (s)				
SL 737-SL-49-058 REV. C	FALSE AUXILIARY POWER UNIT (APU) MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2001			- (s)				
SL 737-SL-49-058 REV. D	FALSE AUXILIARY POWER UNIT (APU) MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-APR-2004			-				
SL 737-SL-49-058 REV. E	FALSE AUXILIARY POWER UNIT (APU) MAINTENANCE LIGHT ILLUMINATION, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAY-2009			-				
SL 737-SL-49-059	START POWER UNIT (SPU) TRANSFORMER MOUNTING PLATE IMPROVEMENT ALLIED SIGNAL MODEL 131-9B AUXILIARY POWER UNIT (APU), SERVICE LETTER					RECOMMENDED	
		MOS					
08-APR-1998			- (s)				
SL 737-SL-49-060	BENEFITS OF OPERATING TWO AIR CONDITIONING PACKS WITH 131-9B AUXILIARY POWER UNIT (APU), SERVICE LETTER					RECOMMENDED	
		MOS					
03-JUN-1998			- (s)				
SL 737-SL-49-061	131-9B APU START CONVERTER UNIT MODIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
10-JUL-1998			- (s)				
SL 737-SL-49-067	131-9B AUXILIARY POWER UNIT ELECTRONIC CONTROL UNIT (ECU), SERVICE LETTER					RECOMMENDED	
		MOS					
12-AUG-1999			- (s)				
SL 737-SL-49-067 REV. A	131-9B AUXILIARY POWER UNIT ELECTRONIC CONTROL UNIT (ECU), SERVICE LETTER					RECOMMENDED	
		MOS					
20-SEP-1999			- (s)				
SL 737-SL-49-071	MISSING COMBUSTOR CASE DRAIN PLUG CAUSING HEAT DAMAGE TO THE APU DOOR, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-JUN-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-49-071 REV. A	MISSING COMBUSTER CASE DRAIN PLUG CAUSING HEAT DAMAGE TO THE APU DOOR, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-APR-2003			-				
SL 737-SL-49-072	131-9B APU START SYSTEM IMPREOVEMENT - INTRODUCTION OF NEW START CONVERTER UNIT AND START POWER UNIT, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-JUL-2001			- (s)				
SL 737-SL-49-074	PAINT PEELING OFF FROM APU EDUCTOR INLET DUCT, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-APR-2003			-				
SL 737-SL-49-075	HIGH RESISTANCE ACROSS APU EXHAUST GROUND STRAP, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-FEB-2004			-				
SL 737-SL-49-075 REV. A	HIGH RESISTANCE ACROSS APU EXHAUST GROUND STRAP, SERVICE LETTER					INFORMATIONAL	
		MOS					
05-APR-2004			-				
SL 737-SL-49-076	APU AIR INLET DUCT BOX CORROSION, SERVICE LETTER						
		MOS					
15-AUG-2005			-				
SL 737-SL-49-076 REV. A	APU AIR INLET DUCT BOX CORROSION, SERVICE LETTER					RECOMMENDED	
		MOS					
04-JUN-2009			-				
SL 737-SL-49-076 REV. B	APU AIR INLET DUCT BOX CORROSION (SUPERSEDED BY SL 737-SL-49-076 REV. C), SERVICE LETTER					INFORMATIONAL	
		MOS					
30-MAR-2010			-				
SL 737-SL-49-076 REV. C	APU AIR INLET DUCT BOX CORROSION, SERVICE LETTER					RECOMMENDED	
		MOS					
26-MAR-2013			-				
SL 737-SL-49-077	APU EXHAUST MUFFLER - INSULATION BLANKET REPAIR, SERVICE LETTER						
		MOS					
22-SEP-2005			-				
SL 737-SL-49-078	APU ECU SOFTWARE - VERSION 4, SERVICE LETTER						
		MOS					
14-AUG-2008			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-49-078 REV. A	APU ECU SOFTWARE - VERSION 4, SERVICE LETTER						
		MOS					
31-OCT-2008			-				
SL 737-SL-49-078 REV. B	APU ECU SOFTWARE - VERSION 4, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JAN-2010			-				
SL 737-SL-49-079	GAP IN APU INSULATION BLANKET, SERVICE LETTER					RECOMMENDED	
		MOS					
11-MAY-2009			-				
SL 737-SL-49-080	UNDERTORQUED FASTENERS IN APU MOUNT INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-49-080 REV. A	UNDERTORQUED FASTENERS IN APU MOUNT INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
21-JAN-2010			-				
SL 737-SL-49-081	IMPROPER REMOVAL OF DRY FILM LUBRICANT FROM APU MOUNT STRUT ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
30-OCT-2009			-				
SL 737-SL-49-081 REV. A	IMPROPER REMOVAL OF DRY FILM LUBRICANT FROM APU MOUNT STRUT ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
22-DEC-2000			-				
SL 737-SL-49-082	VERSION 5 - APU ECU OPERATION SOFTWARE, SERVICE LETTER					RECOMMENDED	
		MOS					
14-MAY-2010			-				
SL 737-SL-49-084	HYDRAULIC LOCK IN APU SOLENOID VALVE, SERVICE LETTER					RECOMMENDED	
		MOS					
06-APR-2012			-				
SL 737-SL-49-085	LOW DUCT PRESSURE DUE TO APU INLET GUIDE VANE DISAGREES WITH COMMAND FAULT, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAR-2012			-				
SL 737-SL-49-086	APU OIL DRAIN TUBE MISALIGNMENT CAUSING EXTERNAL OIL STREAKING, SERVICE LETTER					RECOMMENDED	
		MOS					
22-MAR-2012			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-49-087	FIRST STAGE TURBINE WHEEL BLADE WALKING - 131-9B APU (SUPERSEDED BY SL 737-SL-49-087 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-49-087 REV. A	FIRST STAGE TURBINE WHEEL BLADE WALKING - 131-9B APU, SERVICE LETTER					RECOMMENDED	
		MOS					
28-JUL-2014			-				
SL 737-SL-49-088	131-9B APU CERAMIC DUPLEX BALL BEARING ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
12-JUL-2012			-				
SL 737-SL-49-089	APU DATA MEMORY MODULE WITH NON-COMPLIANT COMPONENT, SERVICE LETTER					RECOMMENDED	
		MOS					
01-AUG-2012			-				
SL 737-SL-49-090	COMMON COMMERCIAL CONTROL UNIT - 131-9B APU (SUPERSEDED BY SL 737-SL-49-090 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-49-090 REV. A	COMMON COMMERCIAL CONTROL UNIT - 131-9B APU, SERVICE LETTER					RECOMMENDED	
		MOS					
11-OCT-2012			-				
SL 737-SL-49-091	STARTER- GENERATOR IMPROVEMENT - 9 STARTER GENERATOR, SERVICE LETTER					RECOMMENDED	
		MOS					
12-SEP-2012			-				
SL 737-SL-49-092	MANUFACTURING ESCAPE - LOOSE COMBUSTOR DRAIN ADAPTOR - 131-9B APU, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JAN-2013			-				
SL 737-SL-49-093	POSSIBLE GROUND JUMPER ASSEMBLY UNDER TORQUE - 131-9B APU (SUPERSEDED BY SL 737-SL-49-093 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-49-093 REV. A	POSSIBLE GROUND JUMPER ASSEMBLY UNDER TORQUE - 131-9B APU, SERVICE LETTER					RECOMMENDED	
		MOS					
19-JUN-2013			-				

© Camp Systems

EFTA00618642

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-49-094	INCORRECT INSTALLATION OF SEALING PLUGS IN APU WIRING HARNESS CONNECTORS - 131-9B APU (SUPERSEDED BY SL 737-SL-49-094 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-49-094 REV. A	INCORRECT INSTALLATION OF SEALING PLUGS IN APU WIRING HARNESS CONNECTORS - 131-9B APU, SERVICE LETTER					RECOMMENDED	
	20-DEC-2013		MOS	-				
SL	737-SL-51-022	WING AND HORIZONTAL STABILIZER INSPAR FINISHES (ORIGINALLY REPORTED AS ATA 5180-21) (SUPERSEDED BY SL 737-SL-51-022 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS	-				
SL	737-SL-51-022 REV. A	WING AND HORIZONTAL STABILIZER INSPAR FINISHES (ORIGINALLY REPORTED AS ATA 5180-21), SERVICE LETTER					RECOMMENDED	
	13-APR-2012		MOS	-				
SL	737-SL-51-027 REV. B	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA, SERVICE LETTER					INFORMATIONAL	
	10-JUL-2002		MOS	- (s)				
SL	737-SL-51-027 REV. D	BOEING COMMERCIAL AIRPLANES REVIEW AND DELEGATED APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA, SERVICE LETTER						
	12-MAY-2005		MOS	-				
SL	737-SL-51-027 REV. E	BOEING COMMERCIAL AIRPLANES REVIEW AND DELEGATED APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA, SERVICE LETTER						
	11-OCT-2006		MOS	-				
SL	737-SL-51-027 REV. F	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIRS, SERVICE LETTER						
	24-MAY-2007		MOS	-				
SL	737-SL-51-027 REV. G	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIRS, SERVICE LETTER						
	21-JAN-2008		MOS	-				
SL	737-SL-51-027 REV. H	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIRS, SERVICE LETTER						
	19-JUN-2008		MOS	-				

© Camp Systems

EFTA00618643

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-51-027 REV. I	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-APR-2010			-				
SL 737-SL-51-027 REV. J	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA (SUPERSEDED BY SL 737-SL-51-027 REV. K), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-027 REV. K	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIR AND MODIFICATION DATA (SUPERSEDED BY SL 737-SL-51-027 REV. L), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-027 REV. L	BOEING APPROVAL OF AIRPLANE STRUCTURAL REPAIRS, SERVICE LETTER					RECOMMENDED	
		MOS					
11-APR-2014			-				
SL 737-SL-51-029 REV. B	DAMAGE TOLERANT MAINTENANCE REQUIREMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-DEC-2002			-				
SL 737-SL-51-035	DESIGN IMPROVEMENT TO PREVENT DIFFICULTY IN THE OPERATION OF THE FORWARD ENTRY DOOR, SERVICE LETTER						
		MOS					
26-NOV-2002			-				
SL 737-SL-51-036	"METALBOND"-STRUCTURAL ALUMINUM BONDING PRECAUTIONS AND PROCEDURES, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-AUG-2003			-				
SL 737-SL-51-037	INACTIVATION OF BACB30MY6()*X AND Y FASTENERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-APR-2003			-				
SL 737-SL-51-037 REV. A	INACTIVATION OF BACB30MY6()()X AND Y FASTENERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-JUL-2003			-				
SL 737-SL-51-038 REV. A	DAMAGE IDENTIFICATION AND REMOVAL DURING STRUCTURAL REPAIRS, SERVICE LETTER						
		MOS					
14-JUL-2006			-				

© Camp Systems

EFTA00618644

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-51-039	MAJOR REVISIONS TO STRUCTURAL REPAIR MANUAL METALBOND SECTIONS, SERVICE LETTER						
		MOS					
15-SEP-2005			-				
SL 737-SL-51-039 REV. A	MAJOR REVISIONS TO STRUCTURAL REPAIR MANUAL METALBOND SECTIONS, SERVICE LETTER						
		MOS					
17-OCT-2007			-				
SL 737-SL-51-040	POSSIBLE CORROSION ON THE EMERGENCY ESCAPE HATCH UPPER SILLS. BS616 & 639 (-600 & -700) BS578 & BS639 (-800 & -900), SERVICE LETTER						NOT APPLICABLE
		MOS			22-AUG-2008		
17-DEC-2006			-		3260:48		
		AFL			782		
SL 737-SL-51-040 REV. A	POSSIBLE CORROSION ON THE EMERGENCY ESCAPE HATCH UPPER SILLS. BS616 & 639 (-600 & -700) BS578 & BS639 (-800 & -900), SERVICE LETTER						
		MOS					
10-JUL-2007			-				
SL 737-SL-51-041	MAJOR MINOR REPAIR CLASSIFICATION (SUPERSEDED BY SL 737-SL-51-041 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-041 REV. A	MAJOR/MINOR REPAIR CLASSIFICATION (SUPERSEDED BY SL 737-SL-51-041 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-041 REV. B	MAJOR MINOR REPAIR CLASSIFICATION (SUPERSEDED BY SL 737-SL-51-041 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-041 REV. C	MAJOR MINOR REPAIR CLASSIFICATION (SUPERSEDED BY SL 737-SL-51-041 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-041 REV. D	MAJOR/MINOR REPAIR CLASSIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
22-NOV-2013			-				
SL 737-SL-51-042 REV. B	DAMAGE REPORTING AND REPAIR PLAN/DESIGN GUIDELINES, SERVICE LETTER					RECOMMENDED	
		MOS					
09-DEC-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-51-042 REV. C	DAMAGE REPORTING AND REPAIR PLAN/DESIGN GUIDELINES (SUPERSEDED BY SL 737-SL-51-042 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-042 REV. D	DAMAGE REPORTING AND REPAIR PLAN/DESIGN GUIDELINES, SERVICE LETTER					RECOMMENDED	
		MOS					
16-MAR-2011			-				
SL 737-SL-51-043	BOEING SUPPORT OF OPERATOR COMPLIANCE WITH THE AGING AIRPLANE SAFETY RULE (SUPERSEDED BY SL 737-SL-51-043 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-043 REV. A	BOEING SUPPORT OF OPERATOR COMPLIANCE WITH THE AGING AIRPLANE SAFETY RULE (SUPERSEDED BY SL 737-SL-51-043 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-51-043 REV. B	BOEING SUPPORT OF OPERATOR COMPLIANCE WITH THE AGING AIRPLANE SAFETY RULE, SERVICE LETTER					RECOMMENDED	
		MOS					
27-OCT-2010			-				
SL 737-SL-51-044	PINHOLES IN THE FINISH OF CARBON FIBER REINFORCED PLASTIC (CFRP) PARTS, SERVICE LETTER					RECOMMENDED	
		MOS					
21-OCT-2011			-				
SL 737-SL-51-045	CORROSION PREVENTION AND CONTROL PROGRAMS, SERVICE LETTER					RECOMMENDED	
		MOS					
02-FEB-2012			-				
SL 737-SL-51-047	ESCAPEMENT OF SPS TECHNOLOGIES BACN10JR3CFD NUTPLATES WITH MISSING CADMIUM PLATING, SERVICE LETTER					RECOMMENDED	
		MOS					
25-JAN-2013			-				
SL 737-SL-52-023	WING REFUEL ACCESS DOOR HOLD OPEN STRUT ASSY LOCK MODIFICATION TO PREVENT OVER EXTENSION, SERVICE LETTER					RECOMMENDED	
		MOS					
18-JAN-1999			- (s)				
SL 737-SL-52-024	AFT LEFT ENTRY DOOR HANDLE SEPARATION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-OCT-1999			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-52-024 REV. A	AFT LEFT ENTRY DOOR HANDLE SEPARATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-FEB-2002			- (s)				
SL 737-SL-52-025	AUTOMATIC OVERWING EXIT FLIGHT LOCK - SOLENOID IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
05-OCT-2000			- (s)				
SL 737-SL-52-026	FORWARD AIRSTAIR TOP STEP CONTROL ACTUATOR AND ROLLER ENGAGEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-SEP-2001			- (s)				
SL 737-SL-52-026 REV. A	FORWARD AIRSTAIR TO STEP CONTROL ACTUATOR AND ROLLER ENGAGEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-MAY-2003			-				
SL 737-SL-52-027	FORWARD AIRSTAIR TOP STEP INTERFFERENCE WITH FLOOR BEAM HEX-DRIVE BOLT COLLARS, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-NOV-2001			- (s)				
SL 737-SL-52-027 REV. A	FORWARD AIRSTAIR TOP STEP INTERFERENCE WITH FLOOR BEAM HEX-DRIVE BOLT COLLARS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-SEP-2005			-				
SL 737-SL-52-027 REV. B	FORWARD AIRSTAIR TOP STEP INTERFERENCE WITH FLOOR BEAM HEX-DRIVE BOLT COLLARS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-MAR-2009			-				
SL 737-SL-52-027 REV. C	FORWARD AIRSTAIR TOP STEP INTERFERENCE WITH FLOOR BEAM HEX-DRIVE BOLT COLLARS, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-MAR-2010			-				
SL 737-SL-52-028	FORWARD AIRSTAIR DOOR LOCK PIN ACTUATOR - NEW POTTING MATERIAL, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-MAY-2002			- (s)				
SL 737-SL-52-029	CARGO DOOR SWITCH COVER IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
11-APR-2002			- (s)				
SL 737-SL-52-029 REV. A	AFT CARGO DOOR SWITCH COVER IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-OCT-2002			-				

© Camp Systems

EFTA00618647

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-52-029 REV. B	AFT CARGO DOOR SWITCH COVER IMPROVEMENT, SERVICE LETTER						
		MOS					
13-NOV-2006			-				
SL 737-SL-52-030	ENHANCED SECURITY FLIGHT DECK DOOR PRESSURE RELIEF LATCH REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
31-JAN-2003			- (s)				
SL 737-SL-52-031	SECURE FLIGHT DECK DOOR LOCK CONTROL MODULE ROTARY SWITCH, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-APR-2003			-				
SL 737-SL-52-032 REV. A	ENHANCED FLIGHT DECK ACCESS DOOR, NEW BEZEL FOR ACCESS SYSTEM KEYPAD MODULE, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-MAY-2003			-				
SL 737-SL-52-034	AIRSTAIR DOOR INDICATION TARGET AND BRACKET-REPLACEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
20-MAY-2003			-				
SL 737-SL-52-034 REV. A	AIRSTAIR DOOR INDICATION TARGET AND BRACKET-REPLACEMENT, SERVICE LETTER						COMPLIED WITH - COMPONENT REPLACEMENT COMPLIED WITH
		MOS		02-MAR-2006			
13-SEP-2005			-	2509:38			
		AFL		609			
SL 737-SL-52-036 REV. A	DEADBOLT ARMOR PLATE INSTALLATION, SERVICE LETTER						
		MOS					
16-NOV-2006			-				
SL 737-SL-52-037 REV. A	C&D AEROSPACE ENHANCED SECURITY FLIGHT DECK DOOR DIFFICULT TO OPEN, SERVICE LETTER						
		MOS					
16-APR-2004			-				
SL 737-SL-52-038	FORWARD AIRSTAIR RELIABILITY IMPROVEMENTS - PRR 38582, SERVICE LETTER						
		MOS					
17-NOV-2005			-				
SL 737-SL-52-039	AIRSTAIR DOOR FORWARD OVERHEAD WARNING LIGHT - INOP PLACARD CHECK, SERVICE LETTER						
		MOS					
09-APR-2007			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-52-039 REV. A	AIRSTAIR DOOR FORWARD OVERHEAD WARNING LIGHT - INOP PLACARD CHECK, SERVICE LETTER						
			MOS					
	28-AUG-2007			-				
SL	737-SL-52-039 REV. B	AIRSTAIR DOOR FORWARD OVERHEAD WARNING LIGHT - INOP PLACARD CHECK, SERVICE LETTER						
			MOS					
	23-JUL-2008			-				
SL	737-SL-52-040	AFT FAIRING BRAKE ACCUMULATOR DOOR HOLD OPEN STRUT ASSEMBLY, SERVICE LETTER						
			MOS					
	21-MAY-2007			-				
SL	737-SL-52-040 REV. A	AFT FAIRING BRAKE ACCUMULATOR DOOR HOLD OPEN STRUT ASSEMBLY, SERVICE LETTER						
			MOS					
	22-JUN-2007			-				
SL	737-SL-52-041	CARGO DOOR HANDLE IMPROVEMENTS, SERVICE LETTER						
			MOS					
	24-JUL-2007			-				
SL	737-SL-52-042	MAIN LANDING GEAR DOOR, BULB SEAL ATTACHMENT, SERVICE LETTER						
			MOS					
	23-JUL-2007			-				
SL	737-SL-52-043	STAB TRIM AND FLIGHT DECK DOOR CONTROL P8-47 PANEL - ANNUNCIATOR, SERVICE LETTER						
			MOS					
	24-JAN-2008			-				
SL	737-SL-52-044	AVAILABILITY OF IMPROVED FORWARD ENTRY DOOR SNUBBER, SERVICE LETTER						
			MOS					
	22-DEC-2008			-				
SL	737-SL-52-044 REV. A	AVAILABILITY OF IMPROVED FORWARD ENTRY DOOR SNUBBER, SERVICE LETTER						
			MOS					
	19-JAN-2009			-				
SL	737-SL-52-044 REV. B	AVAILABILITY OF IMPROVED FORWARD ENTRY DOOR SNUBBER, SERVICE LETTER					RECOMMENDED	
			MOS					
	13-MAY-2009			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-52-045	FORWARD ENTRY DOOR GUIDE ARM RADIUS LINKS PIN SCREW, SERVICE LETTER						
		MOS					
22-DEC-2008			-				
SL 737-SL-52-047	AVAILABILITY OF IMPROVEMENTS FOR AFT ENTRY, AFT SERVICE AND FORWARD GALLEY DOOR SNUBBERS (SUPERSEDED BY SL 737-SL-52-047 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-52-047 REV. A	AVAILABILITY OF IMPROVEMENTS FOR AFT ENTRY, AFT SERVICE AND FORWARD GALLEY DOOR SNUBBERS, SERVICE LETTER					RECOMMENDED	
		MOS					
18-AUG-2010			-				
SL 737-SL-52-048	AVAILABILITY OF IMPROVED FORWARD AND AFT CARGO DOOR LATCH ASSEMBLIES, SERVICE LETTER					RECOMMENDED	
		MOS					
13-AUG-2009			-				
SL 737-SL-52-048 REV. A	AVAILABILITY OF IMPROVED FORWARD AND AFT CARGO DOOR LATCH ASSEMBLIES, SERVICE LETTER					INFORMATIONAL	
		MOS					
25-MAR-2010			-				
SL 737-SL-52-049	AVAILABILITY OF IMPROVED EE BAY DOOR LATCH ASSEMBLY, SERVICE LETTER					RECOMMENDED	
		MOS					
08-DEC-2009			-				
SL 737-SL-52-049 REV. A	AVAILABILITY OF IMPROVED EE BAY DOOR LATCH ASSEMBLY, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-MAR-2010			-				
SL 737-SL-52-050	POTENTIAL DAMAGE TO THE FORWARD ENTRY DOOR SEAL AND SEAL RETAINER, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2010			-				
SL 737-SL-52-051	SECURE FLIGHT DECK DOOR - DESIGN CHANGE FOR THE SOLENOID STRIKER LINK, SERVICE LETTER					RECOMMENDED	
		MOS					
06-AUG-2010			-				
SL 737-SL-52-052	FORWARD AIRSTAIR ASSEMBLY - ACTUATOR GEAR - DISCREPANCY, SERVICE LETTER					RECOMMENDED	
		MOS					
07-OCT-2010			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-52-053	DURABILITY IMPROVEMENT FOR THE BEARING PLATE ON THE DOORSTOP PAD INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
11-NOV-2010			-				
SL 737-SL-52-054	POSSIBLE INCORRECTLY INSTALLED O-RING IN DOOR HANDLES IN THE FORWARD GALLEY, AFT GALLEY AND AFT ENTRY DOORS (SUPERSEDED BY SL 737-SL-52-054 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-52-054 REV. A	POSSIBLE INCORRECTLY INSTALLED O-RING IN DOOR HANDLES IN THE FORWARD GALLEY, AFT GALLEY AND AFT ENTRY DOORS, SERVICE LETTER					RECOMMENDED	
		MOS					
23-AUG-2011			-				
SL 737-SL-52-055	DOORS - FORWARD AIRSTAIR - BALLSCREW - DISCREPANT MATERIAL, SERVICE LETTER					RECOMMENDED	
		MOS					
27-JAN-2011			-				
SL 737-SL-52-057	FORWARD AIRSTAIRS -DOOR - CONTROLS - OCK PIN ACTUATOR - MODIFICATION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-NOV-2011			-				
SL 737-SL-52-058	"FORWARD AIRSTAIR - AFT HANDRAIL BRACKET - STRIKER PLATE", SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2012			-				
SL 737-SL-52-060	FORWARD ENTRY DOOR PROXIMITY SENSOR TARGET UPGRADE, SERVICE LETTER					RECOMMENDED	
		MOS					
16-NOV-2012			-				
SL 737-SL-53-047	NOSE RADOME DIVERTER STRIP ATTACHINSERT SEALING IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
22-DEC-2008			- (s)				
SL 737-SL-53-048	POSSIBLE MISSING SEALANT COMMON TO A BSTA 727 BRACKET, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-OCT-2000			- (s)				
SL 737-SL-53-049	POSSIBLE MISLOCATED ELEVATOR CONTROL CABLE ISOLATION BLOCKS ON SECTION 43 SEAT TRACKS, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-SEP-2000			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-53-050	POSSIBLE CRACKS IN THE COUNTERSINKS OF FASTNER HOLES COMMON TO FRONT SPAR TO REAR SPAR UNDERWING PANELS, SERVICE LETTER					INFORMATIONAL	
		MOS	72 (s)	08-OCT-1999			
20-SEP-2000							
SL 737-SL-53-051	SKIN PANEL ASSEMBLY REPLACEMENT-LAP JOINT FASTNER SIZE INSTALLATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-OCT-2000			- (s)				
SL 737-SL-53-051 REV. A	SKIN PANEL ASSEMBLY REPLACEMENT-LAP JOINT FASTENER SIZE INSTALLATION, SERVICE LETTER						
		MOS					
01-SEP-2006			-				
SL 737-SL-53-054	MISSING WING-TO-BODY FAIRING ELECTRICALLY BONDED FASTENERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
30-OCT-2000			- (s)				
SL 737-SL-53-055	MISSING FASTENERS COMMON TO BS 420 STRINGER CLIPS AT S- 19R/22R/23R/24R, SERVICE LETTER					RECOMMENDED	
		MOS					
28-MAR-2002			-				
SL 737-SL-53-056	ALLOWABLE FUSELAGE SKIN WRINKLING CRITERIA, SERVICE LETTER					RECOMMENDED	
		MOS					
22-AUG-2001			- (s)				
SL 737-SL-53-056 REV. A	ALLOWABLE FUSELAGE SKIN WRINKLING CRITERIA, SERVICE LETTER						
		MOS					
12-MAR-2002			- (s)				
SL 737-SL-53-057	EXAMINATION OF BS1016 AFT PRESSURE BULKHEAD AND SURROUNDING SECTION 48 STRUCTURE, SERVICE LETTER						
		MOS					
25-SEP-2001			- (s)				
SL 737-SL-53-058	POSSIBLE RIDING CONDITION BETWEEN FASTENER AND RUDDER PEDAL SHAFT NUT P/N BACN10RF25, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-NOV-2001			- (s)				
SL 737-SL-53-058 REV. A	POSSIBLE RIDING CONDITION BETWEEN FASTENER AND RUDDER PEDAL SHAFT NUT P/N BACN10RF25, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-JUL-2004			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-53-059	SECTION 48 - MISSING STRINGER 2AL AND 2AR FASTENERS, SERVICE LETTER					INFORMATIONAL	
			MOS					
	15-JAN-2002			- (s)				
SL	737-SL-53-060	GREASE EXTRUDING FROM THE SPLIT LINE OF THE BODY STATION 706 MAIN LANDING GEAR SUPPORT FITTING ASSEMBLY., SERVICE LETTER						
			MOS	6 (s)				
	18-JUL-2002							
SL	737-SL-53-060 REV. A	GREASE EXTRUDING FROM THE SPLIT LINE OF THE BODY STATION 706 MAIN LANDING GEAR SUPPORT FITTING ASSEMBLY, SERVICE LETTER						
			MOS					
	28-MAR-2003			- (s)				
SL	737-SL-53-061	POSSIBLE INADEQUATE SEALING BETWEEN THE BODY STATION 1016 BULKHEAD WEB AND VERTICAL FIN ATTACH FITTING, SERVICE LETTER					INFORMATIONAL	
			MOS					
	12-APR-2002			- (s)				
SL	737-SL-53-062	MISSING FASTENERS COMMON TO FUSELAGE SKIN JUST FORWARD OF BS 1016 (SUPERSEDED BY SL 737-SL-53-062 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				- (s)				
SL	737-SL-53-062 REV. A	MISSING FASTENERS COMMON TO FUSELAGE SKIN JUST FORWARD OF BS 1016, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-JUL-2010			-				
SL	737-SL-53-064	MISSING FASTNERS COMMON TO BS 360 SHEAR TIE BETWEEN STRINGER 14R AND STRINGER 15R, SERVICE LETTER						COMPLIED WITH
			MOS			29-AUG-2011		
	31-MAR-2004			-		3533:32		
			AFL			863		
SL	737-SL-53-065	POSSIBLE TOOL MARK ON BSTA 178 BULKHEAD, SERVICE LETTER						
			MOS					
	06-MAY-2005			-				
SL	737-SL-53-066 REV. A	CARGO COMPARTMENT CORROSION, SERVICE LETTER						
			MOS					
	29-JAN-2007			-				
SL	737-SL-53-067	TORLON CLIP-ON NUTS FOR FLOOR PANEL INSTALLATION, SERVICE LETTER						
			MOS					
	07-SEP-2005			-				

© Camp Systems

EFTA00618653

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-53-068	POSSIBLE TOOL MARKS ON PASSENGER WINDOW FRAMES, SERVICE LETTER						
		MOS					
15-SEP-2005			-				
SL 737-SL-53-069	BS 294.5 JACK PAD FITTING FASTENER HOLES DISCREPANCY, SERVICE LETTER						
		MOS					
14-JUL-2006			-				
SL 737-SL-53-070	SECTION 41 DRAIN PATH PLUGGED, SERVICE LETTER						
		MOS					
14-JUL-2006			-				
SL 737-SL-53-071	FUSELAGE SKIN WEAR DAMAGE FROM DORSAL FIN WEAR BETWEEN BS 851.5 TO 853.5, SERVICE LETTER						
		MOS					
01-JUN-2007			-				
SL 737-SL-53-072	POSSIBLE EXCESS THREAD PROTRUSION ON KEEL BEAM BOLTS AT BS540, WL150, LBL10 AND RBL10, SERVICE LETTER						COMPLIED WITH
		MOS			22-AUG-2008		
22-JUN-2007			-		3260:48		
		AFL			782		
SL 737-SL-53-072 REV. A	POSSIBLE EXCESS THREAD PROTRUSION ON KEEL BEAM BOLTS AT BS540, WL150, LBL10 AND RBL10, SERVICE LETTER					RECOMMENDED	
		MOS					
13-AUG-2009			-				
SL 737-SL-53-073	MISSING FILLET SEAL AT VACUUM WASTE SERVICE PANEL SUPPORT STRUCTURE, SERVICE LETTER						
		MOS					
25-JAN-2007			-				
SL 737-SL-53-075	IN FLIGHT DEPARTURE OF WING-TO-BODY FAIRING, AFT WHEEL WELL FAIRING PANEL, SERVICE LETTER						
		MOS					
05-MAR-2007			-				
SL 737-SL-53-075 REV. A	IN FLIGHT DEPARTURE OF WING-TO-BODY FAIRING, AFT WHEEL WELL FAIRING PANEL, SERVICE LETTER						
		MOS					
13-NOV-2007							
		AFL	1000 (s)				
SL 737-SL-53-076	POSSIBLE MISSING FILLER IN MAIN ENTRY DOOR UPPER SILL AT BS294.5, SERVICE LETTER						
		MOS					
09-APR-2007			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-53-077	POSSIBLE DRILL START MARKS IN THE OUTBOARD EDGE OF THE P/N 141A1116-10 FRAME WEB AND THE OUTBOARD RADIUS OF THE P/N 141A1115-4 FAIL SAFE CHORD, SERVICE LETTER						
			MOS					
	12-APR-2007			-				
SL	737-SL-53-078	MAIN CABIN FLOOR BEAM CORROSION, SERVICE LETTER						
			MOS					
	14-JUN-2007			-				
SL	737-SL-53-078 REV. A	MAIN CABIN FLOOR BEAM CORROSION (SUPERSEDED BY 737-SL-53-078 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-53-078 REV. B	MAIN CABIN FLOOR BEAM CORROSION, SERVICE LETTER						
			MOS					
	28-FEB-2008			-				
SL	737-SL-53-079	BOLTS INSTALLED WITH GAPS, MISSING WASHERS, AND INCORRECT NUTS AT BS 727 AT S-19R AND S-19L., SERVICE LETTER						COMPLIED WITH
			MOS			22-AUG-2008		
	21-AUG-2007			-		3260:48		
			AFL			782		
SL	737-SL-53-080	POSSIBLE DAMAGED HI-LOKS IN MAIN ENTRY DOOR UPPER SILL AT BS303.90, SERVICE LETTER						
			MOS					
	04-OCT-2007			-				
SL	737-SL-53-081	EXCESSIVE SEALANT IN NOSE LANDING GEAR HINGE CAVITY, SERVICE LETTER						
			MOS					
	04-DEC-2007			-				
SL	737-SL-53-082	TOOL MARK COMMON TO THE LOWER INBOARD EDGE OF STRAP AT STRINGER 18A, SERVICE LETTER						
			MOS					
	09-OCT-2007			-				
SL	737-SL-53-083	POSSIBLE GAP COMMON TO THE BODY STATION 203 WATERLINE 234 INNER CHORD SPLICE STRUCTURE (SUPERSEDED BY SL 737-SL-53-083 REV. A), SERVICE LETTER						
			MOS					
	09-NOV-2007			-				
SL	737-SL-53-083 REV. A	POSSIBLE GAP COMMON TO THE BODY STATION 203 WATERLINE 234 INNER CHORD SPLICE STRUCTURE (SUPERSEDED BY SL 737-SL-53-083 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				

© Camp Systems

EFTA00618655

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-53-083 REV. B	POSSIBLE GAP COMMON TO THE BODY STATION 203 WATERLINE 234 INNER CHORD SPLICE STRUCTURE, SERVICE LETTER					RECOMMENDED	
		MOS					
23-MAR-2012			-				
SL 737-SL-53-084	EXTERNAL GROUND POWER RECEPTACLE SKIN AND DOUBLER - PREVENTIVE MODIFICATION, SERVICE LETTER						
		MOS					
10-MAR-2008			-				
SL 737-SL-53-085	MISSING AND MISLOCATED FASTENERS IN SECTION 48 SKIN ASSEMBLY AT APPROXIMATELY STA 1088, S-20L AND S-20R, SERVICE LETTER					RECOMMENDED	
		MOS					
11-JAN-2010			-				
SL 737-SL-53-088	POSSIBLE MISSING STIFFENER IN TRANSVERSE FLOOR BEAM AT BS 344, RBL 54.6., SERVICE LETTER						
		MOS					
03-OCT-2008			-				
SL 737-SL-53-089	REPLACEMENT OF INSULATION BLANKET ATTACHMENT TCLAMPS/ SPRING CLIPS WITH BOND-ON PINS AT THE MAIN LANDING SUPPORT FRAME STA 695 AND 716 ABOVE S-17. (SUPERSEDED BY 737-SL-53-089 REV.A), SERVICE LETTER					SUPERSEDED	
		MOS					
19-DEC-2008			-				
SL 737-SL-53-089 REV. A	REPLACEMENT OF INSULATION BLANKET ATTACHMENT T-CLAMPS/SPRING CLIPS WITH BOND-ON PINS AT THE MAIN LANDING SUPPORT FRAME STA 695 AND 716 ABOVE S-17, SERVICE LETTER						
		MOS					
29-JUN-2010			-				
SL 737-SL-53-090	SEAL VOIDS AT BS 1016 AND BS 1088 VERTICAL FIN LUGS (SUPERSEDED BY SL 737-SL-53-090 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
24-APR-2009			-				
SL 737-SL-53-090 REV. A	SEAL VOIDS AT BS 1016 AND BS 1088 VERTICAL FIN LUGS, SERVICE LETTER					RECOMMENDED	
		MOS					
08-FEB-2013			-				
SL 737-SL-53-091	EXCESSIVE SEALANT IN APU DOOR HINGE CORNERS, SERVICE LETTER					RECOMMENDED	
		MOS					
02-JUL-2009			-				

© Camp Systems

EFTA00618656

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-53-093	LOWER AIRSTAIR SILL INSTALLATION GAPPING ON AIRCRAFT WITH AIRSTAIRS AND WITHOUT AIRSTAIRS, SERVICE LETTER					RECOMMENDED	
		MOS					
22-DEC-2010			-				
SL 737-SL-53-095	POSSIBLE MISSING FASTENERS FROM A GUSSET ASSY AND ANGLE ASSY AT FORWARD INBOARD CORNER OF WALL SURROUNDING WASTE TANK IN AFT CARGO BAY, SERVICE LETTER					RECOMMENDED	
		MOS					
12-NOV-2010			-				
SL 737-SL-53-097	POTENTIALLY INSUFFICIENT GRIP LENGTH FOR FLIGHT DECK FORWARD PANEL SUPPORT FASTENERS AT STA 204,WL208,RBL & LBL 29, SERVICE LETTER					RECOMMENDED	
		MOS					
25-APR-2011			-				
SL 737-SL-53-098	"AIR STAIR DOOR JUMPER POSSIBLY INSTALLED INCORRECTLY", SERVICE LETTER					RECOMMENDED	
		MOS					
20-SEP-2011			-				
SL 737-SL-53-099	DIFFICULTY CLOSING AND OPENING THE 141A5130-21 ALTERNATE GEAR EXTENSION DOOR ASSEMBLY DUE TO POSSIBLE INTERFERENCE (SUPERSEDED BY SL 737-SL-53-099 REV. A), SERVICE LETTER					RECOMMENDED	
		MOS					
09-APR-2012			-				
SL 737-SL-53-099 REV. A	DIFFICULTY CLOSING AND OPENING THE 141A5130-21 ALTERNATE GEAR EXTENSION DOOR ASSEMBLY DUE TO POSSIBLE INTERFERENCE, SERVICE LETTER					RECOMMENDED	
		MOS					
08-APR-2013			-				
SL 737-SL-53-100	POTENTIAL DRILL STARTS COMMON TO BS 540 FRAME, SERVICE LETTER					RECOMMENDED	
		MOS					
13-APR-2012			-				
SL 737-SL-53-101	POTENTIAL GOUGES FOUND AT BSTA 727 BULKHEAD FRAME, LBL AND RBL 10 (SUPERSEDED BY SL 737-SL-53-101 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-53-101 REV. A	POTENTIAL GOUGES FOUND AT BSTA 727 BULKHEAD FRAME, LBL AND RBL 10, SERVICE LETTER					RECOMMENDED	
		MOS					
07-AUG-2012			-				
SL 737-SL-53-102	POTENTIALLY MISSING NAS1368 GROMMETS AT STA312 AND STA328, TRANSVERSE FLOOR BEAM, SERVICE LETTER					RECOMMENDED	
		MOS					
18-SEP-2012			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-53-103	BS 578 TO 639 STUB BEAM FASTENERS MISSING COUNTER BORE WASHER (SUPERSEDED BY SL 737-SL-53-103 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-53-103 REV. A	BS 578 TO 639 STUB BEAM FASTENERS MISSING COUNTER BORE WASHER, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-AUG-2013			-				
SL	737-SL-53-104	CLEARING FALSE-POSITIVE CHEM-MILL CRACK INDICATIONS, SERVICE LETTER					RECOMMENDED	
			MOS					
	29-APR-2013			-				
SL	737-SL-53-105	POSSIBLE INADEQUATE SEALANT COMMON TO THE BS 887 STRINGER SPLICES, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-JAN-2014			-				
SL	737-SL-53-106	X-BAND RADOME MOISTURE INGRESSION, SERVICE LETTER					RECOMMENDED	
			MOS					
	25-FEB-2014			-				
SL	737-SL-54-019	POTENTIAL MISSING PRIMER FROM NACELLE STRUT DIAGONAL BRACE, SERVICE LETTER					INFORMATIONAL	
			MOS	60 (s)		08-OCT-1999		
	27-APR-1999							
SL	737-SL-54-021	AFT STRUT FAIRING PANEL HEAT DAMAGE, SERVICE LETTER					INFORMATIONAL	
			MOS					
	23-JAN-2004			-				
SL	737-SL-55-019	VERTICAL STABILIZER AFT REAR SPAR-PRIMARY FITTING SHIM MIGRATION, SERVICE LETTER						
			DAYS	180 (s)				
SL	737-SL-55-019 REV. A	VERTICAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER						
			DAYS	180 (s)				
	04-MAR-2002							
SL	737-SL-55-019 REV. B	VERTICAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER						
			MOS	180 (s)				
	02-MAY-2005							
SL	737-SL-55-019 REV. C	VERTICAL STABILIZER REAR SPAR SHIM MIGRATION (SUPERSEDED BY SL 737-SL-55-019 REV. D), SERVICE LETTER					SUPERSEDED	
			MOS					
				- (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-55-019 REV. D	VERTICAL STABILIZER REAR SPAR SHIM MIGRATION (SUPERSEDED BY SL 737-SL-55-019 REV. E), SERVICE LETTER					SUPERSEDED	
			MOS	- (s)				
SL	737-SL-55-019 REV. E	VERTICAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER					RECOMMENDED	
	17-JUN-2014		MOS	24 (s)				
			AFL	4800				
SL	737-SL-55-019 STEP 1	VERTICAL STABILIZER AFT REAR SPAR - PRIMARY FITTING SHIM MIGRATION, SERVICE LETTER					INFORMATIONAL	
	01-JAN-2000		MOS	- (s)				
SL	737-SL-55-019 STEP 5	VERTICAL STABILIZER AFT REAR SPAR - PRIMARY FITTING SHIM MIGRATION, SERVICE LETTER					RECOMMENDED	
	01-JAN-2000		MOS	- (s)				
SL	737-SL-55-020	HORIZONTAL STABILIZER HINGE PIN BUSHING RETAINER MISSING, SERVICE LETTER					INFORMATIONAL	
	05-JUL-2001		MOS	- (s)				
SL	737-SL-55-021	CLEANING OF DEICING/ANTI-ICING FLUID RESIDUE ON ELEVATOR TAB EXTERIOR, SERVICE LETTER					INFORMATIONAL	
	05-MAR-2002		MOS	- (s)				
SL	737-SL-55-021 REV. A	CLEANING OF DEICING/ANTI-ICING FLUID RESIDUE ON ELEVATOR TAB EXTERIOR, SERVICE LETTER					INFORMATIONAL	
	10-MAY-2002		MOS	- (s)				
SL	737-SL-55-023	VERTICAL STABILIZER REAR SPAR ATTACHMENT-POSSIBLE INCORRECT SPACER INSTALLATION AND FITTING DAMAGE, SERVICE LETTER					INFORMATIONAL	
	25-SEP-2003		MOS	-				
SL	737-SL-55-024	HORIZONTAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER						
	25-SEP-2003		MOS	24 (s)				
SL	737-SL-55-024 REV. A	HORIZONTAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER						
	03-NOV-2003		MOS	24 (s)				
SL	737-SL-55-024 REV. B	HORIZONTAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER						
	12-NOV-2003		MOS	24 (s)				

© Camp Systems

EFTA00618659

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-55-024 REV. C	HORIZONTAL STABILIZER REAR SPAR SHIM MIGRATION, SERVICE LETTER	MOS	24 (s)		12-SEP-2005		
SL 737-SL-55-025	HORIZONTAL STABILIZER REMOVABLE LEADING EDGE ASSEMBLY REWORK, SERVICE LETTER	MOS	-		18-DEC-2006		
SL 737-SL-55-025 REV. A	HORIZONTAL STABILIZER REMOVEABLE LEADING EDGE ASSEMBLY REWORK, SERVICE LETTER	MOS	-		12-JUN-2008		
SL 737-SL-55-026	HORIZONTAL STABILIZER AND HORIZONTAL STABILIZER CENTER SECTION MIGRATED BUSHING INSPECTION, SERVICE LETTER	MOS	-		21-MAY-2007		
SL 737-SL-55-027	HORIZONTAL STABILIZER FRONT SPAR TERMINAL FITTING BOLTS INSPECTION AND REWORK, SERVICE LETTER	MOS	-		12-APR-2007		
SL 737-SL-55-028	HORIZONTAL STABILIZER REAR SPAR TERMINAL FITTING BOLTS INSPECTION AND REWORK (SUPERSEDED BY SL 737-SL-55-028 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-55-028 REV. A	CANCELLED - HORIZONTAL STABILIZER REAR SPAR TERMINAL FITTING BOLTS INSPECTION AND REWORK (SUPERSEDED BY SL 737-SL-55-028 REV. B), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-55-028 REV. B	CANCELLED - HORIZONTAL STABILIZER REAR SPAR TERMINAL FITTING BOLTS INSPECTION AND REWORK, SERVICE LETTER	MOS	-		05-JUN-2012	CANCELLED	
SL 737-SL-55-029	GAP BETWEEN DORSAL FIN AND VERTICAL STABILIZER, SERVICE LETTER	MOS	-		24-APR-2007		
SL 737-SL-55-030	USE OF POLYURETHANE PROTECTIVE TAPE FOR EROSION PROTECTION ON HF ANTENNA, SERVICE LETTER	MOS	-		21-MAY-2009	RECOMMENDED	

© Camp Systems

EFTA00618660

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-55-031	IMPROVEMENTS FOR EROSION PROTECTION OF HF ANTENNA FIBERGLASS PANEL LEADING EDGE, SERVICE LETTER					RECOMMENDED	
		MOS					
31-JUL-2010			-				
SL 737-SL-55-033	HORIZONTAL STBILIZER AND HORIZONTAL STABILIZER CENTER SECTION DAMAGED BUSHING ASSESSMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
18-MAR-2014			-				
SL 737-SL-56-011	INABILITY TO OPEN CO-PILOT'S RIGHT HAND NUMBER 2 SLIDING WINDOW WITH EMERGENCY EXIT RELEASE HANDLE, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-AUG-2004			-				
SL 737-SL-56-012	AVAILICABILITY OF IMPROVED PASSENGER WINDOW ASSEMBLY TO REDUCE FOGGING., SERVICE LETTER						
		MOS					
13-APR-2006			-				
SL 737-SL-56-013	AVAILABILITY OF IMPROVED DOOR WINDOW ASSEMBLY TO REDUCE FOGGING, SERVICE LETTER						
		MOS					
28-JUN-2007			-				
SL 737-SL-56-014	AVAILABILITY OF NUMBER 2 TRANSPARENCY WITH IMPROVED TEMPERATURE SENSOR WIRE ROUTING AND INTERNAL CONNECTION, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUL-2013			-				
SL 737-SL-57-074	AILERON BALANCE PANEL FASTENERS, SERVICE LETTER					RECOMMENDED	
		MOS					
12-JUN-2000			- (s)				
SL 737-SL-57-075	WING TRAILING EDGE FLAP, WBL 201.24 DEFLECTION CONTROL RIB-IMPROVED NUT LOCKINF MECHANISMS, SERVICE LETTER					RECOMMENDED	
		MOS					
07-SEP-2000			- (s)				
SL 737-SL-57-075 REV. A	WING TRAILING EDGE FLAP, WBL 201.24 DEFLECTION CONTROL RIB-IMPROVED NUT LOCKINF MECHANISMS, SERVICE LETTER					RECOMMENDED	
		MOS					
04-OCT-2000			- (s)				
SL 737-SL-57-075 REV. E	WING TRAILING EDGE FLAP, WBL 201.24 DEFLECTION CONTROL RIB - IMPROVED NUT LOCKING MECHANISMS, SERVICE LETTER					RECOMMENDED	
		MOS					
25-SEP-2001			- (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-57-075 REV. F	WING TRAILING EDGE FLAP, WBL 201.24 DEFLECTION CONTROL RIB - IMPROVED NUT LOCKING MECHANISIM, SERVICE LETTER						
		MOS					
18-FEB-2002			- (s)				
SL 737-SL-57-077	WING TRAILING EDGE OUTBOARD AND INBOARD FLAP INSTALLATION, DESIGN/INSTALLATION IMPROVEMENTS TO THE CARRIAGE AND GIMBAL ASSEMBLIES., SERVICE LETTER					INFORMATIONAL	
		MOS					
07-AUG-2001			- (s)				
SL 737-SL-57-078	LOOSE FASTNERS IN THE AFT FLAP PROGRAMMING TRACKS, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-NOV-2001			- (s)				
SL 737-SL-57-079	WING TRAILING EDGE - INBOARD FIXED PANEL INTERFERENCE WITH GROUND SPOILERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
14-NOV-2001			- (s)				
SL 737-SL-57-080	INBOARD AFT FLAP LOWER SERVICE FOREIGN OBJECT DEBRIS (FOD) PROTECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
01-JUL-2002			- (s)				
SL 737-SL-57-080 REV. A	737-NG INBOARD AFT FLAP LOWER SURFACE FOREIGN OBJECT DEBRIS (FOD) PROTECTION, SERVICE LETTER					INFORMATIONAL	
		MOS					
09-JAN-2003			-				
SL 737-SL-57-081	INBOARD TRAILING EDGE FLAP, MAIN INBOARD TRACKS NUMBER 4 & 5 TUNGSTEN-CARBIDE COATING WEAR, SERVICE LETTER					INFORMATIONAL	
		MOS	6 (s)				
03-OCT-2003							
		AFL	1000				
SL 737-SL-57-081 REV. A	737NG INBOARD TRAILING EDGE FLAP, MAIN INBOARD TRACKS NUMBER 4 & 5 TUNGSTEN-CARBIDE COATING WEAR, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-AUG-2004			- (s)				
SL 737-SL-57-081 REV. B	737NG INBOARD TRAILING EDGE FLAP, MAIN INBOARD TRACKS NUMBER 4 & 5 TUNGSTEN-CARBIDE COATING WEAR, SERVICE LETTER						
		MOS					
13-NOV-2008			-				
SL 737-SL-57-082	WING TRAILING EDGES INBOARD MAIN FLAP AND OUTBOARD AFT FLAP DISBONDS, SERVICE LETTER						
		MOS					
16-MAY-2005			-				

© Camp Systems

	Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-57-082 REV. A	WING TRAILING EDGE - INBOARD MAIN FLAP AND OUTBOARD AFT FLAP DISBONDS (SUPERSEDED BY SL 737-SL-57-082 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-57-082 REV. B	WING TRAILING EDGE - INBOARD MAIN FLAP AND OUTBOARD AFT FLAP DISBONDS, SERVICE LETTER					RECOMMENDED	
			MOS					
	09-SEP-2013			-				
SL	737-SL-57-083	LEADING EDGE SLAT ASSEMBLY PART NUMBER IDENTIFICATION, SERVICE LETTER						NOT APPLICABLE
			MOS					
	06-OCT-2005			-				
SL	737-SL-57-084	FUEL LEAK FROM NUMBER 5 SLAT, INBOARD TRACK CAN, SERVICE LETTER						
			MOS					
	15-DEC-2005			-				
SL	737-SL-57-084 REV. A	FUEL LEAK FROM NUMBER 5 SLAT, INBOARD TRACK CAN, SERVICE LETTER						
			MOS					
	28-MAR-2006			-				
SL	737-SL-57-084 REV. B	FUEL LEAK FROM NUMBER 5 SLAT, INBOARD TRACK CAN, SERVICE LETTER						COMPLIED WITH - I.A.W. AD 2007-18-52
			MOS		05-SEP-2007			
	10-JUL-2007			-	2971:33			
			AFL		703			
SL	737-SL-57-084 REV. C	FUEL LEAK FROM NUMBER 5 SLAT, INBOARD TRACK CAN (SUPERSEDED BY 737-SL-57-084-D), SERVICE LETTER					SUPERSEDED	
			MOS					
	01-FEB-2010			-				
SL	737-SL-57-084 REV. D	FUEL LEAK FROM NUMBER 5 SLAT, INBOARD TRACK CAN, SERVICE LETTER						
			MOS					
	07-JUN-2010			-				
SL	737-SL-57-085	MESH GASKETS FOR FUEL TANK ACCESS DOORS (SUPERSEDED BY SL 737-SL-57-085 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-57-085 REV. A	MESH GASKETS FOR FUEL TANK ACCESS DOORS (SUPERSEDED BY SL 737-SL-57-085 REV. B), SERVICE LETTER					SUPERSEDED	COMPLIED WITH
			MOS		28-SEP-2009			
				-	3378:04			
			AFL		812			

© Camp Systems

EFTA00618663

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-57-085 REV. B	MESH GASKETS FOR FUEL TANK ACCESS DOORS (SUPERSEDED BY SL 737-SL-57-085 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-57-085 REV. C	MESH GASKETS FOR FUEL TANK ACCESS DOORS, SERVICE LETTER					RECOMMENDED	
		MOS					
28-OCT-2011			-				
SL 737-SL-57-087	INBOARD MAIN FLAP - AFT FLAP DRIVE BUSHING, SERVICE LETTER						
		MOS					
23-JUL-2007			-				
SL 737-SL-57-088	SLAT TRAILING EDGE WEDGE WEAR, SERVICE LETTER						
		MOS					
10-OCT-2007			-				
SL 737-SL-57-088 REV. A	SLAT TRAILING EDGE WEDGE WEAR, SERVICE LETTER						
		MOS					
24-MAR-2008			-				
SL 737-SL-57-089	SLAT TRACK CAN/HOUSING - INADVERTENT DAMAGE, SERVICE LETTER						
		MOS					
22-FEB-2008			-				
SL 737-SL-57-090	COSMETIC FINISH CRACK OF WINGLET TRAILING EDGE, SERVICE LETTER					RECOMMENDED	
		MOS					
08-DEC-2009			-				
SL 737-SL-57-093	SPAR CORROSION COMMON TO MAIN FUEL TANK BOOST PUMP BONDING JUMPERS, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-APR-2010			-				
SL 737-SL-57-094	WING FIXED TRAILING EDGE PANEL ELECTRIC BONDING WASHERS, SERVICE LETTER					RECOMMENDED	
		MOS					
07-SEP-2010			-				
SL 737-SL-57-095	MID SPAN FIXED TRAILING EDGE TURNBUCKLE CLEVIS INSTALLATION, SERVICE LETTER					RECOMMENDED	
		MOS					
04-NOV-2010			-				
SL 737-SL-57-097	AFT ROLLER BEARING, OUTBOARD FLAP INBOARD CARRAIGE, SERVICE LETTER					RECOMMENDED	
		MOS					
06-SEP-2011			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-57-098	737NG MAIN FLAP TRACKS UPPER AND LOWER FLANGES WEAR COMMON TO ROLLER CONTACT SURFACES, SERVICE LETTER					RECOMMENDED	
			MOS					
	06-SEP-2011			-				
SL	737-SL-57-099	"WING LEADING EDGE ? SLAT DETENT ARM AND ROLLER ALIGNMENT" (SUPERSEDED BY SL 737-SL-57-099 REV. A), SERVICE LETTER					RECOMMENDED	
			MOS					
	28-FEB-2012			-				
SL	737-SL-57-099 REV. A	"WING LEADING EDGE SLAT 4 AND 5 DETENT ARM AND ROLLER ALIGNMENT", SERVICE LETTER					RECOMMENDED	
			MOS					
	18-JUN-2012			-				
SL	737-SL-57-101	WEAR OF INBOARD AFT FLAP PROGRAM TRACK EDGE COMMON TO BEARING AND RUB PADS, SERVICE LETTER					RECOMMENDED	
			MOS					
	26-JUN-2012			-				
SL	737-SL-57-101 REV. A	WEAR OF INBOARD AFT FLAP PROGRAM TRACK EDGE COMMON TO BEARING AND RUB PADS (SUPERSEDED BY SL 737-SL-57-101 REV. B), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				
SL	737-SL-57-101 REV. B	WEAR OF INBOARD AFT FLAP PROGRAM TRACK EDGE, SERVICE LETTER					RECOMMENDED	
			MOS					
	20-SEP-2013			-				
SL	737-SL-57-102	MLG FORWARD TRUNNION FITTING BEARING RETAINING NUT INSPECTION, SERVICE LETTER					RECOMMENDED	
			MOS					
	06-SEP-2012			-				
SL	737-SL-57-103	POSSIBLE INCORRECT OR MISSING FASTENERS IN THE WING CENTER SECTION REAR SPAR, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-DEC-2012			-				
SL	737-SL-57-104	POSSIBLE LOOSE HARDWARE ON UPPER TRAILING EDGE PANEL SUPPORT, SERVICE LETTER					RECOMMENDED	
			MOS					
	19-APR-2013			-				
SL	737-SL-57-106	LH AND RH WING NACELLE SUPPORT OUTBOARD SIDELOAD BACKUP FITTING - MISSING FILLET SEAL (SUPERSEDED BY SL 737-SL-57-106 REV. A), SERVICE LETTER					SUPERSEDED	
			MOS					
				-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-57-106 REV. A	LH AND RH WING NACELLE SUPPORT OUTBOARD SIDELOAD BACKUP FITTING - MISSING FILLET SEAL, SERVICE LETTER					RECOMMENDED	
		MOS					
07-NOV-2013			-				
SL 737-SL-57-107	FRONT SPAR WEB CORROSION PREVENTION (SUPERSEDED BY SL 737-SL-57-107 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-57-107 REV. A	FRONT SPAR WEB CORROSION PREVENTION, SERVICE LETTER					RECOMMENDED	
		MOS					
30-SEP-2013			-				
SL 737-SL-57-108	FRONT SPAR LEADING EDGE STRAP CORROSION PREVENTION, SERVICE LETTER					RECOMMENDED	
		MOS					
20-SEP-2013			-				
SL 737-SL-57-109	RESTORATION OF ANTI-STATIC COATING COMMON TO THE AILERON FAIRINGS, SERVICE LETTER					RECOMMENDED	
		MOS					
10-OCT-2013			-				
SL 737-SL-71-028 REV. A	737 ENGINE INLET HAZARD ZONE BOUNDRIES PAINTED ON RAMP SURFACES, SERVICE LETTER					INFORMATIONAL	
		MOS					
25-APR-2002			- (s)				
SL 737-SL-71-047	ENGINE COWLING PLACARD REVISION, SERVICE LETTER					RECOMMENDED	
		MOS					
13-JAN-2000			- (s)				
SL 737-SL-71-047 REV. A	ENGINE COWLING PLACARD REVISION, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-OCT-2000			- (s)				
SL 737-SL-71-049	THRUST LINK DESIGN IMPROVEMENT-INTRODUCTION OF ANTI-ROTATION WASHER, SERVICE LETTER					RECOMMENDED	
		MOS					
01-JUN-2001			- (s)				
SL 737-SL-71-050	INCORRECT GRIP LENGTH OF AFT ENGINE MOUNT BOLTS, SERVICE LETTER					RECOMMENDED	
		MOS					
05-SEP-2001			- (s)				
SL 737-SL-71-050 REV. A	INCORRECT GRIP LENGTH OF AFT ENGINE MOUNT BOLTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2001			- (s)				

© Camp Systems

EFTA00618666

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-71-051	SPLIT DUCT PRESSURE DURING HIGH POWER ENGINE OPERATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-OCT-2001			- (s)				
SL 737-SL-71-053	INLET COWL LIPSKIN CORROSION PREVENTION, SERVICE LETTER						
		MOS					
04-AUG-2003			-				
SL 737-SL-71-053 REV. A	INLET COWL LIPSKIN CORROSION PREVENTION., SERVICE LETTER						
		MOS					
23-MAR-2005			-				
SL 737-SL-71-054	ENGINE FAN CASE BRACKET IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
30-SEP-2003			-				
SL 737-SL-71-054 REV. A	ENGINE FAN CASE BRACKET IMPROVEMENT, SERVICE LETTER						
		MOS					
20-NOV-2007			-				
SL 737-SL-71-055	ENGINE FIRE DETECTOR WIRE ROUTING CHANGE (SUPERSEDED BY SL 737-SL-71-055 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-71-055 REV. A	ENGINE FIRE DETECTOR WIRE ROUTING CHANGE (SUPERSEDED BY SL 737-SL-71-055 REV. B), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-71-055 REV. B	ENGINE FIRE DETECTOR WIRE ROUTING CHANGE (SUPERSEDED BY SL 737-SL-71-055 REV. C), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-71-055 REV. C	ENGINE FIRE DETECTOR WIRE ROUTING CHANGE, SERVICE LETTER					RECOMMENDED	
		MOS					
03-OCT-2012			-				
SL 737-SL-71-056	GROUND SUPPORT EQUIPMENT(GSE) FITTING ASSEMBLY FOR AFT BOOTSTRAP EQUIPMENT, SERVICE LETTER						
		MOS					
20-MAY-2005			-				
SL 737-SL-71-057	FORWARD ENGINE MOUNT DESIGN IMPROVEMENT - INTRODUCTION OF ANTI-ROTATION WASHER, SERVICE LETTER						
		MOS					
08-OCT-2007			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	737-SL-71-058	POWER FEEDER WIRE BUNDLE CHAFED AGAINST FAN COWL HINGE BRACKET, SERVICE LETTER						
			MOS					
	24-AUG-2006			-				
SL	737-SL-71-059	ENGINE COWL ANTI-ICE DUCT BOLT RETENTION DISCREPANCY, SERVICE LETTER						
			MOS					
				-				
SL	737-SL-71-059 REV. A	ENGINE COWL ANTI-ICE DUCT BOLT RETENTION DISCREPANCY, SERVICE LETTER						
			MOS					
				-				
SL	737-SL-71-059 REV. B	ENGINE COWL ANTI-ICE DUCT BOLT RETENTION DISCREPANCY, SERVICE LETTER						
			MOS					
	04-APR-2008			500 (s)				
SL	737-SL-71-061	INCORRECT MATERIAL USED FOR BACP18BC03B08P COTTER PINS INSTALLED ON ENGINE MOUNTS, SERVICE LETTER					SUPERSEDED	
			MOS					
				- (s)				
SL	737-SL-71-061 REV. A	INCORRECT MATERIAL USED FOR BACP18BC03B08P COTTER PINS INSTALLED ON ENGINE MOUNTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	30-SEP-2009			4000 (s)				
SL	737-SL-71-062	ENGINE-MOUNTED FAN COWL RADIAL SUPPORT BRACKET IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
			MOS					
	12-OCT-2009			-				
SL	737-SL-71-064	INLET COWL LIPSKIN FASTENER IMPROVEMENTS, SERVICE LETTER					RECOMMENDED	
			MOS					
	18-DEC-2013			-				
SL	737-SL-71-065	IMPROVED COWL THERMAL ANTI-ICE (CTAI) DUCT, SERVICE LETTER					RECOMMENDED	
			MOS					
	27-MAR-2014			-				
SL	737-SL-72-009	REDUCED INSPECTION INTERVAL FOR THE AFT SUMP CHIP DETECTOR - CFM56-7B ENGINES, SERVICE LETTER					RECOMMENDED	
			MOS					
	22-FEB-1999			- (s)				

© Camp Systems

EFTA00618668

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-72-010	ENGINE FAN BLADE LUBRICATION RECOMMENDATION, SERVICE LETTER						
		MOS					
28-NOV-2001			- (s)				
SL 737-SL-72-010 REV. A	ENGINE FAN BLADE LUBRICATION RECOMMENDATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
05-NOV-2002			-				
SL 737-SL-72-012	CFM56-7BE ENGINE INTRODUCTION (SUPERSEDED BY SL 737-SL-72-012 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-72-012 REV. A	CFM56-7BE ENGINE INTRODUCTION, SERVICE LETTER					RECOMMENDED	
		MOS					
21-DEC-2011			-				
SL 737-SL-73-013	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
04-AUG-1998			- (s)				
SL 737-SL-73-013 REV. A	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-OCT-1999			- (s)				
SL 737-SL-73-013 REV. B	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
08-FEB-1999			- (s)				
SL 737-SL-73-013 REV. C	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-JAN-2000			- (s)				
SL 737-SL-73-013 REV. D	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-JUN-2000			- (s)				
SL 737-SL-73-013 REV. E	CFM56-7B ENGINE EEC SOFTWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
19-DEC-2000			- (s)				
SL 737-SL-73-013 REV. F	CFM56-7B ENGINE ECC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-SEP-2001			- (s)				

© Camp Systems

EFTA00618669

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-73-013 REV. G	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-OCT-2001			- (s)				
SL 737-SL-73-013 REV. H	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2002			-				
SL 737-SL-73-013 REV. I	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS	6 (s)				
28-APR-2003							
SL 737-SL-73-013 REV. J	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
05-MAR-2004			-				
SL 737-SL-73-013 REV. K	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
03-MAR-2005			-				
SL 737-SL-73-013 REV. L	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
07-SEP-2005			-				
SL 737-SL-73-013 REV. M	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
28-MAR-2006			-				
SL 737-SL-73-013 REV. N	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
01-JUN-2007			-				
SL 737-SL-73-013 REV. O	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						COMPLIED WITH
		MOS		22-AUG-2008			
04-OCT-2007			-	3260:48			
		AFL		782			
SL 737-SL-73-013 REV. P	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
28-NOV-2007			-				

© Camp Systems

EFTA00618670

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-73-013 REV. R	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER	MOS	-				
03-JUN-2008							
SL 737-SL-73-013 REV. S	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY (SUPERSEDED BY SL 737-SL-73-013 REV. T), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-73-013 REV. T	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY (SUPERSEDED BY SL 737-SL-73-013 REV. U), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-73-013 REV. U	CFM56-7B ENGINE EEC SOFTWARE AND HARDWARE INTERCHANGEABILITY, SERVICE LETTER	MOS	-			RECOMMENDED	
22-JUL-2014							
SL 737-SL-73-014	ENGINE RATING CHECK, SERVICE LETTER	MOS	- (s)			RECOMMENDED	
12-AUG-1998							
SL 737-SL-73-017	HYDRO-MECHANICAL UNIT P/N 1853M56P08, SERVICE LETTER	MOS	- (s)				
13-MAR-2002							
SL 737-SL-73-018	IMPROVED FUEL FILTER DIFFERENTIAL PRESSURE SWITCH, TO REDUCE FALSE ENGINE FUEL FILTER BYPASS WARNING LIGHT INDICATIONS (SUPERSEDED BY SL 737-SL-73-018 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-73-018 REV. A	IMPROVED FUEL FILTER DIFFERENTIAL PRESSURE SWITCH TO REDUCE FALSE ENGINE FUEL FILTER BYPASS WARNING LIGHT INDICATIONS (SUPERSEDED BY SL 737-SL-73-018 REV. B), SERVICE LETTER	MOS	-			SUPERSEDED	
SL 737-SL-73-018 REV. B	IMPROVED FUEL FILTER DIFFERENTIAL PRESSURE SWITCH TO REDUCE FALSE ENGINE FUEL FILTER BYPASS WARNING LIGHT INDICATIONS, SERVICE LETTER	MOS	-			RECOMMENDED	
06-SEP-2012							
SL 737-SL-73-019	DIODE DECALS MAY BE INCORRECTLY LABELED. (SUPERSEDED BY SL 737-SL-73-019 REV. A), SERVICE LETTER	MOS	-			SUPERSEDED	

© Camp Systems

EFTA00618671

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-73-019 REV. A	DIODE DECALS MAY BE INCORRECTLY LABELED., SERVICE LETTER					RECOMMENDED	
		MOS					
18-SEP-2012			-				
SL 737-SL-76-020	ENGINE START BRAKE ASSEMBLY SWITCH IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
29-NOV-1999			- (s)				
SL 737-SL-76-021	AUTOTHROTTLE SWITCHPACK - IMPROVED WIRE ROUTING, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-NOV-2001			- (s)				
SL 737-SL-76-021 REV. A	AUTOTHROTTLE SWITCHPACK - IMPROVED WIRE ROUTING, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-JAN-2002			- (s)				
SL 737-SL-76-022	CRACKED ROLLER IN REVERSE THRUST LEVER ASSEMBLY, SERVICE LETTER						
		MOS					
13-DEC-2007			-				
SL 737-SL-77-014	AIRBORNE VIBRATION MONITORING (AVM) SIGNAL CONDITIONER IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
29-JUN-1998			- (s)				
SL 737-SL-77-015	, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-MAY-1999			- (s)				
SL 737-SL-77-015 REV. A	ENGINE AIRBORNE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGESBILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-JUN-2000			- (s)				
SL 737-SL-77-015 REV. B	ENGINE AIRBORNE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGESBILITY SERVICE LETTER, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-JUN-2000			- (s)				
SL 737-SL-77-015 REV. C	ENGINE AIRBORNE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGESBILITY SERVICE LETTER, SERVICE LETTER					INFORMATIONAL	
		MOS					
26-APR-2001			- (s)				
SL 737-SL-77-015 REV. D	ENGINE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGEABILITY, SERVICE LETTER					INFORMATIONAL	
		MOS					
12-APR-2002			- (s)				

© Camp Systems

EFTA00618672

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-77-015 REV. E	ENGINE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGEABILITY, SERVICE LETTER						
		MOS					
13-JAN-2004			-				
SL 737-SL-77-015 REV. F	ENGINE VIBRATION MONITORING SIGNAL CONDITIONER INTERCHANGEABILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
02-OCT-2009			-				
SL 737-SL-77-016	AIRPLANE OPERATION WITH ENGINE NUMBER 1 BEARING VIBRATION SENSOR DEACTIVATED, SERVICE LETTER					INFORMATIONAL	
		MOS					
21-SEP-1999			- (s)				
SL 737-SL-77-018	ADVANCED AIRBORNE VIBRATION MONITOR, SERVICE LETTER					RECOMMENDED	
		MOS					
19-NOV-2009			-				
SL 737-SL-78-041	, SERVICE LETTER					INFORMATIONAL	
		MOS					
27-MAY-1999			- (s)				
SL 737-SL-78-041 REV. A	AUTO THROTTLE SWITCH PACK IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
17-SEP-1999			- (s)				
SL 737-SL-78-042	T/R INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
10-SEP-1999			- (s)				
SL 737-SL-78-042 REV. A	T/R INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS, SERVICE LETTER						
		MOS					
			- (s)				
SL 737-SL-78-042 REV. B	THRUST REVERSER INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS, SERVICE LETTER						
		MOS					
11-MAR-2002			- (s)				
SL 737-SL-78-042 REV. C	THRUST REVERSER INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS (SUPERSEDED BY SL 737-SL-78-042 REV. D), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

EFTA00618673

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-042 REV. D	THRUST REVERSER INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS (SUPERSEDED BY SL 737-SL-78-042 REV. E), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-78-042 REV. E	THRUST REVERSER INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS (SUPERSEDED BY SL 737-SL-78-042 REV. F), SERVICE LETTER					SUPERSEDED	
		MOS	-				
SL 737-SL-78-042 REV. F	THRUST REVERSER INSULATION BLANKET INTERFERENCE WITH ENGINE COMPONENTS, SERVICE LETTER					RECOMMENDED	
16-APR-2014		MOS	-				
SL 737-SL-78-044 REV. B	INCORRECT DOUBLE FLUSH RIVET INSTALLATION ON FAN DUCT COWL AND THRUST REVERSER AFT COWL, SERVICE LETTER					INFORMATIONAL	
10-JUL-2001		MOS	- (s)				
SL 737-SL-78-045	THRUST REVERSER SYSTEM - HINGE FITTING MIS-LOCATION, EXAMINATION AND RE-ALIGNMENT, SERVICE LETTER					INFORMATIONAL	
14-AUG-2000		MOS	- (s)				
SL 737-SL-78-048	THRUST REVERSER BLOCKER DOOR SUPPORT SEPARATION, SERVICE LETTER					INFORMATIONAL	
24-SEP-2001		MOS	- (s)				
SL 737-SL-78-048 REV. A	THRUST REVERSER BLOCKER DOOR SUPPORT SEPARATION, SERVICE LETTER					INFORMATIONAL	
25-FEB-2004		MOS	-				
SL 737-SL-78-048 REV. B	THRUST REVERSER BLOCKER DOOR SUPPORT SEPARATION, SERVICE LETTER						COMPLIED WITH
05-MAY-2005		MOS	-		07-SEP-2005 2202:24		
		AFL			541		
SL 737-SL-78-048 REV. C	THRUST REVERSER BLOCKER DOOR SUPPORT SEPARATION, SERVICE LETTER					INFORMATIONAL	
14-SEP-2005		MOS	-				
SL 737-SL-78-048 REV. D	THRUST REVERSER BLOCKER DOOR SUPPORT SEPARATION, SERVICE LETTER						
08-DEC-2005		MOS	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-049	TROUBLESHOOTING OF THRUST REVERSER SYSTEM ANOMALITIES, SERVICE LETTER						
		MOS					
06-FEB-2002			- (s)				
SL 737-SL-78-049 REV. A	TROUBLESHOOTING OF THRUST REVERSER SYSTEM ANOMALIES, SERVICE LETTER					INFORMATIONAL	
		MOS					
16-APR-2002			- (s)				
SL 737-SL-78-050	THRUST REVERSER INSULATION BLANKET REPAIRS (SUPERSEDED BY SL 737-SL-78-050 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-050 REV. A	THRUST REVERSER INSULATION BLANKET REPAIRS, SERVICE LETTER					RECOMMENDED	
		MOS					
11-NOV-2013			-				
SL 737-SL-78-051	THRUST REVERSER CASCADE ASSEMBLY INSTALLATION ANOMALIES, SERVICE LETTER						
		MOS	6 (s)				
15-MAR-2004							
SL 737-SL-78-052	THRUST REVERSER AFT WEB TORQUE BOX CRACKING, SERVICE LETTER					INFORMATIONAL	
		MOS					
02-JAN-2004			-				
SL 737-SL-78-052 REV. A	THRUST REVERSER AFT WEB TORQUE BOX CRACKING, SERVICE LETTER						
		MOS					
02-MAY-2005			-				
SL 737-SL-78-052 REV. B	TRHUST REVERSER AFT WEB TORQUE BOX CRACKING, SERVICE LETTER						
		MOS					
04-MAY-2006			-				
SL 737-SL-78-053	THRUST REVERSER BLOCKER DOOR WEAR PAD SEPARATION, SERVICE LETTER					INFORMATIONAL	
		MOS					
24-MAR-2004			-				
SL 737-SL-78-053 REV. A	THRUST REVERSER BLOCKER DOOR WEAR PAD SEPARATION, SERVICE LETTER						COMPLIED WITH
		MOS		28-SEP-2009			
17-OCT-2007			-	3378:04			
		AFL		812			
SL 737-SL-78-054	THRUST REVERSER BLOCKER DOOR COVER IMPROVEMENTS, SERVICE LETTER					INFORMATIONAL	
		MOS					
13-APR-2004			-				

© Camp Systems

EFTA00618675

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-054 REV. A	THRUST REVERSER BLOCKER DOOR COVER IMPROVEMENTS, SERVICE LETTER						
		MOS					
01-MAR-2005			-				
SL 737-SL-78-055	NUMBER 2 ENGINE THRUST REVERSER INDICATION ANOMALIES - IMPROVED W5160 WIRE ROUTING, SERVICE LETTER					INFORMATIONAL	
		MOS					
07-MAR-2005			-				
SL 737-SL-78-055 REV. A	NUMBER 2 ENGINE THRUST REVERSER INDICATION ANOMALIES - IMPROVED W5160 WIRE ROUTING., SERVICE LETTER						
		MOS					
29-APR-2005			-				
SL 737-SL-78-056	IMPROVED THRUST REVERSER TRANSLATING SLEEVE MAIN TRACK SEAL, SERVICE LETTER						
		MOS					
14-SEP-2005			-				
SL 737-SL-78-056 REV. A	IMPROVED THRUST REVERSER TRANSLATING SLEEVE MAIN TRACK SEAL, SERVICE LETTER						
		MOS					
28-MAR-2006			-				
SL 737-SL-78-056 REV. B	IMPROVED THRUST REVERSER TRANSLATING SLEEVE MAIN TRACK SEAL, SERVICE LETTER						
		MOS					
19-FEB-2009			-				
SL 737-SL-78-057	THRUST REVERSER SYNC-SHAFT TUBE IMPROVEMENT, SERVICE LETTER						
		MOS					
18-APR-2006			-				
SL 737-SL-78-057 REV. A	THRUST REVERSER SYNC-SHAFT TUBE IMPROVEMENT, SERVICE LETTER						
		MOS					
06-DEC-2006			-				
SL 737-SL-78-058	AVAILABILITY OF THRUST REVERSER BLOCKER DOOR DRAG LINK SPHERICAL LINER BEARING BACB10ES06AG, SERVICE LETTER						
		MOS					
09-JUN-2006			-				
SL 737-SL-78-059	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE, SERVICE LETTER						
		MOS					
30-JUN-2006			-				

© Camp Systems

EFTA00618676

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-059 REV. A	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE, SERVICE LETTER						
		MOS					
09-NOV-2006			-				
SL 737-SL-78-059 REV. B	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE, SERVICE LETTER						
		MOS					
30-APR-2008			-				
SL 737-SL-78-059 REV. C	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE, SERVICE LETTER						
		MOS					
24-OCT-2008			-				
SL 737-SL-78-059 REV. D	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE (SUPERSEDED BY SL 737-SL-78-059 REV. E), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-059 REV. E	AVAILABILITY OF A NEW THRUST REVERSER HYDRAULIC CONTROL VALVE MODULE, SERVICE LETTER					RECOMMENDED	
		MOS					
30-JUN-2011			-				
SL 737-SL-78-060	CFM56-7B ENGINE PRIMARY EXHAUST NOZZLE FENCE CRACKING, SERVICE LETTER						
		MOS					
29-AUG-2006			-				
SL 737-SL-78-060 REV. A	CFM56-7B ENGINE PRIMARY EXHAUST NOZZLE FENCE CRACKING, SERVICE LETTER						
		MOS					
13-JUL-2007			-				
SL 737-SL-78-060 REV. B	CFM56-7B ENGINE PRIMARY EXHAUST NOZZLE FENCE CRACKING, SERVICE LETTER						
		MOS					
03-OCT-2007			-				
SL 737-SL-78-061	THRUST REVERSER OPENING ACTUATOR HEAT TREATMENT DISCLOSURE, SERVICE LETTER						
		MOS					
28-NOV-2007			-				
SL 737-SL-78-061 REV. A	THRUST REVERSER OPENING ACTUATOR HEAT TREATMENT DISCLOSURE, SERVICE LETTER						
		MOS					
08-JUL-2008			-				

© Camp Systems

EFTA00618677

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-062	AFT FAIRING RIVET TAILS CONTACTING HINGE BEAM, SERVICE LETTER						
		MOS					
27-JUL-2007			-				
SL 737-SL-78-062 REV. A	AFT FAIRING RIVET TAILS CONTACTING HINGE BEAM, SERVICE LETTER						COMPLIED WITH
		MOS		14-FEB-2008			
21-JAN-2008			-	3151:22			
		AFL		746			
SL 737-SL-78-062 REV. B	AFT FAIRING RIVET TAILS CONTACTING HINGE BEAM, SERVICE LETTER					RECOMMENDED	
		MOS					
12-MAY-2009			-				
SL 737-SL-78-062 REV. C	AFT FAIRING RIVET TAILS CONTACTING HINGE BEAM, SERVICE LETTER					RECOMMENDED	
		MOS					
30-OCT-2009			-				
SL 737-SL-78-063	THRUST REVERSER OVERHAUL PROGRAM GUIDELINES (SUPERSEDED BY SL 737-SL-78-063 REV. A) , SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-063 REV. A	THRUST REVERSER OVERHAUL PROGRAM GUIDELINES, SERVICE LETTER					RECOMMENDED	
		MOS					
22-APR-2011			-				
SL 737-SL-78-065	IMPROVED AUTOTHROTTLE SWITCHPACK (SUPERSEDED BY SL 737-SL-78-065 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-065 REV. A	IMPROVED AUTOTHROTTLE SWITCHPACK, SERVICE LETTER					RECOMMENDED	
		MOS					
08-JUN-2011			-				
SL 737-SL-78-067	UNDER-TORQUED FASTENERS INSTALLED ON THRUST REVERSER HINGE BEAM FAIRING, SERVICE LETTER					RECOMMENDED	
		MOS					
13-JUL-2009			-				
SL 737-SL-78-068	THRUST REVERSER INTERCHANGEABILITY (SUPERSEDED BY SL 737-SL-78-068 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-068 REV. A	THRUST REVERSER INTERCHANGEABILITY, SERVICE LETTER					RECOMMENDED	
		MOS					
16-MAR-2011			-				
SL 737-SL-78-069	THRUST REVERSER LATCH BEAM FAIRING MISSING SEALANT, SERVICE LETTER					RECOMMENDED	
		MOS					
05-NOV-2009			-				
SL 737-SL-78-069 REV. A	THRUST REVERSER LATCH BEAM FAIRING MISSING SEALANT, SERVICE LETTER					RECOMMENDED	
		MOS					
07-JAN-2010			-				
SL 737-SL-78-070	THRUST REVERSER CONTROL VALVE MODULE - QUALITY DISCLOSURE, SERVICE LETTER					RECOMMENDED	
		MOS					
15-MAR-2010			-				
SL 737-SL-78-071	THRUST REVERSER LVDT IMPROVEMENT (SUPERSEDED BY SL 737-SL-78-071 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-071 REV. A	THRUST REVERSER LVDT IMPROVEMENT, SERVICE LETTER					RECOMMENDED	
		MOS					
21-JAN-2011			-				
SL 737-SL-78-073	"ALTERNATE SPLIT-LINE FASTENERS FOR CFM56-7B EXHAUST PRIMARY PLUG" (SUPERSEDED BY SL 737-SL-78-073 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				
SL 737-SL-78-073 REV. A	ALTERNATE SPLIT-LINE FASTENERS FOR CFM56-7B EXHAUST PRIMARY PLUG, SERVICE LETTER					RECOMMENDED	
		MOS					
27-FEB-2014			-				
SL 737-SL-78-074	PIP EXHAUST RETROFIT SERVICE BULLETINS 737-78-1089 AND 737-54-1047 PRELIMINARY PLANNING INFORMATION, SERVICE LETTER					RECOMMENDED	
		MOS					
09-JAN-2012			-				
SL 737-SL-78-076	THRUST REVERSER BLOCKER DOOR SUPPORT LOOSE OR MISSING SCREWS (SUPERSEDED BY SL 737-SL-78-076 REV. A), SERVICE LETTER					SUPERSEDED	
		MOS					
			-				

© Camp Systems

EFTA00618679

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 737-SL-78-076 REV. A	THRUST REVERSER BLOCKER DOOR SUPPORT LOOSE OR MISSING SCREWS, SERVICE LETTER					RECOMMENDED	
		MOS					
02-JUN-2014			-				
SL 737-SL-78-077	THRUST REVERSER PART MARKING RECOMMENDATIONS UNDER FAA AD 2012-05-02, SERVICE LETTER					RECOMMENDED	
		MOS					
20-JUN-2014			-				
SL 737-SL-80-001	STARTING, GENREAL, START SYSTEM, RELIABILITY IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-DEC-1980			- (s)				
SL 737-SL-80-001 REV. A	STARTING, GENREAL, START SYSTEM, RELIABILITY IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	
		MOS					
15-JUN-2000			- (s)				
SL 737-SL-80-018	ENGINE PNEUMATIC START VALVE QUALITY DISCLOSURE, SERVICE LETTER						
		MOS	6 (s)				
11-OCT-2004							
SL BBJ-28-17A	AUXILIARY FUEL SYSTEM ALERT AND MAINTENANCE MESSAGES, SERVICE LETTER						
		MOS					
			-				
SL BBJ-28-6	TANK RAIL MODIFICATION, SERVICE LETTER						
		MOS					
20-FEB-2000			-				
SL BBJ2-28-04A	AUXILIARY FUEL SYSTEM ALERT AND MAINTENENACE MESSAGES, SERVICE LETTER						
		MOS					
			-				
SL ST00936NY-28-SL-001	CENTER WING FUEL TANK REFUEL LINE B-NUT TORQUE, SERVICE LETTER						COMPLIED WITH
		MOS			18-AUG-2009		
15-JUN-2005			-		3378:04		
		AFL			812		
SL ST00936NY-D-26-SL-007	INSTRUCTIONS FOR BOEING SERVICE BULLETIN 737-26-1121, REV 1, SERVICE LETTER						
		MOS					
			-				
SL ST01384NY-28-SL-001	CENTER WING FUEL TANK REFUEL LINE B-NUT TORQUE, SERVICE LETTER						NOT APPLICABLE
		MOS					
15-JUN-2005			-				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
VSB 174080-35-04 REV 000	OXYGEN - PASSENGER OXYGEN SYSTEM MASK IN-LINE FLOW INDICATOR REPLACEMENT, VENDOR SERVICE BULLETIN					MANDATORY	
		MOS					
06-SEP-2010			-				
VSB 3289562-36-1909	PNEUMATIC - FOUR INCH DIAMETER PRECOOLER CONTROL VALVE - REWORK FOUR INCH DIAMETER PRECOOLER CONTROL VALVE, PN 3289562-7 TO PN 3289562-5, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-APR-2014			-				
VSB 3289562-36-1911	PNEUMATIC - FOUR INCH DIAMETER PRECOOLER CONTROL VALVE - REWORK FOUR INCH DIAMETER PRECOOLER CONTROL VALVE (PCCV), PN 3289562-6 TO PN 3289562-5, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-APR-2014			-				
VSB 4091900-31-0005	INDICATING/RECORDING SYSTEMS - PHASE 3 DISPLAY UNIT - MODIFICATION (MOD) B TO PHASE 3 DISPLAY UNIT, PN 4091900-931 THRU -934, -941 THRU -944; REPLACE BOTH BACKLIGHT ASSEMBLY, PN 4091896-902, AND BACKLIGHT ELECTRONICS PRINTED BOARD ASSEMBLY (PBA), PN 4091894-1002, WITH NEW PART NUMBERS IF ONE IS UNSERVICEABLE AND CANNOT BE REPAIRED OR REPLACED WITH THE SAME PART NUMBER, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-MAR-2014			-				
VSB 4091900-31-0006	INDICATING/RECORDING SYSTEMS - PHASE 3 DISPLAY UNIT - MODIFICATION (MOD) C TO PHASE 3 DISPLAY UNIT, PN 4091900-931 THRU -934, -941 THRU -944; IMPROVE DISPLAY UNIT CONTROLLER (DUC) SEQUENCER FIRMWARE IN DETECTING WHEN LIGHT EMITTING DIODE (LED) STRING IS OUT, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-MAR-2014			-				
VSB 930-3000/3001-34-1	NAVIGATION - DA-1A/DA-1B ANTENNA DRIVE ASSEMBLIES - MODIFICATION (MOD) OF THE DA-1A/DA-1B ANTENNA DRIVE ASSEMBLIES, PN 930-3000-001 AND PN 930-3001-001; REPLACEMENT OF THE TRANSMITTER RECEIVER (TR)/GIMBAL DRIVE INTERCONNECT CABLE ASSEMBLIES AND THE CLOCK SPRING CLAMPS (SUPERSEDED BY SB 930-3000/3001-34-1 R1), VENDOR SERVICE BULLETIN					SUPERSEDED	
		MOS					
			-				
VSB R1 930-3000/3001-34-1	NAVIGATION - DA-1A/DA-1B ANTENNA DRIVE ASSEMBLIES - MODIFICATION (MOD) OF THE DA-1A/DA-1B ANTENNA DRIVE ASSEMBLIES, PN 930-3000-001 AND PN 930-3001-001; REPLACEMENT OF THE TRANSMITTER RECEIVER (TR)/GIMBAL DRIVE INTERCONNECT CABLE ASSEMBLIES AND THE CLOCK SPRING CLAMPS, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
15-APR-2014			-				
VSB 964-0452-23-41	COMMUNICATION - XK516D HF RADIO SYSTEM - UNIT MODIFICATION (MOD) 49 TO XK516D1 HIGH FREQUENCY (HF) TRANSCEIVER (TRANSCEIVER), PN 964-0452-011, -022, OR -042; DISABLE TWO DISCRETE COUPLER FAULT INPUT LINES TO REDUCE NUISANCE "COUPLER NOGO" FAULT MESSAGES (BOEING), VENDOR SERVICE BULLETIN					OPTIONAL	
		MOS					
08-MAY-2014			-				

© Camp Systems

EFTA00618681

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
VSB TPA-100-34-01 R9	NAVIGATION - TPA-100 TCAS PROCESSOR - TPA-100 TCAS PROCESSOR, TPA-100A, PN 940-0300-001, PN 940-0330-001, PN 940-0331-001, PN 940-0400-001, PN 940-0430-001, PN 940-0431-001, PN 941-1431-001, AND TPA-100B, PN 940-0351-001, PN 940-0351-010, PN 940-0451-001, PN 940-0451-010; TO PROVIDE ACCEPTANCE TEST PROCEDURE (ATP) SOFTWARE UPGRADE TO PN 998-3449-537 FOR RETURN-TO-SERVICE (RTS) TESTING OF THE TPA-100 TCAS PROCESSOR, VENDOR SERVICE BULLETIN	MOS				RECOMMENDED	
05-JUN-2014			-				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-5180/3800702-1								
SB	131-49-8084	APU - AUXILIARY AIRBORNE POWER - GAS TURBINE ENGINE - REPLACE THE STARTER/GENERATOR, PN 28B545-7A, -7B, OR -7C, WITH PN 28B545-9A, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	27-JUL-2012			-				
SB	131-49-8122	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT THE STARTER/GENERATOR, PN 28B545-7 AND -9, AND REWORK AS NECESSARY (SUPERSEDED BY SB 131-49-8122 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS					
			MSC	-				
SB	131-49-8122 R1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT THE STARTER/GENERATOR, PN 28B545-7 AND -9, AND REWORK AS NECESSARY ON THE 131-9[B] APU, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	09-JUL-2014		MSC	A/R				
SB	131-49-8128	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - APPROVE THE USE OF IGNITION UNIT, PN 3888058-5, IN PLACE OF IGNITION UNIT, PN 3888058-7, FOR THE 131-9[B] AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					OPTIONAL	
			MOS					
	07-FEB-2014		MSC	-				
SB	2024215	APU - TESTING - DATA MEMORY MODULE (DMM) READER - PN 2024215-2; IMPROPER FIRMWARE PROGRAMMING WITH PN 2024215-2, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	09-FEB-2011		MSC	-				
SB	24-4232	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF STARTER/GENERATOR, PN 28B545-9 - REPLACEMENT OF ROTOR, SERVICE BULLETIN					SUPERSEDED	
			MOS					
	06-DEC-2012		MSC	-				
SB	24-4232 R1	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF STARTER/GENERATOR, PN 28B545-9 - REPLACEMENT OF ROTOR, SERVICE BULLETIN					SUPERSEDED	
			MOS					
	21-DEC-2012		MSC	-				
SB	24-4232 R2	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF STARTER/GENERATOR, PN 28B545-9 - REPLACEMENT OF ROTOR, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	10-JAN-2013		MSC	DUE (s)				
SB	24-4232 R3	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF STARTER/GENERATOR, PN 28B545-9 - REPLACEMENT OF ROTOR, SERVICE BULLETIN						
			MOS					
			MSC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 28B545-24-4231	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF THE STARTER/GENERATOR FROM PN 28B545-7 STYLE C TO PN 28B545-9 STYLE A, SERVICE BULLETIN						
		MOS					
26-JUL-2012		MSC	-				
SB 28B545-24-4233	APU - ELECTRICAL POWER - STARTER/GENERATOR - MODIFICATION OF STARTER/GENERATOR, PN 28B545-7 AND -9 - REPLACEMENT OF STATOR HOUSING ASSEMBLY, PN 6430800-4, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-JUL-2014		MSC	-				
SB 3291238-49-7032	APU - AIRBORNE AUXILIARY POWER - 3.0 INCH DIAMETER SURGE CONTROL VALVE - INSPECTION OF THE CHROME PLATING ON THE BUTTERFLY SHAFT, PN 3180688-1, USED ON THE 3.0 INCH DIAMETER SURGE CONTROL VALVE, PN 3291238-2, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
22-APR-2014		MSC	-				
SB 49-0001	APU - FCU INSPECTION FOR MISSING LOAD SPRING, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-0002	APU - INCORPORATE AN IMPROVED FCU TORQUE MOTOR METERING VALVE, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-2376	APU - , SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-2377	APU - , SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7031	APU - INSPECT 3291238-2 SCV FOR THE UPPER BUTTERFLY SHAFT BUSHING, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7365	APU - REPLACE IGV CLEVIC ASSY AND BOLT TO ELIMINATE CAPTIVE BOLT DESIGN, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7366	APU - REPLACE IGV ASSEMBLY 3810821-4 WITH 3810821-5 TO ELIMINATE CAPTIVE BOLT DESIGN, SERVICE BULLETIN						
		MOS					
		MSC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 49-7373	APU - REPL COMP COUP SHAFT P/N 3822510-1 W/-2 TO ELIMINATE A POTENTIAL TOLERANCE STACK CONDITION THAT WOULD RESULT IN, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7431	APU - REWORK UPPER AND LOWER INLET PLENUM TO ELIMINATE RIVETED GROUND STRAPS, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7476	APU - REWORK TURBINE BEARING SUPPORT AND REAR BEARING SEAL RETAINER FOR SOFT HYDRAULIC MOUNT, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7480	APU - REWORK OR REPLACE DRIVEN COMPRESSOR BEARING HOUSING AND COUPLING SHAFT FOR IMPROVED L/C SEAL CAVITY DRAINAGE., SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7483	APU - RPL/RWK SURGE DUCT P/N 3885003-1 TO 3885003-2, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7513	APU - INSTALL MS25083-5BB7 GROUND STRAP TO IMPROVE ELECTRICAL PATH BETWEEN PERFORATED INLET HOUSING AND MAIN APU ELECTRICAL GROUND, SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7527	APU - REPLACE EDUCTOR HOUSING WITH NEW IGNITION UNIT BRACKET THAT ALLOWS ELIMINATION OF 3617110-2 IGNITION UNIT ADAPTER BRACKET., SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7541R1	APU - INSTL NEW 3884980-3 & 3884984-3 STATIC/TOTAL PRESS TUBES HAVING DRAIN HOLES ADDED CLEANING PROC TO REMOVE ALL CONTAM, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7561	APU - RPL TRBN SEAL GSKT P/N 3844707-1 W/ 3844707-2, SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7577	APU - PROVIDE VE HARDWARE-PWR SECTION ASSY P/N 3801103-2 REPLACES 3801103-1, SERVICE BULLETIN						
		MOS					
		MSC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 49-7597	APU - PROVIDE COST REDUCE TURBINE BRG CAVITY DESIGN-PWR SECT ASSY P/N 3801103-3 REPLACES 3801103-2, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7667	APU - PROVIDE ADDITIONAL RETENTION FOR PLUG P/N AS9902-6 AND AS169J6L REPLACES MS9901-6, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
		MSC	-	2778			
		APUS		2287			
SB 49-7688	APU - ENHANCE PRODUCIBILITY AND COSTS-FCU P/N 441921-5 REPLACES 4491921-4, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7743	APU - IMPROVES FIELD RELIABILITY-OIL COOLER P/N 160564-2 REPLACES 160564-1, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7776	APU - IMPROVE PERFORMANCE AND RELIABILITY-ROTATING GRP P/N 3822505-8 REPLACES P/N 3822505-7, SERVICE BULLETIN						
		MOS					
		MSC	-				
SB 49-7857R1	APU - REPLACE/REWORK FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840303-1, TO FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840160-7, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-DEC-2005		MSC	-				
SB 49-7860R1	APU - REPLACE FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840303-1, WITH FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840160-8, REPLACE/REWORK FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840160-5, WITH/TO FIRST STAGE TURBINE ROTOR ASSEMBLY, PART NO. 3840160-8, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-DEC-2005		MSC	-				
SB 49-7881	APU - , SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7903	APU - REWORK ENGINE WIRING HARNESS, PN 3888449-1, TO PN 3888449-2 (SUPERSEDED BY SB 3888449-49-7903 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		MSC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 49-7903 R1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK ENGINE WIRING HARNESS, PN 3888449-1 TO PN 3888449-2, SERVICE BULLETIN					RECOMMENDED	
		MOS					
05-NOV-2013		MSC	-				
SB 49-7953	APU - , SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7971 R3	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE FIRST STAGE TURBINE ASSEMBLY, PN 3840160-5, -7, -8 OR PN 3840303-1, AND STATIONARY SEAL ASSEMBLY, PN 3844738-5, WITH FIRST STAGE TURBINE ASSEMBLY, PN 3840310-3 AND STATIONARY SEAL ASSEMBLY, PN 3844738-6, SERVICE BULLETIN					RECOMMENDED	
		MOS					
26-NOV-2012		MSC	-				
SB 49-7988	APU - , SERVICE BULLETIN						COMPLIED WITH
		MOS		25-JUN-2010			
		MSC	-	3001			
		APUS		2487			
SB 49-7997 R2	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN						
		MOS					
22-DEC-2010		MSC	-				
SB 49-7997 R3	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN						
		MOS					
16-JAN-2014		MSC	-				
SB 49-8023	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE FUEL DRAIN TUBE, PN 3883848-3 WITH FCU DRAIN TUBE ASSEMBLY, PN 3879078-1, SCV DRAIN TUBE ASSEMBLY, PN 3879078-2, IGV DRAIN TUBE ASSEMBLY, PN 3879078-3, FUEL DRAIN TUBE ASSEMBLY, PN 3879078-4, AND DRAIN TUBE ASSEMBLY, PN 3879078-5, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-OCT-2010		MSC	-				
SB 49-8027	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE INLET GUIDE VANE ACTUATOR, PN 3886188-2 WITH PN 3886188-3, SERVICE BULLETIN					OPTIONAL	
		MOS					
13-DEC-2010		MSC	-				
SB 49-8054	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE FLOW DIVIDER TEE, PN 3883830-1 WITH PN 3883830-2, SERVICE BULLETIN					OPTIONAL	
		MOS					
07-SEP-2011		MSC	-				

© Camp Systems

EFTA00618687

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 49-8065	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE DUPLEX BALL BEARING ASSEMBLY, MATCHED SET, PN 3822478-1, WITH PN 3822666-2, COMPRESSOR BEARING HOUSING, PN 3827265-4, WITH PN 3827265-8, COMPRESSOR BEARING RETAINER PLATE, PN 3827385-1, WITH PN 3827385-2, AND COMPRESSION SPRING WASHER, PN 3827075-1, WITH PN 791-548-9301. REMOVE BEARING DAMPER RING, PN 3827173-3, AND SPRING RETAINER, PN 3827074-4, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-JUN-2012		MSC	-				
SB 49-8065 R1	APU - GAS TURBINE ENGINE - REPLACE DUPLEX BALL BEARING ASSEMBLY, MATCHED SET, PN 3822478-1, WITH PN 3822666-2, COMPRESSOR BEARING HOUSING, PN 3827265-4, WITH PN 3827265-8, COMPRESSOR BEARING RETAINER PLATE, PN 3827385-1, WITH PN 3827385-2, AND COMPRESSION SPRING WASHER, PN 3827075-1, WITH PN 791-548-9301. REMOVE BEARING DAMPER RING, PN 3827173-3, AND SPRING RETAINER, PN 3827074-4, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-SEP-2012		MSC	-				
SB 49-8079	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACEMENT OF DISCREPANT DATA MEMORY MODULE (DMM), PN 3876287-1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JUN-2012		MSC	-				
SB 49-8079 R1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACEMENT OF DISCREPANT DATA MEMORY MODULE (DMM), PN 3876287-1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-NOV-2012		MSC	-				
SB 49-8091	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND INSPECT THE SECOND STAGE TURBINE ROTOR ASSEMBLY, PN 3840165-4, FOR LINEAR INDICATIONS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-NOV-2012		MSC					
		APUS	17450 (s)				
SB 49-8091 R1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND INSPECT THE SECOND STAGE TURBINE ROTOR ASSEMBLY, PN 3840165-4, FOR LINEAR INDICATIONS (SUPERSEDED BY SB 49-8091 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		MSC	- (s)				
SB 49-8091 R2	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND INSPECT THE SECOND STAGE TURBINE ROTOR ASSEMBLY, PN 3840165-4, FOR LINEAR INDICATIONS, SERVICE BULLETIN						
		MOS					
		MSC	-				
		APUS					
SB 49-8098	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACEMENT OF THE BEARING SET (TURBINE ROLLER BEARING), PN 3840242-1, WITH THE INCORRECT ROLLING ELEMENT MATERIAL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-NOV-2012		MSC	-				

© Camp Systems

EFTA00618688

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	49-8100	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE STARTER/GENERATOR ASSEMBLY, PN 28B545-9, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	10-DEC-2012		MSC	-				
SB	49-8100 R1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE STARTER/GENERATOR ASSEMBLY, PN 28B545-9, SERVICE BULLETIN					RECOMMENDED	
			MOS		(EFF)			
	19-DEC-2012		MSC	-				
SB	49-8100 R2	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE STARTER/GENERATOR ASSEMBLY, PN 28B545-9, SERVICE BULLETIN						
			MOS					
			MSC	-				
SIL	126 R3	APU - 131-9[B] WORKSCOPE PLANNING GUIDE (WPG), SERVICE INFORMATION LETTER						
			MOS					
	30-APR-2013		MSC	-				

© Camp Systems

EFTA00618689

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - 874437/CFM56-7B27/B3							
ASB 72-A0328	NO. 1 ENGINE - LOW PRESSURE TURBINE SHAFT - REDUCED INTERVAL FOR AFT SUMP MCD OR DMS INSPECTION, ALERT SERVICE BULLETIN						
		MOS					
12-MAR-2002		MSC	-				
ASB 72-A0328 R1	NO. 1 ENGINE - LOW PRESSURE TURBINE SHAFT - REDUCED INTERVAL FOR AFT SUMP MCD OR DMS INSPECTION, ALERT SERVICE BULLETIN						
		DAYS	1 (s)				
12-MAR-2002		HRS/MSC					
		ENC					
ASB 72-A0329	NO. 1 ENGINE - LOW PRESSURE TURBINE SHAFT - REPLACEMENT OF NO.4 ROLLER BEARING., ALERT SERVICE BULLETIN						
		MOS					
12-MAR-2002		HRS/MSC	-				
		ENC					
ASB 73-A0026	NO. 1 ENGINE - INTRODUCITON OF SOFTWARE VERSION 7.B.J (7B3A), ALERT SERVICE BULLETIN						
		MOS					
15-JAN-1999		HRS/MSC	-				
		ENC					
ASB 73-A0034 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH NEW FILTER COVER, ALERT SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0000	NO. 1 ENGINE - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B SERVICE BULLETINS, SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0000 R1	NO. 1 ENGINE - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B (SUPERSEDED BY 72-0000 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0000 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B SERVICE BULLETINS, SERVICE BULLETIN					INFORMATIONAL	
		MOS					
11-MAY-2011		HRS/MSC	-				
		ENC					
SB 72-0001	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	- INFORMATION ONLY
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0001 R1	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0001 R2	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION., SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0001 R3	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	
27-JUL-2006		MOS HRS/MSC ENC	- 				
SB 72-0001 R4	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION , SERVICE BULLETIN						
25-MAY-2007		MOS HRS/MSC ENC	- 				
SB 72-0001 R5	NO. 1 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0002	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS HRS/MSC ENC	- 				
SB 72-0002 R1	NO. 1 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0003	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						- PRODUCT IMPROVEMENT
		MOS HRS/MSC ENC	- 				
SB 72-0003 R1	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R10	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0003 R2	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R3	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618691

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0003 R4	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R5	NO. 1 ENGINE - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R6	NO. 1 ENGINE - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0003 R7	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- 				
SB 72-0003 R8	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R9	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS (SUPERSEDED BY 72-0003 R10), SERVICE BULLETIN					SUPERSEDED	
10-MAR-2011		MOS HRS/MSC ENC	- 				
SB 72-0004	NO. 1 ENGINE - INSTALLATION OF CERTIFIED CFM56-7B ENGINE NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0004 R1	NO. 1 ENGINE - CERTIFIED CFM56-7B ENGINE NAMEPLATE, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0005	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS HRS/MSC ENC	- 				
SB 72-0006 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0006 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0006 R3	NO. 1 ENGINE - CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0006 R4	NO. 1 ENGINE - CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0007 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0007 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0007 R3	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0007 R4	NO. 1 ENGINE - CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0008 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0008 R3	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0008 R4	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0008 R5	NO. 1 ENGINE - CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618693

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0009	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F (7B2B), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R3	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R4	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0010 R3	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R4	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R5	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN					OPTIONAL	
17-FEB-2011		MOS HRS/MSC - ENC					
SB 72-0011 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0011 R3	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0011 R4	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS					
28-APR-2000		HRS/MSC	-				
		ENC					
SB 72-0012	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0013	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0014	NO. 1 ENGINE - NUT AND TORQUE CHANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0015	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0016	NO. 1 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
11-JUL-1997		HRS/MSC	-				
		ENC					
SB 72-0016 R1	NO. 1 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
05-AUG-1997		HRS/MSC	-	0			
		ENC		0			
SB 72-0017	NO. 1 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0017 R1	NO. 1 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0018	NO. 1 ENGINE - INCREASING OF BOLT LENGTH AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0018 R1	NO. 1 ENGINE - INCREASING OF BOLT LENGTH AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0018 R2	NO. 1 ENGINE - INCREASING OF LENGTH BOLT AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0019	NO. 1 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0020 R1	NO. 1 ENGINE - ADDITON OF A SPACER ON THE RETAINING CABLE OF THE IDENTIFICATION PLUG KIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0021	NO. 1 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0021 R10	NO. 1 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0021R1	NO. 1 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0022	NO. 1 ENGINE - MODIFICATION OF THE J10 WIRING HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0022 R1	NO. 1 ENGINE - MODIFICATION OF THE J10 WIRING HARNESS, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0093
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0023	NO. 1 ENGINE - INTERFERENCE BETWEEN THE BODY ACTUATOR AND THE LVDT SENSOR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0023 R1	NO. 1 ENGINE - INTERFERENCE BETWEEN THE BODY ACTUATOR AND THE LVDT SENSOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0024	NO. 1 ENGINE - REPLACEMENT OF BOLTS ON OIL SENSOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0024 R1	NO. 1 ENGINE - REPLACEMENT OF BOLTS ON OIL SENSOR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0025	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION CONNECTOR KITS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0025 R2	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION CONNECTOR KITS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0026 R1	NO. 1 ENGINE - REWORK OF SHROUD PAD, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0027	NO. 1 ENGINE - REPOSITIONING OF VBV HARNNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0028 R2	NO. 1 ENGINE - THRUST REVERSER KIT MODIFICATION OF INTERNAL VEE GROOVE AND FITTING SHROUDS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0029	NO. 1 ENGINE - REPLACEMENT OF BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0030 R1	NO. 1 ENGINE - MODIFICATION OF NAMEPLATE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0030 R2	NO. 1 ENGINE - MODIFICATION OF NAMEPLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0031	NO. 1 ENGINE - INTRODUCTION OF THE NEW PLATFORM FAN BLADE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0032	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN CASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0033	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0033 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0033 R2	NO. 1 ENGINE - , SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0034 R1	NO. 1 ENGINE - TURBINE CLEARANCE CONTROL VALVE SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0035	NO. 1 ENGINE - MODIFICATION OF BRACKET ASSY AND HARNESS J5 AND J6, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0101
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0035 R1	NO. 1 ENGINE - MODIFICATION OF BRACKET ASSY AND HARNESS J5 AND J6, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0036 R1	NO. 1 ENGINE - INSTALLATION OF A TUBE OIL DRAIN, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0037	NO. 1 ENGINE - REPLACEMENT OF ONE BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0038	NO. 1 ENGINE - MODIFICATION OF AXIAL LOAD LINK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0039 R2	NO. 1 ENGINE - INSTALLATION OF NEW BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0040 R1	NO. 1 ENGINE - MODIFICATION OF BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0040 R2	NO. 1 ENGINE - MODIFICATION OF BRACKET ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0041	NO. 1 ENGINE - DELETION OF BRACKETS ASSY FOLOWING PRECOOLER DEFLECTOR AST SIDE PANELS REMOVAL, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0042	NO. 1 ENGINE - HPTCC MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0043	NO. 1 ENGINE - INTRODUCTION OF NEW BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0044 R1	NO. 1 ENGINE - SUPPORT BRACKET IMPROVEMENTS FOR THE CJ9 HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0045 R2	NO. 1 ENGINE - REWORK OF SHROUD PAD OF STRUT N°4 ON "VEE GROOVE", SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0045 R3	NO. 1 ENGINE - REWORK OF SHROUD PAD OF STRUT N°4 ON "VEE GROOVE", SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0046	NO. 1 ENGINE - MODIFICATION OF TWO BRACKETS ON BOEING FUEL SUPPLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0047	NO. 1 ENGINE - NEW HPT SHROUD RETAINING CLIP INTRODUCTION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0047 R1	NO. 1 ENGINE - NEW HPT SHROUD RETAINING CLIP INTRODUCTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0047 R2	NO. 1 ENGINE - HPT AND LPT NOZZLE STAGE 1 - INTRODUCTION OF NEW LOW STRESS C-CLIPS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0048 R1	NO. 1 ENGINE - ANTI-ICE AND DRAIN MANIFOLD BRACKET REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0098
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0049 R1	NO. 1 ENGINE - MODIFICATION OF HARNESS MW0304, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0050	NO. 1 ENGINE - MODIFICATION OF HARNESS MW0301, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0051	NO. 1 ENGINE - GENERAL (72-00-00) SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0052	NO. 1 ENGINE - INSPECTION OF J5, J6, J10, MW0301,MW0302, AND MW0304 HARNESSES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0053 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG 52X CWM-91X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0054	NO. 1 ENGINE - REPLACEMENT OF T49.5 BRACKETS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0054R1	NO. 1 ENGINE - REPLACEMENT OF T49.5 BRACKETS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0055 R1	NO. 1 ENGINE - CHANGE OF HARDWARE FROM CORE ASSEMBLY TO ENGINE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0056	NO. 1 ENGINE - VBV FUEL MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0057	NO. 1 ENGINE - INTRODUCTION OF NEW HPT NOZZLE SEGMENTS, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0099
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0058	NO. 1 ENGINE - INTRODUCTION OF NEW FRONT FLANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0059	NO. 1 ENGINE - NEW VSV FUEL MANIFOLD LOOP CLAMP BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0060	NO. 1 ENGINE - REPLACEMENT OF OVERHEAT DETECTOR BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0060 R1	NO. 1 ENGINE - REPLACEMENT OF OVERHEAT DETECTOR BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0061	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 32X,41X,52X,91X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0062	NO. 1 ENGINE - INTRODUCTION OF A REPLACEABLE CUSHION FOR HINGED CLAMP (ELECTRICAL HARNESSES ATTACHMENT), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0063 R1	NO. 1 ENGINE - REPLACEMENT OF HOLD OPEN ROD BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0064 R1	NO. 1 ENGINE - REPLACEMENT OF TWO BRACKETS ATTACHING THE J12 HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0065	NO. 1 ENGINE - INTRODUCTION OF A NEW SOURCE FOR THE VIBRATION BRG1, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0066	NO. 1 ENGINE - INTRODUCTION OF NEW SOURCE FOR SENSOR VIBRATION FFCC, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0067 R1	NO. 1 ENGINE - INTRODUCTION OF A HEAT SHIELD BETWEEN THE OIL PRESSURE SENSOR AND THE OIL DISTRIBUTION BLOCK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 91X NA-SUPERSEDED 72-0151 - 23X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0068	NO. 1 ENGINE - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0068 R1	NO. 1 ENGINE - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0068 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN					INFORMATIONAL	
		MOS					
03-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0069	NO. 1 ENGINE - INTRODUCTION/REWORK OF TWO PS3 BRACKETS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0070 R1	NO. 1 ENGINE - ECS DUCT BRACKET REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0071	NO. 1 ENGINE - MODIFICATION OF BRACKET ATTACHING THE MW0312, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0072	NO. 1 ENGINE - INTRODUCTION OF A PAINT-MARKED COVER ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0073	NO. 1 ENGINE - DRAIN TUBE SUPPORT CHANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0074	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0074 R1	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 41X,91X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

EFTA00618702

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0075	NO. 1 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE AND IGNITER HARDWARE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0076	NO. 1 ENGINE - INTRODUCTION OF NEW IDG OIL COOLER WITH A NEW GOEMETRY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0077	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0077 R2	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0078 R1	NO. 1 ENGINE - INTRODUCTION OF LONGER SCREWS ON LPTACC PANEL, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0079	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R1	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0079 R2	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R3	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R4	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R5	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0079 R6	NO. 1 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN					RECOMMENDED	
23-NOV-2010		MOS HRS/MSC ENC	- 				
SB 72-0080	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0081	NO. 1 ENGINE - CMF56-7B ENGINE CONVERSION TO CFM56-7B20/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0081 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0082	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0082 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0083	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0083 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0084	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0084 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0085	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0085 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/2, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0086	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0086 R1	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
04-DEC-2007		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0087	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0103
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0088	NO. 1 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0088 R1	NO. 1 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0088 R2	NO. 1 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0089	NO. 1 ENGINE - LPT MODULE (72-54-00)-INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 53X,54X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0089 R1	NO. 1 ENGINE - LPT MODULE (72-54-00)-INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0089 R2	NO. 1 ENGINE - REWORK OF OLD LPT STAGE 1 NOZZLE SEGMENT OR INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND NEW STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
27-JAN-2006		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0089 R3	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REWORK OF OLD LPT STAGE 1 NOZZLE SEGMENT OR INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND NEW STAGE 1 SEAL-SEGMENT, SERVICE BULLETIN						
10-APR-2009		MOS HRS/MSC ENC	- 				
SB 72-0090	NO. 1 ENGINE - REINFORCEMENT OF FORWARD MOUNTING LUG OF THE LPT COOLING MANIFOLDS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 	16-DEC-1998 0 0			
SB 72-0091	NO. 1 ENGINE - REMOVAL OF EXTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU107, 874-110 THRU 112, 874-115 AND -116, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0091 R1	NO. 1 ENGINE - REMOVAL OF EXTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU107, 874-110 THRU 112, 874-115 AND -116, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0092	NO. 1 ENGINE - INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- 	16-DEC-1998 0 0			
SB 72-0092 R1	NO. 1 ENGINE - INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0093	NO. 1 ENGINE - INTRODUCTION OF NEW MOUNT HARNESS WITH J9, J10, MW0311, MW0315, MW0316 ASSOCIATED HARNESSES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- 	16-DEC-1998 0 0			
SB 72-0094	NO. 1 ENGINE - INTRODUCTION OF NEW LPT NOZZLE STAGE 2, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- 	16-DEC-1998 0 0			
SB 72-0094 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LPT NOZZLE STAGE 2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0095	NO. 1 ENGINE - INTRODUCTION OF LARGE BORE TRANSIENT BLEED VALVE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- 	16-DEC-1998 0 0			

© Camp Systems

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0096	NO. 1 ENGINE - INTRODUCTION OF HPT NOZZLE SUPPORT WITH IMPROVED PINS, SERVICE BULLETIN						NOT APPLICABLE
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0097 R1	NO. 1 ENGINE - INTRODUCTION OF LONGER BOLTS ON ENGINE AND CORE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0098	NO. 1 ENGINE - INTRODUCTION OF A NEW AIR DUCT SUPPORT BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0099	NO. 1 ENGINE - INTRODUCTION OF NEW HPT NOZZLE SEGMENTS WITH INNER SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0100	NO. 1 ENGINE - CFM56-7B ENGINE NAMEPLATE MARKING, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0101	NO. 1 ENGINE - NEW ROUTING OF J5 AND J6 HARNESSES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0102	NO. 1 ENGINE - INTRODUCTION OF DAC HPT ROTOR ASSEMBLY FOR USE ON THE SAC HPT ROTOR ASSEMBLY, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0103	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN						
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0103 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0103 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN					RECOMMENDED	
	17-FEB-2011		MOS					
			HRS/MSC	-				
			ENC					
SB	72-0104	NO. 1 ENGINE - INTRODUCTION OF A NEW PAINT ON LPT SHAFT, SERVICE BULLETIN						- SUPERSEDED SB-PENDING
			MOS					
			HRS/MSC	-				
			ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0104 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW PAINT ON LPT SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0105	NO. 1 ENGINE - ARRANGEMENT OF VBV TURNBUCKLE, BELLCRANK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106	NO. 1 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R2	NO. 1 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R3	NO. 1 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R4	NO. 1 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
14-AUG-2007		MOS HRS/MSC - ENC					
SB 72-0107	NO. 1 ENGINE - REPLACEMENT CLAMP FOR DAC AFT SUMP OIL SUPPLY TUBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0108	NO. 1 ENGINE - NEW VBV FUEL MANIFOLD BOLTS AND VSV FUEL MANIFOLD LOOP CLAMP BOLTS, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0109	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0109 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0109 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R1	NO. 1 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0110 R2	NO. 1 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R3	NO. 1 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R4	NO. 1 ENGINE - COMBUSTION CHAMBER - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0111	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH INCREASED LIFE LIMIT, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0114
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0112	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0113	NO. 1 ENGINE - INTRODUCTION OF NEW ECS DUCT BRACKET AND FAN COWL SUPPORT BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0113 R1	NO. 1 ENGINE - INTRODUCTION OF NEW ECS DUCT BRACKET AND FAN COWL SUPPORT BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0114	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH MODIFIED HUB, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0114 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH MODIFIED HUB, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115	NO. 1 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115 R1	NO. 1 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115 R2	NO. 1 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0116	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0117	NO. 1 ENGINE - LPT COOLING AIR TUBE METERING PLATE DELETION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0117 R1	NO. 1 ENGINE - LPT COOLING AIR TUBE METERING PLATE DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0118	NO. 1 ENGINE - INTRODUCTION OF A NEW HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0119	NO. 1 ENGINE - RTV APPLICATION ADJUSTMENT ON THE NEW VEE GROOV SYSTEM, SERVICE BULLETIN						- PRODUCT IMPROVEMENT
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0120	NO. 1 ENGINE - WASHERS TO PC FUEL TUBE/MANIFOLD, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0121 R1	NO. 1 ENGINE - CORE ASSEMBLY HARDWARE CHANGE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0122	NO. 1 ENGINE - DELETION OF THE STAGE 5 BLEED COVER PLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0123 R1	NO. 1 ENGINE - INSPECTION OF TGB AIR/OIL TUBE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0124	NO. 1 ENGINE - INTRODUCTION OF A NEW CENTER VENT TUBE (CVT) REMOVABLE AT ENGINE LEVEL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0124 R3	NO. 1 ENGINE - INTRODUCTION OF A NEW CENTER VENT TUBE (CVT) REMOVABLE AT ENGINE LEVEL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0125	NO. 1 ENGINE - HPT NOZZLE INNER SEAL REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0126	NO. 1 ENGINE - CORE CONFIGURATION UPDATES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0128	NO. 1 ENGINE - REPLACEMENT OF BOLTS AND WASHERS ATTACHING THE REAR CONE FLANGE ON THE FAN DISK FRONT FLANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0129	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0129 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0130	NO. 1 ENGINE - STARTER GEARSHAFT REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE L5 STARTER GEARSHAFT SERIAL NUMBER
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0130 R1	NO. 1 ENGINE - STARTER GEARSHAFT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0131	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0132	NO. 1 ENGINE - REDUCED INTERVAL FOR MAGNETIC CHIP DETECTOR INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE AGB STARTER GEARSHAFT SERIAL NUMBER
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0133	NO. 1 ENGINE - CHANGE OF TRANSFER GEARBOX AIR/OIL TUBE - REPLACEMENT OF RIGID AIR TUBE BY A SEMI-RIGID AIR TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 23X,91X
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0133 R1	NO. 1 ENGINE - CHANGE OF TRANSFER GEARBOX AIR/OIL TUBE - REPLACEMENT OF RIGID AIR TUBE BY A SEMI-RIGID AIR TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0134	NO. 1 ENGINE - INTRODUCTION OF A NEW CLAMP-LOOP AND ITS BRACKET FOR J12 ELECTRIC HARNESS HOLDING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0135	NO. 1 ENGINE - RESPONSIBILITY TRANSFER OF THREE FIRE DETECTION BRACKETS FROM BOEING TO CFMI, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0135 R1	NO. 1 ENGINE - RESPONSIBILITY TRANSFER OF THREE FIRE DETECTION BRACKETS FROM BOEING TO CFMI, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0136 R1	NO. 1 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0136 R2	NO. 1 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0136 R3	NO. 1 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0138	NO. 1 ENGINE - INTRODUCTION OF A HEAT SHRINK SLEEVE ON J7 AND J8 HARNESSES, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0146
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0139	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0140	NO. 1 ENGINE - BONDED CAUTION PLATE ON COVER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0140 R1	NO. 1 ENGINE - BONDED CAUTION PLATE ON COVER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0141	NO. 1 ENGINE - INTRODUCTION OF NEW LPTACC TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0142	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0143	NO. 1 ENGINE - REPLACEMENT OF SUSPECT J9 HARNESSES ., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0144	NO. 1 ENGINE - INTRODUCTION OF A NEW PS3 AIR TUBE WITH NEW ROUTING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0145	NO. 1 ENGINE - CLAMP ASSEMBLY ADDITION TO THE TRANSIENT BLEED VALVE DRAIN TUBE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0146	NO. 1 ENGINE - J8 HARNESS ECU CONNECTION - NEW ROUTING OF "DP0808" LEG, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0147	NO. 1 ENGINE - N1 MODIFIER SCHEDULE CHANGE FOR CFM56-7B26 AND CFM56-7B27 ENGINES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0148	NO. 1 ENGINE - SAFETYING OF OIL RETURN TUBE - INTRODUCTION OF A NEW BOLT PERMITTING INSTALLATION OF SAFETY WIRE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0148 R1	NO. 1 ENGINE - SAFETYING OF OIL RETURN TUBE - INTRODUCTION OF A NEW BOLT PERMITTING INSTALLATION OF SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0149	NO. 1 ENGINE - FAN AND BOOSTER ADDITION OF A NEW WASHER ON PT25 AIR TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0150	NO. 1 ENGINE - BRACKETS ASSY DELETION OF ALERNATES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0151	NO. 1 ENGINE - REPLACEMENT OF SWAGED SPACERS BY WELDED SPACERS ON ELECTRICAL HARNESSES, OIL AND FUEL TUBE BRACKETS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 91X NA-SUPERSEDED 72-0133 - 23X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0151 R1	NO. 1 ENGINE - REPLACEMENT OF SWAGED SPACERS BY WELDED SPACERS ON ELECTRICAL HARNESSES, OIL AND FUEL TUBE BRACKETS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0152	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 91X OPEN-51X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0153	NO. 1 ENGINE - INTRODUCTION OF A NEW J7 HARNESS WITH COIL INTEGRATED, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0154	NO. 1 ENGINE - INTRODUCTION OF A NEW VSV FUEL TUBE WITH NEW ROUTING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0155	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0155 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0156	NO. 1 ENGINE - HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0156 R1	NO. 1 ENGINE - HPT NOZZLE SHRUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0156 R2	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE (72-53-00) - HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN					OPTIONAL	
13-FEB-2012		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0157	NO. 1 ENGINE - IMPROVED SEAL MATERIAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0158	NO. 1 ENGINE - COMBUSTOR LINER PRODUCIBILITY IMPROVEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0158 R1	NO. 1 ENGINE - COMBUSTOR LINER PRODUCIBILTY IMPROVEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0159	NO. 1 ENGINE - INCREASING OF BOLT LENGTH ON T49.5 PROBE BOX, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0160	NO. 1 ENGINE - REMOVAL OF INTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU 874-105, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0161	NO. 1 ENGINE - REPLACEMENT OF ECU BRACKET ASSY ON THE FAN FRAME, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618715

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0162	NO. 1 ENGINE - INSPECT HPT STR MANIFOLD/LPT STAGE 1 NOZZLE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0163	NO. 1 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH A NEW DESIGN, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0164	NO. 1 ENGINE - HPT CLEARANCE CONTROL MANIFOLD, LPT COOLING/TF SENSOR AND ELECTRICAL SUPPORT BRACKET CHANGES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0165	NO. 1 ENGINE - RETROFIT INSTALLATION FOR COMPLYANCE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						NOT APPLICABLE - 91X OPEN-56X
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0168	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0168 R1	NO. 1 ENGINE - CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0168 R2	NO. 1 ENGINE - CFM 56-7B ENGINE CONVERSION TO CFM 56-7B27/B3., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169	NO. 1 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169 R2	NO. 1 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0170	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0171	NO. 1 ENGINE - INTRODUCTION OF A NEW STAGE 1 VANE ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0172	NO. 1 ENGINE - REPLACEMENT OF BRACKET FOR INSTALLATION OF BOEING FLOWMETER KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0173	NO. 1 ENGINE - LPT SHIFT MARAGING 250 MATERIAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0173 R1	NO. 1 ENGINE - LOW PRESSURE TURBINE SHAFT - INTRODUCTION OF A NEW LPT SHAFT MADE OF MARAGING 250 MATERIAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0174	NO. 1 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0175	NO. 1 ENGINE - INTRODUCTION OF TWO WAISTS ON ATTACHMENT STRUT 4 AND STRTUT 10 CLAMPS ASSY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176	NO. 1 ENGINE - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176 R1	NO. 1 ENGINE - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176 R2	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
30-SEP-2009		MOS HRS/MSC - ENC					
SB 72-0177	NO. 1 ENGINE - INTRODUCTION OF A NEW HPT STATOR PIN RETAINER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0178	NO. 1 ENGINE - NEW NO. 5 BEARING SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0179	NO. 1 ENGINE - VSV FUEL MANIFOLD AND VSV MANIFOLD BRACKET REPLACEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0180	NO. 1 ENGINE - REDUCED INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0181	NO. 1 ENGINE - FAN FRAME -NEW BRACKET ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0182	NO. 1 ENGINE - PT25 AIR TUBE INSTALLATION IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0182 R1	NO. 1 ENGINE - PT25 AIR TUBE INSTALLATION IMPROVEMENT, SERVICE BULLETIN						
10-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0183	NO. 1 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0184	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0185	NO. 1 ENGINE - INTRODUCTION OF A NEW NO. 4 ROLLER BEARING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0185 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW NO. 4 ROLLER BEARING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0186	NO. 1 ENGINE - NEW LPT STAGE 2 NOZZLE SEGMENTS, SERVICE BULLETIN						
23-SEP-1999		MOS HRS/MSC ENC	- 				
SB 72-0186 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LPT STAGE 2 NOZZLE SEGMENTS, SERVICE BULLETIN						
08-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0187	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188	NO. 1 ENGINE - DISCONNECTION AND RECONNECTION OF J01 AND J02 HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188 R1	NO. 1 ENGINE - DISCONNECTION AND RECONNECTION OF J01 AND J02 HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188 R2	NO. 1 ENGINE - FAN FRAME ASSEMBLY - DISCONNECTION AND RECONNECTION OF MW0301 (J01) AND MW0302 (J02) HARNESSES AT THEIR APPROPRIATE LOCATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0189	NO. 1 ENGINE - INTRODUCTION OF A NEW VSV FUEL MANIFOLD AND VSV MANIFOLD BRACKET CHANGE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0190	NO. 1 ENGINE - REPLACEMENT OF STAGE 2 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0191	NO. 1 ENGINE - SHORTER BOLT FOR T49.5 ELECTRICAL HARNESS SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0191 R1	NO. 1 ENGINE - NEW SHORTER BOLT FOR T49.5 ELECTRICAL HARNESS SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0192	NO. 1 ENGINE - REPLACEMENT OF NO.4 ROLLER BEARING 335-352-301-0, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0193	NO. 1 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH NEW DESIGN ON FLANGE B6. J1 ELECTRIC HARNESS HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0194	NO. 1 ENGINE - INTRODUCTION OF A WAIST ON STRUT PROFILE (9 O'CLOCK), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0195	NO. 1 ENGINE - INTRODUCTION OF NEW NIPPLE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0196	NO. 1 ENGINE - ABRADABLE STAGE 3 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0197	NO. 1 ENGINE - CHAMFER ON LOCKS-STAGE 2 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0198	NO. 1 ENGINE - LPT STAGE 2 SEAL SEGMENT WITH NEW LOCK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0199	NO. 1 ENGINE - TWO NEW LONGER BOLTS FOR ELECTRICAL HARNESS SUPPORT (3 O'CLOCK), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0200	NO. 1 ENGINE - INTRODUCTION OF A NEW ASSY WITH NEW DESIGN ON FLANGE B6. FUEL TUBE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0201	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7 IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0202	NO. 1 ENGINE - REMOVAL OF SILICONE ELASTOMER SEALS FROM FAN DUCT PANELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0203	NO. 1 ENGINE - INTRODUCTION OF A STRAIGHT HEADLESS PIN TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0204	NO. 1 ENGINE - FUEL TRANSIENT BLEED VALVE MANIFOLD BOLT CHANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0205	NO. 1 ENGINE - MODIFICATION OF ONE FIRE DETECTION BRACKET ASSY AND INCREASING OF OVERTAKING BOLTS ON FLANGE B6, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0206	NO. 1 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0207	NO. 1 ENGINE - RETURN TO CFMI OF NO.4 ROLLER BEARING 335-352-301-0 STORED AS SPARES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0208	NO. 1 ENGINE - INTRODUCTION OF NEW NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0208 R1	NO. 1 ENGINE - INTRODUCTION OF NEW NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0208 R2	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0208 R3	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
08-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0208 R4	NO. 1 ENGINE - INTRODUCTION OF A NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
25-MAY-2007		HRS/MSC	-				
		ENC					
SB 72-0208 R5	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
14-JAN-2009		HRS/MSC	-				
		ENC					
SB 72-0209 R1	NO. 1 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R4	NO. 1 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R5	NO. 1 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R6	NO. 1 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
05-FEB-2010		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0209 R7	NO. 1 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
13-FEB-2012		MOS HRS/MSC ENC	- 				
SB 72-0210	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY, NEW PS3 SIGNAL AIR TUBE AND NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0210 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY, NEW PS3 SIGNAL AIR TUBE AND NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0211	NO. 1 ENGINE - INTRODUCTION OF A NEW FORWARD INNER NOZZLE SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0212	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0212 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0213	NO. 1 ENGINE - INTRODUCTION OF A INTERMEDIATE FLANGE WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0214	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0215	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0216	NO. 1 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH NEW DESIGN ON THE ACCESSORY GEARBOX. ELECTRIC HARNESSES AND POWERS FEEDERS IDG CABLE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0217	NO. 1 ENGINE - LPT BLADES STAGE 4 IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0218	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0219	NO. 1 ENGINE - INTRODUCTION OF A NEW FOOL PROOF PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0220	NO. 1 ENGINE - INTRODUCTION OF NEW N2 SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0221	NO. 1 ENGINE - INTRODUCTION OF NEW OIL INLET COVER ASSY OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0221 R1	NO. 1 ENGINE - INTRODUCTION OF NEW OIL INLET COVER ASSY OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0222	NO. 1 ENGINE - REMOVAL EXTERNAL INSTRUMENTATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0223	NO. 1 ENGINE - INTRODUCTION OF A NEW OUTER LINER LUG RING TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0224	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7-B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0225	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0225 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0226	NO. 1 ENGINE - INTRODUCTION OF STAGE 2 AND STAGE 4 BLADE KITS TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0227	NO. 1 ENGINE - INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0227 R1	NO. 1 ENGINE - INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0228	NO. 1 ENGINE - INTRODUCTION OF A NEW NEXT HIGHER ASSEMBLY COOLING MANIFOLD UP AND DOWN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0229	NO. 1 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0229 R1	NO. 1 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
11-FEB-2008		MOS HRS/MSC ENC	-				
SB 72-0229 R2	NO. 1 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
22-FEB-2011		MOS HRS/MSC ENC	-				
SB 72-0229 R3	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
13-SEP-2011		MOS HRS/MSC ENC	-				
SB 72-0229 R4	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
23-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0230	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618725

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0230 R1	NO. 1 ENGINE - , SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0231	NO. 1 ENGINE - INTRODUCTION OF A NEW TURNBUCKLE ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0232	NO. 1 ENGINE - INTRODUCTION OF A NEW J6 HARNESS WITH NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0233	NO. 1 ENGINE - INTRODUCTION OF A FIELD REWORKED HPT NOZZLE STATOR SEGMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0234	NO. 1 ENGINE - INTRODUCTION OF UPPER DRAIN MANIFOLD GASKET, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0235	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0236	NO. 1 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT HOUSING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0237	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN FRAME WITH GANGS CHANNEL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0239	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLUGS FOR THE DEACTIVATION OF THE BURNER STAGING VALVE FUNCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0239 R1	NO. 1 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLUGS FOR THE DEACTIVATION OF THE BURNER STAGING VALVE FUNCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0240 R1	NO. 1 ENGINE - INTRODUCTION OF THE NEW MOUNT HARNESS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0240 R2	NO. 1 ENGINE - MODIFICATION OF HARNESSES MOUNTS, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0241	NO. 1 ENGINE - NEW LPT NOZZLE SEGMENTS STAGE 2 AND STAGE 3 REWORK, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0241 R1	NO. 1 ENGINE - NEW LPT NOZZLE SEGMENTS STAGE 2 AND STAGE 3 REWORK, SERVICE BULLETIN						
08-JAN-2007		MOS HRS/MSC ENC	 25000 (s)				
SB 72-0242	NO. 1 ENGINE - INTRODUCTION OF NEW LONGER BOLTS ON KIT CLOSE DMS BOX ATTACHMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0243	NO. 1 ENGINE - INTRODUCTION OF A BRACKET ASSY ON NO.1 AND NO. 2 BEARING SUPPORT OIL SUPPLY TUBE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0244 R1	NO. 1 ENGINE - POSITIONING MODIFICATION OF 2 CLAMPS ATTACHING THE FUEL TUBE AND THE OIL RETURN TUBE TO FACILITATE THE ENGINE COVER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0245	NO. 1 ENGINE - SPARE PARTS RELEASE CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246	NO. 1 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618727

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0247	NO. 1 ENGINE - INTRODUCTION OR REWORK OF THE BRACKET ASSY ON ACCESSORY GEARBOX ATTACHING THE J5 ELECTRIC WIRING HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0248	NO. 1 ENGINE - REPLACEMENT OR REWORK OF BRACKET ASSY ATTACHING THE MW0301 ELECTRICAL HARNESS ON FLANGE B4, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0249	NO. 1 ENGINE - INTRODUCTION OF NEW SEAL SEGMENTS STAGE 1, 2, 3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0249 R1	NO. 1 ENGINE - INTRODUCTION OF NEW SEAL SEGMENTS STAGE 1, 2, 3, SERVICE BULLETIN						
		MOS					
23-OCT-2007		HRS/MSC	-				
		ENC					
SB 72-0251	NO. 1 ENGINE - FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0252	NO. 1 ENGINE - INTRODUCTION OF NEW RADIAL SHAFT SUPPORT GUIDE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						COMPLIED WITH
		MOS		07-SEP-2005			
		HRS/MSC	-	2202:24			
		ENC		511			
SB 72-0253 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253 R3	NO. 1 ENGINE - FAN AND BOOSTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0253 R4	NO. 1 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0253 R5	NO. 1 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0253 R6	NO. 1 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0254	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0255	NO. 1 ENGINE - INTRODUCTION OF NEW BRACKET ASSY WITH NEW DESIGN FOR T49.5 HARNESS HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0255 R1	NO. 1 ENGINE - ENGINE ASSEMBLY - INTRODUCTION OF NEW BRACKET ASSY WITH NEW DESIGN FOR T49.5 HARNESS ATTACHMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0256	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0257	NO. 1 ENGINE - FAN FRAME ASSEMBLY - REPLACEMENT OF TWO BRACKETS ASSY TO ATTACH THE MW0315 AND MW0316 ELECTRICAL HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0258	NO. 1 ENGINE - NEW FIRE DETECTION HARNESSES MW0325 AND MW0326, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0258 R1	NO. 1 ENGINE - NEW FIRE DETECTION HARNESSES MW0325 AND MW0326, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618729

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0259	NO. 1 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR WITH DESIGN IMPROVED OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0259 R1	NO. 1 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR WITH DESIGN IMPROVED OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0259 R2	NO. 1 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0260	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0260 R1	NO. 1 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0261	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0262	NO. 1 ENGINE - NEW MW0311 ELECTRICAL HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0262 R1	NO. 1 ENGINE - NEW MW0311 ELECTRICAL HARNESS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0263	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0264	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0265	NO. 1 ENGINE - INTRODUCTION OF NEW LPT SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0266	NO. 1 ENGINE - INTRODUCTION OF A NEW ASSY ON FLANGE B4 - CJ13 ELECTRICAL HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0266 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY ON FLANGE B4 - CJ13 ELECTRICAL HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0267	NO. 1 ENGINE - INTRODUCTION OF A NEW LOCKS OF STAGE 2,3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0267 R1	NO. 1 ENGINE - FAN AND BOOSTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0267 R2	NO. 1 ENGINE - FAN AND BOOSTER - INTRODUCTION OF A NEW LOCK OF STAGE 2, 3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
17-DEC-2001		HRS/MSC	-				
		ENC					
SB 72-0267 R3	NO. 1 ENGINE - FAN AND BOOSTER - INTRODUCTION OF A NEW LOCK OF STAGE 2, 3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R2	NO. 1 ENGINE - INTRODUCTION OF NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R3	NO. 1 ENGINE - FAN AND BOOSTER - INTRODUCTION OF THE NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
17-DEC-2001		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0269	NO. 1 ENGINE - FIRE DETECTION HARNESSES MW0325 AND MW0326 TERMINAL LUG REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0269 R1	NO. 1 ENGINE - FIRE DETECTION HARNESSES MW0325 AND MW0326 TERMINAL LUG REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0270	NO. 1 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY-J7 HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R1	NO. 1 ENGINE - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R2	NO. 1 ENGINE - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R3	NO. 1 ENGINE - FAN BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	10000 (s)				
SB 72-0271 R4	NO. 1 ENGINE - FAN BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	10000 (s)				
SB 72-0271 R5	NO. 1 ENGINE - FAN AND BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0272	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0273	NO. 1 ENGINE - ROUTING OPTIMIZATION AND REMARKING OF THE HARNESSES MW0301 AND MW0302, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618732

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0273 R1	NO. 1 ENGINE - ROUTING OPTIMIZATION AND REMARKING OF THE HARNESSES MW0301 AND MW0302, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0274	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC - ENC					
SB 72-0275	NO. 1 ENGINE - NO.1 AND NO. 2 BEARING SUPPORT - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY AIR/OIL SEAL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0275 R1	NO. 1 ENGINE - NO.1 AND NO. 2 BEARING SUPPORT ASSEMBLY - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0276	NO. 1 ENGINE - SPARE PARTS FOR CFM56-7B, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0277	NO. 1 ENGINE - INTRODUCTION OF NEW OIL COLLECTOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0278	NO. 1 ENGINE - INTRODUCTION OF HPT/LPT NOZZLE SHROUD ASSEMBLY 9324M62G05 AND HPT NOZZLE SHROUD SUPPORT 2002M69G03, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0279	NO. 1 ENGINE - INTRODUCTION OF NEW HPT STATOR AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0280	NO. 1 ENGINE - INTRODUCTION OF NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0281	NO. 1 ENGINE - HARDWARE TRANSFER TO ENGINE LEVEL FROM CORE LEVEL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0283	NO. 1 ENGINE - GENERAL - INTRODUCTION OF CLAMP AND ATTACHING BOLT OF MW0325 HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0284	NO. 1 ENGINE - TRANFER OF THE VBV ACTUATORS FROM THE FAN FRAME LEVEL TO THE ENGINE ASSEMBLY LEVEL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0284 R1	NO. 1 ENGINE - TRANSFER OF THE VBV ACTUATORS FROM THE FAN FRAME LEVEL TO THE ENGINE ASSEMBLY LEVEL, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0285	NO. 1 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0285 R1	NO. 1 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0285 R2	NO. 1 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0286 R1	NO. 1 ENGINE - TURBINE LOW PRESSURE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0286 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT BLADE STAGE 1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0287	NO. 1 ENGINE - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0287 R1	NO. 1 ENGINE - ENGINE - ENGINE(72-00-00) - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618734

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0287 R2	NO. 1 ENGINE - ENGINE - ENGINE(72-00-00) - ACCIDENT INVOLVED HARDWARE (SUPERSEDED BY SB 72-0287 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0287 R3	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - ACCIDENT INVOLVED HARDWARE (SUPERSEDED BY SB 72-0287 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0287 R4	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN					INFORMATIONAL	
15-OCT-2013		MOS HRS/MSC - ENC					
SB 72-0288	NO. 1 ENGINE - INTRODUCTION OF NEW HPT INNER STATOR STATIONARY SEAL HEAT SHIELD TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0289	NO. 1 ENGINE - INTRODUCTION OF ALTERNATE INNER DOME, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0290	NO. 1 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0290 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291	NO. 1 ENGINE - TRANSFER GEARBOX, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291 R1	NO. 1 ENGINE - TRANSFER GEARBOX - INSPECTION OF A SPECIFIC POPULATION OF OUTER RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291 R2	NO. 1 ENGINE - TRANSFER GEARBOX - INSPECTION OF A SPECIFIC POPULATION OF OUTER RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618735

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0292	NO. 1 ENGINE - LOW PRESSURE TURBINE SHAFT - DELETION OF THE PRELIMINARY ATTACHMENT SYSTEM OF THE AIR/OIL SEAL TO THE LPT SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0292 R1	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT (72-55-00) - DELETION OF THE PRELIMINARY ATTACHMENT SYSTEM OF THE AIR/OIL SEAL OF THE LPT SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0293	NO. 1 ENGINE - INTRODUCTION OF A SELF LOCKING BORESCOPE CAP ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0293 R1	NO. 1 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF SELF LOCKING BORESCOPE CAP ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0294	NO. 1 ENGINE - INTRODUCTION OF STAINLESS STEEL NUTS TO REPLACE CADMIUM PLATING NUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0295	NO. 1 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL (SUPERSEDED BY 72-0295 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0295 R1	NO. 1 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL (SUPERSEDED BY 72-0295 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0295 R3	NO. 1 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL, SERVICE BULLETIN						
22-JUN-2007		MOS					
		HRS/MSC					
		ENC	15000 (s)				
SB 72-0296	NO. 1 ENGINE - FAN AND BOOSTER (SUPERSEDED BY 72-0296 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0296 R1	NO. 1 ENGINE - FAN AND BOOSTER (SUPERSEDED BY 72-0296 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0296 R2	NO. 1 ENGINE - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0296 R3	NO. 1 ENGINE - INTRODUCTION OF COUNTER WEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	 - (s) 				
SB 72-0296 R4	NO. 1 ENGINE - FAN AND BOOSTER, INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL.(SUPERSEDED BY 72-0296 R5), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	 - (s) 				
SB 72-0296 R5	NO. 1 ENGINE - FAN AND BOOSTER - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R6), SERVICE BULLETIN						
17-DEC-2001		MOS HRS/MSC ENC	 7000 (s)				
SB 72-0296 R6	NO. 1 ENGINE - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R7), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	 - (s) 				
SB 72-0296 R7	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 7000 (s)				
SB 72-0297	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	 - 				
SB 72-0298	NO. 1 ENGINE - NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				
SB 72-0298 R1	NO. 1 ENGINE - FAN FRAME ASSEMBLY - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				
SB 72-0298 R2	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				

© Camp Systems

EFTA00618737

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0298 R3	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0299	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R3	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FORWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R4	NO. 1 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FORWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0301	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0302	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0303	NO. 1 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618738

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0303 R1	NO. 1 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0304	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
13-NOV-2001		HRS/MSC	1700 (s)				
		ENC					
SB 72-0304 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	15000 (s)				
		ENC					
SB 72-0304 R2	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	15000 (s)				
		ENC					
SB 72-0304 R3	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-MAR-2007		HRS/MSC	15000 (s)				
		ENC					
SB 72-0305	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0306	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0308	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0309	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0310	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618739

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0311	NO. 1 ENGINE - LPT SHAFT - REPLACEMENT OF THE NO.4 ROLLER BEARING, SERVICE BULLETIN						
24-JAN-2001		MOS HRS/MSC ENC	-				
SB 72-0312	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0313	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0314	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0315	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316	NO. 1 ENGINE - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R1	NO. 1 ENGINE - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R3	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316R4	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
24-JUN-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0317	NO. 1 ENGINE - SPARE PARTS INTRODUCTION, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0318	NO. 1 ENGINE - APPLICATION OF ROOM TEMPERATURE VULCANIZING (RTV) ON THE FAN BLADE RETAING FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0318 R1	NO. 1 ENGINE - APPLICATION OF ROOM TEMPERATURE VULCANIZING (RTV) ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0319	NO. 1 ENGINE - INTRODUCTION OF A MILLED COMBUSTION CASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0319 R1	NO. 1 ENGINE - INTRODUCTION OF A MILLED COMBUSTION CASE, SERVICE BULLETIN						
10-DEC-2007		MOS HRS/MSC ENC	- 				
SB 72-0320	NO. 1 ENGINE - INTRODUCTION OF THE NEW REAR FLANGE AS ALTERNATE ON THE LPT NOZZLE STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0321	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0322	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0322 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-NOV-2006		MOS HRS/MSC ENC	- 				
SB 72-0323	NO. 1 ENGINE - REPLACEMENT OF THE AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0323 R1	NO. 1 ENGINE - REPLACEMENT OF THE AIR MANIFOLD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0324	NO. 1 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0324 R2	NO. 1 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0324 R3	NO. 1 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0324 R5	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
03-JAN-2012		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0325	NO. 1 ENGINE - ELASTOMER AXIAL STOP PIN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0325 R1	NO. 1 ENGINE - ELASTOMETER AXIAL STOP PIN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0325 R2	NO. 1 ENGINE - INTRODUCTION OF ELASTOMETER AXIAL STOP PIN INSTEAD OF RTV ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
17-DEC-2001		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0325 R3	NO. 1 ENGINE - INTRODUCTION OF ELASTOMETER AXIAL STOP PIN INSTEAD OF RTV ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0326	NO. 1 ENGINE - ON-WING BORESCOPE INSPECTION OF HPT BLADES, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008		RECURRING	
14-NOV-2001		HRS/MSC		3260:48			
		ENC	1000	746	**1746**		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0327	NO. 1 ENGINE - ENGINE - GENERAL - INSTALLATION OF A SAFETY WIRE OVER THE OIL TEMPERATURE PROBE HOUSING, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC - ENC					
SB 72-0328	NO. 1 ENGINE - REDUCE INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0328 R1	NO. 1 ENGINE - REDUCE INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0329	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING 305-355-717-0, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0330	NO. 1 ENGINE - INSPECTION AND REPLACEMENT OF THE IDENTIFICATION PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0330 R1	NO. 1 ENGINE - INSPECTION AND REPLACEMENT OF THE IDENTIFICATION PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0331	NO. 1 ENGINE - DELETION OF BURNER STAGING VALVE PARKING BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0332	NO. 1 ENGINE - INTRODUCTION OF NEW VSV INNER BUSHING AND WASHERS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0332 R1	NO. 1 ENGINE - COMPRESSOR FRONT STATOR - INTRODUCTION OF NEW VSV INNER BUSHINGS AND WASHERS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0333	NO. 1 ENGINE - CORE MODULE AND FAN MODULE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0333 R1	NO. 1 ENGINE - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R2	NO. 1 ENGINE - CORE MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE HOLES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R3	NO. 1 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R4	NO. 1 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334	NO. 1 ENGINE - FAN MAJOR MODULE - INTRODUCTION OF A 4-5 O'CLOCK LPYACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334 R1	NO. 1 ENGINE - INTRODUCTION OF A 4-5 O'CLOCK LPTACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334 R2	NO. 1 ENGINE - INTRODUCTION OF A 4-5 O'CLOCK LPT ACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0335	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0336	NO. 1 ENGINE - INSTALLATION OF SAFETY WIRE OVER THE OIL TEMPERATURE PROBE AND HOUSING, SERVICE BULLETIN						COMPLIED WITH
		MOS			07-JUL-2001		
		HRS/MSC	-		782		
		ENC			54		
SB 72-0337	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618744

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0337 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0338	NO. 1 ENGINE - ENGINE FAN AND BOOSTER SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0338 R1	NO. 1 ENGINE - ENGINE FAN AND BOOSTER SPARE PARTS RELEASE FOR CFM56-7B , SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0339	NO. 1 ENGINE - LPT FRAME - REPLACEMENT OF THE CURRENT OIL SUPPLY TUBE BY A REMOVABLE TUBE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0340	NO. 1 ENGINE - TURBINE FRAME, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0341	NO. 1 ENGINE - INTRODUCTION OF BOLTS FOR FUEL TUBE CLAMPS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0341 R1	NO. 1 ENGINE - INTRODUCTION OF BOLTS FOR FUEL TUBE CLAMPS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0342	NO. 1 ENGINE - DELETION OF STAGE 6-8 VANE SECTOR END BLOCKS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0342 R1	NO. 1 ENGINE - DELETION OF STAGE 6-8 VANE SECTOR END BLOCKS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0343	NO. 1 ENGINE - INTRODUCTION OD IMPROVED HPT ROTOR SPOOL WEIGHTS FOR STAGES 6-9, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0344	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE SPACER OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0344 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE SPACER OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0345 R1	NO. 1 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF NEW LPT NOZZLE SEGMENTS STAGE 2 AND A NEW SEALING PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0345 R2	NO. 1 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF NEW LPT NOZZLE SEGMENTS STAGE 2 AND A NEW SEALING PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346	NO. 1 ENGINE - ENGINE - TURBINE LOW PRESSURE - (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS ON THE LPT STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346 R1	NO. 1 ENGINE - ENGINE - TURBINE LOW PRESSURE - (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS ON THE LPT STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346 R2	NO. 1 ENGINE - ENGINE - TURBINE LOW PRESSURE (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS OF THE LPT STAGE 1, SERVICE BULLETIN						
02-MAR-2006		MOS HRS/MSC - ENC					
SB 72-0347	NO. 1 ENGINE - ENGINE - INTRODUCTION OF NEW BALANCING CLIPS ON LPT STAGE 4, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0347 R1	NO. 1 ENGINE - INTRODUCTION OF NEW BALANCING CLIPS ON LPT STAGE 4 BLADES, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0348	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0349	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0350	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE - INTRODUCTION OF FIELD REWORK FOR HPT AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0350 R1	NO. 1 ENGINE - INTRODUCE A FIELD REWORKED AIR HPT STATOR MANIFOLD P/N 2071M29G02, SERVICE BULLETIN						
30-JAN-2009		MOS HRS/MSC ENC	- 				
SB 72-0351 R1	NO. 1 ENGINE - INTRODUCTION OF HIGH PRESSURE TURBINE BLADE KIT 737L325G03 AND HPT BLADE 1957M10P01, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0352	NO. 1 ENGINE - INTRODUCTION OF NEW NO. 4 ROLLER BEARINGS WITH NEW OUTER RACE MATERIALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0352 R1	NO. 1 ENGINE - INTRODUCTION OF NEW NO. 4 ROLLER BEARINGS WITH NEW OUTER RACE MATERIALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0353	NO. 1 ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF A NEW FAN BLADE PLATFORM DESIGN 340-001-814-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0354	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0355	NO. 1 ENGINE - INTRODUCTION OF NEW BRACKETS ASSY ON THE AIR COOLING MANIFOLD ASSY UP AND DOWN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0355 R1	NO. 1 ENGINE - INTRODUCTION OF NEW BRACKETS ASSY ON THE AIR COOLING MANIFOLD ASSY UP AND DOWN, SERVICE BULLETIN						
04-AUG-2005		MOS HRS/MSC ENC	- 				
SB 72-0356	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0357 R1	NO. 1 ENGINE - INTRODUCTION OF NO. 4 STRUT FAIRING WITH NEW MATERIAL (STEEL VERSION), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0358	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY WITH AN OBLONG HOLE AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0359	NO. 1 ENGINE - INTRODUCTION OF NEW LPT REAR FRAME AND NEW OIL COLLECTOR WITH DELETION OF 16 HOLES AND BOLTS OUT OF 32, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0360	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0361	NO. 1 ENGINE - INTRODUCTION OF A NEW IDENTIFICATION PLATE WITH A 2D BARRED MANUFACTURER CODE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0362	NO. 1 ENGINE - INTRODUCTION OF NEW AFT ACOUSTICAL PANEL ASSEMBLY AT IDG AIR / OIL COOLER LOCATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0363	NO. 1 ENGINE - INTRODUCTION OF NEW STAGE 4 LOCKING BLADES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0363 R1	NO. 1 ENGINE - INTRODUCTION OF NEW STAGE 4 LOCKING BLADES, SERVICE BULLETIN						
22-APR-2005		MOS HRS/MSC ENC	- 				
SB 72-0364	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0365	NO. 1 ENGINE - REPLACEMENT OF BRACKETS BY NEW ONES WITH ERROR PROOFING DEVICE INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0365 R1	NO. 1 ENGINE - REPLACEMENT OF BRACKETS BY NEW ONES WITH ERROR PROOFING DEVICE INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0366	NO. 1 ENGINE - REPLACEMENT OF FAN RETAINING FLANGE OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0366 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - REPLACEMENT OF THE FAN RETAINING FLANGE OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0367	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0368 R1	NO. 1 ENGINE - ENGINE-ACCESSORY GEARBOX (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0368 R2	NO. 1 ENGINE - ENGINE-ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
25-SEP-2006		MOS HRS/MSC - ENC					
SB 72-0368 R3	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT (SUPERSEDED BY SB 72-0368 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0368 R4	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
18-OCT-2013		MOS HRS/MSC - ENC					
SB 72-0369	NO. 1 ENGINE - VGB GUIDE PAD INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0371 R1	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0372	NO. 1 ENGINE - OIL TEMP PROBE SAFETYWIRE, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008			
		HRS/MSC	-	3260:48			
		ENC		746			
SB 72-0374	NO. 1 ENGINE - FAN AND BOOSTER - TIGHTENING OF BOOSTER SPOOL FOWARD PINS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0375	NO. 1 ENGINE - HPT REAR SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0376	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0379	NO. 1 ENGINE - ENGINE-HIGH PRESSURE TURBINE NOZZLE (72-51-00) - REAR SUPPORT NUT SHIELD MATERIAL CHANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0380	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0381	NO. 1 ENGINE - INTRO HPC STG 4 BLADE KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0381 R1	NO. 1 ENGINE - INTRODUCTION OF STAGE 4 BLADE KIT TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0382	NO. 1 ENGINE - REPLACEMENT OF NEW NO.5 ROLLER BEARING WITH AN OUTER RACE MODIFIED TO INCREASE THE THICKNESS OF THE OIL FILM OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0382 R1	NO. 1 ENGINE - INTRODUCTION OF NEW NO.5 ROLLER BEARING WITH AN OUTER RACE MODIFIED TO INCREASE THE THICKNESS OF THE OIL FILM OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0383	NO. 1 ENGINE - TURBINE LOW PRESSURE - BORESCOPE INSPECTION FOR STAGE 1 LPT BLADE POSITION, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0384	NO. 1 ENGINE - FAN AND BOOSTER - ONE TIME INSPECTION FOR RETAINING FLANGE THREADED PIN PRESENCE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0385	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0386	NO. 1 ENGINE - FAN AND BOOSTER - ONE TIME TIGHTENING OF FOWARD BOOSTER SPOOL PINS, SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0386 R1	NO. 1 ENGINE - FAN AND BOOSTER - ONE TIME TIGHTENING OF FOWARD BOOSTER SPOOL PINS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0388	NO. 1 ENGINE - HPTR FRT DAMPER SLEEVE INSPECT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0389	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR (72-52-00) - INTRODUCTION OF HIGH PRESSURE TURBINE BLADE P/N 1957M72P01 AND P/N 1957M72P02 THROUGH FIELD REWORK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0390	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0391	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - DRAIN TUBE REDUCER ELIMINATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0392	NO. 1 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - FUEL NOZZLE BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0392 R1	NO. 1 ENGINE - FUEL NOZZLE BOLT LENGTH OPTIMIZATION, SERVICE BULLETIN						
11-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0392 R2	NO. 1 ENGINE - FUEL NOZZLE BOLT LENGTH OPTIMIZATION, SERVICE BULLETIN						
13-JUN-2007		MOS HRS/MSC ENC	-				
SB 72-0393	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF A NEW CFM56-7B27A ACCESSORY GEARBOX ASSY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0393 R1	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF A NEW CFM56-7B27A ACCESSORY GEARBOX ASSY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0394	NO. 1 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE - BRACKET HARDWARE ELIMINATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0395	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF NO. 4 ROLLER BEARING 340-167-901-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0395 R1	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF NO. 4 ROLLER BEARING 340-167-901-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396 R2	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0398	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0399	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0399 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400	NO. 1 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARING IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R1	NO. 1 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARING IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R2	NO. 1 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARINGS IN FIELD (SUPERSEDED BY 72-0400 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R3	NO. 1 ENGINE - LPT SHAFT ASSEMBLY (72-55-00) - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO. 4 ROLLER BEARINGS IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0401	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0402	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0403	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR REAR SHAFT WITH IMPROVED DAMPING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0404	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0411	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0414	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
07-JUL-2008		MOS HRS/MSC ENC	-				
SB 72-0415	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CF56-7B IPC, SERVICE BULLETIN						
20-DEC-2002		MOS HRS/MSC ENC	-				
SB 72-0417	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0419	NO. 1 ENGINE - SPARE PARTS FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0420	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0421	NO. 1 ENGINE - INTRODUCTION OF HPC REAR STATOR 1887M17G01, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0422	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
23-NOV-2009		MOS HRS/MSC ENC	-				
SB 72-0423	NO. 1 ENGINE - TURBINE LOW PRESSURE (72-54-00) - REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR RETAINING PLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0423 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR RETAINING PLATE, SERVICE BULLETIN						
02-SEP-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0425	NO. 1 ENGINE - ENGINE-GENERAL-SPARE PARTS RELEASE FOR CFM56-7 IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0427	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0429	NO. 1 ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF N2 SENSOR ADJUSTMENT SHIM SCREWS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0431	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00)-INTRODUCTION OF IMPROVED DOUBLE ANNULAR COMBUSTION (DAC) CHAMBER INNER LINER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0432	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
08-APR-2008		MOS HRS/MSC - ENC					
SB 72-0433	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0434	NO. 1 ENGINE - COMBUSTION CHAMBER (72-42-00) PIN AND MATING SLOT ELIMINATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0435	NO. 1 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0436	NO. 1 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - FUEL SPRAY SHIELD MATERIAL IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0437	NO. 1 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0438	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
10-APR-2006		MOS HRS/MSC ENC	- -				
SB 72-0439	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - MODIFICATION OF HARDWARE FOR THE NEW BOEING FIRE DETECTION ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0439 R1	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - MODIFICATION OF HARDWARE FOR THE NEW BOEING FIRE DETECTION ROUTING, SERVICE BULLETIN						
28-APR-2003		MOS HRS/MSC ENC	- -				
SB 72-0440 R1	NO. 1 ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOL ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD., SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R3	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R4	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R6	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
25-SEP-2006		MOS HRS/MSC ENC	 DUE				
SB 72-0441	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND LOW PRESSURE TURBINE NOZZLE STAGE 1 (72-53-00) - INTRODUCTION OF A NEW FRONT FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0442	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND LOW PRESSURE TURBINE NOZZLE STAGE 1 (72-53-00) - INTRODUCTION OF A NEW REAR FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				

© Camp Systems

EFTA00618756

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0442 R1	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW REAR FLANGE ON THE LPT STAGE 1 NOZZLE, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0444	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
	30-NOV-2006		HRS/MSC	-				
			ENC					
SB	72-0445	NO. 1 ENGINE - ENGINE-TRANSFER GEARBOX (72-62-00) - REPLACEMENT OF BALL BEARING 340-052-502-0 IN A SUSPECT LOT, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0446	NO. 1 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0446 R1	NO. 1 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS					
	30-MAY-2006		HRS/MSC	-				
			ENC					
SB	72-0447	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR (72-31-00) - BLADE AND VANE IMPROVEMENT, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0447 R1	NO. 1 ENGINE - IMPROVE THE DURABILITY OF THE HPC BLADES AND VANES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0448	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0449	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0449 R1	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
	26-JUN-2008		HRS/MSC	-				
			ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0450	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FAN RETAINING FLANGE PINS AND FAN DISK MID-FLANGE LOG PINS ON ALL CFM5607B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0450 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FAN RETAINING FLANGE PINS AND FAN DISK MID-FLANGE LUG PINS ON ALL CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0451	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FORWARD BOOSTER SPOOL PINS ON CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0451 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FORWARD BOOSTER SPOOL PINS ON CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0452	NO. 1 ENGINE - ENGINE - TURBINE LOW PRESSURE (72-54-00) - IN SHOP VISUAL INSPECTION OF STAGE 2 NOZZLE SEGMENTS FOR AXIAL CRACKS ON AIRFOIL LEADING EDGE, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0452 R1	NO. 1 ENGINE - IN SHOP VISUAL INSPECTION OF STAGE 2 NOZZLE SEGMENTS FOR AXIAL CRACKS ON AIRFOIL LEADING EDGE, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	9000 (s)				
SB 72-0453	NO. 1 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0454	NO. 1 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0454 R1	NO. 1 ENGINE - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION IN FIELD ONLY, SERVICE BULLETIN	MOS					
06-DEC-2007		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618758

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0454 R2	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION IN FIELD ONLY, SERVICE BULLETIN						
01-JUL-2009		MOS HRS/MSC ENC	- - -				
SB 72-0455	NO. 1 ENGINE - COMBUSTION CHAMBER (72-42-00) - SWIRLERS - THICK FLANGE (SUPERSEDED BY SB 72-0455 R1), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0455 R1	NO. 1 ENGINE - COMBUSTION CHAMBER (72-42-00) - SWIRLERS - THICK FLANGE, SERVICE BULLETIN					CATEGORY 7	
02-MAY-2014		MOS HRS/MSC ENC	- - -				
SB 72-0457	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0459	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0460	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0460 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0461	NO. 1 ENGINE - ENGINE - HPT ROTOR (72-52-00) - NEW DISK WITH IMPROVED LIFE DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0462	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW MW0312 HARNESS WITH A NEW DP1204 CONNECTOR AND REWORK OF THE OLD HARNESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0462 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW MW0312 HARNESS WITH A NEW DP1204 CONNECTOR AND REWORK OF THE OLD HARNESS, SERVICE BULLETIN						
27-AUG-2008		MOS HRS/MSC ENC	- - -				

© Camp Systems

EFTA00618759

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0463	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0463 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0464	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR MANIFOLD ASSY AND OF NEW BRACKETS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0465	NO. 1 ENGINE - GENERAL - INTRODUCTION OF DAMPERS ON THE ACCESSORY GEARBOX AXIAL LINK ENDS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0465 R1	NO. 1 ENGINE - GENERAL - INTRODUCTION OF DAMPERS ON THE ACCESSORY GEARBOX AXIAL LINK ENDS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0466	NO. 1 ENGINE - ENGINE - HPT (72-51-00) - NEW NOZZLES - ADDITIONAL COOLING HOLES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0466 R1	NO. 1 ENGINE - ENGINE - HPT (72-51-00) - NEW NOZZLES - ADDITIONAL COOLING HOLES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0467	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0468	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - DELETION OF THE FLAT WASHERS AT THE MAIN OIL/FUEL HEAT EXCHANGER AND FUEL RETURN TUBE LOCATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0469	NO. 1 ENGINE - HPC (72-32-00) - STAGES 2 AND 3 SHROUDS - LEADING EDGE CUTBACK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0471	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0474	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0475	NO. 1 ENGINE - INTRODUCTION OF NEW AIR TUBE, A NEW BRACKET ASSY WITH SAFETY WIRE HOLES AND REWORK OF THE PREVIOUS CONFIGURATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0476	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0477	NO. 1 ENGINE - INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0477 R2	NO. 1 ENGINE - INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD, SERVICE BULLETIN						
06-FEB-2008		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0480	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0481 R1	NO. 1 ENGINE - IN FIELD INTRODUCTION OF FAN BLADE SHIMS WITH NEW AXIAL STOP, SERVICE BULLETIN						
		DAYS	1 (s)				
		HRS/MSC					
		ENC					
SB 72-0482	NO. 1 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0483	NO. 1 ENGINE - ENGINE - HPT (72-51-00) - NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0483 R1	NO. 1 ENGINE - ENGINE - HPT (72-51-00) - NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618761

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0484	NO. 1 ENGINE - INTRODUCTION OF A NEW FUEL SUPPLY TUBE, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0485	NO. 1 ENGINE - INTRODUCTION OF NEW FAN DISK AND NEW SPACERS AND NEW SHIMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0485 R1	NO. 1 ENGINE - INTRODUCTION OF NEW FAN DISK AND NEW SPACERS AND NEW SHIMS, SERVICE BULLETIN						
13-AUG-2004		MOS HRS/MSC ENC	- 				
SB 72-0486	NO. 1 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0487	NO. 1 ENGINE - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL AND NEW NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS, SERVICE BULLETIN						
09-NOV-2004		MOS HRS/MSC ENC	- 				
SB 72-0487 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL AND INTRODUCTION OF A NEW NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0488 R1	NO. 1 ENGINE - REPLACEMENT OF IDENTIFICATION PLATES ON THE TRANSFER GEARBOX ASSEMBLY AND THE ACCESSORY GEARBOX ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0489	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0489 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0490	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0491	NO. 1 ENGINE - NEW MATERIAL (N5-) TO ELIMINATE YTTRIUM AND REDUCE SULFUR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0493	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0494	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0495 R2	NO. 1 ENGINE - REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINUM DOUBLER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0495 R3	NO. 1 ENGINE - REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINUM DOUBLER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0497	NO. 1 ENGINE - INTRODUCTION OF VESPEL NUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0498	NO. 1 ENGINE - REDUCE INSPECTION INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0498 R1	NO. 1 ENGINE - REDUCE INSPECTION INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0499 R1	NO. 1 ENGINE - INTRODUCTION OF NEW NO.5 BEARING SUPPORT NIPPLE DESIGN OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
16-DEC-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0500	NO. 1 ENGINE - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0500 R2	NO. 1 ENGINE - ENGINE - HPC (72-31-00) - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					OPTIONAL	
02-MAR-2011		MOS HRS/MSC ENC	- 				
SB 72-0500 R3	NO. 1 ENGINE - ENGINE - HPC (72-31-00) - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					OPTIONAL	
17-AUG-2011		MOS HRS/MSC ENC	- 				
SB 72-0501 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - DELETION OF THE BLANKING PLATE AND INTRODUCTION OF A NEW OIL SUPPLY TUBE WITH ITS NEW ATTACHMENT BRACKETS., SERVICE BULLETIN						
14-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0502 R1	NO. 1 ENGINE - REPLACEMENT OF NO.10 STRUT FAIRING (STEEL VERSION) BY STRUT FAIRING (ALUMINUM VERSION), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0502 R2	NO. 1 ENGINE - REPLACEMENT OF NO.10 STRUT FAIRING (STEEL VERSION) BY STRUT FAIRING (ALUMINUM VERSION), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503	NO. 1 ENGINE - FORWARD INNER NOZZLE SUPPORT - FORWARD FLANGE REPLACEMENT AND COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503 R1	NO. 1 ENGINE - FORWARD INNER NOZZLE SUPPORT - FORWARD FLANGE REPLACEMENT AND COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503 R2	NO. 1 ENGINE - ENGINE -HPT (72-51-00) -FORWARD INNER NOZZLE SUPPORT -FORWARD FLANGE REPLACEMENT AND COATING , SERVICE BULLETIN						
29-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0506	NO. 1 ENGINE - INSPECTION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN						
30-JUL-2004		MOS HRS/MSC ENC	- (s) 				
SB 72-0506 R1	NO. 1 ENGINE - INSPECTION OF OUTER LINER COOLING HOLES, SERVICE BULLETIN					SUPERSEDED	
23-AUG-2006		MOS HRS/MSC ENC	- 				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0507	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0509	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0509 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-APR-2008		MOS HRS/MSC ENC	-				
SB 72-0510	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0511	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0512	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLER PANEL IN TWO PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0512 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLER PANEL IN TWO PARTS AND REWORK OF THE PREVIOUS CONFIGURATION, SERVICE BULLETIN						
06-OCT-2006		MOS HRS/MSC ENC	-				
SB 72-0513	NO. 1 ENGINE - SPARE PARTS INFORMATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0514 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC (SUPERSEDED BY SB 72-0514 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0514 R2	NO. 1 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN					CATEGORY 8	
22-NOV-2013		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0515	NO. 1 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R1	NO. 1 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R2	NO. 1 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
18-APR-2006		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R3	NO. 1 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R4	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
12-FEB-2009		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R5	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R6	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
03-OCT-2011		MOS HRS/MSC ENC	24000 (s)				
SB 72-0515 R7	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
21-OCT-2011		MOS HRS/MSC ENC	24000 (s)				
SB 72-0520	NO. 1 ENGINE - INSPECTION OF THE FORWARD LPT SHAFT FOR MISSING PAINT, SERVICE BULLETIN						
08-FEB-2006		MOS HRS/MSC ENC	-				
SB 72-0521	NO. 1 ENGINE - INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0521 R1	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS, SERVICE BULLETIN					RECOMMENDED	
13-JUN-2012		MOS HRS/MSC ENC	- -				
SB 72-0522	NO. 1 ENGINE - INTRODUCTION OF AN IDENTIFICATION PLATE COMPLYING WITH THE NEW EUROPEAN REGULATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0523	NO. 1 ENGINE - INTRODUCTION OF A NEW CONNECTING TUBE WITH A NEW COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0523 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW CONNECTING TUBE WITH A NEW COATING, SERVICE BULLETIN						
29-NOV-2006		MOS HRS/MSC ENC	- -				
SB 72-0524	NO. 1 ENGINE - ENGINE - COMBUSTOR (72-42-00) - NEW DOME, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0525	NO. 1 ENGINE - FAN DISK DOVETAIL FACES WEAR DEPTH INSPECTION, SERVICE BULLETIN						
25-MAR-2005		MOS HRS/MSC ENC	 3000 (s)				
SB 72-0525 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	- -				
SB 72-0525 R2 PARA D (1)	NO. 1 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-410-0)					RECOMMENDED	
		MOS HRS/MSC ENC	 2000 (s)				
SB 72-0525 R2 PARA D (2)	NO. 1 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-420-0)					RECOMMENDED	
		MOS HRS/MSC ENC	 7000 (s)				
SB 72-0525 R2 PARA D (3)	NO. 1 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-471/472/473/474)					RECOMMENDED	
		MOS HRS/MSC ENC	 7000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0525 R2 PARA D (4)	NO. 1 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-485/486/490-0)					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	7000 (s)				
SB 72-0527	NO. 1 ENGINE - INTRODUCTION OF NEW LOW PRESSURE TURBINE (LPT) REAR FRAMES WITH A NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0527 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LOW PRESSURE TURBINE (LPT) REAR FRAMES WITH A NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
29-SEP-2005		HRS/MSC	-				
		ENC					
SB 72-0527 R2	NO. 1 ENGINE - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
21-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0527 R3	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
22-DEC-2009		HRS/MSC	-				
		ENC					
SB 72-0527 R4	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
04-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0528	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0529	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0530	NO. 1 ENGINE - BELLCRANK SUPPORT NUT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0531 R1	NO. 1 ENGINE - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
26-SEP-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0531 R2	NO. 1 ENGINE - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
10-APR-2008		MOS HRS/MSC ENC	- (s)				
SB 72-0531 R3	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
25-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0531 R4	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
18-APR-2013		MOS HRS/MSC ENC	ESV				
SB 72-0533	NO. 1 ENGINE - ENGINE - COMBUSTOR (72-41-00) - SWIRLER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0536	NO. 1 ENGINE - INNER LINER EXTENSION FOR REPAIR, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0539	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0540	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0540 R1	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
18-APR-2005		MOS HRS/MSC ENC	-				
SB 72-0540 R2	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
29-AUG-2007		MOS HRS/MSC ENC	-				
SB 72-0541	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0542	NO. 1 ENGINE - HPT NOZZLE FORWARD INNER NOZZLE SUPPORT (FINS) WITH IMPROVED EROSION COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618769

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0543	NO. 1 ENGINE - INTRODUCTION OF A NEW OIL INLET COVER O-RING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0545	NO. 1 ENGINE - FAN DISK LIFE LIMIT INCREASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	16000 (s)				
SB 72-0547	NO. 1 ENGINE - ON WING INSPECTION AND SHOP LEVEL ACTION FOT INNER AND OUTER LINERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1600 (s)				
SB 72-0547 R1	NO. 1 ENGINE - ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS, SERVICE BULLETIN						
08-MAR-2006		MOS					
		HRS/MSC					
		ENC	1600 (s)				
SB 72-0548	NO. 1 ENGINE - INTRODUCTION OF A NEW ELASTOMER SPACER, SERVICE BULLETIN						
		MOS					
17-FEB-2006		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0548 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW ELASTOMER SPACER, SERVICE BULLETIN						
		MOS					
25-OCT-2006		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0550	NO. 1 ENGINE - INTRODUCTION OF A NEW REAR VENT TUBE, SERVICE BULLETIN						
		MOS					
16-FEB-2007		HRS/MSC	-				
		ENC					
SB 72-0552	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR/STATOR ASSEMBLY (72-54-00) - REIDENTIFICATION OF LPT CASE IN FIELD, SERVICE BULLETIN						
		MOS					
27-JAN-2006		HRS/MSC	-				
		ENC					
SB 72-0552 R1	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR/STATOR ASSEMBLY (72-54-00) - REIDENTIFICATION OF LPT CASE IN FIELD, SERVICE BULLETIN						
		MOS					
16-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0553	NO. 1 ENGINE - INTRODUCTION OF AN ANTI-EROSION PAINT ON THE FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
20-OCT-2006		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618770

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0553 R1	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF AN ANTI-EROSION PAINT ON THE FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0554	NO. 1 ENGINE - REDUCED INSPECTION INTERVAL FOR FORWARD SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0554 R1	NO. 1 ENGINE - REDUCED INSPECTION INTERVAL FOR FORWARD SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0555	NO. 1 ENGINE - ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0556	NO. 1 ENGINE - FORWARD INNER NOZZLE SUPPORT (FINS) - WITH IMPROVED EROSION COATING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0557	NO. 1 ENGINE - ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0558	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
18-JAN-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0558 R1	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
21-SEP-2007		MOS					
		HRS/MSC					
		ENC		16350 (s)			
SB 72-0558 R2	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
02-DEC-2008		MOS					
		HRS/MSC					
		ENC		16350 (s)			
SB 72-0558 R3	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC		16350 (s)			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0558 R4	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
21-MAY-2013		HRS/MSC	-				
		ENC					
SB 72-0559	NO. 1 ENGINE - INTRODUCTION OF NEW MW0316 FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
06-JUN-2007		HRS/MSC	-				
		ENC					
SB 72-0560	NO. 1 ENGINE - INTRODUCTION OF A NEW MW0301 HARNESS WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS					
01-MAR-2007		HRS/MSC	-				
		ENC					
SB 72-0561	NO. 1 ENGINE - INTRODUCTION OF OLD NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS WITH NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0562	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
17-JAN-2006		HRS/MSC	-				
		ENC					
SB 72-0563	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
22-MAY-2006		HRS/MSC	-				
		ENC					
SB 72-0564	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION IN PRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW STARTER DRIVE PAD AND NEW HANDCRANCKING COVER, SERVICE BULLETIN						
		MOS					
13-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0564 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0564 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
		MOS					
16-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0564 R3	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE (SUPERSEDED BY SB 72-0564 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0564 R4	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE (SUPERSEDED BY SB 72-0564 R5), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0564 R5	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN					CATEGORY 3	
14-JAN-2014		MOS HRS/MSC ENC	 ESV 				
SB 72-0565 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	 - 				
SB 72-0566	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
23-MAY-2006		MOS HRS/MSC ENC	 - 				
SB 72-0567	NO. 1 ENGINE - INTRODUCTION OF A NEW OR REWORKED STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
10-MAY-2007		MOS HRS/MSC ENC	 - 				
SB 72-0567 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-03) - INTRODUCTION OF A NEW OR REWORKED STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	 - 				
SB 72-0568	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
20-MAR-2006		MOS HRS/MSC ENC	 - 				
SB 72-0568 R1	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
21-SEP-2007		MOS HRS/MSC ENC	 17400 (s)				
SB 72-0568 R2	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS HRS/MSC ENC	 17400 (s)				
SB 72-0569	NO. 1 ENGINE - INTRODUCTION OF NEW SPACERS ON THE B6 FRONT FLANGE OF THE FAN FRAME, SERVICE BULLETIN						
23-MAR-2007		MOS HRS/MSC ENC	 - 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0569 R1	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF NEW SPACERS ON THE B6 FRONT FLANGE OF THE FAN FRAME, SERVICE BULLETIN						
		MOS					
14-OCT-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R1	NO. 1 ENGINE - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
03-JUL-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R2	NO. 1 ENGINE - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
02-SEP-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R3	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD (SUPERSEDED BY SB 72-0570 R4), SERVICE BULLETIN						
		MOS					
13-JUN-2012		HRS/MSC	-				
		ENC					
SB 72-0570 R4	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN					CATEGORY 7	
		MOS					
26-JUN-2014		HRS/MSC	-				
		ENC					
SB 72-0571	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
23-MAR-2007		HRS/MSC	-				
		ENC					
SB 72-0572	NO. 1 ENGINE - HPT OUTER STATIONARY SEAL WITH INTEGRAL NUT SHIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0573	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
24-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0574	NO. 1 ENGINE - NEW NO.3 BEARING REAR STATIONARY AIR/OIL SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
		MOS					
10-APR-2006		HRS/MSC	-				
		ENC					
SB 72-0574 R1	NO. 1 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
		MOS					
24-JUL-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0574 R2	NO. 1 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
20-SEP-2006		MOS HRS/MSC ENC	-				
SB 72-0574 R3	NO. 1 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
24-OCT-2006		MOS HRS/MSC ENC	-				
SB 72-0574 R4	NO. 1 ENGINE - NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
31-AUG-2007		MOS HRS/MSC ENC	-				
SB 72-0575	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0576	NO. 1 ENGINE - REPAIR PARTS, SERVICE BULLETIN						
20-JUL-2006		MOS HRS/MSC ENC	-				
SB 72-0578	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0579	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
04-JUL-2006		MOS HRS/MSC ENC	-				
SB 72-0579 R1	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
27-OCT-2006		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R2	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R3	NO. 1 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
09-APR-2008		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R4	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
01-DEC-2008		MOS HRS/MSC ENC	19000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0579 R5	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R6	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
15-DEC-2009		MOS					
		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R7	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
19-FEB-2010		MOS					
		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R8	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
25-JAN-2012		MOS					
		HRS/MSC					
		ENC	19000 (s)				
SB 72-0580	NO. 1 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
25-MAY-2007		HRS/MSC	-				
		ENC					
SB 72-0580 R1	NO. 1 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
25-MAY-2008		HRS/MSC	-				
		ENC					
SB 72-0580 R2	NO. 1 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
27-APR-2009		HRS/MSC	-				
		ENC					
SB 72-0580 R3	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0581	NO. 1 ENGINE - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
		MOS					
26-JUL-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0581 R1	NO. 1 ENGINE - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
		MOS					
12-JAN-2007		HRS/MSC	-				
		ENC					
SB 72-0581 R2	NO. 1 ENGINE - ENGINE - HPC STATOR FORWARD ASSEMBLY (72-32-00) - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
		MOS					
14-AUG-2009		HRS/MSC	-				
		ENC					
SB 72-0582	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
07-AUG-2006		HRS/MSC	-				
		ENC					
SB 72-0582 R1	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
25-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0584 R1	NO. 1 ENGINE - INTRODUCTION OF NEW ENHANCED DURABILITY HPT BLADES, SERVICE BULLETIN						
		MOS					
04-JUN-2007		HRS/MSC	-				
		ENC					
SB 72-0584 R2	NO. 1 ENGINE - INTRODUCTION OF NEW ENHANCED DURABILITY HPT BLADES, SERVICE BULLETIN						
		MOS					
31-AUG-2007		HRS/MSC	-				
		ENC					
SB 72-0585	NO. 1 ENGINE - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN						
		MOS					
04-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0585 R1	NO. 1 ENGINE - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
		MOS					
25-APR-2008		HRS/MSC	-				
		ENC					
SB 72-0585 R2	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
		MOS					
03-JAN-2012		HRS/MSC	-				
		ENC					
SB 72-0586	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE PLATFORM WITH A NEW ELASTOMER SEAL, SERVICE BULLETIN						
		MOS					
24-NOV-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0586 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW FAN BLADE PLATFORM WITH A NEW ELASTOMER SEAL, SERVICE BULLETIN						
02-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0587	NO. 1 ENGINE - LPT FRAME ASSEMBLY (72-56-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
04-JUL-2008		MOS HRS/MSC ENC	-				
SB 72-0588	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0589	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0589 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0589 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0590	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0591	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0591 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0593	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	-				
SB 72-0593 R1	NO. 1 ENGINE - CONVERSION OF ANY AFFECTED CFM56-7B MODEL ENGINE TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618778

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0593 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0594	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0594 R1	NO. 1 ENGINE - CFM56-78 ENGINE CONVERSION TO CFM56-7B24/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0595	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0595 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
13-AUG-2007		MOS HRS/MSC ENC	- 				
SB 72-0595 R2	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0596	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3F, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0596 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3F, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0597	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0597 R1	NO. 1 ENGINE - CFM56-78 ENGINE CONVERSION TO CFM56-7B26/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0600	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618779

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0601 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0602	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0603	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0603 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0604	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0604 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1F, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0605	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
07-NOV-2006		MOS HRS/MSC ENC	- 				
SB 72-0606	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
31-MAY-2007		MOS HRS/MSC ENC	- 				
SB 72-0607	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
01-SEP-2006		MOS HRS/MSC ENC	- 				
SB 72-0608	NO. 1 ENGINE - INSPECTION OF THE LOW PRESSURE TURBINE (LPT) CASE, SERVICE BULLETIN						
23-AUG-2007		MOS HRS/MSC ENC	- 				
SB 72-0608 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-03) - INSPECTION OF THE LOW PRESSURE TURBINE (LPT) CASE ON ASSEMBLED LPT MODULE, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	- 				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0609	NO. 1 ENGINE - INTRODUCTION OF N5 HPT SHROUDS WITH HEAT TRANSFER ENHANCEMENT (HTE) BUMPS, SERVICE BULLETIN						
		MOS					
25-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0610	NO. 1 ENGINE - INTRODUCTION OF 8 MIL THICK HPC GUIDE SECTORS, SERVICE BULLETIN						
		MOS					
15-NOV-2006		HRS/MSC	-				
		ENC					
SB 72-0611	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
31-OCT-2006		HRS/MSC	-				
		ENC					
SB 72-0612	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-OCT-2006		HRS/MSC	-				
		ENC					
SB 72-0613	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
25-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0614	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
09-NOV-2006		HRS/MSC	-				
		ENC					
SB 72-0615	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
08-FEB-2007		HRS/MSC	-				
		ENC					
SB 72-0616	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0617	NO. 1 ENGINE - CLEANING OF THE CONTROL ALTERNATOR AND CHANGE OF THE NUTS ATTACHING THE LINE NO. 1 BEARING OUTER RACE ON THE AGB HOUSING, SERVICE BULLETIN						
		MOS					
03-JUL-2007		HRS/MSC	10000 (s)				
		ENC	5000				
SB 72-0617 R2	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - CLEANING OF THE CONTROL ALTERNATOR AND INSPECTION OF THE KEY-LOCKED STUDS ATTACHING THE LINE NO. 1 BEARING OUTER RACE ON THE AGB HOUSING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	10000 (s)				
		ENC	5000				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0618	NO. 1 ENGINE - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
25-JAN-2007		MOS HRS/MSC ENC	- 				
SB 72-0618 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0618 R2	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
09-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0619	NO. 1 ENGINE - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
27-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0619 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
02-DEC-2008		MOS HRS/MSC ENC	- 				
SB 72-0619 R2	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	- 				
SB 72-0620	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
19-DEC-2006		MOS HRS/MSC ENC	- 				
SB 72-0621	NO. 1 ENGINE - FIELD INTRODUCTION OF A NEW PLATE WITH TECH INSERTION KITS INSTALLED AND N1 TRIM INFORMATION, SERVICE BULLETIN						
16-JUL-2007		MOS HRS/MSC ENC	- 				
SB 72-0621 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - FIELD INTRODUCTION OF A NEW PLATE WITH TECH INSERTION KITS INSTALLED AND N1 TRIM INFORMATION, SERVICE BULLETIN						
01-DEC-2011		MOS HRS/MSC ENC	- 				
SB 72-0622	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-SEP-2007		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0623	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
20-JUN-2007		HRS/MSC	-				
		ENC					
SB 72-0626	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS					
28-SEP-2007		HRS/MSC	-				
		ENC					
SB 72-0626 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS					
21-APR-2008		HRS/MSC	-				
		ENC					
SB 72-0626 R2	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS					
04-MAY-2009		HRS/MSC	-				
		ENC					
SB 72-0626 R3	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
30-MAR-2012		HRS/MSC	-				
		ENC					
SB 72-0627	NO. 1 ENGINE - DELETION IN PRODUCTION OF THE ALTERNATE STAGE 3 ROTATING AIR SEAL RING, SERVICE BULLETIN						
		MOS					
28-SEP-2007		HRS/MSC	-				
		ENC					
SB 72-0627 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - DELETION IN PRODUCTION OF THE ALTERNATE STAGE 3 ROTATING AIR SEAL RING, SERVICE BULLETIN						
		MOS					
02-DEC-2008		HRS/MSC	-				
		ENC					
SB 72-0630	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
07-MAR-2008		HRS/MSC	-				
		ENC					
SB 72-0631	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
13-OCT-2008		HRS/MSC	-				
		ENC					
SB 72-0632	NO. 1 ENGINE - BOOSTER SPOOL FORWARD FLANGE INSPECTION, SERVICE BULLETIN						
		MOS					
22-JUN-2007		HRS/MSC					
		ENC	15000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0634	NO. 1 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
22-JUN-2007		MOS HRS/MSC ENC	- -				
SB 72-0634 R1	NO. 1 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
30-JUL-2007		MOS HRS/MSC ENC	- -				
SB 72-0634 R2	NO. 1 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0635	NO. 1 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE AIR COOLING TUBES, SERVICE BULLETIN						
16-FEB-2007		MOS HRS/MSC ENC	- -				
SB 72-0636	NO. 1 ENGINE - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 4800 (s)				
SB 72-0636 R1	NO. 1 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA, SERVICE BULLETIN					RECOMMENDED	
09-FEB-2012		MOS HRS/MSC ENC	 800 (s)				
SB 72-0636 R2	NO. 1 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA (SUPERSEDED BY 72-0636 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- -				
SB 72-0636 R3	NO. 1 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	- -				
SB 72-0637	NO. 1 ENGINE - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R1	NO. 1 ENGINE - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS					
16-AUG-2007		HRS/MSC	-				
		ENC					
SB 72-0637 R1 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 R1 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R2	NO. 1 ENGINE - STAGE 1 NOZZLES, SERVICE BULLETIN						
		MOS					
05-SEP-2007		HRS/MSC	-				
		ENC					
SB 72-0637 R2 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN HPT						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 R2 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN LPT						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R3	NO. 1 ENGINE - STAGE 1 NOZZLES, SERVICE BULLETIN						
		MOS					
04-APR-2008		HRS/MSC	-				
		ENC					
SB 72-0637 R3 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN HPT						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 R3 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN LPT						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R5	NO. 1 ENGINE - ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R5 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN HPT					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0637 R5 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN LPT					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0637 R6	NO. 1 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R6 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN HPT					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0637 R6 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN LPT					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0637 R7	NO. 1 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 R7 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R7 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8	NO. 1 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9	NO. 1 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9 PART 1	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9 PART 2	NO. 1 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0638	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0639	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
09-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0640	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0640 R1	NO. 1 ENGINE - INTRODUCTION OF PRE-GROUND HPT BLADE KIT (SPD), SERVICE BULLETIN						
18-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0643	NO. 1 ENGINE - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN						
28-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0643 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0643 R3	NO. 1 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN					RECOMMENDED	
24-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0645	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0646	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0647	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER REWORK, SERVICE BULLETIN						
15-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0647 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN						
05-JUN-2009		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618788

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0647 R2	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN						
20-NOV-2009		MOS HRS/MSC ENC	- -				
SB 72-0647 R3	NO. 1 ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN					CATEGORY 7	
30-MAY-2014		MOS HRS/MSC ENC	- -				
SB 72-0648	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
14-JUN-2007		MOS HRS/MSC ENC	- -				
SB 72-0649	NO. 1 ENGINE - INTRODUCTION OF NEW FAN BLADE SHIM ASSY, SERVICE BULLETIN						
08-FEB-2008		MOS HRS/MSC ENC	- - (s)				
SB 72-0649 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE SHIM ASSY, SERVICE BULLETIN					RECOMMENDED	
18-JAN-2011		MOS HRS/MSC ENC	- ESV				
SB 72-0650	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
25-JUN-2007		MOS HRS/MSC ENC	- -				
SB 72-0652	NO. 1 ENGINE - INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-RING MATERIAL AND REWORK OF OLD MAGNETIC SEAL AND OLD SEALOL SEAL TO THE NEW ONE, SERVICE BULLETIN						
29-JUL-2008		MOS HRS/MSC ENC	- 8000 (s)				
SB 72-0652 R2	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-RING MATERIAL AND REWORK OF OLD SEALOL SEAL TO THE NEW ONE, SERVICE BULLETIN						
12-JAN-2011		MOS HRS/MSC ENC	- 8000		**8000**		
SB 72-0653	NO. 1 ENGINE - ENGINE - NO.1 AND NO.2 BEARING SUPPORT ASSEMBLY (72-22-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
02-OCT-2008		MOS HRS/MSC ENC	- -				
SB 72-0655	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0656	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0657	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0658	NO. 1 ENGINE - INTRODUCTION OF NEW ALTERNATE LOOP CLAMP, SERVICE BULLETIN						
24-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0659	NO. 1 ENGINE - DELETION OF THE ALTERNATE TRIM BALANCE BOLTS IN PRODUCTION ONLY, SERVICE BULLETIN						
13-DEC-2007		MOS HRS/MSC ENC	- 				
SB 72-0661	NO. 1 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO N 4 ROLLER BEARING SUSPECTED BATCH, SERVICE BULLETIN						
23-AUG-2007		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0661 R1	NO. 1 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO NO 4 ROLLER BEARING SUSPECTED BATCH., SERVICE BULLETIN						
		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0661 R2	NO. 1 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO NO.4 ROLLER BEARING SUSPECTED BATCH, SERVICE BULLETIN						
21-JAN-2008		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0662	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-78 ENGINES, SERVICE BULLETIN						
29-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0663	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
26-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0663 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
12-JAN-2009		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0665	NO. 1 ENGINE - INTRODUCTION OF NEW METALLIC-COMPOSITE VSV BUSHING, SERVICE BULLETIN						
27-SEP-2007		MOS HRS/MSC ENC	-				
SB 72-0665 R1	NO. 1 ENGINE - INTRODUCTION OF NEW METALLIC-COMPOSITE VSV BUSHING, SERVICE BULLETIN						
10-DEC-2007		MOS HRS/MSC ENC	-				
SB 72-0666	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
15-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0667	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0667 R1	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-MAY-2012		MOS HRS/MSC ENC	-				
SB 72-0668	NO. 1 ENGINE - ENGINE - GENERAL (72-00-01) - INTRODUCTION OF A NEW FLAT WASHER AT THE JUNCTION OF RADIAL DRIVE SHAFT SLEEVE AND THE FAN FRAME SHROUD, SERVICE BULLETIN						
11-JUN-2008		MOS HRS/MSC ENC	-				
SB 72-0669	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
16-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0670	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
25-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0670 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-JAN-2009		MOS HRS/MSC ENC	-				
SB 72-0671	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFMS6-7B IPC, SERVICE BULLETIN						
04-DEC-2007		MOS HRS/MSC ENC	-				
SB 72-0673	NO. 1 ENGINE - INTRODUCTION OF A NEW ANTI-ROTATION STRAIGHT HEADED PIN, SERVICE BULLETIN						
02-NOV-2007		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618791

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0673 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - NEW VSV SHROUD HEADED ANTI- ROTATION PIN - INTRODUCTION, SERVICE BULLETIN						
15-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0674	NO. 1 ENGINE - ELIMINATION OF HPT STATOR MIDDLE HEAT SHIELD (SUPERSEDED BY 72-0674 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0674 R1	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND STAGE 1 LOW PRESSURE TURBINE NOZZLE ASSEMBLY (72-53-00) - ELIMINATION OF HPT STATOR MIDDLE HEAT SHIELD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0676	NO. 1 ENGINE - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
30-JUN-2008		MOS HRS/MSC ENC	-				
SB 72-0676 R1	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
17-NOV-2008		MOS HRS/MSC ENC	-				
SB 72-0676 R2	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
16-JUN-2009		MOS HRS/MSC ENC	-				
SB 72-0677	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC AND CMM, SERVICE BULLETIN						
31-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0678	NO. 1 ENGINE - ENGINE - FAN AND B00STER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW AXIAL STOP PIN, SERVICE BULLETIN						
05-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0679	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY, SERVICE BULLETIN						
29-AUG-2008		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0680	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
29-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0680 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-JUL-2008		MOS HRS/MSC ENC	- 				
SB 72-0681	NO. 1 ENGINE - CONVERSION OF ANY AFFECTED ENGINE MODELS TO CFM56-7B18,CFM56-7B20,CFM56-7B22,CFM56-7B24,CFM56-7B26 OR CFM56-7B27, SERVICE BULLETIN						
14-MAY-2008		MOS HRS/MSC ENC	- 				
SB 72-0682	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
17-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0683	NO. 1 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - REWORK OF HPT NOZZLES TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION, SERVICE BULLETIN						
25-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0683 R1	NO. 1 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - REWORK OF HPT NOZZLES TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION (SUPERSEDED BY SB 72-0683 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0683 R2	NO. 1 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - SPLIT VANE REPAIR AND REWORK TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION, SERVICE BULLETIN					CATEGORY 7	
21-JAN-2014		MOS HRS/MSC ENC	- 				
SB 72-0684	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
19-DEC-2007		MOS HRS/MSC ENC	- 				
SB 72-0685	NO. 1 ENGINE - DELETION OF SOME ALTERNATE NO.4 ROLLER BEARINGS, SERVICE BULLETIN						
01-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0686	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
05-MAR-2008		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0687	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0689	NO. 1 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
19-AUG-2008		MOS HRS/MSC ENC	- 				
SB 72-0689 R1	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
04-DEC-2009		MOS HRS/MSC ENC	- 				
SB 72-0689 R2	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
22-DEC-2011		MOS HRS/MSC ENC	- 				
SB 72-0690	NO. 1 ENGINE - BOLTS COMMONALITY FOR AIR LPT COOLING TUBE RETAINING STRAPS, SERVICE BULLETIN						
20-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0694 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF THE INNER COMBUSTION CHAMBER LINER, SERVICE BULLETIN					RECOMMENDED	
21-OCT-2011		MOS HRS/MSC ENC	- 				
SB 72-0696	NO. 1 ENGINE - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN						
21-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0696 R1	NO. 1 ENGINE - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN						
28-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0696 R2	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
02-SEP-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0698	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF ALTERNATE LPT REAR FRAMES ON SAC ENGINES IN FIELD, SERVICE BULLETIN						
23-MAR-2009		MOS HRS/MSC ENC	- 				
SB 72-0699	NO. 1 ENGINE - CONVERSION OF ANY AFFECTED ENGINE MODELS TO FCM56-7B/3 TI ENGINE MODEL, SERVICE BULLETIN						
14-MAY-2008		MOS HRS/MSC ENC	- 				
SB 72-0699 R2	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B (SAC) TO CFM56-7B/3 (TI), SERVICE BULLETIN						
03-NOV-2009		MOS HRS/MSC ENC	- 				
SB 72-0700	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - IMPROVEMENT OF THE FUEL SUPPLY TUBE WITH NEW INSERTS, SERVICE BULLETIN						
24-FEB-2009		MOS HRS/MSC ENC	- 				
SB 72-0701	NO. 1 ENGINE - NEW SPARE PARTS THAT ARE INTERCHANGABLE WITH THE OLD PARTS THEY REPLACE, SERVICE BULLETIN						
13-MAY-2008		MOS HRS/MSC ENC	- 				
SB 72-0702	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-JUN-2008		MOS HRS/MSC ENC	- 				
SB 72-0704	NO. 1 ENGINE - INSPECTION OF OIL SCAVENGE FILTER TO DETECT NO. 3 BEARING DETERIORATION, SERVICE BULLETIN					RECOMMENDED	
23-JUN-2008		MOS HRS/MSC ENC	 1000 (s) 				
SB 72-0704 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) INSPECTION OF OIL SCAVENGE FILTER TO DETECT NO. 3 BEARING DETERIORATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0706	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B2, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0707	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- 				
SB 72-0707 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2011		MOS HRS/MSC ENC	- 				
SB 72-0708	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2F, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- 				
SB 72-0708 R1	NO. 1 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2F, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2011		MOS HRS/MSC ENC	- 				
SB 72-0709 R1	NO. 1 ENGINE - INTRODUCTION OF NEW BOLT FOR HPTACC MANIFOLD ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
29-OCT-2008		MOS HRS/MSC ENC	 - (s) 	28-SEP-2009 3378:04 776			
SB 72-0711	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
16-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0712	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-NOV-2008		MOS HRS/MSC ENC	- 				
SB 72-0713 R1	NO. 1 ENGINE - FUEL NOZZLE COUPLING NUT INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
25-JUL-2008		MOS HRS/MSC ENC	 - 	28-SEP-2009 3378:04 776			
SB 72-0716	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0718 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - REWORK OF THE LPT CASE RAIL "0" SUPPORT RING AND REIDENTIFICATION OF THE LPT CASE, SERVICE BULLETIN						
04-JUN-2013		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0720	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE SPACER, SERVICE BULLETIN						
28-APR-2009		MOS HRS/MSC ENC	-				
SB 72-0720 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE SPACER, SERVICE BULLETIN						
11-JAN-2010		MOS HRS/MSC ENC	-				
SB 72-0722	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-78 IPC, SERVICE BULLETIN						
10-DEC-2008		MOS HRS/MSC ENC	-				
SB 72-0724	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
10-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0725	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF TWO NEW BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
29-JAN-2009		MOS HRS/MSC ENC	-				
SB 72-0726	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF TWO BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
26-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0727	NO. 1 ENGINE - ENGINE - GENERAL (72-00-03) - INTRODUCTION OF A NEW SILVER PLATED NUT FOR THE LPT ROTOR SUPPORT / LPT SHAFT ATTACHMENT FLANGE JUNCTION, SERVICE BULLETIN						
28-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0728	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
06-MAR-2009		MOS HRS/MSC ENC	12 (s)				
SB 72-0728 R1	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	12 (s)				

© Camp Systems

EFTA00618797

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0728 R2	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
09-FEB-2010		MOS HRS/MSC ENC	12 (s)				
SB 72-0730	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - REIDENTIFICATION OF THE CONTAINMENT CASE 340-059-813-0 AND 340-059-814-0, SERVICE BULLETIN						
13-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0731	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 301-480-320-0 IN A SUSPECT LOT, SERVICE BULLETIN						
26-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0732	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
02-JUN-2009		MOS HRS/MSC ENC	19000 (s)				
SB 72-0732 R1	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	19000 (s)				
SB 72-0733	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
14-APR-2009		MOS HRS/MSC ENC	-				
SB 72-0734	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF NEW LPT STAGE 1 NOZZLE SEGMENTS, SERVICE BULLETIN						
13-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0734 R1	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF NEW LPT STAGE 1 NOZZLE SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0735	NO. 1 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY - (72-53-00) - MODIFICATION OF HPT STATOR SHROUD- ENHANCED DURABILITY PUCK REPAIR, SERVICE BULLETIN						
26-JUN-2009		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618798

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0735 R1	NO. 1 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY - (72-53-00) - MODIFICATION OF HPT STATOR SHROUD - ENHANCED DURABILITY PUCK REPAIR, SERVICE BULLETIN						
		MOS					
04-DEC-2009		HRS/MSC	-				
		ENC					
SB 72-0737	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS TO CFM56-7B27A ENGINES, SERVICE BULLETIN						
		MOS					
15-MAY-2009		HRS/MSC	-				
		ENC					
SB 72-0738	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
28-JAN-2009		HRS/MSC	-				
		ENC					
SB 72-0738 R1	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
30-JUN-2011		HRS/MSC	-				
		ENC					
SB 72-0739	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - PRECAUTIONS TO BE FOLLOWED CONCERNING INSULATION BLANKETS CONTAINING RCF, SERVICE BULLETIN						
		MOS					
08-FEB-2013		HRS/MSC	-				
		ENC					
SB 72-0740	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN					INFORMATIONAL	
		MOS					
17-FEB-2009		HRS/MSC	-				
		ENC					
SB 72-0742	NO. 1 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE ASSEMBLY (72-00-02) - HPC FRONT CASE BLEED PORT REMOVAL AND SIMPLIFICATION, SERVICE BULLETIN						
		MOS					
30-JUN-2009		HRS/MSC	-				
		ENC					
SB 72-0743	NO. 1 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF SUSPECT STAGE 3 LPT DISK 336-002-006-0, SERVICE BULLETIN						
		MOS					
26-OCT-2009		HRS/MSC					
		ENC	9500 (s)				
SB 72-0743 R1	NO. 1 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF SUSPECT STAGE 3 LPT DISK 336-002-006-0, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2010		HRS/MSC					
		ENC	9500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0744	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF THREE BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0745	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF AN ALTERNATE PROVISIONING SOURCE FOR THE NO. 1, 2 AND 5 BEARINGS, SERVICE BULLETIN						
26-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0747	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE SERIALIZATION-MANUFACTURING SEQUENCE, SERVICE BULLETIN						
04-JUN-2009		MOS HRS/MSC ENC	-				
SB 72-0747 R1	NO. 1 ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE SERIALIZATION-MANUFACTURING SEQUENCE, SERVICE BULLETIN					CATEGORY 9	
03-MAR-2014		MOS HRS/MSC ENC	-				
SB 72-0748	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
30-JUN-2009		MOS HRS/MSC ENC	-				
SB 72-0749	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW RETAINING PLATE, SERVICE BULLETIN						
01-FEB-2011		MOS HRS/MSC ENC	-				
SB 72-0750	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
08-OCT-2009		MOS HRS/MSC ENC	-				
SB 72-0751	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
08-OCT-2009		MOS HRS/MSC ENC	-				
SB 72-0752	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
02-JUL-2009		MOS HRS/MSC ENC	-				
SB 72-0753	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK IN FIELD OF THE FAN BLADE REAR SHANK FOR WEAR, SERVICE BULLETIN						
14-OCT-2009		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0753 R1	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK IN FIELD OF THE FAN BLADE REAR SHANK FOR WEAR, SERVICE BULLETIN						
03-DEC-2012		MOS HRS/MSC ENC	-				
SB 72-0754	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF ONE BRACKET ON THE FLANGE A1 AND THREE BRACKETS ASSY ON THE FLANGE B6 WITH A NEW DESIGN, SERVICE BULLETIN					RECOMMENDED	
10-NOV-2010		MOS HRS/MSC ENC	-				
SB 72-0756	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0757	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
28-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0758	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR BLADES, SERVICE BULLETIN						
22-SEP-2009		MOS HRS/MSC ENC	-				
SB 72-0759	NO. 1 ENGINE - ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES, SERVICE BULLETIN					OPTIONAL	
27-OCT-2010		MOS HRS/MSC ENC	-				
SB 72-0759 R1	NO. 1 ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES (SUPERSEDED BY SB 72-0759 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0759 R2	NO. 1 ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
22-OCT-2013		MOS HRS/MSC ENC	-				
SB 72-0760	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
03-SEP-2009		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0761	NO. 1 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
08-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0762	NO. 1 ENGINE - ENGINE - TRANSFER GEARBOX ASSEMBLY (72-62-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
29-SEP-2009		HRS/MSC	-				
		ENC					
SB 72-0763	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0764 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF PREFORMED PACKING O-RINGS IN THE LPT ROTOR / STATOR ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0764 R2	NO. 1 ENGINE - GENERAL (72-00-00) - REPLACEMENT OF PREFORMED PACKING O-RINGS IN THE LPT ROTOR / STATOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	
		MOS					
25-JUL-2012		HRS/MSC	-				
		ENC					
SB 72-0767	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
28-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0768	NO. 1 ENGINE - NOT ISSUED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0769	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF INNER AND OUTER SEGMENT LINER SPARE PARTS, SERVICE BULLETIN						
		MOS					
06-FEB-2010		HRS/MSC	-				
		ENC					
SB 72-0772	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
04-DEC-2009		HRS/MSC	-				
		ENC					
SB 72-0773	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
25-NOV-2009		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0774	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
20-JAN-2010		HRS/MSC	-				
		ENC					
SB 72-0775	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0776	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0777	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN DISK MIDDLE LUG REWORK IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0778	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0779	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW MW0311 ELECTRICAL HARNESS AND IN FIELD REWORK OF THE OLD MW0311 ELECTRICAL HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0780	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-23-00) - REWORK IN FIELD OF FAN CONTAINMENT CASE B1 FLANGE AT HOLES NO. 84 AND 85, SERVICE BULLETIN						
		MOS					
18-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0780 R1	NO. 1 ENGINE - FAN AND BOOSTER ASSEMBLY (72-23-00) - REWORK IN FIELD OF FAN CONTAINMENT CASE B1 FLANGE AT HOLES NO. 84 AND 85, SERVICE BULLETIN						
		MOS					
11-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0781	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW LPT COOLING MANIFOLDS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
26-JUN-2013		HRS/MSC	-				
		ENC					
SB 72-0783	NO. 1 ENGINE - ENGINE - HPT ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0784	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PART RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0785	NO. 1 ENGINE - ENGINE - ENGINE (72-00-00) - DAC FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0786	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW OUTER LINER FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0787	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0789	NO. 1 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - ENGINE OPERATION IN THE ENHANCED PROCEDURES ZONE FROM VOLCANO EYJAFJALLAJOKULL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0789 R1	NO. 1 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - ENGINE OPERATION IN THE ENHANCED PROCEDURES ZONE FROM VOLCANO EYJAFJALLAJOKULL, SERVICE BULLETIN					RECOMMENDED	
21-JUL-2011		MOS HRS/MSC ENC	- 				
SB 72-0789 R2	NO. 1 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - INTRODUCTION OF A LEADING INDICATOR PROGRAM FOR ENGINE OPERATION IN LOW CONCENTRATIONS OF VOLCANIC ASH, SERVICE BULLETIN					RECOMMENDED	
14-DEC-2011		MOS HRS/MSC ENC	- 				
SB 72-0790	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0791	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0792	NO. 1 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING , SERVICE BULLETIN					OPTIONAL	
30-JUL-2010		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0794	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
15-OCT-2010		HRS/MSC	-				
		ENC					
SB 72-0795	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS , SERVICE BULLETIN					OPTIONAL	
		MOS					
03-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0795 R2	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-APR-2012		HRS/MSC	-				
		ENC					
SB 72-0795 R3	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JUN-2012		HRS/MSC	-				
		ENC					
SB 72-0796	NO. 1 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE INTERCHANGEABILITY LIMITATIONS (SUPERSEDED BY SB 72-0796 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0796 R1	NO. 1 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE INTERCHANGEABILITY LIMITATIONS, SERVICE BULLETIN					CATEGORY 4	
		MOS					
18-FEB-2013		HRS/MSC	-				
		ENC					
SB 72-0797	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE MOMENT-WEIGHT MISMARKING, SERVICE BULLETIN						
		MOS					
27-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0798	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - REWORK OF HPC STAGE 1 THROUGH STAGE 9 BLADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0799	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - REWORK OF HPC TECH INSERTION HPC BLADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JAN-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0801	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW FRONT FLANGE WITH 6 VENTILATION HOLES AND REWORK OF THE OLD PART, SERVICE BULLETIN						
30-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0802	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0803	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
12-OCT-2010		MOS HRS/MSC ENC	- 				
SB 72-0804	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
09-NOV-2010		MOS HRS/MSC ENC	- 				
SB 72-0804 R1	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
24-MAR-2011		MOS HRS/MSC ENC	- 				
SB 72-0805	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
02-NOV-2010		MOS HRS/MSC ENC	- 				
SB 72-0806	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF NEW SUPPORT WITH CAPTIVE NUT, SERVICE BULLETIN						
18-JUL-2011		MOS HRS/MSC ENC	- 				
SB 72-0807	NO. 1 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON CFM56-7B27A ENGINES, SERVICE BULLETIN					OPTIONAL	
19-JAN-2012		MOS HRS/MSC ENC	 11200 (s)				
SB 72-0808	NO. 1 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INSPECTION OF STAGE 1 LPT NOZZLES DUE TO INDIA ENVIRONMENTAL DISTRESS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
27-SEP-2013		MOS HRS/MSC ENC	- 				
SB 72-0809	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF CFM56-7BE LPT HARDWARE ON CFM56-7B, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0810	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0811	NO. 1 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLY DURABILITY IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
20-JAN-2011		MOS HRS/MSC ENC	-				
SB 72-0811 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLY DURABILITY IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
29-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0812	NO. 1 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING, SERVICE BULLETIN					RECOMMENDED	
26-SEP-2011		MOS HRS/MSC ENC	-				
SB 72-0812 R1	NO. 1 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING, SERVICE BULLETIN					RECOMMENDED	
06-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0813	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - INTRODUCTION OF HPT BLADE P/N 2403M91P02, SERVICE BULLETIN					INFORMATIONAL	
30-JAN-2012		MOS HRS/MSC ENC	-				
SB 72-0814	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
11-APR-2011		MOS HRS/MSC ENC	-				
SB 72-0815	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
20-DEC-2011		MOS HRS/MSC ENC	-				
SB 72-0816	NO. 1 ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - NEW SHROUD HPT STATOR HANGER WITH MODIFIED AIR FILTER, SERVICE BULLETIN					RECOMMENDED	
19-JAN-2011		MOS HRS/MSC ENC	-				
SB 72-0817	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
03-OCT-2011		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618807

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0817 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0818 R1	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR, SERVICE BULLETIN					RECOMMENDED	
24-MAR-2011		MOS HRS/MSC ENC	-				
SB 72-0819	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
03-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0820	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF NO. 4 FAIRING STEEL VERSION, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
31-JUL-2012		MOS HRS/MSC ENC	-				
SB 72-0821	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
04-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0821 R1	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
26-MAR-2013		MOS HRS/MSC ENC	-				
SB 72-0822	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BOLT TO ATTACH THE MW0325 HARNESS, SERVICE BULLETIN						
18-AUG-2011		MOS HRS/MSC ENC	-				
SB 72-0822 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BOLTS TO ATTACH THE MW0325 HARNESS, SERVICE BULLETIN						
26-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0823	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05 (SUPERSEDED BY 72-0823 R1), SERVICE BULLETIN					SUPERSEDED	
11-APR-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0823 R1	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05, SERVICE BULLETIN					INFORMATIONAL	
11-MAY-2011		MOS HRS/MSC ENC	- -				
SB 72-0823 R2	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05, SERVICE BULLETIN					INFORMATIONAL	
23-JUN-2011		MOS HRS/MSC ENC	- -				
SB 72-0824	NO. 1 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - MANIFOLD HPT CLEARANCE CONTROL BRACKET CHANGE, SERVICE BULLETIN					OPTIONAL	
21-NOV-2011		MOS HRS/MSC ENC	- -				
SB 72-0825	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	 25000 (s)				
SB 72-0825 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
29-NOV-2011		MOS HRS/MSC ENC	 15000 (s)				
SB 72-0825 R2	NO. 1 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES (SUPERSEDED BY SB 72-0825 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	 - (s) 				
SB 72-0825 R3	NO. 1 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					CATEGORY 2	
30-APR-2014		MOS HRS/MSC ENC	- -				
SB 72-0826	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0827	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK OF THE BOOSTER SPOOL, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
27-MAY-2013		MOS HRS/MSC ENC	- -				

© Camp Systems

EFTA00618809

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0829	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - RELEASE OF CFM56-7BE HPT ROTOR HARDWARE TO EARLIER CFM56-7B ENGINE MODELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-JAN-2012		HRS/MSC	-				
		ENC					
SB 72-0830	NO. 1 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - RELEASE OF CFM56-7BE COMBUSTION CASE TO EARLIER CFM56-7B ENGINE MODELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JAN-2012		HRS/MSC	-				
		ENC					
SB 72-0831	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
02-DEC-2011		HRS/MSC	-				
		ENC					
SB 72-0832	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
05-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0833	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B TURBOFAN ENGINES, SERVICE BULLETIN						
		MOS					
31-AUG-2011		HRS/MSC	-				
		ENC					
SB 72-0833 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B TURBOFAN ENGINES, SERVICE BULLETIN						
		MOS					
28-NOV-2011		HRS/MSC	-				
		ENC					
SB 72-0834	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE PART NUMBERS AND REIDENTIFICATION OF OLD FAN BLADES IN FIELD, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
08-JUN-2011		HRS/MSC	-				
		ENC					
SB 72-0834 R1	NO. 1 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE PART NUMBERS AND REIDENTIFICATION OF OLD FAN BLADES IN FIELD, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
20-JUL-2012		HRS/MSC	-				
		ENC					
SB 72-0835	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION COMBUSTION CHAMBER INNER LINER WITH THIN TBC, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-DEC-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0836	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER INNER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
23-SEP-2011		MOS HRS/MSC ENC	-				
SB 72-0837	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B20E, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0838	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B22E, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0839	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B22E/B1, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0840	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B24E, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0841	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B24E/B1, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0842 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0843 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B1, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0844 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B2, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0845 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/F, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0846 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B2F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0848 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B27E/B1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0850 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B27E/F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0852	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT ROTOR SUPPORT, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
16-OCT-2012		HRS/MSC	-				
		ENC					
SB 72-0853	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE MATE FACE SURFACE INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-SEP-2011		HRS/MSC	-				
		ENC					
SB 72-0854	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY ON THE FILTER SUPPORT, SERVICE BULLETIN						
		MOS					
15-NOV-2011		HRS/MSC	-				
		ENC					
SB 72-0856	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY, SERVICE BULLETIN						
		MOS					
28-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0857	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
21-DEC-2011		HRS/MSC	-				
		ENC					
SB 72-0858	NO. 1 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INSPECTION OF SUSPECT FAN CONTAINMENT CASE FOR MISSING OR MISLOCATED ANODIZATION, SERVICE BULLETIN						
		MOS					
12-SEP-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0859	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTION CHAMBER DOME WITH RETAINERLESS SWIRL NOZZLES, SERVICE BULLETIN					RECOMMENDED	
21-SEP-2011		MOS HRS/MSC ENC	- 				
SB 72-0859 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTION CHAMBER DOME WITH RETAINERLESS SWIRL NOZZLES, SERVICE BULLETIN					RECOMMENDED	
28-JAN-2013		MOS HRS/MSC ENC	- 				
SB 72-0861	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
09-JAN-2012		MOS HRS/MSC ENC	- 				
SB 72-0862	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITHOUT MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
12-JAN-2012		MOS HRS/MSC ENC	- 				
SB 72-0863	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING (SUPERSEDED BY 72-0863 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0863 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING (SUPERSEDED BY 72-0863 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0863 R2	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING, SERVICE BULLETIN					RECOMMENDED	
22-MAY-2012		MOS HRS/MSC ENC	- 				
SB 72-0864	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 2 AND STAGE 3 SHROUDS AND STAGE 4 THROUGH 8 VANE ASSEMBLIES AND SECTORS, SERVICE BULLETIN					RECOMMENDED	
25-AUG-2011		MOS HRS/MSC ENC	- 				
SB 72-0865	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMLY (72-54-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
08-DEC-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0866	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY FOR ATTACHMENT OF J5 HARNESS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
14-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0867	NO. 1 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - RELEASE OF NEW HPT STATOR SHROUD, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-APR-2012		HRS/MSC	-				
		ENC					
SB 72-0868	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITHOUT MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0869	NO. 1 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - RELEASE OF SPD AIR DUCT SLEEVE P/N 1812M68G02, SERVICE BULLETIN						
		MOS					
02-NOV-2011		HRS/MSC	-				
		ENC					
SB 72-0871	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - HPC STAGE 4 THROUGH STAGE 9 BLADE LOCK ON-WING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)				
19-OCT-2011		HRS/MSC					
		ENC					
SB 72-0871 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - HPC STAGE 4 THROUGH STAGE 9 BLADE LOCK ON-WING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-APR-2012		HRS/MSC	DUE (s)				
		ENC					
SB 72-0872	NO. 1 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 3 BLADES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
12-DEC-2012		HRS/MSC	-				
		ENC					
SB 72-0873	NO. 1 ENGINE - LPT SHAFT ASSEMBLY (72-55-00) - INTRODUCTION OF A NEW SEAL ON THE CENTER VENT TUBE, SERVICE BULLETIN						
		MOS					
27-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0874	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-OCT-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0874 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS (SUPERSEDED BY SB 72-0874 R2), SERVICE BULLETIN					RECOMMENDED	
08-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0874 R2	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS, SERVICE BULLETIN					CATEGORY 4	
14-JUL-2014		MOS HRS/MSC ENC	-				
SB 72-0875	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
23-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0876	NO. 1 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-00-02) - INSPECTION OF FUEL NOZZLE SUPPLY TUBE NO. 7 FOR WEAR OR CLOSE CLEARANCE, SERVICE BULLETIN					RECOMMENDED	
27-DEC-2011		MOS HRS/MSC ENC	12 (s)				
SB 72-0877	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
18-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0878	NO. 1 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - FUEL MANIFOLD SUPPORT BRACKETS AND IGNITER CABLE BRACKET ASSEMBLY REDESIGN, SERVICE BULLETIN					OPTIONAL	
21-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0879 R1	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSEMBLY AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
12-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0879 R3	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSEMBLY AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN					CATEGORY 6	
15-JAN-2014		MOS HRS/MSC ENC	-				
SB 72-0880	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF TECH INSERTION INNER COMBUSTION CHAMBER LINER INTO MULTI-HOLE COOLING PATCH WITH THIN TBC CONFIGURATION, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2012		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0881	NO. 1 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - HPT STATOR AIR IMPINGEMENT MANIFOLD REWORK, SERVICE BULLETIN					RECOMMENDED	
11-APR-2012		MOS HRS/MSC ENC	- 				
SB 72-0882	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
26-SEP-2012		MOS HRS/MSC ENC	- 				
SB 72-0884	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REPETITIVE ON-WING INSPECTION OF THE FAN BLADE PLATFORMS, SERVICE BULLETIN					RECOMMENDED	
24-JAN-2012		MOS HRS/MSC ENC	12 (s) 				
SB 72-0885	NO. 1 ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 2 BLADES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0886	NO. 1 ENGINE - ENGINE - HPT BLADES (72-52-01) - INSPECTION OF HPT BLADES - INDIA REGION, SERVICE BULLETIN					RECOMMENDED	
27-FEB-2012		MOS HRS/MSC ENC	 400 (s)				
SB 72-0886 R1	NO. 1 ENGINE - ENGINE - HPT BLADES (72-52-01) - INSPECTION OF HPT BLADES - INDIA REGION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0888	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THICK TBC, SERVICE BULLETIN					RECOMMENDED	
30-AUG-2012		MOS HRS/MSC ENC	- 				
SB 72-0888 R1	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF NEW OUTER LINERS WITH A MORE DURABLE AFT OUTER SUPPORT AND THICK TBC, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
03-JAN-2013		MOS HRS/MSC ENC	- 				
SB 72-0889	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THIN TBC, SERVICE BULLETIN					RECOMMENDED	
23-AUG-2012		MOS HRS/MSC ENC	- 				
SB 72-0889 R1	NO. 1 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THIN TBC, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
17-OCT-2012		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0890	NO. 1 ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION CHAMBER ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-AUG-2012		HRS/MSC	-				
		ENC					
SB 72-0892	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
13-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0893	NO. 1 ENGINE - INTRODUCTION OF A NEW BOLT-WASHER ASSEMBLY TO IMPROVE THE FLANGE ASSEMBLY ATTACHMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0894	NO. 1 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF A NEW COMPRESSOR ROTOR STAGES 4 THROUGH 9 SPOOL ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-MAR-2012		HRS/MSC	-				
		ENC					
SB 72-0894 R1	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF A NEW COMPRESSOR ROTOR STAGES 4 THROUGH 9 SPOOL ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0895	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF 76 BLADE HPT ROTOR KIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0895 R1	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF 76 BLADE HPT ROTOR KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0897	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT ASSEMBLY (72-55-00) - REPETITIVE REPAIR OF THE AIR/OIL SEPARATOR IN SHOP, SERVICE BULLETIN						
		MOS					
20-MAR-2012		HRS/MSC	-				
		ENC					
SB 72-0897 R1	NO. 1 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT ASSEMBLY (72-55-00) - REPETITIVE REPAIR OF THE AIR/OIL SEPARATOR IN SHOP, SERVICE BULLETIN						
		MOS					
28-MAR-2013		HRS/MSC	-				
		ENC					
SB 72-0898	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-MAR-2012		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618817

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0899	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE SPLIT VANE REPAIR, SERVICE BULLETIN					RECOMMENDED	
17-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0900	NO. 1 ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 1 BLADES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0902	NO. 1 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - DELETION OF ALTERNATE COMBUSTION CHAMBER ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
20-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0903	NO. 1 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - REWORK OF N500 MATERIAL HPT STATOR SHROUDS, SERVICE BULLETIN					RECOMMENDED	
12-APR-2013		MOS HRS/MSC ENC	-				
SB 72-0904 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW AIR/OIL SEPARATOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
17-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0907	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7BE BASELINE CONFIGURATION HARDWARE RELEASED TO EARLIER CFM56-7B SAC ENGINE MODELS, SERVICE BULLETIN					INFORMATIONAL	
04-JUN-2013		MOS HRS/MSC ENC	-				
SB 72-0909	NO. 1 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE PLATFORM, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
20-NOV-2012		MOS HRS/MSC ENC	-				
SB 72-0911	NO. 1 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
17-JUL-2012		MOS HRS/MSC ENC	-				
SB 72-0912	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
27-SEP-2012		MOS HRS/MSC ENC	-				
SB 72-0913	NO. 1 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
05-NOV-2012		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618818

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0914	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
25-MAR-2013		MOS HRS/MSC ENC	- 				
SB 72-0914 R1	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
12-APR-2013		MOS HRS/MSC ENC	- 				
SB 72-0915	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
30-NOV-2012		MOS HRS/MSC ENC	- 				
SB 72-0916	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE SPLIT VANE REPAIR, SERVICE BULLETIN						
15-JAN-2013		MOS HRS/MSC ENC	- 				
SB 72-0917	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW OIL SCAVENGE TUBE CLAMP, SERVICE BULLETIN					RECOMMENDED	
16-OCT-2012		MOS HRS/MSC ENC	- 				
SB 72-0918	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT (SUPERSEDED BY SB 72-0918 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0918 R1	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					CATEGORY 4	
11-JUN-2014		MOS HRS/MSC ENC	- 				
SB 72-0920	NO. 1 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT NOZZLE KIT, SERVICE BULLETIN					LIMITED DISTRIBUTION	
15-NOV-2013		MOS HRS/MSC ENC	- 				
SB 72-0921	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE (SUPERSEDED BY 72-0921 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0921 R1	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE (SUPERSEDED BY SB 72-0921 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618819

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0921 R2	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE, SERVICE BULLETIN					CATEGORY 5	
		MOS					
09-DEC-2013		HRS/MSC	-				
		ENC					
SB 72-0922	NO. 1 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
25-FEB-2013		HRS/MSC	-				
		ENC					
SB 72-0924	NO. 1 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BRACKET ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	
		MOS					
23-JUL-2014		HRS/MSC	-				
		ENC					
SB 72-0926	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON-WING INSPECTION OF VSV STAGE 3 OUTER BUSHINGS (SUPERSEDED BY SB 72-0926 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0926 R1	NO. 1 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON-WING INSPECTION OF VSV STAGE 3 OUTER BUSHINGS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0927	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - DELETION OF BALL BEARING 335-304-401-0 ALTERNATIVE FOR THE HANDCRANKING LINE (SUPERSEDED BY SB 72-0927 R1), SERVICE BULLETIN						
		MOS					
03-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0927 R1	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - DELETION OF BALL BEARING 335-304-401-0 ALTERNATIVE FOR THE HANDCRANKING LINE, SERVICE BULLETIN					CATEGORY 3	
		MOS					
14-APR-2014		HRS/MSC	ESV				
		ENC					
SB 72-0928	NO. 1 ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - REPLACEMENT OF LPT STAGE 1 NOZZLE SEGMENTS DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS					
22-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0929	NO. 1 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR DISK AIR SLOT REDESIGN, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
06-AUG-2013		HRS/MSC	-				
		ENC					
SB 72-0930	NO. 1 ENGINE - ENGINE - HPT/LPT SHROUD NOZZLE ASSEMBLY (72-53-00) - FORWARD FLANGE WEAR GROOVE HPT/LPT SHROUD NOZZLE SUPPORT REWORK, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
02-OCT-2013		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618820

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0931	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW THICKER FAN CONTAINMENT CASE (SUPERSEDED BY SB 72-0931 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0931 R1	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW THICKER FAN CONTAINMENT CASE, SERVICE BULLETIN					CATEGORY 7	
10-JAN-2014		MOS HRS/MSC ENC	-				
SB 72-0933	NO. 1 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW CUP TO ATTACH THE OUTER PLATFORM OF THE OGV TO THE CONTAINMENT CASE, SERVICE BULLETIN					CATEGORY 7	
20-FEB-2014		MOS HRS/MSC ENC	-				
SB 72-0934	NO. 1 ENGINE - COMBUSTION ASSEMBLY (72-41-00) - REWORK OF THE COMBUSTION CASE P/N 2002M81G09, SERVICE BULLETIN					CATEGORY 7	
14-FEB-2014		MOS HRS/MSC ENC	-				
SB 72-0935	NO. 1 ENGINE - HPT ROTOR ASSEMBLY (72-52-00) - INTRODUCTION OF HPT ROTOR BLADE P/N 2403M91P03 AND 76-BLADE HPT ROTOR KIT, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
03-SEP-2013		MOS HRS/MSC ENC	-				
SB 72-0938	NO. 1 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - INTRODUCTION OF A NEW METALLIC C-SEAL TO THE SPARE PARTS LIST, SERVICE BULLETIN					RECOMMENDED	
04-SEP-2013		MOS HRS/MSC ENC	-				
SB 72-0939	NO. 1 ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - INTRODUCTION OF HPT STATOR SHROUD P/N 2080M28P06, SERVICE BULLETIN					CATEGORY 7	
21-NOV-2013		MOS HRS/MSC ENC	-				
SB 72-0940	NO. 1 ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - FORWARD INNER NOZZLE SUPPORT REWORK BY FORWARD FLANGE REPLACEMENT AND APPLICATION OF EROSION COATING (SUPERSEDED BY SB 72-0940 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0940 R1	NO. 1 ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - FORWARD INNER NOZZLE SUPPORT REWORK BY FORWARD FLANGE REPLACEMENT AND APPLICATION OF EROSION COATING, SERVICE BULLETIN					CATEGORY 7	
04-FEB-2014		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0946	NO. 1 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - REPLACEMENT OF FORWARD DAMPER SLEEVE FOR THE HPT ROTOR FRONT SHAFTS P/N 2048M21P01 AND P/N 2048M21P03 (SUPERSEDED BY SB 72-0946 R1), SERVICE BULLETIN					CATEGORY 4	
29-JAN-2014		MOS HRS/MSC ENC	- 				
SB 72-0946 R1	NO. 1 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - REPLACEMENT OF FORWARD DAMPER SLEEVE FOR THE HPT ROTOR FRONT SHAFTS P/N 2048M21P01 AND P/N 2048M21P03, SERVICE BULLETIN					CATEGORY 4	
06-MAY-2014		MOS HRS/MSC ENC	- 				
SB 72-0952	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF IMPROVED CAST INCO 718 BLADE LOCKS FOR STAGES 4 THROUGH 9, SERVICE BULLETIN					CATEGORY 7	
14-JUL-2014		MOS HRS/MSC ENC	- 				
SB 72-223	NO. 1 ENGINE - INTRODUCTION OF A NEW OUTER LINER LUG RING TO THE SPARE PARTS LIST, SERVICE BULLETIN						
02-FEB-2000		MOS HRS/MSC ENC	- 				
SB 72-A0140 R1	NO. 1 ENGINE - INTRODUCTION OF A BONDED CAUTION PLATE ON HANDCRANKING COVER, SERVICE BULLETIN						
25-JUN-1999		MOS HRS/MSC ENC	- 				
SB 72-A0336	NO. 1 ENGINE - INSTALLATION OF SAFETY WIRE OVER THE OIL TEMPERATURE PROBE AND HOUSING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-A0368	NO. 1 ENGINE - ACCESSORY GEARBOX - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A DEFECTIVE BATCH, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0001	NO. 1 ENGINE - INTRODUCTION OF NEW IGNITER PLUG, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 73-0002	NO. 1 ENGINE - EEC-SOFTWARE VERSION 7.B.D, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0008R1
		MOS HRS/MSC ENC	- 				
SB 73-0003	NO. 1 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	73-0003 R1	NO. 1 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0007
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0003 R2	NO. 1 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0004	NO. 1 ENGINE - HMU 1853M56P05(VIN 442026), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0020
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0005	NO. 1 ENGINE - ELECTRONIC CONTROL UNIT (73-00-00) PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0005 R1	NO. 1 ENGINE - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS (SUPERSEDED BY SB 73-0005 R2), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0005 R2	NO. 1 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS, SERVICE BULLETIN					CATEGORY 3	
	29-OCT-2013		MOS					
			HRS/MSC	-				
			ENC					
SB	73-0005 R3	NO. 1 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS (SUPERSEDED BY SB 73-0005 R4), SERVICE BULLETIN					SUPERSEDED	
			MOS					
			HRS/MSC	-				
			ENC					
SB	73-0005 R4	NO. 1 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS, SERVICE BULLETIN					CATEGORY 3	
	14-JUL-2014		MOS					
			HRS/MSC	ESV				
			ENC					
SB	73-0006 R1	NO. 1 ENGINE - TRANSFER OF THE COOLING AIR ORIFICE PLATE TO THE EEC COMPONENT ASSEMBLY LEVEL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	73-0007	NO. 1 ENGINE - INTRODUCTION OF NEW MAIN FUEL PUMP WITH A NEW STATIONARY SHAFT SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			

© Camp Systems

EFTA00618823

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0008 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.E., SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0009
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0009	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F (7B2B), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0012
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0010	NO. 1 ENGINE - DRAIN TUBE AND FUEL MANIFOLD REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0011	NO. 1 ENGINE - INTRODUCTION OF A SERVO FUEL HEATER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0011 R1	NO. 1 ENGINE - INTRODUCTION OF A SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0012	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F3 (7B2E), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0015
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0013	NO. 1 ENGINE - OPERATE CFM USING CIS TS-1 FUELS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0014 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0015	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F4 (7B31), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0018R1
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0017	NO. 1 ENGINE - INTRODUCTION OF ECU/EEC HARDWARE/SOFTWARE KITS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0018 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.G (7B30), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0021R1
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0019	NO. 1 ENGINE - NEW FUEL TRANSIENT BLEED VALVE MANIFOLD AND SUPPORTING BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0020	NO. 1 ENGINE - INTRODUCTION OF HMU VIN 442098 (GE 1853M56P06), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0021 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.H2 (7B36), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0023R1
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0022	NO. 1 ENGINE - MODIFICATION OF FUEL NOZZLE FILTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0023	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I (7B37), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0023 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I(7B37), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0024
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0024	NO. 1 ENGINE - EEC-SOFTWARE VERSION 7.B.I1 (7B38), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0025	NO. 1 ENGINE - MODIFICATION OF THE FUEL NOZZLE FILTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0026	NO. 1 ENGINE - INTRODUCTION OF EEC- SOFTWARE VERSION 7.B.J(7B3A), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0027	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0028	NO. 1 ENGINE - INTRODUCTION TO HMU 1853M56P07 (VIN 442124), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618825

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	73-0028 R1	NO. 1 ENGINE - INTRODUCTION TO HMU 1853M56P07 (VIN 442124), SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0029	NO. 1 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0029 R1	NO. 1 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0029 R2	NO. 1 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0030	NO. 1 ENGINE - ECU/EECS WITH DPM-3 CONVERSION, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0030 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (73-00-00) - INTRODUCTION OF NEW ECU/EECS WITH NEW DPM-3 AND CONVERSION, SERVICE BULLETIN					OPTIONAL	
	22-FEB-2011		MOS HRS/MSC - ENC					
SB	73-0031	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
			MOS HRS/MSC - ENC					
SB	73-0032	NO. 1 ENGINE - REPLACEMENT OF VESPEL BALL P/N 1419-240, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0033	NO. 1 ENGINE - CONVERSION NON-PMUX ENGINE AND PMUX TO NON-PMUX ENGINE, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0034	NO. 1 ENGINE - INTRODUCTION OF NEW FIEL PUMP WITH NEW FILTER COVER, SERVICE BULLETIN						
			MOS HRS/MSC - ENC					
SB	73-0035	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.J1 (7B2D), SERVICE BULLETIN						
			MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0036	NO. 1 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC - ENC					
SB 73-0037	NO. 1 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R1	NO. 1 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R2	NO. 1 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R3	NO. 1 ENGINE - HPSOV SWITCH, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC - ENC					
SB 73-0037 R4	NO. 1 ENGINE - HYDROMECHANICAL UNIT - HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R5	NO. 1 ENGINE - HYDROMECHANICAL UNIT - HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0038	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL FLOW TRANSMITTER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0039	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0040	NO. 1 ENGINE - ENGINE FUEL CONTROL INTRODUCTION OF SOFTWARE 1853M78P16 (7B41), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0041	NO. 1 ENGINE - INTRODUCTION OF A NEW VSV RIGHT SIDE DRAIN MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618827

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0042	NO. 1 ENGINE - NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0042 R1	NO. 1 ENGINE - NEW FUEL DIFFERNTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043	NO. 1 ENGINE - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043 R1	NO. 1 ENGINE - ELECTRONIC CONTROL UNIT - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043 R2	NO. 1 ENGINE - ELECTRONIC FUEL CONTROL - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044	NO. 1 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044 R1	NO. 1 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044 R2	NO. 1 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0045	NO. 1 ENGINE - NEW HPTCC VALVE FUEL MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0046	NO. 1 ENGINE - ENGINE FUEL CONTROL INTRODUCTION OF SOFTWARE 1853M78P17 (7B42), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0047	NO. 1 ENGINE - LOWER DRAIN MANIFOLD IDENTIFICATION PLATE FIELD REPLACEMENT AND NEW LOWER DRAIN MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0047 R1	NO. 1 ENGINE - LOWER DRAIN MANIFOLD IDENTIFICATION PLATE FIELD REPLACEMENT AND NEW LOWER DRAIN MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0049	NO. 1 ENGINE - INSPECTION OF HMU MAIN BODY FOR HPT2 THIN WALL CASTING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0050	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL INTRODUCTION OF SOFTWARE 1853M78P18 (7B46), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0050 R1	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 1853M78P18 (7B46), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0051	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0052	NO. 1 ENGINE - INTRODUCTION OF A NEW IMPELLER DRIVE SHAFT AND IMPELLER DRIVE SHAFT PREFORMED PACKING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0052 R2	NO. 1 ENGINE - ENGINE FUEL CONTROL (73-00-00) - MAIN FUEL PUMP - INTRODUCTION OF A NEW IMPELLER DRIVE SHAFT AND IMPELLER DRIVE SHAFT PREFORMED PACKING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053	NO. 1 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053 R1	NO. 1 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0053 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053 R3	NO. 1 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0054	NO. 1 ENGINE - FIELD DELETION BURN STAGE VALVE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0054 R1	NO. 1 ENGINE - CORE ENGINE MAJOR MODULE - FIELD DELETION OF THE BURNER STAGING VALVE SYSTEM, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0055	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P19 (7B4A), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0055 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P19 (7B4A), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0056	NO. 1 ENGINE - , SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0057	NO. 1 ENGINE - SPARE PARTS RELEASE FOR BAE SYSTEMS CONTROLS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0058	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CFM56-7B SAC ENGINE CONFIGURATIONS J9 AND J10 HARNESS WITH IMPROVED OR REWORKED DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0058 R1	NO. 1 ENGINE - CFM56-7B SAC ENGINE CONFIGURATIONS J9 AND J10 HARNESSES WITH IMPROVED OR REWORKED DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0059	NO. 1 ENGINE - ECU DPM INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0060	NO. 1 ENGINE - ENGINE FUEL CONTROL - INTRODUCTION OF A NEW SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0061	NO. 1 ENGINE - ENGINE FUEL AND CONTROL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0061 R1	NO. 1 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC - ENC					
SB 73-0061 R2	NO. 1 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0061 R3	NO. 1 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0062	NO. 1 ENGINE - INTRODUCTION OF NEW/REWORKED ECU WITH LOCKWIRE CAPABILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0062 R1	NO. 1 ENGINE - INTRODUCTION OF NEW OR REWORKED ELECTRONIC CONTROL UNIT WITH LOCKWIRE CAPABILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0063	NO. 1 ENGINE - INTRODUCTION OF FUEL MANIFOLDS WITH INTERNAL DRAIN PLUGS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0064	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P20, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618831

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0064 R1	NO. 1 ENGINE - ELCTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 1853M78P20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0065	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL - PRESSURE SUBSYSTEM, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0066	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF SPEED SERVO (MATCHED) VALVE AND SLEEVE ASSEMBLY AND THRUST WASHER., SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC ENC	-				
SB 73-0066 R1	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF SPEED SERVO (MATCHED) VALVE AND SLEEVE ASSEMBLY AND THRUST WASHER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0067	NO. 1 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0067 R1	NO. 1 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0067 R2	NO. 1 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0067 R3	NO. 1 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0068	NO. 1 ENGINE - REWORK OF THE HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) TO HYDROMECHANICAL UNIT VIN 442124 (GE 1853M56P07), SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0069	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618832

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0069 R1	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0069 R2	NO. 1 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0070	NO. 1 ENGINE - ELECTRONIC CONTROL UNIT - PRESSURE SUBSYSTEM CONVERSION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0071 R2	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 7. B. 01 1853M78P23, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0073	NO. 1 ENGINE - ENGINE FUEL CONTROL - ENGINE FUEL CONTROL (73-00-00) - RESISTOR MODIFICATION FOR PSS TRANSDUCER INCOMPATIBILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - INSPECTION OF SHUTOFF SPACER FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - INSPECTION OF SHUTOFF SPACER FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) INSPECTION OF SHUTOFF SPACER P/N 2687048 FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) INSPECTION OF SHUTOFF SPACER P/N 2687048 FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0075	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - HYDROMECHANICAL UNIT - INTRODUCTION OF IMPROVED VALVE EXTENSION AND FEEDBACK DRIVERS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0075 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - HYDROMECHANICAL UNIT - INTRODUCTION OF IMPROVED VALVE EXTENSION AND FEEDBACK DRIVERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0076	NO. 1 ENGINE - MEC SERVO FUEL HTR LEAKS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0077	NO. 1 ENGINE - FIELD REWORK OF SINGLE ANNULAR COMBUSTOR (SAC) FUEL MANIFOLDS TO ELIMINATE DEAD-END ZONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0078	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - INTRODUCTION OF A NEW FUEL FILTER ELEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS			01-MAR-2007		
		HRS/MSC	-		2871:05		
		ENC			646		
SB 73-0079	NO. 1 ENGINE - REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT OF THE FUEL FILTER COVER OF THE MAIN FUEL PUMP EQUIPPED WITH D-HEAD BOLT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0080	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - REPLACEMENT OF SHUTOFF SPACER 2687048 WITH NEW DESIGN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0081	NO. 1 ENGINE - HYDROMECHANICAL UNIT (HMU) (73-21-10) - INTRODUCTION OF HONEYWELL HMU VIN 442317 (GE 1853M56P09), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0082	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 7.B.N 1853M78P21, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0083	NO. 1 ENGINE - REMOVAL AND TEST OF ELECTROHYDRAULIC SERVO VALVE FOR TEMPERATURE SENSITIVITY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0083 R1	NO. 1 ENGINE - REMOVAL AND TEST OF ELECTROHYDRAULIC SERVO VALVE FOR TEMPERATURE SENSITIVITY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0084	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 7.B.0 1853M78P22, SERVICE BULLETIN						
		MOS	6 (s)				
		HRS/MSC					
		ENC					
SB 73-0084 R1	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE 7.B.0 1853M78P22, SERVICE BULLETIN						
		MOS	6 (s)				
		HRS/MSC					
		ENC					
SB 73-0085 R1	NO. 1 ENGINE - INTRODUCTION OF NEW J10 HARNESSES OR REWORK OF THE OLD ONES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0086	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0088	NO. 1 ENGINE - IMPROVED FUEL FLOW TRANSMITTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0089	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE HARNESSES CJ9, CJ10 (73-24-05) - INTRODUCTION OF A NEW CJ9 HARNESS OR REWORK OF THE OLD ONE AND DELETION OF THE DUMMY RECEPTACLE BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0090	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0090 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0093	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10) -INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVO VALVE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0094	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10)- INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0094 R1	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0094 R2	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0095	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED BURNER STAGING VALVE (BSV) SOLENOID AND VALVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0096 R1	NO. 1 ENGINE - REPLACEMENT OF FLUOROSILICONE PREFORMED PACKINGS WITH FLUOROCARBON PREFORMED PACKINGS (SUPERSEDED BY 73-0096 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0096 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HMU (73-21-79) - REPLACEMENT OF FLUOROSILICONE PREFORMED PACKINGS WITH FLUOROCARBON PREFORMED PACKINGS, SERVICE BULLETIN					RECOMMENDED	
05-JAN-2012		MOS HRS/MSC ENC	-				
SB 73-0097	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-00-00) - NEW 7.B.P SOFTWARE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	6 (s)				
SB 73-0097 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-00-00) - NEW 7.B.P SOFTWARE, SERVICE BULLETIN						
08-MAR-2005		MOS HRS/MSC ENC	6 (s)				
SB 73-0098	NO. 1 ENGINE - ECU CHASSIS MODIFICATION (SUPERSEDED BY SB 73-0098 R1), SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0098 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU CHASSIS MODIFICATION, SERVICE BULLETIN					CATEGORY 7	
01-APR-2014		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0099	NO. 1 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED ADJUSTMENT SCREW (PN 2689127), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-01	NO. 1 ENGINE - FUEL FLOW TRANSMITTER CALIBRATION IMPROVEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0100	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102	NO. 1 ENGINE - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400HZ DISCONNECTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R1	NO. 1 ENGINE - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400HZ DISCONNECTS, SERVICE BULLETIN						
07-MAR-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400 HZ DISCONNECTS (SUPERSEDED BY SB 73-0102 R3), SERVICE BULLETIN					RECOMMENDED	
10-NOV-2010		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400 HZ DISCONNECTS, SERVICE BULLETIN					CATEGORY 7	
20-JUN-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0103	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT(73-21-10) - LOW PRESSURE LEAK CHECK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0104	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - ONE TIME INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AND INTRODUCTION OF KEVLAR CUSHION CLAMPS, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS			22-AUG-2008		
		HRS/MSC	-		3260:48		
		ENC			746		
SB 73-0106	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU PMUX (73-00-00) - PRESSURE SUBSYSTEM REDESIGN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0106 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU PMUX (73-00-00) - PRESSURE SUBSYSTEM REDESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0107	NO. 1 ENGINE - INSPECTION OF PUMP COVER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0108 R1	NO. 1 ENGINE - BURNER STAGING VALVE SOLENOID REMOVAL FROM HMU, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0108 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HMU (73-21-79) - BURNER STAGING VALVE SOLENOID REMOVAL FROM HMU, SERVICE BULLETIN					RECOMMENDED	
16-FEB-2012		MOS HRS/MSC ENC	-				
SB 73-0109 R1	NO. 1 ENGINE - NEW SOLENOID AND VALVE, SERVICE BULLETIN						
07-MAR-2006		MOS HRS/MSC ENC	-				
SB 73-0111	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-00-00) - INTRODUCTION OF FADEC3 HARDWARE AND SOFTWARE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0113	NO. 1 ENGINE - INSPECTION OF MAIN-STAGE CHECK VALVE SPRING (SUPERSEDED BY 73-0113 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0113 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL NOZZLES (73-00-00) - INSPECTION OF MAIN-STAGE CHECK VALVE SPRING, SERVICE BULLETIN					RECOMMENDED	
13-JAN-2012		MOS HRS/MSC ENC	-				
SB 73-0115	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.Q SOFTWARE, SERVICE BULLETIN						
06-JUN-2005		MOS HRS/MSC ENC	6 (s)				
SB 73-0115 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.Q SOFTWARE, SERVICE BULLETIN						
30-MAY-2008		MOS HRS/MSC ENC	6 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0116	NO. 1 ENGINE - INTRODUCTION OF NEW ELECTRONIC CONTROL UNIT WITH SAFETYWIRE CAPABILITY TO THE IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0116 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - INTRODUCTION OF NEW ELECTRONIC CONTROL UNIT WITH SAFETYWIRE CAPABILITY TO THE IPC, SERVICE BULLETIN						
13-NOV-2009		MOS HRS/MSC ENC	- 				
SB 73-0117	NO. 1 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0118 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH A NEW COVER, SERVICE BULLETIN						
23-FEB-2006		MOS HRS/MSC ENC	- 				
SB 73-0120	NO. 1 ENGINE - NEW SOFTWARE VERSION 7.B.Q1F3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0120 R1	NO. 1 ENGINE - NEW SOFTWARE VERSION 7.B.Q1F3, SERVICE BULLETIN						
30-MAY-2008		MOS HRS/MSC ENC	- 				
SB 73-0121	NO. 1 ENGINE - FRONT PANEL ASSEMBLY ALIGNMENT PIN MODIFICATION PROCEDURE, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 73-0122	NO. 1 ENGINE - FADEC3 -SIA CONNECTOR HARDWARE RETENTION, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 73-0123	NO. 1 ENGINE - VSV SYSTEM (72-00-02) - NEW FUEL MANIFOLDS, SERVICE BULLETIN						
12-APR-2006		MOS HRS/MSC ENC	- 				
SB 73-0124	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
21-APR-2008		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0126	NO. 1 ENGINE - ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS , SERVICE BULLETIN						
		MOS					
17-JUL-2006		HRS/MSC	-				
		ENC					
SB 73-0126 R1	NO. 1 ENGINE - ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS, SERVICE BULLETIN						
		MOS					
14-AUG-2007		HRS/MSC	-				
		ENC					
SB 73-0126 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU MODIFICATION, ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS, SERVICE BULLETIN						
		MOS					
02-OCT-2009		HRS/MSC	-				
		ENC					
SB 73-0127	NO. 1 ENGINE - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
17-JUL-2006		HRS/MSC	-				
		ENC					
SB 73-0127 R1	NO. 1 ENGINE - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
26-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0127 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU MODIFICATION - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS 9SUPERSEDED BY 73-0127 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0127 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (73-00-00) - ECU/EEC MODIFICATION - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0128 R1	NO. 1 ENGINE - INTRODUCTION OF FADEC3 HARDWARE FOR DAC ENGINES, SERVICE BULLETIN						
		MOS					
02-APR-2007		HRS/MSC	-				
		ENC					
SB 73-0130	NO. 1 ENGINE - INSPECTION OF HYDROMECHANICAL UNIT FOR NON-HYDROCARBON CONTAMINATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)				
07-MAY-2007		HRS/MSC	1500				
		ENC					
SB 73-0132	NO. 1 ENGINE - INTRODUCTION OF FUEL NOZZLE WITH REVISED O-RING MATERIAL FOR HIGHER TEMPERATURE CAPABILITY, SERVICE BULLETIN						
		MOS					
13-JUN-2007		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0132 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - INTRODUCTION OF FUEL NOZZLE WITH REVISED O-RING MATERIAL FOR HIGHER TEMPERATURE CAPABILITY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JUN-2012		HRS/MSC	-				
		ENC					
SB 73-0133	NO. 1 ENGINE - REPLACEMENT OF SUSPECT T12 SENSOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER S/N 874437 N/A
		MOS		08-NOV-2007			
12-APR-2007		HRS/MSC	1200 (s)/DUE				
		ENC					
SB 73-0134	NO. 1 ENGINE - INTRODUCTION OF NEW UNISON ALTERNATOR STATOR VIN 506569-1 (2123M63P02) AND ALTERNATOR ROTOR VIN 505344-1 (2123M62P01), SERVICE BULLETIN						
		MOS					
08-JUN-2007		HRS/MSC	-				
		ENC					
SB 73-0134 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - POWERPLANT - ALTERNATOR (73-00-00) - INTRODUCTION OF NEW UNISON ALTERNATOR STATOR VIN 506569-1 (2123M63P02) AND ALTERNATOR ROTOR VIN 505344-1 (2123M62P01), SERVICE BULLETIN						
		MOS					
04-MAY-2009		HRS/MSC	-				
		ENC					
SB 73-0135	NO. 1 ENGINE - NEW SOFTWARE VERSION 7.B.R3, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
30-MAR-2007		HRS/MSC	-	3260:48			
		ENC		746			
SB 73-0135 R1	NO. 1 ENGINE - NEW SOFTWARE VERSION 7.B.R3, SERVICE BULLETIN						
		MOS					
30-MAY-2008		HRS/MSC	-				
		ENC					
SB 73-0136	NO. 1 ENGINE - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVOVALVE, SERVICE BULLETIN						
		MOS					
20-JUN-2007		HRS/MSC	-				
		ENC					
SB 73-0136 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVOVALVE, SERVICE BULLETIN						
		MOS					
18-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0137	NO. 1 ENGINE - HMU OVER-FUEL THRESHOLD MARGIN INCREASE, SERVICE BULLETIN						
		MOS					
20-JUN-2007		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618841

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0137 R1	NO. 1 ENGINE - HMU OVER-FUEL THRESHOLD MARGIN INCREASE, SERVICE BULLETIN						
18-FEB-2008		MOS HRS/MSC ENC	- 				
SB 73-0138	NO. 1 ENGINE - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 73-0138 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R1 PARA 3.A	NO. 1 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU						
		MOS HRS/MSC ENC	 10000 (s)				
SB (3) 73-0138 R1 PARA 3.A	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS						
		MOS HRS/MSC ENC	 3000 (s) 				
SB 73-0138 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R2 PARA 3.A	NO. 1 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	 10000 (s) 				
SB (3) 73-0138 R2 PARA 3.A	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	 3000 (s) 				
SB 73-0138 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
12-SEP-2011		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R3 PARA 3.A	NO. 1 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU					RECOMMENDED	
		MOS HRS/MSC ENC	 10000 (s) 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0138 R3 PARA 3.A (3)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
		MOS					
		HRS/MSC	3000 (s)				
		ENC					
SB 73-0138 R4	NO. 1 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	-				
		ENC					
SB 73-0138 R4 PARA 3.A (1)	NO. 1 ENGINE - FLOW ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN CHECK OF ALL FUEL NOZZLES					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	ESV (s)				
		ENC					
SB 73-0138 R4 PARA 3.A (2)	NO. 1 ENGINE - CLEAN ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND OVERHAUL HMU					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	10000 (s)/ESV				
		ENC					
SB 73-0138 R4 PARA 3.A (3)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	3000 (s)				
		ENC					
SB 73-0139	NO. 1 ENGINE - NEW SOFTWARE VERSION 7.B.S, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
12-OCT-2007		HRS/MSC	-		3260:48		
		ENC			746		
SB 73-0140	NO. 1 ENGINE - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-78 ENGINES, SERVICE BULLETIN						
		MOS					
28-NOV-2007		HRS/MSC	-				
		ENC					
SB 73-0140 R1	NO. 1 ENGINE - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0140 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-21-60) - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
13-APR-2009		HRS/MSC	-				
		ENC					
SB 73-0140 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-21-60) - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-FEB-2012		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618843

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0141	NO. 1 ENGINE - FRONT TRANSIENT PROTECTION BOARD FUSE INSPECTION AND REWORK ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS	4 (s)				
	28-NOV-2007	HRS/MSC					
		ENC					
SB 73-0142 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRICAL HARNESS CJ9, CJ10 (73-24-05) - DELETION OF CJ9 WIRING HARNESS T5 BRANCH FOR NON-PMUX ENGINE IN THE FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0143	NO. 1 ENGINE - PRESSURE SUBSYSTEM (PSS) TRANSDUCER RELIABILITY IMPROVEMENT, SERVICE BULLETIN						
		MOS					
	21-FEB-2008	HRS/MSC	-				
		ENC					
SB 73-0144	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
	04-APR-2008	HRS/MSC	-				
		ENC					
SB 73-0145	NO. 1 ENGINE - ENGINE FUEL AND CONTROL SYSTEM (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
	25-AUG-2008	HRS/MSC	-				
		ENC					
SB 73-0146	NO. 1 ENGINE - REPLACEMENT OF SUSPECTED J7 WIRING HARNESS, SERVICE BULLETIN						
		MOS					
	08-APR-2008	HRS/MSC					
		ENC	5 (s)				
SB 73-0151 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.T SOFTWARE VERSION, SERVICE BULLETIN						
		MOS					
	27-FEB-2009	HRS/MSC	-				
		ENC					
SB 73-0152	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
	08-OCT-2009	HRS/MSC	-				
		ENC					
SB 73-0153	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INSPECTION OF MAIN BODY ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0154	NO. 1 ENGINE - FADEC3 - CFM56-7B - EEC/ECU CONVERSION FROM P/N 2042M67P02 TO P/N 2042M67P04, SERVICE BULLETIN						
		MOS					
	04-MAY-2009	HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0154 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FADEC3 - CFM56-7B - EEC/ECU CONVERSION FROM P/N 2042M67P02 TO P/N 2042M67P04, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0156	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE HARNESSES CJ9, CJ10 (73-24-05) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
16-NOV-2011		MOS HRS/MSC ENC	-				
SB 73-0157	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN					RECOMMENDED	
21-JUL-2009		MOS HRS/MSC ENC	6 (s)				
SB 73-0157 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN						
14-AUG-2009		MOS HRS/MSC ENC	6 (s)				
SB 73-0157 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN						
02-FEB-2010		MOS HRS/MSC ENC	6 (s)				
SB 73-0158	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF MODIFIED METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
15-MAY-2009		MOS HRS/MSC ENC	-				
SB 73-0159	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - INTRODUCTION OF FADEC3 ECU/EEC WITH NEW MAIN CHANNEL BOARD, SERVICE BULLETIN						
09-DEC-2009		MOS HRS/MSC ENC	-				
SB 73-016 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-00-00) - SCHEDULED INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE HYDROMECHANICAL UNIT (HMU) PART NUMBER
		MOS HRS/MSC ENC	-				
SB 73-0161	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
21-JUL-2009		MOS HRS/MSC ENC	-				
SB 73-0163	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
05-OCT-2009		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618845

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0167	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ECU MODIFICATION -REPLACEMENT OF CR1 AND CR14 RECTIFIERS ON THE PSM (SUPERSEDED BY 73-0167 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- -				
SB 73-0167 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ECU MODIFICATION - REPLACEMENT OF CR1 AND CR14 RECTIFIERS ON THE PSM, SERVICE BULLETIN					RECOMMENDED	
04-JAN-2012		MOS HRS/MSC ENC	- -				
SB 73-0169	NO. 1 ENGINE - ENGINE FUEL AND CONTROL-ELECTRONIC CONTROL UNIT (73-00-00)-DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 73-0169 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN					OPTIONAL	
13-JUL-2011		MOS HRS/MSC ENC	- -				
SB 73-0169 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION (SUPERSEDED BY SB 73-0169 R3), SERVICE BULLETIN					RECOMMENDED	
22-SEP-2011		MOS HRS/MSC ENC	- -				
SB 73-0169 R3	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN					CATEGORY 7	
17-APR-2014		MOS HRS/MSC ENC	- -				
SB 73-0170	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BODY NON-FERROUS RING CHIP CONTAMINATION (SUPERSEDED BY 73-0170 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- -				
SB 73-0170 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BODY NON-FERROUS RING CHIP CONTAMINATION, SERVICE BULLETIN					RECOMMENDED	
16-MAY-2011		MOS HRS/MSC ENC	- -				
SB 73-0171	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT MANUFACTURABILITY IMPROVEMENTS, SERVICE BULLETIN					OPTIONAL	
24-SEP-2010		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0172	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF FUEL METERING VALVE RESOLVER MODIFICATION , SERVICE BULLETIN					OPTIONAL	
17-DEC-2010		MOS HRS/MSC ENC	-				
SB 73-0172 R1	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF FUEL METERING VALVE RESOLVER MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
15-FEB-2012		MOS HRS/MSC ENC	-				
SB 73-0173	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - CFM56-7B ECU INSPECTION - IOM SOLDER JOINT CRACKING (SUPERSEDED BY SB 73-0173 R1), SERVICE BULLETIN					RECOMMENDED	
20-JAN-2011		MOS HRS/MSC ENC	-				
SB 73-0173 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - CFM56-7B ECU INSPECTION - IOM SOLDER JOINT CRACKING, SERVICE BULLETIN					CATEGORY 5	
17-APR-2014		MOS HRS/MSC ENC	-				
SB 73-0174	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					RECOMMENDED	
23-NOV-2010		MOS HRS/MSC ENC	-				
SB 73-0174 R1	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
19-JUL-2011		MOS HRS/MSC ENC	-				
SB 73-0174 R2	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE (SUPERSEDED BY SB 73-0193), SERVICE BULLETIN					SUPERSEDED	
01-MAY-2013		MOS HRS/MSC ENC	-				
SB 73-0175	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION (SUPERSEDED BY 73-0175 R1) , SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0175 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION, SERVICE BULLETIN					RECOMMENDED	
16-MAY-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0175 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION (SUPERSEDED BY SB 73-0194), SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-MAY-2013		HRS/MSC	-				
		ENC					
SB 73-0178	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V2, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-JUN-2011		HRS/MSC	-				
		ENC					
SB 73-0178 R2	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ENGINE #1 ECU SOFTWARE P/N 1853M78P33, VERSION 7B98 (7.B.V2 F2)
		MOS			28-AUG-2013		
17-AUG-2011		HRS/MSC	-		3728:53		
		ENC			875		
SB 73-0180	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY 73-0180 1R), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0180 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
23-MAY-2012		HRS/MSC	-				
		ENC					
SB 73-0181	NO. 1 ENGINE - ENGINE FUEL AND CONTROL-IDENTIFICATION PLUG (73-21-83) - INTRODUCTION OF NEW CODING COMBINATIONS FOR -7BE LPT HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0182	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN76 BRIDGE BGA ON ASELEC MANUFACTURED MAIN CHANNEL BOARDS (SUPERSEDED BY SB 73-0182 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 73-0182 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN76 BRIDGE BGA ON ASELEC MANUFACTURED MAIN CHANNEL BOARDS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0184	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF T2 AND T4 TRANSFORMER ON THE PSM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-FEB-2012		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0185	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - BUCK POWER SUPPLY U540 MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-OCT-2011		HRS/MSC	-				
		ENC					
SB 73-0186	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - REPETITIVE INSPECTION OF THE FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY SB 73-0192), SERVICE BULLETIN					SUPERSEDED	
		MOS					
28-NOV-2011		HRS/MSC	15000 (s)				
		ENC					
SB 73-0186 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - REPETITIVE INSPECTION OF THE FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY SB 73-0192), SERVICE BULLETIN						
		MOS					
29-MAR-2013		HRS/MSC	-				
		ENC					
SB 73-0188	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE THREE WAY TWO STAGE ELECTROHYDAULIC SERVO VALVE WITH VENTED SLEEVE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-FEB-2012		HRS/MSC	-				
		ENC					
SB 73-0189	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - IDENTIFICATION PLUG (73-24-06) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
18-JUN-2012		HRS/MSC	-				
		ENC					
SB 73-0190	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - REPLACEMENT OF THE FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					SUPERSEDED	
		MOS					
20-JUL-2012		HRS/MSC	- (s)				
		ENC					
SB 73-0190 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - REPLACEMENT OF THE FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0191	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V3, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
11-DEC-2012		HRS/MSC	-				
		ENC					
SB 73-0191 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V3, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-APR-2013		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618849

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0192	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - FUEL DIFFERENTIAL PRESSURE SWITCH MANAGEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0193	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
01-MAY-2013		HRS/MSC	-				
		ENC					
SB 73-0194	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-2013		HRS/MSC	ESV				
		ENC					
SB 73-0195	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ADDITION OF ARINC SERIES RESISTORS ON TX3 LINES TO ACCOMMODATE NEWER MCB MN52 DEVICE, SERVICE BULLETIN					OPTIONAL	
		MOS					
14-JUN-2013		HRS/MSC	-				
		ENC					
SB 73-0196	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN82 ARINC/CCDL/IMSB CONTROLLER ON TRONICO MANUFACTURED MAIN CHANNEL BOARDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2013		HRS/MSC	-				
		ENC					
SB 73-0198	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - INTRODUCTION OF NEW CONNECTORS FOR ELECTRICAL HARNESSES, SERVICE BULLETIN					CATEGORY 6	
		MOS					
20-FEB-2014		HRS/MSC	-				
		ENC					
SB 73-0199	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V4 (SUPERSEDED BY SB 73-0199 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0199 R1	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V4, SERVICE BULLETIN					CATEGORY 7	
		MOS					
28-JAN-2014		HRS/MSC	-				
		ENC					
SB 73-0203	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - NEW SOFTWARE VERSION 7.B.WF2 FOR DAC ENGINES, SERVICE BULLETIN					CATEGORY 2	
		MOS	12 (s)				
09-JUN-2014		HRS/MSC					
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0204	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - NEW SOFTWARE VERSIONS 7.B.WF3 FOR SAC AND DAC ENGINES AND 7.B.WF2 FOR SAC ENGINES, SERVICE BULLETIN					CATEGORY 2	
		MOS	12 (s)				
09-JUN-2014		HRS/MSC					
		ENC					
SB 73-A002	NO. 1 ENGINE - SERCK AVIATION SERVO FUEL HEATERS - IDENTIFICATION OF POTENTIAL LEAKING UNITS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-A0024	NO. 1 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I1 (7B38), SERVICE BULLETIN						
		MOS					
02-SEP-1998		HRS/MSC	-				
		ENC					
SB 73-A0034	NO. 1 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH NEW FILTER COVER, SERVICE BULLETIN						
		MOS					
23-JUL-1999		HRS/MSC	-				
		ENC					
SB 73-A0076	NO. 1 ENGINE - SERVO FUEL HEATERS - IDENTIFICATION OF POTENTIAL LEAKING UNITS, SERVICE BULLETIN						
		DAYS	30 (s)				
		HRS/MSC					
		ENC					
SB 73-A0091	NO. 1 ENGINE - INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AT CLAMP LOCATIONS, SERVICE BULLETIN					CANCELLED	NOT APPLICABLE
		MOS			22-AUG-2008		
		HRS/MSC	- (s)		3260:48		
		ENC			746		
SB 73-A0091 R1	NO. 1 ENGINE - INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AT CLAMP LOCATIONS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0001	NO. 1 ENGINE - INTRODUCTION OF NEW IGNITER PLUG, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0002	NO. 1 ENGINE - INTRODUCTION OF A NEW UNISON IGNITER PLUG, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0003	NO. 1 ENGINE - IGNITION - IGNITION SYSTEM (74-00-00) - SCREENING OF IGNITION UNIT EXCITER VIN 10-631045-2 (P/N 9238M66P08) FOR SUSPECT DIODES, SERVICE BULLETIN						
		MOS	18 (s)				
		HRS/MSC					
		ENC					

© Camp Systems

EFTA00618851

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	74-0004	NO. 1 ENGINE - IGNITION - IGNITION SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION UNIT EXCITER VIN 10-631045-3 (P/N 9238M66P11), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0001 R1	NO. 1 ENGINE - LPT ACC FUEL MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS			16-DEC-1998		
			HRS/MSC	-		0		
			ENC			0		
SB	75-0002	NO. 1 ENGINE - INTRODUCTION OF HPTC VALVE VIN 3291186-6 (CFMI 1821M59P06), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003 R1	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003 R2	NO. 1 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004	NO. 1 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0005	NO. 1 ENGINE - INSPECTION OF PS3 LINE FITTING, SERVICE BULLETIN					MANDATORY SCRAP	
	14-NOV-2001		MOS					
			HRS/MSC	-				
			ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0025 R1	NO. 1 ENGINE - INTRODUCTION OF REWORKED VBV ACUTATOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0027	NO. 1 ENGINE - MODIFICATION OF THE PS3 LINE FITTING CONNECTIONS TORQUE SEQUENCE AND ADDITION OF PERMANENT BONDING TO THE CAP, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0027 R1	NO. 1 ENGINE - AIR - COOLING AIR - MODIFICATION OF PS3 LINE FITTING CONNECTIONS TORQUE SEQUENCE AND ADDITION OF PERMANENT BONDING OF THE CAP, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0030	NO. 1 ENGINE - ENGINE AIR-TRANSIENT BLEED VALVE (72-00-02) - REWORK TRANSIENT BLEED VALVE PN 3291390-1 TO PN 3291390-3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0030 R1	NO. 1 ENGINE - AIR - AIR TRANSIENT BLEED VALVE (75-21-10) - REWORK OF TRANSIENT BLEED VALVE VIN 3291390-1 (P/N 1821M60P02) TO VIN 3291390-3 (P/N 1821M60P04), SERVICE BULLETIN						
		MOS					
14-JUL-2009		HRS/MSC	-				
		ENC					
SB 75-0032	NO. 1 ENGINE - REPLACEMENT OF VBV TURNBUCKLE (STEEL VERSION) BY NEW ONES WITH NEW MATERIAL (ALUMINIUM VERSION), SERVICE BULLETIN						
		MOS					
21-JUN-2005		HRS/MSC	-				
		ENC					
SB 75-0033	NO. 1 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION ON THE FAN MAJOR MODULE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0033 R1	NO. 1 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION ON THE FAN MAJOR MODULE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0033 R2	NO. 1 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0035	NO. 1 ENGINE - INTRODUCTION OF A NEW AIR SUPPLY DUCT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0036	NO. 1 ENGINE - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE (SUPERSEDED BY SB 75-0036 R1) , SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 75-0036 R1	NO. 1 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVES (75-22-10) - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE (SUPERSEDED BY SB 75-0036 R2), SERVICE BULLETIN					CATEGORY 7	
25-APR-2014		MOS HRS/MSC ENC	-				
SB 75-0036 R2	NO. 1 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVES (75-22-10) - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE, SERVICE BULLETIN					CATEGORY 7	
09-JUN-2014		MOS HRS/MSC ENC	-				
SB 75-0037	NO. 1 ENGINE - INTRODUCTION OF NEW VBV TURNBUCKLE, SERVICE BULLETIN						
08-SEP-2006		MOS HRS/MSC ENC	-				
SB 75-0037 R1	NO. 1 ENGINE - INTRODUCTION OF NEW VBV TURNBUCKLE, SERVICE BULLETIN						
13-FEB-2007		MOS HRS/MSC ENC	-				
SB 75-0038	NO. 1 ENGINE - INTRODUCTION OF PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
14-DEC-2006		MOS HRS/MSC ENC	-				
SB 75-0039	NO. 1 ENGINE - AIR - LPTACC VALVE (75-23-15) -INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
15-DEC-2008		MOS HRS/MSC ENC	-				
SB 75-0041	NO. 1 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
05-FEB-2009		MOS HRS/MSC ENC	-				
SB 75-0041 R1	NO. 1 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
15-JUN-2009		MOS HRS/MSC ENC	-				
SB 75-0042	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-FEB-2008		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0043	NO. 1 ENGINE - REWORK OF THE AIR MANIFOLD AND THE BRACKET OF THE COOLING MANIFOLD IN FIELD, SERVICE BULLETIN						
05-SEP-2008		MOS HRS/MSC ENC	- 				
SB 75-0044	NO. 1 ENGINE - AIR-ACTUATOR VBV (75-32-14) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
05-FEB-2010		MOS HRS/MSC ENC	- 				
SB 75-0045	NO. 1 ENGINE - AIR - ACTUATOR VBV (75-32-14) - INTRODUCTION OF THE LVDT SENSOR VIN 8070287 (325-500-002-0), SERVICE BULLETIN						
09-JAN-2009		MOS HRS/MSC ENC	- 				
SB 75-0047	NO. 1 ENGINE - AIR - LPTACC VALVE (75-23-15) - IN FIELD REIDENTIFICATION OF LPTACC VALVE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 75-0048	NO. 1 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF A NEW LPTACC VALVE WITH A NEW IDENTIFICATION PLATE, SERVICE BULLETIN					OPTIONAL	
19-JAN-2012		MOS HRS/MSC ENC	- 				
SB 75-0050	NO. 1 ENGINE - AIR - COOLING (75-22-10) - REWORK OF TURBINE CLEARANCE CONTROL VALVES VIN 3291186-5 (P/N 1821M59P05) AND VIN 3291186-6 (P/N 1821M59P06), SERVICE BULLETIN					RECOMMENDED	
23-FEB-2012		MOS HRS/MSC ENC	- 				
SB 75-0051	NO. 1 ENGINE - AIR - GENERAL - INTRODUCTION OF NEW TBV TUBE AND BRACKET, SERVICE BULLETIN					RECOMMENDED	
03-SEP-2012		MOS HRS/MSC ENC	- 				
SB 75-0052	NO. 1 ENGINE - AIR - VARIABLE STATOR ACTUATOR (75-32-10) - REPLACEMENT OF LVDT FOR FAULTY VSV ACTUATORS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 75-1040	NO. 1 ENGINE - REWORK HIGH PRESSURE TURBINE CLEARANCE VALVE, PN 3291186-5, TO PN 3291186-6, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 77-0001	NO. 1 ENGINE - CONTROL UNIT ALTERNATOR - REPLACEMENT OF CONNECTOR SEALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618855

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 77-0002	NO. 1 ENGINE - SPARE PARTS RELEASE FOR ENGINE CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0003	NO. 1 ENGINE - ENGINE INDICATING - T49.5 THERMOCOUPLE LEAD ASSY (77-21-10) - INTRODUCTION OF NEW OR REWORKED T49.5 PROBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0004	NO. 1 ENGINE - ENGINE INDICATING - T5 SENSOR REMOVAL (77-22-10) - INTRODUCTION OF NEW TEMPERATURE SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0004 R1	NO. 1 ENGINE - INTRODUCTION OF NEW TEMPERATURE SENSOR, SERVICE BULLETIN						
04-MAR-2005		MOS HRS/MSC - ENC					
SB 77-0005	NO. 1 ENGINE - ELIMINATE CHAFING OF BOEING ECS TUBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0007	NO. 1 ENGINE - INTRODUCTION OF A NEW N1 SPEED SENSOR, SERVICE BULLETIN						
01-DEC-2006		MOS HRS/MSC - ENC					
SB 77-0008	NO. 1 ENGINE - INTRODUCTION OF A NEW N2 SPEED SENSOR, SERVICE BULLETIN						
20-OCT-2006		MOS HRS/MSC - ENC					
SB 77-0008 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW N2 SPEED SENSOR, SERVICE BULLETIN						
27-FEB-2008		MOS HRS/MSC - ENC					
SB 77-0009	NO. 1 ENGINE - ENGINE INDICATING - (77-00-00) - SPARES PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
12-JAN-2009		MOS HRS/MSC - ENC					
SB 77-0010	NO. 1 ENGINE - ENGINE INDICATING - N1 SPEED SENSOR (77-12-19) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
17-DEC-2009		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618856

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0001	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						- INFORMATION ONLY
		MOS HRS/MSC ENC	- 				
SB 79-0001 R1	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R10	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN					CATEGORY 9	
14-APR-2014		MOS HRS/MSC ENC	- 				
SB 79-0001 R2	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R3	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R4	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R5	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R6	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
07-JUL-2006		MOS HRS/MSC ENC	- 				
SB 79-0001 R7	NO. 1 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
10-JUL-2008		MOS HRS/MSC ENC	- 				
SB 79-0001 R8	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
14-MAY-2009		MOS HRS/MSC ENC	- 				
SB 79-0001 R9	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES (SUPERSEDED BY SB 79-0001 R10), SERVICE BULLETIN					INFORMATIONAL	
19-AUG-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618857

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0002 R1	NO. 1 ENGINE - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 79-0002 R2	NO. 1 ENGINE - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0002 R3	NO. 1 ENGINE - OIL - LUBRICATION UNIT (79-00-00) - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						
14-MAY-2009		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0003	NO. 1 ENGINE - INTRODUCTION OF A NEW OIL CLOGGING INDICATOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0004 R1	NO. 1 ENGINE - ADDITION OF A CAUTION LABEL ON OIL SCAVENGE FILTER BOWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0005	NO. 1 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						COMPLIED WITH - NO REWORK REQUIRED
		MOS		22-AUG-2008			
		HRS/MSC	-	3260:48			
		ENC		746			
SB 79-0006	NO. 1 ENGINE - OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF AN IMPROVED OIL SCAVENGE FILTER ASSY WITH MODIFIED BOWL AND HEAD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0008	NO. 1 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	1500 (s)				
		ENC					
SB 79-0008 R1	NO. 1 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0008 R2	NO. 1 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	1500 (s)				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0009	NO. 1 ENGINE - LUBRICATION UNIT REMOVAL (79-21-10) - INTRODUCTION OF NEW PACKING PREFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRIFICATION UNIT., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0009 R1	NO. 1 ENGINE - LUBRICATION UNIT (79-21-10)-INTRODUCTION OF NEW PACKING PERFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRICATION UNIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0009 R2	NO. 1 ENGINE - LUBRICATION UNIT (79-21-10)-INTRODUCTION OF NEW PACKING PERFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRIFICATION UNIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0010	NO. 1 ENGINE - INTRODUCTION OF NEW FLUOROCARBONE O-RINGS ON OIL FUEL HEAT EXCHANGER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0010 R1	NO. 1 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-20) - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0010 R2	NO. 1 ENGINE - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
20-DEC-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0011	NO. 1 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-20) - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0011 R1	NO. 1 ENGINE - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RING, SERVICE BULLETIN						
20-DEC-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0012	NO. 1 ENGINE - REWORK OF A SPECIFIC BATCH OF OIL LEVEL SENSORS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0013	NO. 1 ENGINE - INTRODUCTION OF A NEW OIL BYPASS VALVE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	79-0014	NO. 1 ENGINE - OIL - OIL SYSTEM (79-00-00) - DELETION OF THE OIL BYPASS VALVE AND ITS HARDWARE, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	79-0017	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R1	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R2	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R3	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES (SUPERSEDED BY SB 79-0017 R4), SERVICE BULLETIN					RECOMMENDED	
	16-FEB-2007		MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R4	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
	14-APR-2014		MOS HRS/MSC ENC	- 				
SB	79-0018	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING, SERVICE BULLETIN						
			DAYS HRS/MSC ENC	30 (s) 				
SB	79-0018 R1	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING (SUPERSEDED BY SB 79-0018 R2), SERVICE BULLETIN						
			DAYS HRS/MSC ENC	30 (s) 				
SB	79-0018 R2	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING, SERVICE BULLETIN						
	14-APR-2014		MOS HRS/MSC ENC	- 				
SB	79-0020	NO. 1 ENGINE - OIL - DEBRIS MONITORING SYSTEM (DMS) (79-21-54) - INTRODUCTION OF NEW DMS DETECTOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618860

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0020 R1	NO. 1 ENGINE - INTRODUCTION OF NEW DMS DETECTOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
16-JAN-2006		HRS/MSC	-				
		ENC					
SB 79-0021 R2	NO. 1 ENGINE - INTRODUCTION OF A NEW OIL SCAVENGE HOSE TUBE WITH A NEW ROUTING AND A NEW BRACKET, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 79-0022	NO. 1 ENGINE - OIL - DMS JUNCTION BOX (79-21-53) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
26-NOV-2008		HRS/MSC	-				
		ENC					
SB 79-0023	NO. 1 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-25) - INTRODUCTION OF A NEW MAIN OIL/FUEL HEAT EXCHANGER WITH KEY LOCKED INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0023 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW MAIN OIL/FUEL HEAT EXCHANGER WITH KEY LOCKED INSERTS, SERVICE BULLETIN						
		MOS					
20-DEC-2006		HRS/MSC	-				
		ENC					
SB 79-0024	NO. 1 ENGINE - INTRODUCTION OF NEW PACKING PREFORMED O-RINGS IN FLUOROCARBONE WITH BETTER PERFORMANCE AT LOW TEMPERATURE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	500 (s)				
		ENC					
SB 79-0025	NO. 1 ENGINE - NEW FORWARD TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0026	NO. 1 ENGINE - INTRODUCTION OF NEW OUTER SEALING SPOOL, SERVICE BULLETIN						
		MOS					
25-OCT-2007		HRS/MSC	-				
		ENC					
SB 79-0027	NO. 1 ENGINE - OIL CONSUMPTION MONITORING, SERVICE BULLETIN						
		DAYS	30 (s)				
10-JUL-2008		HRS/MSC					
		ENC					
SB 79-0029	NO. 1 ENGINE - OIL - OIL SCAVENGE FILTER ASSEMBLY (79-21-42) - INTRODUCTION OF A NEW BYPASS VALVE SPRING, SERVICE BULLETIN						
		MOS					
08-OCT-2009		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0030	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - INTRODUCTION OF AN OIL SUPPLY TUBE WITH A NEW DESIGN, SERVICE BULLETIN					RECOMMENDED	
05-NOV-2010		MOS HRS/MSC ENC	- -				
SB 79-0031	NO. 1 ENGINE - OIL - LUBRICATION UNIT (79-21-16) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN					INFORMATIONAL	
10-DEC-2010		MOS HRS/MSC ENC	- -				
SB 79-0032	NO. 1 ENGINE - OIL - GENERAL (79-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
22-JAN-2013		MOS HRS/MSC ENC	- -				
SB 79-0069	NO. 1 ENGINE - DELETION OF ELECTRICAL CHIP DETECTOR KIT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 80-0001	NO. 1 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 80-0001 R1	NO. 1 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 80-0003R1
		MOS HRS/MSC ENC	- -				
SB 80-0001 R3	NO. 1 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 80-0001 R4	NO. 1 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
13-AUG-1999		MOS HRS/MSC ENC	- -				
SB 80-0002	NO. 1 ENGINE - AIR TURBINE STARTER CLAMP ROTATION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
26-MAR-1998		MOS HRS/MSC ENC	- -		16-DEC-1998 0 0		
SB 80-0003 R1	NO. 1 ENGINE - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- -		16-DEC-1998 0 0		
SB 80-0004	NO. 1 ENGINE - REPLACE THE GEAR SHAFT P/N 3507167-1 WITH P/N 3507167-2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0004 R1	NO. 1 ENGINE - REPLACE THE GEAR SHAFT P/N 3507167-1 WITH P/N 3507167-2, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0005	NO. 1 ENGINE - AIR TURBINE STARTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0006	NO. 1 ENGINE - STARTING - INTRODUCTION OF NEW TURBINE AIR STARTER VIN 3505945-9 (GE 1851M36P09) FIELD UPGRADE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0006 R1	NO. 1 ENGINE - STARTING - INTRODUCTION OF NEW TURBINE AIR STARTER VIN 3505945-9 (GE 1851M36P09) FIELD UPGRADE, SERVICE BULLETIN						
		MOS					
11-MAR-2004		HRS/MSC	-				
		ENC					
SB 80-0007	NO. 1 ENGINE - INTRODUCTION OF AIR TURBINE STARTER VIN 3505945-10 (GE 1851M36P10), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0008	NO. 1 ENGINE - INSPECTION AND REPLACEMENT OF NONCONFORMING MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
06-AUG-2002		HRS/MSC	- (s)		3260:48		
		ENC			746		
SB 80-0009	NO. 1 ENGINE - STARTING - STARTING (80-00-00) - AIR TURBINE STARTER VIN 3505945-9 (GE 1851M36P09) TO VIN 3505945-10 (GE 1851M36P10) REWORK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0010	NO. 1 ENGINE - PACKINGS FOR HTS OILS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	DUE				
		ENC					
SB 80-0010 R1	NO. 1 ENGINE - PACKINGS FOR HTS OILS AND NEW MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0010 R2	NO. 1 ENGINE - PACKINGS FOR HTS OILS AND NEW MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						
		MOS					
25-JUL-2006		HRS/MSC	- (s)				
		ENC					

© Camp Systems

EFTA00618863

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0011	NO. 1 ENGINE - MAGNETIC DRAIN PLUG WITH LARGER KNOB TO EASE REMOVAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0012	NO. 1 ENGINE - REPLACEMENT OF THE SPRING WASHER IN AIR TURBINE STARTERS VIN 3505945-9 (1851M36P09) AND VIN 3505945-10 (1851M36P10), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0013	NO. 1 ENGINE - STARTING - GENERAL (80-00-00) - ALLOW THE CHANGE IN THE FIELD OF THE AIR TURBINE STARTER DECOUPLER ASSEMBLY VIN 3504835-1 (SUPERSEDED BY 80-0013 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
14-FEB-2012		HRS/MSC	-				
		ENC					
SB 80-0013 R1	NO. 1 ENGINE - STARTING - GENERAL (80-00-00) - ALLOW THE CHANGE IN THE FIELD OF THE AIR TURBINE STARTER DECOUPLER ASSEMBLY VIN 3504835-1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
28-MAR-2012		HRS/MSC	-				
		ENC					
SB 80-0014	NO. 1 ENGINE - STARTING - STARTER (80-11-00) - INTRODUCTION OF NEW AIR TURBINE STARTERS VIN 3505945-11 (P/N 1851M36P11) AND VIN 3505945-12 (P/N 1851M36P12), SERVICE BULLETIN					OPTIONAL	
		MOS					
17-APR-2013		HRS/MSC	-				
		ENC					
SB 80-0015	NO. 1 ENGINE - STARTING - STARTER (80-11-00) - RETURN SUSPECT AIR TURBINE STARTERS, P/N 3505945-10, FOR INSPECTION AND EVALUATION (SUPERSEDED BY SB 80-0015 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 80-0015 R1	NO. 1 ENGINE - STARTING - STARTER (80-11-00) - RETURN SUSPECT AIR TURBINE STARTERS, P/N 3505945-10, FOR INSPECTION AND EVALUATION, SERVICE BULLETIN					CATEGORY 2	
		MOS					
09-JAN-2014		HRS/MSC	-				
		ENC					
SB 80-1709	NO. 1 ENGINE - REWORK THE AIR TURBINE ENGINE STARTER, PN 3505945-5/-6 TO PN 3505945-7/-8, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SI SER 79-0001	NO. 1 ENGINE - SERVICE EVALUATION REQUEST OF FLIGHT EVALUATION OF OILS, SERVICE INSTRUCTIONS						
		MOS					
		HRS/MSC					
		ENC	5000 (s)				
VSB 3291186-75-1074 R1	NO. 1 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVE - REWORK HIGH PRESSURE TURBINE CLEARANCE VALVES, PN 3291186-5 AND PN 3291186-6 TO REDUCE FUEL LEAKAGE, VENDOR SERVICE BULLETIN					RECOMMENDED	
		MOS					
19-FEB-2014		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - 874438/CFM56-7B27/B3							
ASB 72-A0328	NO. 2 ENGINE - LOW PRESSURE TURBINE SHAFT - REDUCED INTERVAL FOR AFT SUMP MCD OR DMS INSPECTION, ALERT SERVICE BULLETIN						
12-MAR-2002		MOS HRS/MSC ENC	-				
ASB 72-A0328 R1	NO. 2 ENGINE - LOW PRESSURE TURBINE SHAFT - REDUCED INTERVAL FOR AFT SUMP MCD OR DMS INSPECTION, ALERT SERVICE BULLETIN						
12-MAR-2002		DAYS HRS/MSC ENC	1 (s)				
ASB 72-A0329	NO. 2 ENGINE - LOW PRESSURE TURBINE SHAFT - REPLACEMENT OF NO.4 ROLLER BEARING., ALERT SERVICE BULLETIN						
12-MAR-2002		MOS HRS/MSC ENC	-				
ASB 73-A0026	NO. 2 ENGINE - INTRODUCITON OF SOFTWARE VERSION 7.B.J (7B3A), ALERT SERVICE BULLETIN						
15-JAN-1999		MOS HRS/MSC ENC	-				
ASB 73-A0034 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH NEW FILTER COVER, ALERT SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0000	NO. 2 ENGINE - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B SERVICE BULLETINS, SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0000 R1	NO. 2 ENGINE - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B (SUPERSEDED BY 72-0000 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0000 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CFM56-7B SERVICE BULLETINS, SERVICE BULLETIN					INFORMATIONAL	
11-MAY-2011		MOS HRS/MSC ENC	-				
SB 72-0001	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	- INFORMATION ONLY
		MOS HRS/MSC ENC	-				
SB 72-0001 R1	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618865

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0001 R2	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION., SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0001 R3	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN					SUPERSEDED	
27-JUL-2006		MOS HRS/MSC ENC	- 				
SB 72-0001 R4	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION , SERVICE BULLETIN						
25-MAY-2007		MOS HRS/MSC ENC	- 				
SB 72-0001 R5	NO. 2 ENGINE - CFM56-7B ENGINE MODELS IDENTIFICATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0002	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS HRS/MSC ENC	- 				
SB 72-0002 R1	NO. 2 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0003	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						- PRODUCT IMPROVEMENT
		MOS HRS/MSC ENC	- 				
SB 72-0003 R1	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R10	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0003 R2	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODEL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R3	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0003 R4	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO DERIVATIVE MODELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R5	NO. 2 ENGINE - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R6	NO. 2 ENGINE - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0003 R7	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- 				
SB 72-0003 R8	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0003 R9	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B MODEL ENGINES TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS (SUPERSEDED BY 72-0003 R10), SERVICE BULLETIN					SUPERSEDED	
10-MAR-2011		MOS HRS/MSC ENC	- 				
SB 72-0004	NO. 2 ENGINE - INSTALLATION OF CERTIFIED CFM56-7B ENGINE NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0004 R1	NO. 2 ENGINE - CERTIFIED CFM56-7B ENGINE NAMEPLATE, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0005	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS HRS/MSC ENC	- 				
SB 72-0006 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0006 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0006 R3	NO. 2 ENGINE - CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0006 R4	NO. 2 ENGINE - CONVERSION TO CFM56-7B18, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0007 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0007 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0007 R3	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0007 R4	NO. 2 ENGINE - CONVERSION TO CFM56-7B20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0008 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0008 R3	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0008 R4	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0008 R5	NO. 2 ENGINE - CONVERSION TO CFM56-7B22, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618868

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0009	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F (7B2B), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R3	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0009 R4	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0010 R3	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R4	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0010 R5	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26, SERVICE BULLETIN					OPTIONAL	
17-FEB-2011		MOS HRS/MSC - ENC					
SB 72-0011 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618869

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0011 R3	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0011 R4	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27, SERVICE BULLETIN					OPTIONAL	
		MOS					
28-APR-2000		HRS/MSC	-				
		ENC					
SB 72-0012	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0013	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0014	NO. 2 ENGINE - NUT AND TORQUE CHANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0015	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	- CANCELLED
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0016	NO. 2 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
11-JUL-1997		HRS/MSC	-				
		ENC					
SB 72-0016 R1	NO. 2 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
05-AUG-1997		HRS/MSC	-	0			
		ENC		0			
SB 72-0017	NO. 2 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0017 R1	NO. 2 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0018	NO. 2 ENGINE - INCREASING OF BOLT LENGTH AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0018 R1	NO. 2 ENGINE - INCREASING OF BOLT LENGTH AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0018 R2	NO. 2 ENGINE - INCREASING OF LENGTH BOLT AND ADDITION OF A WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0019	NO. 2 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0020 R1	NO. 2 ENGINE - ADDITON OF A SPACER ON THE RETAINING CABLE OF THE IDENTIFICATION PLUG KIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0021	NO. 2 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0021 R10	NO. 2 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0021R1	NO. 2 ENGINE - REPLACEMENT OF STAGE 9 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0022	NO. 2 ENGINE - MODIFICATION OF THE J10 WIRING HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0022 R1	NO. 2 ENGINE - MODIFICATION OF THE J10 WIRING HARNESS, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0093
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0023	NO. 2 ENGINE - INTERFERENCE BETWEEN THE BODY ACTUATOR AND THE LVDT SENSOR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0023 R1	NO. 2 ENGINE - INTERFERENCE BETWEEN THE BODY ACTUATOR AND THE LVDT SENSOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0024	NO. 2 ENGINE - REPLACEMENT OF BOLTS ON OIL SENSOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0024 R1	NO. 2 ENGINE - REPLACEMENT OF BOLTS ON OIL SENSOR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0025	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION CONNECTOR KITS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0025 R2	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION CONNECTOR KITS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0026 R1	NO. 2 ENGINE - REWORK OF SHROUD PAD, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0027	NO. 2 ENGINE - REPOSITIONING OF VBV HARNNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0028 R2	NO. 2 ENGINE - THRUST REVERSER KIT MODIFICATION OF INTERNAL VEE GROOVE AND FITTING SHROUDS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0029	NO. 2 ENGINE - REPLACEMENT OF BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0030 R1	NO. 2 ENGINE - MODIFICATION OF NAMEPLATE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0030 R2	NO. 2 ENGINE - MODIFICATION OF NAMEPLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0031	NO. 2 ENGINE - INTRODUCTION OF THE NEW PLATFORM FAN BLADE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0032	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN CASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0033	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0033 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0033 R2	NO. 2 ENGINE - , SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0034 R1	NO. 2 ENGINE - TURBINE CLEARANCE CONTROL VALVE SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0035	NO. 2 ENGINE - MODIFICATION OF BRACKET ASSY AND HARNESS J5 AND J6, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0101
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0035 R1	NO. 2 ENGINE - MODIFICATION OF BRACKET ASSY AND HARNESS J5 AND J6, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0036 R1	NO. 2 ENGINE - INSTALLATION OF A TUBE OIL DRAIN, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0037	NO. 2 ENGINE - REPLACEMENT OF ONE BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0038	NO. 2 ENGINE - MODIFICATION OF AXIAL LOAD LINK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0039 R2	NO. 2 ENGINE - INSTALLATION OF NEW BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0040 R1	NO. 2 ENGINE - MODIFICATION OF BRACKET ASSY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0040 R2	NO. 2 ENGINE - MODIFICATION OF BRACKET ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0041	NO. 2 ENGINE - DELETION OF BRACKETS ASSY FOLOWING PRECOOLER DEFLECTOR AST SIDE PANELS REMOVAL, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0042	NO. 2 ENGINE - HPTCC MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0043	NO. 2 ENGINE - INTRODUCTION OF NEW BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0044 R1	NO. 2 ENGINE - SUPPORT BRACKET IMPROVEMENTS FOR THE CJ9 HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0045 R2	NO. 2 ENGINE - REWORK OF SHROUD PAD OF STRUT N°4 ON "VEE GROOVE", SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0045 R3	NO. 2 ENGINE - REWORK OF SHROUD PAD OF STRUT N°4 ON "VEE GROOVE", SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0046	NO. 2 ENGINE - MODIFICATION OF TWO BRACKETS ON BOEING FUEL SUPPLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0047	NO. 2 ENGINE - NEW HPT SHROUD RETAINING CLIP INTRODUCTION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0047 R1	NO. 2 ENGINE - NEW HPT SHROUD RETAINING CLIP INTRODUCTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0047 R2	NO. 2 ENGINE - HPT AND LPT NOZZLE STAGE 1 - INTRODUCTION OF NEW LOW STRESS C-CLIPS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0048 R1	NO. 2 ENGINE - ANTI-ICE AND DRAIN MANIFOLD BRACKET REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0098
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0049 R1	NO. 2 ENGINE - MODIFICATION OF HARNESS MW0304, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0050	NO. 2 ENGINE - MODIFICATION OF HARNESS MW0301, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0051	NO. 2 ENGINE - GENERAL (72-00-00) SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0052	NO. 2 ENGINE - INSPECTION OF J5, J6, J10, MW0301,MW0302, AND MW0304 HARNESSES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0053 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG 52X CWM-91X
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0054	NO. 2 ENGINE - REPLACEMENT OF T49.5 BRACKETS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0054R1	NO. 2 ENGINE - REPLACEMENT OF T49.5 BRACKETS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0055 R1	NO. 2 ENGINE - CHANGE OF HARDWARE FROM CORE ASSEMBLY TO ENGINE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0056	NO. 2 ENGINE - VBV FUEL MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0057	NO. 2 ENGINE - INTRODUCTION OF NEW HPT NOZZLE SEGMENTS, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0099
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0058	NO. 2 ENGINE - INTRODUCTION OF NEW FRONT FLANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0059	NO. 2 ENGINE - NEW VSV FUEL MANIFOLD LOOP CLAMP BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0060	NO. 2 ENGINE - REPLACEMENT OF OVERHEAT DETECTOR BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0060 R1	NO. 2 ENGINE - REPLACEMENT OF OVERHEAT DETECTOR BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0061	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 32X,41X,52X,91X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0062	NO. 2 ENGINE - INTRODUCTION OF A REPLACEABLE CUSHION FOR HINGED CLAMP (ELECTRICAL HARNESSES ATTACHMENT), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0063 R1	NO. 2 ENGINE - REPLACEMENT OF HOLD OPEN ROD BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0064 R1	NO. 2 ENGINE - REPLACEMENT OF TWO BRACKETS ATTACHING THE J12 HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0065	NO. 2 ENGINE - INTRODUCTION OF A NEW SOURCE FOR THE VIBRATION BRG1, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0066	NO. 2 ENGINE - INTRODUCTION OF NEW SOURCE FOR SENSOR VIBRATION FFCC, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0067 R1	NO. 2 ENGINE - INTRODUCTION OF A HEAT SHIELD BETWEEN THE OIL PRESSURE SENSOR AND THE OIL DISTRIBUTION BLOCK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 91X NA-SUPERSEDED 72-0151
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0068	NO. 2 ENGINE - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0068 R1	NO. 2 ENGINE - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0068 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE HMU BOLTS, SERVICE BULLETIN					INFORMATIONAL	
		MOS					
03-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0069	NO. 2 ENGINE - INTRODUCTION/REWORK OF TWO PS3 BRACKETS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0070 R1	NO. 2 ENGINE - ECS DUCT BRACKET REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0071	NO. 2 ENGINE - MODIFICATION OF BRACKET ATTACHING THE MW0312, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0072	NO. 2 ENGINE - INTRODUCTION OF A PAINT-MARKED COVER ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0073	NO. 2 ENGINE - DRAIN TUBE SUPPORT CHANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0074	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0074 R1	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 41X,91X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0075	NO. 2 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE AND IGNITER HARDWARE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0076	NO. 2 ENGINE - INTRODUCTION OF NEW IDG OIL COOLER WITH A NEW GOEMETRY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0077	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0077 R2	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0078 R1	NO. 2 ENGINE - INTRODUCTION OF LONGER SCREWS ON LPTACC PANEL, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0079	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R1	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0079 R2	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R3	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R4	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0079 R5	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0079 R6	NO. 2 ENGINE - NEW OR REWORKED HPT SHROUD AND SHROUD HANGERS, SERVICE BULLETIN					RECOMMENDED	
23-NOV-2010		MOS HRS/MSC ENC	- 				
SB 72-0080	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0081	NO. 2 ENGINE - CMF56-7B ENGINE CONVERSION TO CFM56-7B20/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0081 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0082	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0082 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0083	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0083 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0084	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 72-0084 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0085	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/2, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618879

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0085 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/2, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0086	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0086 R1	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
04-DEC-2007		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0087	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0103
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0088	NO. 2 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0088 R1	NO. 2 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0088 R2	NO. 2 ENGINE - EGT BRACKET ASSEMBLY AND BOLT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0089	NO. 2 ENGINE - LPT MODULE (72-54-00)-INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 53X,54X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0089 R1	NO. 2 ENGINE - LPT MODULE (72-54-00)-INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0089 R2	NO. 2 ENGINE - REWORK OF OLD LPT STAGE 1 NOZZLE SEGMENT OR INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND NEW STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
27-JAN-2006		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618880

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0089 R3	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REWORK OF OLD LPT STAGE 1 NOZZLE SEGMENT OR INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT AND NEW STAGE 1 SEAL-SEGMENT, SERVICE BULLETIN						
10-APR-2009		MOS HRS/MSC ENC	- 				
SB 72-0090	NO. 2 ENGINE - REINFORCEMENT OF FORWARD MOUNTING LUG OF THE LPT COOLING MANIFOLDS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	 - 	16-DEC-1998 0 0			
SB 72-0091	NO. 2 ENGINE - REMOVAL OF EXTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU107, 874-110 THRU 112, 874-115 AND -116, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				
SB 72-0091 R1	NO. 2 ENGINE - REMOVAL OF EXTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU107, 874-110 THRU 112, 874-115 AND -116, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	 - 				
SB 72-0092	NO. 2 ENGINE - INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	 - 	16-DEC-1998 0 0			
SB 72-0092 R1	NO. 2 ENGINE - INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				
SB 72-0093	NO. 2 ENGINE - INTRODUCTION OF NEW MOUNT HARNESS WITH J9, J10, MW0311, MW0315, MW0316 ASSOCIATED HARNESSES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	 - 	16-DEC-1998 0 0			
SB 72-0094	NO. 2 ENGINE - INTRODUCTION OF NEW LPT NOZZLE STAGE 2, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	 - 	16-DEC-1998 0 0			
SB 72-0094 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LPT NOZZLE STAGE 2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 - 				
SB 72-0095	NO. 2 ENGINE - INTRODUCTION OF LARGE BORE TRANSIENT BLEED VALVE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	 - 	16-DEC-1998 0 0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0096	NO. 2 ENGINE - INTRODUCTION OF HPT NOZZLE SUPPORT WITH IMPROVED PINS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0097 R1	NO. 2 ENGINE - INTRODUCTION OF LONGER BOLTS ON ENGINE AND CORE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0098	NO. 2 ENGINE - INTRODUCTION OF A NEW AIR DUCT SUPPORT BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0099	NO. 2 ENGINE - INTRODUCTION OF NEW HPT NOZZLE SEGMENTS WITH INNER SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0100	NO. 2 ENGINE - CFM56-7B ENGINE NAMEPLATE MARKING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0101	NO. 2 ENGINE - NEW ROUTING OF J5 AND J6 HARNESSES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0102	NO. 2 ENGINE - INTRODUCTION OF DAC HPT ROTOR ASSEMBLY FOR USE ON THE SAC HPT ROTOR ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0103	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0103 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0103 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITH ONE CLOCKING LUG, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-FEB-2011		HRS/MSC	-				
		ENC					
SB 72-0104	NO. 2 ENGINE - INTRODUCTION OF A NEW PAINT ON LPT SHAFT, SERVICE BULLETIN						- SUPERSEDED - SB PENDING
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0104 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW PAINT ON LPT SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0105	NO. 2 ENGINE - ARRANGEMENT OF VBV TURNBUCKLE, BELLCRANK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106	NO. 2 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R2	NO. 2 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R3	NO. 2 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0106 R4	NO. 2 ENGINE - INTRODUCTION OF RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS, SERVICE BULLETIN						
14-AUG-2007		MOS HRS/MSC - ENC					
SB 72-0107	NO. 2 ENGINE - REPLACEMENT CLAMP FOR DAC AFT SUMP OIL SUPPLY TUBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0108	NO. 2 ENGINE - NEW VBV FUEL MANIFOLD BOLTS AND VSV FUEL MANIFOLD LOOP CLAMP BOLTS, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0109	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC - ENC					
SB 72-0109 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0109 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION CHAMBER LUG RING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R1	NO. 2 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0110 R2	NO. 2 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R3	NO. 2 ENGINE - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0110 R4	NO. 2 ENGINE - COMBUSTION CHAMBER - BIRD BUMPER (SWIRLER SUPPORT) ELIMINATION AND INTRODUCTION OF COMBUSTION CHAMBER WITH ONE LUG KEY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0111	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH INCREASED LIFE LIMIT, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0114
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0112	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0113	NO. 2 ENGINE - INTRODUCTION OF NEW ECS DUCT BRACKET AND FAN COWL SUPPORT BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0113 R1	NO. 2 ENGINE - INTRODUCTION OF NEW ECS DUCT BRACKET AND FAN COWL SUPPORT BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0114	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH MODIFIED HUB, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0114 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT REAR FRAME WITH MODIFIED HUB, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115	NO. 2 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115 R1	NO. 2 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0115 R2	NO. 2 ENGINE - INTRODUCTION OF NEW HPT BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0116	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0117	NO. 2 ENGINE - LPT COOLING AIR TUBE METERING PLATE DELETION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0117 R1	NO. 2 ENGINE - LPT COOLING AIR TUBE METERING PLATE DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0118	NO. 2 ENGINE - INTRODUCTION OF A NEW HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0119	NO. 2 ENGINE - RTV APPLICATION ADJUSTMENT ON THE NEW VEE GROOV SYSTEM, SERVICE BULLETIN						- PRODUCT IMPROVEMENT
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0120	NO. 2 ENGINE - WASHERS TO PC FUEL TUBE/MANIFOLD, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0121 R1	NO. 2 ENGINE - CORE ASSEMBLY HARDWARE CHANGE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0122	NO. 2 ENGINE - DELETION OF THE STAGE 5 BLEED COVER PLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0123 R1	NO. 2 ENGINE - INSPECTION OF TGB AIR/OIL TUBE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0124	NO. 2 ENGINE - INTRODUCTION OF A NEW CENTER VENT TUBE (CVT) REMOVABLE AT ENGINE LEVEL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0124 R3	NO. 2 ENGINE - INTRODUCTION OF A NEW CENTER VENT TUBE (CVT) REMOVABLE AT ENGINE LEVEL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0125	NO. 2 ENGINE - HPT NOZZLE INNER SEAL REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0126	NO. 2 ENGINE - CORE CONFIGURATION UPDATES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0128	NO. 2 ENGINE - REPLACEMENT OF BOLTS AND WASHERS ATTACHING THE REAR CONE FLANGE ON THE FAN DISK FRONT FLANGE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0129	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0129 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0130	NO. 2 ENGINE - STARTER GEARSHAFT REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE L5 STARTER GEARSHAFT SERIAL NUMBER
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0130 R1	NO. 2 ENGINE - STARTER GEARSHAFT REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0131	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0132	NO. 2 ENGINE - REDUCED INTERVAL FOR MAGNETIC CHIP DETECTOR INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE AGB STARTER GEARSHAFT SERIAL NUMBER
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0133	NO. 2 ENGINE - CHANGE OF TRANSFER GEARBOX AIR/OIL TUBE - REPLACEMENT OF RIGID AIR TUBE BY A SEMI-RIGID AIR TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 23X,91X
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0133 R1	NO. 2 ENGINE - CHANGE OF TRANSFER GEARBOX AIR/OIL TUBE - REPLACEMENT OF RIGID AIR TUBE BY A SEMI-RIGID AIR TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0134	NO. 2 ENGINE - INTRODUCTION OF A NEW CLAMP-LOOP AND ITS BRACKET FOR J12 ELECTRIC HARNESS HOLDING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0135	NO. 2 ENGINE - RESPONSIBILITY TRANSFER OF THREE FIRE DETECTION BRACKETS FROM BOEING TO CFMI, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0135 R1	NO. 2 ENGINE - RESPONSIBILITY TRANSFER OF THREE FIRE DETECTION BRACKETS FROM BOEING TO CFMI, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0136 R1	NO. 2 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 72-0136 R2	NO. 2 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0136 R3	NO. 2 ENGINE - IMPROVEMENT OF LUG AND WIRE CONNECTION FOR THE FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0138	NO. 2 ENGINE - INTRODUCTION OF A HEAT SHRINK SLEEVE ON J7 AND J8 HARNESSES, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 72-0146
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0139	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0140	NO. 2 ENGINE - BONDED CAUTION PLATE ON COVER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0140 R1	NO. 2 ENGINE - BONDED CAUTION PLATE ON COVER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0141	NO. 2 ENGINE - INTRODUCTION OF NEW LPTACC TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0142	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0143	NO. 2 ENGINE - REPLACEMENT OF SUSPECT J9 HARNESSES ., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0144	NO. 2 ENGINE - INTRODUCTION OF A NEW PS3 AIR TUBE WITH NEW ROUTING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0145	NO. 2 ENGINE - CLAMP ASSEMBLY ADDITION TO THE TRANSIENT BLEED VALVE DRAIN TUBE, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0146	NO. 2 ENGINE - J8 HARNESS ECU CONNECTION - NEW ROUTING OF "DP0808" LEG, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0147	NO. 2 ENGINE - N1 MODIFIER SCHEDULE CHANGE FOR CFM56-7B26 AND CFM56-7B27 ENGINES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0148	NO. 2 ENGINE - SAFETYING OF OIL RETURN TUBE - INTRODUCTION OF A NEW BOLT PERMITTING INSTALLATION OF SAFETY WIRE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0148 R1	NO. 2 ENGINE - SAFETYING OF OIL RETURN TUBE - INTRODUCTION OF A NEW BOLT PERMITTING INSTALLATION OF SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0149	NO. 2 ENGINE - FAN AND BOOSTER ADDITION OF A NEW WASHER ON PT25 AIR TUBE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0150	NO. 2 ENGINE - BRACKETS ASSY DELETION OF ALERNATES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0151	NO. 2 ENGINE - REPLACEMENT OF SWAGED SPACERS BY WELDED SPACERS ON ELECTRICAL HARNESSES, OIL AND FUEL TUBE BRACKETS, SERVICE BULLETIN						COMPLIED WITH - PARTIALLY AT MFG
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0151 R1	NO. 2 ENGINE - REPLACEMENT OF SWAGED SPACERS BY WELDED SPACERS ON ELECTRICAL HARNESSES, OIL AND FUEL TUBE BRACKETS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0152	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE 91X OPEN-51X
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0153	NO. 2 ENGINE - INTRODUCTION OF A NEW J7 HARNESS WITH COIL INTEGRATED, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0154	NO. 2 ENGINE - INTRODUCTION OF A NEW VSV FUEL TUBE WITH NEW ROUTING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0155	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0155 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0156	NO. 2 ENGINE - HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0156 R1	NO. 2 ENGINE - HPT NOZZLE SHRUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0156 R2	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE (72-53-00) - HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01, SERVICE BULLETIN					OPTIONAL	
	13-FEB-2012		MOS					
			HRS/MSC	-				
			ENC					
SB	72-0157	NO. 2 ENGINE - IMPROVED SEAL MATERIAL, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0158	NO. 2 ENGINE - COMBUSTOR LINER PRODUCIBILITY IMPROVEMENT, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0158 R1	NO. 2 ENGINE - COMBUSTOR LINER PRODUCIBILTY IMPROVEMENT, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0159	NO. 2 ENGINE - INCREASING OF BOLT LENGTH ON T49.5 PROBE BOX, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	72-0160	NO. 2 ENGINE - REMOVAL OF INTERNAL INSTRUMENTED HARDWARE ON COMPLIANCE ENGINES: 874-101 THRU 874-105, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0161	NO. 2 ENGINE - REPLACEMENT OF ECU BRACKET ASSY ON THE FAN FRAME, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0162	NO. 2 ENGINE - INSPECT HPT STR MANIFOLD/LPT STAGE 1 NOZZLE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0163	NO. 2 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH A NEW DESIGN, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 72-0164	NO. 2 ENGINE - HPT CLEARANCE CONTROL MANIFOLD, LPT COOLING/TF SENSOR AND ELECTRICAL SUPPORT BRACKET CHANGES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0165	NO. 2 ENGINE - RETROFIT INSTALLATION FOR COMPLYANCE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						NOT APPLICABLE - 91X OPEN-56X
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0166 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0167 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0168	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0168 R1	NO. 2 ENGINE - CONVERSION OF CFM56-7B TO 7B27/B3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0168 R2	NO. 2 ENGINE - CFM 56-7B ENGINE CONVERSION TO CFM 56-7B27/B3., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169	NO. 2 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0169 R2	NO. 2 ENGINE - INTRODUCTION OF NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0170	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0171	NO. 2 ENGINE - INTRODUCTION OF A NEW STAGE 1 VANE ASSY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0172	NO. 2 ENGINE - REPLACEMENT OF BRACKET FOR INSTALLATION OF BOEING FLOWMETER KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0173	NO. 2 ENGINE - LPT SHIFT MARAGING 250 MATERIAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0173 R1	NO. 2 ENGINE - LOW PRESSURE TURBINE SHAFT - INTRODUCTION OF A NEW LPT SHAFT MADE OF MARAGING 250 MATERIAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0174	NO. 2 ENGINE - INCREASING OF BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0175	NO. 2 ENGINE - INTRODUCTION OF TWO WAISTS ON ATTACHMENT STRUT 4 AND STRTUT 10 CLAMPS ASSY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176	NO. 2 ENGINE - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176 R1	NO. 2 ENGINE - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0176 R2	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - NEW OUTER DOME AND INNER DOME INTRODUCTION, SERVICE BULLETIN						
30-SEP-2009		MOS HRS/MSC - ENC					
SB 72-0177	NO. 2 ENGINE - INTRODUCTION OF A NEW HPT STATOR PIN RETAINER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0178	NO. 2 ENGINE - NEW NO. 5 BEARING SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0179	NO. 2 ENGINE - VSV FUEL MANIFOLD AND VSV MANIFOLD BRACKET REPLACEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0180	NO. 2 ENGINE - REDUCED INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0181	NO. 2 ENGINE - FAN FRAME -NEW BRACKET ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0182	NO. 2 ENGINE - PT25 AIR TUBE INSTALLATION IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0182 R1	NO. 2 ENGINE - PT25 AIR TUBE INSTALLATION IMPROVEMENT, SERVICE BULLETIN						
10-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0183	NO. 2 ENGINE - CANCELLATION NOTICE, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0184	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0185	NO. 2 ENGINE - INTRODUCTION OF A NEW NO. 4 ROLLER BEARING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0185 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW NO. 4 ROLLER BEARING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0186	NO. 2 ENGINE - NEW LPT STAGE 2 NOZZLE SEGMENTS, SERVICE BULLETIN						
23-SEP-1999		MOS HRS/MSC ENC	- 				
SB 72-0186 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LPT STAGE 2 NOZZLE SEGMENTS, SERVICE BULLETIN						
08-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0187	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188	NO. 2 ENGINE - DISCONNECTION AND RECONNECTION OF J01 AND J02 HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188 R1	NO. 2 ENGINE - DISCONNECTION AND RECONNECTION OF J01 AND J02 HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0188 R2	NO. 2 ENGINE - FAN FRAME ASSEMBLY - DISCONNECTION AND RECONNECTION OF MW0301 (J01) AND MW0302 (J02) HARNESSES AT THEIR APPROPRIATE LOCATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0189	NO. 2 ENGINE - INTRODUCTION OF A NEW VSV FUEL MANIFOLD AND VSV MANIFOLD BRACKET CHANGE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0190	NO. 2 ENGINE - REPLACEMENT OF STAGE 2 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0191	NO. 2 ENGINE - SHORTER BOLT FOR T49.5 ELECTRICAL HARNESS SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0191 R1	NO. 2 ENGINE - NEW SHORTER BOLT FOR T49.5 ELECTRICAL HARNESS SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0192	NO. 2 ENGINE - REPLACEMENT OF NO.4 ROLLER BEARING 335-352-301-0, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0193	NO. 2 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH NEW DESIGN ON FLANGE B6. J1 ELECTRIC HARNESS HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0194	NO. 2 ENGINE - INTRODUCTION OF A WAIST ON STRUT PROFILE (9 O'CLOCK), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0195	NO. 2 ENGINE - INTRODUCTION OF NEW NIPPLE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0196	NO. 2 ENGINE - ABRADABLE STAGE 3 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0197	NO. 2 ENGINE - CHAMFER ON LOCKS-STAGE 2 SEAL SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0198	NO. 2 ENGINE - LPT STAGE 2 SEAL SEGMENT WITH NEW LOCK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0199	NO. 2 ENGINE - TWO NEW LONGER BOLTS FOR ELECTRICAL HARNESS SUPPORT (3 O'CLOCK), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0200	NO. 2 ENGINE - INTRODUCTION OF A NEW ASSY WITH NEW DESIGN ON FLANGE B6. FUEL TUBE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0201	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7 IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0202	NO. 2 ENGINE - REMOVAL OF SILICONE ELASTOMER SEALS FROM FAN DUCT PANELS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0203	NO. 2 ENGINE - INTRODUCTION OF A STRAIGHT HEADLESS PIN TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0204	NO. 2 ENGINE - FUEL TRANSIENT BLEED VALVE MANIFOLD BOLT CHANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0205	NO. 2 ENGINE - MODIFICATION OF ONE FIRE DETECTION BRACKET ASSY AND INCREASING OF OVERTAKING BOLTS ON FLANGE B6, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0206	NO. 2 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0207	NO. 2 ENGINE - RETURN TO CFMI OF NO.4 ROLLER BEARING 335-352-301-0 STORED AS SPARES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0208	NO. 2 ENGINE - INTRODUCTION OF NEW NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0208 R1	NO. 2 ENGINE - INTRODUCTION OF NEW NAMEPLATE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0208 R2	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0208 R3	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
08-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0208 R4	NO. 2 ENGINE - INTRODUCTION OF A NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
25-MAY-2007		HRS/MSC	-				
		ENC					
SB 72-0208 R5	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW IDENTIFICATION PLATE AND NEW ACCOMPLISHMENT INSTRUCTIONS FOR MARKING, SERVICE BULLETIN						
		MOS					
14-JAN-2009		HRS/MSC	-				
		ENC					
SB 72-0209 R1	NO. 2 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R4	NO. 2 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R5	NO. 2 ENGINE - ENGINE-COMBUSTION ASSEMBLY (72-41-00)-INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0209 R6	NO. 2 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN						
		MOS					
05-FEB-2010		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0209 R7	NO. 2 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY AND HPT NOZZLE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
13-FEB-2012		MOS HRS/MSC ENC	- 				
SB 72-0210	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY, NEW PS3 SIGNAL AIR TUBE AND NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0210 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW COMBUSTION ASSEMBLY, NEW PS3 SIGNAL AIR TUBE AND NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0211	NO. 2 ENGINE - INTRODUCTION OF A NEW FORWARD INNER NOZZLE SUPPORT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0212	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0212 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0213	NO. 2 ENGINE - INTRODUCTION OF A INTERMEDIATE FLANGE WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0214	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0215	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0216	NO. 2 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY WITH NEW DESIGN ON THE ACCESSORY GEARBOX. ELECTRIC HARNESSES AND POWERS FEEDERS IDG CABLE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0217	NO. 2 ENGINE - LPT BLADES STAGE 4 IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0218	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0219	NO. 2 ENGINE - INTRODUCTION OF A NEW FOOL PROOF PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0220	NO. 2 ENGINE - INTRODUCTION OF NEW N2 SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0221	NO. 2 ENGINE - INTRODUCTION OF NEW OIL INLET COVER ASSY OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0221 R1	NO. 2 ENGINE - INTRODUCTION OF NEW OIL INLET COVER ASSY OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0222	NO. 2 ENGINE - REMOVAL EXTERNAL INSTRUMENTATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0223	NO. 2 ENGINE - INTRODUCTION OF A NEW OUTER LINER LUG RING TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0224	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7-B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0225	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0225 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0226	NO. 2 ENGINE - INTRODUCTION OF STAGE 2 AND STAGE 4 BLADE KITS TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0227	NO. 2 ENGINE - INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0227 R1	NO. 2 ENGINE - INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0228	NO. 2 ENGINE - INTRODUCTION OF A NEW NEXT HIGHER ASSEMBLY COOLING MANIFOLD UP AND DOWN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0229	NO. 2 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0229 R1	NO. 2 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
11-FEB-2008		MOS HRS/MSC - ENC					
SB 72-0229 R2	NO. 2 ENGINE - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
22-FEB-2011		MOS HRS/MSC - ENC					
SB 72-0229 R3	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
13-SEP-2011		MOS HRS/MSC - ENC					
SB 72-0229 R4	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - INNER AND OUTER LINER THICKER TBC FIELD REWORK, SERVICE BULLETIN						
23-FEB-2012		MOS HRS/MSC - ENC					
SB 72-0230	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0230 R1	NO. 2 ENGINE - , SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0231	NO. 2 ENGINE - INTRODUCTION OF A NEW TURNBUCKLE ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0232	NO. 2 ENGINE - INTRODUCTION OF A NEW J6 HARNESS WITH NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0233	NO. 2 ENGINE - INTRODUCTION OF A FIELD REWORKED HPT NOZZLE STATOR SEGMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0234	NO. 2 ENGINE - INTRODUCTION OF UPPER DRAIN MANIFOLD GASKET, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0235	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0236	NO. 2 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT HOUSING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0237	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN FRAME WITH GANGS CHANNEL, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0239	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLUGS FOR THE DEACTIVATION OF THE BURNER STAGING VALVE FUNCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0239 R1	NO. 2 ENGINE - INTRODUCTION OF NEW IDENTIFICATION PLUGS FOR THE DEACTIVATION OF THE BURNER STAGING VALVE FUNCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0240 R1	NO. 2 ENGINE - INTRODUCTION OF THE NEW MOUNT HARNESS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0240 R2	NO. 2 ENGINE - MODIFICATION OF HARNESSES MOUNTS, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0241	NO. 2 ENGINE - NEW LPT NOZZLE SEGMENTS STAGE 2 AND STAGE 3 REWORK, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0241 R1	NO. 2 ENGINE - NEW LPT NOZZLE SEGMENTS STAGE 2 AND STAGE 3 REWORK, SERVICE BULLETIN						
08-JAN-2007		MOS HRS/MSC ENC	 25000 (s)				
SB 72-0242	NO. 2 ENGINE - INTRODUCTION OF NEW LONGER BOLTS ON KIT CLOSE DMS BOX ATTACHMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0243	NO. 2 ENGINE - INTRODUCTION OF A BRACKET ASSY ON NO.1 AND NO. 2 BEARING SUPPORT OIL SUPPLY TUBE HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0244 R1	NO. 2 ENGINE - POSITIONING MODIFICATION OF 2 CLAMPS ATTACHING THE FUEL TUBE AND THE OIL RETURN TUBE TO FACILITATE THE ENGINE COVER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0245	NO. 2 ENGINE - SPARE PARTS RELEASE CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246	NO. 2 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0246 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW HOSE FUEL TUBE WITH A NEW ROUTING, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0247	NO. 2 ENGINE - INTRODUCTION OR REWORK OF THE BRACKET ASSY ON ACCESSORY GEARBOX ATTACHING THE J5 ELECTRIC WIRING HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0248	NO. 2 ENGINE - REPLACEMENT OR REWORK OF BRACKET ASSY ATTACHING THE MW0301 ELECTRICAL HARNESS ON FLANGE B4, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0249	NO. 2 ENGINE - INTRODUCTION OF NEW SEAL SEGMENTS STAGE 1, 2, 3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0249 R1	NO. 2 ENGINE - INTRODUCTION OF NEW SEAL SEGMENTS STAGE 1, 2, 3, SERVICE BULLETIN						
23-OCT-2007		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0251	NO. 2 ENGINE - FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0252	NO. 2 ENGINE - INTRODUCTION OF NEW RADIAL SHAFT SUPPORT GUIDE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						COMPLIED WITH
		MOS			07-SEP-2005		
		HRS/MSC	-		2202:24		
		ENC			511		
SB 72-0253 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0253 R3	NO. 2 ENGINE - FAN AND BOOSTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0253 R4	NO. 2 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0253 R5	NO. 2 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0253 R6	NO. 2 ENGINE - INTRODUCTION OF NEW FAN BLADE AND REWORK OF THE FAN BLADE PRESSURE FACE UNDERCUT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0254	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT FRAME WITH SYMMETRICAL STRUTS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0255	NO. 2 ENGINE - INTRODUCTION OF NEW BRACKET ASSY WITH NEW DESIGN FOR T49.5 HARNESS HOLDING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0255 R1	NO. 2 ENGINE - ENGINE ASSEMBLY - INTRODUCTION OF NEW BRACKET ASSY WITH NEW DESIGN FOR T49.5 HARNESS ATTACHMENT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0256	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0257	NO. 2 ENGINE - FAN FRAME ASSEMBLY - REPLACEMENT OF TWO BRACKETS ASSY TO ATTACH THE MW0315 AND MW0316 ELECTRICAL HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0258	NO. 2 ENGINE - NEW FIRE DETECTION HARNESSES MW0325 AND MW0326, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0258 R1	NO. 2 ENGINE - NEW FIRE DETECTION HARNESSES MW0325 AND MW0326, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

EFTA00618904

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0259	NO. 2 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR WITH DESIGN IMPROVED OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0259 R1	NO. 2 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR WITH DESIGN IMPROVED OR REWORK, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0259 R2	NO. 2 ENGINE - INTRODUCTION OF NEW N2 SPEED SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0260	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0260 R1	NO. 2 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0261	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0262	NO. 2 ENGINE - NEW MW0311 ELECTRICAL HARNESSES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0262 R1	NO. 2 ENGINE - NEW MW0311 ELECTRICAL HARNESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0263	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0264	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0265	NO. 2 ENGINE - INTRODUCTION OF NEW LPT SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0266	NO. 2 ENGINE - INTRODUCTION OF A NEW ASSY ON FLANGE B4 - CJ13 ELECTRICAL HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0266 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY ON FLANGE B4 - CJ13 ELECTRICAL HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0267	NO. 2 ENGINE - INTRODUCTION OF A NEW LOCKS OF STAGE 2,3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0267 R1	NO. 2 ENGINE - FAN AND BOOSTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0267 R2	NO. 2 ENGINE - FAN AND BOOSTER - INTRODUCTION OF A NEW LOCK OF STAGE 2, 3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
17-DEC-2001		HRS/MSC	-				
		ENC					
SB 72-0267 R3	NO. 2 ENGINE - FAN AND BOOSTER - INTRODUCTION OF A NEW LOCK OF STAGE 2, 3 AND 4 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R2	NO. 2 ENGINE - INTRODUCTION OF NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0268 R3	NO. 2 ENGINE - FAN AND BOOSTER - INTRODUCTION OF THE NEW BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
17-DEC-2001		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0269	NO. 2 ENGINE - FIRE DETECTION HARNESSES MW0325 AND MW0326 TERMINAL LUG REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0269 R1	NO. 2 ENGINE - FIRE DETECTION HARNESSES MW0325 AND MW0326 TERMINAL LUG REPLACEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0270	NO. 2 ENGINE - INTRODUCTION OF A NEW BRACKET ASSY-J7 HARNESS HOLDING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R1	NO. 2 ENGINE - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R2	NO. 2 ENGINE - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0271 R3	NO. 2 ENGINE - FAN BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	10000 (s)				
SB 72-0271 R4	NO. 2 ENGINE - FAN BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	10000 (s)				
SB 72-0271 R5	NO. 2 ENGINE - FAN AND BOOSTER (72-21-00) - REPLACEMENT OF THE FAN BLADE PLATFORM AND REWORK OF THE FAN BLADE PLATFORM BUSHING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0272	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0273	NO. 2 ENGINE - ROUTING OPTIMIZATION AND REMARKING OF THE HARNESSES MW0301 AND MW0302, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0273 R1	NO. 2 ENGINE - ROUTING OPTIMIZATION AND REMARKING OF THE HARNESSES MW0301 AND MW0302, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0274	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0275	NO. 2 ENGINE - NO.1 AND NO. 2 BEARING SUPPORT - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY AIR/OIL SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0275 R1	NO. 2 ENGINE - NO.1 AND NO. 2 BEARING SUPPORT ASSEMBLY - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0276	NO. 2 ENGINE - SPARE PARTS FOR CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0277	NO. 2 ENGINE - INTRODUCTION OF NEW OIL COLLECTOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0278	NO. 2 ENGINE - INTRODUCTION OF HPT/LPT NOZZLE SHROUD ASSEMBLY 9324M62G05 AND HPT NOZZLE SHROUD SUPPORT 2002M69G03, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0279	NO. 2 ENGINE - INTRODUCTION OF NEW HPT STATOR AIR MANIFOLD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0280	NO. 2 ENGINE - INTRODUCTION OF NEW PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0281	NO. 2 ENGINE - HARDWARE TRANSFER TO ENGINE LEVEL FROM CORE LEVEL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0283	NO. 2 ENGINE - GENERAL - INTRODUCTION OF CLAMP AND ATTACHING BOLT OF MW0325 HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0284	NO. 2 ENGINE - TRANFER OF THE VBV ACTUATORS FROM THE FAN FRAME LEVEL TO THE ENGINE ASSEMBLY LEVEL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0284 R1	NO. 2 ENGINE - TRANSFER OF THE VBV ACTUATORS FROM THE FAN FRAME LEVEL TO THE ENGINE ASSEMBLY LEVEL, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0285	NO. 2 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED., SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0285 R1	NO. 2 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0285 R2	NO. 2 ENGINE - GENERAL - REPLACEMENT OF CURRENT CLAMPS BY NEW CLAMPS WITH INNER DIAMETER MATERIAL THICKNESS INCREASED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0286 R1	NO. 2 ENGINE - TURBINE LOW PRESSURE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0286 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT BLADE STAGE 1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0287	NO. 2 ENGINE - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0287 R1	NO. 2 ENGINE - ENGINE - ENGINE(72-00-00) - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0287 R2	NO. 2 ENGINE - ENGINE - ENGINE(72-00-00) - ACCIDENT INVOLVED HARDWARE (SUPERSEDED BY SB 72-0287 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0287 R3	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - ACCIDENT INVOLVED HARDWARE (SUPERSEDED BY SB 72-0287 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0287 R4	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - ACCIDENT INVOLVED HARDWARE, SERVICE BULLETIN					INFORMATIONAL	
15-OCT-2013		MOS HRS/MSC - ENC					
SB 72-0288	NO. 2 ENGINE - INTRODUCTION OF NEW HPT INNER STATOR STATIONARY SEAL HEAT SHIELD TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0289	NO. 2 ENGINE - INTRODUCTION OF ALTERNATE INNER DOME, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0290	NO. 2 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0290 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291	NO. 2 ENGINE - TRANSFER GEARBOX, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291 R1	NO. 2 ENGINE - TRANSFER GEARBOX - INSPECTION OF A SPECIFIC POPULATION OF OUTER RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0291 R2	NO. 2 ENGINE - TRANSFER GEARBOX - INSPECTION OF A SPECIFIC POPULATION OF OUTER RADIAL DRIVE SHAFT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0292	NO. 2 ENGINE - LOW PRESSURE TURBINE SHAFT - DELETION OF THE PRELIMINARY ATTACHMENT SYSTEM OF THE AIR/OIL SEAL TO THE LPT SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0292 R1	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT (72-55-00) - DELETION OF THE PRELIMINARY ATTACHMENT SYSTEM OF THE AIR/OIL SEAL OF THE LPT SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0293	NO. 2 ENGINE - INTRODUCTION OF A SELF LOCKING BORESCOPE CAP ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0293 R1	NO. 2 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF SELF LOCKING BORESCOPE CAP ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0294	NO. 2 ENGINE - INTRODUCTION OF STAINLESS STEEL NUTS TO REPLACE CADMIUM PLATING NUTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0295	NO. 2 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL (SUPERSEDED BY 72-0295 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0295 R1	NO. 2 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL (SUPERSEDED BY 72-0295 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0295 R3	NO. 2 ENGINE - FAN AND BOOSTER (72-21-00) INSPECTION OF THE BOOSTER SPOOL, SERVICE BULLETIN						
22-JUN-2007		MOS					
		HRS/MSC					
		ENC	15000 (s)				
SB 72-0296	NO. 2 ENGINE - FAN AND BOOSTER (SUPERSEDED BY 72-0296 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0296 R1	NO. 2 ENGINE - FAN AND BOOSTER (SUPERSEDED BY 72-0296 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0296 R2	NO. 2 ENGINE - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0296 R3	NO. 2 ENGINE - INTRODUCTION OF COUNTER WEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0296 R4	NO. 2 ENGINE - FAN AND BOOSTER, INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL.(SUPERSEDED BY 72-0296 R5), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0296 R5	NO. 2 ENGINE - FAN AND BOOSTER - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R6), SERVICE BULLETIN						
17-DEC-2001		MOS					
		HRS/MSC					
		ENC	7000 (s)				
SB 72-0296 R6	NO. 2 ENGINE - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL (SUPERSEDED BY 72-0296 R7), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0296 R7	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF COUNTERWEIGHTS ON THE BOOSTER SPOOL, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	7000 (s)				
SB 72-0297	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0298	NO. 2 ENGINE - NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0298 R1	NO. 2 ENGINE - FAN FRAME ASSEMBLY - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0298 R2	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0298 R3	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW PROBE HOUSING WITH INCREASED LENGTH INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0299	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FOWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R3	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FORWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0300 R4	NO. 2 ENGINE - INTRODUCTION OF A NEW BOOSTER SPOOL WITH THE INCREASED THICKNESS FORWARD FLANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0301	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0302	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0303	NO. 2 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0303 R1	NO. 2 ENGINE - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0304	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
13-NOV-2001		HRS/MSC	15000 (s)				
		ENC					
SB 72-0304 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	15000 (s)				
		ENC					
SB 72-0304 R2	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	15000 (s)				
		ENC					
SB 72-0304 R3	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - ON-WING BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER OUTER COWL, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-MAR-2007		HRS/MSC	15000 (s)				
		ENC					
SB 72-0305	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0306	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0308	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0309	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/B1, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0310	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0311	NO. 2 ENGINE - LPT SHAFT - REPLACEMENT OF THE NO.4 ROLLER BEARING, SERVICE BULLETIN						
24-JAN-2001		MOS HRS/MSC ENC	-				
SB 72-0312	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0313	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0314	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	-				
SB 72-0315	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316	NO. 2 ENGINE - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R1	NO. 2 ENGINE - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316 R3	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0316R4	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF THE POWER FEEDER BRACKET ASSY AND DRAIN TUBE BRACKET, SERVICE BULLETIN						
24-JUN-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0317	NO. 2 ENGINE - SPARE PARTS INTRODUCTION, SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0318	NO. 2 ENGINE - APPLICATION OF ROOM TEMPERATURE VULCANIZING (RTV) ON THE FAN BLADE RETAING FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0318 R1	NO. 2 ENGINE - APPLICATION OF ROOM TEMPERATURE VULCANIZING (RTV) ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0319	NO. 2 ENGINE - INTRODUCTION OF A MILLED COMBUSTION CASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0319 R1	NO. 2 ENGINE - INTRODUCTION OF A MILLED COMBUSTION CASE, SERVICE BULLETIN						
10-DEC-2007		MOS HRS/MSC ENC	- 				
SB 72-0320	NO. 2 ENGINE - INTRODUCTION OF THE NEW REAR FLANGE AS ALTERNATE ON THE LPT NOZZLE STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0321	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				
SB 72-0322	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0322 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-NOV-2006		MOS HRS/MSC ENC	- 				
SB 72-0323	NO. 2 ENGINE - REPLACEMENT OF THE AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0323 R1	NO. 2 ENGINE - REPLACEMENT OF THE AIR MANIFOLD, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0324	NO. 2 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0324 R2	NO. 2 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0324 R3	NO. 2 ENGINE - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0324 R5	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF REWORKED FAN DISKS AND NEW SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
	03-JAN-2012		MOS					
			HRS/MSC	-				
			ENC					
SB	72-0325	NO. 2 ENGINE - ELASTOMER AXIAL STOP PIN, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0325 R1	NO. 2 ENGINE - ELASTOMETER AXIAL STOP PIN, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0325 R2	NO. 2 ENGINE - INTRODUCTION OF ELASTOMETER AXIAL STOP PIN INSTEAD OF RTV ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
	17-DEC-2001		MOS					
			HRS/MSC	-				
			ENC					
SB	72-0325 R3	NO. 2 ENGINE - INTRODUCTION OF ELASTOMETER AXIAL STOP PIN INSTEAD OF RTV ON THE FAN BLADE RETAINING FLANGE, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	72-0326	NO. 2 ENGINE - ON-WING BORESCOPE INSPECTION OF HPT BLADES, SERVICE BULLETIN						COMPLIED WITH
			MOS		22-AUG-2008		RECURRING	
	14-NOV-2001		HRS/MSC		3260:48			
			ENC	1000	746	**1746**		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0327	NO. 2 ENGINE - ENGINE - GENERAL - INSTALLATION OF A SAFETY WIRE OVER THE OIL TEMPERATURE PROBE HOUSING, SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0328	NO. 2 ENGINE - REDUCE INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0328 R1	NO. 2 ENGINE - REDUCE INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DMS INSPECTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0329	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING 305-355-717-0, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0330	NO. 2 ENGINE - INSPECTION AND REPLACEMENT OF THE IDENTIFICATION PLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0330 R1	NO. 2 ENGINE - INSPECTION AND REPLACEMENT OF THE IDENTIFICATION PLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0331	NO. 2 ENGINE - DELETION OF BURNER STAGING VALVE PARKING BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0332	NO. 2 ENGINE - INTRODUCTION OF NEW VSV INNER BUSHING AND WASHERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0332 R1	NO. 2 ENGINE - COMPRESSOR FRONT STATOR - INTRODUCTION OF NEW VSV INNER BUSHINGS AND WASHERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333	NO. 2 ENGINE - CORE MODULE AND FAN MODULE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0333 R1	NO. 2 ENGINE - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R2	NO. 2 ENGINE - CORE MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE HOLES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R3	NO. 2 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0333 R4	NO. 2 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE AND FAN FRAME - INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY WIRE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334	NO. 2 ENGINE - FAN MAJOR MODULE - INTRODUCTION OF A 4-5 O'CLOCK LPYACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334 R1	NO. 2 ENGINE - INTRODUCTION OF A 4-5 O'CLOCK LPTACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0334 R2	NO. 2 ENGINE - INTRODUCTION OF A 4-5 O'CLOCK LPT ACC STRUT PANEL WITH DESIGN IMPROVED OR REWORKED, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 72-0335	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0336	NO. 2 ENGINE - INSTALLATION OF SAFETY WIRE OVER THE OIL TEMPERATURE PROBE AND HOUSING, SERVICE BULLETIN						COMPLIED WITH
		MOS			07-JUL-2001		
		HRS/MSC	-		782		
		ENC			54		
SB 72-0337	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0337 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0338	NO. 2 ENGINE - ENGINE FAN AND BOOSTER SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0338 R1	NO. 2 ENGINE - ENGINE FAN AND BOOSTER SPARE PARTS RELEASE FOR CFM56-7B , SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0339	NO. 2 ENGINE - LPT FRAME - REPLACEMENT OF THE CURRENT OIL SUPPLY TUBE BY A REMOVABLE TUBE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0340	NO. 2 ENGINE - TURBINE FRAME, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0341	NO. 2 ENGINE - INTRODUCTION OF BOLTS FOR FUEL TUBE CLAMPS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0341 R1	NO. 2 ENGINE - INTRODUCTION OF BOLTS FOR FUEL TUBE CLAMPS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0342	NO. 2 ENGINE - DELETION OF STAGE 6-8 VANE SECTOR END BLOCKS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0342 R1	NO. 2 ENGINE - DELETION OF STAGE 6-8 VANE SECTOR END BLOCKS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0343	NO. 2 ENGINE - INTRODUCTION OD IMPROVED HPT ROTOR SPOOL WEIGHTS FOR STAGES 6-9, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0344	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE SPACER OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0344 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE SPACER OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0345 R1	NO. 2 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF NEW LPT NOZZLE SEGMENTS STAGE 2 AND A NEW SEALING PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0345 R2	NO. 2 ENGINE - TURBINE LOW PRESSURE (72-54-00) - INTRODUCTION OF NEW LPT NOZZLE SEGMENTS STAGE 2 AND A NEW SEALING PLATE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346	NO. 2 ENGINE - ENGINE - TURBINE LOW PRESSURE - (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS ON THE LPT STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346 R1	NO. 2 ENGINE - ENGINE - TURBINE LOW PRESSURE - (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS ON THE LPT STAGE 1, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0346 R2	NO. 2 ENGINE - ENGINE - TURBINE LOW PRESSURE (72-54-00) - REPLACEMENT OF BLADES AND DEFLECTORS OF THE LPT STAGE 1, SERVICE BULLETIN						
02-MAR-2006		MOS HRS/MSC - ENC					
SB 72-0347	NO. 2 ENGINE - ENGINE - INTRODUCTION OF NEW BALANCING CLIPS ON LPT STAGE 4, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0347 R1	NO. 2 ENGINE - INTRODUCTION OF NEW BALANCING CLIPS ON LPT STAGE 4 BLADES, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0348	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0349	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0350	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE - INTRODUCTION OF FIELD REWORK FOR HPT AIR MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0350 R1	NO. 2 ENGINE - INTRODUCE A FIELD REWORKED AIR HPT STATOR MANIFOLD P/N 2071M29G02, SERVICE BULLETIN						
30-JAN-2009		MOS HRS/MSC ENC	- 				
SB 72-0351 R1	NO. 2 ENGINE - INTRODUCTION OF HIGH PRESSURE TURBINE BLADE KIT 737L325G03 AND HPT BLADE 1957M10P01, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0352	NO. 2 ENGINE - INTRODUCTION OF NEW NO. 4 ROLLER BEARINGS WITH NEW OUTER RACE MATERIALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0352 R1	NO. 2 ENGINE - INTRODUCTION OF NEW NO. 4 ROLLER BEARINGS WITH NEW OUTER RACE MATERIALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0353	NO. 2 ENGINE - FAN AND BOOSTER (72-21-00) - INTRODUCTION OF A NEW FAN BLADE PLATFORM DESIGN 340-001-814-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0354	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0355	NO. 2 ENGINE - INTRODUCTION OF NEW BRACKETS ASSY ON THE AIR COOLING MANIFOLD ASSY UP AND DOWN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0355 R1	NO. 2 ENGINE - INTRODUCTION OF NEW BRACKETS ASSY ON THE AIR COOLING MANIFOLD ASSY UP AND DOWN, SERVICE BULLETIN						
04-AUG-2005		MOS HRS/MSC ENC	- 				
SB 72-0356	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0357 R1	NO. 2 ENGINE - INTRODUCTION OF NO. 4 STRUT FAIRING WITH NEW MATERIAL (STEEL VERSION), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0358	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY WITH AN OBLONG HOLE AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0359	NO. 2 ENGINE - INTRODUCTION OF NEW LPT REAR FRAME AND NEW OIL COLLECTOR WITH DELETION OF 16 HOLES AND BOLTS OUT OF 32, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0360	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0361	NO. 2 ENGINE - INTRODUCTION OF A NEW IDENTIFICATION PLATE WITH A 2D BARRED MANUFACTURER CODE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0362	NO. 2 ENGINE - INTRODUCTION OF NEW AFT ACOUSTICAL PANEL ASSEMBLY AT IDG AIR / OIL COOLER LOCATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0363	NO. 2 ENGINE - INTRODUCTION OF NEW STAGE 4 LOCKING BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0363 R1	NO. 2 ENGINE - INTRODUCTION OF NEW STAGE 4 LOCKING BLADES, SERVICE BULLETIN						
		MOS					
22-APR-2005		HRS/MSC	-				
		ENC					
SB 72-0364	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0365	NO. 2 ENGINE - REPLACEMENT OF BRACKETS BY NEW ONES WITH ERROR PROOFING DEVICE INSTALLATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0365 R1	NO. 2 ENGINE - REPLACEMENT OF BRACKETS BY NEW ONES WITH ERROR PROOFING DEVICE INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0366	NO. 2 ENGINE - REPLACEMENT OF FAN RETAINING FLANGE OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0366 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - REPLACEMENT OF THE FAN RETAINING FLANGE OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0367	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0368 R1	NO. 2 ENGINE - ENGINE-ACCESSORY GEARBOX (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0368 R2	NO. 2 ENGINE - ENGINE-ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
25-SEP-2006		MOS HRS/MSC - ENC					
SB 72-0368 R3	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT (SUPERSEDED BY SB 72-0368 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC - ENC					
SB 72-0368 R4	NO. 2 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A SUSPECT LOT, SERVICE BULLETIN						
18-OCT-2013		MOS HRS/MSC - ENC					
SB 72-0369	NO. 2 ENGINE - VGB GUIDE PAD INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 72-0371 R1	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0372	NO. 2 ENGINE - OIL TEMP PROBE SAFETYWIRE, SERVICE BULLETIN						COMPLIED WITH
		MOS		22-AUG-2008			
		HRS/MSC	-	3260:48			
		ENC		746			
SB 72-0374	NO. 2 ENGINE - FAN AND BOOSTER - TIGHTENING OF BOOSTER SPOOL FOWARD PINS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0375	NO. 2 ENGINE - HPT REAR SHAFT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0376	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0379	NO. 2 ENGINE - ENGINE-HIGH PRESSURE TURBINE NOZZLE (72-51-00) - REAR SUPPORT NUT SHIELD MATERIAL CHANGE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0380	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0381	NO. 2 ENGINE - INTRO HPC STG 4 BLADE KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0381 R1	NO. 2 ENGINE - INTRODUCTION OF STAGE 4 BLADE KIT TO THE SPARE PARTS LIST, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0382	NO. 2 ENGINE - REPLACEMENT OF NEW NO.5 ROLLER BEARING WITH AN OUTER RACE MODIFIED TO INCREASE THE THICKNESS OF THE OIL FILM OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0382 R1	NO. 2 ENGINE - INTRODUCTION OF NEW NO.5 ROLLER BEARING WITH AN OUTER RACE MODIFIED TO INCREASE THE THICKNESS OF THE OIL FILM OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0383	NO. 2 ENGINE - TURBINE LOW PRESSURE - BORESCOPE INSPECTION FOR STAGE 1 LPT BLADE POSITION, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0384	NO. 2 ENGINE - FAN AND BOOSTER - ONE TIME INSPECTION FOR RETAINING FLANGE THREADED PIN PRESENCE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0385	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0386	NO. 2 ENGINE - FAN AND BOOSTER - ONE TIME TIGHTENING OF FOWARD BOOSTER SPOOL PINS, SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0386 R1	NO. 2 ENGINE - FAN AND BOOSTER - ONE TIME TIGHTENING OF FOWARD BOOSTER SPOOL PINS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0388	NO. 2 ENGINE - HPTR FRT DAMPER SLEEVE INSPECT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0389	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR (72-52-00) - INTRODUCTION OF HIGH PRESSURE TURBINE BLADE P/N 1957M72P01 AND P/N 1957M72P02 THROUGH FIELD REWORK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0390	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0391	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - DRAIN TUBE REDUCER ELIMINATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0392	NO. 2 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - FUEL NOZZLE BOLT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0392 R1	NO. 2 ENGINE - FUEL NOZZLE BOLT LENGTH OPTIMIZATION, SERVICE BULLETIN						
11-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0392 R2	NO. 2 ENGINE - FUEL NOZZLE BOLT LENGTH OPTIMIZATION, SERVICE BULLETIN						
13-JUN-2007		MOS HRS/MSC ENC	-				
SB 72-0393	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF A NEW CFM56-7B27A ACCESSORY GEARBOX ASSY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0393 R1	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF A NEW CFM56-7B27A ACCESSORY GEARBOX ASSY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0394	NO. 2 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE - BRACKET HARDWARE ELIMINATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0395	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF NO. 4 ROLLER BEARING 340-167-901-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0395 R1	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF NO. 4 ROLLER BEARING 340-167-901-0, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0396 R2	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR (72-31-00) - FLOURESCENT-PENETRANT-INSPECTION OF HIGH PRESSURE COMPRESSOR STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0398	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0399	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0399 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400	NO. 2 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARING IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R1	NO. 2 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARING IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R2	NO. 2 ENGINE - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO.4 ROLLER BEARINGS IN FIELD (SUPERSEDED BY 72-0400 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0400 R3	NO. 2 ENGINE - LPT SHAFT ASSEMBLY (72-55-00) - REPLACEMENT OF OUTER RACE BY A NEW OUTER RACE MATERIAL FOR NO. 4 ROLLER BEARINGS IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0401	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0402	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0403	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR REAR SHAFT WITH IMPROVED DAMPING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0404	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0411	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0414	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
07-JUL-2008		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0415	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CF56-7B IPC, SERVICE BULLETIN						
20-DEC-2002		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0417	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0419	NO. 2 ENGINE - SPARE PARTS FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0420	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0421	NO. 2 ENGINE - INTRODUCTION OF HPC REAR STATOR 1887M17G01, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0422	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
23-NOV-2009		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0423	NO. 2 ENGINE - TURBINE LOW PRESSURE (72-54-00) - REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR RETAINING PLATE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0423 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR RETAINING PLATE, SERVICE BULLETIN						
02-SEP-2011		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0425	NO. 2 ENGINE - ENGINE-GENERAL-SPARE PARTS RELEASE FOR CFM56-7 IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0427	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0429	NO. 2 ENGINE - ACCESSORY GEARBOX (72-63-00) - INTRODUCTION OF N2 SENSOR ADJUSTMENT SHIM SCREWS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0431	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00)-INTRODUCTION OF IMPROVED DOUBLE ANNULAR COMBUSTION (DAC) CHAMBER INNER LINER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0432	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
08-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0433	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0434	NO. 2 ENGINE - COMBUSTION CHAMBER (72-42-00) PIN AND MATING SLOT ELIMINATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0435	NO. 2 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0436	NO. 2 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - FUEL SPRAY SHIELD MATERIAL IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0437	NO. 2 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0438	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
10-APR-2006		MOS HRS/MSC ENC	- -				
SB 72-0439	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - MODIFICATION OF HARDWARE FOR THE NEW BOEING FIRE DETECTION ROUTING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0439 R1	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - MODIFICATION OF HARDWARE FOR THE NEW BOEING FIRE DETECTION ROUTING, SERVICE BULLETIN						
28-APR-2003		MOS HRS/MSC ENC	- -				
SB 72-0440 R1	NO. 2 ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOL ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD., SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R3	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R4	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0440 R6	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - IDG AIR/OIL COOLER ACOUSTICAL PANEL REMOVAL AND ON WING OR IN SHOP INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
25-SEP-2006		MOS HRS/MSC ENC	 DUE				
SB 72-0441	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND LOW PRESSURE TURBINE NOZZLE STAGE 1 (72-53-00) - INTRODUCTION OF A NEW FRONT FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0442	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND LOW PRESSURE TURBINE NOZZLE STAGE 1 (72-53-00) - INTRODUCTION OF A NEW REAR FLANGE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				

© Camp Systems

EFTA00618931

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0442 R1	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW REAR FLANGE ON THE LPT STAGE 1 NOZZLE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0444	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
30-NOV-2006		MOS HRS/MSC ENC	-				
SB 72-0445	NO. 2 ENGINE - ENGINE-TRANSFER GEARBOX (72-62-00) - REPLACEMENT OF BALL BEARING 340-052-502-0 IN A SUSPECT LOT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0446	NO. 2 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0446 R1	NO. 2 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
30-MAY-2006		MOS HRS/MSC ENC	-				
SB 72-0447	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR (72-31-00) - BLADE AND VANE IMPROVEMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0447 R1	NO. 2 ENGINE - IMPROVE THE DURABILITY OF THE HPC BLADES AND VANES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0448	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0449	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0449 R1	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
26-JUN-2008		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618932

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0450	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FAN RETAINING FLANGE PINS AND FAN DISK MID-FLANGE LOG PINS ON ALL CFM5607B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0450 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FAN RETAINING FLANGE PINS AND FAN DISK MID-FLANGE LUG PINS ON ALL CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0451	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FORWARD BOOSTER SPOOL PINS ON CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0451 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - ONE TIME TIGHTENING WITH INCREASED TORQUE OF FORWARD BOOSTER SPOOL PINS ON CFM56-7B ENGINES, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	1500 (s)				
SB 72-0452	NO. 2 ENGINE - ENGINE - TURBINE LOW PRESSURE (72-54-00) - IN SHOP VISUAL INSPECTION OF STAGE 2 NOZZLE SEGMENTS FOR AXIAL CRACKS ON AIRFOIL LEADING EDGE, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0452 R1	NO. 2 ENGINE - IN SHOP VISUAL INSPECTION OF STAGE 2 NOZZLE SEGMENTS FOR AXIAL CRACKS ON AIRFOIL LEADING EDGE, SERVICE BULLETIN	MOS					
		HRS/MSC					
		ENC	9000 (s)				
SB 72-0453	NO. 2 ENGINE - ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0454	NO. 2 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION, SERVICE BULLETIN	MOS					
		HRS/MSC	-				
		ENC					
SB 72-0454 R1	NO. 2 ENGINE - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION IN FIELD ONLY, SERVICE BULLETIN	MOS					
06-DEC-2007		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0454 R2	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER (72-21-00) - IMPROVEMENT OF THE FAN AND BOOSTER VANE ASSY TO PREVENT THE CORROSION IN FIELD ONLY, SERVICE BULLETIN						
		MOS					
01-JUL-2009		HRS/MSC	-				
		ENC					
SB 72-0455	NO. 2 ENGINE - COMBUSTION CHAMBER (72-42-00) - SWIRLERS - THICK FLANGE (SUPERSEDED BY SB 72-0455 R1), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0455 R1	NO. 2 ENGINE - COMBUSTION CHAMBER (72-42-00) - SWIRLERS - THICK FLANGE, SERVICE BULLETIN					CATEGORY 7	
		MOS					
02-MAY-2014		HRS/MSC	-				
		ENC					
SB 72-0457	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0459	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0460	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0460 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0461	NO. 2 ENGINE - ENGINE - HPT ROTOR (72-52-00) - NEW DISK WITH IMPROVED LIFE DESIGN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0462	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW MW0312 HARNESS WITH A NEW DP1204 CONNECTOR AND REWORK OF THE OLD HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0462 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW MW0312 HARNESS WITH A NEW DP1204 CONNECTOR AND REWORK OF THE OLD HARNESS, SERVICE BULLETIN						
		MOS					
27-AUG-2008		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0463	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0463 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0464	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR MANIFOLD ASSY AND OF NEW BRACKETS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0465	NO. 2 ENGINE - GENERAL - INTRODUCTION OF DAMPERS ON THE ACCESSORY GEARBOX AXIAL LINK ENDS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0465 R1	NO. 2 ENGINE - GENERAL - INTRODUCTION OF DAMPERS ON THE ACCESSORY GEARBOX AXIAL LINK ENDS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0466	NO. 2 ENGINE - ENGINE - HPT (72-51-00) - NEW NOZZLES - ADDITIONAL COOLING HOLES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0466 R1	NO. 2 ENGINE - ENGINE - HPT (72-51-00) - NEW NOZZLES - ADDITIONAL COOLING HOLES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0467	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0468	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - DELETION OF THE FLAT WASHERS AT THE MAIN OIL/FUEL HEAT EXCHANGER AND FUEL RETURN TUBE LOCATION, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0469	NO. 2 ENGINE - HPC (72-32-00) - STAGES 2 AND 3 SHROUDS - LEADING EDGE CUTBACK, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0471	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0474	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0475	NO. 2 ENGINE - INTRODUCTION OF NEW AIR TUBE, A NEW BRACKET ASSY WITH SAFETY WIRE HOLES AND REWORK OF THE PREVIOUS CONFIGURATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0476	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0477	NO. 2 ENGINE - INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0477 R2	NO. 2 ENGINE - INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD, SERVICE BULLETIN						
06-FEB-2008		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0480	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0481 R1	NO. 2 ENGINE - IN FIELD INTRODUCTION OF FAN BLADE SHIMS WITH NEW AXIAL STOP, SERVICE BULLETIN						
		DAYS	1 (s)				
		HRS/MSC					
		ENC					
SB 72-0482	NO. 2 ENGINE - GENERAL - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0483	NO. 2 ENGINE - ENGINE - HPT (72-51-00) - NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0483 R1	NO. 2 ENGINE - ENGINE - HPT (72-51-00) - NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0484	NO. 2 ENGINE - INTRODUCTION OF A NEW FUEL SUPPLY TUBE, SERVICE BULLETIN						
11-MAR-2005		MOS HRS/MSC ENC	- 				
SB 72-0485	NO. 2 ENGINE - INTRODUCTION OF NEW FAN DISK AND NEW SPACERS AND NEW SHIMS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0485 R1	NO. 2 ENGINE - INTRODUCTION OF NEW FAN DISK AND NEW SPACERS AND NEW SHIMS, SERVICE BULLETIN						
13-AUG-2004		MOS HRS/MSC ENC	- 				
SB 72-0486	NO. 2 ENGINE - ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0487	NO. 2 ENGINE - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL AND NEW NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS, SERVICE BULLETIN						
09-NOV-2004		MOS HRS/MSC ENC	- 				
SB 72-0487 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW NO.1 BEARING STATIONARY SEAL AND INTRODUCTION OF A NEW NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0488 R1	NO. 2 ENGINE - REPLACEMENT OF IDENTIFICATION PLATES ON THE TRANSFER GEARBOX ASSEMBLY AND THE ACCESSORY GEARBOX ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0489	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0489 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0490	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0491	NO. 2 ENGINE - NEW MATERIAL (N5-) TO ELIMINATE YTTRIUM AND REDUCE SULFUR, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0493	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0494	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0495 R2	NO. 2 ENGINE - REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINUM DOUBLER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0495 R3	NO. 2 ENGINE - REWORK AND REIDENTIFICATION OF FAN FRAME SHROUD WITH AN ALUMINUM DOUBLER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0497	NO. 2 ENGINE - INTRODUCTION OF VESPEL NUTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0498	NO. 2 ENGINE - REDUCE INSPECTION INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 50 (s) 				
SB 72-0498 R1	NO. 2 ENGINE - REDUCE INSPECTION INTERVAL FOR AFT SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS HRS/MSC ENC	 50 (s) 				
SB 72-0499 R1	NO. 2 ENGINE - INTRODUCTION OF NEW NO.5 BEARING SUPPORT NIPPLE DESIGN OR REWORK OF THE OLD ONE, SERVICE BULLETIN						
16-DEC-2006		MOS HRS/MSC ENC	- -				
SB 72-0500	NO. 2 ENGINE - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0500 R2	NO. 2 ENGINE - ENGINE - HPC (72-31-00) - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					OPTIONAL	
02-MAR-2011		MOS HRS/MSC ENC	- 				
SB 72-0500 R3	NO. 2 ENGINE - ENGINE - HPC (72-31-00) - REWORK PART NUMBERS TO THE IPC, SERVICE BULLETIN					OPTIONAL	
17-AUG-2011		MOS HRS/MSC ENC	- 				
SB 72-0501 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - DELETION OF THE BLANKING PLATE AND INTRODUCTION OF A NEW OIL SUPPLY TUBE WITH ITS NEW ATTACHMENT BRACKETS., SERVICE BULLETIN						
14-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0502 R1	NO. 2 ENGINE - REPLACEMENT OF NO.10 STRUT FAIRING (STEEL VERSION) BY STRUT FAIRING (ALUMINUM VERSION), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0502 R2	NO. 2 ENGINE - REPLACEMENT OF NO.10 STRUT FAIRING (STEEL VERSION) BY STRUT FAIRING (ALUMINUM VERSION), SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503	NO. 2 ENGINE - FORWARD INNER NOZZLE SUPPORT - FORWARD FLANGE REPLACEMENT AND COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503 R1	NO. 2 ENGINE - FORWARD INNER NOZZLE SUPPORT - FORWARD FLANGE REPLACEMENT AND COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0503 R2	NO. 2 ENGINE - ENGINE -HPT (72-51-00) -FORWARD INNER NOZZLE SUPPORT -FORWARD FLANGE REPLACEMENT AND COATING , SERVICE BULLETIN						
29-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0506	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN						
30-JUL-2004		MOS HRS/MSC ENC	- (s) 				
SB 72-0506 R1	NO. 2 ENGINE - INSPECTION OF OUTER LINER COOLING HOLES, SERVICE BULLETIN					SUPERSEDED	
23-AUG-2006		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0507	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0509	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0509 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0510	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0511	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0512	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLER PANEL IN TWO PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0512 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN FRAME SHROUD WITH NEW IDG AIR/OIL COOLER PANEL IN TWO PARTS AND REWORK OF THE PREVIOUS CONFIGURATION, SERVICE BULLETIN						
06-OCT-2006		MOS HRS/MSC ENC	- 				
SB 72-0513	NO. 2 ENGINE - SPARE PARTS INFORMATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0514 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC (SUPERSEDED BY SB 72-0514 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0514 R2	NO. 2 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN					CATEGORY 8	
22-NOV-2013		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0515	NO. 2 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
			MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R1	NO. 2 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
			MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R2	NO. 2 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
	18-APR-2006		MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R3	NO. 2 ENGINE - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
			MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R4	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN						
	12-FEB-2009		MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R5	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
			MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R6	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
	03-OCT-2011		MOS HRS/MSC ENC	24000 (s)				
SB	72-0515 R7	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - ON WING BORESCOPE INSPECTION FOR HPC STATOR-TO-ROTOR CONTACT, SERVICE BULLETIN					RECOMMENDED	
	21-OCT-2011		MOS HRS/MSC ENC	24000 (s)				
SB	72-0520	NO. 2 ENGINE - INSPECTION OF THE FORWARD LPT SHAFT FOR MISSING PAINT, SERVICE BULLETIN						
	08-FEB-2006		MOS HRS/MSC ENC	-				
SB	72-0521	NO. 2 ENGINE - INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0521 R1	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS, SERVICE BULLETIN					RECOMMENDED	
13-JUN-2012		MOS HRS/MSC ENC	- -				
SB 72-0522	NO. 2 ENGINE - INTRODUCTION OF AN IDENTIFICATION PLATE COMPLYING WITH THE NEW EUROPEAN REGULATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0523	NO. 2 ENGINE - INTRODUCTION OF A NEW CONNECTING TUBE WITH A NEW COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0523 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW CONNECTING TUBE WITH A NEW COATING, SERVICE BULLETIN						
29-NOV-2006		MOS HRS/MSC ENC	- -				
SB 72-0524	NO. 2 ENGINE - ENGINE - COMBUSTOR (72-42-00) - NEW DOME, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0525	NO. 2 ENGINE - FAN DISK DOVETAIL FACES WEAR DEPTH INSPECTION, SERVICE BULLETIN						
25-MAR-2005		MOS HRS/MSC ENC	 3000 (s)				
SB 72-0525 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	- -				
SB 72-0525 R2 PARA D (1)	NO. 2 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-410-0)					RECOMMENDED	
		MOS HRS/MSC ENC	 2000 (s)				
SB 72-0525 R2 PARA D (2)	NO. 2 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-420-0)					RECOMMENDED	
		MOS HRS/MSC ENC	 7000 (s)				
SB 72-0525 R2 PARA D (3)	NO. 2 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-471/472/473/474)					RECOMMENDED	
		MOS HRS/MSC ENC	 7000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0525 R2 PARA D (4)	NO. 2 ENGINE - WEAR INSPECTION ENGINE - GENERAL (72-00-00) - FAN DISK PRESSURE FACES INSPECTION, SERVICE BULLETIN FAN DISK DOVETAIL PRESSURE FACES (340-000-485/486/490-0)					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	7000 (s)				
SB 72-0527	NO. 2 ENGINE - INTRODUCTION OF NEW LOW PRESSURE TURBINE (LPT) REAR FRAMES WITH A NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0527 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LOW PRESSURE TURBINE (LPT) REAR FRAMES WITH A NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
29-SEP-2005		HRS/MSC	-				
		ENC					
SB 72-0527 R2	NO. 2 ENGINE - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
21-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0527 R3	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN						
		MOS					
22-DEC-2009		HRS/MSC	-				
		ENC					
SB 72-0527 R4	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
04-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0528	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0529	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0530	NO. 2 ENGINE - BELLCRANK SUPPORT NUT LENGTH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0531 R1	NO. 2 ENGINE - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
26-SEP-2006		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618943

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0531 R2	NO. 2 ENGINE - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
10-APR-2008		MOS HRS/MSC ENC	- (s)				
SB 72-0531 R3	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
25-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0531 R4	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - NEW INSPECTION OF FAN FRAME SHROUD, SERVICE BULLETIN						
18-APR-2013		MOS HRS/MSC ENC	ESV				
SB 72-0533	NO. 2 ENGINE - ENGINE - COMBUSTOR (72-41-00) - SWIRLER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0536	NO. 2 ENGINE - INNER LINER EXTENSION FOR REPAIR, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0539	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0540	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0540 R1	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
18-APR-2005		MOS HRS/MSC ENC	-				
SB 72-0540 R2	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
29-AUG-2007		MOS HRS/MSC ENC	-				
SB 72-0541	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0542	NO. 2 ENGINE - HPT NOZZLE FORWARD INNER NOZZLE SUPPORT (FINS) WITH IMPROVED EROSION COATING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0543	NO. 2 ENGINE - INTRODUCTION OF A NEW OIL INLET COVER O-RING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0545	NO. 2 ENGINE - FAN DISK LIFE LIMIT INCREASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	16000 (s)				
SB 72-0547	NO. 2 ENGINE - ON WING INSPECTION AND SHOP LEVEL ACTION FOT INNER AND OUTER LINERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	1600 (s)				
SB 72-0547 R1	NO. 2 ENGINE - ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OUTER LINERS, SERVICE BULLETIN						
08-MAR-2006		MOS					
		HRS/MSC					
		ENC	1600 (s)				
SB 72-0548	NO. 2 ENGINE - INTRODUCTION OF A NEW ELASTOMER SPACER, SERVICE BULLETIN						
		MOS					
17-FEB-2006		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0548 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW ELASTOMER SPACER, SERVICE BULLETIN						
		MOS					
25-OCT-2006		HRS/MSC	5000 (s)				
		ENC	3000				
SB 72-0550	NO. 2 ENGINE - INTRODUCTION OF A NEW REAR VENT TUBE, SERVICE BULLETIN						
		MOS					
16-FEB-2007		HRS/MSC	-				
		ENC					
SB 72-0552	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR/STATOR ASSEMBLY (72-54-00) - REIDENTIFICATION OF LPT CASE IN FIELD, SERVICE BULLETIN						
		MOS					
27-JAN-2006		HRS/MSC	-				
		ENC					
SB 72-0552 R1	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR/STATOR ASSEMBLY (72-54-00) - REIDENTIFICATION OF LPT CASE IN FIELD, SERVICE BULLETIN						
		MOS					
16-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0553	NO. 2 ENGINE - INTRODUCTION OF AN ANTI-EROSION PAINT ON THE FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
20-OCT-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0553 R1	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF AN ANTI-EROSION PAINT ON THE FAN FRAME ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0554	NO. 2 ENGINE - REDUCED INSPECTION INTERVAL FOR FORWARD SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0554 R1	NO. 2 ENGINE - REDUCED INSPECTION INTERVAL FOR FORWARD SUMP MAGNETIC CHIP DETECTOR OR DEBRIS MONITORING SYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	50 (s)				
		ENC					
SB 72-0555	NO. 2 ENGINE - ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0556	NO. 2 ENGINE - FORWARD INNER NOZZLE SUPPORT (FINS) - WITH IMPROVED EROSION COATING, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0557	NO. 2 ENGINE - ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0558	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
18-JAN-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0558 R1	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
21-SEP-2007		MOS					
		HRS/MSC					
		ENC		16350 (s)			
SB 72-0558 R2	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
02-DEC-2008		MOS					
		HRS/MSC					
		ENC		16350 (s)			
SB 72-0558 R3	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC		16350 (s)			

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0558 R4	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON DAC ENGINES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
21-MAY-2013		HRS/MSC	-				
		ENC					
SB 72-0559	NO. 2 ENGINE - INTRODUCTION OF NEW MW0316 FIRE DETECTION HARNESS, SERVICE BULLETIN						
		MOS					
06-JUN-2007		HRS/MSC	-				
		ENC					
SB 72-0560	NO. 2 ENGINE - INTRODUCTION OF A NEW MW0301 HARNESS WITH A NEW ROUTING, SERVICE BULLETIN						
		MOS					
01-MAR-2007		HRS/MSC	-				
		ENC					
SB 72-0561	NO. 2 ENGINE - INTRODUCTION OF OLD NO.1 BEARING VIBRATION SENSOR ATTACHING PARTS WITH NEW STATIONARY SEAL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0562	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
17-JAN-2006		HRS/MSC	-				
		ENC					
SB 72-0563	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
22-MAY-2006		HRS/MSC	-				
		ENC					
SB 72-0564	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION IN PRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW STARTER DRIVE PAD AND NEW HANDCRANCKING COVER, SERVICE BULLETIN						
		MOS					
13-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0564 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0564 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
		MOS					
16-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0564 R3	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE (SUPERSEDED BY SB 72-0564 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0564 R4	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE (SUPERSEDED BY SB 72-0564 R5), SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0564 R5	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH A NEW STARTER DRIVE PAD AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN					CATEGORY 3	
14-JAN-2014		MOS HRS/MSC ENC	ESV				
SB 72-0565 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0566	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
23-MAY-2006		MOS HRS/MSC ENC	-				
SB 72-0567	NO. 2 ENGINE - INTRODUCTION OF A NEW OR REWORKED STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
10-MAY-2007		MOS HRS/MSC ENC	-				
SB 72-0567 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-03) - INTRODUCTION OF A NEW OR REWORKED STAGE 1 SEAL SEGMENT, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0568	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
20-MAR-2006		MOS HRS/MSC ENC	-				
SB 72-0568 R1	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
21-SEP-2007		MOS HRS/MSC ENC	17400 (s)				
SB 72-0568 R2	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS HRS/MSC ENC	17400 (s)				
SB 72-0569	NO. 2 ENGINE - INTRODUCTION OF NEW SPACERS ON THE B6 FRONT FLANGE OF THE FAN FRAME, SERVICE BULLETIN						
23-MAR-2007		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618948

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0569 R1	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF NEW SPACERS ON THE B6 FRONT FLANGE OF THE FAN FRAME, SERVICE BULLETIN						
		MOS					
14-OCT-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R1	NO. 2 ENGINE - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
03-JUL-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R2	NO. 2 ENGINE - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN						
		MOS					
02-SEP-2008		HRS/MSC	-				
		ENC					
SB 72-0570 R3	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD (SUPERSEDED BY SB 72-0570 R4), SERVICE BULLETIN						
		MOS					
13-JUN-2012		HRS/MSC	-				
		ENC					
SB 72-0570 R4	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - IMPROVEMENT OF SUPPORTING HARDWARE ON FAN CASE AND FAN FRAME SHROUD, SERVICE BULLETIN					CATEGORY 7	
		MOS					
26-JUN-2014		HRS/MSC	-				
		ENC					
SB 72-0571	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
23-MAR-2007		HRS/MSC	-				
		ENC					
SB 72-0572	NO. 2 ENGINE - HPT OUTER STATIONARY SEAL WITH INTEGRAL NUT SHIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0573	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
24-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0574	NO. 2 ENGINE - NEW NO.3 BEARING REAR STATIONARY AIR/OIL SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
		MOS					
10-APR-2006		HRS/MSC	-				
		ENC					
SB 72-0574 R1	NO. 2 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
		MOS					
24-JUL-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0574 R2	NO. 2 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
20-SEP-2006		MOS HRS/MSC ENC	-				
SB 72-0574 R3	NO. 2 ENGINE - NO.3 BEARING (72-00-01)- NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
24-OCT-2006		MOS HRS/MSC ENC	-				
SB 72-0574 R4	NO. 2 ENGINE - NEW STATIONARY SEAL WITH IMPROVED ADHESIVE, SERVICE BULLETIN						
31-AUG-2007		MOS HRS/MSC ENC	-				
SB 72-0575	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0576	NO. 2 ENGINE - REPAIR PARTS, SERVICE BULLETIN						
20-JUL-2006		MOS HRS/MSC ENC	-				
SB 72-0578	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0579	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
04-JUL-2006		MOS HRS/MSC ENC	-				
SB 72-0579 R1	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
27-OCT-2006		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R2	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R3	NO. 2 ENGINE - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
09-APR-2008		MOS HRS/MSC ENC	19000 (s)				
SB 72-0579 R4	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
01-DEC-2008		MOS HRS/MSC ENC	19000 (s)				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0579 R5	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R6	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS					
15-DEC-2009		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R7	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS					
19-FEB-2010		HRS/MSC					
		ENC	19000 (s)				
SB 72-0579 R8	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
		MOS					
25-JAN-2012		HRS/MSC					
		ENC	19000 (s)				
SB 72-0580	NO. 2 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
25-MAY-2007		HRS/MSC	-				
		ENC					
SB 72-0580 R1	NO. 2 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
25-MAY-2008		HRS/MSC	-				
		ENC					
SB 72-0580 R2	NO. 2 ENGINE - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
27-APR-2009		HRS/MSC	-				
		ENC					
SB 72-0580 R3	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - REWORK FOR FAN CONTAINMENT CASE B1 FLANGE AT FIRE DETECTOR LOCATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0581	NO. 2 ENGINE - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
		MOS					
26-JUL-2006		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0581 R1	NO. 2 ENGINE - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
12-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0581 R2	NO. 2 ENGINE - ENGINE - HPC STATOR FORWARD ASSEMBLY (72-32-00) - STAGE 2 AND STAGE 3 IMPROVED INNER BUSHINGS, VANES, SEALS AND SHROUDS, SERVICE BULLETIN						
14-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0582	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
07-AUG-2006		MOS HRS/MSC ENC	-				
SB 72-0582 R1	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
25-SEP-2006		MOS HRS/MSC ENC	-				
SB 72-0584 R1	NO. 2 ENGINE - INTRODUCTION OF NEW ENHANCED DURABILITY HPT BLADES, SERVICE BULLETIN						
04-JUN-2007		MOS HRS/MSC ENC	-				
SB 72-0584 R2	NO. 2 ENGINE - INTRODUCTION OF NEW ENHANCED DURABILITY HPT BLADES, SERVICE BULLETIN						
31-AUG-2007		MOS HRS/MSC ENC	-				
SB 72-0585	NO. 2 ENGINE - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN						
04-SEP-2006		MOS HRS/MSC ENC	-				
SB 72-0585 R1	NO. 2 ENGINE - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
25-APR-2008		MOS HRS/MSC ENC	-				
SB 72-0585 R2	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FIELD INTRODUCTION OF REWORKED FAN DISK, SPACERS AND SHIMS, SERVICE BULLETIN					OPTIONAL	
03-JAN-2012		MOS HRS/MSC ENC	-				
SB 72-0586	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE PLATFORM WITH A NEW ELASTOMER SEAL, SERVICE BULLETIN						
24-NOV-2006		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0586 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW FAN BLADE PLATFORM WITH A NEW ELASTOMER SEAL, SERVICE BULLETIN						
02-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0587	NO. 2 ENGINE - LPT FRAME ASSEMBLY (72-56-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
04-JUL-2008		MOS HRS/MSC ENC	-				
SB 72-0588	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B18/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0589	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0589 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0589 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B20/3, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0590	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0591	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0591 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B22/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0593	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	-				
SB 72-0593 R1	NO. 2 ENGINE - CONVERSION OF ANY AFFECTED CFM56-7B MODEL ENGINE TO ALLOWABLE DERIVATIVE MODEL DESIGNATIONS, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0593 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- - -				
SB 72-0594	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B24/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0594 R1	NO. 2 ENGINE - CFM56-78 ENGINE CONVERSION TO CFM56-7B24/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- - -				
SB 72-0595	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
13-APR-2007		MOS HRS/MSC ENC	- - -				
SB 72-0595 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
13-AUG-2007		MOS HRS/MSC ENC	- - -				
SB 72-0595 R2	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- - -				
SB 72-0596	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3F, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- - -				
SB 72-0596 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3F, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- - -				
SB 72-0597	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B1, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- - -				
SB 72-0597 R1	NO. 2 ENGINE - CFM56-78 ENGINE CONVERSION TO CFM56-7B26/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- - -				
SB 72-0600	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- - -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0601 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0602	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0603	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0603 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0604	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1F, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0604 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B27/3B1F, SERVICE BULLETIN						
24-OCT-2007		MOS HRS/MSC ENC	- 				
SB 72-0605	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
07-NOV-2006		MOS HRS/MSC ENC	- 				
SB 72-0606	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
31-MAY-2007		MOS HRS/MSC ENC	- 				
SB 72-0607	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
01-SEP-2006		MOS HRS/MSC ENC	- 				
SB 72-0608	NO. 2 ENGINE - INSPECTION OF THE LOW PRESSURE TURBINE (LPT) CASE, SERVICE BULLETIN						
23-AUG-2007		MOS HRS/MSC ENC	- 				
SB 72-0608 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-03) - INSPECTION OF THE LOW PRESSURE TURBINE (LPT) CASE ON ASSEMBLED LPT MODULE, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0609	NO. 2 ENGINE - INTRODUCTION OF N5 HPT SHROUDS WITH HEAT TRANSFER ENHANCEMENT (HTE) BUMPS, SERVICE BULLETIN						
		MOS					
25-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0610	NO. 2 ENGINE - INTRODUCTION OF 8 MIL THICK HPC GUIDE SECTORS, SERVICE BULLETIN						
		MOS					
15-NOV-2006		HRS/MSC	-				
		ENC					
SB 72-0611	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
31-OCT-2006		HRS/MSC	-				
		ENC					
SB 72-0612	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-OCT-2006		HRS/MSC	-				
		ENC					
SB 72-0613	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
25-SEP-2006		HRS/MSC	-				
		ENC					
SB 72-0614	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
09-NOV-2006		HRS/MSC	-				
		ENC					
SB 72-0615	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
08-FEB-2007		HRS/MSC	-				
		ENC					
SB 72-0616	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0617	NO. 2 ENGINE - CLEANING OF THE CONTROL ALTERNATOR AND CHANGE OF THE NUTS ATTACHING THE LINE NO. 1 BEARING OUTER RACE ON THE AGB HOUSING, SERVICE BULLETIN						
		MOS					
03-JUL-2007		HRS/MSC	10000 (s)				
		ENC	5000				
SB 72-0617 R2	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - CLEANING OF THE CONTROL ALTERNATOR AND INSPECTION OF THE KEY-LOCKED STUDS ATTACHING THE LINE NO. 1 BEARING OUTER RACE ON THE AGB HOUSING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	10000 (s)				
		ENC	5000				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0618	NO. 2 ENGINE - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
25-JAN-2007		MOS HRS/MSC ENC	-				
SB 72-0618 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0618 R2	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW DESIGN OF LPT STAGE 1 NOZZLE SEGMENT, SERVICE BULLETIN						
09-OCT-2008		MOS HRS/MSC ENC	-				
SB 72-0619	NO. 2 ENGINE - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
27-SEP-2007		MOS HRS/MSC ENC	-				
SB 72-0619 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
02-DEC-2008		MOS HRS/MSC ENC	-				
SB 72-0619 R2	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW STAGE 3 ROTATING RING, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0620	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
19-DEC-2006		MOS HRS/MSC ENC	-				
SB 72-0621	NO. 2 ENGINE - FIELD INTRODUCTION OF A NEW PLATE WITH TECH INSERTION KITS INSTALLED AND N1 TRIM INFORMATION, SERVICE BULLETIN						
16-JUL-2007		MOS HRS/MSC ENC	-				
SB 72-0621 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - FIELD INTRODUCTION OF A NEW PLATE WITH TECH INSERTION KITS INSTALLED AND N1 TRIM INFORMATION, SERVICE BULLETIN						
01-DEC-2011		MOS HRS/MSC ENC	-				
SB 72-0622	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-SEP-2007		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0623	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0626	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
28-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0626 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
21-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0626 R2	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN						
04-MAY-2009		MOS HRS/MSC ENC	- 				
SB 72-0626 R3	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT CASE AND NEW STAGE 1 SEAL SEGMENTS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
30-MAR-2012		MOS HRS/MSC ENC	- 				
SB 72-0627	NO. 2 ENGINE - DELETION IN PRODUCTION OF THE ALTERNATE STAGE 3 ROTATING AIR SEAL RING, SERVICE BULLETIN						
28-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0627 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - DELETION IN PRODUCTION OF THE ALTERNATE STAGE 3 ROTATING AIR SEAL RING, SERVICE BULLETIN						
02-DEC-2008		MOS HRS/MSC ENC	- 				
SB 72-0630	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
07-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0631	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
13-OCT-2008		MOS HRS/MSC ENC	- 				
SB 72-0632	NO. 2 ENGINE - BOOSTER SPOOL FORWARD FLANGE INSPECTION, SERVICE BULLETIN						
22-JUN-2007		MOS HRS/MSC ENC	 15000 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0634	NO. 2 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
22-JUN-2007		MOS HRS/MSC ENC	-				
SB 72-0634 R1	NO. 2 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
30-JUL-2007		MOS HRS/MSC ENC	-				
SB 72-0634 R2	NO. 2 ENGINE - BOOSTER SPOOL LIFE LIMIT INCREASE AND REIDENTIFICATION IN FIELD, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0635	NO. 2 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE AIR COOLING TUBES, SERVICE BULLETIN						
16-FEB-2007		MOS HRS/MSC ENC	-				
SB 72-0636	NO. 2 ENGINE - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	4800 (s)				
SB 72-0636 R1	NO. 2 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA, SERVICE BULLETIN					RECOMMENDED	
09-FEB-2012		MOS HRS/MSC ENC	800 (s)				
SB 72-0636 R2	NO. 2 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA (SUPERSEDED BY 72-0636 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0636 R3	NO. 2 ENGINE - ENGINE - HP COMPRESSOR AND HP TURBINE BLADES (72-31-01 AND 72-52-01) - INSPECTION FOR ENGINE HARDWARE DISTRESS DUE TO CONTINUOUS SAND, DUST AND DIRT INGESTION IN THE MIDDLE EAST AND NORTH AFRICA, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	-				
SB 72-0637	NO. 2 ENGINE - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618959

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R1	NO. 2 ENGINE - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS					
16-AUG-2007		HRS/MSC	-				
		ENC					
SB 72-0637 R1 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 R1 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R2	NO. 2 ENGINE - STAGE 1 NOZZLES, SERVICE BULLETIN						
		MOS					
05-SEP-2007		HRS/MSC	-				
		ENC					
SB 72-0637 R2 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN HPT						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				
SB 72-0637 R2 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN LPT						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R3	NO. 2 ENGINE - STAGE 1 NOZZLES, SERVICE BULLETIN						
		MOS					
04-APR-2008		HRS/MSC	-				
		ENC					
SB 72-0637 R3 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN HPT						
		MOS					
		HRS/MSC					
		ENC	9600 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 R3 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 NOZZLES, SERVICE BULLETIN LPT						
		MOS					
		HRS/MSC					
		ENC	6400 (s)				
SB 72-0637 R5	NO. 2 ENGINE - ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R5 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN HPT					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0637 R5 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R6), SERVICE BULLETIN LPT					RECOMMENDED	
24-JUN-2011		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 72-0637 R6	NO. 2 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R6 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN HPT					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0637 R6 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY 72-0637 R7), SERVICE BULLETIN LPT					RECOMMENDED	
		MOS					
		HRS/MSC					
		ENC	800 (s)				
SB 72-0637 R7	NO. 2 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0637 R7 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R7 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R8), SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8	NO. 2 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R8 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS (SUPERSEDED BY SB 72-0637 R9), SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9	NO. 2 ENGINE - STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9 PART 1	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 HPT NOZZLES					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0637 R9 PART 2	NO. 2 ENGINE - BORESCOPE INSPECTION STAGE 1 HPT AND LPT NOZZLES (72-51-01 AND 72-53-01) - INSPECTION OF STAGE 1 HPT NOZZLES AND STAGE 1 LPT NOZZLES DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN OF THE STAGE 1 LPT NOZZLES					CATEGORY 7	
31-MAR-2014		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0638	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0639	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
09-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0640	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0640 R1	NO. 2 ENGINE - INTRODUCTION OF PRE-GROUND HPT BLADE KIT (SPD), SERVICE BULLETIN						
18-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0643	NO. 2 ENGINE - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN						
28-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0643 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-0643 R3	NO. 2 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS, SERVICE BULLETIN					RECOMMENDED	
24-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0645	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0646	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
17-APR-2007		MOS HRS/MSC ENC	- 				
SB 72-0647	NO. 2 ENGINE - COMBUSTION CHAMBER OUTER LINER REWORK, SERVICE BULLETIN						
15-JUN-2007		MOS HRS/MSC ENC	- 				
SB 72-0647 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN						
05-JUN-2009		MOS HRS/MSC ENC	- 				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0647 R2	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN						
20-NOV-2009		MOS HRS/MSC ENC	- -				
SB 72-0647 R3	NO. 2 ENGINE - COMBUSTION CHAMBER (72-42-00) - OUTER COMBUSTION CHAMBER LINER REWORK, SERVICE BULLETIN					CATEGORY 7	
30-MAY-2014		MOS HRS/MSC ENC	- -				
SB 72-0648	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
14-JUN-2007		MOS HRS/MSC ENC	- -				
SB 72-0649	NO. 2 ENGINE - INTRODUCTION OF NEW FAN BLADE SHIM ASSY, SERVICE BULLETIN						
08-FEB-2008		MOS HRS/MSC ENC	- - (s)				
SB 72-0649 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE SHIM ASSY, SERVICE BULLETIN					RECOMMENDED	
18-JAN-2011		MOS HRS/MSC ENC	- ESV				
SB 72-0650	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
25-JUN-2007		MOS HRS/MSC ENC	- -				
SB 72-0652	NO. 2 ENGINE - INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-RING MATERIAL AND REWORK OF OLD MAGNETIC SEAL AND OLD SEALOL SEAL TO THE NEW ONE, SERVICE BULLETIN						
29-JUL-2008		MOS HRS/MSC ENC	- 8000 (s)				
SB 72-0652 R2	NO. 2 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL WITH NEW O-RING MATERIAL AND REWORK OF OLD SEALOL SEAL TO THE NEW ONE, SERVICE BULLETIN						
12-JAN-2011		MOS HRS/MSC ENC	- 8000		**8000**		
SB 72-0653	NO. 2 ENGINE - ENGINE - NO.1 AND NO.2 BEARING SUPPORT ASSEMBLY (72-22-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
02-OCT-2008		MOS HRS/MSC ENC	- -				
SB 72-0655	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0656	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0657	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-SEP-2007		MOS HRS/MSC ENC	- 				
SB 72-0658	NO. 2 ENGINE - INTRODUCTION OF NEW ALTERNATE LOOP CLAMP, SERVICE BULLETIN						
24-JAN-2008		MOS HRS/MSC ENC	- 				
SB 72-0659	NO. 2 ENGINE - DELETION OF THE ALTERNATE TRIM BALANCE BOLTS IN PRODUCTION ONLY, SERVICE BULLETIN						
13-DEC-2007		MOS HRS/MSC ENC	- 				
SB 72-0661	NO. 2 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO N 4 ROLLER BEARING SUSPECTED BATCH, SERVICE BULLETIN						
23-AUG-2007		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0661 R1	NO. 2 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO NO 4 ROLLER BEARING SUSPECTED BATCH., SERVICE BULLETIN						
		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0661 R2	NO. 2 ENGINE - ONE TIME INSPECTION OF MAGNETIC DEBRIS MONITORING SYSTEM AND OIL FILTER DUE TO NO.4 ROLLER BEARING SUSPECTED BATCH, SERVICE BULLETIN						
21-JAN-2008		MOS HRS/MSC ENC	 500 (s) 				
SB 72-0662	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-78 ENGINES, SERVICE BULLETIN						
29-APR-2008		MOS HRS/MSC ENC	- 				
SB 72-0663	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
26-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0663 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
12-JAN-2009		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0665	NO. 2 ENGINE - INTRODUCTION OF NEW METALLIC-COMPOSITE VSV BUSHING, SERVICE BULLETIN						
27-SEP-2007		MOS HRS/MSC ENC	-				
SB 72-0665 R1	NO. 2 ENGINE - INTRODUCTION OF NEW METALLIC-COMPOSITE VSV BUSHING, SERVICE BULLETIN						
10-DEC-2007		MOS HRS/MSC ENC	-				
SB 72-0666	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
15-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0667	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-OCT-2007		MOS HRS/MSC ENC	-				
SB 72-0667 R1	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
11-MAY-2012		MOS HRS/MSC ENC	-				
SB 72-0668	NO. 2 ENGINE - ENGINE - GENERAL (72-00-01) - INTRODUCTION OF A NEW FLAT WASHER AT THE JUNCTION OF RADIAL DRIVE SHAFT SLEEVE AND THE FAN FRAME SHROUD, SERVICE BULLETIN						
11-JUN-2008		MOS HRS/MSC ENC	-				
SB 72-0669	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
16-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0670	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
25-JAN-2008		MOS HRS/MSC ENC	-				
SB 72-0670 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-JAN-2009		MOS HRS/MSC ENC	-				
SB 72-0671	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFMS6-7B IPC, SERVICE BULLETIN						
04-DEC-2007		MOS HRS/MSC ENC	-				
SB 72-0673	NO. 2 ENGINE - INTRODUCTION OF A NEW ANTI-ROTATION STRAIGHT HEADED PIN, SERVICE BULLETIN						
02-NOV-2007		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618966

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0673 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR (72-32-00) - NEW VSV SHROUD HEADED ANTI- ROTATION PIN - INTRODUCTION, SERVICE BULLETIN						
		MOS					
15-MAY-2009		HRS/MSC	-				
		ENC					
SB 72-0674	NO. 2 ENGINE - ELIMINATION OF HPT STATOR MIDDLE HEAT SHIELD (SUPERSEDED BY 72-0674 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0674 R1	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE SHROUD AND STAGE 1 LOW PRESSURE TURBINE NOZZLE ASSEMBLY (72-53-00) - ELIMINATION OF HPT STATOR MIDDLE HEAT SHIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0676	NO. 2 ENGINE - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
		MOS					
30-JUN-2008		HRS/MSC	-				
		ENC					
SB 72-0676 R1	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
		MOS					
17-NOV-2008		HRS/MSC	-				
		ENC					
SB 72-0676 R2	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF A NEW LOW PRESSURE TURBINE (LPT) REAR FRAME AND OF A NEW FLANGE ASSEMBLY, SERVICE BULLETIN						
		MOS					
16-JUN-2009		HRS/MSC	-				
		ENC					
SB 72-0677	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC AND CMM, SERVICE BULLETIN						
		MOS					
31-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0678	NO. 2 ENGINE - ENGINE - FAN AND B00STER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW AXIAL STOP PIN, SERVICE BULLETIN						
		MOS					
05-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0679	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY, SERVICE BULLETIN						
		MOS					
29-AUG-2008		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0680	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
29-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0680 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
09-JUL-2008		HRS/MSC	-				
		ENC					
SB 72-0681	NO. 2 ENGINE - CONVERSION OF ANY AFFECTED ENGINE MODELS TO CFM56-7B18,CFM56-7B20,CFM56-7B22,CFM56-7B24,CFM56-7B26 OR CFM56-7B27, SERVICE BULLETIN						
		MOS					
14-MAY-2008		HRS/MSC	-				
		ENC					
SB 72-0682	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
17-JAN-2008		HRS/MSC	-				
		ENC					
SB 72-0683	NO. 2 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - REWORK OF HPT NOZZLES TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION, SERVICE BULLETIN						
		MOS					
25-FEB-2008		HRS/MSC	-				
		ENC					
SB 72-0683 R1	NO. 2 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - REWORK OF HPT NOZZLES TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION (SUPERSEDED BY SB 72-0683 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0683 R2	NO. 2 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - SPLIT VANE REPAIR AND REWORK TO DOUBLE VERTICAL SEAL SLOT CONFIGURATION, SERVICE BULLETIN					CATEGORY 7	
		MOS					
21-JAN-2014		HRS/MSC	-				
		ENC					
SB 72-0684	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
19-DEC-2007		HRS/MSC	-				
		ENC					
SB 72-0685	NO. 2 ENGINE - DELETION OF SOME ALTERNATE NO.4 ROLLER BEARINGS, SERVICE BULLETIN						
		MOS					
01-APR-2008		HRS/MSC	-				
		ENC					
SB 72-0686	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
05-MAR-2008		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618968

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0687	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-FEB-2008		MOS HRS/MSC ENC	- 				
SB 72-0689	NO. 2 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
19-AUG-2008		MOS HRS/MSC ENC	- 				
SB 72-0689 R1	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
04-DEC-2009		MOS HRS/MSC ENC	- 				
SB 72-0689 R2	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - INTRODUCTION OF NEW ACCESSORY GEARBOX WITH NEW ROLLER BEARING AND REWORK OF OLD ACCESSORY GEARBOX TO THE NEW ONE, SERVICE BULLETIN						
22-DEC-2011		MOS HRS/MSC ENC	- 				
SB 72-0690	NO. 2 ENGINE - BOLTS COMMONALITY FOR AIR LPT COOLING TUBE RETAINING STRAPS, SERVICE BULLETIN						
20-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0694 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF THE INNER COMBUSTION CHAMBER LINER, SERVICE BULLETIN					RECOMMENDED	
21-OCT-2011		MOS HRS/MSC ENC	- 				
SB 72-0696	NO. 2 ENGINE - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN						
21-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0696 R1	NO. 2 ENGINE - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN						
28-MAR-2008		MOS HRS/MSC ENC	- 				
SB 72-0696 R2	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
02-SEP-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0698	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INTRODUCTION OF ALTERNATE LPT REAR FRAMES ON SAC ENGINES IN FIELD, SERVICE BULLETIN						
23-MAR-2009		MOS HRS/MSC ENC	-				
SB 72-0699	NO. 2 ENGINE - CONVERSION OF ANY AFFECTED ENGINE MODELS TO FCM56-7B/3 TI ENGINE MODEL, SERVICE BULLETIN						
14-MAY-2008		MOS HRS/MSC ENC	-				
SB 72-0699 R2	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CONVERSION OF CFM56-7B (SAC) TO CFM56-7B/3 (TI), SERVICE BULLETIN						
03-NOV-2009		MOS HRS/MSC ENC	-				
SB 72-0700	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - IMPROVEMENT OF THE FUEL SUPPLY TUBE WITH NEW INSERTS, SERVICE BULLETIN						
24-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0701	NO. 2 ENGINE - NEW SPARE PARTS THAT ARE INTERCHANGABLE WITH THE OLD PARTS THEY REPLACE, SERVICE BULLETIN						
13-MAY-2008		MOS HRS/MSC ENC	-				
SB 72-0702	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-JUN-2008		MOS HRS/MSC ENC	-				
SB 72-0704	NO. 2 ENGINE - INSPECTION OF OIL SCAVENGE FILTER TO DETECT NO. 3 BEARING DETERIORATION, SERVICE BULLETIN					RECOMMENDED	
23-JUN-2008		MOS HRS/MSC ENC	1000 (s)				
SB 72-0704 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) INSPECTION OF OIL SCAVENGE FILTER TO DETECT NO. 3 BEARING DETERIORATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	500 (s)				
SB 72-0706	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/B2, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0707	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- - -				
SB 72-0707 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2011		MOS HRS/MSC ENC	- - -				
SB 72-0708	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2F, SERVICE BULLETIN						
11-JUN-2009		MOS HRS/MSC ENC	- - -				
SB 72-0708 R1	NO. 2 ENGINE - CFM56-7B ENGINE CONVERSION TO CFM56-7B26/3B2F, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2011		MOS HRS/MSC ENC	- - -				
SB 72-0709 R1	NO. 2 ENGINE - INTRODUCTION OF NEW BOLT FOR HPTACC MANIFOLD ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
29-OCT-2008		MOS HRS/MSC ENC	- - (s) -	28-SEP-2009 3378:04 776			
SB 72-0711	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
16-OCT-2008		MOS HRS/MSC ENC	- - -				
SB 72-0712	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
06-NOV-2008		MOS HRS/MSC ENC	- - -				
SB 72-0713 R1	NO. 2 ENGINE - FUEL NOZZLE COUPLING NUT INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
25-JUL-2008		MOS HRS/MSC ENC	- - -	28-SEP-2009 3378:04 776			
SB 72-0716	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-OCT-2008		MOS HRS/MSC ENC	- - -				
SB 72-0718 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - REWORK OF THE LPT CASE RAIL "0" SUPPORT RING AND REIDENTIFICATION OF THE LPT CASE, SERVICE BULLETIN						
04-JUN-2013		MOS HRS/MSC ENC	- - -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0720	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE SPACER, SERVICE BULLETIN						
28-APR-2009		MOS HRS/MSC ENC	-				
SB 72-0720 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE SPACER, SERVICE BULLETIN						
11-JAN-2010		MOS HRS/MSC ENC	-				
SB 72-0722	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-78 IPC, SERVICE BULLETIN						
10-DEC-2008		MOS HRS/MSC ENC	-				
SB 72-0724	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
10-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0725	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF TWO NEW BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
29-JAN-2009		MOS HRS/MSC ENC	-				
SB 72-0726	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF TWO BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
26-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0727	NO. 2 ENGINE - ENGINE - GENERAL (72-00-03) - INTRODUCTION OF A NEW SILVER PLATED NUT FOR THE LPT ROTOR SUPPORT / LPT SHAFT ATTACHMENT FLANGE JUNCTION, SERVICE BULLETIN						
28-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0728	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
06-MAR-2009		MOS HRS/MSC ENC	12 (s)				
SB 72-0728 R1	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	12 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0728 R2	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
09-FEB-2010		MOS HRS/MSC ENC	12 (s)				
SB 72-0730	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - REIDENTIFICATION OF THE CONTAINMENT CASE 340-059-813-0 AND 340-059-814-0, SERVICE BULLETIN						
13-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0731	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - REPLACEMENT OF BALL BEARING 301-480-320-0 IN A SUSPECT LOT, SERVICE BULLETIN						
26-FEB-2009		MOS HRS/MSC ENC	-				
SB 72-0732	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN						
02-JUN-2009		MOS HRS/MSC ENC	19000 (s)				
SB 72-0732 R1	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	19000 (s)				
SB 72-0733	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
14-APR-2009		MOS HRS/MSC ENC	-				
SB 72-0734	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF NEW LPT STAGE 1 NOZZLE SEGMENTS, SERVICE BULLETIN						
13-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0734 R1	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF NEW LPT STAGE 1 NOZZLE SEGMENTS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0735	NO. 2 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY - (72-53-00) - MODIFICATION OF HPT STATOR SHROUD- ENHANCED DURABILITY PUCK REPAIR, SERVICE BULLETIN						
26-JUN-2009		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618973

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0735 R1	NO. 2 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY - (72-53-00) - MODIFICATION OF HPT STATOR SHROUD - ENHANCED DURABILITY PUCK REPAIR, SERVICE BULLETIN						
04-DEC-2009		MOS HRS/MSC ENC	- -				
SB 72-0737	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - INTRODUCTION OF IMPROVED HPC AND HPT ROTATING PARTS TO CFM56-7B27A ENGINES, SERVICE BULLETIN						
15-MAY-2009		MOS HRS/MSC ENC	- -				
SB 72-0738	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
28-JAN-2009		MOS HRS/MSC ENC	- -				
SB 72-0738 R1	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
30-JUN-2011		MOS HRS/MSC ENC	- -				
SB 72-0739	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - PRECAUTIONS TO BE FOLLOWED CONCERNING INSULATION BLANKETS CONTAINING RCF, SERVICE BULLETIN						
08-FEB-2013		MOS HRS/MSC ENC	- -				
SB 72-0740	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN					INFORMATIONAL	
17-FEB-2009		MOS HRS/MSC ENC	- -				
SB 72-0742	NO. 2 ENGINE - ENGINE - CORE ENGINE MAJOR MODULE ASSEMBLY (72-00-02) - HPC FRONT CASE BLEED PORT REMOVAL AND SIMPLIFICATION, SERVICE BULLETIN						
30-JUN-2009		MOS HRS/MSC ENC	- -				
SB 72-0743	NO. 2 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF SUSPECT STAGE 3 LPT DISK 336-002-006-0, SERVICE BULLETIN						
26-OCT-2009		MOS HRS/MSC ENC	 9500 (s)				
SB 72-0743 R1	NO. 2 ENGINE - ENGINE - LPT ROTOR / STATOR ASSEMBLY (72-54-00) - REPLACEMENT OF SUSPECT STAGE 3 LPT DISK 336-002-006-0, SERVICE BULLETIN					RECOMMENDED	
09-NOV-2010		MOS HRS/MSC ENC	 9500 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0744	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF THREE BRACKETS ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
12-MAY-2009		MOS HRS/MSC ENC	-				
SB 72-0745	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF AN ALTERNATE PROVISIONING SOURCE FOR THE NO. 1, 2 AND 5 BEARINGS, SERVICE BULLETIN						
26-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0747	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE SERIALIZATION-MANUFACTURING SEQUENCE, SERVICE BULLETIN						
04-JUN-2009		MOS HRS/MSC ENC	-				
SB 72-0747 R1	NO. 2 ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE SERIALIZATION-MANUFACTURING SEQUENCE, SERVICE BULLETIN					CATEGORY 9	
03-MAR-2014		MOS HRS/MSC ENC	-				
SB 72-0748	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
30-JUN-2009		MOS HRS/MSC ENC	-				
SB 72-0749	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW RETAINING PLATE, SERVICE BULLETIN						
01-FEB-2011		MOS HRS/MSC ENC	-				
SB 72-0750	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
08-OCT-2009		MOS HRS/MSC ENC	-				
SB 72-0751	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
08-OCT-2009		MOS HRS/MSC ENC	-				
SB 72-0752	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
02-JUL-2009		MOS HRS/MSC ENC	-				
SB 72-0753	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK IN FIELD OF THE FAN BLADE REAR SHANK FOR WEAR, SERVICE BULLETIN						
14-OCT-2009		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618975

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0753 R1	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK IN FIELD OF THE FAN BLADE REAR SHANK FOR WEAR, SERVICE BULLETIN						
03-DEC-2012		MOS HRS/MSC ENC	-				
SB 72-0754	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF ONE BRACKET ON THE FLANGE A1 AND THREE BRACKETS ASSY ON THE FLANGE B6 WITH A NEW DESIGN, SERVICE BULLETIN					RECOMMENDED	
10-NOV-2010		MOS HRS/MSC ENC	-				
SB 72-0756	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY WITH A NEW DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0757	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
28-AUG-2009		MOS HRS/MSC ENC	-				
SB 72-0758	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR BLADES, SERVICE BULLETIN						
22-SEP-2009		MOS HRS/MSC ENC	-				
SB 72-0759	NO. 2 ENGINE - ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES, SERVICE BULLETIN					OPTIONAL	
27-OCT-2010		MOS HRS/MSC ENC	-				
SB 72-0759 R1	NO. 2 ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES (SUPERSEDED BY SB 72-0759 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0759 R2	NO. 2 ENGINE - FIRE DETECTION (26-11-02) - INTRODUCTION OF NEW SEMI-RIGID FIRE DETECTION HARNESSES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
22-OCT-2013		MOS HRS/MSC ENC	-				
SB 72-0760	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
03-SEP-2009		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0761	NO. 2 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - INTRODUCTION OF NEW COMBUSTION CASE, SERVICE BULLETIN						
		MOS					
08-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0762	NO. 2 ENGINE - ENGINE - TRANSFER GEARBOX ASSEMBLY (72-62-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
29-SEP-2009		HRS/MSC	-				
		ENC					
SB 72-0763	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0764 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF PREFORMED PACKING O-RINGS IN THE LPT ROTOR / STATOR ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0764 R2	NO. 2 ENGINE - GENERAL (72-00-00) - REPLACEMENT OF PREFORMED PACKING O-RINGS IN THE LPT ROTOR / STATOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	
		MOS					
25-JUL-2012		HRS/MSC	-				
		ENC					
SB 72-0767	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
28-OCT-2009		HRS/MSC	-				
		ENC					
SB 72-0768	NO. 2 ENGINE - NOT ISSUED, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0769	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF INNER AND OUTER SEGMENT LINER SPARE PARTS, SERVICE BULLETIN						
		MOS					
06-FEB-2010		HRS/MSC	-				
		ENC					
SB 72-0772	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
04-DEC-2009		HRS/MSC	-				
		ENC					
SB 72-0773	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
25-NOV-2009		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618977

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0774	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
20-JAN-2010		HRS/MSC	-				
		ENC					
SB 72-0775	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0776	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0777	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN DISK MIDDLE LUG REWORK IN FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0778	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0779	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW MW0311 ELECTRICAL HARNESS AND IN FIELD REWORK OF THE OLD MW0311 ELECTRICAL HARNESS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0780	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-23-00) - REWORK IN FIELD OF FAN CONTAINMENT CASE B1 FLANGE AT HOLES NO. 84 AND 85, SERVICE BULLETIN						
		MOS					
18-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0780 R1	NO. 2 ENGINE - FAN AND BOOSTER ASSEMBLY (72-23-00) - REWORK IN FIELD OF FAN CONTAINMENT CASE B1 FLANGE AT HOLES NO. 84 AND 85, SERVICE BULLETIN						
		MOS					
11-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0781	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW LPT COOLING MANIFOLDS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
26-JUN-2013		HRS/MSC	-				
		ENC					
SB 72-0783	NO. 2 ENGINE - ENGINE - HPT ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618978

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	72-0784	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PART RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0785	NO. 2 ENGINE - ENGINE - ENGINE (72-00-00) - DAC FUEL NOZZLE INDUCED STAGES 1, 2, AND 3 LPT NOZZLE DISTRESS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0786	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW OUTER LINER FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0787	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0789	NO. 2 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - ENGINE OPERATION IN THE ENHANCED PROCEDURES ZONE FROM VOLCANO EYJAFJALLAJOKULL, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0789 R1	NO. 2 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - ENGINE OPERATION IN THE ENHANCED PROCEDURES ZONE FROM VOLCANO EYJAFJALLAJOKULL, SERVICE BULLETIN					RECOMMENDED	
	21-JUL-2011		MOS HRS/MSC ENC	- 				
SB	72-0789 R2	NO. 2 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - INTRODUCTION OF A LEADING INDICATOR PROGRAM FOR ENGINE OPERATION IN LOW CONCENTRATIONS OF VOLCANIC ASH, SERVICE BULLETIN					RECOMMENDED	
	14-DEC-2011		MOS HRS/MSC ENC	- 				
SB	72-0790	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0791	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	72-0792	NO. 2 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING , SERVICE BULLETIN					OPTIONAL	
	30-JUL-2010		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0794	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
15-OCT-2010		HRS/MSC	-				
		ENC					
SB 72-0795	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS , SERVICE BULLETIN					OPTIONAL	
		MOS					
03-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0795 R2	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-APR-2012		HRS/MSC	-				
		ENC					
SB 72-0795 R3	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMENT OPERATORS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-JUN-2012		HRS/MSC	-				
		ENC					
SB 72-0796	NO. 2 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE INTERCHANGEABILITY LIMITATIONS (SUPERSEDED BY SB 72-0796 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0796 R1	NO. 2 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE INTERCHANGEABILITY LIMITATIONS, SERVICE BULLETIN					CATEGORY 4	
		MOS					
18-FEB-2013		HRS/MSC	-				
		ENC					
SB 72-0797	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - FAN BLADE MOMENT-WEIGHT MISMARKING, SERVICE BULLETIN						
		MOS					
27-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0798	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - REWORK OF HPC STAGE 1 THROUGH STAGE 9 BLADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-JAN-2011		HRS/MSC	-				
		ENC					
SB 72-0799	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - REWORK OF HPC TECH INSERTION HPC BLADES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
20-JAN-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0801	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INTRODUCTION OF A NEW FRONT FLANGE WITH 6 VENTILATION HOLES AND REWORK OF THE OLD PART, SERVICE BULLETIN						
		MOS					
30-JUN-2011		HRS/MSC	-				
		ENC					
SB 72-0802	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0803	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-OCT-2010		HRS/MSC	-				
		ENC					
SB 72-0804	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0804 R1	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
24-MAR-2011		HRS/MSC	-				
		ENC					
SB 72-0805	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
02-NOV-2010		HRS/MSC	-				
		ENC					
SB 72-0806	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF NEW SUPPORT WITH CAPTIVE NUT, SERVICE BULLETIN						
		MOS					
18-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0807	NO. 2 ENGINE - ENGINE - LPT FRAME ASSEMBLY (72-56-00) - INSPECTION OF TURBINE REAR FRAME ON CFM56-7B27A ENGINES, SERVICE BULLETIN					OPTIONAL	
		MOS					
19-JAN-2012		HRS/MSC					
		ENC	11200 (s)				
SB 72-0808	NO. 2 ENGINE - ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - INSPECTION OF STAGE 1 LPT NOZZLES DUE TO INDIA ENVIRONMENTAL DISTRESS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
27-SEP-2013		HRS/MSC	-				
		ENC					
SB 72-0809	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF CFM56-7BE LPT HARDWARE ON CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0810	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
09-JUN-2011		MOS HRS/MSC ENC	- 				
SB 72-0811	NO. 2 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLY DURABILITY IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
20-JAN-2011		MOS HRS/MSC ENC	- 				
SB 72-0811 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLY DURABILITY IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
29-NOV-2011		MOS HRS/MSC ENC	- 				
SB 72-0812	NO. 2 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING, SERVICE BULLETIN					RECOMMENDED	
26-SEP-2011		MOS HRS/MSC ENC	- 				
SB 72-0812 R1	NO. 2 ENGINE - ENGINE - INLET NO. 3 BEARING ASSEMBLY GEARBOX (72-61-00) - NEW BALL THRUST NO. 3 BEARING WITH NITRIDE HARDENING, SERVICE BULLETIN					RECOMMENDED	
06-FEB-2012		MOS HRS/MSC ENC	- 				
SB 72-0813	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - INTRODUCTION OF HPT BLADE P/N 2403M91P02, SERVICE BULLETIN					INFORMATIONAL	
30-JAN-2012		MOS HRS/MSC ENC	- 				
SB 72-0814	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
11-APR-2011		MOS HRS/MSC ENC	- 				
SB 72-0815	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
20-DEC-2011		MOS HRS/MSC ENC	- 				
SB 72-0816	NO. 2 ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - NEW SHROUD HPT STATOR HANGER WITH MODIFIED AIR FILTER, SERVICE BULLETIN					RECOMMENDED	
19-JAN-2011		MOS HRS/MSC ENC	- 				
SB 72-0817	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
03-OCT-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0817 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0818 R1	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF NEW HPT ROTOR, SERVICE BULLETIN					RECOMMENDED	
24-MAR-2011		MOS HRS/MSC ENC	-				
SB 72-0819	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
03-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0820	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - REPLACEMENT OF NO. 4 FAIRING STEEL VERSION, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
31-JUL-2012		MOS HRS/MSC ENC	-				
SB 72-0821	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
04-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0821 R1	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					RECOMMENDED	
26-MAR-2013		MOS HRS/MSC ENC	-				
SB 72-0822	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BOLT TO ATTACH THE MW0325 HARNESS, SERVICE BULLETIN						
18-AUG-2011		MOS HRS/MSC ENC	-				
SB 72-0822 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BOLTS TO ATTACH THE MW0325 HARNESS, SERVICE BULLETIN						
26-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0823	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05 (SUPERSEDED BY 72-0823 R1), SERVICE BULLETIN					SUPERSEDED	
11-APR-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0823 R1	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05, SERVICE BULLETIN					INFORMATIONAL	
11-MAY-2011		MOS HRS/MSC ENC	- -				
SB 72-0823 R2	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT STATOR NOZZLE P/N 2080M35G05, SERVICE BULLETIN					INFORMATIONAL	
23-JUN-2011		MOS HRS/MSC ENC	- -				
SB 72-0824	NO. 2 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - MANIFOLD HPT CLEARANCE CONTROL BRACKET CHANGE, SERVICE BULLETIN					OPTIONAL	
21-NOV-2011		MOS HRS/MSC ENC	- -				
SB 72-0825	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
		MOS HRS/MSC ENC	 25000 (s)				
SB 72-0825 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	
29-NOV-2011		MOS HRS/MSC ENC	 15000 (s)				
SB 72-0825 R2	NO. 2 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES (SUPERSEDED BY SB 72-0825 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	 - (s) 				
SB 72-0825 R3	NO. 2 ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON WING INSPECTION OF PRE-CFM56-7B S/B 72-0811 ACTUATION COMPRESSOR STATOR INLET GUIDE VANE RING ASSEMBLIES, SERVICE BULLETIN					CATEGORY 2	
30-APR-2014		MOS HRS/MSC ENC	- -				
SB 72-0826	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- -				
SB 72-0827	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REWORK OF THE BOOSTER SPOOL, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
27-MAY-2013		MOS HRS/MSC ENC	- -				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0829	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - RELEASE OF CFM56-7BE HPT ROTOR HARDWARE TO EARLIER CFM56-7B ENGINE MODELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-JAN-2012		HRS/MSC	-				
		ENC					
SB 72-0830	NO. 2 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - RELEASE OF CFM56-7BE COMBUSTION CASE TO EARLIER CFM56-7B ENGINE MODELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-JAN-2012		HRS/MSC	-				
		ENC					
SB 72-0831	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
02-DEC-2011		HRS/MSC	-				
		ENC					
SB 72-0832	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
05-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0833	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B TURBOFAN ENGINES, SERVICE BULLETIN						
		MOS					
31-AUG-2011		HRS/MSC	-				
		ENC					
SB 72-0833 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B TURBOFAN ENGINES, SERVICE BULLETIN						
		MOS					
28-NOV-2011		HRS/MSC	-				
		ENC					
SB 72-0834	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE PART NUMBERS AND REIDENTIFICATION OF OLD FAN BLADES IN FIELD, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
08-JUN-2011		HRS/MSC	-				
		ENC					
SB 72-0834 R1	NO. 2 ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF NEW FAN BLADE PART NUMBERS AND REIDENTIFICATION OF OLD FAN BLADES IN FIELD, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
20-JUL-2012		HRS/MSC	-				
		ENC					
SB 72-0835	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION COMBUSTION CHAMBER INNER LINER WITH THIN TBC, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-DEC-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0836	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF COMBUSTION CHAMBER INNER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
23-SEP-2011		MOS HRS/MSC ENC	-				
SB 72-0837	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B20E, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0838	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B22E, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0839	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B22E/B1, SERVICE BULLETIN					OPTIONAL	
16-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0840	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B24E, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0841	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B24E/B1, SERVICE BULLETIN					OPTIONAL	
15-JUN-2011		MOS HRS/MSC ENC	-				
SB 72-0842 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0843 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B1, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0844 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B2, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				
SB 72-0845 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/F, SERVICE BULLETIN					RECOMMENDED	
25-JUL-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0846 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B26E/B2F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0848 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B27E/B1, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0850 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7B ENGINE CONVERSION TO CFM56-7B27E/F, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2011		HRS/MSC	-				
		ENC					
SB 72-0852	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF A NEW LPT ROTOR SUPPORT, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
16-OCT-2012		HRS/MSC	-				
		ENC					
SB 72-0853	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE MATE FACE SURFACE INSPECTION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-SEP-2011		HRS/MSC	-				
		ENC					
SB 72-0854	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY ON THE FILTER SUPPORT, SERVICE BULLETIN						
		MOS					
15-NOV-2011		HRS/MSC	-				
		ENC					
SB 72-0856	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW BRACKET ASSY, SERVICE BULLETIN						
		MOS					
28-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0857	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS					
21-DEC-2011		HRS/MSC	-				
		ENC					
SB 72-0858	NO. 2 ENGINE - ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INSPECTION OF SUSPECT FAN CONTAINMENT CASE FOR MISSING OR MISLOCATED ANODIZATION, SERVICE BULLETIN						
		MOS					
12-SEP-2011		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0859	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTION CHAMBER DOME WITH RETAINERLESS SWIRL NOZZLES, SERVICE BULLETIN					RECOMMENDED	
21-SEP-2011		MOS HRS/MSC ENC	- 				
SB 72-0859 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTION CHAMBER DOME WITH RETAINERLESS SWIRL NOZZLES, SERVICE BULLETIN					RECOMMENDED	
28-JAN-2013		MOS HRS/MSC ENC	- 				
SB 72-0861	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITH MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
09-JAN-2012		MOS HRS/MSC ENC	- 				
SB 72-0862	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF PRE-TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITHOUT MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
12-JAN-2012		MOS HRS/MSC ENC	- 				
SB 72-0863	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING (SUPERSEDED BY 72-0863 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0863 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING (SUPERSEDED BY 72-0863 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 72-0863 R2	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF HPC TI KITS WITH PVD EROSION COATING, SERVICE BULLETIN					RECOMMENDED	
22-MAY-2012		MOS HRS/MSC ENC	- 				
SB 72-0864	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 2 AND STAGE 3 SHROUDS AND STAGE 4 THROUGH 8 VANE ASSEMBLIES AND SECTORS, SERVICE BULLETIN					RECOMMENDED	
25-AUG-2011		MOS HRS/MSC ENC	- 				
SB 72-0865	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMLY (72-54-00) - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
08-DEC-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0866	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW BRACKET ASSY FOR ATTACHMENT OF J5 HARNESS, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
14-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0867	NO. 2 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - RELEASE OF NEW HPT STATOR SHROUD, SERVICE BULLETIN					RECOMMENDED	
20-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0868	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF TECH INSERTION OUTER COMBUSTION CHAMBER LINER WITHOUT MULTI-HOLE COOLING PATCH, SERVICE BULLETIN					RECOMMENDED	
07-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0869	NO. 2 ENGINE - ENGINE - ENGINE ASSEMBLY (72-00-00) - RELEASE OF SPD AIR DUCT SLEEVE P/N 1812M68G02, SERVICE BULLETIN						
02-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0871	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - HPC STAGE 4 THROUGH STAGE 9 BLADE LOCK ON-WING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
19-OCT-2011		MOS HRS/MSC ENC	6 (s)				
SB 72-0871 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - HPC STAGE 4 THROUGH STAGE 9 BLADE LOCK ON-WING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
11-APR-2012		MOS HRS/MSC ENC	DUE (s)				
SB 72-0872	NO. 2 ENGINE - ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 3 BLADES, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
12-DEC-2012		MOS HRS/MSC ENC	-				
SB 72-0873	NO. 2 ENGINE - LPT SHAFT ASSEMBLY (72-55-00) - INTRODUCTION OF A NEW SEAL ON THE CENTER VENT TUBE, SERVICE BULLETIN						
27-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0874	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS, SERVICE BULLETIN					RECOMMENDED	
20-OCT-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0874 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS (SUPERSEDED BY SB 72-0874 R2), SERVICE BULLETIN					RECOMMENDED	
08-FEB-2012		MOS HRS/MSC ENC	-				
SB 72-0874 R2	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - SUSPECT HPC STAGE 8 AND 9 BLADE LOCKS, SERVICE BULLETIN					CATEGORY 4	
14-JUL-2014		MOS HRS/MSC ENC	-				
SB 72-0875	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
23-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0876	NO. 2 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-00-02) - INSPECTION OF FUEL NOZZLE SUPPLY TUBE NO. 7 FOR WEAR OR CLOSE CLEARANCE, SERVICE BULLETIN					RECOMMENDED	
27-DEC-2011		MOS HRS/MSC ENC	12 (s)				
SB 72-0877	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
18-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0878	NO. 2 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - FUEL MANIFOLD SUPPORT BRACKETS AND IGNITER CABLE BRACKET ASSEMBLY REDESIGN, SERVICE BULLETIN					OPTIONAL	
21-NOV-2011		MOS HRS/MSC ENC	-				
SB 72-0879 R1	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSEMBLY AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN						
12-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0879 R3	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW ACCESSORY GEARBOX ASSEMBLY (AGB) WITH NEW HOUSING ASSEMBLY AND NEW STARTER DRIVE PAD ASSEMBLY AND REWORK OF THE OLD AGB TO THE NEW ONE, SERVICE BULLETIN					CATEGORY 6	
15-JAN-2014		MOS HRS/MSC ENC	-				
SB 72-0880	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - REWORK OF TECH INSERTION INNER COMBUSTION CHAMBER LINER INTO MULTI-HOLE COOLING PATCH WITH THIN TBC CONFIGURATION, SERVICE BULLETIN					RECOMMENDED	
22-FEB-2012		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0881	NO. 2 ENGINE - ENGINE - CORE ASSEMBLY (72-00-02) - HPT STATOR AIR IMPINGEMENT MANIFOLD REWORK, SERVICE BULLETIN					RECOMMENDED	
		MOS					
11-APR-2012		HRS/MSC	-				
		ENC					
SB 72-0882	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
26-SEP-2012		HRS/MSC	-				
		ENC					
SB 72-0884	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - REPETITIVE ON-WING INSPECTION OF THE FAN BLADE PLATFORMS, SERVICE BULLETIN					RECOMMENDED	
		MOS	12 (s)				
24-JAN-2012		HRS/MSC					
		ENC					
SB 72-0885	NO. 2 ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 2 BLADES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0886	NO. 2 ENGINE - ENGINE - HPT BLADES (72-52-01) - INSPECTION OF HPT BLADES - INDIA REGION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
27-FEB-2012		HRS/MSC					
		ENC	400 (s)				
SB 72-0886 R1	NO. 2 ENGINE - ENGINE - HPT BLADES (72-52-01) - INSPECTION OF HPT BLADES - INDIA REGION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0888	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THICK TBC, SERVICE BULLETIN					RECOMMENDED	
		MOS					
30-AUG-2012		HRS/MSC	-				
		ENC					
SB 72-0888 R1	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF NEW OUTER LINERS WITH A MORE DURABLE AFT OUTER SUPPORT AND THICK TBC, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
03-JAN-2013		HRS/MSC	-				
		ENC					
SB 72-0889	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THIN TBC, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-AUG-2012		HRS/MSC	-				
		ENC					
SB 72-0889 R1	NO. 2 ENGINE - ENGINE - COMBUSTION CHAMBER ASSEMBLY (72-42-00) - INTRODUCTION OF A NEW OUTER LINER WITH A MORE DURABLE AFT OUTER SUPPORT AND THIN TBC, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
17-OCT-2012		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00618991

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0890	NO. 2 ENGINE - COMBUSTION ASSEMBLY (72-41-00) - INTRODUCTION OF A NEW COMBUSTION CHAMBER ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-AUG-2012		HRS/MSC	-				
		ENC					
SB 72-0892	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
13-FEB-2012		HRS/MSC	-				
		ENC					
SB 72-0893	NO. 2 ENGINE - INTRODUCTION OF A NEW BOLT-WASHER ASSEMBLY TO IMPROVE THE FLANGE ASSEMBLY ATTACHMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0894	NO. 2 ENGINE - ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF A NEW COMPRESSOR ROTOR STAGES 4 THROUGH 9 SPOOL ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-MAR-2012		HRS/MSC	-				
		ENC					
SB 72-0894 R1	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF A NEW COMPRESSOR ROTOR STAGES 4 THROUGH 9 SPOOL ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0895	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF 76 BLADE HPT ROTOR KIT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
10-MAY-2012		HRS/MSC	-				
		ENC					
SB 72-0895 R1	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - RELEASE OF 76 BLADE HPT ROTOR KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0897	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT ASSEMBLY (72-55-00) - REPETITIVE REPAIR OF THE AIR/OIL SEPARATOR IN SHOP, SERVICE BULLETIN						
		MOS					
20-MAR-2012		HRS/MSC	-				
		ENC					
SB 72-0897 R1	NO. 2 ENGINE - ENGINE - LOW PRESSURE TURBINE SHAFT ASSEMBLY (72-55-00) - REPETITIVE REPAIR OF THE AIR/OIL SEPARATOR IN SHOP, SERVICE BULLETIN						
		MOS					
28-MAR-2013		HRS/MSC	-				
		ENC					
SB 72-0898	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-MAR-2012		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0899	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE SPLIT VANE REPAIR, SERVICE BULLETIN					RECOMMENDED	
17-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0900	NO. 2 ENGINE - LPT ROTOR/STATOR ASSEMBLY (72-54-00) - INTRODUCTION OF NEW LPT STAGE 1 BLADES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 72-0902	NO. 2 ENGINE - ENGINE - COMBUSTION ASSEMBLY (72-41-00) - DELETION OF ALTERNATE COMBUSTION CHAMBER ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
20-APR-2012		MOS HRS/MSC ENC	-				
SB 72-0903	NO. 2 ENGINE - ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - REWORK OF N500 MATERIAL HPT STATOR SHROUDS, SERVICE BULLETIN					RECOMMENDED	
12-APR-2013		MOS HRS/MSC ENC	-				
SB 72-0904 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW AIR/OIL SEPARATOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
17-OCT-2012		MOS HRS/MSC ENC	-				
SB 72-0907	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - CFM56-7BE BASELINE CONFIGURATION HARDWARE RELEASED TO EARLIER CFM56-7B SAC ENGINE MODELS, SERVICE BULLETIN					INFORMATIONAL	
04-JUN-2013		MOS HRS/MSC ENC	-				
SB 72-0909	NO. 2 ENGINE - ENGINE - FAN AND BOOSTER ASSEMBLY (72-21-00) - INTRODUCTION OF A NEW FAN BLADE PLATFORM, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
20-NOV-2012		MOS HRS/MSC ENC	-				
SB 72-0911	NO. 2 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
17-JUL-2012		MOS HRS/MSC ENC	-				
SB 72-0912	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
27-SEP-2012		MOS HRS/MSC ENC	-				
SB 72-0913	NO. 2 ENGINE - ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - RELEASE OF NEW HPT STATOR NOZZLE, SERVICE BULLETIN					RECOMMENDED	
05-NOV-2012		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00618993

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0914	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
25-MAR-2013		MOS HRS/MSC ENC	- - -				
SB 72-0914 R1	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
12-APR-2013		MOS HRS/MSC ENC	- - -				
SB 72-0915	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
30-NOV-2012		MOS HRS/MSC ENC	- - -				
SB 72-0916	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - HPT STATOR NOZZLE SPLIT VANE REPAIR, SERVICE BULLETIN						
15-JAN-2013		MOS HRS/MSC ENC	- - -				
SB 72-0917	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW OIL SCAVENGE TUBE CLAMP, SERVICE BULLETIN					RECOMMENDED	
16-OCT-2012		MOS HRS/MSC ENC	- - -				
SB 72-0918	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT (SUPERSEDED BY SB 72-0918 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- - -				
SB 72-0918 R1	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR BLADE MANAGEMENT, SERVICE BULLETIN					CATEGORY 4	
11-JUN-2014		MOS HRS/MSC ENC	- - -				
SB 72-0920	NO. 2 ENGINE - HIGH PRESSURE TURBINE NOZZLE ASSEMBLY (72-51-00) - RELEASE OF HPT NOZZLE KIT, SERVICE BULLETIN					LIMITED DISTRIBUTION	
15-NOV-2013		MOS HRS/MSC ENC	- - -				
SB 72-0921	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE (SUPERSEDED BY 72-0921 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- - -				
SB 72-0921 R1	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE (SUPERSEDED BY SB 72-0921 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- - -				

© Camp Systems

EFTA00618994

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0921 R2	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF A NEW CENTER VENT TUBE, SERVICE BULLETIN					CATEGORY 5	
		MOS					
09-DEC-2013		HRS/MSC	-				
		ENC					
SB 72-0922	NO. 2 ENGINE - ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
25-FEB-2013		HRS/MSC	-				
		ENC					
SB 72-0924	NO. 2 ENGINE - GENERAL (72-00-00) - INTRODUCTION OF NEW BRACKET ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	
		MOS					
23-JUL-2014		HRS/MSC	-				
		ENC					
SB 72-0926	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON-WING INSPECTION OF VSV STAGE 3 OUTER BUSHINGS (SUPERSEDED BY SB 72-0926 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0926 R1	NO. 2 ENGINE - ENGINE - COMPRESSOR FRONT STATOR ASSEMBLY (72-32-00) - ON-WING INSPECTION OF VSV STAGE 3 OUTER BUSHINGS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 72-0927	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - DELETION OF BALL BEARING 335-304-401-0 ALTERNATIVE FOR THE HANDCRANKING LINE (SUPERSEDED BY SB 72-0927 R1), SERVICE BULLETIN						
		MOS					
03-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0927 R1	NO. 2 ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-63-00) - DELETION OF BALL BEARING 335-304-401-0 ALTERNATIVE FOR THE HANDCRANKING LINE, SERVICE BULLETIN					CATEGORY 3	
		MOS					
14-APR-2014		HRS/MSC	ESV				
		ENC					
SB 72-0928	NO. 2 ENGINE - HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (72-53-00) - REPLACEMENT OF LPT STAGE 1 NOZZLE SEGMENTS DUE TO ENVIRONMENTAL DISTRESS, SERVICE BULLETIN						
		MOS					
22-JUL-2013		HRS/MSC	-				
		ENC					
SB 72-0929	NO. 2 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - HPT ROTOR DISK AIR SLOT REDESIGN, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
06-AUG-2013		HRS/MSC	-				
		ENC					
SB 72-0930	NO. 2 ENGINE - ENGINE - HPT/LPT SHROUD NOZZLE ASSEMBLY (72-53-00) - FORWARD FLANGE WEAR GROOVE HPT/LPT SHROUD NOZZLE SUPPORT REWORK, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
02-OCT-2013		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0931	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW THICKER FAN CONTAINMENT CASE (SUPERSEDED BY SB 72-0931 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0931 R1	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW THICKER FAN CONTAINMENT CASE, SERVICE BULLETIN					CATEGORY 7	
10-JAN-2014		MOS HRS/MSC ENC	-				
SB 72-0933	NO. 2 ENGINE - FAN FRAME ASSEMBLY (72-23-00) - INTRODUCTION OF A NEW CUP TO ATTACH THE OUTER PLATFORM OF THE OGV TO THE CONTAINMENT CASE, SERVICE BULLETIN					CATEGORY 7	
20-FEB-2014		MOS HRS/MSC ENC	-				
SB 72-0934	NO. 2 ENGINE - COMBUSTION ASSEMBLY (72-41-00) - REWORK OF THE COMBUSTION CASE P/N 2002M81G09, SERVICE BULLETIN					CATEGORY 7	
14-FEB-2014		MOS HRS/MSC ENC	-				
SB 72-0935	NO. 2 ENGINE - HPT ROTOR ASSEMBLY (72-52-00) - INTRODUCTION OF HPT ROTOR BLADE P/N 2403M91P03 AND 76-BLADE HPT ROTOR KIT, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
03-SEP-2013		MOS HRS/MSC ENC	-				
SB 72-0938	NO. 2 ENGINE - CORE ENGINE MAJOR MODULE (72-00-02) - INTRODUCTION OF A NEW METALLIC C-SEAL TO THE SPARE PARTS LIST, SERVICE BULLETIN					RECOMMENDED	
04-SEP-2013		MOS HRS/MSC ENC	-				
SB 72-0939	NO. 2 ENGINE - HPT/LPT NOZZLE SHROUD ASSEMBLY (72-53-00) - INTRODUCTION OF HPT STATOR SHROUD P/N 2080M28P06, SERVICE BULLETIN					CATEGORY 7	
21-NOV-2013		MOS HRS/MSC ENC	-				
SB 72-0940	NO. 2 ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - FORWARD INNER NOZZLE SUPPORT REWORK BY FORWARD FLANGE REPLACEMENT AND APPLICATION OF EROSION COATING (SUPERSEDED BY SB 72-0940 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 72-0940 R1	NO. 2 ENGINE - HPT NOZZLE ASSEMBLY (72-51-00) - FORWARD INNER NOZZLE SUPPORT REWORK BY FORWARD FLANGE REPLACEMENT AND APPLICATION OF EROSION COATING, SERVICE BULLETIN					CATEGORY 7	
04-FEB-2014		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-0946	NO. 2 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - REPLACEMENT OF FORWARD DAMPER SLEEVE FOR THE HPT ROTOR FRONT SHAFTS P/N 2048M21P01 AND P/N 2048M21P03 (SUPERSEDED BY SB 72-0946 R1), SERVICE BULLETIN					CATEGORY 4	
29-JAN-2014		MOS HRS/MSC ENC	- 				
SB 72-0946 R1	NO. 2 ENGINE - HP TURBINE ROTOR ASSEMBLY (72-52-00) - REPLACEMENT OF FORWARD DAMPER SLEEVE FOR THE HPT ROTOR FRONT SHAFTS P/N 2048M21P01 AND P/N 2048M21P03, SERVICE BULLETIN					CATEGORY 4	
06-MAY-2014		MOS HRS/MSC ENC	- 				
SB 72-0952	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-31-00) - INTRODUCTION OF IMPROVED CAST INCO 718 BLADE LOCKS FOR STAGES 4 THROUGH 9, SERVICE BULLETIN					CATEGORY 7	
14-JUL-2014		MOS HRS/MSC ENC	- 				
SB 72-223	NO. 2 ENGINE - INTRODUCTION OF A NEW OUTER LINER LUG RING TO THE SPARE PARTS LIST, SERVICE BULLETIN						
02-FEB-2000		MOS HRS/MSC ENC	- 				
SB 72-A0140 R1	NO. 2 ENGINE - INTRODUCTION OF A BONDED CAUTION PLATE ON HANDCRANKING COVER, SERVICE BULLETIN						
25-JUN-1999		MOS HRS/MSC ENC	- 				
SB 72-A0336	NO. 2 ENGINE - INSTALLATION OF SAFETY WIRE OVER THE OIL TEMPERATURE PROBE AND HOUSING, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 72-A0368	NO. 2 ENGINE - ACCESSORY GEARBOX - REPLACEMENT OF BALL BEARING 340-052-602-0 IN A DEFECTIVE BATCH, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0001	NO. 2 ENGINE - INTRODUCTION OF NEW IGNITER PLUG, SERVICE BULLETIN						NOT APPLICABLE
		MOS HRS/MSC ENC	- 				
SB 73-0002	NO. 2 ENGINE - EEC-SOFTWARE VERSION 7.B.D, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0008R1
		MOS HRS/MSC ENC	- 				
SB 73-0003	NO. 2 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0007
		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00618997

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0003 R1	NO. 2 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0003 R2	NO. 2 ENGINE - SPEED SERVO SLEEVE OF THE SPEED SERVO VALVE AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0004	NO. 2 ENGINE - HMU 1853M56P05(VIN 442026), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0020
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0005	NO. 2 ENGINE - ELECTRONIC CONTROL UNIT (73-00-00) PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0005 R1	NO. 2 ENGINE - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS (SUPERSEDED BY SB 73-0005 R2), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0005 R2	NO. 2 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS, SERVICE BULLETIN					CATEGORY 3	
29-OCT-2013		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0005 R3	NO. 2 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS (SUPERSEDED BY SB 73-0005 R4), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0005 R4	NO. 2 ENGINE - COMBUSTION ASSEMBLY (72-42-00) - INTRODUCTION AND REWORK OF SAC INNER AND OUTER FUEL MANIFOLDS, SERVICE BULLETIN					CATEGORY 3	
14-JUL-2014		MOS					
		HRS/MSC	ESV				
		ENC					
SB 73-0006 R1	NO. 2 ENGINE - TRANSFER OF THE COOLING AIR ORIFICE PLATE TO THE EEC COMPONENT ASSEMBLY LEVEL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		
SB 73-0007	NO. 2 ENGINE - INTRODUCTION OF NEW MAIN FUEL PUMP WITH A NEW STATIONARY SHAFT SEAL, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS			16-DEC-1998		
		HRS/MSC	-		0		
		ENC			0		

© Camp Systems

EFTA00618998

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0008 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.E., SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0009
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0009	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F (7B2B), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0012
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0010	NO. 2 ENGINE - DRAIN TUBE AND FUEL MANIFOLD REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0011	NO. 2 ENGINE - INTRODUCTION OF A SERVO FUEL HEATER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0011 R1	NO. 2 ENGINE - INTRODUCTION OF A SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0012	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F3 (7B2E), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0015
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0013	NO. 2 ENGINE - OPERATE CFM USING CIS TS-1 FUELS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0014 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0015	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.F4 (7B31), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0018R1
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0017	NO. 2 ENGINE - INTRODUCTION OF ECU/EEC HARDWARE/SOFTWARE KITS, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0018 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.G (7B30), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0021R1
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0019	NO. 2 ENGINE - NEW FUEL TRANSIENT BLEED VALVE MANIFOLD AND SUPPORTING BRACKET, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0020	NO. 2 ENGINE - INTRODUCTION OF HMU VIN 442098 (GE 1853M56P06), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0021 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.H2 (7B36), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0023R1
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0022	NO. 2 ENGINE - MODIFICATION OF FUEL NOZZLE FILTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0023	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I (7B37), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0023 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I(7B37), SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 73-0024
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0024	NO. 2 ENGINE - EEC-SOFTWARE VERSION 7.B.I1 (7B38), SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 73-0025	NO. 2 ENGINE - MODIFICATION OF THE FUEL NOZZLE FILTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0026	NO. 2 ENGINE - INTRODUCTION OF EEC- SOFTWARE VERSION 7.B.J(7B3A), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0027	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0028	NO. 2 ENGINE - INTRODUCTION TO HMU 1853M56P07 (VIN 442124), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0028 R1	NO. 2 ENGINE - INTRODUCTION TO HMU 1853M56P07 (VIN 442124), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0029	NO. 2 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0029 R1	NO. 2 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0029 R2	NO. 2 ENGINE - HMU UPGRADE TO 1853M56P07, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0030	NO. 2 ENGINE - ECU/EECS WITH DPM-3 CONVERSION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0030 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (73-00-00) - INTRODUCTION OF NEW ECU/EECS WITH NEW DPM-3 AND CONVERSION, SERVICE BULLETIN					OPTIONAL	
22-FEB-2011		MOS HRS/MSC - ENC					
SB 73-0031	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC - ENC					
SB 73-0032	NO. 2 ENGINE - REPLACEMENT OF VESPEL BALL P/N 1419-240, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0033	NO. 2 ENGINE - CONVERSION NON-PMUX ENGINE AND PMUX TO NON-PMUX ENGINE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0034	NO. 2 ENGINE - INTRODUCTION OF NEW FIEL PUMP WITH NEW FILTER COVER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0035	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.J1 (7B2D), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0036	NO. 2 ENGINE - , SERVICE BULLETIN					CANCELLED	
		MOS HRS/MSC - ENC					
SB 73-0037	NO. 2 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R1	NO. 2 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R2	NO. 2 ENGINE - ENGINE FUEL CONTROL (73-00-00) HMU HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R3	NO. 2 ENGINE - HPSOV SWITCH, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC - ENC					
SB 73-0037 R4	NO. 2 ENGINE - HYDROMECHANICAL UNIT - HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0037 R5	NO. 2 ENGINE - HYDROMECHANICAL UNIT - HPSOV SWITCH, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0038	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL FLOW TRANSMITTER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0039	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0040	NO. 2 ENGINE - ENGINE FUEL CONTROL INTRODUCTION OF SOFTWARE 1853M78P16 (7B41), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0041	NO. 2 ENGINE - INTRODUCTION OF A NEW VSV RIGHT SIDE DRAIN MANIFOLD, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0042	NO. 2 ENGINE - NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0042 R1	NO. 2 ENGINE - NEW FUEL DIFFERNTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043	NO. 2 ENGINE - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043 R1	NO. 2 ENGINE - ELECTRONIC CONTROL UNIT - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0043 R2	NO. 2 ENGINE - ELECTRONIC FUEL CONTROL - PRESSURE SUBSYSTEM BUFFER MATERIAL MODIFICATION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044	NO. 2 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044 R1	NO. 2 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0044 R2	NO. 2 ENGINE - BURNER STAGING VALVE SYSTEM DELETION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0045	NO. 2 ENGINE - NEW HPTCC VALVE FUEL MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0046	NO. 2 ENGINE - ENGINE FUEL CONTROL INTRODUCTION OF SOFTWARE 1853M78P17 (7B42), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0047	NO. 2 ENGINE - LOWER DRAIN MANIFOLD IDENTIFICATION PLATE FIELD REPLACEMENT AND NEW LOWER DRAIN MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0047 R1	NO. 2 ENGINE - LOWER DRAIN MANIFOLD IDENTIFICATION PLATE FIELD REPLACEMENT AND NEW LOWER DRAIN MANIFOLD INTRODUCTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0049	NO. 2 ENGINE - INSPECTION OF HMU MAIN BODY FOR HPT2 THIN WALL CASTING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0050	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL INTRODUCTION OF SOFTWARE 1853M78P18 (7B46), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0050 R1	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 1853M78P18 (7B46), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0051	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0052	NO. 2 ENGINE - INTRODUCTION OF A NEW IMPELLER DRIVE SHAFT AND IMPELLER DRIVE SHAFT PREFORMED PACKING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0052 R2	NO. 2 ENGINE - ENGINE FUEL CONTROL (73-00-00) - MAIN FUEL PUMP - INTRODUCTION OF A NEW IMPELLER DRIVE SHAFT AND IMPELLER DRIVE SHAFT PREFORMED PACKING, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053	NO. 2 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053 R1	NO. 2 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0053 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0053 R3	NO. 2 ENGINE - HYDROMECHANICAL UNIT - IMPROVED ELECTRICAL WIRE RETENTION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0054	NO. 2 ENGINE - FIELD DELETION BURN STAGE VALVE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0054 R1	NO. 2 ENGINE - CORE ENGINE MAJOR MODULE - FIELD DELETION OF THE BURNER STAGING VALVE SYSTEM, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0055	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P19 (7B4A), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0055 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P19 (7B4A), SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0056	NO. 2 ENGINE - , SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0057	NO. 2 ENGINE - SPARE PARTS RELEASE FOR BAE SYSTEMS CONTROLS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0058	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CFM56-7B SAC ENGINE CONFIGURATIONS J9 AND J10 HARNESS WITH IMPROVED OR REWORKED DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0058 R1	NO. 2 ENGINE - CFM56-7B SAC ENGINE CONFIGURATIONS J9 AND J10 HARNESSES WITH IMPROVED OR REWORKED DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0059	NO. 2 ENGINE - ECU DPM INSPECTION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0060	NO. 2 ENGINE - ENGINE FUEL CONTROL - INTRODUCTION OF A NEW SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0061	NO. 2 ENGINE - ENGINE FUEL AND CONTROL, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0061 R1	NO. 2 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
19-DEC-2001		MOS HRS/MSC ENC	- 				
SB 73-0061 R2	NO. 2 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0061 R3	NO. 2 ENGINE - ON-WING AFSO SWITCH ASSEMBLY REPLACEMENT ON HMU WITH WIRE RETENTION SYSTEM INSTALLED, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0062	NO. 2 ENGINE - INTRODUCTION OF NEW/REWORKED ECU WITH LOCKWIRE CAPABILITY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0062 R1	NO. 2 ENGINE - INTRODUCTION OF NEW OR REWORKED ELECTRONIC CONTROL UNIT WITH LOCKWIRE CAPABILITY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0063	NO. 2 ENGINE - INTRODUCTION OF FUEL MANIFOLDS WITH INTERNAL DRAIN PLUGS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0064	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 1853M78P20, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0064 R1	NO. 2 ENGINE - ELCTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 1853M78P20, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0065	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL - PRESSURE SUBSYSTEM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0066	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF SPEED SERVO (MATCHED) VALVE AND SLEEVE ASSEMBLY AND THRUST WASHER., SERVICE BULLETIN						
19-DEC-2001		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0066 R1	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF SPEED SERVO (MATCHED) VALVE AND SLEEVE ASSEMBLY AND THRUST WASHER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0067	NO. 2 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0067 R1	NO. 2 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0067 R2	NO. 2 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0067 R3	NO. 2 ENGINE - INTRODUCTION OF HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) WITH NEW HIGH PRESSURE SHUTOFF VALVE (HPSOV) SWITCH ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0068	NO. 2 ENGINE - REWORK OF THE HYDROMECHANICAL UNIT VIN 442238 (GE 1853M56P08) TO HYDROMECHANICAL UNIT VIN 442124 (GE 1853M56P07), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0069	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0069 R1	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0069 R2	NO. 2 ENGINE - REMOVAL AND REPLACEMENT OF SHUTTLE VALVE, PISTON, AND SLEEVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0070	NO. 2 ENGINE - ELECTRONIC CONTROL UNIT - PRESSURE SUBSYSTEM CONVERSION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0071 R2	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 7. B. 01 1853M78P23, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0073	NO. 2 ENGINE - ENGINE FUEL CONTROL - ENGINE FUEL CONTROL (73-00-00) - RESISTOR MODIFICATION FOR PSS TRANSDUCER INCOMPATIBILITY, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - INSPECTION OF SHUTOFF SPACER FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT - INSPECTION OF SHUTOFF SPACER FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) INSPECTION OF SHUTOFF SPACER P/N 2687048 FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0074 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) INSPECTION OF SHUTOFF SPACER P/N 2687048 FOR PROPER INSTALLATION, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 73-0075	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - HYDROMECHANICAL UNIT - INTRODUCTION OF IMPROVED VALVE EXTENSION AND FEEDBACK DRIVERS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0075 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - HYDROMECHANICAL UNIT - INTRODUCTION OF IMPROVED VALVE EXTENSION AND FEEDBACK DRIVERS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0076	NO. 2 ENGINE - MEC SERVO FUEL HTR LEAKS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0077	NO. 2 ENGINE - FIELD REWORK OF SINGLE ANNULAR COMBUSTOR (SAC) FUEL MANIFOLDS TO ELIMINATE DEAD-END ZONE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0078	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE FUEL CONTROL (73-00-00) - INTRODUCTION OF A NEW FUEL FILTER ELEMENT, SERVICE BULLETIN						COMPLIED WITH
		MOS			01-MAR-2007		
		HRS/MSC	-		2871:05		
		ENC			646		
SB 73-0079	NO. 2 ENGINE - REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT OF THE FUEL FILTER COVER OF THE MAIN FUEL PUMP EQUIPPED WITH D-HEAD BOLT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0080	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - REPLACEMENT OF SHUTOFF SPACER 2687048 WITH NEW DESIGN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0081	NO. 2 ENGINE - HYDROMECHANICAL UNIT (HMU) (73-21-10) - INTRODUCTION OF HONEYWELL HMU VIN 442317 (GE 1853M56P09), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0082	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL - INTRODUCTION OF SOFTWARE 7.B.N 1853M78P21, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0083	NO. 2 ENGINE - REMOVAL AND TEST OF ELECTROHYDRAULIC SERVO VALVE FOR TEMPERATURE SENSITIVITY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0083 R1	NO. 2 ENGINE - REMOVAL AND TEST OF ELECTROHYDRAULIC SERVO VALVE FOR TEMPERATURE SENSITIVITY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0084	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 7.B.0 1853M78P22, SERVICE BULLETIN						
		MOS	6 (s)				
		HRS/MSC					
		ENC					
SB 73-0084 R1	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE 7.B.0 1853M78P22, SERVICE BULLETIN						
		MOS	6 (s)				
		HRS/MSC					
		ENC					
SB 73-0085 R1	NO. 2 ENGINE - INTRODUCTION OF NEW J10 HARNESSES OR REWORK OF THE OLD ONES, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0086	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0088	NO. 2 ENGINE - IMPROVED FUEL FLOW TRANSMITTER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0089	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE HARNESSES CJ9, CJ10 (73-24-05) - INTRODUCTION OF A NEW CJ9 HARNESS OR REWORK OF THE OLD ONE AND DELETION OF THE DUMMY RECEPTACLE BRACKET, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0090	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0090 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0093	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10) -INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVO VALVE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0094	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10)- INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0094 R1	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0094 R2	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF NEW METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0095	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED BURNER STAGING VALVE (BSV) SOLENOID AND VALVE ASSEMBLY, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0096 R1	NO. 2 ENGINE - REPLACEMENT OF FLUOROSILICONE PREFORMED PACKINGS WITH FLUOROCARBON PREFORMED PACKINGS (SUPERSEDED BY 73-0096 R2), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0096 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HMU (73-21-79) - REPLACEMENT OF FLUOROSILICONE PREFORMED PACKINGS WITH FLUOROCARBON PREFORMED PACKINGS, SERVICE BULLETIN					RECOMMENDED	
05-JAN-2012		MOS HRS/MSC ENC	-				
SB 73-0097	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-00-00) - NEW 7.B.P SOFTWARE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	6 (s)				
SB 73-0097 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-00-00) - NEW 7.B.P SOFTWARE, SERVICE BULLETIN						
08-MAR-2005		MOS HRS/MSC ENC	6 (s)				
SB 73-0098	NO. 2 ENGINE - ECU CHASSIS MODIFICATION (SUPERSEDED BY SB 73-0098 R1), SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0098 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU CHASSIS MODIFICATION, SERVICE BULLETIN					CATEGORY 7	
01-APR-2014		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0099	NO. 2 ENGINE - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED ADJUSTMENT SCREW (PN 2689127), SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-01	NO. 2 ENGINE - FUEL FLOW TRANSMITTER CALIBRATION IMPROVEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0100	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102	NO. 2 ENGINE - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400HZ DISCONNECTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R1	NO. 2 ENGINE - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400HZ DISCONNECTS, SERVICE BULLETIN						
07-MAR-2006		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400 HZ DISCONNECTS (SUPERSEDED BY SB 73-0102 R3), SERVICE BULLETIN					RECOMMENDED	
10-NOV-2010		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0102 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - BUCK POWER SUPPLY ROBUSTNESS MODIFICATION FOR 115V 400 HZ DISCONNECTS, SERVICE BULLETIN					CATEGORY 7	
20-JUN-2014		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0103	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT(73-21-10) - LOW PRESSURE LEAK CHECK, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0104	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - ONE TIME INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AND INTRODUCTION OF KEVLAR CUSHION CLAMPS, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS			22-AUG-2008		
		HRS/MSC	-		3260:48		
		ENC			746		
SB 73-0106	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU PMUX (73-00-00) - PRESSURE SUBSYSTEM REDESIGN, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0106 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU PMUX (73-00-00) - PRESSURE SUBSYSTEM REDESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0107	NO. 2 ENGINE - INSPECTION OF PUMP COVER, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0108 R1	NO. 2 ENGINE - BURNER STAGING VALVE SOLENOID REMOVAL FROM HMU, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0108 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HMU (73-21-79) - BURNER STAGING VALVE SOLENOID REMOVAL FROM HMU, SERVICE BULLETIN					RECOMMENDED	
16-FEB-2012		MOS HRS/MSC ENC	-				
SB 73-0109 R1	NO. 2 ENGINE - NEW SOLENOID AND VALVE, SERVICE BULLETIN						
07-MAR-2006		MOS HRS/MSC ENC	-				
SB 73-0111	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-00-00) - INTRODUCTION OF FADEC3 HARDWARE AND SOFTWARE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0113	NO. 2 ENGINE - INSPECTION OF MAIN-STAGE CHECK VALVE SPRING (SUPERSEDED BY 73-0113 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0113 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL NOZZLES (73-00-00) - INSPECTION OF MAIN-STAGE CHECK VALVE SPRING, SERVICE BULLETIN					RECOMMENDED	
13-JAN-2012		MOS HRS/MSC ENC	-				
SB 73-0115	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.Q SOFTWARE, SERVICE BULLETIN						
06-JUN-2005		MOS HRS/MSC ENC	6 (s)				
SB 73-0115 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.Q SOFTWARE, SERVICE BULLETIN						
30-MAY-2008		MOS HRS/MSC ENC	6 (s)				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0116	NO. 2 ENGINE - INTRODUCTION OF NEW ELECTRONIC CONTROL UNIT WITH SAFETYWIRE CAPABILITY TO THE IPC, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0116 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - INTRODUCTION OF NEW ELECTRONIC CONTROL UNIT WITH SAFETYWIRE CAPABILITY TO THE IPC, SERVICE BULLETIN						
13-NOV-2009		MOS HRS/MSC ENC	- 				
SB 73-0117	NO. 2 ENGINE - SPARE PARTS RELEASE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0118 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH A NEW COVER, SERVICE BULLETIN						
23-FEB-2006		MOS HRS/MSC ENC	- 				
SB 73-0120	NO. 2 ENGINE - NEW SOFTWARE VERSION 7.B.Q1F3, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0120 R1	NO. 2 ENGINE - NEW SOFTWARE VERSION 7.B.Q1F3, SERVICE BULLETIN						
30-MAY-2008		MOS HRS/MSC ENC	- 				
SB 73-0121	NO. 2 ENGINE - FRONT PANEL ASSEMBLY ALIGNMENT PIN MODIFICATION PROCEDURE, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 73-0122	NO. 2 ENGINE - FADEC3 -SIA CONNECTOR HARDWARE RETENTION, SERVICE BULLETIN						
27-JUN-2007		MOS HRS/MSC ENC	- 				
SB 73-0123	NO. 2 ENGINE - VSV SYSTEM (72-00-02) - NEW FUEL MANIFOLDS, SERVICE BULLETIN						
12-APR-2006		MOS HRS/MSC ENC	- 				
SB 73-0124	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
21-APR-2008		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0126	NO. 2 ENGINE - ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS , SERVICE BULLETIN						
		MOS					
17-JUL-2006		HRS/MSC	-				
		ENC					
SB 73-0126 R1	NO. 2 ENGINE - ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS, SERVICE BULLETIN						
		MOS					
14-AUG-2007		HRS/MSC	-				
		ENC					
SB 73-0126 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU MODIFICATION, ADDITION OF SIDE TRANSIENT PROTECTION BOARD (STPB) PROTECTION CIRCUITS, SERVICE BULLETIN						
		MOS					
02-OCT-2009		HRS/MSC	-				
		ENC					
SB 73-0127	NO. 2 ENGINE - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
17-JUL-2006		HRS/MSC	-				
		ENC					
SB 73-0127 R1	NO. 2 ENGINE - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
26-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0127 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - ECU MODIFICATION - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS 9SUPERSEDED BY 73-0127 R3), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0127 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (73-00-00) - ECU/EEC MODIFICATION - REPLACEMENT OF ZENER DIODES AND TANTALUM CAPACITORS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0128 R1	NO. 2 ENGINE - INTRODUCTION OF FADEC3 HARDWARE FOR DAC ENGINES, SERVICE BULLETIN						
		MOS					
02-APR-2007		HRS/MSC	-				
		ENC					
SB 73-0130	NO. 2 ENGINE - INSPECTION OF HYDROMECHANICAL UNIT FOR NON-HYDROCARBON CONTAMINATION, SERVICE BULLETIN					RECOMMENDED	
		MOS	6 (s)				
07-MAY-2007		HRS/MSC	1500				
		ENC					
SB 73-0132	NO. 2 ENGINE - INTRODUCTION OF FUEL NOZZLE WITH REVISED O-RING MATERIAL FOR HIGHER TEMPERATURE CAPABILITY, SERVICE BULLETIN						
		MOS					
13-JUN-2007		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00619015

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0132 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - INTRODUCTION OF FUEL NOZZLE WITH REVISED O-RING MATERIAL FOR HIGHER TEMPERATURE CAPABILITY, SERVICE BULLETIN					RECOMMENDED	
		MOS					
13-JUN-2012		HRS/MSC	-				
		ENC					
SB 73-0133	NO. 2 ENGINE - REPLACEMENT OF SUSPECT T12 SENSOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER S/N 874438 N/A
		MOS		08-NOV-2007			
12-APR-2007		HRS/MSC	1200 (s)/DUE				
		ENC					
SB 73-0134	NO. 2 ENGINE - INTRODUCTION OF NEW UNISON ALTERNATOR STATOR VIN 506569-1 (2123M63P02) AND ALTERNATOR ROTOR VIN 505344-1 (2123M62P01), SERVICE BULLETIN						
		MOS					
08-JUN-2007		HRS/MSC	-				
		ENC					
SB 73-0134 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - POWERPLANT - ALTERNATOR (73-00-00) - INTRODUCTION OF NEW UNISON ALTERNATOR STATOR VIN 506569-1 (2123M63P02) AND ALTERNATOR ROTOR VIN 505344-1 (2123M62P01), SERVICE BULLETIN						
		MOS					
04-MAY-2009		HRS/MSC	-				
		ENC					
SB 73-0135	NO. 2 ENGINE - NEW SOFTWARE VERSION 7.B.R3, SERVICE BULLETIN						COMPLIED WITH - IAW THE SB
		MOS		22-AUG-2008			
30-MAR-2007		HRS/MSC	-	3260:48			
		ENC		746			
SB 73-0135 R1	NO. 2 ENGINE - NEW SOFTWARE VERSION 7.B.R3, SERVICE BULLETIN						
		MOS					
30-MAY-2008		HRS/MSC	-				
		ENC					
SB 73-0136	NO. 2 ENGINE - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVOVALVE, SERVICE BULLETIN						
		MOS					
20-JUN-2007		HRS/MSC	-				
		ENC					
SB 73-0136 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE ELECTROHYDRAULIC SERVOVALVE, SERVICE BULLETIN						
		MOS					
18-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0137	NO. 2 ENGINE - HMU OVER-FUEL THRESHOLD MARGIN INCREASE, SERVICE BULLETIN						
		MOS					
20-JUN-2007		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0137 R1	NO. 2 ENGINE - HMU OVER-FUEL THRESHOLD MARGIN INCREASE, SERVICE BULLETIN						
18-FEB-2008		MOS HRS/MSC ENC	- 				
SB 73-0138	NO. 2 ENGINE - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 73-0138 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R1 PARA 3.A	NO. 2 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU						
		MOS HRS/MSC ENC	 10000 (s)				
SB (3) 73-0138 R1 PARA 3.A	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL - (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS						
		MOS HRS/MSC ENC	 3000 (s) 				
SB 73-0138 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R2 PARA 3.A	NO. 2 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	 10000 (s) 				
SB (3) 73-0138 R2 PARA 3.A	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
20-DEC-2010		MOS HRS/MSC ENC	 3000 (s) 				
SB 73-0138 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
12-SEP-2011		MOS HRS/MSC ENC	- 				
SB (2) 73-0138 R3 PARA 3.A	NO. 2 ENGINE - OVERHAUL ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND CLEAN HMU					RECOMMENDED	
		MOS HRS/MSC ENC	 10000 (s) 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0138 R3 PARA 3.A (3)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
		MOS					
		HRS/MSC	3000 (s)				
		ENC					
SB 73-0138 R4	NO. 2 ENGINE - ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	-				
		ENC					
SB 73-0138 R4 PARA 3.A (1)	NO. 2 ENGINE - FLOW ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN CHECK OF ALL FUEL NOZZLES					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	ESV (s)				
		ENC					
SB 73-0138 R4 PARA 3.A (2)	NO. 2 ENGINE - CLEAN ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN AND OVERHAUL HMU					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	10000 (s)/ESV				
		ENC					
SB 73-0138 R4 PARA 3.A (3)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL AND CONTROL (73-00-00) - USE OF CIS FUELS IN CFM56-7B ENGINES, SERVICE BULLETIN OF ALL FUEL SYSTEM COMPONENTS FOR LEAKS					RECOMMENDED	
		MOS					
25-SEP-2012		HRS/MSC	3000 (s)				
		ENC					
SB 73-0139	NO. 2 ENGINE - NEW SOFTWARE VERSION 7.B.S, SERVICE BULLETIN						COMPLIED WITH
		MOS			22-AUG-2008		
12-OCT-2007		HRS/MSC	-		3260:48		
		ENC			746		
SB 73-0140	NO. 2 ENGINE - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-78 ENGINES, SERVICE BULLETIN						
		MOS					
28-NOV-2007		HRS/MSC	-				
		ENC					
SB 73-0140 R1	NO. 2 ENGINE - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
12-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0140 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-21-60) - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS					
13-APR-2009		HRS/MSC	-				
		ENC					
SB 73-0140 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU/EEC (73-21-60) - REPLACEMENT OF K1 AND K2 RELAY ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
23-FEB-2012		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00619018

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0141	NO. 2 ENGINE - FRONT TRANSIENT PROTECTION BOARD FUSE INSPECTION AND REWORK ON FADEC3 FOR CFM56-7B ENGINES, SERVICE BULLETIN					RECOMMENDED	
		MOS	4 (s)				
28-NOV-2007		HRS/MSC					
		ENC					
SB 73-0142 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRICAL HARNESS CJ9, CJ10 (73-24-05) - DELETION OF CJ9 WIRING HARNESS T5 BRANCH FOR NON-PMUX ENGINE IN THE FIELD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0143	NO. 2 ENGINE - PRESSURE SUBSYSTEM (PSS) TRANSDUCER RELIABILITY IMPROVEMENT, SERVICE BULLETIN						
		MOS					
21-FEB-2008		HRS/MSC	-				
		ENC					
SB 73-0144	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
04-APR-2008		HRS/MSC	-				
		ENC					
SB 73-0145	NO. 2 ENGINE - ENGINE FUEL AND CONTROL SYSTEM (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
25-AUG-2008		HRS/MSC	-				
		ENC					
SB 73-0146	NO. 2 ENGINE - REPLACEMENT OF SUSPECTED J7 WIRING HARNESS, SERVICE BULLETIN						
		MOS					
08-APR-2008		HRS/MSC					
		ENC	5 (s)				
SB 73-0151 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW 7.B.T SOFTWARE VERSION, SERVICE BULLETIN						
		MOS					
27-FEB-2009		HRS/MSC	-				
		ENC					
SB 73-0152	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
08-OCT-2009		HRS/MSC	-				
		ENC					
SB 73-0153	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INSPECTION OF MAIN BODY ASSEMBLY, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0154	NO. 2 ENGINE - FADEC3 - CFM56-7B - EEC/ECU CONVERSION FROM P/N 2042M67P02 TO P/N 2042M67P04, SERVICE BULLETIN						
		MOS					
04-MAY-2009		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00619019

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0154 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FADEC3 - CFM56-7B - EEC/ECU CONVERSION FROM P/N 2042M67P02 TO P/N 2042M67P04, SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 73-0156	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE HARNESSES CJ9, CJ10 (73-24-05) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
16-NOV-2011		MOS HRS/MSC ENC	-				
SB 73-0157	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN					RECOMMENDED	
21-JUL-2009		MOS HRS/MSC ENC	6 (s)				
SB 73-0157 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN						
14-AUG-2009		MOS HRS/MSC ENC	6 (s)				
SB 73-0157 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.U1, SERVICE BULLETIN						
02-FEB-2010		MOS HRS/MSC ENC	6 (s)				
SB 73-0158	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF MODIFIED METERING VALVE RESOLVER BODY ASSEMBLY, SERVICE BULLETIN						
15-MAY-2009		MOS HRS/MSC ENC	-				
SB 73-0159	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - INTRODUCTION OF FADEC3 ECU/EEC WITH NEW MAIN CHANNEL BOARD, SERVICE BULLETIN						
09-DEC-2009		MOS HRS/MSC ENC	-				
SB 73-016 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-00-00) - SCHEDULED INSPECTION, SERVICE BULLETIN						NOT APPLICABLE - BASED ON THE HYDROMECHANICAL UNIT (HMU) PART NUMBER
		MOS HRS/MSC ENC	-				
SB 73-0161	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
21-JUL-2009		MOS HRS/MSC ENC	-				
SB 73-0163	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
05-OCT-2009		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0167	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ECU MODIFICATION -REPLACEMENT OF CR1 AND CR14 RECTIFIERS ON THE PSM (SUPERSEDED BY 73-0167 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 73-0167 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ECU MODIFICATION - REPLACEMENT OF CR1 AND CR14 RECTIFIERS ON THE PSM, SERVICE BULLETIN					RECOMMENDED	
04-JAN-2012		MOS HRS/MSC ENC	- 				
SB 73-0169	NO. 2 ENGINE - ENGINE FUEL AND CONTROL-ELECTRONIC CONTROL UNIT (73-00-00)-DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 73-0169 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN					OPTIONAL	
13-JUL-2011		MOS HRS/MSC ENC	- 				
SB 73-0169 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION (SUPERSEDED BY SB 73-0169 R3), SERVICE BULLETIN					RECOMMENDED	
22-SEP-2011		MOS HRS/MSC ENC	- 				
SB 73-0169 R3	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-00-00) - DIGITAL INTERFACE UNIT MODIFICATION, SERVICE BULLETIN					CATEGORY 7	
17-APR-2014		MOS HRS/MSC ENC	- 				
SB 73-0170	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BODY NON-FERROUS RING CHIP CONTAMINATION (SUPERSEDED BY 73-0170 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	- 				
SB 73-0170 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BODY NON-FERROUS RING CHIP CONTAMINATION, SERVICE BULLETIN					RECOMMENDED	
16-MAY-2011		MOS HRS/MSC ENC	- 				
SB 73-0171	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT MANUFACTURABILITY IMPROVEMENTS, SERVICE BULLETIN					OPTIONAL	
24-SEP-2010		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0172	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF FUEL METERING VALVE RESOLVER MODIFICATION , SERVICE BULLETIN					OPTIONAL	
17-DEC-2010		MOS HRS/MSC ENC	-				
SB 73-0172 R1	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF FUEL METERING VALVE RESOLVER MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
15-FEB-2012		MOS HRS/MSC ENC	-				
SB 73-0173	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - CFM56-7B ECU INSPECTION - IOM SOLDER JOINT CRACKING (SUPERSEDED BY SB 73-0173 R1), SERVICE BULLETIN					RECOMMENDED	
20-JAN-2011		MOS HRS/MSC ENC	-				
SB 73-0173 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - CFM56-7B ECU INSPECTION - IOM SOLDER JOINT CRACKING, SERVICE BULLETIN					CATEGORY 5	
17-APR-2014		MOS HRS/MSC ENC	-				
SB 73-0174	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					RECOMMENDED	
23-NOV-2010		MOS HRS/MSC ENC	-				
SB 73-0174 R1	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
19-JUL-2011		MOS HRS/MSC ENC	-				
SB 73-0174 R2	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-00-00) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE (SUPERSEDED BY SB 73-0193), SERVICE BULLETIN					SUPERSEDED	
01-MAY-2013		MOS HRS/MSC ENC	-				
SB 73-0175	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION (SUPERSEDED BY 73-0175 R1) , SERVICE BULLETIN					SUPERSEDED	
		MOS HRS/MSC ENC	-				
SB 73-0175 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION, SERVICE BULLETIN					RECOMMENDED	
16-MAY-2011		MOS HRS/MSC ENC	-				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0175 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE ROTATION (SUPERSEDED BY SB 73-0194), SERVICE BULLETIN					SUPERSEDED	
		MOS					
01-MAY-2013		HRS/MSC	-				
		ENC					
SB 73-0178	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V2, SERVICE BULLETIN					RECOMMENDED	
		MOS					
07-JUN-2011		HRS/MSC	-				
		ENC					
SB 73-0178 R2	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ENGINE #2 ECU SOFTWARE P/N 1853M78P33, VERSION 7B98 (7.B.V2 F2)
		MOS			28-AUG-2013		
17-AUG-2011		HRS/MSC	-		3728:53		
		ENC			875		
SB 73-0180	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY 73-0180 1R), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0180 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - INTRODUCTION OF A NEW FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
23-MAY-2012		HRS/MSC	-				
		ENC					
SB 73-0181	NO. 2 ENGINE - ENGINE FUEL AND CONTROL-IDENTIFICATION PLUG (73-21-83) - INTRODUCTION OF NEW CODING COMBINATIONS FOR -7BE LPT HARDWARE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0182	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN76 BRIDGE BGA ON ASELEC MANUFACTURED MAIN CHANNEL BOARDS (SUPERSEDED BY SB 73-0182 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	- (s)				
		ENC					
SB 73-0182 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN76 BRIDGE BGA ON ASELEC MANUFACTURED MAIN CHANNEL BOARDS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0184	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF T2 AND T4 TRANSFORMER ON THE PSM, SERVICE BULLETIN					RECOMMENDED	
		MOS					
16-FEB-2012		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0185	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - BUCK POWER SUPPLY U540 MODIFICATION, SERVICE BULLETIN					RECOMMENDED	
		MOS					
18-OCT-2011		HRS/MSC	-				
		ENC					
SB 73-0186	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - REPETITIVE INSPECTION OF THE FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY SB 73-0192), SERVICE BULLETIN					SUPERSEDED	
		MOS					
28-NOV-2011		HRS/MSC	15000 (s)				
		ENC					
SB 73-0186 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - REPETITIVE INSPECTION OF THE FUEL DIFFERENTIAL PRESSURE SWITCH (SUPERSEDED BY SB 73-0192), SERVICE BULLETIN						
		MOS					
29-MAR-2013		HRS/MSC	-				
		ENC					
SB 73-0188	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INTRODUCTION OF IMPROVED TRANSIENT BLEED VALVE THREE WAY TWO STAGE ELECTROHYDAULIC SERVO VALVE WITH VENTED SLEEVE, SERVICE BULLETIN					RECOMMENDED	
		MOS					
14-FEB-2012		HRS/MSC	-				
		ENC					
SB 73-0189	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - IDENTIFICATION PLUG (73-24-06) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
18-JUN-2012		HRS/MSC	-				
		ENC					
SB 73-0190	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - REPLACEMENT OF THE FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					SUPERSEDED	
		MOS					
20-JUL-2012		HRS/MSC	- (s)				
		ENC					
SB 73-0190 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-10) - REPLACEMENT OF THE FUEL DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0191	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V3, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
11-DEC-2012		HRS/MSC	-				
		ENC					
SB 73-0191 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V3, SERVICE BULLETIN					RECOMMENDED	
		MOS					
12-APR-2013		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0192	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL DIFFERENTIAL PRESSURE SWITCH (73-34-11) - FUEL DIFFERENTIAL PRESSURE SWITCH MANAGEMENT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0193	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - HYDROMECHANICAL UNIT (73-21-10) - INCORPORATION OF NEW INTEGRATOR SPRING ASSEMBLY FOR ANTI-ROTATION OF BYPASS INTEGRATOR VALVE, SERVICE BULLETIN					CUSTOMER CONVENIENCE	
		MOS					
01-MAY-2013		HRS/MSC	-				
		ENC					
SB 73-0194	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (73-21-10) - HYDROMECHANICAL UNIT BYPASS VALVE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
		MOS					
01-MAY-2013		HRS/MSC	ESV				
		ENC					
SB 73-0195	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - ADDITION OF ARINC SERIES RESISTORS ON TX3 LINES TO ACCOMMODATE NEWER MCB MN52 DEVICE, SERVICE BULLETIN					OPTIONAL	
		MOS					
14-JUN-2013		HRS/MSC	-				
		ENC					
SB 73-0196	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - REPLACEMENT OF MN82 ARINC/CCDL/IMSB CONTROLLER ON TRONICO MANUFACTURED MAIN CHANNEL BOARDS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
25-JUL-2013		HRS/MSC	-				
		ENC					
SB 73-0198	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - INTRODUCTION OF NEW CONNECTORS FOR ELECTRICAL HARNESSES, SERVICE BULLETIN					CATEGORY 6	
		MOS					
20-FEB-2014		HRS/MSC	-				
		ENC					
SB 73-0199	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V4 (SUPERSEDED BY SB 73-0199 R1), SERVICE BULLETIN					SUPERSEDED	
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-0199 R1	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU (73-21-60) - NEW SOFTWARE VERSION 7.B.V4, SERVICE BULLETIN					CATEGORY 7	
		MOS					
28-JAN-2014		HRS/MSC	-				
		ENC					
SB 73-0203	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - NEW SOFTWARE VERSION 7.B.WF2 FOR DAC ENGINES, SERVICE BULLETIN					CATEGORY 2	
		MOS	12 (s)				
09-JUN-2014		HRS/MSC					
		ENC					

© Camp Systems

EFTA00619025

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-0204	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC CONTROL UNIT (73-21-60) - NEW SOFTWARE VERSIONS 7.B.WF3 FOR SAC AND DAC ENGINES AND 7.B.WF2 FOR SAC ENGINES, SERVICE BULLETIN					CATEGORY 2	
		MOS	12 (s)				
09-JUN-2014		HRS/MSC					
		ENC					
SB 73-A002	NO. 2 ENGINE - SERCK AVIATION SERVO FUEL HEATERS - IDENTIFICATION OF POTENTIAL LEAKING UNITS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 73-A0024	NO. 2 ENGINE - INTRODUCTION OF SOFTWARE VERSION 7.B.I1 (7B38), SERVICE BULLETIN						
		MOS					
02-SEP-1998		HRS/MSC	-				
		ENC					
SB 73-A0034	NO. 2 ENGINE - INTRODUCTION OF A NEW FUEL PUMP WITH NEW FILTER COVER, SERVICE BULLETIN						
		MOS					
23-JUL-1999		HRS/MSC	-				
		ENC					
SB 73-A0076	NO. 2 ENGINE - SERVO FUEL HEATERS - IDENTIFICATION OF POTENTIAL LEAKING UNITS, SERVICE BULLETIN						
		DAYS	30 (s)				
		HRS/MSC					
		ENC					
SB 73-A0091	NO. 2 ENGINE - INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AT CLAMP LOCATIONS, SERVICE BULLETIN					CANCELLED	NOT APPLICABLE
		MOS			22-AUG-2008		
		HRS/MSC	- (s)		3260:48		
		ENC			746		
SB 73-A0091 R1	NO. 2 ENGINE - INSPECTION OF 3 FUEL SUPPLY TUBES FOR WEAR AT CLAMP LOCATIONS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0001	NO. 2 ENGINE - INTRODUCTION OF NEW IGNITER PLUG, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0002	NO. 2 ENGINE - INTRODUCTION OF A NEW UNISON IGNITER PLUG, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 74-0003	NO. 2 ENGINE - IGNITION - IGNITION SYSTEM (74-00-00) - SCREENING OF IGNITION UNIT EXCITER VIN 10-631045-2 (P/N 9238M66P08) FOR SUSPECT DIODES, SERVICE BULLETIN						
		MOS	18 (s)				
		HRS/MSC					
		ENC					

© Camp Systems

EFTA00619026

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	74-0004	NO. 2 ENGINE - IGNITION - IGNITION SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION UNIT EXCITER VIN 10-631045-3 (P/N 9238M66P11), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0001 R1	NO. 2 ENGINE - LPT ACC FUEL MANIFOLD BOLT REPLACEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
			MOS		16-DEC-1998			
			HRS/MSC	-	0			
			ENC		0			
SB	75-0002	NO. 2 ENGINE - INTRODUCTION OF HPTC VALVE VIN 3291186-6 (CFMI 1821M59P06), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003 R1	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0003 R2	NO. 2 ENGINE - INTRODUCTION OF NEW LPT COOLING AIR TUBE AND TCC AIR MANIFOLD CHECK VALVE FLANGE ASSEMBLIES, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004	NO. 2 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0004 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW VBV ACTUATOR, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	75-0005	NO. 2 ENGINE - INSPECTION OF PS3 LINE FITTING, SERVICE BULLETIN					MANDATORY SCRAP	
	14-NOV-2001		MOS					
			HRS/MSC	-				
			ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0025 R1	NO. 2 ENGINE - INTRODUCTION OF REWORKED VBV ACUTATOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0027	NO. 2 ENGINE - MODIFICATION OF THE PS3 LINE FITTING CONNECTIONS TORQUE SEQUENCE AND ADDITION OF PERMANENT BONDING TO THE CAP, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0027 R1	NO. 2 ENGINE - AIR - COOLING AIR - MODIFICATION OF PS3 LINE FITTING CONNECTIONS TORQUE SEQUENCE AND ADDITION OF PERMANENT BONDING OF THE CAP, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0030	NO. 2 ENGINE - ENGINE AIR-TRANSIENT BLEED VALVE (72-00-02) - REWORK TRANSIENT BLEED VALVE PN 3291390-1 TO PN 3291390-3, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0030 R1	NO. 2 ENGINE - AIR - AIR TRANSIENT BLEED VALVE (75-21-10) - REWORK OF TRANSIENT BLEED VALVE VIN 3291390-1 (P/N 1821M60P02) TO VIN 3291390-3 (P/N 1821M60P04), SERVICE BULLETIN						
		MOS					
14-JUL-2009		HRS/MSC	-				
		ENC					
SB 75-0032	NO. 2 ENGINE - REPLACEMENT OF VBV TURNBUCKLE (STEEL VERSION) BY NEW ONES WITH NEW MATERIAL (ALUMINIUM VERSION), SERVICE BULLETIN						
		MOS					
21-JUN-2005		HRS/MSC	-				
		ENC					
SB 75-0033	NO. 2 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION ON THE FAN MAJOR MODULE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0033 R1	NO. 2 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION ON THE FAN MAJOR MODULE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0033 R2	NO. 2 ENGINE - REPLACEMENT OF CLAMPS WITH METALLIC FOAM CUSHION BY CLAMPS WITH KEVLAR CUSHION, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 75-0035	NO. 2 ENGINE - INTRODUCTION OF A NEW AIR SUPPLY DUCT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					

© Camp Systems

EFTA00619028

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0036	NO. 2 ENGINE - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE (SUPERSEDED BY SB 75-0036 R1) , SERVICE BULLETIN						
		MOS HRS/MSC ENC	-				
SB 75-0036 R1	NO. 2 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVES (75-22-10) - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE (SUPERSEDED BY SB 75-0036 R2), SERVICE BULLETIN					CATEGORY 7	
25-APR-2014		MOS HRS/MSC ENC	-				
SB 75-0036 R2	NO. 2 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVES (75-22-10) - REWORK TURBINE CLEARANCE CONTROL VALVES, VIN 3291186-5 (1821M59P05) AND VIN 3291186-6 (1821M59P06) TO REDUCE FUEL LEAKAGE, SERVICE BULLETIN					CATEGORY 7	
09-JUN-2014		MOS HRS/MSC ENC	-				
SB 75-0037	NO. 2 ENGINE - INTRODUCTION OF NEW VBV TURNBUCKLE, SERVICE BULLETIN						
08-SEP-2006		MOS HRS/MSC ENC	-				
SB 75-0037 R1	NO. 2 ENGINE - INTRODUCTION OF NEW VBV TURNBUCKLE, SERVICE BULLETIN						
13-FEB-2007		MOS HRS/MSC ENC	-				
SB 75-0038	NO. 2 ENGINE - INTRODUCTION OF PS3 SIGNAL TUBE BRACKET, SERVICE BULLETIN						
14-DEC-2006		MOS HRS/MSC ENC	-				
SB 75-0039	NO. 2 ENGINE - AIR - LPTACC VALVE (75-23-15) -INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
15-DEC-2008		MOS HRS/MSC ENC	-				
SB 75-0041	NO. 2 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
05-FEB-2009		MOS HRS/MSC ENC	-				
SB 75-0041 R1	NO. 2 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF THE NEW LPTACC VALVE, SERVICE BULLETIN						
15-JUN-2009		MOS HRS/MSC ENC	-				
SB 75-0042	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B IPC, SERVICE BULLETIN						
20-FEB-2008		MOS HRS/MSC ENC	-				

© Camp Systems

EFTA00619029

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 75-0043	NO. 2 ENGINE - REWORK OF THE AIR MANIFOLD AND THE BRACKET OF THE COOLING MANIFOLD IN FIELD, SERVICE BULLETIN						
05-SEP-2008		MOS HRS/MSC ENC	- 				
SB 75-0044	NO. 2 ENGINE - AIR-ACTUATOR VBV (75-32-14) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
05-FEB-2010		MOS HRS/MSC ENC	- 				
SB 75-0045	NO. 2 ENGINE - AIR - ACTUATOR VBV (75-32-14) - INTRODUCTION OF THE LVDT SENSOR VIN 8070287 (325-500-002-0), SERVICE BULLETIN						
09-JAN-2009		MOS HRS/MSC ENC	- 				
SB 75-0047	NO. 2 ENGINE - AIR - LPTACC VALVE (75-23-15) - IN FIELD REIDENTIFICATION OF LPTACC VALVE, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 75-0048	NO. 2 ENGINE - AIR - LPTACC VALVE (75-23-15) - INTRODUCTION OF A NEW LPTACC VALVE WITH A NEW IDENTIFICATION PLATE, SERVICE BULLETIN					OPTIONAL	
19-JAN-2012		MOS HRS/MSC ENC	- 				
SB 75-0050	NO. 2 ENGINE - AIR - COOLING (75-22-10) - REWORK OF TURBINE CLEARANCE CONTROL VALVES VIN 3291186-5 (P/N 1821M59P05) AND VIN 3291186-6 (P/N 1821M59P06), SERVICE BULLETIN					RECOMMENDED	
23-FEB-2012		MOS HRS/MSC ENC	- 				
SB 75-0051	NO. 2 ENGINE - AIR - GENERAL - INTRODUCTION OF NEW TBV TUBE AND BRACKET, SERVICE BULLETIN					RECOMMENDED	
03-SEP-2012		MOS HRS/MSC ENC	- 				
SB 75-0052	NO. 2 ENGINE - AIR - VARIABLE STATOR ACTUATOR (75-32-10) - REPLACEMENT OF LVDT FOR FAULTY VSV ACTUATORS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 75-1040	NO. 2 ENGINE - REWORK HIGH PRESSURE TURBINE CLEARANCE VALVE, PN 3291186-5, TO PN 3291186-6, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 77-0001	NO. 2 ENGINE - CONTROL UNIT ALTERNATOR - REPLACEMENT OF CONNECTOR SEALS, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 77-0002	NO. 2 ENGINE - SPARE PARTS RELEASE FOR ENGINE CFM56-7B IPC, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0003	NO. 2 ENGINE - ENGINE INDICATING - T49.5 THERMOCOUPLE LEAD ASSY (77-21-10) - INTRODUCTION OF NEW OR REWORKED T49.5 PROBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0004	NO. 2 ENGINE - ENGINE INDICATING - T5 SENSOR REMOVAL (77-22-10) - INTRODUCTION OF NEW TEMPERATURE SENSOR, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0004 R1	NO. 2 ENGINE - INTRODUCTION OF NEW TEMPERATURE SENSOR, SERVICE BULLETIN						
04-MAR-2005		MOS HRS/MSC - ENC					
SB 77-0005	NO. 2 ENGINE - ELIMINATE CHAFING OF BOEING ECS TUBE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 77-0007	NO. 2 ENGINE - INTRODUCTION OF A NEW N1 SPEED SENSOR, SERVICE BULLETIN						
01-DEC-2006		MOS HRS/MSC - ENC					
SB 77-0008	NO. 2 ENGINE - INTRODUCTION OF A NEW N2 SPEED SENSOR, SERVICE BULLETIN						
20-OCT-2006		MOS HRS/MSC - ENC					
SB 77-0008 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW N2 SPEED SENSOR, SERVICE BULLETIN						
27-FEB-2008		MOS HRS/MSC - ENC					
SB 77-0009	NO. 2 ENGINE - ENGINE INDICATING - (77-00-00) - SPARES PARTS RELEASE FOR CFM56-7B, SERVICE BULLETIN						
12-JAN-2009		MOS HRS/MSC - ENC					
SB 77-0010	NO. 2 ENGINE - ENGINE INDICATING - N1 SPEED SENSOR (77-12-19) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
17-DEC-2009		MOS HRS/MSC - ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0001	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						- INFORMATION ONLY
		MOS HRS/MSC ENC	- 				
SB 79-0001 R1	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R10	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN					CATEGORY 9	
14-APR-2014		MOS HRS/MSC ENC	- 				
SB 79-0001 R2	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R3	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R4	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R5	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 79-0001 R6	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
07-JUL-2006		MOS HRS/MSC ENC	- 				
SB 79-0001 R7	NO. 2 ENGINE - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
10-JUL-2008		MOS HRS/MSC ENC	- 				
SB 79-0001 R8	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES, SERVICE BULLETIN						
14-MAY-2009		MOS HRS/MSC ENC	- 				
SB 79-0001 R9	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - APPROVED OILS FOR CFM56-7B ENGINES (SUPERSEDED BY SB 79-0001 R10), SERVICE BULLETIN					INFORMATIONAL	
19-AUG-2011		MOS HRS/MSC ENC	- 				

© Camp Systems

EFTA00619032

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0002 R1	NO. 2 ENGINE - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		16-DEC-1998			
		HRS/MSC	-	0			
		ENC		0			
SB 79-0002 R2	NO. 2 ENGINE - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0002 R3	NO. 2 ENGINE - OIL - LUBRICATION UNIT (79-00-00) - INTRODUCTION OF THE DEBRIS MONITORING SYSTEM OPTIONAL KIT, SERVICE BULLETIN						
		MOS					
14-MAY-2009		HRS/MSC	-				
		ENC					
SB 79-0003	NO. 2 ENGINE - INTRODUCTION OF A NEW OIL CLOGGING INDICATOR, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0004 R1	NO. 2 ENGINE - ADDITION OF A CAUTION LABEL ON OIL SCAVENGE FILTER BOWL, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0005	NO. 2 ENGINE - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						COMPLIED WITH - NO REWORK REQUIRED
		MOS		22-AUG-2008			
		HRS/MSC	-	3260:48			
		ENC		746			
SB 79-0006	NO. 2 ENGINE - OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF AN IMPROVED OIL SCAVENGE FILTER ASSY WITH MODIFIED BOWL AND HEAD, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0008	NO. 2 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	1500 (s)				
		ENC					
SB 79-0008 R1	NO. 2 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0008 R2	NO. 2 ENGINE - INTRODUCTION OF NEW GASKET SEAL BETWEEN THE HEAT EXCHANGER AND THE SERVO FUEL HEATER, SERVICE BULLETIN						
		MOS					
		HRS/MSC	1500 (s)				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0009	NO. 2 ENGINE - LUBRICATION UNIT REMOVAL (79-21-10) - INTRODUCTION OF NEW PACKING PREFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRIFICATION UNIT., SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0009 R1	NO. 2 ENGINE - LUBRICATION UNIT (79-21-10)-INTRODUCTION OF NEW PACKING PERFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRICATION UNIT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0009 R2	NO. 2 ENGINE - LUBRICATION UNIT (79-21-10)-INTRODUCTION OF NEW PACKING PERFORMED O-RINGS AND REWORK OR INTRODUCTION OF NEW INNER SEALING SPOOL TO THE LUBRIFICATION UNIT, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0010	NO. 2 ENGINE - INTRODUCTION OF NEW FLUOROCARBONE O-RINGS ON OIL FUEL HEAT EXCHANGER, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0010 R1	NO. 2 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-20) - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0010 R2	NO. 2 ENGINE - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
20-DEC-2006		MOS HRS/MSC - ENC					
SB 79-0011	NO. 2 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-20) - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RINGS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0011 R1	NO. 2 ENGINE - REPLACEMENT OF FLUOROSILICONE BY FLUOROCARBONE O-RING, SERVICE BULLETIN						
20-DEC-2006		MOS HRS/MSC - ENC					
SB 79-0012	NO. 2 ENGINE - REWORK OF A SPECIFIC BATCH OF OIL LEVEL SENSORS, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					
SB 79-0013	NO. 2 ENGINE - INTRODUCTION OF A NEW OIL BYPASS VALVE, SERVICE BULLETIN						
		MOS HRS/MSC - ENC					

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	79-0014	NO. 2 ENGINE - OIL - OIL SYSTEM (79-00-00) - DELETION OF THE OIL BYPASS VALVE AND ITS HARDWARE, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				
SB	79-0017	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R1	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R2	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
			MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R3	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES (SUPERSEDED BY SB 79-0017 R4), SERVICE BULLETIN					RECOMMENDED	
	16-FEB-2007		MOS HRS/MSC ENC	6 (s) 				
SB	79-0017 R4	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES, SERVICE BULLETIN						
	14-APR-2014		MOS HRS/MSC ENC	- 				
SB	79-0018	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING, SERVICE BULLETIN						
			DAYS HRS/MSC ENC	30 (s) 				
SB	79-0018 R1	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING (SUPERSEDED BY SB 79-0018 R2), SERVICE BULLETIN						
			DAYS HRS/MSC ENC	30 (s) 				
SB	79-0018 R2	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - TREND MONITORING, SERVICE BULLETIN						
	14-APR-2014		MOS HRS/MSC ENC	- 				
SB	79-0020	NO. 2 ENGINE - OIL - DEBRIS MONITORING SYSTEM (DMS) (79-21-54) - INTRODUCTION OF NEW DMS DETECTOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
			MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0020 R1	NO. 2 ENGINE - INTRODUCTION OF NEW DMS DETECTOR AND REWORK OF THE OLD ONE, SERVICE BULLETIN						
		MOS					
16-JAN-2006		HRS/MSC	-				
		ENC					
SB 79-0021 R2	NO. 2 ENGINE - INTRODUCTION OF A NEW OIL SCAVENGE HOSE TUBE WITH A NEW ROUTING AND A NEW BRACKET, SERVICE BULLETIN						
		MOS					
11-MAR-2005		HRS/MSC	-				
		ENC					
SB 79-0022	NO. 2 ENGINE - OIL - DMS JUNCTION BOX (79-21-53) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN						
		MOS					
26-NOV-2008		HRS/MSC	-				
		ENC					
SB 79-0023	NO. 2 ENGINE - OIL/FUEL HEAT EXCHANGER (79-21-25) - INTRODUCTION OF A NEW MAIN OIL/FUEL HEAT EXCHANGER WITH KEY LOCKED INSERTS, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0023 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW MAIN OIL/FUEL HEAT EXCHANGER WITH KEY LOCKED INSERTS, SERVICE BULLETIN						
		MOS					
20-DEC-2006		HRS/MSC	-				
		ENC					
SB 79-0024	NO. 2 ENGINE - INTRODUCTION OF NEW PACKING PREFORMED O-RINGS IN FLUOROCARBONE WITH BETTER PERFORMANCE AT LOW TEMPERATURE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	500 (s)				
		ENC					
SB 79-0025	NO. 2 ENGINE - NEW FORWARD TUBE, SERVICE BULLETIN						
		MOS					
		HRS/MSC	-				
		ENC					
SB 79-0026	NO. 2 ENGINE - INTRODUCTION OF NEW OUTER SEALING SPOOL, SERVICE BULLETIN						
		MOS					
25-OCT-2007		HRS/MSC	-				
		ENC					
SB 79-0027	NO. 2 ENGINE - OIL CONSUMPTION MONITORING, SERVICE BULLETIN						
		DAYS	30 (s)				
10-JUL-2008		HRS/MSC					
		ENC					
SB 79-0029	NO. 2 ENGINE - OIL - OIL SCAVENGE FILTER ASSEMBLY (79-21-42) - INTRODUCTION OF A NEW BYPASS VALVE SPRING, SERVICE BULLETIN						
		MOS					
08-OCT-2009		HRS/MSC	-				
		ENC					

© Camp Systems

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-0030	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - INTRODUCTION OF AN OIL SUPPLY TUBE WITH A NEW DESIGN, SERVICE BULLETIN					RECOMMENDED	
05-NOV-2010		MOS HRS/MSC ENC	- 				
SB 79-0031	NO. 2 ENGINE - OIL - LUBRICATION UNIT (79-21-16) - SPARE PARTS RELEASE FOR CFM56-7B CMM, SERVICE BULLETIN					INFORMATIONAL	
10-DEC-2010		MOS HRS/MSC ENC	- 				
SB 79-0032	NO. 2 ENGINE - OIL - GENERAL (79-00-00) - SPARE PARTS RELEASE FOR CFM56-7B ENGINES, SERVICE BULLETIN						
22-JAN-2013		MOS HRS/MSC ENC	- 				
SB 79-0069	NO. 2 ENGINE - DELETION OF ELECTRICAL CHIP DETECTOR KIT, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 80-0001	NO. 2 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 80-0001 R1	NO. 2 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED 80-0003R1
		MOS HRS/MSC ENC	- 				
SB 80-0001 R3	NO. 2 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				
SB 80-0001 R4	NO. 2 ENGINE - NEW AIR TURBINE STARTER DESIGN, SERVICE BULLETIN						
13-AUG-1999		MOS HRS/MSC ENC	- 				
SB 80-0002	NO. 2 ENGINE - AIR TURBINE STARTER CLAMP ROTATION, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
26-MAR-1998		MOS HRS/MSC ENC	- 		16-DEC-1998 0 0		
SB 80-0003 R1	NO. 2 ENGINE - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	- 		16-DEC-1998 0 0		
SB 80-0004	NO. 2 ENGINE - REPLACE THE GEAR SHAFT P/N 3507167-1 WITH P/N 3507167-2, SERVICE BULLETIN						
		MOS HRS/MSC ENC	- 				

© Camp Systems

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	80-0004 R1	NO. 2 ENGINE - REPLACE THE GEAR SHAFT P/N 3507167-1 WITH P/N 3507167-2, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0005	NO. 2 ENGINE - AIR TURBINE STARTER, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0006	NO. 2 ENGINE - STARTING - INTRODUCTION OF NEW TURBINE AIR STARTER VIN 3505945-9 (GE 1851M36P09) FIELD UPGRADE, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0006 R1	NO. 2 ENGINE - STARTING - INTRODUCTION OF NEW TURBINE AIR STARTER VIN 3505945-9 (GE 1851M36P09) FIELD UPGRADE, SERVICE BULLETIN						
			MOS					
	11-MAR-2004		HRS/MSC	-				
			ENC					
SB	80-0007	NO. 2 ENGINE - INTRODUCTION OF AIR TURBINE STARTER VIN 3505945-10 (GE 1851M36P10), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0008	NO. 2 ENGINE - INSPECTION AND REPLACEMENT OF NONCONFORMING MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH
			MOS			22-AUG-2008		
	06-AUG-2002		HRS/MSC	- (s)		3260:48		
			ENC			746		
SB	80-0009	NO. 2 ENGINE - STARTING - STARTING (80-00-00) - AIR TURBINE STARTER VIN 3505945-9 (GE 1851M36P09) TO VIN 3505945-10 (GE 1851M36P10) REWORK, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0010	NO. 2 ENGINE - PACKINGS FOR HTS OILS, SERVICE BULLETIN						
			MOS					
			HRS/MSC	DUE				
			ENC					
SB	80-0010 R1	NO. 2 ENGINE - PACKINGS FOR HTS OILS AND NEW MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0010 R2	NO. 2 ENGINE - PACKINGS FOR HTS OILS AND NEW MAGNETIC DRAIN PLUG ASSEMBLY, SERVICE BULLETIN						
			MOS					
	25-JUL-2006		HRS/MSC	- (s)				
			ENC					

© Camp Systems

Task	No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	80-0011	NO. 2 ENGINE - MAGNETIC DRAIN PLUG WITH LARGER KNOB TO EASE REMOVAL, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0012	NO. 2 ENGINE - REPLACEMENT OF THE SPRING WASHER IN AIR TURBINE STARTERS VIN 3505945-9 (1851M36P09) AND VIN 3505945-10 (1851M36P10), SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0013	NO. 2 ENGINE - STARTING - GENERAL (80-00-00) - ALLOW THE CHANGE IN THE FIELD OF THE AIR TURBINE STARTER DECOUPLER ASSEMBLY VIN 3504835-1 (SUPERSEDED BY 80-0013 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS					
	14-FEB-2012		HRS/MSC	-				
			ENC					
SB	80-0013 R1	NO. 2 ENGINE - STARTING - GENERAL (80-00-00) - ALLOW THE CHANGE IN THE FIELD OF THE AIR TURBINE STARTER DECOUPLER ASSEMBLY VIN 3504835-1, SERVICE BULLETIN					RECOMMENDED	
			MOS					
	28-MAR-2012		HRS/MSC	-				
			ENC					
SB	80-0014	NO. 2 ENGINE - STARTING - STARTER (80-11-00) - INTRODUCTION OF NEW AIR TURBINE STARTERS VIN 3505945-11 (P/N 1851M36P11) AND VIN 3505945-12 (P/N 1851M36P12), SERVICE BULLETIN					OPTIONAL	
			MOS					
	17-APR-2013		HRS/MSC	-				
			ENC					
SB	80-0015	NO. 2 ENGINE - STARTING - STARTER (80-11-00) - RETURN SUSPECT AIR TURBINE STARTERS, P/N 3505945-10, FOR INSPECTION AND EVALUATION (SUPERSEDED BY SB 80-0015 R1), SERVICE BULLETIN					SUPERSEDED	
			MOS					
			HRS/MSC	-				
			ENC					
SB	80-0015 R1	NO. 2 ENGINE - STARTING - STARTER (80-11-00) - RETURN SUSPECT AIR TURBINE STARTERS, P/N 3505945-10, FOR INSPECTION AND EVALUATION, SERVICE BULLETIN					CATEGORY 2	
			MOS					
	09-JAN-2014		HRS/MSC	-				
			ENC					
SB	80-1709	NO. 2 ENGINE - REWORK THE AIR TURBINE ENGINE STARTER, PN 3505945-5/-6 TO PN 3505945-7/-8, SERVICE BULLETIN						
			MOS					
			HRS/MSC	-				
			ENC					
SI	SER 79-0001	NO. 2 ENGINE - SERVICE EVALUATION REQUEST OF FLIGHT EVALUATION OF OILS, SERVICE INSTRUCTIONS						
			MOS					
			HRS/MSC					
			ENC	5000 (s)				
VSB	3291186-75-1074 R1	NO. 2 ENGINE - ENGINE AIR - HIGH PRESSURE TURBINE CLEARANCE VALVE - REWORK HIGH PRESSURE TURBINE CLEARANCE VALVES, PN 3291186-5 AND PN 3291186-6 TO REDUCE FUEL LEAKAGE, VENDOR SERVICE BULLETIN					RECOMMENDED	
			MOS					
	19-FEB-2014		HRS/MSC	-				
			ENC					

© Camp Systems