



A/C Actual Compliance Last - Reason

Print Date: 20/02/2008 11:09  
Page: 1 of 36

E/C (Category AD)	Document/SB	E/C Description	Schedule	Remaining	Last Compliance Information
			Hrs/Cyc/Dys/Dte	Next Due	
E/C: 1974-08-09	25-120-00-01 25-130-00-01 25400-00-00 25400-100-10000-1 25400-12-0080 254100-01000 74-08-09R2 A122540	WASTE RECEPTACLE DOOR INSPECTION	1000 Hrs	035.78	WD 12017 14/01/2008 Rev 9 A/C Total Hours: 123024 A/C Total Cycles: 451 CREDIT DURING 1A CSK REF TWD 12017
Category AD Status: OPEN Rev: 9			Recur EARLIEST	01/09/2009	
E/C: 1987-08-09	320000-00000	RELATION OF IRS'S WITH AIRFRAME			Reason E/C NOT TO BE USED FOR CHECK TASK AS IT IS AT WORK STEP 12 (10/01/00) Manual Compliance: 01/01/1987 Rev 2 A/C Total Hours: 0.00 A/C Total Cycles: 0 THIS TASK IS CONTROLLED THROUGH DAILY CHECK REF DAILY CHECK TASK CARD
Category AD Status: TERMINATED Rev: 2					Amount NO 30-1680
E/C: 1989-18-12	1991-10-02	CLASS B MAIN DECK CARGO COMPARTMENT			
Category AD Status: CANCEL Rev: 2		Superseded By: 1991-10-02			Amount NO 30-8547
E/C: 1989-10-02	1989-18-12	CLASS B MAIN DECK CARGO COMPARTMENT			
Category AD Status: CANCEL Rev: 2		Superseded By: 1993-07-15	EARLIEST		Amount NO 30-8108
E/C: 1993-07-15	1989-18-12 1991-10-02	CLASS B MAIN DECK CARGO COMPARTMENT			
Category AD Status: N/A Rev: 2					Amount NO 30-8547

Certified that the above modifications have been embodied by the aircraft constructor at the time of certification of the aircraft, additional to the basic design.

Signed..... (for Constructor)

Date.....

MANDATORY MODIFICATION RECORD

Aircraft Registration: AG-DFR

Owner's Name: AMIRI FLIGHT

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
2	3	4	5	6
AD2008-03-01	TRF WITH TANGENTIAL STRUTS - MANDATORY INSPECTIONS - LIFE TIMES.	SB CFM 56-78-72-0579.		AD REQUIREMENT CONTROLLED BY SB CFM 56-78-72-0579. SB C/W ON 28/01/08 BY BEING BARRICAD TO CLOSED.
AD2008-05-05	STRUCTURE ATTACHMENT FITTINGS - INADEQUATE SEALING (ARVMD) VERTICAL FIN LVLS.	SB 737-53A1242		SB C/W UNDER TWD 12175 D/H 8/14/08.
AD2008-08-22	GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION.	SB 737-30-1056	EO 83-30-1056.	SB C/W BY LHT ON 11/01/07. REF. DEL. P/L.
AD2008-09-14	EMERG. FUEL FEED SYS. BOOST PUMP CTRL RELAY GRD. LOC. CHANGE.	SB 737-28-1257	LHT EO 155809.	V/ SB 25-343 C/W ON ALL S/RAFTS.
AD2008-06-27	EMERG. EVAC. EQUIP. SLIDE RAFTS - SHEAR PIN RESTRAINTS REPLACEMENT.	V/ SB 25-343		SB C/W & RECD AWLS ARE INCORPORATED INTO A/C AD CLOSED.
AD2008-06-03	EMERG. FUEL FEED SYS. MOTOR OPERATED VLV. ACT. RECD & EMERG. FUEL FEED SYS. MOTOR OPERATED VLV. AWLS (SB 737-28A1207) C/W & RECD AWLS NOW INCORPORATED TO A/C.	SB 737-28A1207.		AWLS ARE INCORPORATED INTO A/C AS PER AD PER. AD CLOSED.
AD2008-10-10	A/C REVISION TO INCLUDE AWL RELATED TO FUEL TANK SYSTEMS.			
AD2008-11-08	FLIGHT DECK NO. 2, 4 AND 5 WINDOWS INSPECTION.	SB 737-56A1022 (UNSP)		
AD2004-05-19	MODIFICATION OF THE PINS/BOLTS THAT ATTACH THE HORIZONTAL STAB.	SB 737-55-1086		SB C/W DURING 2C CHK REF W/O 12142 D/H 08/10/08.
AD2005-23-16	C/WT. WIRE BUNDLE INSTALLATION CHANNEL.	SB 737-28-1209		SB 28-1209 C/W D/H 08/10/08. 2C CHK REF W/O 12142 D/H 08/10/08.
AD2006-21-01	LUBRICATION & FREELAY CHECK OF AILERON BALANCE TAB BEARINGS.	SB 737-27-1273		
EASA AD2006-0440-E	AIR CONDITIONING - ZONAL DRYING SYSTEM DEACTIVATION - EMERG. AD.	AD	SNCB73-21-015	REF W/O 12893 D/H 09 OCT. 08.
AD2006-07-04	FLUID ACCUMULATION IN ENGINE SCROT AFT FAIRING.	SB 737-54-1041	EO 83-54-1041	MOD PART OF SB C/W REF W/O 16115 D/H 02/11/11

MANDATORY MODIFICATION RECORD

Aircraft Registration A6-DFR  
 Owner's Name AMIRI FL.

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
AD 2008-22-01	PREVENT USAGE OF AUXILIARY FUEL TANK - FAA NOTIFICATION PART 43 BY OA ON 02/11/08.			4007, REF W/O 12640 Dtd 16.08.08.
AD 2008-24-08	EMERGENCY EVACUATION SLIDE INFLATION VALVE RECALIBRATION.	SB 737-25-1491		PH 5A3307-5 FIXED ON A/C SATISFIES AD REQUIREMENT AD CLOSED.
AD 2008-24-09	EMERGENCY AD - INSPECTION FOR MIS-WIRING AFTER ACCOMPLISHMENT OF SB 737-28A1206.			4007, REF W/O 13014 Dtd 19.11.08.
AD 2008-23-07	AIRPLANE FLIGHT MANUAL REVISION - CABIN ALTITUDE WARNING.	EO B3-2008-2307		4007, REF W/O 12982 Dtd 03.08.08.
AD 2008-24-05	WINDSHIELD WIPER MOTOR REPLACEMENT.	SB 737-30A1057		REF W/O 12229 Dtd 11.01.09.
AD 2005-18-23	CORROSION PROTECTION OF ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (CIRCUIT CONTROLLED BY EO/B3-24A1148)	SB 737-24A1148	EO B3-24A1148.	OPEN
AD 2008-16-13	FLT. CONTROLS - ELEVATOR AND TAB - LEFT & RIGHT ELEVATOR TAB PUSHERS REPLACEMENTS.	SB 737-27-1284	EO B3-27-1284.	4007, REF W/O 13098 Dtd 03/03/09. AD CLOSED.
AD 2008-08-24	NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRINGS DRAIN TUBE ASSY REPLACEMENT.	SB 737-54-1043	EO B3-54-1043	4007, REF W/O 13098 Dtd 03/03/09. AD CLOSED.
AD 2008-21-02	NACELLES/PYLONS - HEAT INSULATION BLANKETS - REPLACEMENT.	SB 737-54-1045		SB CLOSED DURING A/C K. BY DTD 07/09/09 REF W/O 13629.
AD 2009-0251E	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT.			REF T/LM 2198667/07 Dtd 27 NOV. 09
AD 2009-0262	FIRE PROTECTION - PORTABLE FIRE EXT. IDENTIFICATION & REPLACEMENT.		SWC 26-003	FOUND AFFECTED PIN NOT FITTED.
AD 2009-0278	FIRE PROTECTION - PORTABLE HALON 1211 IDENTIFICATION & REPLACEMENT.		SWC 26-004	REF. W/O # 14291. DT. 28/12/09.
AD 2010-01-03	PORTABLE HALON 1211 (BCP) FIRE EXT. MANTLED BY FFE.			SB AD 2009-0251E 2009-0262 FOUND C/W WEBS AD REQ. AD CLOSED.

MANDATORY MODIFICATION RECORD

Aircraft Registration A6-DFR  
 Owner's Name FOR PRESIDENTIAL FL.

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
AD 2009-26-04	MAIN Ldg GEAR - FWD TRUNNION PIN INSPECTION AND REPLACEMENT.	SB 737-32-1376		SB FOUND C/W AS PER LHT SB LIST DTD 15/11/07. AD CLOSED.
AD 2009-26-03	ELECTRICAL PWR - STANDBY STATIC INVERTER MODIFICATION.	SB 737-24-1165		SB FOUND C/W AS PER LHT SB LIST AT TIME OF DEL.
AD 2010-17-05	FUEL PUMP CONTROL QAD FAULT INTERRUPTER (GFI) RELAY INSTALLATION.	B3-281201R1		REF W/O 13629 Dtd 02/09/09.
AD 2010-17-19	ELEVATOR TAB CONTROL MECHANISM DETAILED INSP.	SB 737-27A1297	EO B3-27A1297	SUPERSEDED BY 2013-06-05.
AD 2010-19-03	PREVENT USAGE OF AUXILIARY FUEL TANKS OR MODIFY AUXILIARY FUEL SYS.	SB 5700936NY-D-28-SB-001	ST00936NY-D-28-SB-021	SB'S C/W UNDER W/O 12640 Dtd 16/18/08.
AD 2011-20-07	FUEL PUMP CONTROL GROUND FAULT INTERRUPTER RELAY INSTALLATION.	SB 737-28A1201R1		REF W/O 13629 Dtd 02/09/2009.
AD 2011-20-10	RUDDER & RUDDER TRIM CONTROL SYS - RUDDER QUADRANT CLEARANCE INSPECTION.	SB 737-27-1282		REF W/O 12252 Dtd 26/13/08.
AD 2011-06-05	HORN OF SLAT TRACK DOWN STOP ASSYS ON ALL L/E SLATS.	SB 737-57A1302		W/O 16115 DTD 16.09.11.
AD 2011-18-10	AFT ENG MOUNT - CENTER LINK ASSY - INSP TO ENSURE CORRECT INSTALLATION.	SB 737-71A1462		W/O 12650 DTD 14 JAN 08 W/O 12361 DTD 29 APR 08.
AD 2010-02-04	ENG FUEL FEED - MAIN TANKS ENG FUEL SPAR VLV BODY REPLACEMENT.	SB 737-28-1272		W/O 16115 DTD 16 SEP 11.
AD 2011-27-03	HORIZ STAB TRIM CTRL SYS - STAB TRIM ACT OIL, HOIST BALLSCREW & NUT INSP & LUB.	SB 737-27A1277		
AD 2010-02-24	EXHAUST - THRUST REVERSER INNER WALL MODIFICATION / INSP.	SB 737-78-1082 SB 737-78-1079 SB 737-78-1085		
AD 2010-24-11	CENTER & OUTER WING - FASTENER SEALING & WIRE BUNDLE SPT - QVI	SB 737-27A1277		W/O 16115 DTD 16 SEP 11.





## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name AMIRI FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
14	B3-24-1171	INSPECTION, REPAIR AND INSTALLATION OF PROTECTIVE SLEEVE ON WIRE BUNDLE WOODS IN THE FT. DECK.	SB 737-24-1171	-	REF TWO 12246 Dtd 26/03/08.
15	B3-27-1282	RUDDER & RUDDER TRIM CONTROL SYS: WIRE BUNDLE W 448 AND LEFT FWD. RUDDER QUADRANT CLEARANCE INSPECTION.	SB 737-27-1282	-	REF TWO 12252 Dtd 26/03/08.
16	B3-31-1327	CDS: INSTALL OPS BLOCK POINT 06.	SB 737-31-1327	-	REF TWO 12244 Dtd 26/03/08.
17	B3-30-1066	GRAYWATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION	SB 737-30-1066	-	REF TWO 12175 Dtd 08/04/08.
18	B3-34-152	REPLACE ANGLE OF ATTACK SENSOR	737-SL-34-152	-	REF TWO 12302 Dtd 08/04/08.
19	B3-52-1157	DOORS-ENTRANCE STAIRS - FWD AIRSTAIR - AIRSTAIR HANDRAIL SAFETY IMPROVEMENTS.	737-52-1157 (SIS)	-	REF TWO 12285 Dtd 28 APR. 08.
20	B3-34-1894	EGPWS: PEAKS & OBSTACLES OPTION ACTIVATION.	SB 737-34-1894	-	REF TWO 12367 Dtd 15/05/08.
21	B3-22-1199	AP: TO ENABLE LNAV AS THE DEFAULT ROLL MODE FOR G/A IN LIEU OF TRX HOLD	SB 737-22-1199	-	REF TWO 12348 Dtd 15/05/08.
22	B3-34-1918	FMC: UPDATE FMC SOFTWARE TO VERSION 10-7	SB 737-34-1918	-	REF TWO 12310 Dtd 15/05/08.
23	B3-34-2098	EGPWS: ALTITUDE CALLOUTS REVISION MENU ID 38.	SB 737-34-2098	-	REF TWO 12349 Dtd 29/04/08.
24	B3-25-066AF	EQUIP. FURNISHING REPLACEMENT OF EXISTING NIF AT L1 DOOR.	GCAA	-	REF TWO 12429 Dtd 18 MAY 08.
25	SWCB 73-35-003	JAMMING OF PAX OXYGEN GEN. RELEASE PIN.	OIT M-7200-00-02474	-	REF TWO 2084/2389 Dtd 18/05/08.
26	B3-25-066AF	EQUIP. FURNISHING - FWD GALLEY INTRODUCTION OF NEW 'ENDURA' TYPE COFFEE MAKERS	EO B3-25-066AF (90)	-	REF TWO 12572 Dtd 6/1/08.

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name AMIRI FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
27	SWCB73-25-019	FLIGHT DECK SUITCASE RESTRAINT STRAP CLIP INSTALLATION	737-SL-25-098	-	REF TWO 12592 Dtd 9/07/08.
28	B3-53-081	EXCESSIVE SEALANT IN NOSE LANDING GEAR HINGE CAVITY	737-SL-53-081	-	REF TWO 12537 Dtd 9/7/08.
29	B3-52034	AIRSTAIR DOOR LOCKPIN SENSOR - TARGET AND BRACKET REPLACEMENT.	737-SL-52-034	-	REF TWO 12583 Dtd 14/07/08.
30	SWCB73-25-025	FLIGHT COMPARTMENT SEATS- RESTRAINT SYSTEM INSPECTION.	V/SB 1180003-25-07.	-	REF TWO 12668 Dtd 14/07/08.
31	B3-27198	NOSE DOWN SIBS TAKE-OFF WARNING SW. (S-540) PLACARD AND STOP WHEEL DOWN LIMIT SWITCH (S-145) PLACARD INSTALLED	737-SL-27-198	-	REF TWO 12535 Dtd 15/07/08.
32	SWCB73-38-004	VALVUM WASTE TANK DRAIN FITTING INSPECTION FOR LEAKS.	MSG 1-725906264.	-	REF TWO 12575 Dtd 15/07/08.
33	B3-29-1106	REMOVAL OF HYDR SWR PRESSURIZATION MUD. AND DEPRESSURIZATION VALVES.	SB 737-29-1106 RE	-	REF TWO 12594 Dtd 15/07/08.
34	SWCB73-49-013	APV BLD DUCT INSPECTION FOR MISSING MATERIAL.	SWC B3-49-013	-	REF TWO 12532 Dtd 15/07/08.
35	B3-29-1110	HYD POWER-HYDRAULIC RSVR. OVERFILL WARNING MARKER INSTALLATION.	SB 737-29-1110.	-	REF TWO 12534 Dtd 17/07/08.
36	SWCB73-25-046	INSTALLATION OF AFT CARGO COMPT. DOOR NET.	SWCB73-25-046	-	REF. W/O 12835 DT. 05/11/08.
37	737-SL-49-078	KPU ECU SOFTWARE - VERSION. 4	B3-49-078	-	REF. W/O 12742 DT. 05/11/08.
⊕	⊕	PLS REF TO ATTACHED LIBOOK MAINT. ENTRY SHEETS (24) FOR DETAILS OF SB/SL CHG DURING 2c CHK DTD 08/09/08			AF 12 TR
114-09					

	<b>LOG BOOK MAINTENANCE ENTRY</b> Continuation page	A/C Regn.: A6-DFR W/P Ref.: 039405-WO 12079&12142 Date of CRS: 08 Sep 2008
	<p>ITEM The following additional maintenance has been carried out during this Maintenance Visit</p> <p>2.08 737-57-1250 – Center wing box – inspection of secondary fuel vapor barrier application on the wing c/out law EO B3-57-1250 (SB Closed)</p> <p>2.09 737-57-1284 – Wings – Trailing edge and trailing edge devices – inspection, repair - wing BL 147 to BL 201 c/out law EO B3-57-1284 (SB Open)</p> <p>2.10 737-28A1248 – CWT fuel pumps Power failed on protection system – Relay installation c/out law EO B3-28A1248 (SB Closed)</p> <p>2.11 737-55-1074 – Inspection &amp; Repair of the interface bushings between the horiz stab c/out law EO B3-55-1074 (SB Open)</p> <p>2.12 737-53-1282 – Fuselage – wheel well – nose wheel upper drag brace and trunnion bushing replacement c/out law EO B3-53-1282 (SB Closed)</p> <p>2.13 737-53-1277 – Fuselage – structure attachments fittings – nose wheel well retract actuator support fitting inspection c/out law EO B3-53-1277 (SB Closed)</p> <p>2.14 737-49-1133 – APU flap and vortex generator assy modification c/out law EO B3-49-1133 (SB Closed)</p> <p>2.15 737-34-1811 – Pitot static probe: Ground plate and nut plate installation c/out law EO B3-341811. (SB Closed)</p> <p>2.16 737-27-1270 – Rudder feel &amp; centering unit – inspection and rework c/out law EO B3-27-1270 (SB Closed)</p> <p>2.17 737-21-1148 – Pack flow control and pack cooling system – ram air inlet sys comp insp and replacement c/out law EO B3-21-1148 (SB Closed)</p> <p>2.18 737-24-1161 – Installation of protection guards on the P6 &amp; P18 load control panels c/out law EO B3-241161 (SB Closed)</p> <p>2.19 737-53-1245 – Ground pneumatic service connector – high pressure door insp/modification c/out law EO B3-53-1245 (SB Closed???)</p> <p>2.20 737-21-1155 – Equipment cooling duct inspection and tape installation to prevent rub condition c/out law EO B3-21-1155 (SB Closed)</p> <p><b>3.0 Following Service Letters Accomplished</b></p> <p>3.1 737-SL-78-058 – Availability thrust reverser blocker door drag link spherical liner bearing c/out (SL Closed)</p> <p>3.2 737-SL-78-060 – CFM56-7B Engine primary exhaust nozzle fince cracking c/out law SWCB73-78-008 (SL Closed)</p> <p>3.3 737-SL-71-059 – Engine Cowl anti-ice duct bolt retention discrepancy inspection c/out law SWCB73-71-009 (SL Open)</p> <p>3.4 737-SL-52-027 – Fwd airstair top step interference with floor beam hex drive bolt collars – c/out law SWCB73-52-003 (SL Closed)</p> <p>3.5 737-SL-21-078 – Forward door heat system duct kinking c/out law B3-21-078 (SL Closed)</p> <p>3.6 737-SL-28-062 – Possible miss-location of fuel tank vent tube climb port c/out law SWCB73-28-013 (SL Closed)</p>	
All Work Pack Processing has been completed & all Log Books have been updated, signed & stamped.		Name: K.H.Abdul Kader Signature: <i>K.H.Abdul Kader</i> Date: 01/11/2008 Authorisation Stamp: 

Form No. MP81 0707

Page 2 of 4

	<b>LOG BOOK MAINTENANCE ENTRY</b>				A/C Regn.: A6-DFR W/P Ref.: 039405-WO 12079&12142 Date of CRS: 08 Sep 2008
	A/C TYPE	MSN / Prod. No/ LINE No	FLIGHT HOURS	FLIGHT CYCLES	CHECK TYPE PERFORMED
R737 7BC	30884 / 747/YG03R	1469.35	767	2C/1C/A CHECKS	
ENG TYPE	INSTL POSN	SERIAL NUMBER	TSN	CSN	INPUT DATE OUTPUT DATE
CF6 80C2B1FG	#1	888148	1469.35	767	20/07/2008 08/09/2008
CF6 80C2B1FG	#2	889151	1469.35	767	
APU TYPE	SERIAL NUMBER	TSN	CSN	AMS REF No / REV. No. / DATE	STATION
131 0B	P 5843	2301	1088	BBJ MS 03/11/07	EHAM
ITEM	The following work performed during 2C/1C/A Check and additional maintenance has been carried out during this Maintenance Visit				
01	<b>Following ADs' Accomplished</b>				
1.01	AD 1974-08-09 – Waste receptacle door inspection c/out law task card (AD Open)				
1.02	AD 2004-05-19 – Modification of the pins/bolts that attach the horizontal stab c/out law EO B3-55-1086. (AD Closed)				
1.03	AD 2005-23-16 – CWT, Wire bundle installation change c/out law EO B3-281209. (AD Closed)				
1.04	AD 2006-21-01 – Lubrication of aileron balance tab bearings and free play check c/out as per EO B3-27-1273 INSP & B3-27-1273 LUBE (AD Open)				
02	<b>Following SBs' Accomplished</b>				
2.01	737-28-1172 – Alignment of center tank boost pumps inlets & fuel pump alignment bracket – c/out law EO KLM JOBS70004C (SB Closed)				
2.02	737-55-1086 – Modification of the pins/bolts that attach the horizontal stab c/out law EO B3-55-1086 (SB Closed)				
2.03	737-28-1209 – CWT Wire bundle installation change c/out law EO B3-281209 (SB Closed)				
2.04	737-27-1273 – Lubrication and free play check of Aileron balance tab bearings c/out law Eos B3-27-1273 Lube and B3-27-1273 Insp (SB Open)				
2.05	737-24-1172 – Inspection & repair of electrical bonding resistance at the wing to body feed thru receptacles c/out law EO B3-24-1172 (SB Closed)				
2.06	737-28A1206 – CWT boost pump auto shut off & master caution logic change c/out law EO B3-28A1206 (SB Closed)				
2.07	737-78-1075 – Inspection and replacement of the fire seal on each thrust reverser half c/out law EO B73-78-1075 (SB Closed)				
All Work Pack Processing has been completed & all Log Books have been updated, signed & stamped.		Name: K.H.Abdul Kader Signature: <i>K.H.Abdul Kader</i> Date: 01/11/2008 Authorisation Stamp: 			

Form No. MP81 0707

Page 1 of 4

	<b>LOG BOOK MAINTENANCE ENTRY</b> Continuation page	A/C Regn.: A6-DFR W/P Ref.: 039405-WO 12079&12142 Date of CRS: 08 Sep 2008
	<p>ITEM The following additional maintenance has been carried out during this Maintenance Visit</p> <p><b>5.0 Vendor SBs' &amp; SL's Accomplished</b></p> <p>5.1 BBJ-33-37 – De-activation of cargo compartment lights above the auxiliary fuel tanks – c/out law B3-33-37 (SB Closed)</p> <p>5.2 473957-26-436 – Cargo fire extinguisher modification c/out law B3-26-436 (SB Closed)</p> <p>5.3 ST00936NY-D-28-SB-029 – Aux fuel tanks-conversion from 7 cell to 5 cell config – c/out law B3-D-28-SB-029 (SB Closed)</p> <p>5.4 ST00936NY-28-SL-001 – Center wing tank refueling line B-nut torque c/out law B3-28SL001 (SL Closed)</p> <p><b>6.0 Other additional works/Checks Accomplished during lay-over</b></p> <p>6.1 Monthly 1 and 2 Checks performed ref Work orders 12612 and 12608</p>	
All Work Pack Processing has been completed & all Log Books have been updated, signed & stamped.		Name: K.H.Abdul Kader Signature: <i>K.H.Abdul Kader</i> Date: 01/11/2008 Authorisation Stamp: 

Form No. MP81 0707

Page 4 of 4

	<b>LOG BOOK MAINTENANCE ENTRY</b> Continuation page				A/C Regn.: A6-DFR W/P Ref.: 039405-WO 12079&12142 Date of CRS: 08 Sep 2008
	<p>ITEM The following additional maintenance has been carried out during this Maintenance Visit</p> <p>3.7 737-SL-27-182 – Elevator feel shift module fillet seal inspection c/out law SWCB73-27-017 (SL Closed)</p> <p>3.8 737-SL-78-053 – Thrust reverser blocker door wear pad separation c/out law SWCB73-78-004 (SL Closed)</p> <p>3.9 737-SL-78-052 – Thrust reverser aft web torque box cracking c/out law B73-78-052 (SL Closed)</p> <p>3.10 737-SL-53-076 – Fuselage – possible missing filler in main entry door upper sill at BS294.5 c/out law B3-SL-53-076 (SL Closed)</p> <p>3.11 737-SL-53-058 – Possible riding condition between fastener and rudder pedal shaft nut c/out law B3-SL-53-058 (SL Closed)</p> <p>3.12 737-SL-78-062 – AFT fairing rivet tails contacting hinge beam c/out law B3-78062 (SL Closed)</p> <p>3.13 737-SL-55-026 – Horizontal stabilizer and horizontal stab center section migrated bushing inspection c/out law B3-55026 (SL Closed)</p> <p><b>3.14 737-SL-55-019 – Vertical stabilizer rear spar shim migration – c/out law B3-55019 (SL Open)</b></p> <p>3.15 737-SL-55-027 – Horizontal stabilizer front spar terminal fitting bolts inspection and rework c/out law B3-55-027 (SL Closed)</p> <p>3.16 737-SL-53-072 – Possible excess thread protrusion on keel beam bolts c/out law B3-53072 (SL Closed)</p> <p>3.17 737-SL-53-071 – Fuselage skin wear damage from dorsal fin wear between BS 851.5 to 853.5 c/out law B3-53071 (SL Closed)</p> <p>3.18 737-SL-27-186 – Trailing edge flap handle hard to rotate – pulley and cable check c/out law B3-27186 (SL Closed)</p> <p>3.19 737-SL-27-171 – Elevator control cable inspection – insufficient clearance – c/out law B3-27171 (SL Closed)</p> <p>3.20 737-SL-27-154 – Elevator output torque tube control crank bearing c/out law B3-27154 (SL Open)</p> <p>3.21 737-SL-24-188 – Drain mast heater wire chafing c/out B3-24-188 (SL Closed)</p> <p>3.22 737-SL-26-048 – Cargo fire extinguisher – metering assy/drier disc rupture c/out law B3-26-048 (SL Closed)</p> <p>3.23 737-SL-29-091 – Methods to help reduce or eliminate preload when replacing fractured hyd press tube c/out law B3-29091 (SL Closed)</p> <p><b>4.0 Engine SB/SL Accomplished (eng s/n 889151 &amp; 888148)</b></p> <p>4.01 CFM56-7B-72-0586 – Introduction of a new fan blade platform design 340-001-816-0 c/out on both engines law B3-72-0586 (SB Closed)</p> <p>4.02 CFM56-7B-77-0005 – Eliminate chafing of Boeing ECS tube c/out on both engines law B3-77-0005 (SB Closed)</p>				
All Work Pack Processing has been completed & all Log Books have been updated, signed & stamped.		Name: K.H.Abdul Kader Signature: <i>K.H.Abdul Kader</i> Date: 01/11/2008 Authorisation Stamp: 			

Form No. MP81 0707

Page 3 of 4

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFROwner's Name AMIRI K.T.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying, Authority, Signature and Date
1	2	3	4	5	6
38	B3-116-09	INTRODUCTION OF NEW UAE NATIONAL EMBLEM EXTERIOR LIVERY DECAL.	116-09	-	REF W/O 12831 Dtd 16. SEP 08.
39	B3-28A 1201	FUEL PUMP CONTROL GROUND FAULT INTERRUPTER (GFI) RELAY INSTALLATION	ASB 737-28A1201	-	REF W/O 12582 Dtd 8.10.08.
40	B3-31-1380	CDS: INSTALLATION OF VERTICAL SITUATION DISPLAY FEATURE.	SB 737-31-1380	-	REF W/O 12879 Dtd 22/12/08.
41	B3-24-1875	EGPWC CHANGE	SB 737-34-1875	-	REF W/O 13077 Dtd 22/12/08.
42	B3-52029	CARGO DOOR SWITCH COVER IMPROVEMENT.	737-SL-52-029	-	REF W/O 12540 Dtd 23/12/08.
43	B3-27179	LF SLAT POSITION SENSOR INSTALLATION INSPECTION/CORRECTION.	737-SL-27-179	-	REF W/O 12536 Dtd 29/12/08.
44	SWCB73-29-008	ENH. STRUT HYDRAULIC FITTING - CHECK FOR LOOSE JAM NUT	737-SL-29-0856	-	(copy. Ref) W/O 12536 Dtd 29/12/08.
45	SWCB73-29-009	TITEFLEX DISCLOSURE IMPROPER HEAT TREAT ON HOSE B-NUTS	737-SL-29-087	-	W/O 12536 Dtd 29/12/08.
46	B3-53073	MISSING FILLET SEAL AT VACUUM WASTE SERVICE PANEL SUPPORT STR.	737-SL-53-073	-	REF W/O 13077 Dtd 02. DEC. 08.
47	SWCG 34-018	EGPWS- LOAD TERRAIN DATABASE 452 WITH ENVELOPE MODULATION DB 202	V/SB 965-1676-34-126	-	REF W/O 13077 Dtd 02. DEC. 08.
48	B3-28-072	WIRE BUNDLE W/126: POSSIBLE CHAFFING.	737-SL-28-072	-	REF W/O 13077 Dtd 02. DEC. 08.
49	B3-30A1057	WIND SHIELD WIPER MOTOR REPLACEMENT.	ASB 737-30A1057	-	REF W/O 12229 Dtd 11.01.09.
50	737-SL-71-054-A	ENH. FAN CASE BRKT IMPROVEMENT.	737-SL-71-054	-	REF W/O 13310 Dtd 19/02/09.

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFROwner's Name PRESIDENTIAL K.T.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying, Authority, Signature and Date
1	2	3	4	5	6
51	SWCB 73-2805	APU FUEL LINE SHROUD DRAIN MAST DAMAGE PROTECTION.	737-SL-28-063	-	REF W/O 13107 Dtd 19.02.09.
52	737-SL-71-054-A	ENH. FAN CASE BRACKET IMPROVEMENT.	737-SL-71-054	-	REF W/O 13058 AF 12 TR Dtd 22/12/09.
53	B3-GLU-920-3425	REDUCE OCCURANCE OF INCORRECT GPS DATE (SB NO. 26)	V/SB GLU-920-34-25.	-	REF W/O 13344 Dtd 26/12/09. AF 12 TR
54	B3-56-1016	FLT COMPARTMENT NUMBER 2 OPENABLE WINDOW HOLD OPEN LATCH ASSY INSPECTION/REPLACEMENT.	SB 737-56-1016	-	REF W/O 13328 AF 12 TR Dtd 04/03/09.
55	B3-24-1182	INSPECT & CHANGE WIRE BUNDLE TO PREVENT CONTACT WITH MAIN BATTERY CABLE.	SB 24-737-24-1182	-	
56	B3-27-1284	FLT. CONTROLS - ELEVATOR AND TAB - LEFT & RIGHT ELEVATOR TAB PUSHRODS REPLACEMENTS.	SB 737-27-1284	AD 2008-16-13	
57	B3-25-1607	EQUIP. FURNISHINGS - FLT. COMPARTMENT - WINDOW NUMBERS 2 AND 3 ROLLER SUNSHADES INSTALLATION.	SB 737-25-1607	-	C/OUT DURING A'CHK UNDER W.O. 13098
58	B3-32-1410	WLG. WIRE BUNDLE & HANGER LINK ASSY INSPECTION, REPAIR & MODIFICATION.	SB 737-32-1410	-	Dtd 05 MAR. 09. AF 12 TR
59	B3-54-1043	NACELLES PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING'S DRAIN TUBE ASSY REPLACEMENT.	SB 737-54-1043	AD 2008-08-24	
60	B3-26-1123	REPLACEMENT OF LEFT & RIGHT ENGINE CASE FIRE DETECTION HARNESSSES.	SB 737-26-1123	-	
61	B3-56-1024	WINDOWS - CONTROL CABIN SLIDING WINDOWS - LEFT SIDE AND RIGHT SIDE NUMBER 2 WINDOW FRAME REPAIR.	SB 737-56-1024	-	
62	B3-53-1264	INBRD FLAP PRIMARY TORQUE TUBE INSPECTION REPAIR AND AFT WING TO BODY FAIRING MODIFICATION.	SB 737-53-1264	-	
63	B3-53-084	EXTERNAL GND. POWER RECEPTACLE SKIN AND DOUBLER - PREVENTIVE MODIFICATION.	737-SL-53-084	-	

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL FLT.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
64	B3-55029	GAP BETWEEN DORSAL FIN AND VERTICAL STABILIZER	737-SL-55-029	-	
65	B3-52-045	FWD ENTRY DOOR GUIDE ARM RADIUS LINKS PIN SCREW.	737-SL-52-045	-	
66	B3-32086	LANDING GEAR RETRACTION DIFFICULTIES CAUSED BY MANUAL EXTENSION SYSTEM SWITCH.	737-SL-32-086	-	
67	B3-SL-29-102	STANDBY HYD. SYS. CASE DRAIN FILTER/CHK VALVE INSTALLATION.	737-SL-29-102	-	OUT DURING 'A'
68	B3-SL-53-088	POSSIBLE MISSING STIFFENER IN TRANSVERSE FLOOR BEAM AT BS 344 RBL 54.6.	737-SL-53-088	-	CHK UNDER W/O 13098 DTD
69	B3-35-SIL 69	OXYGEN-CREW OXYGEN MASK REGULATOR FULL FACE QUICK DONNING MASK REGULATOR REGULATOR.	SIL 69	-	05 MAR - 092
70	B3-25-131	EA-1 RACK SHROUD DRAIN TUBE INSPECTION.	737-SL-25-131	-	
71	B3-28060	SHORT SCREENS INSTALLED ON EMU FUEL SHUT OFF VALVE, CROSSFEED VALVE & DEFUEL VALVE.	737-SL-28-060	-	
72	B3-EB21-0193	ZONAL DRYING SYS. MODIFICATION/REACTIVATION AFTER AD NOTE.	EB 13737-EB21-0193	-	
73	B3-25-058AF	EQUIP FURNISHING - INSTALLATION OF FOLDABLE MEAL CART STOWAGE.	B3-25-058AF	-	
74	SWCG 34-019	EGPWS - LOAD TERRAIN DATABASE 453 WITH ENVELOPE MODULATION DATABASE 807	VISB 965-1676-34-126	-	REF W/O 13384 DTD 22/03/09
75	B3-62-1159	DOOR WARNING SYS - FWD ENTRY DOOR LATCH SWITCH & WARNING INSTALLATION & MODIFICATION.	SB 737-52-1159	-	REF W/O 13472 DTD 15/04/09
76	SWCB73-25-041	IFES SURVEY ACCESS	SWCB73-25-041	-	REF W/O 13474 DTD 15/04/09

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL FLT.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
77	SWCB73-25-042	EQUIP FURNISHING - SOUND INSULATION - TEMPORARY REMOVAL OF BT/01 SOUND INSULATION AT CONFERENCE/DINING ROOM.	SWCB73-25-042	-	REF W/O 13506 DTD 21/04/09
78	B3-34-1551	NAV. INSTALLATION OF AN ALTERNATE NAV SYS. & UPGRADE OF THE DATA LINK	SB 737-34-1551	-	REF W/O 13460 DTD 29/04/09
79	SWCG 24-026	EMI TESTING		-	REF W/O
80	B3-25-060AF/CAF	EQUIP FURNISHING - REPLACE EXISTING TEMP 2000 WITH TEMPUS 1C MODEL.	EO B3-25-060 AF	-	13510 DTD 03/05/09
81	B3-BBTELS 737-00-2-02	STRUCTURAL PROVISIONS INSTALLATION TO FACILITATE FITMENT OF 3D PN 2004.006/2 UNITS.	VISB BBTELS 737-00-2-02	-	OUT. REF W/O 13563 DTD 24/05/09
82	B3-52-1148	HORIZONTAL AIRSTAIRS MOISTURE SHROUD INSTALLATION - SUPPORT RAIL REPLACEMENT.	SB 737-52-1148	-	OUT. REF W/O 13588 DTD 25/05/09
83	SWCG 34-019	EGPWS - LOAD TERRAIN DATABASE 454 WITH ENVELOPE MODULATION DB 807.	VISB 965-1676-34-126	-	REF W/O 13703 DTD 01/07/09
84	B3-30-1058	ICE & RAIN PROTECTION: COIL CORD ASSY REPLACEMENT ON THE NO. 2 WINDOW IN THE KIT. COMPARTMENT.	SB 737-30-1058	-	
85	B3-28A1201	FUEL PUMP CONTROL GFI BONDING RESISTANCE CHECK.	ASB 737-28A1201	-	OUT DURING 'A' CHK DTD
86	B3-54-1045	NAVELLES/PYLONS - HEAT INSULATION BLANKETS - REPLACEMENT.	SB 737-54-1045	AD 2008-21-02	02 SEP 09 .AF
87	B3-53-091	EXCESSIVE SEALANT IN APV DOOR HINGE CORNERS	737-SL-53-091	-	W/O 13629
88	B3-33-053	ANTI-COLLISION LITE POWER SUPPLY & BRACKET - FATIUM SEAL APPLICATION	737-SL-33-053	-	
89	B3-53070	FUSELAGE - SECTION 41 DRAIN PATH PLUGGED.	737-SL-53-070	-	

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL FLT.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying, Authority, Signature and Date
1	2	3	4	5	6
90	B3-33-052	REFUELING PANEL FLOOD LIGHT INSTALLATION.	737-SL-33-052	-	
91	B3-24-193	ELECTRICAL BRACKET ASSY INSTALLED INCORRECTLY.	737-SL-24-193	-	C/OUT DURING
92	B3-33-050	SEALING OF TAIL CONE AND ANTI-COLLISION LIGHT INTERFACE.	737-SL-33-050	-	A CHK DTD 02 SEP 09 AF
93	B3-49-075	HIGH RESISTANCE ACROSS APU EXHAUST GROUND STRAP.	737-SL-49-075A	-	REF W/O 13629R 12
94	SNCRB-71-009	ENGINE LOWL ANTI-ICE DUCT BOLT RETENTION DISCREPANCY.	737-SL-71-059	-	
95	B3-53-084	EXTERNAL GROUND POWER RECEPTACLE SKIN AND DOOR - PRENT. MOD.	737-SL-53-084	-	REF W/O 139745R 12 TR
96	SWCG 34-019	EGPWS-LOAD TERRAIN DATABASE ASS WITH ENVELOPE MODULATION DATABASE B07	V/SB 965-1676-34-126	-	REF W/O 13987 Dtd 23/10/09.
97	737-31-1293	CDS - UPDATE PHASE 3 DU DATABASE INSTLN.	B3-31-1293	-	REF W/O 14220 DT. 24/12/09. AF 13 TR
98	737-SL-20-052.	WIRE BUNDLE SUPPORT BRKETS IN NOSE GEAR FIE BAY INCORRECTLY INSTALED.	B3-20052	-	REF W/O 14294 DT. 28/12/09. AF 13 TR
99	737-SL-21-079	EIE COOLING IN PS PNL - POTENTIAL WIRE CHAFING AGAINST NOSE CLAMP.	B3-21-079	-	
100	SWCG 34-019	EGPWS-LOAD TERRAIN DATABASE 456 WITH ENVELOPE MODULATION DB B07.	V/SB 965-1676-34-126	-	C/OUT. REF W/O 14305 Dtd 29.12.09 AF 12 TR
101	B3-25-063PF	EQUIP. FURNISHING - EMERGENCY-LIFE RAFT REPLACEMENT.	B3-25-063PF	-	REF W/O 14327 Dtd 31 DEC. 09 AF 12 TR
102	B3-27A1296	ELEVATOR TAB CONTROL MECH. DETAILED INSP.	SB 737-27A1296	-	C/OUT AT L3 REF W/O 14633 15/04/10. AF 12 TR

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL FLT.

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying, Authority, Signature and Date
1	2	3	4	5	6
103	B3-46-1010	CIS: INSTALLATION OF CLASS 3 EFB DUAL DISPLAY SYS.	SB 737-46-1010	-	C/OUT AT L3 Comm. REF W/O 14325 AF 12 TR
104	B3-EB23-1699	REPLACEMENT OF TW100 BY ATWSD LIVE TV SYSTEM.	EB 737-EB23-1699	-	Dtd 15/04/10. AF 12 TR
105	SWCG 34-019	MK VEGPWS-INSTALL. A TERRAIN DB & AN ENVELOPE MODULATION DB	V/SB 965-1676-34-126	-	C/OUT AT L3 REF W/O 14654 DTD 15/04/10. AF 12 TR
106	ST9766 SC-D	EQUIP. FURNISHING - MID CABIN RECON FIGURATION.	STC ST9766 SC-D	-	C/OUT AT L3 Comm. REF W/O 14654 DTD 15/04/10. AF 12 TR
107	B3-32-1410	WLG: WIRE BUNDLE & HANGER LINK ASSY INSP. REP & MODIFICATION.	SB 737-32-1410	-	
108	B3-53-1244	PASSENGER CABIN FLOORS - STA 520 TO 540 PIVOT LINK ASSY REPAIR/REPLACE.	SB 737-53-1244	-	
109	737-57-1295 MOD	WINGS - TRAILING EDGE & TRAILING EDGE DB 1165. WING INBD FIXED TO UPPER PANEL BULB SEAL CHAFING ON WTB PNL.	SB 737-57-1295	-	C/OUT AT AF 12 TR
110	B3-78-1074	THRUST REV. BLOCKER DOOR AERO/FIRE SEAL REPLACEMENT.	SB 737-78-1074	-	L3 Comm. REF W/O 13575
111	B3-52-1165	DOORS - AFT ENTRY & AFT GALLEY SVLDR DOOR SNUBBER STOP LINK ASSY CHNG.	SB 737-52-1165	-	Dtd 15/04/10.
112	B3-38-1053	DRAIN MAST - REPLACEMENT OF THE FWD DRAIN MAST ASSY.	SB 737-38-1053	-	- AF 12 TR
113	B3-53077	POSSIBLE DRILL START MARKS IN THE OUTBD EDGE OF THE FRAME WEB.	737-SL-53-077	-	
114	B3-B43570-1-35-001	EMERL. OXYGEN SYS. REPLACEMENT OF BURST DISC ON OXYGEN CYLINDER AND HAND VALVE ASSY.	V/SB 843570-1-35-001	-	C/OUT. REF W/O 14221 Dtd 21/04/10. AF 12 TR
115	B3-25-137	FLT. DECK SIDE GRILL MODIFICATION	737-SL-25-137	-	C/OUT. REF W/O 14699 Dtd 21/04/10. AF 12 TR

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL PRESIDENTIAL

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date	
1	2	3	4	5	6	
116	B3-32-164	LANDING GEAR ALTERNATE SWITCH ADJUSTMENT / REPLACEMENT.	737-SL-32-164	-	REF W/O 14733 Dtd 05/05/10	AF 12 TR
117	B3-30-105663	GRAY WATER COMPOSITE DRAIN MAST BONDING JUMPER INSTALLATION.	SB 737-30-1066	-	REF W/O 14412 Dtd 30/05/10.	AF 12 TR
118	B3-25-066 PF	EQUIP. FURNISHINGS - A6 DFR FWD LOUNGE DIVAN DAMPST FABRIC COVER REPLACEMENT WITH LEATHER.	EO IFRA	-	REF W/O 14928 Dtd 12/06/10. YMODEL ADAP INTO ROT/AGREF/OLO.	AF 12 TR
119	SWCB73-34-007	ATC / SATCOM: MODE 'S' CODE CHANGE.	SWCB	-	REF TO W/O	AF 12 TR
120	SWCB73-23-019	AIRSHOW GENE SYS: DATABASE UPDATE.	SWCB	-	14945 Dtd 17 JUN. 2010.	AF 12 TR
121	B3-21-083	PROTECTIVE CAPS NOT REMOVED FROM MIX MANIFOLD TEMP. SENSORS.	737-SL-21-083	-	REF W/O 14823 Dtd 25/06/10.	AF 13 TR
122	B3-33-1133	MIDST SUPPLY TEST GRD SIGNAL WIRING SEPERATION	737-SB-33-1133	-	SB C/OVT. REF W/O 14879 Dtd 25/06/10.	AF 13 TR
123	965-1676-34-126	MKV EGPWS - INSTALL A TERRAIN DATA BASE 458.	SWC63499	-	W/O 15019 DT. 31/06/10	AF 13 TR
124	B3-MOD 'C'	ADOPT EXISTING CMS/IFE TO TW 500 LIVE TV SYS.	VSB MOD C	(PARTIAL)	REF W/O 15090 Dtd 21/07/10.	AF 12 TR
125	B3-27-212	HORIZONTAL STABILIZER LIMIT AND WARNING SWITCH.	737-SL-27-212	-	REF W/O 15115 Dtd 14 AUG. 10	AF 12 TR
126	B3-MOD 'C'	ADOPT EXISTING CMS/IFE TO TW 500 LIVE TV SYSTEM	VSB MOD C	(PARTIAL)	REF W/O 15203 Dtd 18/09/10.	AF 12 TR
127	B3-57-1293	WINGS - LEADING EDGE AND LEADING EDGE DEVICES FUEL DRAIN PATH MOD.	SB 737-57-1293	-	REF W/O 15180 Dtd	AF 12 TR
128	B3-24-195	CB TERMINAL SCREWS INSPECTION AND REPLACEMENT.	737-SL-24-195	-	15/09/10.	AF 12 TR

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL LT. COPAIN. ROYAL JED

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date	
1	2	3	4	5	6	
129	B3-49-082	APU ECU: OPS S/WARE VER. 6.	737-SL-49-082	-	REF W/O 15180 Dtd 15 SEP. 10	AF 12 TR
130	B3-57093	SPAN CORROSION COMMON TO MAIN TANK B. PUMP BONDING JUMPERS	737-SL-57-093	-		AF 12 TR
131	932002-44-3	NPM+ SOFTWARE UPGRADE TO REV. K	V/SB 932002-44-3	-	REF W/O 15271 Dtd 08 OCT. 10.	AF 12 TR
132	B3-510936 NY. D. 28-SL 207	CARGO SMOKE DETECTION SYSTEM INSPECTION.	ST00936 NY. D-28-SL 007	-	REF W/O 15507 Dtd 09 NOV. 10.	AF 12 TR
133	ST01335 LA	REINFORCED COCKPIT DOOR INSTAL-LAZRAL	ST01335LA	-	REF W/O 15601 Dtd 26/11/10.	AF 12 TR
134	B3-34A224	FMC: OPS U10.8A SOFTWARE INSTALLATION	737-34A224	-	REF W/O 15318 Dtd 01/12/10.	AF 12 TR
135	SWC634-019	EGPWS - Load TERRAIN DATABASE 459 WITH ENVELOPE MODULATION DATABASE BA	965-1676-34-126	-	REF W/O 15680 Dtd 20/12/10.	AF 12 TR
136	B3-10032786	EQUIP/FURNISHINGS - A6-DFR MID CABIN RECONFIG. EASA STC TO CERTIFY AT FACING 3- SEAT DIVAN FOR TTL	STC 10032786	-	REF W/O 15745 Dtd 28/12/10.	AF 12 TR
137	B3-31-1449	INDICATING / RECORDING SYS - FOR SYS - GROUND WIRE CHANGE	737-31-1449	-	REF W/O 15718 Dtd 12/02/10.	AF 12 TR
138	B3-MOD-C	ADOPT EXISTING CMS/IFE TO TW 500 LIVE TV SYSTEM.	VSB MOD C	-	REF W/O 15389 Dtd 25 FEB 11	AF 12 TR
139	B3-SL-25-143	GRU EMT DEALS SWAPPED ON E1-5 SHELF FOR VHF #2 TRANSMITTER + DME #2 INTERMOD	737-SL-25-143	-	REF W/O 16026	AF 12 TR
140	B3-27-226	STICK SHAKER GROUND TERMINAL INST	737-SL-27-226	-	DATED 12 MAR 11	PF 12 TR

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date	
1	2	3	4	5	6	
141	B3-52-1164	DOORS - FWD & AFT CARGO DOORS - LANYARD ASSY REPLACEMENT	737-52-1164	-		
142	B3-52-25-144	ATTENDANT SERVICE UNIT - BXY DOOR PANEL ASSY DESIGN IMPROVEMENT	737-52-25-144	-	W/O 14 991	PF 14 TR
143	B3-27224	RUBBER PCU - DAMAGED SUMMING LEVER BOLTS.	737-52-27-224	-	DATED	
144	B3-34-198	NAV - CONVERSION OF MK V EGPWS P/N 965-1690X70 965-1690-055. UPDATE	737-52-34-198	-	18-03-2011	PF 14 TR
145	B3-Mod-C	ADOPT EXISTING CNS/IFE TOTW500 LIVE TV SW	Mod "C"	-	W/O 16098 DTD 20-05-11	PF 14 TR
146	SWC 634-07	EGPWS - LOAD TERRAIN DATABASE 460 WITH ENVELOPE MODULATION DATABASE 807	965-1676-34-07	-	W/O 16186 DTD 11 MAY 11	PF 14 TR
147	SWC 634-09	EGPWS - LOAD TERRAIN DATABASE 461 WITH ENVELOPE MOD. DATABASE 807.	965-1676-34-126	126	W/O 16537 D19 05-07-11	PF 14 TR
148	B3-22-061	F/O PITCH CONTROL WHEEL STEERING FORCE TRANSDUCER WIRE.	737-52-22-061	-	W/O 16618 Dtd 04 Aug 2011	PF 14 TR
149	SWC 34-019	EGPWS - TERRAIN DB VER. 462	965-1676-34-126	126	W/O 16889 Dtd 04-10-11	PF 14 TR
150	B3-11-1125	APPLICATION OF EXTERIOR DECORATIVE PAINT SYS ON LH & RH SIDE WINGS.	737-11-1125	-		
151	B3-25-1449	AFT CARGO COMPARTMENT - REPL INSULATION SUPPORT TRAYS.	737-25-1449	-	REF W/O 16115	PF 14 TR
152	B3-25-1612	EXIT/FURNISH - AUTOMATIC OVERWING EXIT DOOR SURROUND STRUCTURE - CHANGE UPPER LNR DOOR SILL.	737-25-1612	-	DTD 16 SEP 11	
153	B3-29-1272	ENG FUEL FEED - MAINTANKS ENG FUEL SPAR VLV BODY REPLACEMENT.	737-29-1272	-		

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date	
1	2	3	4	5	6	
154	B3-52-1152	FWD AIRSTAIR DOOR - REPL DOOR LOCK PIN ACTUATORS, OPEN LIMIT/WARN SWITCH BRACKETS & RACEWAY COVER ASSY.	737-52-1152	-		
155	B3-52-1156	FWD AIRSTAIR SPEEDUP & SLOW-DOWN SYS DELETION	737-52-1156	-		
156	B3-53-1252	STABILIZER CENTER SECT FRONT SPAR - SLIDING SEAL & TRACK MODN.	737-53-1252	-		
157	B3-53-1223	FUSELAGE - WHEEL WELL - HLB FARRING REPLACEMENT	737-53-1223	-		
158	B3-53-1276	FUSELAGE - FWD & AFT CARGO COMPARTMENT CORROSION PREVENTION MODN.	737-53-1276	-		
159	B3-53-1280	FUSELAGE - FILLET FAIRINGS - AFT OUT BOARD WING TO BODY FAIRING - LOWER CHASSI MODN.	737-53-1280	-	REF W/O 16115	PF 14 TR
160	B3-53-1285	PAX CABIN FLOORS - SEC 41447 - ADD W/UP GEL TAPES TO PREVENT CORROSION OF PAX CAB FLOOR INL SPT STRUCTURE	737-53-1285	-	DTD 16 SEP 11	
161	B3-36-1019	ENG BLEED AIR DIST SYS - CLAMP INSTN ON ENG SENSE TUBES FOR PNEUM SYS FLEX LINES (BOTH ENGS)	737-36-1019	-		
162	B3-55-1089	STAB - HORIZ STAB - TIE PANEL, CONDUCTIVE STRIP & TIP CAP ASSY - CHANGE	737-55-1089	-		
163	B3-57A1279	CENTER & OUTER WING - FASTENER SEPARING & WIRE BUNDLE SUPPORT GEN VIS ASP	737-57A1279	-		
164	B3-57A1302	WINGS - A/E SLATS - MAIN TRACK DOWN STOP MODN & DET INSP.	737-57A1302	-		
165	SWC 873-23-007	CABLES RTP P/N. 67404-124	737-52-23-037	-		
166	B3-23-041	VHF #2 ANTENNA CONNECTOR DISCONNECT	737-52-23-041	-		

## MODIFICATION AND REPAIR RECORD

Aircraft Registration N6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
167	83-24-181	VHF ANTENNA WIRE BUNDLE CHAFING AT STA 671 SPOILER C/L QUADRANT	737-SL-24-181	-	
168	83-24-192	W10221 W1032 WIRE BUNDLE CHAFING NEAR FLAP TRACK BEAM.	737-SL-24-192	-	
169	83-26-049	IMPROPERLY TORQUED APU LOWER FIRE DETECTOR SENSOR.	737-SL-26-049	-	
170	83-27-209	ELEV POSN SENSOR INSTALLATION IMPROPER FASTENER TORQUE	737-SL-27-209	-	
171	83-27-230	HORIZ STAB LIMIT SWITCH INSTALLATION	737-SL-27-230	-	
172	83-28-074	CENTER TANK REFUEL TUBE LOCATED IN THE RIGHT WING PN:344A 202-B MAY BE INSTD BACKWARD.	737-SL-28-074	-	REF W/O 1615
173	83-29-104	EXCESS SLACK IN WIRE W8538 CAUSING CHAFING AGAINST FAIRING PANEL	737-SL-29-104	-	DTD 16 SEP 11
174	83-31-057	HORIZ STAB TAKE OFF WARNING SWITCH INSTALLATION	737-SL-31-057	-	
175	83-32-091	NOSE GEAR FLEX CONDUIT	737-SL-32-091	-	
176	83-32110	NLG STARRING - INTERCONNECT-EXCESSIVE GAP BET CABLE QUADRANT & CABLE REAPER PH	737-SL-32-110	-	
177	83-32168	POTENTIALLY INCORRECT MLO AXLE INSTALLATION	737-SL-32-168	-	
178	83-32167	POTENTIALLY INCORRECT M10 LOWER TORSION LINK INSTALLATION.	737-SL-32-167	-	
179	737-SL-49-079	GAP IN APU INSULATION BLANKET	737-SL-49-079	-	

## MODIFICATION AND REPAIR RECORD

Aircraft Registration N6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
180	83-51040	POSSIBLE CORROSION ON THE EMERG E/E HATCH UPPER SILL.	737-SL-51-040	-	
181	83-52042	MLO DOOR, BULB SEAL ATTACHMENT	737-SL-52-042	-	
182	83-53079	BOOTS INSTALLED WITH GAPS, MISSING WASHERS & INCORRECT NUTS 4785727 ATSMR 4-3-96	737-SL-53-079	-	
183	83-53-080	POSS. DAMAGED HI-LOCKS IN MAIN ENTRY DOOR UPPER SILL AT BS 302-90.	737-SL-53-080	-	
184	83-53082	TOOL MARK COMMON TO THE LWR IN/BD EDGE OF STRAP AT STRINGER PA	737-SL-53-082	-	
185	83-53-095	POSS MISSING FASTENERS FM A GUSSET ASSY + ANGLE ASSY AT FWD IN/BD CORNER OF WALL SURROUNDING WASTE TANK - AT (CARGO)	737-SL-53-095	-	REF W/O 1615
186	83-53-085	MISSING & MISLOCATED FASTENERS IN SEC 48 SKIN ASSY AT APPROX STA 1086, S-201L & S-201R.	737-SL-53-085	-	DTD 16 SEP 11
187	83-57-088	SLAT TIE WEDGE WEAR	737-SL-57-088	-	
188	83-57-095	MID SPAN FIXED TIE TURNBUCKLE CLEVIS INSTALLATION	737-SL-57-095	-	
189	83-71-058	POWER FEEDER WIRE BUNDLE CHAFED AGAINST FAN COWL HINGE BRACKET	737-SL-71-058	-	
190	83-76021	AUTO THROTTLE SWITCH PACK WIRE REROUTING	737-SL-76-021	-	
191	SNX 873-32-001	BATTERY PACK LABEL REPLACEMENT	SL777-01	-	
192	SNX 873-78-006	TIR BLOCKER DOOR SUPPORT SEPERATION	737-SL-78-048	-	

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJR

Owner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
193	B3-25-07	EGPT/FURNISHINGS - FLT COMPT SEATS - CHANGE TO COMPT 1/0 SEATS TRIGGER SPRING	V88		W/O 1673 DTD 16 SEPT 11
194	SWC 34-019	EGPWS - TERRAIN DATABASE VER 463 9 ENVELOPE MODULATION DB 307-	V88		W/O 17210 Dtd 2/1/14
195	B3-Mod-C	ADOPT EXISTING CWS/IFE TO TW 500 LIVE TV SYS.	965-1676-34	126	W/O 16651 DTD 17/02/12
196	B3-25-1493	INSULATION BLANKET - MOISTURE REDUCTION OF INSULATION BLANKETS AT THE AUTOMATIC OVERWING EXIT DOORS	Mod "C"	-	W/O 16651 DTD 17/02/12
197	B3-30-1058	ICE & RAIN PROTECTION: COIL CORD ASSY. REFL ON THE #3 WINDOW IN THE FLT COMPART	737-25-493		
198	B3-34-2320	NAV-GPWS - INSTALLATION OF RUNWAY AWARENESS & ADVISORY SYS.	737-30-1058		
199	737-78-1082	INSTN OF A COOLING HOLE & BUSHING, RAINY SEALANT & INSTALL FLANGE INSULATION ABOVE THE TIRE REVERSERS.	737-34-2320		W/O 17373
200	B3-2910	POTENTIAL INSUFFICIENT CLEARANCE BETWEEN HYD TUBE & FILTER MODULE	737-78-1082		DATED 20/02/12
201	B3-24-200	FIRE PNL WIRE INSTALLATION	737-SL-29-113		
202	B3-32135	SHIMMY DAMPER MOUNTING BOLTS - GRIP LENGTH	737-SL-24-200		
203	B3-22-1013	YAW DAMPER: DELETION OF YAW DAMPER INDICATOR.	737-SL-32-135		W/O 17256 DTD 17-02-12
204	B3-24-1176	AC GENERATION SYS: RE PIN WIRES AT TWO LINES-98-START ELECTRICAL CONNECTS AT WHICH ONE START CABLET.	737-22-1013		W/O 17508
205	B3-29-1111	HYD SYS AT B ONE DRIVEN PUMP - SUPPORT BAKT CHANGE FOR THE HYD PRESS HSG	737-24-1176		DTD
			737-29-1111		10 AUG 2012

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJR

Owner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
206	B3-57-1306 Mod	WINGS - TIE FLAPS - INBD FLAPS - INBD MAIN FLAP TRACKS # 175 EXCH PROGRAM	737-57-1306 Mod		
207	B3-53-098	AIR STAIR DOOR JUMPER POSSIBLY INSTLD INCORRECTLY	737-SL-53-098		W/O 17508
208	B3-57-299	VISUAL AIDS FOR VINYL CRACKS WITHIN NO. 222 FIT BECK WINDOWS	737-SL		DTD 10 AUG 2012
208	B3-57-099	WING W/E - SLAT DETENT ARM & ROLLER ALIGNMENT.	737-SL-57-099		
209	B3-78-1085	T/R SYS - CHANGE TO THE INSULATION BLANKET ON THE T/R (RH & LH HALF)	737-78-1085		W/O 17218 DTD 10 AUG 12
210	737-78-1088	T/R INNER WALL INSP & REPAIR	737-78-1088		W/O 17759 DTD 18 AUG 12
211	SWC 34-019	EGPWS - TERRAIN DATABASE VER 467 & ENVELOPE MODULATION D/B B07	965-1676-34-126		W/O 18508 DTD 18/12/12
212	B3-78-069	T/R LATCH BEAM FAIRING MISSING SEALANT	737-SL-78-069		W/O 18670 DTD 02 FEB 13
213	SWC 34-019	EGPWS - TERRAIN D/BASE VER 468 & ENVELOPE MODULATION D/BASE B07.	965-1676-34-126		W/O 19119 DTD 30 05 13
214	B3-26-1121	FIRE PROTECTION - LWR CARGO - COMPT SMOKE DETECTION - INSTALLATION OF	737-26-1121		
215	B3-34-2411	NAV - FLT COMPARTMENT COMPUTER SYS - INSTLN OF THE FUTURE AIR	737-34-2411		W/O 18966
216	B3-32188	SHIMMY DAMPER COMPENSATOR MOUNTING BOLTS	737-SL-32-188		DTD 6/6/13
217	737-SL-49-092	APU COMBUSTOR DRAIN ADAPTER TORQUE	737-SL-49-092		

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
218	B3-57 ADDN	WINGS - L/E + R/E DEVICES - FUEL DRAIN PATH	737-57-1293		19998 W/O DTD 23-09-13
219	SWC G34-019	EGPWS - TERRAIN D/BASE INSTLN	965-1676-34-126		W/O 19633 DTD 09-10-13
220	B3-34- 2461	NAV-AIS SYS - ROCKWELL COLLINS ATC REPL.	737-34-2461		19805 DTD 14-11-13
221	B3-30 1058	ICE + RAIN PROTECTION: COIL COAD ASSY. RPLCT ON #2 WINDOW IN FLT COMPARTMENT	737-30-1058		
222	737-71- 1608	INSPN + REPAIR OF THE ENG BUILDUP BRKTS TO PREVENT DAMAGE TO ENG FAN CASE.	737-71-1608		
223	B3-32- 176	MLG - UPPER TORSION LINK PIN INSPN	737-51-32-176		W/O 19804
224	B3-33- 064	LWR ANTI-COLLISION LIGHT CABLE CHAFING	737-51-33-064		DTD 4/2/14
225	B3-49 086	APU OIL DRAIN TUBE MISALIGNMENT CAUSING EXTERNAL OIL STREAKING	737-51-49-086		
226	B3-31- 1471	CDS - INSTALLATION OF PHASE 3A DISPLAY UNIT + D/BASE SOFTWARE	737-31-1471		W/O 20138 DTD 01-03-14
227	SWCG 34-019	MKV EGPWS: INSTALL A TERRAIN D/BASE + AN ENVELOPE MODULATION D/BASE OF	965-1676-34-126		W/O 20278 DTD 05-03-14
228	B3-34- 2406	REPLACEMENT OF THE TRAFFIC ALERT + COLLISION AVOIDANCE SYS COMPUTER.	737-34-2406		W/O 20359 DTD 26 MAR 14
229	B3-54- 1041	INSTLN OF NEW ENGINE STRUT AFT FAIRING SEALS.	737-54-1041		W/O 16115 DTD 05-09-11
230	B3-21- 1165	AIR COND - CABIN PRESS AND WARN SYS - REDUANT PRESS SWITCH INSTLN	737-21-1165		W/O 20202 08-08-14

## MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
231	B3-22A 1215	AUTO FLT - AUTO THROTTLE SYS - AUTO- THROTTLE COMPUTER REPLACEMENT	737-22A1215		
232	B3-25- 1660	ERPT/FURNISHINGS - ELECTRICAL ERPT RACK MOISTURE SHROUD - CHANGE	737-25-1660		
233	B3-26- 1131	FIRE PROTECTION - W/JELL, WING + LWR AFT BODY O/H DETECT SYS - DUCT LEAK O/H DETECTION	737-26-1131		
234	B3-33- 1146	STROBE POSN LIGHTS - LIGHTNING PROTECTION OF THE TAIL STROBE LIGHT SYS WIRING	737-33-1146		
235	B3-34- 2395	LOW RANGE RADIO ALTIMETER - INSTLN OF THE ANTENNA GASKETS	737-34-2395		W/O 20202
236	B3-53- 1307 INSPN	FILLET FAIRINGS - AFT WING TO BODY FAIRING - PNL 194E + AFT CENTER LINE W/L THE 192B - INSPN.	737-53-1307 INSPN		DTD 08-08-14
237	B3-53- 1326	FUSELAGE - CARGO COMPARTMENT SIDEWALL LININGS - INSPN + REPAIR	737-53-1326		
238	B3-53- 1341	MISC EXTERIOR SERVICE DOORS - EXTERNAL AIR RECEPTACLE DOOR - BONDING JUMPER	737-53-1341		
239	B3-57- 1316	INSTLN OF POLYURETHANE PROTECTIVE TAPE ON LWR SKIN SURFACE OF INAD GRND SPOLER	737-57-1316		
240	737-78- 1087	THRUST REV SYS - RPLCT OF LOCKOUT HANDLE ASSY ON THE THRUST REVERSER	737-78-1087		
241	737-78- 1090	TIR SYS - INSPN FOR + RML OF THE TIR INNER WALL COOLING HOLE BLOCKAGE.	737-78-1090		
242	737-51- 28-096	ENG FUEL SHUT OFF VLV WIRE CHAFING	737-51-28-096		
243	B3-35- 027	CREW OXY - FLEX HOSE + WIRE BUNDLE INSTLN	737-51-35-027		

**MODIFICATION AND REPAIR RECORD**

Aircraft Registration A6-DFR  
 Owner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying, Authority, Signature and Date
244	83-36025	PRE-COOLER CTRL VALV KISS SEAL IMPROVMT	737-SL-36-025		
245	83-53-082	POSSIBLE GAP COMMON TO THE BODY STATION 203 WATER LINE 234 FAIRING CHORD SPACE STRUCTURE	737-SL-53-082		
246	83-57-106	LH+RH WING NACELLE SUPPORT-OVTRD SIDELOAD BACKUP FITTING - MISSING FIALET SEAL	737-SL-57-106		W/O 20202
247	83-57-109	RESTORATION OF ANTI-STATIC COATING COMMON TO THE AILERON FAIRINGS	737-SL-57-109		DD 08-08-14
248	737-SL-78-076	THRUST REVERSE BLOCKER DOOR SUPPORT LOOSE OR MISSING SCREWS	737-SL-78-076		
249	737-SL-23-048	POSSIBLE INCORRECT ORIENTATION OF CRD CREW HORN.	737-SL-23-048		W/O 21016 DD 18 OCT 14
250	SWC 34-019	ATERRAIN DATABASE VER 473+ ENVELOPE MODULATION DATABASE 807	915-1476-34-126 187-56		W/O 21182 DD 30 OCT 14
251	737-24-120S	Electrical Power - Standby Power Sys Replacement of M9 Static Inverter	737-24-120S		W/O 21074 Feb 2015
252	737-26-1131	Fire protection - wheel well etc Refer CRS	737-26-1131		W/O 21074 Feb 2015

ROYAL JET  
 PLO4  
 08/14/2015

**MODIFICATION AND REPAIR RECORD**

Aircraft Registration .....  
 Owner's Name .....

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair
253		<b>LOG BOOK MAINTENANCE</b>
	A/C TYPE	MSN / Prod. No / LINE No
	8737 700	30884
	ENG TYPE	INSTL PSN
	CFM56-7B27/B3	1
		2
	APU TYPE	SERIAL NUMBER
	3800702-1	P-5505
	FLIGHT HOURS	TSN
	5784 30 00	1623 55
		5784 3
	TSN	
		11590.7
	ITEM	
	A Following Directive's	
	1 737-21-1177 - AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM - CHANGE OF THE POW BREAKER	
	2 737-23-1477 - COMMUNICATIONS - VHF TRANSMITTER AND RADIO TUNING PANELS REPLACEMENT	
	3 737-23-1479 - COMMUNICATIONS - ACARS - CMU DATA LINK RECORDING INSTALLATION AND C	
	4 737-23-1482 - COMMUNICATIONS - ACARS - REPLACEMENT OF CMU AIRINC 758 SINGLE ROCKW	
	5 2006-21-01 LUBE - ALLERON BALANCE TAB HINGE BEARINGS AND ROD END BEARINGS LUBRICA	
	6 737-27-1289 - STABILIZER TAKEOFF WARNING SWITCHES - TEST OF THE TAKEOFF WARNING IND	
	7 737-27A1277 - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND NUT INSPE	
	8 737-28-1334 - FUEL - ENGINE FUEL SHUTOFF SPAR VALVE ACTUATOR REPLACEMENT	
	9 737-28A1206 - CWT BOOST PUMP AUTO SHUT OFF AND MASTER CAUTION LOGIC CHANGE	
	10 737-28A1246 - CWT FUEL PUMP - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED F	
	11 737-30-1076 - ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION I	
	12 737-32-1342 - STEERING - INSP & MODIFICATION TO THE NO.6 STEERING COLLAR AND STEERING	
	13 737-32-1448 INSP - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INT	
	14 737-54-1043 - NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASS	
	15 737-54-1043 - NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRING DRAIN TUBE ASS	
	16 737-55-1074 - INSP & REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZ STAB AND TH	
	17 JBSI M-0040580 - ACARS TO SATCOM INTERFACE MODIFICATION	
	18 CFM56-7B-72-0909 - FAN AND BOOSTER ASSEMBLY - INTRODUCTION OF A NEW FAN BLADE PLATFORM	
	19 2015-08-07 - OXYGEN SYSTEM - FLIGHT CREW OXYGEN MASK REGULATOR INFLATABLE	

All Work Pack processing has been completed & all Log Books have been updated, signed & stamped.  
 Name: Muhammad Adeel  
 Signature: [Signature]  
 Date: 10-Sep-15  
 Authority: PLO4  
 Issue Date: 08.07.2014

TURKISH AIRLINES TECHNIC INC.  
 Sabiha Gökçen International Airport, Pendik  
 34912 Istanbul, TURKEY  
 Approval Ref: UAE-145.1051

**AIRCRAFT RELEASE TO SERVICE CERTIFICATE**

A/C Registration: **A6-DFR**  
 Operator Name: **ROYAL JET**  
 A/C Manufacturer and Type: **B737-700**  
 Date: **30.07.2015** 00:00  
 Start: **22.08.2015** 20:20  
 Finish: **22.08.2015** 20:20

Serial Number	Engine 1	Engine 2	Engine 3	Engine 4	APU
30884	876170	889151			P-5505
Flight Hour	5784:30	1623:55	5784:30		11590.7
Cycle	2070	493	2070		7113

Approved Maintenance Program: **MP-AMP-737**  
 Rev: **03**  
 Date: **01.09.2014**

Work Order Number: **1380755**  
 Corresponding Maintenance: **PERFORM A + OOP CHECK & MODS (705...**

Deferred Maintenance Task Cards	Number	Work Order Number
	141-163-164	70533

Deferred Non-Routine Work Items	Number	Work Order Number
	16-41-43-44	70534

\*Certifies that the work specified except as otherwise indicated was carried out in accordance with CAR 145 and in respect to that work the aircraft/aircraft component is considered fit for release to service\*  
 Certifying Staff: [Signature]  
 Authorization Number: **2729**  
 Name Surname: **IDRIS TUFAN**  
 Shop: **BASE MAINTENANCE**  
 Location: **IST**  
 Stamp and Signature: [Stamp]

