

---

**From:** Larry Visoski <[REDACTED]>  
**Sent:** Sunday, December 30, 2012 11:54 AM  
**To:** Jeffrey Epstein  
**Subject:** B727 AIRSTAIRS update items

Jeffrey,

-I have been routinely operating the fwd airstairs, yesterday I lubricated the stairs and operational checks were good.  
-Installed new speed switch on APU, and ops checked good, however the real test is after cold soaking flight if APU will start. Location of speed switch is totally exposed in L/H wheel well. appeared to be original part installed.  
-I also did cockpit checks and ran engines yesterday on Boeing, Capt FMS control head powered up for 4 min, then went blank and appeared to have shut down, I reset system by pulling circuit breaker, and unit came on line for 2 min, then shut down. I swapped Captains side with co pilots side and problem followed, I will locate exchange or rental unit and install. very simple to replace.

just update,

I will be on LSJ on the 9am boat run this morning.

thank you,  
Larry

Sent from my iPad?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">

```
<plist version=.0">
<dict>
  <key>conversation-id</key>
  <integer>240462</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1356868424</integer>
  <key>flags</key>
  <integer>8623750145</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>6</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>266716</string>
</dict>
</plist>
```