

From: Larry Visoski <[REDACTED]>
To: Je vacation <[REDACTED]>, [REDACTED]>
Cc: Rich Kahn <[REDACTED]>
Subject: GIV update
Date: Thu, 24 Mar 2016 13:21:02 +0000

Jeffrey,
Elevator flight control cable was changed due to ware.
While doing flight control checks, Gulfstream mechanic noticed a clicking sound in control yoke, while rotating aileron yoke.

They removed the Yoke from cockpit, replacing nut plate under floor board in cockpit, time consuming,. Better update on delivery status later today.,Dave and I plan to arrive at Westfield at noon tomorrow.

Thx

Larry

Pete and Larry,

Aircraft is still in tail dock. Wing leak checks ongoing as some panels have leaked and require corrective action.

O2 bottles installed and leak checked.

We have run into some challenge's with the yoke repair/installation. This is pushing our time frame back. We will access any revision to delivery later today as work progresses and we can make an accurate estimate.

Thank You,
Mike Tucker



Sent from my iPhone