

From: ZM <[REDACTED]>
To: "jeffrey E." <jeevacation@gmail.com>
Cc: Richard Kahn <[REDACTED]>, ann rodriguez <[REDACTED]>
Subject: Re:
Date: Tue, 14 Mar 2017 19:32:41 +0000

No to water Softener
Yes to new HP Pump
Yes to reprogramming PLC

Incorrect backwashing procedure and no pre treatment have fouled membranes and damaged HP Pump
Post treatment of water needs to be calibrated i.e. Sulphuric acid and Calcium carbonate injection

Patrick believes the product water is High in ph, but low alkalinity and is ionically imbalanced and could be eating away Cistern Walls, hence white residue on fixtures

Once Plant is back online after service flush entire system could be 3 to 4 days

Take new water samples at RO Product ,cistern and main compound and send state side Lab

Establish a 1/4 maintenance program

Sent from my iPhone

On Mar 14, 2017, at 12:57 PM, jeffrey E. <jeevacation@gmail.com> wrote:

Patrick advice guides ro

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved