

From: Larry Visoski <[REDACTED]>
To: Je vacation <jeevacation@gmail.com>
Subject: Fwd: Scan from Meridian Jet Center
Date: Mon, 02 May 2016 18:49:43 +0000
Attachments: img-502135453-0001.pdf

Jeffrey
Pete informs that zero or lower voltage may only be seen with Takeoff power,
Since that is hottest air going thru Precooler,

Sent from my iPhone

Begin forwarded message:

From: Pete Rawson <[REDACTED]>
Date: May 2, 2016 at 2:02:45 PM AST
To: "[REDACTED]" <[REDACTED]>
Subject: FW: Scan from Meridian Jet Center

Hi Larry,
Here are the readings that I got after the fan air valve swap.
These are before the filter unit changes.

We only went to 90%, and didn't wait for a response.
I'm sure that the readings would have changed if we waited.

I'll talk to Gulfstream tomorrow.

Regards,
Pete

-----Original Message-----

From: Meridian Jet Center [<mailto:jetmaintenance@meridian.aero>]
Sent: Monday, May 02, 2016 1:55 PM
To: Pete Rawson <[REDACTED]>
Subject: Scan from Meridian Jet Center

Please open the attached document. It was scanned and sent to you from Meridian Jet Center.

Number of Images: 2
Attachment File Type: PDF

Device Name: Meridian Jet Center
Device Location:

For more information, please visit <http://www.meridian.aero/>

