

From: Daphne Wallace <[REDACTED]>
To: Jeffrey Epstein <jeevacation@gmail.com>
Cc: Gary Kerney <[REDACTED]>, [REDACTED] <[REDACTED]>, [REDACTED] <[REDACTED]>
Subject: Photographs - March 2, 2011 - 1 of 2
Date: Wed, 02 Mar 2011 22:13:40 +0000

Attachments: Little_office.JPG; Little_office_(2).JPG; Little_office_(3).JPG; Little_office_(4).JPG;
Living_room.JPG; Living_room_(2).JPG; Living_room_(3).JPG; Living_room_(4).JPG;
Living_room_(5).JPG; Living_room_(6).JPG; Living_room_(7).JPG; Living_room_(8).JPG;
Pebble_beach_stonework.JPG; Pebble_beach_stonework_(2).JPG;
Pebble_beach_stonework_(3).JPG; Pebble_beach_stonework_(4).JPG; Flagpole_pool.JPG;
Flagpole_pool_(2).JPG; Flagpole_pool_(3).JPG; Flagpole_pool_(4).JPG;
Pool_main_compound.JPG; Landscaping_along_steps_to_master.JPG;
Landscaping_behind_master.JPG; Landscaping_behind_master_(2).JPG;
Landscaping_behind_master_(3).JPG; Landscaping_behind_master_(4).JPG;
Landscaping_behind_master_(5).JPG; Stonework_on_road_above_gym.JPG;
Stonework_on_road_above_gym_(2).JPG; Stonework_at_entry.JPG;
Master_bath_floor.JPG; Master_bath_floor_(2).JPG; Master_bath_floor_(3).JPG;
Master_bath_floor_(4).JPG; Master_closet_floor.JPG; Master_hallway_floor.JPG;
Water_closet_floor.JPG; Wardrobe_area_floor.JPG; Wardrobe_area_floor_(2).JPG;
Wardrobe_area_floor_(3).JPG; Vestibule_floor.JPG; Master_bedroom_floor.JPG;
Master_bedroom_floor_(2).JPG; Master_bedroom_floor_(3).JPG; Nanna_windows.JPG;
Nanna_windows_(2).JPG; Nanna_windows_(3).JPG; Nanna_windows_(4).JPG;
Nanna_windows_(5).JPG

Greetings Mr. Epstein,

March 2 photographs for your review and comments:

Little office
Living room - floor sanding and repair, corner tiling, electrical relocation
Pebble beach stonework - Gary wants to know if the window is the right size
Flagpole Pool
Pool main compound
Landscaping along steps to master and behind master
Stonework on road above gym progress
Stonework on side of entry (wall completed)
Floors of master bath, closet, hallway and water closet - third and final coat of varnish applied
Floors of master wardrobe area, vestibule and bedroom - first coat of varnish applied
Nanna windows

I will send part two shortly.

Respectfully submitted,

Daphne