

From: Eric Roth <[REDACTED]>
To: 'Jeffrey Epstein' <jeevacation@gmail.com>
Cc: 'Larry Visoski' <[REDACTED]>

Subject: Seat switches for R/H #2 and L/H #2

Date: Mon, 14 Oct 2013 15:53:00 +0000

Attachments: photo.JPG

Good morning Jeffrey,

The switches are all wired correctly.

I believe your discontent is that the switches are not produced / nomenclature as "right hand" or "left hand" and are simply produced as one type.

The attached photo is the switch at your seat (R/H #2).

If you would like for us to rewire these switches, it will take the better part of a day as they need to be disassembled, and rewired. Please note that if you do so, the nomenclature will not coordinate (I know you probably do not care because it's very challenging to read - especially if you are sitting in the chair).

Lastly, I am preparing the final invoice which will include some additional costs (camera, etc....). I have been extremely generous with you on this aircraft.

Please provide me with direction.

Thank you.

Eric

ERIC H. ROTH | PRESIDENT

P [REDACTED] | C [REDACTED] | [REDACTED] | [REDACTED]

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York
11779

-----Original Message-----

From: Eric Roth [mailto:[REDACTED]]
Sent: Monday, October 14, 2013 11:45 AM
To: 1- Eric H. Roth

Subject: