

From: [REDACTED] <[REDACTED]>
To: Zorro Ranch <[REDACTED]>
Cc: "jeffrey E." <jeevacation@gmail.com>, Rich Kahn <[REDACTED]>
Subject: ZM HWR Air Pro
Date: Tue, 18 Dec 2018 20:35:07 +0000
Attachments: ZM_Air_Pro_HWR_Repair.pdf; IMG-0863.JPG; IMG-0862.JPG; IMG-0860.JPG; IMG-0861.JPG; IMG-0859.JPG; IMG-0864.JPG

Afternoon

FYI

Attached invoice for payment and photo's to support work performed

The HWR line going to Mech Bay 1 in the Main house at Zorro developed leak
This was due to the line rubbing against the concrete bore hole accessing the basement
The other lines for CTW, CWS, HWS are all in good condition, this seems to be a one off situation
The Repaired Line has been Insulated, Dirt and Landscape Material has been replaced
For the Record, the HVAC system can not operate independently of the Hot Loop in the Winter. There is a requirement for hot water to mix with the Cold Water Supply to be able to operate the Heat Pumps as a heat source. Loop Temps can get into the Low Teens without a heat source.

[REDACTED] can you please process for approval and payment

any concerns let me know

thank you

[REDACTED]
Stanley, NM

LSJ-GSJ, USVI

Ph: ([REDACTED])