

139 Fulton Street | Suite 907 | New York, NY 10038
Mobile | [REDACTED]
www.GRANTpllc.com

From: Doug Arnaudin <[REDACTED]>
Sent: Friday, May 25, 2018 8:47 AM
To: imato [REDACTED] <[REDACTED]>
Subject: FW: 19 West 31 St - NCR #8

Please see the below additional note.

Thanks Imela,

Doug Arnaudin
Mitchell Holdings LLC
745 Fifth Avenue, 5th Floor
New York, NY 10151

[REDACTED]
[REDACTED]

From: Scott Yi [REDACTED]
Sent: Friday, May 25, 2018 8:43 AM
To: Wiktor Wasilewski
Cc: Doug Arnaudin; [REDACTED]
Subject: Re: 19 West 31 St - NCR #8

Doug,

In addition to Wiktor's email, the photo that Grant took clearly shows that the existing condition was not filled with grout. If it was filled then we had to use grout but it was not the case. That's why it is structural sound.

I hope this helps to close the NCR.

Thanks

EFTA01049073

On Fri, May 25, 2018, 8:32 AM Wiktor Wasilewski <[REDACTED]> wrote:

Doug,

The field condition is acceptable.

Best,

Wiktor Wasilewski

On Thu, May 24, 2018 at 5:05 PM, Doug Arnaudin <[REDACTED]> wrote:

Hi Wiktor, per our call earlier, I am following up on NCR #8.

Thanks again,

Doug Arnaudin

Mitchell Holdings LLC

[745 Fifth Avenue, 5th Floor](#)

[New York, NY 10151](#)

[REDACTED]

[REDACTED]