

From: Daphne Wallace <[REDACTED]>

To: Jeffrey Epstein <jeevacation@gmail.com>

Cc: Gary Kerney <[REDACTED]>, Brice Gordon <[REDACTED]>, Sarah K <[REDACTED]>

Subject: Photographs - March 2, 2011 - 1 of 2

Date: Wed, 02 Mar 2011 22:13:40 +0000

Attachments: Little_office.JPG; Little_office_(2).JPG; Little_office_(3).JPG; Little_office_(4).JPG; Living_room.JPG; Living_room_(2).JPG; Living_room_(3).JPG; Living_room_(4).JPG; Living_room_(5).JPG; Living_room_(6).JPG; Living_room_(7).JPG; Living_room_(8).JPG; Pebble_beach_stonework.JPG; Pebble_beach_stonework_(2).JPG; Pebble_beach_stonework_(3).JPG; Pebble_beach_stonework_(4).JPG; Flagpole_pool.JPG; Flagpole_pool_(2).JPG; Flagpole_pool_(3).JPG; Flagpole_pool_(4).JPG; Pool_main_compound.JPG; Landscaping_along_steps_to_master.JPG; Landscaping_behind_master.JPG; Landscaping_behind_master_(2).JPG; Landscaping_behind_master_(3).JPG; Landscaping_behind_master_(4).JPG; Landscaping_behind_master_(5).JPG; Stonework_on_road_above_gym.JPG; Stonework_on_road_above_gym_(2).JPG; Stonework_at_entry.JPG; Master_bath_floor.JPG; Master_bath_floor_(2).JPG; Master_bath_floor_(3).JPG; Master_bath_floor_(4).JPG; Master_closet_floor.JPG; Master_hallway_floor.JPG; Water_closet_floor.JPG; Wardrobe_area_floor.JPG; Wardrobe_area_floor_(2).JPG; Wardrobe_area_floor_(3).JPG; Vestibule_floor.JPG; Master_bedroom_floor.JPG; Master_bedroom_floor_(2).JPG; Master_bedroom_floor_(3).JPG; Nanna_windows.JPG; Nanna_windows_(2).JPG; Nanna_windows_(3).JPG; Nanna_windows_(4).JPG; Nanna_windows_(5).JPG

Greetings Mr. Epstein,

March 2 photographs for your review and comments:

Little office

Living room - floor sanding and repair, corner tiling, electrical relocation

Pebble beach stonework - Gary wants to know if the window is the right size

Flagpole Pool

Pool main compound

Landscaping along steps to master and behind master

Stonework on road above gym progress

Stonework on side of entry (wall completed)

Floors of master bath, closet, hallway and water closet - third and final coat of varnish applied

Floors of master wardrobe area, vestibule and bedroom - first coat of varnish applied

Nanna windows

I will send part two shortly.

Respectfully submitted,

Daphne