

From: Daphne Wallace <[REDACTED]>
To: Jeffrey Epstein <jeevacation@gmail.com>
Cc: Brice Gordon <[REDACTED]> Rich Kahn
<[REDACTED]> Sarah K <[REDACTED]>

Subject: Photographs - January 12, 2012 - Part 2 of 2

Date: Thu, 12 Jan 2012 23:13:47 +0000

Attachments: 33_Concrete_roads_at_Flagpole_(1).JPG; 33_Concrete_roads_at_Flagpole_(2).JPG;
33_Concrete_roads_at_Flagpole_(3).JPG; 35_Compass_steps_(1).JPG;
35_Compass_steps_(2).JPG; 35_Compass_steps_(3).JPG; 35_Compass_steps_(4).JPG;
36_Bench_production.JPG; 37_Engineering.JPG; 39_Paint_ballet_and_yoga_room_(1).JPG;
39_Paint_ballet_and_yoga_room_(2).JPG; 40_Cabana_4_(1).JPG; 40_Cabana_4_(2).JPG;
40_Cabana_4_(3).JPG; 40_Cabana_4_(4).JPG; 40_Cabana_4_(5).JPG;
40_Cabana_4_(6).JPG; 40_Cabana_4_(7).JPG; 40_Cabana_4_(8).JPG;
40_Cabana_4_(9).JPG; 40_Cabana_4_(10).JPG; 40_Cabana_4_(11).JPG;
40_Cabana_4_(12).JPG; 40_Cabana_4_(13).JPG; 41_Lighting_(1).JPG;
41_Lighting_(2).JPG; 41_Lighting_(3).JPG; 43_Waterfall_bottom_(1).JPG;
43_Waterfall_bottom_(2).JPG; 43_Waterfall_bottom_(3).JPG;
43_Waterfall_bottom_(4).JPG; 43_Waterfall_bottom_(5).JPG; 45_Master_bath_(1).JPG;
45_Master_bath_(2).JPG; 45_Master_bath_(3).JPG; 45_Master_bath_(4).JPG;
52_Outdoor_bath_handheld.JPG; 53_Cement_plant.JPG; 53_Dirt_sifter.JPG;
54_Upper_gate_footings_(1).JPG; 54_Upper_gate_footings_(2).JPG;
54_Upper_gate_footings_(3).JPG; 55_Engineering_service_road_reshaped_(1).JPG;
55_Engineering_service_road_reshaped_(2).JPG; 56_Dock_lighting.JPG;
57_Dock_house.JPG; 58_Roads_from_intersection_to_Flagpole_(1).JPG;
58_Roads_from_intersection_to_Flagpole_(2).JPG;
58_Roads_from_intersection_to_Flagpole_(3).JPG; 62_Entry_band_on_courtyard_(1).JPG;
62_Entry_band_on_courtyard_(2).JPG; 62_Entry_band_on_courtyard_(3).JPG;
62_Entry_band_on_courtyard_(4).JPG; 62_Entry_band_on_courtyard_(5).JPG;
62_Entry_band_on_courtyard_(6).JPG; 62_Entry_band_on_courtyard_(7).JPG;
62_Entry_band_on_courtyard_(8).JPG; 63_Nautilus_shells.JPG;
64_Replacement_transformer_Mechanical_building.JPG; 65_Chillax_bath_photos_(1).JPG;
65_Chillax_bath_photos_(2).JPG; 65_Chillax_bath_photos_(3).JPG;
65_Chillax_bath_photos_(4).JPG;
67_Bulldoze_road_from_top_of_hill_down_towards_Flagpole.JPG; 68_Floating_dock.JPG;
69_Remove_rusty_metal_dock_columns_(1).JPG;
69_Remove_rusty_metal_dock_columns_(2).JPG; 70_Lull.JPG; 71_PRD.JPG;
72_Fat_Cat.JPG; 73_Big_N.JPG; Old_mechanical_exhaust_chimney.JPG;
Old_mechanical_exhaust_chimney_(2).JPG

Greetings Mr. Epstein,

January 12 photographs - Part 2 of 2 - for your review and comments:

33 Concrete roads at Flagpole
35 Compass steps
36 Bench production
37 Engineering
39 Ballet and yoga room
40 Cabana 4
41 Lighting

43 Waterfall bottom
45 Master bath
52 Outdoor bath
53 Dirt sifter, cement plant equipment
54 Upper gates footings
55 Engineering service road
56 Dock lighting
57 Dock house
58 Roads from intersection to Flagpole
62 Entry band on courtyard
63 Nautilus shells
64 Mechanical building transformer
65 Chillax bath photos
67 Beginning road from top of hill down towards Flagpole
68 Floating dock
69 Metal dock columns
70 Lull
71 PRD
72 Fat Cat
73 Big N
Old mechanical exhaust chimney removed

Respectfully submitted,

Daphne