

From: Larry Visoski <[REDACTED]>
To: Je vacation <jeevacation@gmail.com>
Subject: G550
Date: Sun, 20 Mar 2016 18:52:44 +0000
Inline-Images: IMG_2147.PNG

Jeffrey ,
 Appears the #3 brake has been changed,
 Number 2 brake is in limits, but ready to be change soon, brakes last a long time on Gulfstream, these are probably the original brakes installed,. Except for #3,.

I'll get exact pricing, I would imagine \$18,000 per brake.

Sent from my iPad

e 5755 FS 758 - <small>23 of 70</small> Inspection	570016	Lwr Wing Extension BL 542-BL 545 (View from Ground) {Right}-Znl Insp		
--	--------	---	--	--

WING BRAKE WEAR INSPECTION CMP CODES WERE COMPLI

CMP Code	Description
324305	Brake Wear Indicator (Left Outboard) - Detailed Inspection #1 BRAKE .250" -- APPROX 28% LIFE LEFT
324306	Brake Wear Indicator (Left Inboard) - Detailed Inspection #2 BRAKE .100" -- APPROX 11% LIFE LEFT
324307	Brake Wear Indicator (Right Inboard) - Detailed Inspection #3 BRAKE .650" -- APPROX 72% LIFE LEFT
324308	Brake Wear Indicator (Right Outboard) - Detailed Inspection #4 BRAKE .300" -- APPROX 33% LIFE LEFT