Subject: Re: what does this mean the comuter keeps shuting down? bug?
From: Vincenzo Iozzo ~~████████@████.com~~>
Sent: Sunday, January 4, 2015 6:53:03 AM
To: "jeffrey E." <jeevacation@gmail.com>

have you upgraded either the RAM or the OS version recently? That might be the problem.
Or the graphic card.

How often does it happen?

On 04/gen/2015, at 03:37, jeffrey E. <jeevacation@gmail.com> wrote:

> Anonymous UUID: 7B10723E-A512-91FB-3F13-3C7F3EF65100
>
> Sat Jan 3 23:28:49 2015
>
> *** Panic Report ***
> panic(cpu 4 caller 0xffffff800941e80a): Kernel trap at 0xffffff7f89f9aa87, type 14=page fault, registers:
> CR0: 0x000000008001003b, CR2: 0xffffff82775d7000, CR3: 0x000000000c583000, CR4:
0x00000000001626e0
> RAX: 0xffffff81f6f32000, RBX: 0xffffff802bc9a008, RCX: 0x00000000201a9400, RDX:
0xffffff802bc9a370
> RSP: 0xffffff81c8f7b230, RBP: 0xffffff81c8f7b230, RSI: 0xffffff802bc9a008, RDI: 0xffffff802bc93808
> R8: 0x00000000007fbe01, R9: 0xffffff81c8f7b244, R10: 0xffffff81a8b34050, R11: 0x0000000000ffefff
> R12: 0x00000000806a5000, R13: 0xffffff802bc9a370, R14: 0x0000000000000000, R15:
0xffffff802bc93808
> RFL: 0x0000000000010a06, RIP: 0xffffff7f89f9aa87, CS: 0x0000000000000008, SS:
0x0000000000000010
> Fault CR2: 0xffffff82775d7000, Error code: 0x0000000000000002, Fault CPU: 0x4
>
> Backtrace (CPU 4), Frame : Return Address
> 0xffffff81c8f7aee0 : 0xffffff800933a811
> 0xffffff81c8f7af60 : 0xffffff800941e80a
> 0xffffff81c8f7b120 : 0xffffff800943a443
> 0xffffff81c8f7b140 : 0xffffff7f89f9aa87
> 0xffffff81c8f7b230 : 0xffffff7f8a064ce6
> 0xffffff81c8f7b270 : 0xffffff7f8a1e3145
> 0xffffff81c8f7b310 : 0xffffff7f8a1dfb7e
> 0xffffff81c8f7b3b0 : 0xffffff7f8a1df55c
> 0xffffff81c8f7b410 : 0xffffff7f8a23e8a8
> 0xffffff81c8f7b610 : 0xffffff7f8a1e3641
> 0xffffff81c8f7b710 : 0xffffff7f8a1e3331
> 0xffffff81c8f7b780 : 0xffffff7f89f6ec40
> 0xffffff81c8f7b840 : 0xffffff7f89f6e5b8
> 0xffffff81c8f7b8f0 : 0xffffff7f89f76ea8
> 0xffffff81c8f7b9a0 : 0xffffff7f89f9f7e4
> 0xffffff81c8f7bba0 : 0xffffff7f89fa1090
> 0xffffff81c8f7bc90 : 0xffffff7f8b2999c7
> 0xffffff81c8f7bcb0 : 0xffffff7f8b2aee25
> 0xffffff81c8f7bcc0 : 0xffffff7f8b297002
> 0xffffff81c8f7bcf0 : 0xffffff7f8b26113a
> 0xffffff81c8f7bd10 : 0xffffff7f8b2606cc
> 0xffffff81c8f7bd40 : 0xffffff7f8b273e0e
> 0xffffff81c8f7bd70 : 0xffffff7f8b1e86a0
> 0xffffff81c8f7bda0 : 0xffffff7f8b20c33d
> 0xffffff81c8f7bde0 : 0xffffff80098b15da

> 0xffffff81c8f7be40 : 0xffffff80098d566e
> 0xffffff81c8f7be80 : 0xffffff7f8bc4da9f
> 0xffffff81c8f7bec0 : 0xffffff7f8bc4d08b
> 0xffffff81c8f7bf10 : 0xffffff7f8bc43444
> 0xffffff81c8f7bf40 : 0xffffff80098d507d
> 0xffffff81c8f7bf80 : 0xffffff80098d5146
> 0xffffff81c8f7bfb0 : 0xffffff80094192c7
>   Kernel Extensions in backtrace:
>   com.apple.driver.AppleMuxControl(3.7.21)[32B7E2DE-1F9D-3555-B687-
7A76A62B81D2]@0xffffff7f8bc42000->0xffffff7f8bc55fff
>   dependency: com.apple.driver.AppleGraphicsControl(3.7.21)[62689710-EEA7-307A-AC83-
B8F25DA88A6A]@0xffffff7f8bc3a000
>   dependency: com.apple.iokit.IOACPIFamily(1.4)[70E2B65E-A91A-3522-A1A0-
79FD63EABB4C]@0xffffff7f8a85d000
>   dependency: com.apple.iokit.IOPCIFamily(2.9)[766FC23F-452C-3B74-951C-
598BB17BCF06]@0xffffff7f89b24000
>   dependency: com.apple.iokit.IOGraphicsFamily(2.4.1)[6D99A3BE-D531-3780-880B-
13F2FC894A4A]@0xffffff7f89eed000
>   dependency: com.apple.driver.AppleBacklightExpert(1.1.0)[0183904C-6A16-32C4-9405-
EEFD7F820B02]@0xffffff7f8bc3d000
>   com.apple.iokit.IOAcceleratorFamily2(156.4)[20DDCE61-E3EC-3CC1-8B79-
170CEF2B603A]@0xffffff7f8b1e0000->0xffffff7f8b24cfff
>   dependency: com.apple.iokit.IOPCIFamily(2.9)[766FC23F-452C-3B74-951C-
598BB17BCF06]@0xffffff7f89b24000
>   dependency: com.apple.iokit.IOGraphicsFamily(2.4.1)[6D99A3BE-D531-3780-880B-
13F2FC894A4A]@0xffffff7f89eed000
>   com.apple.nvidia.driver.NVDAResman(10.0)[53CC0E05-7382-336C-8239-
AE884D6CA71A]@0xffffff7f89f4a000->0xffffff7f8a1bffff
>   dependency: com.apple.iokit.IOPCIFamily(2.9)[766FC23F-452C-3B74-951C-
598BB17BCF06]@0xffffff7f89b24000
>   dependency: com.apple.iokit.IONDRVSupport(2.4.1)[F4738C55-B507-3627-A9CA-
3D29A5230A03]@0xffffff7f89f34000
>   dependency: com.apple.iokit.IOGraphicsFamily(2.4.1)[6D99A3BE-D531-3780-880B-
13F2FC894A4A]@0xffffff7f89eed000
>   dependency: com.apple.AppleGraphicsDeviceControl(3.7.21)[4700601D-3FEB-3B86-B2BA-
8D71AF84D1C4]@0xffffff7f89f44000
>   com.apple.nvidia.driver.NVDAGK100Hal(10.0)[DC43029D-568A-3B7C-976B-
E922C17F5143]@0xffffff7f8a1cb000->0xffffff7f8a378fff
>   dependency: com.apple.nvidia.driver.NVDAResman(10.0.0)[53CC0E05-7382-336C-8239-
AE884D6CA71A]@0xffffff7f89f4a000
>   dependency: com.apple.iokit.IOPCIFamily(2.9)[766FC23F-452C-3B74-951C-
598BB17BCF06]@0xffffff7f89b24000
>   com.apple.GeForce(10.0)[26D2EC64-4AF8-32C8-BF74-5B1E80772FAA]@0xffffff7f8b25b000-
>0xffffff7f8b2f0fff
>   dependency: com.apple.iokit.IOPCIFamily(2.9)[766FC23F-452C-3B74-951C-
598BB17BCF06]@0xffffff7f89b24000
>   dependency: com.apple.iokit.IONDRVSupport(2.4.1)[F4738C55-B507-3627-A9CA-
3D29A5230A03]@0xffffff7f89f34000
>   dependency: com.apple.nvidia.driver.NVDAResman(10.0.0)[53CC0E05-7382-336C-8239-
AE884D6CA71A]@0xffffff7f89f4a000
>   dependency: com.apple.iokit.IOGraphicsFamily(2.4.1)[6D99A3BE-D531-3780-880B-
13F2FC894A4A]@0xffffff7f89eed000
>   dependency: com.apple.iokit.IOAcceleratorFamily2(156.4)[20DDCE61-E3EC-3CC1-8B79-
170CEF2B603A]@0xffffff7f8b1e0000
>
> BSD process name corresponding to current thread: kernel_task

```
>
> Mac OS version:
> 14B25
>
> Kernel version:
> Darwin Kernel Version 14.0.0: Fri Sep 19 00:26:44 PDT 2014; root:xnu-
2782.1.97~2/RELEASE_X86_64
> Kernel UUID: 89E10306-BC78-3A3B-955C-7C4922577E61
> Kernel slide:     0x0000000009000000> Kernel text base: 0xffffff8009200000
> __HIB  text base: 0xffffff8009100000
> System model name: MacBookPro11,3 (Mac-2BD1B31983FE1663)
>
> System uptime in nanoseconds: 11434136233908
> last loaded kext at 386886590816: com.apple.filesystems.smbfs    3.0.0 (addr 0xffffff7f8bdfd000, size
389120)
> last unloaded kext at 128551425280: com.apple.driver.AppleFileSystemDriver    3.0.1 (addr
0xffffff7f8bc74000, size 8192)
> loaded kexts:
> com.apple.filesystems.smbfs    3.0.0
> com.apple.driver.AppleHWSensor    1.9.5d0
> com.apple.driver.AudioAUUC    1.70
> com.apple.driver.ApplePlatformEnabler    2.1.0d1
> com.apple.driver.AGPM    100.14.37
> com.apple.driver.X86PlatformShim    1.0.0
> com.apple.filesystems.autofs    3.0
> com.apple.driver.AppleOSXWatchdog    1
> com.apple.driver.AppleGraphicsDevicePolicy    3.7.7
> com.apple.driver.AppleHDA    267.0
> com.apple.iokit.IOBluetoothSerialManager    4.3.1f2
> com.apple.driver.AppleUpstreamUserClient    3.6.1
> com.apple.iokit.IOUserEthernet    1.0.1
> com.apple.GeForce    10.0.0
> com.apple.driver.AppleIntelHD5000Graphics    10.0.0
> com.apple.driver.AppleIntelFramebufferAzul    10.0.0
> com.apple.driver.AppleLPC    1.7.3
> com.apple.iokit.BroadcomBluetoothHostControllerUSBTransport    4.3.1f2
> com.apple.driver.AppleMCCSControl    1.2.10
> com.apple.driver.AppleSMCLMU    2.0.4d1
> com.apple.Dont_Steal_Mac_OS_X    7.0.0
> com.apple.driver.AppleHWAccess    1
> com.apple.driver.AppleHV    1
> com.apple.driver.AppleCameraInterface    5.23.0
> com.apple.driver.AppleMuxControl    3.7.21
> com.apple.driver.AppleThunderboltIP    2.0.2
> com.apple.driver.AppleUSBTCButtons    240.2> com.apple.driver.AppleUSBTCKeyboard    240.2
> com.apple.driver.AppleUSBCardReader    3.5.0
> com.apple.AppleFSCompression.AppleFSCompressionTypeDataless    1.0.0d1
> com.apple.AppleFSCompression.AppleFSCompressionTypeZlib    1.0.0d1
> com.apple.BootCache    35
> com.apple.driver.AppleUSBHub    705.4.1
> com.apple.driver.XsanFilter    404
> com.apple.iokit.IOAHCIBlockStorage    2.6.5
> com.apple.driver.AppleAHCIPort    3.0.7
> com.apple.driver.AirPort.Brcm4360    901.19.10
> com.apple.driver.AppleUSBXHCI    705.4.14
> com.apple.driver.AppleSmartBatteryManager    161.0.0
```

> com.apple.driver.AppleACPIButtons   3.1
> com.apple.driver.AppleRTC   2.0
> com.apple.driver.AppleHPET   1.8
> com.apple.driver.AppleSMBIOS   2.1
> com.apple.driver.AppleACPIEC   3.1
> com.apple.driver.AppleAPIC   1.7
> com.apple.nke.applicationfirewall   161
> com.apple.security.quarantine   3
> com.apple.security.TMSafetyNet   8
> com.apple.kext.triggers   1.0
> com.apple.driver.DspFuncLib   267.0
> com.apple.kext.OSvKernDSPLib   1.15
> com.apple.iokit.IOAudioFamily   200.6
> com.apple.vecLib.kext   1.2.0
> com.apple.iokit.IOSerialFamily   11
> com.apple.nvidia.driver.NVDAGK100Hal   10.0.0
> com.apple.nvidia.driver.NVDAResman   10.0.0
> com.apple.iokit.IOSurface   97
> com.apple.AppleGraphicsDeviceControl   3.7.21
> com.apple.iokit.IOAcceleratorFamily2   156.4
> com.apple.driver.AppleHDAController   267.0
> com.apple.iokit.IOHDAFamily   267.0
> com.apple.iokit.IOBluetoothHostControllerUSBTransport   4.3.1f2
> com.apple.iokit.IOBluetoothFamily   4.3.1f2
> com.apple.driver.X86PlatformPlugin   1.0.0
> com.apple.driver.IOPlatformPluginFamily   5.8.0d49
> com.apple.driver.AppleSMBusController   1.0.13d1
> com.apple.driver.AppleSMC   3.1.9
> com.apple.driver.AppleBacklightExpert   1.1.0
> com.apple.driver.AppleGraphicsControl   3.7.21
> com.apple.iokit.IONDRVSupport   2.4.1
> com.apple.iokit.IOGraphicsFamily   2.4.1
> com.apple.iokit.IOUSBUserClient   705.4.0
> com.apple.driver.AppleUSBMultitouch   245.2
> com.apple.iokit.IOUSBHIDDriver   705.4.0
> com.apple.iokit.IOSCSIBlockCommandsDevice   3.7.0
> com.apple.iokit.IOUSBMassStorageClass   3.7.0
> com.apple.iokit.IOSCSIArchitectureModelFamily   3.7.0
> com.apple.driver.AppleUSBMergeNub   705.4.0
> com.apple.driver.AppleUSBComposite   705.4.9
> com.apple.driver.CoreStorage   471
> com.apple.driver.AppleThunderboltDPInAdapter   4.0.6
> com.apple.driver.AppleThunderboltDPAdapterFamily   4.0.6
> com.apple.driver.AppleThunderboltPCIDownAdapter   2.0.2
> com.apple.iokit.IOAHCIFamily   2.7.0
> com.apple.driver.AppleThunderboltNHI   3.1.7
> com.apple.iokit.IOThunderboltFamily   4.2.1
> com.apple.iokit.IO80211Family   700.52
> com.apple.driver.mDNSOffloadUserClient   1.0.1b8
> com.apple.iokit.IONetworkingFamily   3.2
> com.apple.iokit.IOUSBFamily   705.4.14
> com.apple.driver.AppleEFINVRAM   2.0
> com.apple.driver.AppleEFIRuntime   2.0
> com.apple.iokit.IOHIDFamily   2.0.0
> com.apple.iokit.IOSMBusFamily   1.1
> com.apple.security.sandbox   300.0

> com.apple.kext.AppleMatch   1.0.0d1
> com.apple.driver.AppleKeyStore   2
> com.apple.driver.AppleMobileFileIntegrity   1.0.5
> com.apple.driver.AppleCredentialManager   1.0
> com.apple.driver.DiskImages   389.1
> com.apple.iokit.IOStorageFamily   2.0
> com.apple.iokit.IOReportFamily   31
> com.apple.driver.AppleFDEKeyStore   28.30
> com.apple.driver.AppleACPIPlatform   3.1
> com.apple.iokit.IOPCIFamily   2.9
> com.apple.iokit.IOACPIFamily   1.4
> com.apple.kec.Libm   1
> com.apple.kec.pthread   1
> com.apple.kec.corecrypto   1.0
> Model: MacBookPro11,3, BootROM MBP112.0138.B11, 4 processors, Intel Core i7, 2.8 GHz, 16 GB,
SMC 2.19f12
> Graphics: Intel Iris Pro, Intel Iris Pro, Built-In
> Graphics: NVIDIA GeForce GT 750M, NVIDIA GeForce GT 750M, PCIe, 2048 MB
> Memory Module: BANK 0/DIMM0, 8 GB, DDR3, 1600 MHz, 0x80AD,
0x484D5434314753364146523841 2D50422020
> Memory Module: BANK 1/DIMM0, 8 GB, DDR3, 1600 MHz, 0x80AD,
0x484D5434314753364146523841 2D50422020
> AirPort: spairport_wireless_card_type_airport_extreme (0x14E4, 0x134), Broadcom BCM43xx 1.0
(7.15.124.12.10)
> Bluetooth: Version 4.3.1f2 15015, 3 services, 19 devices, 1 incoming serial ports
> Network Service: Wi-Fi, AirPort, en0
> Serial ATA Device: APPLE SSD SM1024F, 1 TB
> USB Device: Internal Memory Card Reader
> USB Device: BRCM20702 Hub
> USB Device: Bluetooth USB Host Controller
> USB Device: Apple Internal Keyboard / Trackpad
> Thunderbolt Bus: MacBook Pro, Apple Inc., 17.1
>
>
> --
>   please note
> The information contained in this communication is
> confidential, may be attorney-client privileged, may
> constitute inside information, and is intended only for
> the use of the addressee. It is the property of
> JEE
> Unauthorized use, disclosure or copying of this
> communication or any part thereof is strictly prohibited
> and may be unlawful. If you have received this
> communication in error, please notify us immediately by
> return e-mail or by e-mail to jeevacation@gmail.com, and
> destroy this communication and all copies thereof,
> including all attachments. copyright -all rights reserved