wall

Extension of Cutter

Existing Cap
not sealed

Existing Cutter

* Photo was taken looking up from Cutter base.