

From: Larry Visoski <[REDACTED]>
Subject: Fwd: Update on Parts
Sent: Friday, May 23, 2014 3:11:37 PM
Cc: Rich Kahn <[REDACTED]>
To: Je vacation <jeevacation@gmail.com>
[image002.jpg](#)

Email below regarding heli parts.,

Sent from my iPhone

Begin forwarded message:

From: "Burch, David (Edwards)" <[REDACTED]>
Date: May 23, 2014 at 11:07:22 AM EDT
To: Lvjet <[REDACTED]>
Cc: "Gray, Christopher" <[REDACTED]>
Subject: Update on Parts

Good Morning Larry,

The wheels are not through QC and in shipping as of this email... Bell is experiencing manpower issues resulting in the delay...

The drive bolts were received yesterday back from Singapore and QC has placed and inspection / rejection on them due to some abrading on the cadmium plating. I spoke with the chief inspector this morning in Fort Worth and he is going to send me photos of the drive bolts as he feels that this is normal when produced. Chris and I will review the bolts and speak with engineering if needed. We should be able to do one of two things accept them as they are and in an airworthy state, or worst case send them to BHPF and have re-plated. I am opting for the first as these bolts fit inside the drive bushing at installation.

Please understand I am doing everything in my power to move this along up to and including losing my voice and or my job...

I will keep you posted throughout the day...

Kind regards,
David Burch, GM - ERSI



"Offering -5 Star Service to You"