

From: Larry Visoski <[REDACTED]>
Subject: Update
Sent: Monday, November 4, 2013 8:15:04 PM
To: Je vacation <jeevacation@gmail.com>

We found the outflow valves sticks due to overspray paint. Mostly from full open to close. It's best to address the outflow valve cleaning while in Teterboro this week. Avionics is going to Accomplish their functional checks of pressurization controller tonight.
What is your estimated departure time for tomorrow? So I can make sure plane is ready.

Thx
Larry

Sent from my iPhone