
From: Ivje [REDACTED]
Sent: Sunday, December 9, 2012 12:28 AM
To: Je vacation
Subject: GII autopilot

Jeffrey,
Nadia and I completed test flight on GII, during climb and Cruise flight the autopilot was smoothest I've experienced, Changing the Pitch computer repaired the Pitch surging, pourposing.
During decent the aileron had faint left/right wing rocking,,not as pronounced dutch roll we where experiencing, Roll computer is seperate unit which is suspect causing this issue,. Meridian will exchange the roll computer,, no test flight required since its only during decent, in my opinion roll computer will remidy and we'll be good.
Thx
Larry

Sent via BlackBerry by AT&T

```
<?xml version="1.0" encoding="UTF-8"?>
<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version="1.0">
<dict>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1355012878</integer>
  <key>flags</key>
  <integer>8623750145</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>22</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>262640</string>
</dict>
</plist>
```