
From: [REDACTED]
Sent: Thursday, May 16, 2013 6:55 PM
To: jeevacation@gmail.com
Cc: [REDACTED]
Subject: B727 Mx update

Jeffrey

while installing the #2 engine on the Boeing, a Mechanic had to r=move a panel that was not originally necessary during this maintenance visit,. a= you see in the photo, a large area of dis-similar metal corrosion was uncovered= I will have a firm quote to repair this area by tomorrow,. its not as bad as =t appears, just time consuming, Rough estimate is \$20k, mostly labor intensiv=, since parts will be custom made at metal shop,.

I will have firm completion date early next week, We had to install a re-condition Nose gear strut, due to constant leak=ng of Nitrogen and hydraulic fluid, price for strut \$22,000

thank you,
Larry

B727