
From: [REDACTED] <[REDACTED]>
Sent: Wednesday, February 9, 2011 4:41 PM
To: Jeffrey Epstein
Subject: ZORRO UPDATE 2/9/11

Mr. Epstein,

We just wanted to give you an update as to the status of the Ranch. This is more of a log of daily events so to speak.

Jan. 27 - Thursday -

Pump # 5 that works the spa went down.

Took Thunder (black quarter horse) to the vet with colic concerns. =A0

Jan. 28 - Friday

Up all night with sick horse. Took back to vet at 5 am - Jan. 29 - Saturday [REDACTED] found that Main House water meter showed usage of 13,000 gallons. Leak found outside dog pen Up all night with sick horse. Died early am. [REDACTED] buried.

Feb. 1 - Tuesday

Pulled pump # 5 and booster pump at well 4 (down). Fixed water leak outside dog pen. (photos taken) Feb. 2 - Wednesday

Lodge water froze (heat was set at 70 degrees), Underground water vault at Ranch Central froze at the meter and flooded inside vault at Ranch Central up to control panel. (photos taken)

[REDACTED] took pumps and motors in

Feb. 3 - Thursday

-26 degrees and high of -5.

Lost (2) legs of the three phase power that went to the Dakota well. Burned blend motor up. Dakota well down.

Electric company came out to restore broken lines due to cold snap.

Yellow Staff House at Ranch Central had a water line in south side wall freeze and burst. Flooded house with water. Lodge water restored and all is well.

Feb. 4 - Friday

-23 degrees and high of 10.

Ranch Central booster pumps dried out and back on line.

Reservoir out of water - [REDACTED] filled with water truck. (possible water line from well 4 frozen and not filling) [REDACTED]

discovered water leak in 2nd mechanical room and vault closet in Main House. Isolated line.

[REDACTED] changed out blend motor at the Dakota well and got it back up and running.

Frost free water spicket in Stables froze - Turned heat on to defrost.

Kings Butane were called to come fill all propane tanks to 60% or better. Immediate response.

Main House boiler tripped. Set to run in manual mode. [REDACTED] checked every 2 hours all night.

[REDACTED] and [REDACTED] found the Bullhead water valves were frozen and busted. (photos taken) [REDACTED] ([REDACTED] [REDACTED]) and [REDACTED], ([REDACTED] [REDACTED]) worked at yellow house and main house to pull water up from wet carpet.

Feb. 5 - Saturday

Main House boiler would not respond to manual operation. Program issues. Called ECI - Main House irrigation meter blew out gasket and sprayed water and flooded down stairs in the mechanical building. (photos taken) Water damage to control board that operates the HVAC system to the Main House. ECI tried to restore with no response from circuit board. They will order new board.

ECI helped [REDACTED] and [REDACTED] reset the boiler and got it working correctly.

Feb. 6 - Sunday

Maintained the ranch. No further issues.

Pat with ECI called to check on the boiler.

Feb. 7 - Monday

██████ made connection at Bullhead water valves.(photos taken) ██████ purchased \$270 worth of parts to fix and maintain said leaks and be prepared for more. Feb. 8 - Tuesday ██████ introduced water back up to Bullhead water valves after repairing.

██████ and ██████ replaced pump #5 back into pool mechanical room.

Feb.9 - Wednesday

Expecting 6-8 inches of new snow and temp around zero.

Will dedicate the day to finding the leak at the Main House on the non-r/o cold water supply that feeds the pool.

Please be reassured that all issues due to this cold snap are being addressed or have already been resolved. We are monitoring all locations closely and are staying on top of it all.

Hope all is well with you.

Thank you for your time,

██████ and ██████

P.S. Please confirm if received. (thank you)

=A0

--000325574f26cb277e049bdc1fa3-- date-last-viewed 0 date-received 1297269635 flags 8590195713 gmail-label-ids 1322 remote-id 134067