

To: jeevacation@gmail.com[jeevacation@gmail.com]

Cc: [REDACTED]

From: [REDACTED]

Sent: Sat 1/14/2012 4:56:32 PM

Subject: B727ENGINE REPAIR.PDF

[B727enginerepair.pdf](#)

Jeffrey,

REF: B727 #3 engine repair, for your approval

I know we don't have a choice here, and did the best we could to replace only damaged Turbine blades,.

Parts \$146,419.00 Labor: \$46,000.00 total

repair cost: \$189,419.00

from Morrison:

Hi Larry,

Attached is the estimate for the engine. Below are the additional repairs required:

- Repair Outer ducts for delamination
- Replace complete set of T2 vanes due to feather seal slot worn
- Replace complete set of T2 blades due to contact with feather seal

Right now the engine is on schedule to test mid to late next week, so please let me know if you have any questions.

Material

Invoice

Labor

Invoice