

To: Jeffrey Epstein[jeevacation@gmail.com]; Richard Kahn [REDACTED]

From: Stephanie Hodges
Sent: Sun 3/17/2013 12:33:16 AM
Subject: Cistern Inspection
[Coating Failing.JPG](#)
[Crossover Valve.JPG](#)
[Sounding Tube.JPG](#)
[Suction Pick Up.JPG](#)

Good Evening,

Attached are the pictures from inside the cistern this morning. The coating does appear to be coming loose from some of the seams in the concrete. Also the valves, sounding tube and suction pipe all have some rust. There is also a thin layer of dust and rust particles. We will research other cistern repair contractors in St. Thomas. There does seem to be a need for some maintenance but the quote does sound high.

Roy

--

*LSJ, LLC
Island Manager
6100 Red Hook Quarters Suite B3
St Thomas
USVI 00802*