

**To:** jeevacation@gmail.com[jeevacation@gmail.com];  
jeevacation@gmail.com[jeevacation@gmail.com]  
**From:** [REDACTED]  
**Sent:** Wed 3/2/2011 11:14:17 PM  
**Subject:** GII update #2

Jeffrey,

-T-stat approved for install on APU tomorrow morning,..(Gulfsteam's GII specialist will be in tomorrow),.

-Gulfstream suggested swapping the EMI filters in Boost pump system, This is NOT a fuel filter, but a current filter and suppressor, due to high current to the boost pumps located in the wheel well, we are doing this for trouble shooting purposes, if Circuit Breaker tripping moves to L/H side, we will change the EMI filter,. all systems worked normal from ABQ to Long Bch,. and are working normal now,.

-cleaned wires at cannon plug, rang wires in the system and relays, all ops checked normal,.

we **should** be "returned to service" by 4pm Thursday, is my guess at this time tomorrow,.  
I will keep you posted,  
thanks,  
Larry