

From: [REDACTED]
To: [REDACTED]; [REDACTED]; [REDACTED]
Subject: RE: MCC New York 79F
Date: Thursday, September 5, 2019 8:58:23 AM

[REDACTED]

This issue is the model number changed because you had us wait to order the cameras. The cameras you received are the replacement model. My recommendation with the rush to get all this installed, would be to open a magic ticket and request it be added to the approved list. The biggest issue we have right now is that 90 percent of the cameras on the approved list are EOL.

[REDACTED] | Program Manager FBOP Contracts

SigNet Technologies | Convergent Federal Solutions
12300 Kiln Ct Suite E, Beltsville, MD 20705
Office: [REDACTED] | Mobile: [REDACTED] | Direct: [REDACTED]
[REDACTED]

This e-mail and any attachments to it are intended only for the identified recipients. It may contain proprietary or otherwise legally protected information of SigNet Technologies, Inc. Any unauthorized use or disclosure of this communication is strictly prohibited. If you have received this communication in error, please notify the sender and delete or otherwise destroy the e-mail and all attachments immediately.

From: [REDACTED] [mailto:[REDACTED]]
Sent: Thursday, September 5, 2019 8:52 AM
To: [REDACTED] <[REDACTED]>; [REDACTED] <[REDACTED]>; [REDACTED] <[REDACTED]>; [REDACTED] <[REDACTED]>; [REDACTED] <[REDACTED]>
Subject: MCC New York 79F

Good Morning,

There is a discrepancies with the 135 Dome Cameras . The proposal part number was Vicon IQM62WR-B9. I received 135 of Vicon cameras Part Number V942D-W312MIR. What is the best way to fix this problem. The cameras i received are not on the Approver Hardware List for the BOP.

[REDACTED]
Communication Technician
US Department of Justice
MCC-New York
150 Park Row
New York, NY 10007-1704
Phone [REDACTED]
Fax [REDACTED]

4.7.27
[REDACTED]