

From: Rita Luisa Garces <[REDACTED]>
To: [REDACTED] <[REDACTED]>
Cc: Tabitha Lewis <[REDACTED]>

Subject: RE: Appliances for 11J

Date: Tue, 28 Aug 2012 17:23:53 +0000

Inline-Images: image001.jpg

[REDACTED]

I definitely do not think the ref should move to the other end of the kitchen. I also think that the ref probably needs to be a left hinge. I do not think you will have enough room to open the door fully to remove interior baskets etc.

Let's see what the drawings look like....

Thank you

RitaLuisa Garces

Senior Designer

Bilotta Kitchens of New York

Architects & Designers Building

[REDACTED]
T [REDACTED] / F [REDACTED]

Bilotta
www.bilotta.com

From: [REDACTED] [mailto:[REDACTED]]
Sent: Tuesday, August 28, 2012 11:50 AM
To: Tabitha Lewis; Rita Luisa Garces
Subject: Appliances for 11J

Range: GE Profile JGS968SEKSS

<http://products.geappliances.com/AppProducts/Dispatcher?REQUEST=SpecPage&Sku=JGS968SEKSS>

Dishwasher: GE Monogram ZBD0710KSS

<http://products.geappliances.com/AppProducts/Dispatcher?REQUEST=SpecPage&Sku=ZBD0710KSS>

Microwave: GE Profile Spacemaker 2.0 PVM2070SK

<http://products.geappliances.com/AppProducts/Dispatcher?REQUEST=SpecPage&Sku=PVM2070SMSS>

Refrigerator:

Sub-Zero 611-SLH

The only problem I've just realized with the fridge is that the hinge is on the left side, but with the new configuration of the kitchen, it would need to be on the right side, but Sub-Zero doors can not be reversed. I'm not sure what it would look like to put the fridge on the left side of the kitchen first thing when you walk in? Or we may just be forced to buy a new fridge in order to put it at the back of the kitchen by the window. Thoughts?