

Plan d g550

1. Tint the R/H forward cabin molding to match opposite side. (darker)
2. ~~Check recline lever on vip seat, was it installed on the wrong side?~~
3. Recover the 2 forward seats in lower side wall fabric
4. Make an eyeglass storage area on the inboard side of the VIP seat shroud. (soft inside)
5. Adjust all latches to stop rattling
6. ~~Wedge tables outboard to stop rattle when stowed (foam blocks)~~
7. ~~Trim table handle to make pull up easier~~
8. ~~Add a spacer block to the lower side wall where the table rests on to help with bounce~~
9. ~~Check psu switches for rattles~~
10. Make 2 ottomans – leather or fabric. Mentioned tufting
11. Pocket doors on galley coffee and oven area rattle bad when in open position. Foam wedges
12. ~~Galley faucet is reversed. Fix so control in on aisle side~~
13. Look into adding a bulb to the lower section of the r/h galley wall closeout
14. ~~Aft lav drain is inop~~
15. Change potty ring wants it wider – like 4.50"
16. Potty seat cover – make 1" thicker than finished size now. 1st remove hard foam
17. Cut down L/H aft lav PSU (move lights, etc) recover lighter material
18. Recover the R/H galley wall / PSU in lighter material
19. Recover the baggage to aft lavatory head bumper with lighter material
20. Need a cover for the toilet paper. Curved slide door covered in veneer preferred
21. ~~Remove fax from credenza, make a short lip around the existing pull-out with a tall lip outbd~~
22. Make VIP armrests ½" wider
23. Space up bottom cushion on vip seat ¼" – 1"
24. Divan cushions, arm rests, doors need rework and different materials
25. Headrest embroidery wrong arrow direction on pilot headrest – replace
26. Forward entry step removable arm – try to tighten, possible Teflon tape?
27. New credenza top in fabric and foam to match GIV
28. Pronto remote mount in window line monitor location at VIP seat
29. ~~Aft L/H #3 & 4 seats feel loose, wobble in flight / taxi~~
30. Pilot seats need additional foam
31. Leather inserts in ledges
32. Iphone charger needs tweaking
33. Change ledge cupholders, eliminate some
34. ~~Remove 2 of the 4 magnets from the table handle. Too hard to stow~~
35. Cover Aft bulkhead and aft door with fabric
36. Cover rear magazine rack with fabric