

# Brennan Bros. Co., Inc.

*Plumbing-Heating-Fire Protection*

3150 ALBANY CRESCENT - BRONX, NY 10463

Brian Freer-President  
NYC Lic.1545 NYC Lic.816-B  
Westch.Lic# 761

John K. Brennan-Vice President  
NYC Lic. 1540 Westch Lic.880

Terence P. Brennan-Sec./Treas.

Dec. 11, 2010

Mr. Richard J. Barnett  
Property Manager for  
9 East 71<sup>st</sup> St.  
New York, NY 10021

Re: 9 East 71<sup>st</sup> St.  
Basement Catering Kitchen  
Grease Interceptor Replacement

Gentlemen:

We herewith submit our proposal for plumbing repairs at the above referenced property location as outlined in the following:

- To disconnect and remove from residence rotted and leaking JR Smith # 8035 grease interceptor with 70 lb. grease capacity.
- To furnish and install replacement JR Smith # 8035 grease interceptor with 70 lb. grease capacity, with 35 gpm flow rate and gray duco coating inside and out. To make 3" inlet and outlet drain connections and place grease intercepting system back in working order.
- To dispose of old grease interceptor at approved scrap recycling center.

All of the above described plumbing repairs to be performed for the sum of.....\$3,850.00 & tax.

Breakdown-

Material: \$2,925.00 Labor: \$925.00

Sincerely,  
BRENNAN BROS. CO., INC.

Brian Freer, President

Acceptance For 9 East 71<sup>st</sup> St. Owner:

Name: \_\_\_\_\_

Date: \_\_\_\_\_

*We are proud of our connections* ®

EFTA00589458