



Maintenance Due List with Related
Sort By Earliest Due Date
 Include only mandatory service information not yet accomplished

Projected Through:
4684 Hours TT
1564 Landings
16 Mar 2020 Date
2690.5 APU Hours
30 APU Cycles

G-CGUL

Current TT 3484.0
 Current 964
 Current Hr Mtr 3441.1

Phone: 800-810-4853 or FAX: 866-878-8241 or

Log Date -- 24 Dec 2015

Analyst: Gary Leever
 Phone: +44 790-312-5319

Aircraft Make Gulfstream

Aircraft Model G550

Aircraft Serial No. 5176

Airworthiness Date 26 Nov 2007

Regulation EU-EASA

COMPONENT TIMES

Position	Logbook	Description	Serial Number	Total Time	Total Cycles	TSO	CSO
1	Engine	Rolls Royce BR700-710C4-11 (G550)	15455	3484.0	964		
2	Engine	Rolls Royce BR700-710C4-11 (G550)	15456	3484.0	964		
1	APU	Honeywell RE220 (G550)	P-503	2090.5	0		

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number	Serial Number	TSNHR	TSNLD	TSNMO	TSOHR	TSOLD							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref	Event Category		@= Adjustments										

319011	Planeview System Charts - Update							3475.9 961						
Airframe							14 DAY	09 Dec 2015	23 Dec 2015	Expiration	-89 Days			
	Airworthiness Limitation-Insp													

710055	Engine Health Monitoring							50 Hrs	3466.5 953	3516.5Hrs	3516.5	32.5 Hrs		1.0
Engine 1									04 Dec 2014					
	Lubrication/Serviceing (S)													

710055 (710060)	Engine Health Monitoring							50 Hrs	3466.5 953	3516.5Hrs	3516.5	32.5 Hrs		1.0
Engine 2									04 Dec 2014					
	Lubrication/Serviceing (S)													

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

346025	FMS NAV Database - Update								3475.9 961						
Airframe								28 DAY	09 Dec 2015	06 Jan 2016		-75 Days			
										Expiration					

928879	Engine Oil System MCD Inspection							100 Hrs	0.0 0	3566.5 Hrs*	3566.5	82.5 Hrs		
Engine 1									20 Oct 2007					
	TV 151806													

928979()	Engine Oil System MCD Inspection							100 Hrs	0.0 0	3566.5 Hrs*	3566.5	82.5 Hrs		
Engine 2									22 Oct 2007					
	TV 151806													

237235	Securaplane RAD-04 Battery Pack								3466.5 953				\$139.10	
Airframe	JMNN4024CR		NSN		0.0	0	0	12 MOS	18 Feb 2015	29 Feb 2016		-21 Days		
	No													
	ST02049CH-D													

256069	Non-rechargeable Flashlight Batteries (No. 4) - Discard								3484.0 964				\$4.20	1.0
Airframe	MN1300		NSN		17.5	11	11	12 MOS	07 Jan 2016	29 Feb 2016		-21 Days		
	No													
	G550 AMM													

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	256074	Airframe	Flashlight (No. 4) - Operational Test		1.00
Mandatory Related Codes Totals:					1.00

282651	Main Fuel Boost Pump (Left) - Fuel Leak Check							500 Hrs	3307.8 927	3807.8Hrs		323.8 Hrs		
Airframe	1159SCP500-7		1572						17 Mar 2014					
	G550 AMM													

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
282652	Main Fuel Boost Pump (Right) - Fuel Leak Check							500 Hrs	3307.8	3807.8Hrs		323.8 Hrs		
	1159SCP500-7		1574					927						
Airframe	G550 AMM		Special Inspection (R)					17 Mar 2014						
282653	Alternate Fuel Boost Pump (Left) - Fuel Leak Check							500 Hrs	3307.8	3807.8Hrs		323.8 Hrs		
	1159SCP500-7		1575					927						
Airframe	G550 AMM		Special Inspection (R)					17 Mar 2014						
282654	Alternate Fuel Boost Pump (Right) - Fuel Leak Check							500 Hrs	3307.8	3807.8Hrs		323.8 Hrs		
	1159SCP500-7		1578					927						
Airframe	G550 AMM		Special Inspection (R)					17 Mar 2014						
880605	SB BR700-72-900521 (Part B) Rev 4 - Inspection - LP Compressor Annulus Fillers							500 Hrs	3307.8	3807.8Hrs	3807.8	323.8 Hrs		
								927						
Engine 1								24 Mar 2014						
	Service Information													
880605 (890605)	SB BR700-72-900521 (Part B) Rev 4 - Inspection - LP Compressor Annulus Fillers							500 Hrs	3307.8	3807.8Hrs	3807.8	323.8 Hrs		
								927						
Engine 2								24 Mar 2014						
	Service Information													
000008	WEIGH AIRCRAFT								2354.6					
								711						
Airframe								48 MOS	19 Apr 2012	19 Apr 2016	29 Days			
	Special Inspection													

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									
281407	Gravity Water / Fuel Drain Valve (Left) - Operational Test							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		0.5
	G550 AMM		Special Inspection (R)					17 Mar 2014						
281408	Gravity Water / Fuel Drain Valve (Right) - Operational Test							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		0.5
	G550 AMM		Special Inspection (R)					17 Mar 2014						
292501	Auxiliary Hydraulic Pump Manifold Differential Pressure Indicator - Detailed Inspection							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		1.0
	G550 AMM		Special Inspection (R)					17 Mar 2014						
292502	Power Transfer Unit Manifold Differential Pressure Indicator - Detailed Inspection							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		1.0
	G550 AMM		Special Inspection (R)					17 Mar 2014						
315001	Central Warning System (Including Audio) - Operational Test							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		1.0
	G550 AMM		Functional/Ops Test (O)					18 Mar 2014						
321045	Main Landing Gear and Attachments (Left) - General Visual Inspection							500 Hrs	0.0 0	3854.6 Hrs*		370.6 Hrs		
	G550 AMM		Special Inspection (R)					26 Nov 2007						

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
321046	Main Landing Gear and Attachments (Right) - General Visual Inspection							500 Hrs	0.0	3854.6 Hrs*		370.6 Hrs		0.0
	Airframe								0					
	G550 AMM		Special Inspection (R)						26 Nov 2007					
322006	Nose Landing Gear and Attachments - General Visual Inspection							500 Hrs	0.0	3854.6 Hrs*		370.6 Hrs		
	Airframe								0					
	G550 AMM		Special Inspection (R)						26 Nov 2007					
324305	Brake Wear Indicator (Left Outboard) - Detailed Inspection							500 Hrs	3307.8	3854.6 Hrs*		370.6 Hrs		1.0
	Airframe								927					
	G550 AMM		Special Inspection (R)						17 Mar 2014					
324306	Brake Wear Indicator (Left Inboard) - Detailed Inspection							500 Hrs	3307.8	3854.6 Hrs*		370.6 Hrs		1.0
	Airframe								927					
	G550 AMM		Special Inspection (R)						17 Mar 2014					
324307	Brake Wear Indicator (Right Inboard) - Detailed Inspection							500 Hrs	3307.8	3854.6 Hrs*		370.6 Hrs		1.0
	Airframe								927					
	G550 AMM		Special Inspection (R)						17 Mar 2014					
324308	Brake Wear Indicator (Right Outboard) - Detailed Inspection							500 Hrs	3307.8	3854.6 Hrs*		370.6 Hrs		1.0
	Airframe								927					
	G550 AMM		Special Inspection (R)						17 Mar 2014					

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
531012	Exterior Radome Fairing Installation - Detailed Inspection							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		2.0
Airframe	G550 AMM		Special Inspection (R)					17 Mar 2014						
531014	Enhanced Vision System Sapphire Window Installation - Detailed Inspection							500 Hrs	3307.8 927	3854.6 Hrs*		370.6 Hrs		2.0
Airframe	G550 AMM		Special Inspection (R)					17 Mar 2014						
723101	Low-pressure Compressor (Fan) Blades - Detailed Inspection							500 Hrs	3307.8 927	3854.6 Hrs*	3854.6	370.6 Hrs		2.0
Engine 1	G550 AMM		Special Inspection (R)					18 Mar 2014						

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723011	Engine 1	Low-pressure Compressor (Fan) Disc - Visual Inspection		4.00
723113	Engine 1	Low-pressure Compressor (Fan) Blade No. 1 - Removal / Installation	\$17,435.29	0.10
723114	Engine 1	Low-pressure Compressor (Fan) Blade No. 2 - Removal / Installation	\$17,435.29	0.10
723115	Engine 1	Low-pressure Compressor (Fan) Blade No. 3 - Removal / Installation	\$17,435.29	0.10
723116	Engine 1	Low-pressure Compressor (Fan) Blade No. 4 - Removal / Installation	\$17,435.29	0.10
723117	Engine 1	Low-pressure Compressor (Fan) Blade No. 5 - Removal / Installation	\$17,435.29	0.10
723118	Engine 1	Low-pressure Compressor (Fan) Blade No. 6 - Removal / Installation	\$17,435.29	0.10
723119	Engine 1	Low-pressure Compressor (Fan) Blade No. 7 - Removal / Installation	\$17,435.29	0.10
723120	Engine 1	Low-pressure Compressor (Fan) Blade No. 8 - Removal / Installation	\$17,435.29	0.10
723121	Engine 1	Low-pressure Compressor (Fan) Blade No. 9 - Removal / Installation	\$17,435.29	0.10
723122	Engine 1	Low-pressure Compressor (Fan) Blade No. 10 - Removal / Installation	\$17,435.29	0.10
723123	Engine 1	Low-pressure Compressor (Fan) Blade No. 11 - Removal / Installation	\$17,435.29	0.10

Code	Description							Frequency (*=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)				
	MM Ref		Event Category		@= Adjustments										
	723124	Engine 1	Low-pressure Compressor (Fan) Blade No. 12 - Removal / Installation						\$17,435.29		0.10				
	723125	Engine 1	Low-pressure Compressor (Fan) Blade No. 13 - Removal / Installation						\$17,435.29		0.10				
	723126	Engine 1	Low-pressure Compressor (Fan) Blade No. 14 - Removal / Installation						\$17,435.29		0.10				
	723127	Engine 1	Low-pressure Compressor (Fan) Blade No. 15 - Removal / Installation						\$17,435.29		0.10				
	723128	Engine 1	Low-pressure Compressor (Fan) Blade No. 16 - Removal / Installation						\$17,435.29		0.10				
	723129	Engine 1	Low-pressure Compressor (Fan) Blade No. 17 - Removal / Installation						\$17,435.29		0.10				
	723130	Engine 1	Low-pressure Compressor (Fan) Blade No. 18 - Removal / Installation						\$17,435.29		0.10				
	723131	Engine 1	Low-pressure Compressor (Fan) Blade No. 19 - Removal / Installation						\$17,435.29		0.10				
	723132	Engine 1	Low-pressure Compressor (Fan) Blade No. 20 - Removal / Installation						\$17,435.29		0.10				
	723133	Engine 1	Low-pressure Compressor (Fan) Blade No. 21 - Removal / Installation						\$17,435.29		0.10				
	723134	Engine 1	Low-pressure Compressor (Fan) Blade No. 22 - Removal / Installation						\$17,435.29		0.10				
	723135	Engine 1	Low-pressure Compressor (Fan) Blade No. 23 - Removal / Installation						\$17,435.29		0.10				
	723136	Engine 1	Low-pressure Compressor (Fan) Blade No. 24 - Removal / Installation						\$17,435.29		0.10				
Mandatory Related Codes Totals:								\$418,446.96		6.40					

723101 Low-pressure Compressor (Fan) Blades - Detailed Inspection 500 Hrs 3307.8 3854.6 Hrs* 3854.6 370.6 Hrs 2.0
(723102) Engine 2 927
20 Mar
2014

G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723011	Engine 2	Low-pressure Compressor (Fan) Disc - Visual Inspection		4.00
723113	Engine 2	Low-pressure Compressor (Fan) Blade No. 1 - Removal / Installation	\$17,435.29	0.10
723114	Engine 2	Low-pressure Compressor (Fan) Blade No. 2 - Removal / Installation	\$17,435.29	0.10
723115	Engine 2	Low-pressure Compressor (Fan) Blade No. 3 - Removal / Installation	\$17,435.29	0.10
723116	Engine 2	Low-pressure Compressor (Fan) Blade No. 4 - Removal / Installation	\$17,435.29	0.10
723117	Engine 2	Low-pressure Compressor (Fan) Blade No. 5 - Removal / Installation	\$17,435.29	0.10

G-CGUL

G550

5176

Maintenance Due List

Page 7 of 94

21 Mar 2016

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									
	723118	Engine 2	Low-pressure Compressor (Fan) Blade No. 6 - Removal / Installation						\$17,435.29		0.10			
	723119	Engine 2	Low-pressure Compressor (Fan) Blade No. 7 - Removal / Installation						\$17,435.29		0.10			
	723120	Engine 2	Low-pressure Compressor (Fan) Blade No. 8 - Removal / Installation						\$17,435.29		0.10			
	723121	Engine 2	Low-pressure Compressor (Fan) Blade No. 9 - Removal / Installation						\$17,435.29		0.10			
	723122	Engine 2	Low-pressure Compressor (Fan) Blade No. 10 - Removal / Installation						\$17,435.29		0.10			
	723123	Engine 2	Low-pressure Compressor (Fan) Blade No. 11 - Removal / Installation						\$17,435.29		0.10			
	723124	Engine 2	Low-pressure Compressor (Fan) Blade No. 12 - Removal / Installation						\$17,435.29		0.10			
	723125	Engine 2	Low-pressure Compressor (Fan) Blade No. 13 - Removal / Installation						\$17,435.29		0.10			
	723126	Engine 2	Low-pressure Compressor (Fan) Blade No. 14 - Removal / Installation						\$17,435.29		0.10			
	723127	Engine 2	Low-pressure Compressor (Fan) Blade No. 15 - Removal / Installation						\$17,435.29		0.10			
	723128	Engine 2	Low-pressure Compressor (Fan) Blade No. 16 - Removal / Installation						\$17,435.29		0.10			
	723129	Engine 2	Low-pressure Compressor (Fan) Blade No. 17 - Removal / Installation						\$17,435.29		0.10			
	723130	Engine 2	Low-pressure Compressor (Fan) Blade No. 18 - Removal / Installation						\$17,435.29		0.10			
	723131	Engine 2	Low-pressure Compressor (Fan) Blade No. 19 - Removal / Installation						\$17,435.29		0.10			
	723132	Engine 2	Low-pressure Compressor (Fan) Blade No. 20 - Removal / Installation						\$17,435.29		0.10			
	723133	Engine 2	Low-pressure Compressor (Fan) Blade No. 21 - Removal / Installation						\$17,435.29		0.10			
	723134	Engine 2	Low-pressure Compressor (Fan) Blade No. 22 - Removal / Installation						\$17,435.29		0.10			
	723135	Engine 2	Low-pressure Compressor (Fan) Blade No. 23 - Removal / Installation						\$17,435.29		0.10			
	723136	Engine 2	Low-pressure Compressor (Fan) Blade No. 24 - Removal / Installation						\$17,435.29		0.10			
Mandatory Related Codes Totals:								\$418,446.96		6.40				

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

790011 Magnetic Chip Detectors - Detailed Inspection 500 Hrs 3307.8 3854.6 Hrs* 3854.6 370.6 Hrs 1.5
 Engine 1 927 19 Mar 2014
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
710017	Engine 1	Engine Run Leak Check Test 2A - LP Fuel System / Oil System		1.00
790015	Engine 1	Engine Fwd Bearing Chamber Magnetic Chip Detector - Removal / Installation	\$697.06	1.00
790017	Engine 1	Engine Aft Bearing Chamber Magnetic Chip Detector - Removal / Installation	\$697.06	1.00
790019	Engine 1	Engine Accessory Gear Box Magnetic Chip Detector - Removal / Installation	\$697.06	1.00

Mandatory Related Codes Totals: \$2,091.18 4.00

793001 Oil Filter Differential Pressure Indicator - Detailed Inspection 500 Hrs 3307.8 3854.6 Hrs* 3854.6 370.6 Hrs 0.5
 Engine 1 927 19 Mar 2014
 G550 AMM Special Inspection (R)

793001 Oil Filter Differential Pressure Indicator - Detailed Inspection 500 Hrs 3307.8 3854.6 Hrs* 3854.6 370.6 Hrs 0.5
 (793002) Engine 2 927 18 Mar 2014
 G550 AMM Special Inspection (R)

240114 Aft Emergency Battery Pack - Discard 3484.0 \$9,438.92 4.0
 100-0302-01 P2274 1129.4 253 45 964
 Airframe Yes 48 MOS 05 Jan 2016 30 Apr 2016 40 Days
 G550 AMM Replacement (X) 1129.400 Hrs 253.000 Cyc/Lnd 45

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
240104	Airframe	Emergency Battery (Aft) - Removal / Installation	\$9,438.92	1.00
240124	Airframe	Emergency Battery Power System (Aft) - Operational Test		1.00

Mandatory Related Codes Totals: \$9,438.92 2.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

493404	APU Fuel System Components, Lines and Connections - General Visual Inspection							1000 Hrs	0.0	3928.0 Hrs*		444.0 Hrs		
Airframe	G550 AMM		Special Inspection (R)						0	26 Nov 2007				

321005	Main Landing Gear (Left) - Lubrication								3484.0					2.0
Airframe	G550 AMM		Lubrication/Serviceing (L)					4 MOS	964	05 Jan 2016	31 May 2016*	71 Days		

321006	Main Landing Gear (Right) - Lubrication								3484.0					2.0
Airframe	G550 AMM		Lubrication/Serviceing (L)					4 MOS	964	05 Jan 2016	31 May 2016*	71 Days		

322004	Nose Landing Gear - Lubrication								3484.0					2.0
Airframe	G550 AMM		Lubrication/Serviceing (L)					4 MOS	964	03 Jan 2016	31 May 2016*	71 Days		

533415	Drag Beam Overwing Installation - Detailed Inspection								0.0					4.0
Airframe	G550 AMM		Special Inspection (M)					96 MOS	0	05 May 2008	31 May 2016	71 Days		

121400	Air Turbine Starter Oil - Change							500 Hrs	3466.5	3966.5Hrs	3966.5	482.5 Hrs		3.0
Engine 1	G550 AMM		Lubrication/Serviceing (S)						953	16 Feb 2015				

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	801011	Engine 1	Air Turbine Starter Magnetic Chip Collector - Detailed Inspection		0.50
Mandatory Related Codes Totals:					0.50

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

121400 Air Turbine Starter Oil - Change 500 Hrs 3466.5 3966.5Hrs 3966.5 482.5 Hrs 3.0
(121401)
 Engine 2 953
 16 Feb
 2015
 G550 AMM Lubrication/Service (S)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
801011	Engine 2	Air Turbine Starter Magnetic Chip Collector - Detailed Inspection		0.50
Mandatory Related Codes Totals:				0.50

242111 Integrated Drive Generator (Left) - Detailed Inspection 500 Hrs 3466.5 3966.5Hrs 482.5 Hrs 2.0
 Airframe 953
 16 Feb
 2015
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
242109	Airframe	Integrated Drive Generator (Left) - Oil Level Check		1.00
242141	Airframe	Integrated Drive Generator Oil Scavenger Filter Differential Pressure Indicator (Left) - Inspection		
Mandatory Related Codes Totals:				1.00

242112 Integrated Drive Generator (Right) - Detailed Inspection 500 Hrs 3466.5 3966.5Hrs 482.5 Hrs 2.0
 Airframe 953
 16 Feb
 2015
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
242110	Airframe	Integrated Drive Generator (Right) - Oil Level Check		1.00
242142	Airframe	Integrated Drive Generator Oil Scavenger Filter Differential Pressure Indicator (Right) - Inspection		
Mandatory Related Codes Totals:				1.00

242115 Integrated Drive Generator (Left) - Servicing 500 Hrs 3466.5 3966.5Hrs 482.5 Hrs 1.0
 Airframe 953
 16 Feb
 2015
 G550 AMM Lubrication/Service (S)

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

242116	Integrated Drive Generator (Right) - Servicing							500 Hrs	3466.5 953	3966.5Hrs		482.5 Hrs		1.0
Airframe	G550 AMM		Lubrication/Servicing (S)						16 Feb 2015					

723103	Low-pressure Compressor (Fan) Annulus Fillers - Detailed Inspection							500 Hrs	3466.6 953	3966.6Hrs	3966.6	482.6 Hrs		4.0
Engine 1	G550 AMM		Special Inspection (R)						20 May 2015					

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723805	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 1 - Removal / Installation	\$8,738.40	1.00
723806	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 2 - Removal / Installation	\$6,379.41	1.00
723807	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 3 - Removal / Installation	\$8,738.40	1.00
723808	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 4 - Removal / Installation	\$8,738.40	1.00
723809	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 5 - Removal / Installation	\$8,738.40	1.00
723810	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 6 - Removal / Installation	\$8,738.40	1.00
723811	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 7 - Removal / Installation	\$8,738.40	1.00
723812	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 8 - Removal / Installation	\$6,379.41	1.00
723813	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 9 - Removal / Installation	\$8,738.40	1.00
723814	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 10 - Removal / Installation	\$8,738.40	1.00
723815	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 11 - Removal / Installation	\$8,738.40	1.00
723816	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 12 - Removal / Installation	\$8,738.40	1.00
723817	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 13 - Removal / Installation	\$8,738.40	1.00
723818	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 14 - Removal / Installation	\$6,379.41	1.00
723819	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 15 - Removal / Installation	\$8,738.40	1.00

Code	Description							Frequency (*=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
	723820	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 16 - Removal / Installation						\$8,738.40		1.00			
	723821	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 17 - Removal / Installation						\$8,738.40		1.00			
	723822	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 18 - Removal / Installation						\$8,738.40		1.00			
	723823	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 19 - Removal / Installation						\$8,738.40		1.00			
	723824	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 20 - Removal / Installation						\$6,379.41		1.00			
	723825	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 21 - Removal / Installation						\$8,738.40		1.00			
	723826	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 22 - Removal / Installation						\$8,738.40		1.00			
	723827	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 23 - Removal / Installation						\$8,738.40		1.00			
	723828	Engine 1	Low-pressure Compressor (Fan) Annulus Filler No. 24 - Removal / Installation						\$8,738.40		1.00			
Mandatory Related Codes Totals:										\$200,285.64		24.00		

723103 Low-pressure Compressor (Fan) Annulus Fillers - Detailed Inspection 500 Hrs 3466.6 3966.6Hrs 3966.6 482.6 Hrs 4.0
(723104) Engine 2 953
20 May 2015
G550 AMM Special Inspection (R)

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723828	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 24 - Removal / Installation	\$8,738.40	1.00
		723827	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 23 - Removal / Installation	\$8,738.40	1.00
		723826	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 22 - Removal / Installation	\$8,738.40	1.00
		723825	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 21 - Removal / Installation	\$8,738.40	1.00
		723824	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 20 - Removal / Installation	\$8,738.40	1.00
		723823	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 19 - Removal / Installation	\$8,738.40	1.00
		723822	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 18 - Removal / Installation	\$8,738.40	1.00
		723821	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 17 - Removal / Installation	\$8,738.40	1.00
		723820	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 16 - Removal / Installation	\$8,738.40	1.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type	Ops Number(s)					
	MM Ref	Event Category		@= Adjustments										
	723819	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 15 - Removal / Installation						\$8,738.40	1.00				
	723818	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 14 - Removal / Installation						\$6,379.41	1.00				
	723817	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 13 - Removal / Installation						\$8,738.40	1.00				
	723816	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 12 - Removal / Installation						\$8,738.40	1.00				
	723815	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 11 - Removal / Installation						\$8,738.40	1.00				
	723814	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 10 - Removal / Installation						\$8,738.40	1.00				
	723813	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 9 - Removal / Installation						\$8,738.40	1.00				
	723812	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 8 - Removal / Installation						\$8,738.40	1.00				
	723811	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 7 - Removal / Installation						\$8,738.40	1.00				
	723810	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 6 - Removal / Installation						\$8,738.40	1.00				
	723809	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 5 - Removal / Installation						\$8,738.40	1.00				
	723808	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 4 - Removal / Installation						\$8,738.40	1.00				
	723807	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 3 - Removal / Installation						\$8,738.40	1.00				
	723806	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 2 - Removal / Installation						\$6,379.41	1.00				
	723805	Engine 2	Low-pressure Compressor (Fan) Annulus Filler No. 1 - Removal / Installation						\$8,738.40	1.00				
Mandatory Related Codes Totals:								\$205,003.62	24.00					

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

790011 Magnetic Chip Detectors - Detailed Inspection 500 Hrs 3466.5 3966.5Hrs 3966.5 482.5 Hrs 1.5
(790012) Engine 2 953
18 Feb
2015
G550 AMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						710017	Engine 2	Engine Run Leak Check Test 2A - LP Fuel System / Oil System		1.00
						790019	Engine 2	Engine Accessory Gear Box Magnetic Chip Detector - Removal / Installation	\$697.06	1.00
						790017	Engine 2	Engine Aft Bearing Chamber Magnetic Chip Detector - Removal / Installation	\$697.06	1.00
						790015	Engine 2	Engine Fwd Bearing Chamber Magnetic Chip Detector - Removal / Installation	\$697.06	1.00
						Mandatory Related Codes Totals:			\$2,091.18	4.00

256282 Protective Breathing Equipment (No. 1) - Detailed Inspection 500 Hrs 3484.0 3984.0Hrs 500.0 Hrs 1.5
Airframe 12 MOS 13 Jan 31 Jan 10 Mos
2016 2017
G550 AMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						256281	Airframe	Protective Breathing Equipment (No. 1) - Removal / Installation	\$1,799.62	1.50
						Mandatory Related Codes Totals:			\$1,799.62	1.50

256288 Protective Breathing Equipment (No. 3) - Detailed Inspection 500 Hrs 3484.0 3984.0Hrs 500.0 Hrs 1.5
Airframe 12 MOS 13 Jan 31 Jan 10 Mos
2016 2017
G550 AMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						256287	Airframe	Protective Breathing Equipment (No. 3) - Removal / Installation	\$1,534.70	1.50
						Mandatory Related Codes Totals:			\$1,534.70	1.50

275019 Flap Actuator Travel Nut (Left) - Lubrication 500 Hrs 3484.0 3984.0Hrs 500.0 Hrs 1.0
Airframe 24 MOS 20 Jan 31 Jan 22 Mos
2016 2018
G550 AMM Lubrication/Serviceing (L)

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
275020	Flap Actuator Travel Nut (Right) - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							24 MOS	20 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Lubrication/Serviceing (L)											
304105	Windshield Surface Seal (Left) - Detailed Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											
304106	Windshield Surface Seal (Right) - Detailed Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											
321801	Main Landing Gear Door Hinges (Left) - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							24 MOS	21 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Lubrication/Serviceing (L)											
321802	Main Landing Gear Door Hinges (Right) - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							24 MOS	21 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Lubrication/Serviceing (L)											
321803	Main Landing Gear and Doors (Left) - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
	Airframe							12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
321804	Main Landing Gear and Doors (Right) - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
322801	Nose Landing Gear Door Hinges - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
Airframe								24 MOS	25 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM	Lubrication/Serviceing (L)												
322802	Nose Landing Gear and Doors - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		1.0
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
325201	Nose Wheel Steering Unit - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		0.5
Airframe								24 MOS	22 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM	Lubrication/Serviceing (L)												
325202	Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		0.5
Airframe								24 MOS	22 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM	Lubrication/Serviceing (L)												
334050	Navigation (Position) Light Lens - Detailed Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		0.5
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM	Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
531015	Nose Gear Wheel Well FS 44 - FS 119 - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		2.0
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
531045	Main Gear Wheel Wells FS 576 - FS 632 (Left) - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		2.5
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
531046	Main Gear Wheel Wells FS 576 - FS 632 (Right) - Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		2.5
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
531047	Main Gear Wheel Wells FS 576 - FS 632 (Cove Panel Drain Holes) - (Enhanced) Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		2.0
Airframe								12 MOS	20 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
531048	Main Gear Wheel Wells FS 576 - FS 632 (Wiring Harness) - (Enhanced) Zonal Inspection							500 Hrs	3484.0 964	3984.0Hrs		500.0 Hrs		2.0
Airframe								12 MOS	10 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM	Special Inspection (R)												
213301	Decompression Advisory System - Functional Test							2000 Hrs	2047.8 610	4000.0 Hrs*		516.0 Hrs		4.0
Airframe									13 Jul 2011					
	G550 AMM	Functional/Ops Test (F)												
261305	APU Compartment Fire Detect Loop - Operational Test							2000 Hrs	2047.8 610	4000.0 Hrs*		516.0 Hrs		1.0
Airframe									13 Jul 2011					
	G550 AMM	Functional/Ops Test (O)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
272100	Rudder Pedals - Lubrication							2000 Hrs	2047.8 610	4000.0 Hrs*		516.0 Hrs		2.0
Airframe	G550 AMM		Lubrication/Serviceing (L)					72 MOS	13 Jul 2011	31 Jul 2017		16 Mos		
275011	Flap Actuator Gearbox (Left Inboard) - Lubrication							4000 Hrs	0.0 0	4000.0Hrs		516.0 Hrs		0.5
Airframe	G550 AMM		Lubrication/Serviceing (L)					192 MOS	26 Nov 2007	30 Nov 2023		92 Mos		
275012	Flap Actuator Gearbox (Right Inboard) - Lubrication							4000 Hrs	0.0 0	4000.0Hrs		516.0 Hrs		0.5
Airframe	G550 AMM		Lubrication/Serviceing (L)					192 MOS	26 Nov 2007	30 Nov 2023		92 Mos		
275013	Flap Actuator Gearbox (Left Outboard) - Lubrication							4000 Hrs	0.0 0	4000.0Hrs		516.0 Hrs		0.5
Airframe	G550 AMM		Lubrication/Serviceing (L)					192 MOS	26 Nov 2007	30 Nov 2023		92 Mos		
275014	Flap Actuator Gearbox (Right Outboard) - Lubrication							4000 Hrs	0.0 0	4000.0Hrs		516.0 Hrs		0.5
Airframe	G550 AMM		Lubrication/Serviceing (L)					192 MOS	26 Nov 2007	30 Nov 2023		92 Mos		
527003	Main Entrance Door Locked Relay Circuit - Functional Test							2000 Hrs	2047.8 610	4000.0 Hrs*		516.0 Hrs		1.5
Airframe	G550 AMM		Functional/Ops Test (F)						14 Jul 2011					
531068	External Fuselage - General Visual Inspection							2000 Hrs	2047.8 610	4000.0 Hrs*		516.0 Hrs		6.0
Airframe	G550 AMM		Airworthiness Limitation-Insp (M)					800 Cyc/Lnd	13 Jul 2011	1410		446 Cyc/Lnd		

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723500	Low-pressure Compressor (Fan) Blade No. 1 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723113	Engine 1	Low-pressure Compressor (Fan) Blade No. 1 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723500	Low-pressure Compressor (Fan) Blade No. 1 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723501)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723113	Engine 2	Low-pressure Compressor (Fan) Blade No. 1 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723502	Low-pressure Compressor (Fan) Blade No. 2 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723114	Engine 1	Low-pressure Compressor (Fan) Blade No. 2 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723502	Low-pressure Compressor (Fan) Blade No. 2 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723503)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723114	Engine 2	Low-pressure Compressor (Fan) Blade No. 2 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723504 Low-pressure Compressor (Fan) Blade No. 3 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723115	Engine 1	Low-pressure Compressor (Fan) Blade No. 3 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723504 Low-pressure Compressor (Fan) Blade No. 3 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723505) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723115	Engine 2	Low-pressure Compressor (Fan) Blade No. 3 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723506 Low-pressure Compressor (Fan) Blade No. 4 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723116	Engine 1	Low-pressure Compressor (Fan) Blade No. 4 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723506 Low-pressure Compressor (Fan) Blade No. 4 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723507) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723116	Engine 2	Low-pressure Compressor (Fan) Blade No. 4 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723508 Low-pressure Compressor (Fan) Blade No. 5 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723117	Engine 1	Low-pressure Compressor (Fan) Blade No. 5 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723508 Low-pressure Compressor (Fan) Blade No. 5 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723509) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723117	Engine 2	Low-pressure Compressor (Fan) Blade No. 5 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723510 Low-pressure Compressor (Fan) Blade No. 6 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723118	Engine 1	Low-pressure Compressor (Fan) Blade No. 6 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723510 Low-pressure Compressor (Fan) Blade No. 6 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723511) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723118	Engine 2	Low-pressure Compressor (Fan) Blade No. 6 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723512 Low-pressure Compressor (Fan) Blade No. 7 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723119	Engine 1	Low-pressure Compressor (Fan) Blade No. 7 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723512 Low-pressure Compressor (Fan) Blade No. 7 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723513) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723119	Engine 2	Low-pressure Compressor (Fan) Blade No. 7 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723514 Low-pressure Compressor (Fan) Blade No. 8 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM0 Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723120	Engine 1	Low-pressure Compressor (Fan) Blade No. 8 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723514 Low-pressure Compressor (Fan) Blade No. 8 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723515) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM0 Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723120	Engine 2	Low-pressure Compressor (Fan) Blade No. 8 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723516 Low-pressure Compressor (Fan) Blade No. 9 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723121	Engine 1	Low-pressure Compressor (Fan) Blade No. 9 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723516 Low-pressure Compressor (Fan) Blade No. 9 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723517) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723121	Engine 2	Low-pressure Compressor (Fan) Blade No. 9 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723518 Low-pressure Compressor (Fan) Blade No. 10 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723122	Engine 1	Low-pressure Compressor (Fan) Blade No. 10 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723518 Low-pressure Compressor (Fan) Blade No. 10 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723519) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723122	Engine 2	Low-pressure Compressor (Fan) Blade No. 10 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723520 Low-pressure Compressor (Fan) Blade No. 11 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
 FW33513 3000 0 3000 3000 2036
 Engine 1 20 Oct 2007
 G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723123	Engine 1	Low-pressure Compressor (Fan) Blade No. 11 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723520 Low-pressure Compressor (Fan) Blade No. 11 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723521) FW33513 3000 0 3000 3000 2036
 Engine 2 22 Oct 2007
 G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723123	Engine 2	Low-pressure Compressor (Fan) Blade No. 11 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723522 Low-pressure Compressor (Fan) Blade No. 12 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
 FW33513 3000 0 3000 3000 2036
 Engine 1 20 Oct 2007
 G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723124	Engine 1	Low-pressure Compressor (Fan) Blade No. 12 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723522 Low-pressure Compressor (Fan) Blade No. 12 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723523) FW33513 3000 0 3000 3000 2036
 Engine 2 22 Oct 2007
 G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723124	Engine 2	Low-pressure Compressor (Fan) Blade No. 12 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723524 Low-pressure Compressor (Fan) Blade No. 13 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723125	Engine 1	Low-pressure Compressor (Fan) Blade No. 13 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723524 Low-pressure Compressor (Fan) Blade No. 13 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723525) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723125	Engine 2	Low-pressure Compressor (Fan) Blade No. 13 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723526 Low-pressure Compressor (Fan) Blade No. 14 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723126	Engine 1	Low-pressure Compressor (Fan) Blade No. 14 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

723526 Low-pressure Compressor (Fan) Blade No. 14 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723527) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
723126	Engine 2	Low-pressure Compressor (Fan) Blade No. 14 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723528	Low-pressure Compressor (Fan) Blade No. 15 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723127	Engine 1	Low-pressure Compressor (Fan) Blade No. 15 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723528	Low-pressure Compressor (Fan) Blade No. 15 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723529)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723127	Engine 2	Low-pressure Compressor (Fan) Blade No. 15 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723530	Low-pressure Compressor (Fan) Blade No. 16 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723128	Engine 1	Low-pressure Compressor (Fan) Blade No. 16 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723530	Low-pressure Compressor (Fan) Blade No. 16 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723531)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct	2007				
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723128	Engine 2	Low-pressure Compressor (Fan) Blade No. 16 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723532 Low-pressure Compressor (Fan) Blade No. 17 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723129	Engine 1	Low-pressure Compressor (Fan) Blade No. 17 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723532 Low-pressure Compressor (Fan) Blade No. 17 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723533) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723129	Engine 2	Low-pressure Compressor (Fan) Blade No. 17 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723534 Low-pressure Compressor (Fan) Blade No. 18 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723130	Engine 1	Low-pressure Compressor (Fan) Blade No. 18 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723534 Low-pressure Compressor (Fan) Blade No. 18 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723535) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723130	Engine 2	Low-pressure Compressor (Fan) Blade No. 18 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723536	Low-pressure Compressor (Fan) Blade No. 19 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct					
	G550 AMM / RR EMM		Special Inspection (R)						2007					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723131	Engine 1	Low-pressure Compressor (Fan) Blade No. 19 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723536	Low-pressure Compressor (Fan) Blade No. 19 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723537)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct					
	G550 AMM / RR EMM		Special Inspection (R)						2007					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723131	Engine 2	Low-pressure Compressor (Fan) Blade No. 19 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723538	Low-pressure Compressor (Fan) Blade No. 20 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513							3000	0	3000	3000	2036		
Engine 1									20 Oct					
	G550 AMM / RR EMM		Special Inspection (R)						2007					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723132	Engine 1	Low-pressure Compressor (Fan) Blade No. 20 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

723538	Low-pressure Compressor (Fan) Blade No. 20 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723539)	FW33513							3000	0	3000	3000	2036		
Engine 2									22 Oct					
	G550 AMM / RR EMM		Special Inspection (R)						2007					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		723132	Engine 2	Low-pressure Compressor (Fan) Blade No. 20 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:					\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723540	Low-pressure Compressor (Fan) Blade No. 21 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513						3000	0	3000	3000	2036			
Engine 1								20 Oct 2007						
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					723133	Engine 1	Low-pressure Compressor (Fan) Blade No. 21 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:								\$17,435.29	0.10

723540	Low-pressure Compressor (Fan) Blade No. 21 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723541)	FW33513						3000	0	3000	3000	2036			
Engine 2								22 Oct 2007						
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					723133	Engine 2	Low-pressure Compressor (Fan) Blade No. 21 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:								\$17,435.29	0.10

723542	Low-pressure Compressor (Fan) Blade No. 22 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
	FW33513						3000	0	3000	3000	2036			
Engine 1								20 Oct 2007						
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					723134	Engine 1	Low-pressure Compressor (Fan) Blade No. 22 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:								\$17,435.29	0.10

723542	Low-pressure Compressor (Fan) Blade No. 22 Metco 58 Coating - Refurbishment							4000 Hrs	0.0	4000.0Hrs	4000	516.0 Hrs		1.0
(723543)	FW33513						3000	0	3000	3000	2036			
Engine 2								22 Oct 2007						
	G550 AMM / RR EMM		Special Inspection (R)											

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					723134	Engine 2	Low-pressure Compressor (Fan) Blade No. 22 - Removal / Installation	\$17,435.29	0.10
Mandatory Related Codes Totals:								\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

723544 Low-pressure Compressor (Fan) Blade No. 23 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723135	Engine 1	Low-pressure Compressor (Fan) Blade No. 23 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723544 Low-pressure Compressor (Fan) Blade No. 23 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723545) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723135	Engine 2	Low-pressure Compressor (Fan) Blade No. 23 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723546 Low-pressure Compressor (Fan) Blade No. 24 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
FW33513 3000 0 3000 3000 2036
Engine 1 20 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723136	Engine 1	Low-pressure Compressor (Fan) Blade No. 24 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

723546 Low-pressure Compressor (Fan) Blade No. 24 Metco 58 Coating - Refurbishment 4000 Hrs 0.0 4000.0Hrs 4000 516.0 Hrs 1.0
(723547) FW33513 3000 0 3000 3000 2036
Engine 2 22 Oct 2007
G550 AMM / RR EMM Special Inspection (R)

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						723136	Engine 2	Low-pressure Compressor (Fan) Blade No. 24 - Removal / Installation	\$17,435.29	0.10
						Mandatory Related Codes Totals:			\$17,435.29	0.10

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
727103	Bypass Duct Inner Surface - General Visual Inspection							2000 Hrs	2047.8 610	4000.0 Hrs*	4000	516.0 Hrs		6.0
Engine 1	G550 AMM		Special Inspection (R)					12 Jul 2011						
727103 (727104)	Bypass Duct Inner Surface - General Visual Inspection							2000 Hrs	2047.8 610	4000.0 Hrs*	4000	516.0 Hrs		6.0
Engine 2	G550 AMM		Special Inspection (R)					13 Jul 2011						
732119	Electronic Engine Controller Close Fitting Box - Detailed Inspection							2000 Hrs	2047.8 610	4000.0 Hrs*	4000	516.0 Hrs		2.0
Engine 1	G550 AMM		Special Inspection (M)					11 Jul 2011						
732119 (732120)	Electronic Engine Controller Close Fitting Box - Detailed Inspection							2000 Hrs	2047.8 610	4000.0 Hrs*	4000	516.0 Hrs		2.0
Engine 2	G550 AMM		Special Inspection (M)					12 Jul 2011						
994024 (R)	EASA AD 2016-0034 - Low Pressure Turbine Fuel Shut-Off Pawl Carrier Pivot Pin - Replacement								0.0 0					
Airframe							6MOS**		09 Sep 2016		6 Mos			
	Airworthiness Directive													
723109	Low-pressure Compressor Inlet Cone - Detailed Inspection							1000 Hrs	3307.8 927	4307.8Hrs	4307.8	823.8 Hrs		1.0
Engine 1	G550 AMM		Special Inspection (R)					18 Mar 2014						
723109 (723110)	Low-pressure Compressor Inlet Cone - Detailed Inspection							1000 Hrs	3307.8 927	4307.8Hrs	4307.8	823.8 Hrs		1.0
Engine 2	G550 AMM		Special Inspection (R)					20 Mar 2014						

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

313032	Cockpit Voice Recorder (CVR) - Inspect The CVR Installation (EASA EUROCAE)								3484.0 964						0.0
Airframe								6 MOS	03 Mar 2016	30 Sep 2016		6 Mos			
	EASA SIB No. 2009-28 / ED-112		Special Inspection												

316201	Display Unit Manual Reversion - Operational Test							1500 Hrs	2849.4 833	4349.4Hrs		865.4 Hrs		0.5
Airframe									05 Apr 2013					
	G550 AMM		Functional/Ops Test (O)											

731141	Drains Tank Fuel Filter and Housing Inspection							2000 Hrs	2354.6 711	4354.6Hrs	4354.6	870.6 Hrs		2.0
Engine 1									19 Apr 2012					
	RR BR710-C4 EMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	731143	Engine 1	Drains Tank Ejector Inline Filter Element - Removal / Installation	\$972.06	2.00
Mandatory Related Codes Totals:				\$972.06	2.00

731141 (731142)	Drains Tank Fuel Filter and Housing Inspection							2000 Hrs	2354.6 711	4354.6Hrs	4354.6	870.6 Hrs		2.0
Engine 2									28 Mar 2012					
	RR BR710-C4 EMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	731143	Engine 2	Drains Tank Ejector Inline Filter Element - Removal / Installation	\$972.06	2.00
Mandatory Related Codes Totals:				\$972.06	2.00

256045	First Aid Kit (No. 1) Time Limited Supplies - Discard								3475.9 961				\$1,019.70	1.0
Airframe	No							12 MOS	27 Oct 2015	31 Oct 2016		7 Mos		
	G550 AMM		Replacement (X)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256406	Defibrillator Electrode Pads - Discard (Set No. 1)								3444.5				\$106.08	0.5
	989803139261		40409-0954		0.0	0	0		949					
Airframe	No							24 MOS	28 Oct 2014	01 Nov 2016	8 Mos			
	Replacement (X)													

273405	Elevator Hardover Prevention System - Operational Test							1000 Hrs	3444.5	4444.5Hrs		960.5 Hrs	12.0
								949					
Airframe								31 Oct 2014					
	G550 AMM	Functional/Ops Test (O)											

724005	High-pressure Turbine Stage 1 Rotor Blades - Special Detailed Inspection							1000 Hrs	3444.5	4444.5Hrs	4444.5	960.5 Hrs	14.0
								949					
Engine 1								28 Oct 2014					
	G550 AMM	Special Inspection (M)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	742001	Engine 1	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00
	742003	Engine 1	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:				\$6,185.00	8.00

724005 (724006)	High-pressure Turbine Stage 1 Rotor Blades - Special Detailed Inspection							1000 Hrs	3444.5	4444.5Hrs	4444.5	960.5 Hrs	14.0
								949					
Engine 2								28 Oct 2014					
	G550 AMM	Special Inspection (M)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	742001	Engine 2	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00
	742003	Engine 2	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:				\$6,185.00	8.00

724007	High-pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection							1000 Hrs	3444.5	4444.5Hrs	4444.5	960.5 Hrs	20.0
								949					
Engine 1								28 Oct 2014					
	G550 AMM	Special Inspection (M)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	742003	Engine 1	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:				\$3,092.50	4.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

724007 High-pressure Turbine Nozzle Guide Vanes - Special Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 20.0
(724008) Engine 2 28 Oct 2014
G550 AMM Special Inspection (M)

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					742003	Engine 2	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:								\$3,092.50	4.00

724009 Combustion Liner - Special Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 6.0
Engine 1 28 Oct 2014
G550 AMM Special Inspection (M)

Mandatory Related Codes:					Code	Logbook	Description	Parts Cost	Labor Hours
					742001	Engine 1	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00
					731119	Engine 1	Fuel Spray Nozzle (No. 20) - Removal / Installation	\$26,140.00	16.00
					731117	Engine 1	Fuel Spray Nozzle (No. 18) - Removal / Installation	\$26,140.00	16.00
					731118	Engine 1	Fuel Spray Nozzle (No. 19) - Removal / Installation	\$26,140.00	16.00
					731101	Engine 1	Fuel Spray Nozzle (No. 2) - Removal / Installation	\$26,140.00	16.00
					731102	Engine 1	Fuel Spray Nozzle (No. 3) - Removal / Installation	\$26,140.00	16.00
					731103	Engine 1	Fuel Spray Nozzle (No. 4) - Removal / Installation	\$26,140.00	16.00
					731104	Engine 1	Fuel Spray Nozzle (No. 5) - Removal / Installation	\$26,140.00	16.00
					731105	Engine 1	Fuel Spray Nozzle (No. 6) - Removal / Installation	\$26,140.00	16.00
					731106	Engine 1	Fuel Spray Nozzle (No. 7) - Removal / Installation	\$26,140.00	16.00
					731107	Engine 1	Fuel Spray Nozzle (No. 8) - Removal / Installation	\$26,140.00	16.00
					731108	Engine 1	Fuel Spray Nozzle (No. 9) - Removal / Installation	\$26,140.00	16.00
					731109	Engine 1	Fuel Spray Nozzle (No. 10) - Removal / Installation	\$26,140.00	16.00
					731110	Engine 1	Fuel Spray Nozzle (No. 11) - Removal / Installation	\$26,140.00	16.00
					731111	Engine 1	Fuel Spray Nozzle (No. 12) - Removal / Installation	\$26,140.00	16.00
					731112	Engine 1	Fuel Spray Nozzle (No. 13) - Removal / Installation	\$26,140.00	16.00
					731113	Engine 1	Fuel Spray Nozzle (No. 14) - Removal / Installation	\$26,140.00	16.00
					731114	Engine 1	Fuel Spray Nozzle (No. 15) - Removal / Installation	\$26,140.00	16.00
					731115	Engine 1	Fuel Spray Nozzle (No. 16) - Removal / Installation	\$26,140.00	16.00
					731116	Engine 1	Fuel Spray Nozzle (No. 17) - Removal / Installation	\$26,140.00	16.00
					731100	Engine 1	Fuel Spray Nozzle (No. 1) - Removal / Installation	\$26,140.00	16.00
Mandatory Related Codes Totals:								\$525,892.50	324.00

Code	Description							Frequency (* =Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

724009 Combustion Liner - Special Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 6.0
(724010) Engine 2 949
 28 Oct
 2014
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
731100	Engine 2	Fuel Spray Nozzle (No. 1) - Removal / Installation	\$26,140.00	16.00
731116	Engine 2	Fuel Spray Nozzle (No. 17) - Removal / Installation	\$26,140.00	16.00
731115	Engine 2	Fuel Spray Nozzle (No. 16) - Removal / Installation	\$26,140.00	16.00
731114	Engine 2	Fuel Spray Nozzle (No. 15) - Removal / Installation	\$26,140.00	16.00
731113	Engine 2	Fuel Spray Nozzle (No. 14) - Removal / Installation	\$26,140.00	16.00
731112	Engine 2	Fuel Spray Nozzle (No. 13) - Removal / Installation	\$26,140.00	16.00
731111	Engine 2	Fuel Spray Nozzle (No. 12) - Removal / Installation	\$26,140.00	16.00
731110	Engine 2	Fuel Spray Nozzle (No. 11) - Removal / Installation	\$26,140.00	16.00
731109	Engine 2	Fuel Spray Nozzle (No. 10) - Removal / Installation	\$26,140.00	16.00
731108	Engine 2	Fuel Spray Nozzle (No. 9) - Removal / Installation	\$26,140.00	16.00
731107	Engine 2	Fuel Spray Nozzle (No. 8) - Removal / Installation	\$26,140.00	16.00
731106	Engine 2	Fuel Spray Nozzle (No. 7) - Removal / Installation	\$26,140.00	16.00
731105	Engine 2	Fuel Spray Nozzle (No. 6) - Removal / Installation	\$26,140.00	16.00
731104	Engine 2	Fuel Spray Nozzle (No. 5) - Removal / Installation	\$26,140.00	16.00
731103	Engine 2	Fuel Spray Nozzle (No. 4) - Removal / Installation	\$26,140.00	16.00
731102	Engine 2	Fuel Spray Nozzle (No. 3) - Removal / Installation	\$26,140.00	16.00
731101	Engine 2	Fuel Spray Nozzle (No. 2) - Removal / Installation	\$26,140.00	16.00
731118	Engine 2	Fuel Spray Nozzle (No. 19) - Removal / Installation	\$26,140.00	16.00
731117	Engine 2	Fuel Spray Nozzle (No. 18) - Removal / Installation	\$26,140.00	16.00
731119	Engine 2	Fuel Spray Nozzle (No. 20) - Removal / Installation	\$26,140.00	16.00
742001	Engine 2	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00

Mandatory Related Codes Totals: \$525,892.50 324.00

742005 Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 4.0
 Engine 1 949
 22 Oct
 2014
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
742001	Engine 1	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00

Mandatory Related Codes Totals: \$3,092.50 4.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

742005 Igniter Plugs (Except CH34726 and CH34735) No. 1 - Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 4.0
(742006) Y242-5 949
 Engine 2 22 Oct 2014
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
742001	Engine 2	Ignitor Plug (No. 1) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:			\$3,092.50	4.00

742007 Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 4.0
 Engine 1 949
 22 Oct 2014
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
742003	Engine 1	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:			\$3,092.50	4.00

742007 Igniter Plugs (Except CH34726 and CH34735) No. 2 - Detailed Inspection 1000 Hrs 3444.5 4444.5Hrs 4444.5 960.5 Hrs 4.0
(742008) 949
 Engine 2 22 Oct 2014
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
742003	Engine 2	Ignitor Plug (No. 2) - Removal / Installation	\$3,092.50	4.00
Mandatory Related Codes Totals:			\$3,092.50	4.00

271303 Aileron Hardover Prevention System (Left) - Operational Check 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 1.5
 Airframe 953
 23 Feb 2015
 G550 AMM Functional/Ops Test (O)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
271103	Airframe	Aileron / Flight Spoiler Control System - Functional Test		2.00
271141	Airframe	Aileron Actuator Load Relief Bungee (Left) - Load Inspection		0.50
Mandatory Related Codes Totals:				2.50

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

271304 Aileron Hardover Prevention System (Right) - Operational Check 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 1.5
 953
 Airframe 23 Feb 2015
 G550 AMM Functional/Ops Test (O)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
271103	Airframe	Aileron / Flight Spoiler Control System - Functional Test		2.00
271142	Airframe	Aileron Actuator Load Relief Bungee (Right) - Load Inspection		0.50

Mandatory Related Codes Totals: 2.50

272301 Rudder Hardover Prevention System - Operational Test 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 4.0
 953
 Airframe 23 Feb 2015
 G550 AMM Functional/Ops Test (F)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
272113	Airframe	Rudder and Trim Control System - Operational Check		3.00

Mandatory Related Codes Totals: 3.00

273032 Longitudinal Control System Friction Check - Inspection / Check 1000 Hrs 3466.6 4466.6Hrs 982.6 Hrs
 953
 Airframe 26 Feb 2015
 G550 AMM Special Inspection (R)

711003 Inlet Cowl Aerodynamic Surfaces (Left) - Detailed Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 1.0
 953
 Airframe 12 Feb 2015
 G550 AMM Special Inspection (R)

711004 Inlet Cowl Aerodynamic Surfaces (Right) - Detailed Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 1.0
 953
 Airframe 12 Feb 2015
 G550 AMM Special Inspection (R)

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
711005	Cowl Fasteners and Attachment Features (Left) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		1.5
	Airframe								16 Feb 2015					
	G550 AMM		Special Inspection (R)											
711006	Cowl Fasteners and Attachment Features (Right) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		1.5
	Airframe								17 Feb 2015					
	G550 AMM		Special Inspection (R)											
711007	Inlet Cowl Rear Bulkhead External Surfaces (Left) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		1.0
	Airframe								18 Feb 2015					
	G550 AMM		Special Inspection (R)											
711008	Inlet Cowl Rear Bulkhead External Surfaces (Right) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		1.0
	Airframe								16 Feb 2014					
	G550 AMM		Special Inspection (R)											
711015	Fixed Cowls (Left) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		2.5
	Airframe								18 Feb 2015					
	G550 AMM		Special Inspection (R)											
711016	Fixed Cowls (Right) - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		2.5
	Airframe								16 Feb 2015					
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
711315	Powerplant and Nacelle Doors Internal (Left) - Zonal Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		3.0
Airframe	G550 AMM		Special Inspection (R)					16 Feb 2015						
711316	Powerplant and Nacelle Doors Internal (Right) - Zonal Inspection							1000 Hrs	3466.5 953	4466.5Hrs		982.5 Hrs		3.0
Airframe	G550 AMM		Special Inspection (R)					16 Feb 2015						
717007	Engine Drains System - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs	4466.5	982.5 Hrs		2.0
Engine 1	G550 AMM		Special Inspection (R)					16 Feb 2015						
717007 (717008)	Engine Drains System - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs	4466.5	982.5 Hrs		2.0
Engine 2	G550 AMM		Special Inspection (R)					12 Feb 2015						
723401	Fan Track / Cold Stream Duct - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs	4466.5	982.5 Hrs		1.5
Engine 1	G550 AMM		Special Inspection (R)					16 Feb 2015						
723401 (723402)	Fan Track / Cold Stream Duct - Detailed Inspection							1000 Hrs	3466.5 953	4466.5Hrs	4466.5	982.5 Hrs		1.5
Engine 2	G550 AMM		Special Inspection (R)					12 Feb 2015						

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

780005 Thrust Reverser and Exhaust (Left) - Zonal Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 6.0
 953
 Airframe 17 Feb 2015
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
783115	Airframe	Thrust Reverser Deactivate / Activate (Left) - Procedure		1.00
Mandatory Related Codes Totals:				1.00

780006 Thrust Reverser and Exhaust (Right) - Zonal Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 6.0
 953
 Airframe 12 Feb 2015
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
783116	Airframe	Thrust Reverser Deactivate / Activate (Right) - Procedure		1.00
Mandatory Related Codes Totals:				1.00

783009 Thrust Reverser Front Face Torsion Box Front Frame (Left) - Detailed Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 6.0
 953
 Airframe 16 Feb 2015
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
783115	Airframe	Thrust Reverser Deactivate / Activate (Left) - Procedure		1.00
Mandatory Related Codes Totals:				1.00

783010 Thrust Reverser Front Face Torsion Box Front Frame (Right) - Detailed Inspection 1000 Hrs 3466.5 4466.5Hrs 982.5 Hrs 6.0
 953
 Airframe 12 Feb 2015
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
783116	Airframe	Thrust Reverser Deactivate / Activate (Right) - Procedure		1.00
Mandatory Related Codes Totals:				1.00

271110 Aileron Inter-column Linkage Disconnect Assemblies - Operational Test 1000 Hrs 3484.0 4484.0Hrs 1000.0 Hrs 4.0
 964
 Airframe 48 MOS 26 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Functional/Ops Test (O)

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
272004	Rudder Torque Tube Bearing - Lubrication							1000 Hrs	3484.0 964	4484.0Hrs		1000.0 Hrs		1.0
Airframe	G550 AMM		Lubrication/Serviceing (L)					48 MOS	31 Dec 2015	31 Dec 2019		45 Mos		
273113	Elevator Inter-Column Linkage Disconnect Assembly - Operational Test							1000 Hrs	3484.0 964	4484.0Hrs		1000.0 Hrs		2.0
Airframe	G550 AMM		Functional/Ops Test (O)					48 MOS	26 Dec 2015	31 Dec 2019		45 Mos		
274106	Emergency Horizontal Stabilizer (Backup Mode) - Operational Test							1000 Hrs	3484.0 964	4484.0Hrs		1000.0 Hrs		1.5
Airframe	G550 AMM		Functional/Ops Test (O)					48 MOS	04 Feb 2016	29 Feb 2020		47 Mos		
276201	Ground Spoiler Auto Deploy Rejected Takeoff Mode - Operational Test							1000 Hrs	3484.0 964	4484.0Hrs		1000.0 Hrs		4.0
Airframe	G550 AMM		Functional/Ops Test (O)					48 MOS	05 Feb 2016	29 Feb 2020		47 Mos		
276202	Ground Spoiler Manual Retract Mode - Operational Test							1000 Hrs	3484.0 964	4484.0Hrs		1000.0 Hrs		2.5
Airframe	G550 AMM		Functional/Ops Test (O)					48 MOS	05 Feb 2016	29 Feb 2020		47 Mos		
792101	Oil Pressure Filter - Detailed Inspection / Discard							1000 Hrs	3484.0 964	4484.0Hrs	4484	1000.0 Hrs		2.0
Engine 1	QA08196							48 MOS	28 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	710017	Engine 1	Engine Run Leak Check Test 2A - LP Fuel System / Oil System		1.00
	792105	Engine 1	Oil System Pressure Filter Element - Removal / Installation	\$792.55	2.00
Mandatory Related Codes Totals:				\$792.55	3.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

792101	Oil Pressure Filter - Detailed Inspection / Discard							1000 Hrs	3484.0	4484.0Hrs	4484	1000.0 Hrs		2.0
(792102)	QA08196								964					
Engine 2								48 MOS	28 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM	Special Inspection (R)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
792105	Engine 2	Oil System Pressure Filter Element - Removal / Installation	\$792.55	2.00
710017	Engine 2	Engine Run Leak Check Test 2A - LP Fuel System / Oil System		1.00
Mandatory Related Codes Totals:			\$792.55	3.00

801011	Air Turbine Starter Magnetic Chip Collector - Detailed Inspection							1000 Hrs	3484.0	4484.0Hrs	4484	1000.0 Hrs		0.5
Engine 1								48 MOS	28 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM	Special Inspection (R)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
801001	Engine 1	Air Turbine Starter - Removal / Installation	\$355,387.79	4.00
121400	Engine 1	Air Turbine Starter Oil - Change		3.00
Mandatory Related Codes Totals:			\$355,387.79	7.00

801011	Air Turbine Starter Magnetic Chip Collector - Detailed Inspection							1000 Hrs	3484.0	4484.0Hrs	4484	1000.0 Hrs		0.5
(801012)									964					
Engine 2								48 MOS	28 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM	Special Inspection (R)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
121400	Engine 2	Air Turbine Starter Oil - Change		3.00
801001	Engine 2	Air Turbine Starter - Removal / Installation	\$355,387.79	4.00
Mandatory Related Codes Totals:			\$355,387.79	7.00

256404	Defibrillator Battery - Inspect / Check								3484.0					0.0
Airframe								12 MOS	14 Jan 2016	14 Jan 2017		10 Mos		
		Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256306	Emergency Locator Transmitter - Operational Test (FAR 91.207)								3484.0					1.0
	453-5060		04832					964						
Airframe								12 MOS	11 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Functional/Ops Test (O)											

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
256301	Airframe	Emergency Locator Transmitter - Removal / Installation	\$6,063.82	1.00
256302	Airframe	Emergency Locator Transmitter Batteries - Discard	\$615.68	1.00

Mandatory Related Codes Totals: \$6,679.50 2.00

262560	Trash Receptacle Enclosure (Aft Lavatory) - Detailed Inspection								3484.0					1.0
								964						
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

262561	Trash Receptacle Enclosure (Forward Lavatory) - Detailed Inspection								3484.0					1.0
								964						
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

262563	Trash Receptacle Enclosure (Forward Galley / Annex) - Detailed Inspection								3484.0					1.0
								964						
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

262583	Trash Receptacle Fire Extinguisher Nozzles (Aft Lavatory) - Detailed Inspection								3484.0					0.0
								964						
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

262584	Trash Receptacle Fire Extinguisher Nozzles (Forward Lavatory) - Detailed Inspection								3484.0					0.0
								964						
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262586	Trash Receptacle Fire Extinguisher Nozzles (Forward Galley / Annex) - Detailed Inspection								3484.0 964						0.0
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos			
	G550 AMM		Special Inspection (R)												

262601	Portable Halon Fire Extinguisher (Cockpit) - Inspection								3484.0 964					1.0
Airframe								12 MOS	14 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262600	Airframe	Portable Halon Fire Extinguisher (Cockpit) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:				\$0.00	1.00

262602	Portable Halon Fire Extinguisher (Cockpit) - Weight Check								3484.0 964					1.0
Airframe								12 MOS	14 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Lubrication/Serviceing (Z)					Weight Check						

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262600	Airframe	Portable Halon Fire Extinguisher (Cockpit) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:				\$0.00	1.00

262611	Portable Halon Fire Extinguisher (Forward Cabin) - Inspection								3484.0 964					1.0
Airframe								12 MOS	14 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262610	Airframe	Portable Halon Fire Extinguisher (Forward Cabin) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:				\$0.00	1.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262612 Portable Halon Fire Extinguisher (Forward Cabin) - Weight Check 3484.0 964 1.0
 Airframe 12 MOS 14 Jan 31 Jan 10 Mos
 2016 2017
 G550 AMM Lubrication/Serviceing (Z) Weight Check

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262610	Airframe	Portable Halon Fire Extinguisher (Forward Cabin) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:			\$0.00	1.00

262631 Portable Halon Fire Extinguisher (Aft Lavatory) - Inspection 3484.0 964 1.0
 Airframe 12 MOS 14 Jan 31 Jan 10 Mos
 2016 2017
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262630	Airframe	Portable Halon Fire Extinguisher (Aft Lavatory) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:			\$0.00	1.00

262632 Portable Halon Fire Extinguisher (Aft Lavatory) - Weight Check 3484.0 964 1.0
 Airframe 12 MOS 14 Jan 31 Jan 10 Mos
 2016 2017
 G550 AMM Lubrication/Serviceing (Z) Weight Check

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262630	Airframe	Portable Halon Fire Extinguisher (Aft Lavatory) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:			\$0.00	1.00

313031 Flight Data Recorder (FDR) - Download And Analyse Whole Flight Recording (EASA EUROCAE) 3000 Hrs 3484.0 6484.0Hrs 3000.0 Hrs
 Airframe 12 MOS 11 Jan 31 Jan 10 Mos
 2016 2017
 EASA SIB No. 2009-28 / ED-112 Special Inspection

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

313035	Cockpit Voice Recorder (CVR) - Read-Out of Recorded Data (EASA ICAO)								3484.0 964						0.0
Airframe								12 MOS	11 Jan 2016	31 Jan 2017		10 Mos			
	EASA SIB No. 2009-28 / ICAO Annex 6		Special Inspection												

353002	Portable Oxygen Bottle and Mask Assembly (No. 1) - Detailed Inspection								3484.0 964					1.5
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	353001	Airframe	Portable Oxygen Bottle (No. 1) - Removal / Installation	\$1,108.40	1.50
Mandatory Related Codes Totals:				\$1,108.40	1.50

382003	Water Sterilizer Filter - Discard								3484.0 964				\$131.61	2.0
Airframe	06-133802-001		NSN	0.0	0	0		12 MOS	20 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Replacement (X)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	382002	Airframe	Water Sterilizer Filter - Removal / Installation	\$131.61	4.00
Mandatory Related Codes Totals:				\$131.61	4.00

521010	Main Entrance Door - Lubrication								3484.0 964					2.0
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Lubrication/Serviceing (L)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	521015	Airframe	Main Entrance Door - Operating Procedures		2.00
Mandatory Related Codes Totals:					2.00

523005	Baggage Compartment Door - Lubrication								3484.0 964					2.0
Airframe								12 MOS	07 Jan 2016	31 Jan 2017		10 Mos		
	G550 AMM		Lubrication/Serviceing (L)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)				
	MM Ref		Event Category		@= Adjustments										
525001	Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection								3484.0 964						3.0
Airframe								12 MOS	13 Jan 2016	31 Jan 2017		10 Mos			
	G550 AMM		Special Inspection (M)												
256270	Life Raft (No. 1) - Restore								3272.4 917					\$13,851.47	2.0
Airframe	1421FAUL-6KO-1-100		14UL-00240		1485.0	374	35	36 MOS	27 Feb 2014	21 Feb 2017		11 Mos			
	No				1485.000 Hrs 374.000 Cyc/Lnd					Expiration					
	G550 AMM		Overhaul (T)												
Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours							
	256260	Airframe	Life Raft (No. 1) - Removal / Installation				\$13,851.47	1.00							
						Mandatory Related Codes Totals:	\$13,851.47	1.00							
256272	Life Raft (No. 3) - Restore								3272.4 917					\$13,851.47	2.0
Airframe	1421FAUL-6KO-1-100		14UL-00242		1485.0	374	35	36 MOS	27 Feb 2014	21 Feb 2017		11 Mos			
	No				1485.000 Hrs 374.000 Cyc/Lnd					Expiration					
	G550 AMM		Overhaul (T)												
Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours							
	256262	Airframe	Life Raft (No. 3) - Removal / Installation				\$13,851.47	1.00							
						Mandatory Related Codes Totals:	\$13,851.47	1.00							
981710 (R)	CB 171 Inspection - Auxiliary Power Unit (APU) Fuel Shut-off Valve								0.0 0						1.0
Airframe								12MOS**		22 Feb 2017		11 Mos			
			Required Bulletin												
240121	Emergency Battery Power System (Left) - Operational Test								3484.0 964						1.0
Airframe								12 MOS	13 Feb 2016	28 Feb 2017		11 Mos			
	G550 AMM		Functional/Ops Test (O)												
240122	Emergency Battery Power System (Right) - Operational Test								3484.0 964						1.0
Airframe								12 MOS	13 Feb 2016	28 Feb 2017*		11 Mos			
	G550 AMM		Functional/Ops Test (O)												

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
240123	Emergency Battery Power System (Forward) - Operational Test								3484.0						1.0
	G550 AMM		Functional/Ops Test (O)					964							
Airframe								12 MOS	13 Feb 2016	28 Feb 2017		11 Mos			
240124	Emergency Battery Power System (Aft) - Operational Test								3484.0						1.0
	G550 AMM		Functional/Ops Test (O)					964							
Airframe								12 MOS	13 Feb 2016	28 Feb 2017		11 Mos			
243011	L Main Battery - Capacity Check								3484.0						4.0
	1159SCAV519-1		0905200068328					964							
Airframe								12 MOS	14 Jan 2016	28 Feb 2017*		11 Mos			
	G550 AMM		Special Inspection (R)												
Mandatory Related Codes:															
	Code	Logbook	Description				Parts Cost	Labor Hours							
	243001	Airframe	Main Battery (Left) - Removal / Installation				\$18,874.40	2.00							
						Mandatory Related Codes Totals:	\$18,874.40	2.00							
243012	R Main Battery - Capacity Check								3484.0						4.0
	G550 AMM		Special Inspection (R)					964							
Airframe								12 MOS	21 Jan 2016	28 Feb 2017*		11 Mos			
Mandatory Related Codes:															
	Code	Logbook	Description				Parts Cost	Labor Hours							
	243002	Airframe	Main Battery (Right) - Removal / Installation				\$18,874.40	2.00							
						Mandatory Related Codes Totals:	\$18,874.40	2.00							
256071	Flashlight (No. 1) - Operational Test								3484.0						1.0
	G550 AMM		Functional/Ops Test (O)					964							
Airframe								12 MOS	07 Jan 2016	28 Feb 2017*		11 Mos			
256072	Flashlight (No. 2) - Operational Test								3484.0						1.0
	G550 AMM		Functional/Ops Test (O)					964							
Airframe								12 MOS	07 Jan 2016	28 Feb 2017*		11 Mos			

Code	Description						Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)		
	MM Ref		Event Category		@= Adjustments								
256073	Flashlight (No. 3) - Operational Test							3484.0 964					1.0
	Airframe							12 MOS	07 Jan 2016	28 Feb 2017*	11 Mos		
	G550 AMM		Functional/Ops Test (O)										
256074	Flashlight (No. 4) - Operational Test							3484.0 964					1.0
	Airframe							12 MOS	07 Jan 2016	28 Feb 2017*	11 Mos		
	G550 AMM		Functional/Ops Test (O)										

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256201 Life Vest(s) - Detailed Inspection 3484.0 2.0
964
 Airframe 12 MOS 21 Jan 28 Feb 11 Mos
2016 2017*
G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
256250	Airframe	Life Vest (Pilot) - Removal / Installation	\$89.88	1.00
256251	Airframe	Life Vest (Copilot) - Removal / Installation	\$89.88	1.00
256252	Airframe	Life Vest (Observer) - Removal / Installation	\$89.88	1.00
256253	Airframe	Life Vest (Crew Member) - Removal / Installation	\$89.88	1.00
256211	Airframe	Life Vest (No. 1) - Removal / Installation	\$89.88	1.00
256212	Airframe	Life Vest (No. 2) - Removal / Installation	\$89.88	1.00
256213	Airframe	Life Vest (No. 3) - Removal / Installation	\$89.88	1.00
256214	Airframe	Life Vest (No. 4) - Removal / Installation	\$89.88	1.00
256215	Airframe	Life Vest (No. 5) - Removal / Installation	\$89.88	1.00
256216	Airframe	Life Vest (No. 6) - Removal / Installation	\$89.88	1.00
256217	Airframe	Life Vest (No. 7) - Removal / Installation	\$89.88	1.00
256218	Airframe	Life Vest (No. 8) - Removal / Installation	\$89.88	1.00
256219	Airframe	Life Vest (No. 9) - Removal / Installation	\$89.88	1.00
256220	Airframe	Life Vest (No. 10) - Removal / Installation	\$89.88	1.00
256221	Airframe	Life Vest (No. 11) - Removal / Installation	\$89.88	1.00
256222	Airframe	Life Vest (No. 12) - Removal / Installation	\$89.88	1.00
256223	Airframe	Life Vest (No. 13) - Removal / Installation	\$89.88	1.00
256224	Airframe	Life Vest (No. 14) - Removal / Installation	\$89.88	1.00
256225	Airframe	Life Vest (No. 15) - Removal / Installation	\$89.88	1.00
256226	Airframe	Life Vest (No. 16) - Removal / Installation	\$89.88	1.00
256227	Airframe	Life Vest (No. 17) - Removal / Installation	\$89.88	1.00
256228	Airframe	Life Vest (No. 18) - Removal / Installation	\$89.88	1.00
Mandatory Related Codes Totals:			\$1,977.36	22.00

256202 Life Raft(s) (No. 1) - Detailed Inspection 3484.0 1.0
964
 Airframe 12 MOS 13 Jan 28 Feb 11 Mos
2016 2017*
G550 AMM Special Inspection (R)

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
256203	Life Raft(s) (No. 2) - Detailed Inspection								3484.0 964						1.0
Airframe								12 MOS	13 Jan 2016	28 Feb 2017*		11 Mos			
	G550 AMM		Special Inspection (R)												
335020	Cabin Emergency Lighting - Operational Test								3484.0 964						1.0
Airframe								12 MOS	13 Feb 2016	28 Feb 2017*		11 Mos			
	G550 AMM		Functional/Ops Test (O)												
256011	Crew Smoke Goggles (Pilot) - Detailed Inspection								3307.8 927						1.0
Airframe								36 MOS	18 Mar 2014	31 Mar 2017*		12 Mos			
	G550 AMM		Special Inspection (R)												
256012	Crew Smoke Goggles (Copilot) - Detailed Inspection								3307.8 927						1.0
Airframe								36 MOS	18 Mar 2014	31 Mar 2017*		12 Mos			
	G550 AMM		Special Inspection (R)												
256013	Crew Smoke Goggles (Observer) - Detailed Inspection								3307.8 927						1.0
Airframe								36 MOS	18 Mar 2014	31 Mar 2017*		12 Mos			
	G550 AMM		Special Inspection (R)												
274202	Horizontal Stabilizer Actuator - Lubrication								3307.1 927						4.0
Airframe								36 MOS	18 Mar 2014	31 Mar 2017*		12 Mos			
	G550 AMM		Lubrication/Serviceing (L)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

316206	Configuration Message - Operational Test								3307.8 927						12.0
Airframe								36 MOS	31 Mar 2014	31 Mar 2017		12 Mos			
	G550 AMM		Functional/Ops Test (O)												

352004	Passenger Oxygen Drop-down Mask Assemblies - Detailed Inspection								3307.8 927						1.0
Airframe								36 MOS	20 Mar 2014	31 Mar 2017*		12 Mos			
	G550 AMM		Special Inspection (M)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	352009	Airframe	Passenger Oxygen System (Auto / Manual Mode) - Functional Test		4.50
Mandatory Related Codes Totals:					4.50

352009	Passenger Oxygen System (Auto / Manual Mode) - Functional Test								3307.8 927					4.5
Airframe								36 MOS	19 Mar 2014	31 Mar 2017*		12 Mos		
	G550 AMM		Functional/Ops Test (F)											

353004	Portable Oxygen System (No. 1 Bottle) - Operational Test								3307.8 927					1.0
Airframe								36 MOS	19 Mar 2014	31 Mar 2017*		12 Mos		
	G550 AMM		Functional/Ops Test (O)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	353001	Airframe	Portable Oxygen Bottle (No. 1) - Removal / Installation	\$1,108.40	1.50
Mandatory Related Codes Totals:				\$1,108.40	1.50

521009	Main Entrance Door Hinge Pins - Detailed Inspection								3307.8 927					5.0
Airframe								36 MOS	18 Mar 2014	31 Mar 2017*		12 Mos		
	G550 AMM		Special Inspection (M)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									

262512	Portable Water Fire Extinguisher (Forward Cabin, Hydrostatic) - Functional Test								2354.6						1.0
	892480		19164					711							
Airframe								60 MOS	19 Apr 2012	30 Apr 2017		13 Mos			
	G550 AMM		Lubrication/Serviceing (Z)							Hydrostatic					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		262510	Airframe	Portable Water Fire Extinguisher (Forward Cabin) - Removal / Installation	\$2,439.76	1.00
Mandatory Related Codes Totals:					\$2,439.76	1.00

323012	Landing Gear Emergency Extension Nitrogen Blow-down Bottle (Right) - (Hydrostatic) Functional Test								2354.6						3.0
	1159SCH233-11		ALT 603-10595					711							
Airframe								60 MOS	19 Apr 2012	30 Apr 2017		13 Mos			
	G550 AMM		Functional/Ops Test (F)							Hydrostatic					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		323011	Airframe	Landing Gear Emergency Extension Nitrogen Blow-down Bottle (Right) - Removal / Installation	\$961.07	3.00
Mandatory Related Codes Totals:					\$961.07	3.00

351211	Crew Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test								2354.6						8.0
	805983-15		C07091607					711							
Airframe								60 MOS	19 Apr 2012	30 Apr 2017		13 Mos			
	G550 AMM		Functional/Ops Test (F)							Hydrostatic					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		351221	Airframe	Crew Oxygen Cylinder and Regulator Assembly - Removal / Installation	\$1,902.93	8.00
Mandatory Related Codes Totals:					\$1,902.93	8.00

351212	Passenger Oxygen Bottle (No. 2) - (Hydrostatic) Functional Test								2354.6						8.0
	805983-15		C07091608					711							
Airframe								60 MOS	19 Apr 2012	30 Apr 2017		13 Mos			
	G550 AMM		Functional/Ops Test (F)							Hydrostatic					

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		351222	Airframe	Passenger Oxygen Cylinder (No. 2) - Removal / Installation	\$1,902.93	8.00
Mandatory Related Codes Totals:					\$1,902.93	8.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

353003	Portable Oxygen Bottle (No. 1) - (Hydrostatic) Functional Test								2354.6						1.0
	5600-9M6A-F30AN		P07081327					711							
Airframe								60 MOS	19 Apr 2012	30 Apr 2017		13 Mos			
	G550 AMM		Functional/Ops Test (F)							Hydrostatic					

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	353001	Airframe	Portable Oxygen Bottle (No. 1) - Removal / Installation	\$1,108.40	1.50
Mandatory Related Codes Totals:				\$1,108.40	1.50

313006	DFDR Underwater Locator Beacon - Battery Discard (DK120)								2529.2				\$1,893.75	1.0
	DK120		SC90711		0.0	0	17	755						
Airframe	No							72 MOS	29 Aug 2012	01 Jun 2017		15 Mos		
	G550 AMM		Replacement (X)							Expiration				

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	313009	Airframe	DFDR Underwater Locator Beacon - Battery Replacement (DK120)	\$1,893.75	0.00
Mandatory Related Codes Totals:				\$1,893.75	0.00

313010	DFDR Underwater Locator Beacon - Operational Test								2529.2					2.0
								755						
Airframe								72 MOS	29 Aug 2012	30 Jun 2017*		15 Mos		
	G550 AMM		Functional/Ops Test (F)											

981601 (R)	CB 160A Modification - Pressure Supply Line (ASC 122)								0.0					
								0						
Airframe								24MOS**		15 Jul 2017		16 Mos		
			Required Bulletin											

262021	Engine Fire Bottle (Left) - (Hydrostatic) Functional Test								0.0					1.0
	33800100-1		6042401					0						
Airframe								120 MOS	26 Nov 2007	30 Sep 2017		18 Mos		
	G550 AMM		Lubrication/Serviceing (Z)							Hydrostatic				

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262020	Airframe	Engine Fire Bottle (Left) - Removal / Installation	\$25,031.26	4.00
Mandatory Related Codes Totals:				\$25,031.26	4.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

335006	Emergency Floorpath Lighting Battery Pack (Deep Cycle) No. 1 - Functional Test								3484.0						8.0
								964							
Airframe								18 MOS	03 Mar 2016	30 Sep 2017		18 Mos			
	G550 AMM		Lubrication/Service (S)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	335016	Airframe	Emergency Floorpath Lighting Battery Pack No. 1 - Removal / Installation	\$2,203.76	0.00
Mandatory Related Codes Totals:				\$2,203.76	0.00

335007	Emergency Floorpath Lighting Battery Pack (Deep Cycle) No. 2 - Functional Test								3484.0					8.0
								964						
Airframe								18 MOS	03 Mar 2016	30 Sep 2017		18 Mos		
	G550 AMM		Lubrication/Service (S)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	335017	Airframe	Emergency Floorpath Lighting Battery Pack No. 2 - Removal / Installation	\$2,203.76	0.00
Mandatory Related Codes Totals:				\$2,203.76	0.00

335008	Emergency Floorpath Lighting Battery Pack (Deep Cycle) No. 3 - Functional Test								3484.0					8.0
								964						
Airframe								18 MOS	03 Mar 2016	30 Sep 2017		18 Mos		
	G550 AMM		Lubrication/Service (S)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	335018	Airframe	Emergency Floorpath Lighting Battery Pack No. 3 - Removal / Installation	\$2,203.76	0.00
Mandatory Related Codes Totals:				\$2,203.76	0.00

256271	Life Raft (No. 2) - Restore							3444.5					\$13,851.47	2.0
	1421FAUL-6KO-1-100		14UL-00241					949						
Airframe	No		0.0	0	1	36 MOS	03 Nov 2014	01 Oct 2017			19 Mos			
	G550 AMM		Overhaul (T)					Expiration						

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	256261	Airframe	Life Raft (No. 2) - Removal / Installation	\$14,267.01	1.00
Mandatory Related Codes Totals:				\$14,267.01	1.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262026	Engine Fire Bottle (Right) - (Hydrostatic) Functional Test							0.0						1.0
	33800100-1		60539D1					0						
Airframe								120 MOS	26 Nov 2007	31 Oct 2017		19 Mos		
	G550 AMM		Lubrication/Service (Z)							Hydrostatic				

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262025	Airframe	Engine Fire Bottle (Right) - Removal / Installation	\$25,031.26	4.00

Mandatory Related Codes Totals: \$25,031.26 4.00

262108	Engine Fire Bottle Cartridge (Right Bottle, Spare Squib, Service Life) - Discard							0.0					\$984.40	2.0
	30903933		1152HF		0.0	0	0	0						
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017		20 Mos		
	G550 AMM		Replacement (X)											

262110	Engine Fire Bottle Cartridge (Left Bottle, Left Squib, Service Life) - Discard							0.0					\$2,029.49	2.0
	30903959		1667hh		0.0	0	0	0						
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017		20 Mos		
	G550 AMM		Replacement (X)											

262112	Engine Fire Bottle Cartridge (Left Bottle, Right Squib, Service Life) - Discard							0.0					\$659.62	2.0
	30903931		1232hh		0.0	0	0	0						
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017		20 Mos		
	G550 AMM		Replacement (X)											

262114	Engine Fire Bottle Cartridge (Right Bottle, Left Squib, Service Life) - Discard							0.0					\$2,029.49	2.0
	30903959		1663HH		0.0	0	0	0						
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017		20 Mos		
	G550 AMM		Replacement (X)											

262116	Engine Fire Bottle Cartridge (Right Bottle, Right Squib, Service Life) - Discard							0.0					\$659.62	2.0
	30903931		0405HJ		0.0	0	0	0						
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017		20 Mos		
	G550 AMM		Replacement (X)											

Code	Description						Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)		
	MM Ref		Event Category		@= Adjustments								
262118	Engine Fire Bottle Cartridge (Left Bottle, APU / Spare Squib, Service Life) - Discard							0.0				\$984.40	2.0
	30903933		2166hh		0.0	0	0	0					
Airframe	No							120 MOS	26 Nov 2007	30 Nov 2017	20 Mos		
	G550 AMM		Replacement (X)										
981660 (R)	CB 166 Inspection - Rudder Actuator Return Line for Contact With Elevator Torque Tube							0.0					1.0
								24MOS**		10 Dec 2017	21 Mos		
Airframe			Required Bulletin										
493402	Fuel Filter Bypass Indicator - Detailed Inspection (Delta P Indicator)						600 Hrs	1981.0	2581.0Hrs		490.5 Hrs		1.0
	APU 1							0	17 Mar 2014				
	G550 AMM		Special Inspection (R)										
494002	APU Starter - Detailed Inspection						600 Hrs	1981.0	2581.0Hrs		490.5 Hrs		2.0
	APU 1							0	17 Mar 2014				
	G550 AMM		Special Inspection (R)										
498001	APU Exhaust Duct - General Visual Inspection						600 Hrs	1981.0	2581.0Hrs		490.5 Hrs		3.0
	APU 1							0	17 Mar 2014				
	G550 AMM		Special Inspection (R)										
231113	Securaplane 500 Components - GVI							3484.0					
								964					
Airframe								24 MOS	10 Jan 2016	10 Jan 2018	22 Mos		
			Special Inspection (M)										

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
231108	Airshow 4000 Sys Components - GVI								3484.0 964						
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
	ST02048CH-D		Special Inspection (M)												
232134	Magnastar MCS-7000 - Visual Inspection, Above Floor								3484.0 964						2.0
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
	STC ST02047CH-D		Special Inspection (R)												
232138	Radiotelephone Cabin Components GVI								3484.0 964						
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
	STC ST02047CH-D ICA		Special Inspection (R)												
232146	Securaplane 500 Above Floor - Visual Inspection								3484.0 964						
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
	STC STO2049CH-D ICA		Special Inspection (R)												
232158	Airshow 4000 Above Floor - Visual Inspection								3484.0 964						2.0
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
			Special Inspection (R)												
237226	Securaplane 500 Component Inspection								3484.0 964						
Airframe								24 MOS	10 Jan 2016	31 Jan 2018		22 Mos			
			Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									
251008	Crew Seats Inertia Reel (Observer) - Operational Test								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (O)											
251016	Crew Seat Restraints (Pilot) - Detailed Inspection								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											
251017	Crew Seat Restraints (Copilot) - Detailed Inspection								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											
251018	Crew Seat Restraints (Observer) - Detailed Inspection								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											
252102	Passenger Seats Restraints - Detailed Inspection								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (M)											
252104	Passenger Seats Inertia Reels - Operational Test								3484.0 964					1.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (M)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256205	Life Vest - Restore								7.2						2.0
Airframe	No				0.0	0	0	120 MOS	04 Mar 2008	31 Jan 2018		22 Mos			
	G550 AMM		Overhaul (T)												

261302	APU (Fire) Shutdown Circuit - Operational Test								3484.0						2.0
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	282641	Airframe	APU Fuel Shut-off Valve - Operational Check		2.00
Mandatory Related Codes Totals:					2.00

262122	Engine and APU Fire Extinguishing Firing Circuitry (Left Engine) - Integrity Test								3484.0					1.5
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (O)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262020	Airframe	Engine Fire Bottle (Left) - Removal / Installation	\$25,031.26	4.00
Mandatory Related Codes Totals:				\$25,031.26	4.00

262123	Engine and APU Fire Extinguishing Firing Circuitry (Right Engine) - Integrity Test								3484.0					2.0
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (F)											

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	262025	Airframe	Engine Fire Bottle (Right) - Removal / Installation	\$25,031.26	4.00
Mandatory Related Codes Totals:				\$25,031.26	4.00

262124	Engine Fire Bottle Pressure Switch (Left) - Operational Test								3484.0					1.0
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (O)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262125	Engine Fire Bottle Pressure Switch (Right) - Operational Test								3484.0 964						1.0
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

262126	Engine and APU Fire Extinguishing Firing Circuitry (APU) - Integrity Test								3484.0 964						1.0
Airframe								24 MOS	09 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	262020	Airframe	Engine Fire Bottle (Left) - Removal / Installation				\$25,031.26	4.00
						Mandatory Related Codes Totals:	\$25,031.26	4.00

271011	Aileron Control and Trim Cables in Main Wheel Wells / Wing Trailing Edge - Detailed Inspection								3484.0 964						2.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

272108	Rudder Control and Trim Cables in Main Wheel Well / Tail Compartment - Detailed Inspection								3484.0 964						2.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

273100	Elevator Control and Trim Cables in Main Wheel Well and Tail Compartment - Detailed Inspection								3484.0 964						6.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

276105	Speed Brake Cable Assemblies in Main Wheel Well / Wing Trailing Edge - Detailed Inspection								3484.0 964						6.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
282606	Engine Feed Dual Wall Fuel Line (Left) - Detailed Inspection								3484.0 964						1.0
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
282607	Engine Feed Dual Wall Fuel Line (Right) - Detailed Inspection								3484.0 964					1.0	
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
282608	APU Feed Dual Wall Fuel Line - Detailed Inspection								3484.0 964					1.0	
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
282609	Engine Heated Return Feed Dual Wall Fuel Line (Left) - Detailed Inspection								3484.0 964					1.0	
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (M)												
282610	Engine Heated Return Feed Dual Wall Fuel Line (Right) - Detailed Inspection								3484.0 964					1.0	
	Airframe							24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (M)												
282629	Engine Fuel Shut-off Valve (Left) - Operational Check								3484.0 964					1.0	
	Airframe							24 MOS	20 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

282630	Engine Fuel Shut-off Valve (Right) - Operational Check								3484.0						1.0
									964						
Airframe								24 MOS	20 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

313002	DFDR - Functional Test								3484.0						4.0
	2100-2043-00		000147482						964						
Airframe								24 MOS	11 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (F)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	313001	Airframe	DFDR - Removal / Installation	\$33,048.58	2.00
Mandatory Related Codes Totals:				\$33,048.58	2.00

316205	DFDR Fail Message - Operational Test								3484.0						0.5
	2100-2043-00		000147482						964						
Airframe								24 MOS	11 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

323037	Main Landing Gear Bungee (Left) - Lubrication								3484.0						3.0
	1159L50903-001		NSN						964						
Airframe								24 MOS	15 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Lubrication/Serviceing (L)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	323039	Airframe	Main Landing Gear Bungee (Left) - Removal / Installation	\$3,054.18	3.00
Mandatory Related Codes Totals:				\$3,054.18	3.00

323038	Main Landing Gear Bungee (Right) - Lubrication								3484.0						3.0
									964						
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Lubrication/Serviceing (L)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	323040	Airframe	Main Landing Gear Bungee (Right) - Removal / Installation	\$3,054.18	3.00
Mandatory Related Codes Totals:				\$3,054.18	3.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

381300	Supply Line Motor Drain Valve - Operational Test								3484.0 964					2.0
Airframe								24 MOS	21 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (O)											

381301	Drain Line Motor Drain Valve - Operational Test								3484.0 964					2.0
Airframe								24 MOS	21 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Functional/Ops Test (O)											

491005	APU Enclosure FS 767 - FS 797 - Zonal Inspection								3484.0 964					3.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

491300	APU Compartment Drain Collectors - General Visual Inspection								3484.0 964					
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

523003	Baggage Compartment Door Seal - Detailed Inspection								3484.0 964					4.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	523001	Airframe	Baggage Door - Removal / Installation				\$0.00	12.00
Mandatory Related Codes Totals:						\$0.00	12.00	

523004	Baggage Compartment Door Seal Air Supply Moisture Drain Orifice - Detailed Inspection								3484.0 964					2.0
Airframe								24 MOS	20 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

523008	Baggage Door Seal Check Valve - Operational Test								3484.0 964						3.0
Airframe								24 MOS	20 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

527001	Main Entrance Door Secondary Handle Lock Switch and Circuitry - Operational Test								3484.0 964						6.0
Airframe								24 MOS	20 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Functional/Ops Test (O)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	521015	Airframe	Main Entrance Door - Operating Procedures		2.00
Mandatory Related Codes Totals:					2.00

530201	Radome to Structure Perimeter Steps - Detailed Inspection								3484.0 964						3.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

531005	External Lower Fuselage FS -4 thru FS 758 View From Ground - Zonal Inspection								3484.0 964						2.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

531055	Aft Cabin Below Floor FS 632 - FS 684 - Zonal Inspection								3484.0 964						6.0
Airframe								24 MOS	14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	530027	Airframe	Floorboard Clip Nut - Check		0.50
Mandatory Related Codes Totals:					0.50

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

531060	Baggage Compartment Below Floor FS 684 - FS 758 - Zonal Inspection								3484.0						4.0
	Airframe							24 MOS	21 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
530027	Airframe	Floorboard Clip Nut - Check		0.50

Mandatory Related Codes Totals: 0.50

531065	External Upper Fuselage FS 63 - FS 758 View From Ground - Zonal Inspection								3484.0					2.0
	Airframe							24 MOS	13 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

531080	Left Electronic Equipment Rack FS 141 - FS 166 - Zonal Inspection								3484.0					3.0
	Airframe							24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

531081	Right Electronic Equipment Rack FS 147 - FS 181 - Zonal Inspection								3484.0					3.0
	Airframe							24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

531082	Electronic Equipment Rack FS 147 - FS 181 - (Enhanced) Zonal Inspection								3484.0					3.0
	Airframe							24 MOS	09 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (M)											

531085	External Aft Fuselage and Empennage FS 758 - FS 1123 Viewed From Ground - Zonal Inspection								3484.0					2.0
	Airframe							24 MOS	13 Jan 2016	31 Jan 2018		22 Mos		
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
531095	Aft Fuselage Above Floor FS 758 - FS 974 - Zonal Inspection								3484.0 964						6.5
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
570009	Wing Lower Surface (Left) - Zonal Inspection								3484.0 964						2.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
570010	Wing Lower Surface (Right) - Zonal Inspection								3484.0 964						2.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
570015	Lower Wing Extension BL 542 - BL 545 (View from Ground) {Left} - Zonal Inspection								3484.0 964						2.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
570016	Lower Wing Extension BL 542 - BL 545 (View from Ground) {Right} - Zonal Inspection								3484.0 964						2.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
574015	Wing Leading Edge External BL 44.0 - BL 529 Inboard of Navigation Light (Left) - Zonal Inspection								3484.0 964						1.0
Airframe								24 MOS	13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
574016	Wing Leading Edge External BL 44.0 - BL 529 Inboard of Navigation Light (Right) - Zonal Inspection								3484.0						1.0
Airframe								24 MOS	964 13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
575001	Wing Trailing Edge (Left) - Zonal Inspection								3484.0					1.0	
Airframe								24 MOS	964 13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
575002	Wing Trailing Edge (Right) - Zonal Inspection								3484.0					1.0	
Airframe								24 MOS	964 13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
575003	Wing Rear Beam (Left) - Zonal Inspection								3484.0					3.0	
Airframe								24 MOS	964 14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
575004	Wing Rear Beam (Right) - Zonal Inspection								3484.0					3.0	
Airframe								24 MOS	964 14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
575021	Wing Rear Beam (Left Enhanced) - Zonal Inspection								3484.0					3.5	
Airframe								24 MOS	964 14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (M)												

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type	Ops Number(s)						
	MM Ref		Event Category		@= Adjustments										
575022	Wing Rear Beam (Right Enhanced) - Zonal Inspection								3484.0						3.5
Airframe								24 MOS	964 14 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (M)												
711301	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (viewed from ground) - Zonal Inspection								3484.0					1.5	
Engine 1								24 MOS	964 13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
711301 (711302)	External - Powerplants, Pylons, Cowl Doors, Inlet Areas, Thrust Reverser and Nose Cows (viewed from ground) - Zonal Inspection								3484.0					1.5	
Engine 2								24 MOS	964 13 Jan 2016	31 Jan 2018		22 Mos			
	G550 AMM		Special Inspection (R)												
981690 (R)	CB 169 Inspection - Wire Installation in Right Electrical Equipment Rack (REER) Circuit Breaker (CB) Panel								0.0					2.0	
Airframe								24MOS**	0	16 Feb 2018		23 Mos			
			Required Bulletin												
232135	Magnastar MCS-7000 - Functional Check								3484.0					2.0	
Airframe								24 MOS	964 29 Feb 2016	28 Feb 2018		23 Mos			
	STC ST02047CH-D		Functional/Ops Test (F)												
232165	Airshow 4000 System - Functional Test								3484.0					2.0	
Airframe								24 MOS	964 29 Feb 2016	28 Feb 2018		23 Mos			
	STC STO2048CH-D		Functional/Ops Test (F)												

Code	Description						Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number	Serial Number	TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)		
	MM Ref	Event Category		@= Adjustments									
237228	Securaplane 500 Security System-Func test							3484.0 964					4.0
Airframe							24 MOS	29 Feb 2016	28 Feb 2018		23 Mos		
	STO2049CH-D	Functional/Ops Test (F)											
237229	Securaplane 500 Battery Pack Functional Test							3484.0 964					
Airframe							24 MOS	29 Feb 2016	28 Feb 2018		23 Mos		
		Functional/Ops Test (F)											
256283	Protective Breathing Equipment (No. 1) - Discard							7.2 6				\$1,799.62	1.5
Airframe	MR-10039N No	E0703172	0.0	0	1		120 MOS	04 Mar 2008	28 Feb 2018		23 Mos		
	G550 AMM	Replacement (X)		1						Expiration			
Mandatory Related Codes:													
	Code	Logbook	Description				Parts Cost	Labor Hours					
	256281	Airframe	Protective Breathing Equipment (No. 1) - Removal / Installation				\$1,799.62	1.50					
						Mandatory Related Codes Totals:	\$1,799.62	1.50					
321221	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Left)							3484.0 964					20.0
Airframe							24 MOS	05 Feb 2016	28 Feb 2018		23 Mos		
	G550 AMM	Lubrication/Serviceing (S)											
321222	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Right)							3484.0 964					20.0
Airframe							24 MOS	05 Feb 2016	28 Feb 2018		23 Mos		
	G550 AMM	Lubrication/Serviceing (S)											
323023	Main Landing Gear Spindle Pin Freeplay (Left) - Detailed Inspection							3466.5 953					3.0
Airframe							36 MOS	12 Feb 2015	28 Feb 2018*		23 Mos		
	G550 AMM	Special Inspection (R)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

323024	Main Landing Gear Spindle Pin Freeplay (Right) - Detailed Inspection								3466.5 953						3.0
Airframe								36 MOS	12 Feb 2015	28 Feb 2018*		23 Mos			
	G550 AMM		Special Inspection (R)												

324303	Parking / Emergency Brake - Operational Test								3466.5 953						1.0
Airframe								36 MOS	18 Feb 2015	28 Feb 2018		23 Mos			
	G550 AMM		Functional/Ops Test (O)												

341023	Air Data Module No. 1 - Certification								3484.0 964						4.0
Airframe	HG1153CA04		07102631						24 MOS	05 Feb 2016	28 Feb 2018 Calibration		23 Mos		
	G550 AMM		Lubrication/Serviceing (Z)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	341304	Airframe	Air Data System No. 1 - Functional / Leak Test		4.00
Mandatory Related Codes Totals:					4.00

341024	Air Data Module No. 2 - Certification								3484.0 964						4.0
Airframe	HG1153CA04		07102632						24 MOS	05 Feb 2016	28 Feb 2018 Calibration		23 Mos		
	G550 AMM		Lubrication/Serviceing (Z)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	341305	Airframe	Air Data System No. 2 - Functional / Leak Test		4.00
Mandatory Related Codes Totals:					4.00

341025	Air Data Module No. 3 - Certification								3484.0 964						4.0
Airframe	HG1153CA04		07102635						24 MOS	05 Feb 2016	28 Feb 2018 Calibration		23 Mos		
	G550 AMM		Lubrication/Serviceing (Z)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	341306	Airframe	Air Data System No. 3 - Functional / Leak Test		4.00
Mandatory Related Codes Totals:					4.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

341304	Air Data System No. 1 - Functional / Leak Test								3484.0						4.0
	HG1153CA04		07102631					964							
Airframe								24 MOS	05 Feb 2016	28 Feb 2018		23 Mos			
	G550 AMM		Functional/Ops Test (F)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
530205	Airframe	Birdstrike Plate (Left) - Removal / Installation	\$0.00	2.00
530206	Airframe	Birdstrike Plate (Right) - Removal / Installation	\$3,153.07	2.00
Mandatory Related Codes Totals:			\$3,153.07	4.00

341305	Air Data System No. 2 - Functional / Leak Test								3484.0					4.0
	HG1153CA04		07102632					964						
Airframe								24 MOS	05 Feb 2016	28 Feb 2018		23 Mos		
	G550 AMM		Functional/Ops Test (F)											

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
530205	Airframe	Birdstrike Plate (Left) - Removal / Installation	\$0.00	2.00
530206	Airframe	Birdstrike Plate (Right) - Removal / Installation	\$3,153.07	2.00
Mandatory Related Codes Totals:			\$3,153.07	4.00

341306	Air Data System No. 3 - Functional / Leak Test								3484.0					4.0
	HG1153CA04		07102635					964						
Airframe								24 MOS	05 Feb 2016	28 Feb 2018		23 Mos		
	G550 AMM		Functional/Ops Test (F)											

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
530205	Airframe	Birdstrike Plate (Left) - Removal / Installation	\$0.00	2.00
530206	Airframe	Birdstrike Plate (Right) - Removal / Installation	\$3,153.07	2.00
Mandatory Related Codes Totals:			\$3,153.07	4.00

341307	Standby Pitot / Static System - Functional / Leak Test								3484.0					4.0
	501-1860-0102		0368					964						
Airframe								24 MOS	05 Feb 2016	28 Feb 2018		23 Mos		
	G550 AMM		Functional/Ops Test (F)											

345305	ATC No. 1 - Functional Test / Inspection (FAR 91.413)								3484.0					4.0
	7517400-950		0605B157					964						
Airframe								24 MOS	05 Feb 2016	28 Feb 2018	Certification	23 Mos		
	G550 AMM		Functional/Ops Test (F)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
345306	ATC No. 2 - Functional Test / Inspection (FAR 91.413)								3484.0						4.0
	7517400-950		0710D297						964						
Airframe								24 MOS	05 Feb 2016	28 Feb 2018		23 Mos			
	G550 AMM		Functional/Ops Test (F)							Certification					
242005	Standby Electrical Power System - Operational Test								3484.0						1.0
									964						
Airframe								24 MOS	12 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Functional/Ops Test (O)												
291501	Hydraulic System Shut-off Valve (Left) - Operational Test								3484.0						2.0
									964						
Airframe								24 MOS	05 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Functional/Ops Test (O)												
291502	Hydraulic System Shut-off Valve (Right) - Operational Test								3484.0						2.0
									964						
Airframe								24 MOS	05 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Functional/Ops Test (O)												
322220	Nose Landing Gear Corrosion Inhibiting Compound Reapplication								3484.0						18.0
									964						
Airframe								24 MOS	06 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Lubrication/Service (S)												
322306	Nose Landing Gear Bungee - Lubrication								3484.0						3.0
									964						
Airframe								24 MOS	02 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Lubrication/Service (L)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
322305	Airframe	Nose Gear Bungee - Removal / Installation	\$0.00	3.00
Mandatory Related Codes Totals:			\$0.00	3.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
352506	Therapeutic Oxygen System (Outlet No. 1) - Functional Test								3466.5 953						1.0
Airframe								36 MOS	17 Mar 2015	31 Mar 2018		24 Mos			
	G550 AMM		Functional/Ops Test (F)												
352516	Therapeutic Oxygen Mask (No. 1) - Detailed Inspection								3466.5 953						1.0
Airframe								36 MOS	17 Mar 2015	31 Mar 2018		24 Mos			
	G550 AMM		Special Inspection (R)												
491301	Auxiliary Power Unit Turbine Plenum Drains - Operational Test								2090.5 0						3.0
APU 1								24 MOS	26 Feb 2016	31 Mar 2018*		24 Mos			
	G550 AMM		Functional/Ops Test (O)												
262570	Trash Receptacle Fire Extinguishing Bottle (Weight Check, Aft Lavatory) - Functional Test								2849.4 833						1.0
Airframe								60 MOS	04 Apr 2013	30 Apr 2018 Weight Check		25 Mos			
	G550 AMM		Lubrication/Serviceing (Z)												
262571	Trash Receptacle Fire Extinguishing Bottle (Weight Check, Forward Lavatory) - Functional Test								2849.4 833						1.0
Airframe								60 MOS	04 Apr 2013	30 Apr 2018 Weight Check		25 Mos			
	G550 AMM		Lubrication/Serviceing (Z)												
262573	Trash Receptacle Fire Extinguishing Bottle (Weight Check, Forward Galley) - Functional Test								2849.4 833						1.0
Airframe								60 MOS	04 Apr 2013	30 Apr 2018 Weight Check		25 Mos			
	G550 AMM		Lubrication/Serviceing (Z)												

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262603	Portable Halon Fire Extinguisher (Cockpit, Hydrostatic) - Functional Test								0.0					1.0
	898052-01		X-456017					0						
Airframe							144 MOS	26 Nov 2007	31 Jan 2019		34 Mos			
	G550 AMM		Lubrication/Serviceing (Z)						Hydrostatic					

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262600	Airframe	Portable Halon Fire Extinguisher (Cockpit) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:			\$0.00	1.00

321201	Main Landing Gear Shock Absorber (Left) - Servicing								3484.0					5.0
								964						
Airframe							36 MOS	05 Jan 2016	31 Jan 2019		34 Mos			
	G550 AMM		Lubrication/Serviceing (S)											

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
321217	Airframe	Main Landing Gear Shock Absorber (Left) - Removal / Installation	\$119,061.04	12.00
324106	Airframe	Brake Assembly (Left Inboard) - Removal / Installation	\$153,567.61	5.00
Mandatory Related Codes Totals:			\$272,628.65	17.00

321202	Main Landing Gear Shock Absorber (Right) - Servicing								3484.0					5.0
								964						
Airframe							36 MOS	05 Jan 2016	31 Jan 2019		34 Mos			
	G550 AMM		Lubrication/Serviceing (S)											

322202	Nose Landing Gear Shock Strut - Servicing								3484.0					4.0
								964						
Airframe							36 MOS	03 Jan 2016	31 Jan 2019		34 Mos			
	G550 AMM		Lubrication/Serviceing (S)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

323002	Landing Gear Emergency Extension Nitrogen Blow-down Bottle (Left) - (Hydrostatic) Functional Test								3484.0						3.0
Airframe	G550 AMM		Functional/Ops Test (F)					36 MOS	964 03 Feb 2016	31 Jan 2019		34 Mos			
										Hydrostatic					

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
323001	Airframe	Landing Gear Emergency Extension Nitrogen Blow-down Bottle (Left) - Removal / Installation	\$13,966.46	3.00
Mandatory Related Codes Totals:			\$13,966.46	3.00

351111	Crew Oxygen Mask and Regulator (Copilot) - Detailed Inspection								3484.0						1.0
Airframe	G550 AMM		Special Inspection (M)					36 MOS	964 25 Jan 2016	31 Jan 2019		34 Mos			

351112	Crew Oxygen Mask and Regulator (Observer) - Detailed Inspection								3484.0						1.0
Airframe	G550 AMM		Special Inspection (M)					36 MOS	964 25 Jan 2016	31 Jan 2019		34 Mos			

323901	Landing Gear Emergency Extension - Operational Test								3484.0						16.0
Airframe	G550 AMM		Functional/Ops Test (O)					36 MOS	964 08 Feb 2016	28 Feb 2019		35 Mos			

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
323006	Airframe	Landing Gear Emergency Extension Nitrogen Blow-down Bottle - Servicing		1.00
323906	Airframe	Landing Gear Cycling - Operational Test		9.00
Mandatory Related Codes Totals:				10.00

351110	Crew Oxygen Mask and Regulator (Pilot) - Detailed Inspection								3484.0						1.0
Airframe	G550 AMM		Special Inspection (M)					36 MOS	964 08 Feb 2016	28 Feb 2019		35 Mos			

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number	Serial Number	TSNHR	TSNLD	TSNMO	TSOHR	TSOLD							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref	Event Category		@= Adjustments						Ops Number(s)				

351011	Oxygen Mask / Regulator (Pilot) - Restore							2849.4					\$7,292.40	1.5
	MC10-15-158		86782					833						
Airframe	No			0.0	0	0	72 MOS	10 Apr 2013	21 Mar 2019		36 Mos			
	G550 AMM	Overhaul (T)												

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		351021	Airframe	Crew Oxygen Mask and Regulator Box (Pilot) - Removal / Installation	\$2,061.66	1.50
Mandatory Related Codes Totals:					\$2,061.66	1.50

351012	Oxygen Mask / Regulator (Copilot) - Restore							2849.4					\$7,292.40	1.5
	MC10-15-158		SE15008					833						
Airframe	No			0.0	0	1	72 MOS	10 Apr 2013	22 Mar 2019		36 Mos			
	G550 AMM	Overhaul (T)												

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		351022	Airframe	Crew Oxygen Mask and Regulator Box (Copilot) - Removal / Installation	\$2,061.66	1.50
Mandatory Related Codes Totals:					\$2,061.66	1.50

783013	Thrust Reverser Ground Relay (Left) - Operational Test							3484.0						1.0
								964						
Airframe							36 MOS	04 Feb 2016	31 Mar 2019*		36 Mos			
	G550 AMM	Functional/Ops Test (O)												

783014	Thrust Reverser Ground Relay (Right) - Operational Test							3484.0						1.0
								964						
Airframe							36 MOS	04 Feb 2016	31 Mar 2019*		36 Mos			
	G550 AMM	Functional/Ops Test (O)												

351013	Oxygen Mask / Regulator (Observer) - Restore							2849.4					\$7,292.40	1.5
	MC10-15-158		87678					833						
Airframe	No			0.0	0	0	72 MOS	10 Apr 2013	03 Apr 2019		37 Mos			
	G550 AMM	Overhaul (T)												

Mandatory Related Codes:		Code	Logbook	Description	Parts Cost	Labor Hours
		351023	Airframe	Crew Oxygen Mask and Regulator Box (Observer) - Removal / Installation	\$2,061.66	1.50
Mandatory Related Codes Totals:					\$2,061.66	1.50

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

880339 Alert SB BR700-72-A900509 (Revision 4) Replacement of the Fuel Pump Splined Coupling 4000 Hrs 0.0 7029.7 Hrs* 7029.7 3545.7 Hrs 10.0
0

Engine 1

Service Information

880339 Alert SB BR700-72-A900509 (Revision 4) Replacement of the Fuel Pump Splined Coupling 4000 Hrs 0.0 7029.7 Hrs* 7029.7 3545.7 Hrs 10.0
(890339) 0

Engine 2

Service Information

539004 (R) Lower Antenna and Penetration Interface - Detailed Inspection

Airframe

0.0
0
72 MOS 05 May 30 Apr 37 Mos
2008 2019*

G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
231003	Airframe	VHF Antenna No. 1 - Removal / Installation	\$3,318.66	4.00
231006	Airframe	VHF Antenna No. 3 - Removal / Installation	\$3,222.00	4.00
341001	Airframe	Radio Altimeter Antenna No. 1 (Transmit) - Removal / Installation	\$881.68	3.00
341002	Airframe	Radio Altimeter Antenna No. 1 (Receive) - Removal / Installation	\$881.68	3.00
341003	Airframe	Radio Altimeter Antenna No. 2 (Transmit) - Removal / Installation	\$0.00	3.00
341004	Airframe	Radio Altimeter Antenna No. 2 (Receive) - Removal / Installation	\$881.68	3.00
343001	Airframe	Marker Beacon Antenna - Removal / Installation	\$1,209.43	4.00
344303	Airframe	TCAS Antenna No. 1 - Removal / Installation	\$23,999.00	3.00
345105	Airframe	DME Antenna No. 1 - Removal / Installation	\$329.60	2.00
345106	Airframe	DME Antenna No. 2 - Removal / Installation	\$329.60	2.00
345315	Airframe	ATC Mode S Antenna No. 1 (Upper) - Removal / Installation	\$329.60	4.00
345316	Airframe	ATC Mode S Antenna No. 2 (Upper) - Removal / Installation	\$329.60	4.00
383001	Airframe	Alt Drain Mast - Removal / Installation	\$0.00	4.00
Mandatory Related Codes Totals:			\$35,712.53	43.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									

539005 (R) Upper Antenna and Penetration Interface - Detailed Inspection

Airframe
G550 AMM Special Inspection (M)

0.0
0
72 MOS 05 May 2008 30 Apr 2019* 37 Mos

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
345316	Airframe	ATC Mode S Antenna No. 2 (Upper) - Removal / Installation	\$329.60	4.00
345801	Airframe	GPS Antenna No. 1 - Removal / Installation	\$1,547.06	4.00
345802	Airframe	GPS Antenna No. 2 - Removal / Installation	\$1,547.06	4.00
345205	Airframe	ADF Antenna No. 1 - Removal / Installation	\$4,763.75	4.00
345206	Airframe	ADF Antenna No. 2 - Removal / Installation	\$4,763.75	4.00
345315	Airframe	ATC Mode S Antenna No. 1 (Upper) - Removal / Installation	\$329.60	4.00
344304	Airframe	TCAS Antenna No. 2 - Removal / Installation	\$448.11	3.00
231004	Airframe	VHF Antenna No. 2 - Removal / Installation	\$3,318.66	4.00
256303	Airframe	Emergency Locator Transmitter Antenna - Removal Installation	\$1,999.47	2.00

Mandatory Related Codes Totals: \$19,047.06 33.00

521012 Main Entrance Door Internal - Detailed Inspection

Airframe
G550 AMM Special Inspection (R)

2849.4
833
72 MOS 10 Apr 2013 31 May 2019* 38 Mos 8.0

237012 Cockpit Voice Recorder Underwater Locator Beacon - Battery Discard (DK120)
DK120 SD17286 0.0 0 1

Airframe No
G550 AMM Replacement (X)

3029.7
875
72 MOS 24 Sep 2013 01 Aug 2019 Expiration 41 Mos \$1,893.75 1.0

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
237014	Airframe	Cockpit Voice Recorder Underwater Locator Beacon - Battery Replacement (DK120)	\$1,893.75	1.00

Mandatory Related Codes Totals: \$1,893.75 1.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*=Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

262613	Portable Halon Fire Extinguisher (Forward Cabin, Hydrostatic) - Functional Test							7.2						1.0
	100-9750		X-192058					6						
Airframe							144 MOS	04 Mar 2008	30 Sep 2019		42 Mos			
	G550 AMM		Lubrication/Serviceing (Z)						Hydrostatic					

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						262610	Airframe	Portable Halon Fire Extinguisher (Forward Cabin) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:									\$0.00	1.00

262614	Portable Halon Fire Extinguisher (Forward Cabin) - Final Phase Restore							3029.7					\$0.00	0.0
	100-9750		X-192058					875						
Airframe	No				0.0	0	0	72 MOS	30 Sep 2013	30 Sep 2019	42 Mos			
	Flag Fire CMM 100-9750		Overhaul (T)							Overhaul				

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						262610	Airframe	Portable Halon Fire Extinguisher (Forward Cabin) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:									\$0.00	1.00

262634	Portable Halon Fire Extinguisher (Aft Lavatory) - Final Phase Restore							3029.7					\$0.00	0.0
	100-9750		X-192388					875						
Airframe	No				0.0	0	0	72 MOS	30 Sep 2013	30 Sep 2019	42 Mos			
	Flag Fire CMM 100-9750		Overhaul (T)							Overhaul				

Mandatory Related Codes:						Code	Logbook	Description	Parts Cost	Labor Hours
						262630	Airframe	Portable Halon Fire Extinguisher (Aft Lavatory) - Removal / Installation	\$0.00	1.00
Mandatory Related Codes Totals:									\$0.00	1.00

981640 (R)	CB 164 Modification - Spoiler Throwboard Mounting Point (Part 1)							0.0						9.0
								0						
Airframe							48MOS**		20 Nov 2019		44 Mos			
			Required Bulletin											

981641 (R)	CB 164 Modification - Spoiler Throwboard Mounting Point (Part2)							0.0						9.0
								0						
Airframe							48MOS**		20 Nov 2019		44 Mos			
			Required Bulletin											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256289	Protective Breathing Equipment (No. 3) - Discard								1623.4					\$1,799.62	1.5
	MR-10039N		E0904590		0.0	0	0		463						
Airframe	No							120 MOS	09 Oct 2010	25 Nov 2019		44 Mos			
	G550 AMM		Replacement (X)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
256287	Airframe	Protective Breathing Equipment (No. 3) - Removal / Installation	\$1,534.70	1.50

Mandatory Related Codes Totals: \$1,534.70 1.50

256265	ELT Battery, Life Raft (No. 1) - Scrap								3272.4				\$0.00	1.0
	1A2501-1SRB-10				0.0	0	0		917					
Airframe	No							60 MOS	27 Feb 2014	30 Nov 2019		44 Mos		
	Mfg. Rqmt.		Replacement (X)											

256267	ELT Battery, Life Raft (No. 3) - Scrap								3272.4				\$0.00	1.0
	1A2501-1SRB-10				0.0	0	0		917					
Airframe	No							60 MOS	27 Feb 2014	30 Nov 2019		44 Mos		
	Mfg. Rqmt.		Replacement (X)											

262633	Portable Halon Fire Extinguisher (Aft Lavatory, Hydrostatic) - Functional Test								7.2					1.0
	100-9750		X-192388						6					
Airframe								144 MOS	04 Mar 2008	30 Nov 2019		44 Mos		
	G550 AMM		Lubrication/Serviceing (Z)											

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
262630	Airframe	Portable Halon Fire Extinguisher (Aft Lavatory) - Removal / Installation	\$0.00	1.00

Mandatory Related Codes Totals: \$0.00 1.00

236001	L Wing Static Wicks / Bonding - Functional Test								3484.0					1.0
	N/A		N/A						964					
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Functional/Ops Test (F)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
236002	R Wing Static Wicks / Bonding - Functional Test								3484.0						1.0
	N/A		N/A					964							
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Functional/Ops Test (F)												
236003	L Horizontal Stabilizer Static Wick / Bonding - Functional Test								3484.0					1.0	
	N/A		N/A					964							
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Functional/Ops Test (F)												
236004	R Horizontal Stabilizer Static Wick / Bonding - Functional Test								3484.0					1.0	
								964							
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Functional/Ops Test (F)												
236005	Vertical Stabilizer Static Wick / Bonding - Functional Test								3484.0					1.0	
								964							
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Functional/Ops Test (F)												
236006	Tail Cone Static Wick / Bonding - Functional Test								3484.0					1.0	
								964							
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Functional/Ops Test (F)												
240113	Fwd Emergency Battery Pack - Discard								3484.0				\$9,438.92	4.0	
	100-0302-01		P2279					964							
Airframe	Yes	14						48 MOS	31 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Replacement (X)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	240103	Airframe	Emergency Battery (Forward) - Removal / Installation	\$9,438.92	1.00
	240123	Airframe	Emergency Battery Power System (Forward) - Operational Test		1.00
Mandatory Related Codes Totals:				\$9,438.92	2.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

251021 Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection 3484.0 964 1.0
 Airframe 48 MOS 26 Dec 2015 31 Dec 2019 45 Mos
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
251001	Airframe	Pilot Seat - Removal / Installation	\$0.00	3.00
Mandatory Related Codes Totals:			\$0.00	3.00

251022 Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection 3484.0 964 1.0
 Airframe 48 MOS 26 Dec 2015 31 Dec 2019 45 Mos
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
251002	Airframe	Copilot Seat - Removal / Installation	\$29,816.96	3.00
Mandatory Related Codes Totals:			\$29,816.96	3.00

251023 Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection 3484.0 964 1.0
 Airframe 48 MOS 26 Dec 2015 31 Dec 2019 45 Mos
 G550 AMM Special Inspection (M)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
251003	Airframe	Observer Seat - Removal / Installation	\$39,474.00	3.00
Mandatory Related Codes Totals:			\$39,474.00	3.00

252101 Passenger Seats Attachments and Locking - Detailed Inspection 3484.0 964 1.0
 Airframe 48 MOS 26 Dec 2015 31 Dec 2019 45 Mos
 G550 AMM Special Inspection (M)

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

256025	Ditching Line - Detailed Inspection								3484.0						3.0
								964							
Airframe								48 MOS	28 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Special Inspection (R)												

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
562011	Airframe	Emergency Exit Cabin Window (Left No. 1) - Removal / Installation	\$19,865.35	12.00
562012	Airframe	Emergency Exit Cabin Window (Left No. 2) - Removal / Installation	\$19,865.35	12.00
562013	Airframe	Emergency Exit Cabin Window (Right No. 1) - Removal / Installation	\$19,865.35	10.00
562014	Airframe	Emergency Exit Cabin Window (Right No. 2) - Removal / Installation	\$19,865.35	10.00
Mandatory Related Codes Totals:			\$79,461.40	44.00

261418	Alt Equipment Overheat Thermal Switches - Functional Test								3484.0					2.0
								964						
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Functional/Ops Test (F)											

275302	FLAP TRACKS - GENERAL VISUAL INSPECTION								3484.0					2.0
								964						
Airframe								48 MOS	26 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Special Inspection (M)											

531040	Upper Surface of Center Wing FS 426 - FS 576 From Wheel Well - Zonal Inspection								3484.0					2.0
								964						
Airframe								48 MOS	26 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Special Inspection (R)											

534001	Baggage Compartment Electronic Equipment Rack FS 689 - FS 698 - Zonal Inspection								3484.0					2.0
								964						
Airframe								48 MOS	26 Dec 2015	31 Dec 2019		45 Mos		
	G550 AMM		Special Inspection (R)											

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

535028 Tail Compartment Above Floor Electrical Junction Boxes - Detailed Inspection 3484.0 4.0
 964
 Airframe 48 MOS 26 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
240101	Airframe	Emergency Battery (Left) - Removal / Installation	\$9,438.92	1.00
240102	Airframe	Emergency Battery (Right) - Removal / Installation	\$9,438.92	1.00
243001	Airframe	Main Battery (Left) - Removal / Installation	\$18,874.40	2.00
243002	Airframe	Main Battery (Right) - Removal / Installation	\$18,874.40	2.00
Mandatory Related Codes Totals:			\$56,626.64	6.00

541005 Pylons External (Left) - Zonal Inspection 3484.0 4.0
 964
 Airframe 48 MOS 27 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Special Inspection (R)

541006 Pylons External (Right) - Zonal Inspection 3484.0 4.0
 964
 Airframe 48 MOS 27 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Special Inspection (R)

541010 Pylons Internal (Left) - Zonal Inspection 3484.0 12.0
 964
 Airframe 48 MOS 27 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Special Inspection (R)

541011 Pylons Internal (Right) - Zonal Inspection 3484.0 12.0
 964
 Airframe 48 MOS 27 Dec 31 Dec 45 Mos
 2015 2019
 G550 AMM Special Inspection (R)

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO								
Logbook	MM Ref		Event Category		@= Adjustments		Date Type				Ops Number(s)				
551111	Elevator Upper Surface - Detailed Inspection								3484.0 964						4.0
	Airframe							48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (R)											
570005	Wing Upper Surface View from on Wing (Left) - Zonal Inspection								3484.0 964						2.0
	Airframe							48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (R)											
570006	Wing Upper Surface View from on Wing (Right) - Zonal Inspection								3484.0 964						2.0
	Airframe							48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (R)											
570013	Upper Wing Extension BL 542 - BL 545 (View from on Wing) (Left) - Zonal Inspection								3484.0 964						2.0
	Airframe							48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (M)											
570014	Upper Wing Extension BL 542 - BL 545 (View from on Wing) (Right) - Zonal Inspection								3484.0 964						2.0
	Airframe							48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (M)											
573010	Winglet Blade (View From Ground) (Left) - Zonal Inspection								3484.0 964						1.0
	Airframe							48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
		G550 AMM		Special Inspection (R)											

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

573011	Winglet Blade (View From Ground) (Right) - Zonal Inspection								3484.0						1.0
									964						
Airframe								48 MOS	26 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Special Inspection (R)												

575007	Wing Tank Internal Inboard 3 Panels Each Wing (Left) - Detailed Inspection								3484.0						16.0
									964						
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	280003	Airframe	Fuel Tank Vapor Hazards - Reduction		2.00
Mandatory Related Codes Totals:					2.00

575008	Wing Tank Internal Inboard 3 Panels Each Wing (Right) - Detailed Inspection								3484.0						16.0
									964						
Airframe								48 MOS	27 Dec 2015	31 Dec 2019		45 Mos			
	G550 AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	280003	Airframe	Fuel Tank Vapor Hazards - Reduction		2.00
Mandatory Related Codes Totals:					2.00

237201	Security System Battery Pack (No. 1) - Final Phase Restore								3484.0				\$54,539.19	1.0	
	100-1032-01		0703456						964						
Airframe	No							48 MOS	12 Feb 2016	31 Jan 2020	Manufacture	46 Mos			
			Replacement (X)												

240111	L Emergency Battery Pack - Discard								3484.0				\$9,438.92	4.0	
	1159SCAV524-3		P2895						964						
Airframe	Yes							48 MOS	05 Jan 2016	31 Jan 2020		46 Mos			
	G550 AMM		Replacement (X)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	240101	Airframe	Emergency Battery (Left) - Removal / Installation	\$9,438.92	1.00
Mandatory Related Codes Totals:				\$9,438.92	1.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (*Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

284301	Fuel Tank Temperature Bulb - Functional Check								3484.0 964						2.0
Airframe								48 MOS	28 Jan 2016	31 Jan 2020		46 Mos			
	G550 AMM		Functional/Ops Test (F)												

321003	Main Landing Gear Components (Left) - Detailed Corrosion Inspection								3484.0 964						25.0
Airframe								48 MOS	05 Jan 2016	31 Jan 2020		46 Mos			
	G550 AMM		Special Inspection (M)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	321005	Airframe	Main Landing Gear (Left) - Lubrication		2.00
	321029	Airframe	Main Gear Trunnion Pin (Left Aft) - Removal / Installation	\$0.00	10.00
	323021	Airframe	Main Landing Gear Sidebrace (Left) - Removal / Installation	\$60,232.00	14.00
	321217	Airframe	Main Landing Gear Shock Absorber (Left) - Removal / Installation	\$119,061.04	12.00
	321221	Airframe	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Left)		20.00
Mandatory Related Codes Totals:				\$179,293.04	58.00

321004	Main Landing Gear Components (Right) - Detailed Corrosion Inspection								3484.0 964						25.0
Airframe								48 MOS	05 Jan 2016	31 Jan 2020		46 Mos			
	G550 AMM		Special Inspection (M)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	321006	Airframe	Main Landing Gear (Right) - Lubrication		2.00
	321030	Airframe	Main Gear Trunnion Pin (Right Aft) - Removal / Installation	\$0.00	10.00
	323022	Airframe	Main Landing Gear Sidebrace (Right) - Removal / Installation	\$60,232.00	14.00
	321218	Airframe	Main Landing Gear Shock Absorber (Right) - Removal / Installation	\$119,061.04	12.00
	321222	Airframe	Main Landing Gear Corrosion Inhibiting Compound Reapplication (Right)		20.00
Mandatory Related Codes Totals:				\$179,293.04	58.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

560001	Emergency Window Release Mechanism - Functional Test								3484.0						4.0
								964							
Airframe								48 MOS	07 Jan 2016	31 Jan 2020		46 Mos			
	G550 AMM	Special Inspection (R)													

Mandatory Related Codes:					
Code	Logbook	Description	Parts Cost	Labor Hours	
256025	Airframe	Ditching Line - Detailed Inspection		3.00	
562115	Airframe	Cabin Windows - Leak Check		4.00	
Mandatory Related Codes Totals:				7.00	

272303	Standby Rudder System - Operational Test								3484.0					4.0
								964						
Airframe								48 MOS	05 Feb 2016	29 Feb 2020		47 Mos		
	G550 AMM	Functional/Ops Test (O)												

531036	Cabin Below Floor FS 145 - FS 229 - Zonal Inspection								3484.0					12.0
								964						
Airframe								48 MOS	01 Feb 2016	29 Feb 2020		47 Mos		
	G550 AMM	Special Inspection (R)												

Mandatory Related Codes:					
Code	Logbook	Description	Parts Cost	Labor Hours	
530027	Airframe	Floorboard Clip Nut - Check		0.50	
Mandatory Related Codes Totals:				0.50	

TOTAL APPROXIMATE PRICE AND CODE MANHOURS FOR ATAs 05-96	\$200,177.69	2,197.50
TOTAL APPROXIMATE PRICE AND CODE MANHOURS FOR ATAs 97-99	\$0.00	29.00