

CARIBBEAN

Fire & Burglary • CCTV



PROTECTION

Access Control • Parking Control

SYSTEMS

September 9 2015

Little Saint James LLC
6100 Red Hook Quarters
Suite B3
St Thomas VI 00802

Re: Repair of the fire alarm system after inspection

During the fire alarm inspection the following items have been found defective:

The power supply is in constant trouble. It needs more troubleshooting and possible replacement.

The price of a new power supply is \$1275.00

The ventilation fans and dampers in RO plant and generator building did not operate as intended.

It also needs more troubleshooting.

The outdoor strobe is not functioning.

The repair will be billed on a time and materials basis as it is difficult to estimate how long it is going to take.

Our labor rates are :

Supervisor/senior tech: \$90/hour

Technician: \$65/hour

Junior tech: \$45/hour

Please let us know what you would like us.

Thank you for your valued business

Sincerely

Martine Nicolosi

Office manager

Caribbean Protection Systems

Box 306246 • St. Thomas, U.S.V.I. 00803 • Tel

Email:

EFTA00607299