

From: Eric Roth <[REDACTED]>

To: 'Jeffrey Epstein' <jeevacation@gmail.com>

Subject: RE: GIV Discrepancies

Date: Sat, 26 Oct 2013 18:44:23 +0000

Attachments: JVC_KW-NSX700_Receiver.pdf; image002.png

Inline-Images: image007.jpg; image008.jpg; image009.jpg; image011.jpg; image012.jpg; image013.jpg

Jeffrey,

The link below is a 2 page spec on the JVC receiver.

Additionally, I have attached a detailed user manual with detailed specifications found on Page 76 & 77 at the end of the manual.

<http://resources.jvc.com/Resources/00/01/56/15608.PDF>

ERIC H. ROTH | PRESIDENT

 IJ Logo - Horizontal-SMALL

P [REDACTED] | C [REDACTED] | [REDACTED] | www.intljet.com



2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: Jeffrey Epstein [mailto:jeevacation@gmail.com]

Sent: Saturday, October 26, 2013 12:51 PM

To: Eric Roth

Subject: Re: GIV Discrepancies

also send the specs from the jvc car radio system that you guys chose please

On Sat, Oct 26, 2013 at 9:04 AM, Eric Roth <[REDACTED]> wrote:
[A very sincere thank you from the bottom of my heart.](#)

[I will make sure the outstanding discrepancies are satisfied.](#)

EFTA00632225

From: Jeffrey Epstein [mailto:jeevacation@gmail.com]

Sent: Saturday, October 26, 2013 9:01 AM

To: Eric Roth

Subject: Re: GIV Discrepancies

thanks, i will take care of your kid. re stereo . control : i have full access in my mercedes to the control of dvd cd, video. as well as blue tooth source this is the same control in various cheap stereo equipment. sound : many inexpensive home theatre systems come with microphones to adjust fre and volumne, , it is not merely a matter of my liking, it is a matter of flat response. first, only then i can then adjust for source. . i have no weight restrictions on system, ie large credneza, two seats out, no mid range is not a matter of taste.

gaspers. i need alternative solutions. differnt ones, ? new seals , after you played with the one on my seat, it was impossible to control fairly loud hiss, so it does not seem merely to be the center seal. is it he fact that the plating was brushed , ?? that allows air leaks?

carpet, ok.

On Sat, Oct 26, 2013 at 8:14 AM, Eric Roth <[\[REDACTED\]](mailto:[REDACTED])> wrote:

Good morning Jeffrey,

Wiring Diagram -

The engineering wiring diagrams go through revision updates, so yes - there was an update to the drawing on 8/21/13.

Entertainment Audio -

This system has been tuned a few times in anticipation of what you personally would like to hear. Yesterday Dan had the opportunity to speak with you one on one and get a full understanding (bringing back the mid range frequencies). On our drive back to Long Island, we spent much of the ride discussing the system and what would be required. Dan is confident that he can do so. Yes, you do have control from your i-Pad or i-Phone for your stored music selections and video which is what we were told you would be using for source equipment. The fact that the head unit provides the ability to play a DVD / CD is simply a bonus and means for allowing the system to present your stored / mobile music / video selections. Additionally, you can control certain functions through the Cabin Management System control panel at your seat for volume (up/down) and video selection source (Airshow, Camera, DVD/CD, Apple TV) as well as speakers (on/off). We will tune the system to bring back the mid range frequencies for a more uniform balance.

LCD Monitor -

The LCD monitor was purchased by Goodrich - a leading manufacturer in business aviation. I will be speaking with Mike McCullum at their facility on Monday morning and expressing your sentiments, including information you have provided in yesterday's e-mails so that we may come to a conclusion you find satisfactory. Additionally, it was evident that running on aircraft power, we need to install a video isolation filter to clean up the picture quality.

Air gasper -

most gasper appear to be sealing air flow +-97% with a few lower than that introducing "noise" into the cabin. Now that I have experienced it first hand, I will be speaking with my metal plater on Monday morning. Additionally, I will be speaking with my people internally about how best to resolve this annoying issue. It appears that although the "cone" within the air gasper does tighten snugly against the cylinder, there is enough air pressure from the system that is able escape through any deviation between the two surfaces meeting.

Table Tabs -

Please provide a simple sketch of the metal tabs you envision to gain easier access to lift the table lid on the side ledges.

Carpet -

Please have [REDACTED] make sure she orders about 5 lbs of the same color surging yarn for the carpet and that she sends us an e-mail of when she anticipates the new blue silk carpet to be delivered.

Thank you,

Eric

ERIC H. ROTH | PRESIDENT

 IJL Logo - Horizontal-SMALL

P [REDACTED] | C [REDACTED] | [REDACTED] | www.intljet.com



2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: Jeffrey Epstein [mailto:jeevacation@gmail.com]

Sent: Friday, October 25, 2013 10:00 PM

To: Eric Roth; Ivjet

Subject:

eric. the entertainment system is extremely problematic. extremely !! I reviewed the wiring diagram you sent , from a florida firm only drafted the LAST week in august. ??? after takeoff, i wanted to advance the awful music on the dvd, Larry told me there is no way without getting up, walking to the credenza a, and change it at the head. this can't be right . you and i had a firm understanding that this would not happen. control from my seat. was agreed. in addition The idea that instead of using a frequency analyzer, and professional sound adjusmtnet tool, readily available . I had to personally listen to a system that is clearly not right . made little sense. the antique lcd screen was unwatchable . as well as the loud hissing from the gaspers at altitude. made this trip uncomfortable.

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights rese

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

EFTA00632227

Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved