

From: Larry Visoski <[REDACTED]>

To: Je vacation <jeevacation@gmail.com>

Subject: Fuel

Date: Wed, 04 Nov 2015 14:38:31 +0000

Jeffrey

We removed the fwd panel by landing light lens,, no obvious source of leak. Pete will remove file panel upper portion of wing to Fuselage,, appears fuel is coming from upper portion of wing under fuselage. This Will be time consuming repair locating its source.

Fuel leak has slowed to a drip every 2 to 3 seconds now. Still shouldn't leak,. Gulfstream maintenance Manuel allows a one drip per 30 seconds.

Bill would arrive Palm beach at 6pm tonight,

-Should Dave and I head to PBI now and bring Boeing to Newark tonight?

Thx

Larry

Sent from my iPhone