

From: Larry Visoski <[REDACTED]>
To: "jeffrey E." <jeevacation@gmail.com>
Subject: Re:
Date: Mon, 04 Sep 2017 20:09:13 +0000

I thought the same thing,,
Not really,, I have photos of the pressurization Page in April with PAC temp pressure reading 40 degrees,,
Which is a normal reading,, Outside air temperature/ISA has an effect on temperature performance so it does
vary,, This flight we had R/H PAC temp reading of 80,,

Thx
Larry

Sent from my iPhone

On Sep 4, 2017, at 10:06 PM, jeffrey E. <jeevacation@gmail.com> wrote:

is there a reason that such a worn valve was not picked up in pre buy?

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved