

From: Larry Visoski [REDACTED] >
To: "jeffrey E." <jeevacation@gmail.com>
Subject: Re:
Date: Mon, 21 Mar 2016 12:39:54 +0000

I see it,.

5017 follows "Task orientated maintenance program/on condition"
*** the corporate care program states the first Borescope takes place at 3000 hours,

So, at 3000 hours, this will be the first borescope of these engines, after that, each 1000 hours, a borescope will be required, since the engines are on/condition, you continue to do borescopes each 1000 interval until you find something wrong internally with the engine.,

Sent from my iPhone

On Mar 21, 2016, at 8:26 AM, jeffrey E. <jeevacation@gmail.com> wrote:

under engines said it was due at 3000 hrs

On Mon, Mar 21, 2016 at 8:24 AM, Larry Visoski <[\[REDACTED\]](mailto:)> wrote:

Yes, i'll have Pete investigate those areas in the Aircraft records,

Where did you see the mention of hot section?

Sent from my iPhone

On Mar 21, 2016, at 8:21 AM, jeffrey E. <jeevacation@gmail.com> wrote:

landing gear, headliner removal. hot section. brakes. corrosion, all checks . pitting . ?

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved