

From: Brice Gordon <[REDACTED]>

To: "jeffrey E." <jeevacation@gmail.com>

Cc: Rich Kahn <[REDACTED]>, Larry Visoski <[REDACTED]>, Zorro Ranch
<[REDACTED]>

Subject: ZM Mercedes S500

Date: Tue, 23 May 2017 16:23:14 +0000

Attachments: IMG_5346.MOV; ZM_Mercedes_S500.pdf

Jeffrey

attached Video and Repair estimate for your reference

During the final inspection of the Mercedes S 500, the Technician discovered found oil and water contamination in the Transmission control unit. This is due to failed Electronic connector at the Transmission

The cost to repair will be an additional \$1447.879

Total Cost of repairs, as of date, including the above, less tax \$8297.87

Do you wish to proceed with repair?

regards

Brice Gordon
Stanley, NM

Ph: [REDACTED]