

From: Larry Visoski <[REDACTED]>

To: Je vacation <jeevacation@gmail.com>

Cc: Rich Kahn <[REDACTED]>

Subject: GIV update

Date: Wed, 27 Apr 2016 13:42:44 +0000

Jeffrey

Pete informs the FAMV "Fan Air Modulation Valves" were swapped last night, it was a big job, the mechanics also located a filter in the Regulator valve that is mounted on top of the Fan Air valve, once they removed the filter, they noticed a metal filter screen on the R/H Air side of the Regulator valve with Obstruction or FOD, "Foreign Object Debris" they put the screens in an Ultra Sound cleaner and reinstalled, Pete didn't feel the obstruction was large enough to affect operation,

Ground runs / ops check this afternoon,

WiFi box in Tail compartment appears to have failed again, since SatPhone and WiFi didn't work on yesterday's flight, this will be a warranty exchange,

Will keep you advised

Thx
Larry

Sent from my iPhone