

**From:** Ann Rodriquez <[REDACTED]>

**To:** "jeffrey E." <jeevacation@gmail.com>

**Cc:** Rich Kahn <[REDACTED]>

**Subject:** Fwd: Big N

**Date:** Mon, 13 Jul 2015 19:44:54 +0000

**Inline-Images:** image1.JPG; image2.JPG

---

Ann R.

Begin forwarded message:

**From:** gene kral <[REDACTED]>

**Date:** July 13, 2015 at 2:45:52 PM AST

**To:** Ann Rodriquez <[REDACTED]>, Debra Lowry <[REDACTED]>

**Subject:** Big N

**Reply-To:** gene kral <[REDACTED]>

Good Afternoon Anna

I came back on Island today and reviewed progress on Big ,all looks great and I'm please with progress. A decision needs to be made on the fuel tanks. At this time the tanks are not leaking but will in the near future. After extensive cleaning the bottom of the tank has many large pits that will soon start to leak. The condition of the tanks most likely were caused by not having a proper sealing of the deck fuel fitting allowing salt water to enter the tank and do its damage. These fittings were placed on the deck ,in our quote we would have a stand pipe above the deck next to the wheel house so this problem will not happen again. We will need a answer soon so work will not be delayed any longer than necessary.

Please visit or call with any concerns.

Thanks

Gene

**Gene Kral Sr.**

Subbase Drydock, Inc.

[REDACTED]  
[St. Thomas, USVI 00802](#)  
[REDACTED]  
[REDACTED]

image1.JPG

image2.JPG