




Rolls-Royce

9500 Cote de Liesse
Lachine (Québec) H8T 1A2

Rolls-Royce Canada Limited (RRC)



Rolls-Royce Tay

Customer's name: **JEGE, LLC**
 Address: 3800 Southern Blvd, Suite 204, West Palm Beach, FL 33406
 Requested by: Larry Visoski Tel. [REDACTED]
 A/C Type: **GIV**
 A/C S/N: **1085**
 Tail no: **N212JE**
 Location: **BQK or PBI**
 Workscope: **L/H FAN CLOCKING 180, FAN TRIM BALANCE TEST # 9**
 Date: **TBD**
 Personnel: **1 Technicians + 1 FSR**

ENGINE DATA	
Engine type:	TAY
Mark:	611-8
L/H Engine S/N:	16291
TSN	TBA
CSN	TBA
R/H Engine S/N:	XXXXX
TSN	TBA
CSN	TBA

ITEM	DESCRIPTION	RATES	QTY.	SUB-TOTAL	Remarks
	TRAVEL FLAT FEE	\$125.00	32	\$4,000.00	
	Rate /hour	\$125.00	24	\$3,000.00	***NOTE THAT YOU WILL ONLY BE
	FSR FEE	\$1,250.00	2	\$2,500.00	INVOICED FOR THE COST
a	Air Fare	\$850.00	2	\$1,700.00	INCURED TO SUPPORT***
b	Car rental	\$50.00	3	\$150.00	
c	Accommodation	\$150.00	6	\$900.00	
	Per Diem	\$60.00	8	\$480.00	
			1	\$0.00	
	Misc.+ Shipping fee	\$1,000.00	1	\$1,000.00	
	Administration fee on a,b,c		1	\$137.50	
TOTAL USD:				\$13,867.50	

This Cost Estimate for Field Support Services is solely based on the information provided and Field Support Services requested by Customer. This Cost Estimate is subject to Rolls-Royce Standard Conditions for the Sale of Field Services Terms and Conditions (FSTC) and or RRC's Rental Agreement, attached hereto provided Customer's acceptance of this Cost Estimate is received by RRC.

Date: 30-Jun-15 Compiled by: A.Taillon

RRC Customer Field Support
FA [REDACTED]

Date: _____ For: _____ By: _____

Your Purchase Order No.: _____

Please sign and return with your P.O. As **ACCEPTANCE OF COST ESTIMATE FOR FIELD SUPPORT SERVICES**

Customer hereby agrees and accepts the provisions of this Cost Estimate, including all of Rolls-Royce Canada's:

Field Services Terms and Conditions ("FSTC")

attached hereto and which form an integral part of this Cost Estimate as if recited at length.

