

### A/C 5173 Items to be worked

1. Remove aft lav and pocket door "occupied" signs and re-veneer doors for a continuous look.  
Need to confirm if this is a regulatory requirement.
2. 2 each forward tray tables are not working properly.
3. Replace latches that are rattling.
4. Tighten the tray table gaps when in the open position.
5. Evaluate pocket door for proper fit when in the closed position and tighten if possible.
6. Sink drain handle and storage doors are loose.
7. Secure aft lav mirror light cover. Fell off during flight.
8. Copilot O2 mask microphone is intermittent.
9. Forward crew coffee maker outlet is inop.