



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 10		Drawing: N/A		12/12/2016	07/11/2018
<i>Description: Satcom Antenna Repair / Service upgrade</i>					
505-AVIONICS, Mx	1999M.10.505	5093713	12/12/2016	01/09/2018	01/10/2018
<i>Description: Satcom Antenna Repair / Service upgrade</i>					
505-1-AVIONICS, Mx	1999M.10.505-1	5105793		07/10/2018	07/11/2018
<i>Description: Due to serviceable right hand antenna not being available, design and perform procedures to deactivate the Satcom system before next flight</i>					
Count: 2			1		2
Task Card: 11		Drawing: N/A		12/12/2016	06/15/2018
<i>Description: TCAS 7.1 Upgrade P/N 822-2911-002 to 822-2911-002</i>					
505-AVIONICS, Mx	1999M.11.50	5093714	12/12/2016	06/01/2018	06/15/2018
<i>Description: TCAS 7.1 Upgrade P/N 822-2911-002 to 822-2911-002</i>					
Count: 1			1		1
Task Card: 12		Drawing: N/A		12/12/2016	11/17/2017
<i>Description: 081001 - PERFORM AIRCRAFT WEIGHT AND BALANCE</i>					
801-Maintenance	1999M.12.80	5093715	12/12/2016	11/16/2017	11/17/2017
<i>Description: 081001 - PERFORM AIRCRAFT WEIGHT AND BALANCE</i>					
Count: 1			1		1
Task Card: 19		Drawing: N/A		12/12/2016	11/17/2017
<i>Description: TCAS Boeing Service Bulletin</i>					
505-AVIONICS, Mx	1999M.19.50	5093717	12/12/2016	11/16/2017	11/17/2017
<i>Description: TCAS Boeing Service Bulletin</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1B	Drawing: N/A	12/12/2016		
<i>Description: A2 Check</i>				
80-12-Maintenance	1999M.1B.80-12	5094030	12/12/2016	03/10/2017 03/10/2017
<i>Description: 72-020-01: DETAILED INSPECTION OF LEFT ENGINE INLET AND FAN BLADES.</i>				
80-13-Maintenance	1999M.1B.80-13	5094031	12/12/2016	03/10/2017 03/10/2017
<i>Description: 72-020-02: DETAILED INSPECTION OF RIGHT ENGINE INLET AND FAN BLADES</i>				
205-INTERIOR INSTALL, Mx	1999M.1B.20	5094032	12/12/2016	04/05/2017 04/05/2017
<i>Description: 25 020-00-01: INSPECT (DETAILED) THE CAPTAIN, FIRST OFFICER, FIRST OBSERVER AND SECOND OBSERVER (IF INST...</i>				
505-AVIONICS, Mx	1999M.1B.50	5094033	12/12/2016	02/23/2017 02/23/2017
<i>Description: 28 054-00-01: OPERATIONALLY (BITE) CHECK THE FUEL PUMP GFI RELAY. SPECIAL NOTE: AWL TASK (28-AWL-20) IN...</i>				
505-1-AVIONICS, Mx	1999M.1B.50-1	5094034	12/12/2016	01/05/2018 01/08/2018
<i>Description: 28 056-00-01: FUNCTIONALLY CHECK CENTER TANK FUEL BOOST PUMP POWER FAILED ON PROTECTION SYSTEM. SPECIAL...</i>				
505-2-AVIONICS, Mx	1999M.1B.50-2	5094035	12/12/2016	02/23/2017 02/23/2017
<i>Description: 33 055-00-02: FUNCTIONALLY CHECK THE EMERGENCY LIGHTS BATTERY PACKS FOR CAPACITY (15 MIN. MINIMUM) AND O...</i>				
805-3-Mx Interiors	1999M.1B.805-3	5094036	12/12/2016	
<i>Description: 387002: REPLACE WATER FILTER CARTRIDGE</i>				
80-Maintenance	1999M.1B.80	5094037	12/12/2016	
<i>Description: 050012: ACCOMPLISH A2 CHECK</i>				
80-1-Maintenance	1999M.1B.80-1	5094038	12/12/2016	03/27/2017 03/27/2017
<i>Description: 27 170-01-01: LUBRICATE THE LEFT WING TRAILING EDGE FLAP ACTUATION MECHANISM.</i>				
80-2-Maintenance	1999M.1B.80-2	5094039	12/12/2016	03/27/2017 03/27/2017
<i>Description: 27 170-02-01: LUBRICATE THE RIGHT WING TRAILING EDGE FLAP ACTUATION MECHANISM.</i>				
80-3-Maintenance	1999M.1B.80-3	5094040	12/12/2016	01/12/2018 01/16/2018
<i>Description: 28 115-00-01: FUNCTIONALLY CHECK THE CENTER TANK BOOST PUMP AUTO SHUTOFF SYSTEM. NOTE: TASK MEETS INTENT...</i>				
80-4-Maintenance	1999M.1B.80-4	5094041	12/12/2016	
<i>Description: 28 20-01-PATS OPERATIONAL CHECK OF THE AUXILIARY FUEL CONTROL UNIT</i>				
80-5-Maintenance	1999M.1B.80-5	5094042	12/12/2016	03/27/2017 03/27/2017
<i>Description: 52 150-00-01: LUBRICATE THE AIRSTAIR DOOR SYSTEM, (INCLUDES TWO ROLLERS, THE CARRIAGE DRIVE BALL BEARING...</i>				
80-6-Maintenance	1999M.1B.80-6	5094043	12/12/2016	03/27/2017 03/27/2017
<i>Description: 57 952-01-01: INTERNAL - ZONAL (GV): LEFT WINGLET. TASK IS EQUIVALENT TO APB TASK 57-944-01 REF APB MAIN...</i>				
80-7-Maintenance	1999M.1B.80-7	5094044	12/12/2016	04/04/2017 04/04/2017
<i>Description: 57 962-02-01: INTERNAL - ZONAL (GV): RIGHT WINGLET. TASK IS EQUIVALENT TO APB TASK 57-948-01 REF APB MAI...</i>				
80-8-Maintenance	1999M.1B.80-8	5094045	12/12/2016	02/28/2017 02/28/2017
<i>Description: 72 020-01-01 DETAILED INSPECTION OF NO. 1 ENGINE INLET AND FAN BLADES.</i>				
80-9-Maintenance	1999M.1B.80-9	5094046	12/12/2016	03/10/2017 03/10/2017
<i>Description: 72 020-02-01 DETAILED INSPECTION OF NO. 2 ENGINE INLET AND FAN BLADES.</i>				



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
80-10-Maintenance <i>Description: 23-110-00 (FAR 91.207): INSPECT (FIXED) EMERGENCY LOCATOR TRANSMITTER IAW FAR 91.207(D)</i>	1999M.1B.80-10 5094047	12/12/2016	01/03/2018	01/05/2018
701-11-SYSTEM SHOP, FABRICATE <i>Description: 387001 : OPERATIONAL CHECK POTABLE WATER SYSTEM</i>	1999M.1B.701-11 5094048	12/12/2016		
80-14-Maintenance <i>Description: 72-180-01: NO. 1 ENGINE - BORESCOPE COMBUSTION CHAMBER</i>	1999M.1B.80-14 5094049	12/12/2016	08/10/2017	08/10/2017
80-15-Maintenance <i>Description: 72-180-01: NO. 2 ENGINE - BORESCOPE COMBUSTION CHAMBER</i>	1999M.1B.80-15 5094050	12/12/2016	08/10/2017	10/19/2017
80-16-Maintenance <i>Description: 72-200-01: NO. 1 ENGINE - BORESCOPE HIGH PRESSURE TURBINE NOZZLE</i>	1999M.1B.80-16 5094051	12/12/2016	07/29/2017	07/29/2017
80-17-Maintenance <i>Description: 72-200-01: NO. 2 ENGINE - BORESCOPE HIGH PRESSURE TURBINE NOZZLE</i>	1999M.1B.80-17 5094052	12/12/2016	07/29/2017	07/29/2017
80-18-Maintenance <i>Description: 72-210-01: NO. 1 ENGINE - BORESCOPE HIGH PRESSURE TURBINE BLADES</i>	1999M.1B.80-18 5094053	12/12/2016	07/29/2017	07/29/2017
80-19-Maintenance <i>Description: 72-210-01: NO. 2 ENGINE - BORESCOPE HIGH PRESSURE TURBINE BLADES</i>	1999M.1B.80-19 5094054	12/12/2016	07/29/2017	07/29/2017
Count: 25		25		21
Task Card: 1B.50-2.NR-1				
<i>Description: DURING TEST OF EMER LIGHTS CAPACITY CHECK THE FOLLOWING LIGHTS FAILED, LH & RH OVERWIN LIGHTS, ALL FLOOR EMER LIGHTS.</i>		Drawing: N/A	03/16/2017	06/15/2018
505-20-AVIONICS, Mx <i>Description: DURING TEST OF EMER LIGHTS CAPACITY CHECK THE FOLLOWING LIGHTS FAILED, LH & RH OVERWIN LIGHTS, ALL FLOOR EMER LIGHTS.</i>	1999M.1B.50-2.NR-1.50-20 5096681	03/16/2017	01/08/2018	06/15/2018
Count: 1		1		1
Task Card: 1B.701-11.NR-1				
<i>Description: Water Heater leaking aft lavatory- leaking water beyond AMM limits</i>		Drawing: N/A	06/27/2018	
701-27-SYSTEM SHOP, FABRICATE <i>Description: Water Heater leaking aft lavatory- leaking water beyond AMM limits</i>	1999M.1B.701-11.NR-1.701-27 5111752	06/27/2018		
Count: 1		1		0
Task Card: 1B.701-11.NR-2				
<i>Description: Broken water Selector Valve Fwd Crew Lav, leaking static beyond AMM limits</i>		Drawing: N/A	06/27/2018	
701-28-SYSTEM SHOP, FABRICATE <i>Description: Broken water Selector Valve Fwd Crew Lav, leaking static beyond AMM limits</i>	1999M.1B.701-11.NR-2.701-28 5111754	06/27/2018		
Count: 1		1		0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1B.80-2.NR-1 Drawing: N/A 04/05/2017 01/10/2018				
<i>Description: RT I/B FLAP O/B FLAP FAIRING SEAL IS TORN.</i>				
80-23-Maintenance	1999M.1B.80-2.NR-1.80-23	5097835	04/05/2017	01/09/2018 01/10/2018
<i>Description: RT I/B FLAP O/B FLAP FAIRING SEAL IS TORN.</i>				
Count: 1			1	1
Task Card: 1B.80-2.NR-2 Drawing: N/A 04/04/2017 05/10/2017				
<i>Description: ALL RT FLAP (I/N & O/B) TRACKS REQUIRE REMOVAL OF OLD GREASE FROM FLAP TRACK FLANGES.</i>				
801-24-Maintenance	1999M.1B.80-2.NR-2.801-24	5097836	04/04/2017	05/10/2017 05/10/2017
<i>Description: ALL RT FLAP (I/N & O/B) TRACKS REQUIRE REMOVAL OF OLD GREASE FROM FLAP TRACK FLANGES.</i>				
Count: 1			1	1
Task Card: 1B.80-2.NR-3 Drawing: N/A 04/05/2017 04/18/2017				
<i>Description: RT O/B FLAP I/B MAIN FLAP CARRIAGE SEAL RETAINER UNDER DUST CAP IS NO LONGER ENGAGED.</i>				
80-25-Maintenance	1999M.1B.80-2.NR-3.80-25	5097837	04/05/2017	04/18/2017 04/18/2017
<i>Description: RT O/B FLAP I/B MAIN FLAP CARRIAGE SEAL RETAINER UNDER DUST CAP IS NO LONGER ENGAGED.</i>				
Count: 1			1	1
Task Card: 1B.80-5.NR-1 Drawing: N/A 04/05/2017 01/04/2018				
<i>Description: AIRSTAIR DOOR LOCKPIN HAS A CHIP OUT OF THE CORNER OF THE PIN.</i>				
80-21-Maintenance	1999M.1B.80-5.NR-1.80-21	5097832	04/05/2017	01/03/2018 01/04/2018
<i>Description: AIRSTAIR DOOR LOCKPIN HAS A CHIP OUT OF THE CORNER OF THE PIN.</i>				
Count: 1			1	1
Task Card: 1B.80-5.NR-2 Drawing: N/A 04/03/2017				
<i>Description: AIRSTAIR HANDRAIL FORWARD AND AFT UPPER SUPPORT RODS ARE CRACKED.</i>				
80-22-Maintenance	1999M.1B.80-5.NR-2.80-22	5097833	04/03/2017	
<i>Description: AIRSTAIR HANDRAIL FORWARD AND AFT UPPER SUPPORT RODS ARE CRACKED.</i>				
Count: 1			1	0
Task Card: 1B.80-5.NR-3 Drawing: N/A 10/11/2017 01/05/2018				
<i>Description: While replacing airstair outer door lockpin found target support bracket for door warning system damaged</i>				
80-26-Maintenance	1999M.1B.80-5.NR-3.80-26	5102968	10/11/2017	01/04/2018 01/05/2018
<i>Description: While replacing airstair outer door lockpin found target support bracket for door warning system damaged</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C	Drawing: N/A	12/12/2016		
<i>Description: C1 check</i>				
505-AVIONICS, Mx	1999M.1C.50	5093755	12/12/2016	04/11/2017 04/11/2017
<i>Description: 24-130-00: FUNCTIONAL CHECK OF THE EXTERNAL POWER RECEPTACLE PINS FOR EXCESSIVE WEAR</i>				
505-1-AVIONICS, Mx	1999M.1C.50-1	5093756	12/12/2016	03/02/2017 03/02/2017
<i>Description: 24-140-00: DETAILED INSPECTION OF THE EXTERNAL POWER RECEPTACLE PINS FOR SIGNS OF OVERHEAT AND SECURITY OF INSTALLATION.</i>				
80-50-Maintenance	1999M.1C.80-50	5093757	12/12/2016	03/23/2017 03/23/2017
<i>Description: 52-020-00LUBRICATE THE FWD SERVICE DOOR GUIDE PLATE AND ARM ASSEMBLIES, TORQUE TUBE BUSHINGS, THE UPPER AND LOWER HINGE ARMS, GATE HINGES.</i>				
80-51-Maintenance	1999M.1C.80-51	5093758	12/12/2016	04/11/2018 04/12/2018
<i>Description: 52-020-00LUBRICATE THE AFT ENTRY DOOR GUIDE PLATE AND ARM ASSEMBLIES, TORQUE TUBE BUSHINGS, THE UPPER AND LOWER HINGE ARMS, GATE HINGES.</i>				
80-52-Maintenance	1999M.1C.80-52	5093759	12/12/2016	06/20/2018 06/21/2018
<i>Description: 52-020-00LUBRICATE THE AFT SERVICE DOOR GUIDE PLATE AND ARM ASSEMBLIES, TORQUE TUBE BUSHINGS, THE UPPER AND LOWER HINGE ARMS, GATE HINGES.</i>				
80-53-Maintenance	1999M.1C.80-53	5093760	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-030-00INSPECT (DETAILED) THE FORWARD ENTRY DOOR CENTERING GUIDE STUD AND NYLON TRACK PADS FOR CONDITION.</i>				
80-54-Maintenance	1999M.1C.80-54	5093761	12/12/2016	03/23/2017 03/23/2017
<i>Description: 52-040-00INSPECT (DETAILED) THE FWD SERVICE DOOR CENTERING GUIDE BEARINGS</i>				
80-55-Maintenance	1999M.1C.80-55	5093762	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-040-00INSPECT (DETAILED) THE AFT ENTRY DOOR CENTERING GUIDE BEARINGS</i>				
80-56-Maintenance	1999M.1C.80-56	5093763	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-040-00INSPECT (DETAILED) THE AFT SERVICE DOOR CENTERING GUIDE BEARINGS</i>				
80-57-Maintenance	1999M.1C.80-57	5093764	12/12/2016	03/23/2017 03/23/2017
<i>Description: 52-090-00LUBRICATE THE FWD CARGO COMPARTMENT DOOR LATCH TORQUE TUBE BEARINGS AND THE COUNTER BALANCE MAIN BEARINGS.</i>				
80-58-Maintenance	1999M.1C.80-58	5093765	12/12/2016	03/23/2017 03/23/2017
<i>Description: 52-090-00LUBRICATE THE AFT CARGO COMPARTMENT DOOR LATCH TORQUE TUBE BEARINGS AND THE COUNTER BALANCE MAIN BEARINGS.</i>				
80-59-Maintenance	1999M.1C.80-59	5093766	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-120-00LUBRICATE THE E/E ACCESS DOOR HANDLE LATCHING MECHANISM (RACK AND PINION GEAR AND LOCK PINS).</i>				
80-60-Maintenance	1999M.1C.80-60	5093767	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-160-00LUBRICATE THE AIRSTAIR SYSTEM.</i>				
80-61-Maintenance	1999M.1C.80-61	5093768	12/12/2016	02/23/2017 02/23/2017
<i>Description: 52-220-00OPERATIONALLY CHECK (CYCLE) THE AUTOMATIC OVERWING EMERGENCY EXIT DOORS.</i>				
80-62-Maintenance	1999M.1C.80-62	5093769	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-230-00DETAILED VISUAL INSPECTION OF THE AUTO OVERWING EMERGENCY EXIT DOOR LATCH ROLLERS, LINKS,AND PIVOT FITTINGS/JOINTS.</i>				
80-63-Maintenance	1999M.1C.80-63	5093770	12/12/2016	03/24/2017 03/24/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 52-240-00OPERATIONALLY CHECK THE FLIGHT LOCK ENGAGEMENT AND DISENGAGEMENT.</i>				
80-64-Maintenance	1999M.1C.80-64	5093771	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-250-00PERFORM A DETAILED VISUAL INSPECTION OF AUTOMATIC OVERWING EXIT DOOR FLIGHT LOCKS FOR CORROSION AND CONDITION.</i>				
80-65-Maintenance	1999M.1C.80-65	5093772	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-260-00INSPECT (GENERAL VISUAL) THE AUTOMATIC EMERGENCY EXIT DOOR PRESSURE SEALS FOR DEGRADATION.</i>				
80-66-Maintenance	1999M.1C.80-66	5093773	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-510-00EXTERNAL - DETAILED: FORWARD ACCESS DOOR</i>				
80-67-Maintenance	1999M.1C.80-67	5093774	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-540-00EXTERNAL - DETAILED: E/E EQUIPMENT COMPARTMENT ACCESS DOOR</i>				
80-68-Maintenance	1999M.1C.80-68	5093775	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-580-00EXTERNAL - DETAILED: FORWARD AIRSTAIRS DOOR</i>				
80-69-Maintenance	1999M.1C.80-69	5093776	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-590-00EXTERNAL - GENERAL VISUAL: FORWARD AIRSTAIRS DOOR</i>				
80-70-Maintenance	1999M.1C.80-70	5093777	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-610-00EXTERNAL - DETAILED: FORWARD ENTRY DOOR</i>				
80-71-Maintenance	1999M.1C.80-71	5093778	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-610-00EXTERNAL - DETAILED: FORWARD SERVICE DOOR</i>				
80-72-Maintenance	1999M.1C.80-72	5093779	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-610-00EXTERNAL - DETAILED: AFT ENTRY DOOR</i>				
80-73-Maintenance	1999M.1C.80-73	5093780	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-610-00EXTERNAL - DETAILED: AFT SERVICE DOOR</i>				
80-74-Maintenance	1999M.1C.80-74	5093781	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-670-00EXTERNAL - DETAILED: FORWARD CARGO DOOR</i>				
80-75-Maintenance	1999M.1C.80-75	5093782	12/12/2016	03/13/2017 03/13/2017
<i>Description: 52-670-00EXTERNAL - DETAILED: AFT CARGO DOOR</i>				
80-76-Maintenance	1999M.1C.80-76	5093783	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-730-00EXTERNAL - DETAILED: AUTOMATIC OVERWING EMERGENCY EXIT HATCHES/AUTOMATIC OVERWING EXIT DOOR</i>				
80-77-Maintenance	1999M.1C.80-77	5093784	12/12/2016	03/24/2017 03/24/2017
<i>Description: 52-730-00EXTERNAL - DETAILED: AUTOMATIC OVERWING EMERGENCY EXIT HATCHES/AUTOMATIC OVERWING EXIT DOOR</i>				
80-78-Maintenance	1999M.1C.80-78	5093785	12/12/2016	04/05/2017 04/05/2017
<i>Description: 52-804-02INTERNAL - ZONAL (GV): FORWARD CARGO DOOR</i>				
80-79-Maintenance	1999M.1C.80-79	5093786	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-808-02INTERNAL - ZONAL (GV): AFT CARGO DOOR</i>				
80-80-Maintenance	1999M.1C.80-80	5093787	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-812-01INTERNAL - ZONAL (GV): FORWARD PASSENGER ENTRY DOOR</i>				
80-81-Maintenance	1999M.1C.80-81	5093788	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-814-01EXTERNAL - ZONAL (GV): AUTOMATIC OVERWING EXIT. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE AUTOMATIC OVERWING EXIT - SECTION 44, STA 589.5</i>				
80-82-Maintenance	1999M.1C.80-82	5093789	12/12/2016	04/03/2017 04/03/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 52-818-01EXTERNAL - ZONAL (GV): AUTOMATIC OVERWING EMERGENCY EXIT</i>				
80-83-Maintenance	1999M.1C.80-83	5093790	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-824-01INTERNAL - ZONAL (GV): AFT PASSENGER ENTRY DOOR</i>				
80-84-Maintenance	1999M.1C.80-84	5093791	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-826-02EXTERNAL - ZONAL (GV): FORWARD GALLEY SERVICE DOOR.PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE FORWARD GALLEY SERVICE DOOR - SECTION 41, STA 340.</i>				
80-85-Maintenance	1999M.1C.80-85	5093792	12/12/2016	04/05/2017 04/05/2017
<i>Description: 52-828-02INTERNAL - ZONAL (GV): FORWARD SERVICE DOOR</i>				
80-86-Maintenance	1999M.1C.80-86	5093793	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-830-02EXTERNAL - ZONAL (GV): AUTOMATIC OVERWING EMERGENCY EXIT (NOTE: -800, BBJ2 AIRCRAFT ONLY).</i>				
80-87-Maintenance	1999M.1C.80-87	5093794	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-834-02EXTERNAL - ZONAL (GV): AUTOMATIC OVERWING EMERGENCY EXIT</i>				
80-88-Maintenance	1999M.1C.80-88	5093795	12/12/2016	04/03/2017 04/03/2017
<i>Description: 52-838-02EXTERNAL - ZONAL (GV): AFT GALLEY SERVICE DOOR.PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE AFT GALLEY SERVICE DOOR - SECTION 47, STA 980.</i>				
80-89-Maintenance	1999M.1C.80-89	5093796	12/12/2016	04/05/2017 04/05/2017
<i>Description: 52-840-02INTERNAL - ZONAL (GV): AFT SERVICE DOOR</i>				
80-90-Maintenance	1999M.1C.80-90	5093797	12/12/2016	03/13/2017 03/13/2017
<i>Description: 53-030-00EXTERNAL - DETAILED:CARGO DOOR SURROUND STRUCTURE FITTINGS AND STOPS INSPECT FORWARD CARGO DOOR SURROUND STRUCTURE FITTINGS AND STOPS.</i>				
80-91-Maintenance	1999M.1C.80-91	5093798	12/12/2016	03/13/2017 03/13/2017
<i>Description: 53-030-00EXTERNAL - DETAILED:CARGO DOOR FRAME SURROUND STRUCTURE FITTINGS AND STOPS INSPECT AFT CARGO DOOR SURROUND STRUCTURE FITTINGS AND STOPS.</i>				
80-92-Maintenance	1999M.1C.80-92	5093799	12/12/2016	03/24/2017 03/24/2017
<i>Description: 53-310-00EXTERNAL- DETAILED: FORWARD ENTRY DOOR FRAME, STOPS, LATCHES AND HINGES</i>				
80-93-Maintenance	1999M.1C.80-93	5093800	12/12/2016	03/24/2017 03/24/2017
<i>Description: 53-310-00EXTERNAL- DETAILED: FORWARD SERVICE DOOR FRAME, STOPS, LATCHES AND HINGES</i>				
80-94-Maintenance	1999M.1C.80-94	5093801	12/12/2016	03/24/2017 03/24/2017
<i>Description: 53-310-00EXTERNAL- DETAILED: AFT ENTRY DOOR FRAME, STOPS, LATCHES AND HINGES</i>				
80-95-Maintenance	1999M.1C.80-95	5093802	12/12/2016	03/24/2017 03/24/2017
<i>Description: 53-310-00EXTERNAL- DETAILED: AFT SERVICE DOOR FRAME, STOPS, LATCHES AND HINGES</i>				
80-96-Maintenance	1999M.1C.80-96	5093803	12/12/2016	04/05/2017 04/05/2017
<i>Description: 53-802-00PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE RADOME</i>				
80-97-Maintenance	1999M.1C.80-97	5093804	12/12/2016	04/03/2017 04/03/2017
<i>Description: 53-804-00INTERNAL - ZONAL (GV): AREA FORWARD OF NOSE WHEEL WELL. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AREA FORWARD OF THE NOSE WHEEL WELL - SECTION 41, STA 178 TO STA 224.8. (EZAP) THIS EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>				
80-98-Maintenance	1999M.1C.80-98	5093805	12/12/2016	04/03/2017 04/03/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> 53-806-00INTERNAL - ZONAL (GV): AREA ABOVE AND OUTBOARD OF NOSE WHEEL WELL. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AREA ABOVE AND OUTBOARD OF THE NOSE WHEEL WELL. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION				
80-99-Maintenance	1999M.1C.80-99	5093806	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-808-00INTERNAL - ZONAL (GV): ELECTRICAL AND ELECTRONICS COMPARTMENT. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE ELECTRICAL AND ELECTRONICS COMPARTMENT. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FORWARD AIRSTAIR DRIP PAN ACCESS PANEL MUST BE REMOVED IF AIRSTAIR INSTALLED.				
80-100-Maintenance	1999M.1C.80-100	5093807	12/12/2016	03/07/2017 03/07/2017
<i>Description:</i> 53-810-00INTERNAL - ZONAL (GV): ELECTRICAL AND ELECTRONICS COMPARTMENT ACCESS DOOR				
80-101-Maintenance	1999M.1C.80-101	5093808	12/12/2016	02/23/2017 02/23/2017
<i>Description:</i> 53-818-00EXTERNAL - ZONAL (GV):FORWARD CARGO DOOR SURROUND STRUCTURE FITTINGS AND STOPS				
80-102-Maintenance	1999M.1C.80-102	5093809	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-828-00INTERNAL - ZONAL (GV): KEEL BEAM (PART) STA 540 TO 727. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE KEEL BEAM (PART) STA 540 TO 727 - SECTION 44. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-103-Maintenance	1999M.1C.80-103	5093810	12/12/2016	02/23/2017 02/23/2017
<i>Description:</i> 53-836-00PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE AFT CARGO DOOR SURROUND STRUCTURE FITTINGS & STOPS - SECTION 46, STA 827				
80-104-Maintenance	1999M.1C.80-104	5093811	12/12/2016	03/16/2017 03/16/2017
<i>Description:</i> 53-838-00PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AFT CARGO COMPARTMENT VACUUM WASTE COMPARTMENT. ACCESS NOTE: VACUUM WASTE COMPARTMENT PANELS REMOVAL REQUIRED.				
80-105-Maintenance	1999M.1C.80-105	5093812	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-842-00INTERNAL - ZONAL (GV): AFT CARGO COMPARTMENT EQUIPMENT BAY PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AFT CARGO COMPARTMENT EQUIPMENT BAY - SECTION 47, STA 947.5 TO AFT PRESSURE BULKHEAD. (EZAP)				
80-106-Maintenance	1999M.1C.80-106	5093813	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-846-00INTERNAL - ZONAL (GV): LOWER WING TO BODY FAIRING - FORWARD OF WING BOX. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LOWER WING TO BODY FAIRING - FORWARD OF WING BOX. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-107-Maintenance	1999M.1C.80-107	5093814	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-848-00INTERNAL - ZONAL (GV): LOWER WING TO BODY FAIRING - UNDER WING BOX. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LOWER WING TO BODY FAIRING - UNDER THE WING BOX. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-108-Maintenance	1999M.1C.80-108	5093815	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-852-00INTERNAL - ZONAL (GV): LOWER WING TO BODY FAIRING - AFT OF WHEEL WELL				
80-109-Maintenance	1999M.1C.80-109	5093816	12/12/2016	04/19/2017 04/19/2017
<i>Description:</i> 53-858-00EXTERNAL - ZONAL (GV): FLIGHT CONTROL COMPARTMENT PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE FLIGHT CONTROL COMPARTMENT - SECTION 41, STA 178 TO STA 270				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-110-Maintenance	1999M.1C.80-110	5093817	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-860-00INTERNAL - ZONAL (GV): FLIGHT CONTROL COMPARTMENT PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FLIGHT CONTROL COMPARTMENT - SECTION 41, STA 178 TO STA 270.					
80-111-Maintenance	1999M.1C.80-111	5093818	12/12/2016	04/19/2017	04/19/2017
<i>Description:</i> 53-864-00EXTERNAL - ZONAL (GV): PASSENGER COMPARTMENT - AFT OF CONTROL COMPARTMENT TO FWD ENTRY DOOR PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE PASSENGER COMPARTMENT - AFT OF THE CONTROL COMPARTMENT TO FORWARD ENTRY DOOR - LEFT AND RIGHT - SECTION 41, STA 270 TO STA 360					
80-112-Maintenance	1999M.1C.80-112	5093819	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-866-00INTERNAL - ZONAL (GV): PASSENGER COMPARTMENT -SECTION 41, STA 270 TO STA 360. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE PASSENGER COMPARTMENT - SECTION 41, STA 270 TO STA 360.					
80-113-Maintenance	1999M.1C.80-113	5093820	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-870-00EXTERNAL - ZONAL (GV): FORWARD PASSENGER ENTRY DOOR STOPS, LATCHES, AND HINGES					
80-114-Maintenance	1999M.1C.80-114	5093821	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 53-872-00EXTERNAL - ZONAL (GV): FORWARD SERVICE DOOR STOPS, LATCHES, AND HINGES					
80-115-Maintenance	1999M.1C.80-115	5093822	12/12/2016	04/19/2017	04/19/2017
<i>Description:</i> 53-874-00EXTERNAL - ZONAL (GV): FORWARD PASSENGER COMPARTMENT - STA 360 TO STA 663.75					
80-116-Maintenance	1999M.1C.80-116	5093823	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-876-00INTERNAL - ZONAL (GV): FORWARD PASSENGER COMPARTMENT - STA 360 TO STA 663.75					
80-117-Maintenance	1999M.1C.80-117	5093824	12/12/2016	04/19/2017	04/19/2017
<i>Description:</i> 53-882-00EXTERNAL - ZONAL (GV): AFT PASSENGER COMPARTMENT - STA 663.75 TO AFT PRESSURE BULKHEAD					
80-118-Maintenance	1999M.1C.80-118	5093825	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-884-00INTERNAL - ZONAL (GV): AFT PASSENGER COMPARTMENT - STA 663.75 TO AFT PRESSURE BULKHEAD					
80-119-Maintenance	1999M.1C.80-119	5093826	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-890-00EXTERNAL - ZONAL (GV): AFT PASSENGER ENTRY DOOR STOPS, LATCHES, AND HINGES					
80-120-Maintenance	1999M.1C.80-120	5093827	12/12/2016	04/03/2017	04/03/2017
<i>Description:</i> 53-892-00EXTERNAL - ZONAL (GV): AFT SERVICE DOOR STOPS, LATCHES, AND HINGES					
80-121-Maintenance	1999M.1C.80-121	5093828	12/12/2016	10/19/2017	10/20/2017
<i>Description:</i> 53-896-00INTERNAL - ZONAL (GV): AREA AFT OF PRESSURE BULKHEAD. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AREA AFT OF PRESSURE BULKHEAD - SECTION 48, AFT OF AFT PRESSURE BULKHEAD TO STA 1088. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.					
80-122-Maintenance	1999M.1C.80-122	5093829	12/12/2016	04/05/2017	04/05/2017
<i>Description:</i> 53-898-00INTERNAL - ZONAL (GV): STABILIZER TORSION BOX COMPARTMENT. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE STABILIZER TORSION BOX COMPARTMENT - SECTION 48, STA 1088 TO STA 1156. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.					
80-123-Maintenance	1999M.1C.80-123	5093830	12/12/2016	03/07/2017	03/07/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> 53-900-00INTERNAL - ZONAL (GV): APU COMPARTMENT. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE APU COMPARTMENT - SECTION 48, STA 1088 TO STA 1156. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-124-Maintenance	1999M.1C.80-124	5093831	12/12/2016	04/19/2017 04/19/2017
<i>Description:</i> 53-902-00INTERNAL - ZONAL (GV): TAIL CONE. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE TAIL CONE - SECTION 48, STA 1156 TO STA 1217. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-125-Maintenance	1999M.1C.80-125	5093832	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-904-01INTERNAL - ZONAL (GV): FLAP SUPPORT NO. 4 - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FLAP SUPPORT NO. 4 - LEFT WING - SECTION 46, STA 727. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS EXTENDED.				
80-126-Maintenance	1999M.1C.80-126	5093833	12/12/2016	04/03/2017 04/03/2017
<i>Description:</i> 53-906-02INTERNAL - ZONAL (GV): FLAP SUPPORT NO. 5 - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FLAP SUPPORT NO. 5 - RIGHT WING - SECTION 46, STA 727. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS EXTENDED.				
80-128-Maintenance	1999M.1C.80-128	5093834	12/12/2016	03/07/2017 03/07/2017
<i>Description:</i> 54-040-01INTERNAL - GENERAL VISUAL: LEFT STRUT TO WING ATTACHMENTS. INSPECT STRUT TO WING UPPER LINK, DIAGONAL BRACE, SIDE LINKS, AND STRUT ATTACHMENT FITTINGS.				
80-129-Maintenance	1999M.1C.80-129	5093835	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 54-040-02INTERNAL - GENERAL VISUAL: RIGHT STRUT TO WING ATTACHMENTS. INSPECT STRUT TO WING UPPER LINK, DIAGONAL BRACE, SIDE LINKS, AND STRUT ATTACHMENT FITTINGS.				
80-130-Maintenance	1999M.1C.80-130	5093836	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 54-050-01INTERNAL - DETAILED: LEFT STRUT TO WING ATTACHMENTS. INSPECT PINS AND FUSE PINS ON UPPER LINK, MIDSPAR, DIAGONAL BRACE, AND SIDE LINKS. PIN REMOVAL IS NOT REQUIRED.				
80-131-Maintenance	1999M.1C.80-131	5093837	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 54-050-02INTERNAL - DETAILED: RIGHT STRUT TO WING ATTACHMENTS. INSPECT PINS AND FUSE PINS ON UPPER LINK, MIDSPAR, DIAGONAL BRACE, AND SIDE LINKS. PIN REMOVAL IS NOT REQUIRED.				
80-132-Maintenance	1999M.1C.80-132	5093838	12/12/2016	03/10/2017 03/10/2017
<i>Description:</i> 54-800-01INTERNAL - ZONAL (GV): FORWARD STRUT FAIRING - ENGINE NO. 1. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FORWARD STRUT FAIRING - ENGINE NO. 1. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-133-Maintenance	1999M.1C.80-133	5093839	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 54-802-01INTERNAL - ZONAL (GV): FAN COWL SUPPORT BEAM - ENGINE NO. 1. PERFORM AN INTERNAL ZONAL INSPECTION (GV) ON THE FAN COWL SUPPORT BEAM - ENGINE NO. 1. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-134-Maintenance	1999M.1C.80-134	5093840	12/12/2016	03/10/2017 03/10/2017
<i>Description:</i> 54-804-01INTERNAL - ZONAL (GV): STRUT TORQUE BOX - ENGINE NO. 1. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE STRUT TORQUE BOX - ENGINE NO. 1. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.				
80-135-Maintenance	1999M.1C.80-135	5093841	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 54-806-01INTERNAL - ZONAL (GV): AFT STRUT FAIRING - ENGINE NO. 1. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AFT STRUT FAIRING - ENGINE NO. 1. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 12000 FC/4 YR IS SATISFIED BY THIS ZONAL INSPECTION.				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
80-136-Maintenance <i>Description: 54-808-02INTERNAL - ZONAL (GV): FORWARD STRUT FAIRING - ENGINE NO. 2. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FORWARD STRUT FAIRING - ENGINE NO. 2. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-136 5093842	12/12/2016	03/02/2017	03/02/2017
80-137-Maintenance <i>Description: 54-810-02INTERNAL - ZONAL (GV): FAN COWL SUPPORT BEAM - ENGINE NO. 2. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAN COWL SUPPORT BEAM - ENGINE NO. 2. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-137 5093843	12/12/2016	01/03/2018	01/05/2018
80-138-Maintenance <i>Description: 54-812-02INTERNAL - ZONAL (GV): STRUT TORQUE BOX - ENGINE NO. 2. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE STRUT TORQUE BOX - ENGINE NO. 2. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-138 5093844	12/12/2016	01/03/2018	01/05/2018
80-139-Maintenance <i>Description: 54-814-02INTERNAL - ZONAL (GV): AFT STRUT FAIRING - ENGINE NO. 2. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE AFT STRUT FAIRING - ENGINE NO. 2. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 12000 FC/4 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-139 5093845	12/12/2016	03/02/2017	03/02/2017
80-140-Maintenance <i>Description: 55-802-00EXTERNAL - ZONAL (GV): VERTICAL FIN - DORSAL FIN</i>	1999M.1C.80-140 5093846	12/12/2016	04/21/2017	04/21/2017
80-141-Maintenance <i>Description: 55-804-00INTERNAL - ZONAL (GV): VERTICAL FIN - LEADING EDGE</i>	1999M.1C.80-141 5093847	12/12/2016	04/19/2017	04/19/2017
80-142-Maintenance <i>Description: 55-806-00EXTERNAL - ZONAL (GV): VERTICAL FIN - LEADING EDGE</i>	1999M.1C.80-142 5093848	12/12/2016	04/21/2017	04/21/2017
80-143-Maintenance <i>Description: 55-810-00INTERNAL - ZONAL (GV): VERTICAL FIN - FRONT SPAR TO REAR SPAR. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE VERTICAL FIN - FRONT SPAR TO REAR SPAR. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-143 5093849	12/12/2016	04/21/2017	04/21/2017
80-144-Maintenance <i>Description: 55-812-00EXTERNAL - ZONAL (GV): VERTICAL FIN - FRONT SPAR TO REAR SPAR</i>	1999M.1C.80-144 5093850	12/12/2016	04/21/2017	04/21/2017
80-145-Maintenance <i>Description: 55-814-00INTERNAL - ZONAL (GV): VERTICAL FIN - REAR SPAR TO TRAILING EDGE. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE VERTICAL FIN - REAR SPAR TO TRAILING EDGE. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>	1999M.1C.80-145 5093851	12/12/2016	04/21/2017	04/21/2017
80-146-Maintenance <i>Description: 55-816-00EXTERNAL - ZONAL (GV): VERTICAL FIN - REAR SPAR TO TRAILING EDGE</i>	1999M.1C.80-146 5093852	12/12/2016	04/21/2017	04/21/2017
80-147-Maintenance <i>Description: 55-818-00EXTERNAL - ZONAL (GV): RUDDER</i>	1999M.1C.80-147 5093853	12/12/2016	04/21/2017	04/21/2017
80-148-Maintenance <i>Description: 55-820-00EXTERNAL - ZONAL (GV): VERTICAL FIN TIP</i>	1999M.1C.80-148 5093854	12/12/2016	04/21/2017	04/21/2017
80-149-Maintenance <i>Description: 55-822-01EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - LEADING EDGE - LEFT</i>	1999M.1C.80-149 5093855	12/12/2016	03/02/2017	03/02/2017
80-150-Maintenance	1999M.1C.80-150 5093856	12/12/2016	03/03/2017	03/03/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 55-824-01EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - FRONT SPAR TO REAR SPAR-LEFT</i>				
80-151-Maintenance	1999M.1C.80-151	5093857	12/12/2016	04/05/2017 04/05/2017
<i>Description: 55-826-01INTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - FRONT SPAR TO REAR SPAR-LEFT</i>				
80-152-Maintenance	1999M.1C.80-152	5093858	12/12/2016	04/05/2017 04/05/2017
<i>Description: 55-828-01INTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE - LEFT. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE - LEFT. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>				
80-153-Maintenance	1999M.1C.80-153	5093859	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-830-01EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE-LEFT</i>				
80-154-Maintenance	1999M.1C.80-154	5093860	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-832-01EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - ELEVATOR - LEFT</i>				
80-155-Maintenance	1999M.1C.80-155	5093861	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-834-01EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - STABILIZER TIP - LEFT</i>				
80-156-Maintenance	1999M.1C.80-156	5093862	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-836-02EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - LEADING EDGE - RIGHT</i>				
80-157-Maintenance	1999M.1C.80-157	5093863	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-838-02EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - FRONT SPAR TO REAR SPAR-RIGHT</i>				
80-158-Maintenance	1999M.1C.80-158	5093864	12/12/2016	04/05/2017 04/05/2017
<i>Description: 55-840-02INTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - FRONT SPAR TO REAR SPAR-RIGHT</i>				
80-159-Maintenance	1999M.1C.80-159	5093865	12/12/2016	04/05/2017 04/05/2017
<i>Description: 55-842-02INTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE - RIGHT. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE - RIGHT. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION.</i>				
80-160-Maintenance	1999M.1C.80-160	5093866	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-844-02EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - REAR SPAR TO TRAILING EDGE-RIGHT</i>				
80-161-Maintenance	1999M.1C.80-161	5093867	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-846-02EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - ELEVATOR - RIGHT</i>				
80-162-Maintenance	1999M.1C.80-162	5093868	12/12/2016	03/03/2017 03/03/2017
<i>Description: 55-848-02EXTERNAL - ZONAL (GV): HORIZONTAL STABILIZER - STABILIZER TIP - RIGHT</i>				
80-163-Maintenance	1999M.1C.80-163	5093869	12/12/2016	03/24/2017 03/24/2017
<i>Description: 56-010-00LUBRICATE THE INSIDE RELEASE MECHANISMS FOR THE PILOT AND COPILOT'S #2 SLIDING WINDOWS. LUBRICATE OUTSIDE RELEASE MECHANISM FOR THE COPILOT'S #2 SLIDING WINDOW.</i>				
80-164-Maintenance	1999M.1C.80-164	5093870	12/12/2016	02/23/2017 02/23/2017
<i>Description: 56-030-00OPERATIONALLY CHECK THE INSIDE RELEASE MECHANISMS FOR THE PILOT'S AND COPILOT'S #2 SLIDING WINDOW FROM THE OUTSIDE.</i>				
80-165-Maintenance	1999M.1C.80-165	5093871	12/12/2016	04/03/2017 04/03/2017
<i>Description: 56-050-00GENERAL VISUAL CHECK OF THE PILOT'S AND COPILOT'S #2 SLIDING WINDOW SILL DRAIN FOR OBVIOUS DAMAGE, CLOGGING, CONDITION, AND SECURITY.</i>				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
80-166-Maintenance	1999M.1C.80-166	5093872	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 57-100-01INTERNAL - GENERAL VISUAL: LEFT NACELLE SUPPORT FITTINGS. INSPECT THE FOLLOWING FITTINGS: 1. FRONT SPAR PITCH LOAD FITTING (R1); 2. AFT DRAG LOAD FITTING (R2); 3. OUTBOARD SIDE LOAD FITTING (R3); 4. INBOARD SIDE LOAD FITTING (R4); 5. SIDE BRACE SUPPORT FITTINGS (R7 AND R8); 6. R3 FORWARD BACKUP FITTING. INSPECT UPPER WING SKIN AT ATTACHMENT TO NACELLE FITTING R1.				
80-167-Maintenance	1999M.1C.80-167	5093873	12/12/2016	03/08/2017 03/08/2017
<i>Description:</i> 57-100-02INTERNAL - GENERAL VISUAL: RIGHT NACELLE SUPPORT FITTINGS. INSPECT THE FOLLOWING FITTINGS: 1. FRONT SPAR PITCH LOAD FITTING (R1); 2. AFT DRAG LOAD FITTING (R2); 3. OUTBOARD SIDE LOAD FITTING (R3); 4. INBOARD SIDE LOAD FITTING (R4); 5. SIDE BRACE SUPPORT FITTINGS (R7 AND R8); 6. R3 FORWARD BACKUP FITTING. INSPECT UPPER WING SKIN AT ATTACHMENT TO NACELLE FITTING R1.				
80-168-Maintenance	1999M.1C.80-168	5093874	12/12/2016	03/24/2017 03/24/2017
<i>Description:</i> 57-110-01INTERNAL - GENERAL VISUAL: LEFT OUTBOARD WING LOWER SURFACE				
80-169-Maintenance	1999M.1C.80-169	5093875	12/12/2016	04/04/2017 04/04/2017
<i>Description:</i> 57-110-02INTERNAL - GENERAL VISUAL: RIGHT OUTBOARD WING LOWER SURFACE				
80-170-Maintenance	1999M.1C.80-170	5093876	12/12/2016	02/23/2017 02/23/2017
<i>Description:</i> 57-804-01EXTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - INBD OF NACELLE STRUT-LEFT WING				
80-171-Maintenance	1999M.1C.80-171	5093877	12/12/2016	03/13/2017 03/13/2017
<i>Description:</i> 57-806-01INTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - INBD OF NACELLE STRUT - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LEADING EDGE TO FRONT SPAR - INBOARD OF NACELLE STRUT - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS DEPLOYED.				
80-172-Maintenance	1999M.1C.80-172	5093878	12/12/2016	03/13/2017 03/13/2017
<i>Description:</i> 57-808-01EXTERNAL - ZONAL (GV): KRUEGER FLAPS NO. 1 AND 2 - LEFT WING				
80-173-Maintenance	1999M.1C.80-173	5093879	12/12/2016	03/13/2017 03/13/2017
<i>Description:</i> 57-810-01INTERNAL - ZONAL (GV): KRUEGER FLAPS NO. 1 AND 2 - LEFT WING				
80-174-Maintenance	1999M.1C.80-174	5093880	12/12/2016	03/14/2017 03/14/2017
<i>Description:</i> 57-812-01EXTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - OUTBD OF NACELLE STRUT-LEFT WING				
80-175-Maintenance	1999M.1C.80-175	5093881	12/12/2016	03/14/2017 03/14/2017
<i>Description:</i> 57-814-01INTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - OUTBD OF NACELLE STRUT - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LEADING EDGE TO FRONT SPAR - OUTBOARD OF NACELLE STRUT - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: SLATS DEPLOYED.				
80-176-Maintenance	1999M.1C.80-176	5093882	12/12/2016	03/14/2017 03/14/2017
<i>Description:</i> 57-816-01EXTERNAL - ZONAL (GV): SLATS NO. 1, 2, 3, 4 - LEFT WING				
80-177-Maintenance	1999M.1C.80-177	5093883	12/12/2016	03/24/2017 03/24/2017
<i>Description:</i> 57-824-01EXTERNAL - ZONAL (GV): CENTER FUEL TANK - LEFT WING				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-178-Maintenance	1999M.1C.80-178	5093884	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-828-01EXTERNAL - ZONAL (GV): MAIN FUEL TANK - LEFT WING					
80-179-Maintenance	1999M.1C.80-179	5093885	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-832-01EXTERNAL - ZONAL (GV): SURGE TANK - LEFT WING					
80-180-Maintenance	1999M.1C.80-180	5093886	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-834-01EXTERNAL - ZONAL (GV): DRY BAY - LEFT WING					
80-181-Maintenance	1999M.1C.80-181	5093887	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-836-01EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 3 - LEFT WING					
80-182-Maintenance	1999M.1C.80-182	5093888	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-838-01INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 3 - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 3 - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS EXTENDED.					
80-183-Maintenance	1999M.1C.80-183	5093889	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-840-01EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 2 - LEFT WING					
80-184-Maintenance	1999M.1C.80-184	5093890	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-842-01INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 2 - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 2 - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS EXTENDED, INSIDE OF FAIRING.					
80-185-Maintenance	1999M.1C.80-185	5093891	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-844-01EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 1 - LEFT WING					
80-186-Maintenance	1999M.1C.80-186	5093892	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-846-01INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 1 - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 1 - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS EXTENDED.					
80-187-Maintenance	1999M.1C.80-187	5093893	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-848-01EXTERNAL - ZONAL (GV): REAR SPAR TO LANDING GEAR SUPPORT BEAM - LEFT WING					
80-188-Maintenance	1999M.1C.80-188	5093894	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-852-01EXTERNAL - ZONAL (GV): INBOARD SPOILER NO. 6 - LEFT WING					
80-189-Maintenance	1999M.1C.80-189	5093895	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-854-01EXTERNAL - ZONAL (GV): INBOARD FLAPS - LEFT WING					
80-190-Maintenance	1999M.1C.80-190	5093896	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-858-01EXTERNAL - ZONAL (GV): REAR SPAR TO T.E. - OUTBD OF INBD FLAP - INBD OF FIXED T.E. - L. WING. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE REAR SPAR TO TRAILING EDGE - OUTBOARD OF INBOARD FLAP - INBOARD OF FIXED TRAILING EDGE - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS DOWN, SPOILERS RAISED.					
80-191-Maintenance	1999M.1C.80-191	5093897	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-860-01EXTERNAL - ZONAL (GV): SPOILERS NO. 1, 2, 3, 4, 5 - LEFT WING					
80-192-Maintenance	1999M.1C.80-192	5093898	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-862-01EXTERNAL - ZONAL (GV): OUTBOARD FLAPS - LEFT WING					



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-193-Maintenance	1999M.1C.80-193	5093899	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-864-01EXTERNAL - ZONAL (GV): FIXED TRAILING EDGE - LEFT WING					
80-194-Maintenance	1999M.1C.80-194	5093900	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-868-01INTERNAL - ZONAL (GV): FIXED TRAILING EDGE - L. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FIXED TRAILING EDGE - LEFT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: AILERON CONTROL AREA ONLY.					
80-195-Maintenance	1999M.1C.80-195	5093901	12/12/2016	03/24/2017	03/24/2017
<i>Description:</i> 57-870-01EXTERNAL - ZONAL (GV): AILERON - LEFT WING					
80-196-Maintenance	1999M.1C.80-196	5093902	12/12/2016	02/23/2017	02/23/2017
<i>Description:</i> 57-874-02EXTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - INBD OF NACELLE STRUT-RIGHT WING					
80-197-Maintenance	1999M.1C.80-197	5093903	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-876-02INTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - INBD OF NACELLE STRUT - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LEADING EDGE TO FRONT SPAR - INBOARD OF THE NACELLE STRUT - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: FLAPS DEPLOYED.					
80-198-Maintenance	1999M.1C.80-198	5093904	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-878-02EXTERNAL - ZONAL (GV): KRUEGER FLAPS NO. 3 AND 4 - RIGHT WING					
80-199-Maintenance	1999M.1C.80-199	5093905	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-880-02INTERNAL - ZONAL (GV): KRUEGER FLAPS NO. 3 AND 4 - RIGHT WING					
80-200-Maintenance	1999M.1C.80-200	5093906	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-882-02EXTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - OUTBD OF NACELLE STRUT-RIGHT WING					
80-201-Maintenance	1999M.1C.80-201	5093907	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-884-02INTERNAL - ZONAL (GV): LEADING EDGE TO FRONT SPAR - OUTBD OF NACELLE STRUT - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE LEADING EDGE TO FRONT SPAR - OUTBOARD OF THE NACELLE STRUT - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: SLATS DEPLOYED.					
80-202-Maintenance	1999M.1C.80-202	5093908	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-886-02EXTERNAL - ZONAL (GV) : RIGHT WING SLATS No. 5, 6, 7 & 8					
80-203-Maintenance	1999M.1C.80-203	5093909	12/12/2016	03/27/2017	03/27/2017
<i>Description:</i> 57-894-02EXTERNAL - ZONAL (GV): CENTER FUEL TANK - RIGHT WING					
80-204-Maintenance	1999M.1C.80-204	5093910	12/12/2016	03/27/2017	03/27/2017
<i>Description:</i> 57-898-02EXTERNAL - ZONAL (GV): MAIN FUEL TANK - RIGHT WING					
80-205-Maintenance	1999M.1C.80-205	5093911	12/12/2016	03/27/2017	03/27/2017
<i>Description:</i> 57-902-02EXTERNAL - ZONAL (GV): SURGE TANK - RIGHT WING					
80-206-Maintenance	1999M.1C.80-206	5093912	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-904-02EXTERNAL - ZONAL (GV): DRY BAY - RIGHT WING					
80-207-Maintenance	1999M.1C.80-207	5093913	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-906-02EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 6 - RIGHT WING					



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-208-Maintenance	1999M.1C.80-208	5093914	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-908-02INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 6 - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 6 - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. <i>ACCESS NOTE:</i> FLAPS EXTENDED.					
80-209-Maintenance	1999M.1C.80-209	5093915	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-910-02EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 7 - RIGHT WING					
80-210-Maintenance	1999M.1C.80-210	5093916	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-912-02INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 7 - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 7 - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. <i>ACCESS NOTE:</i> FLAPS EXTENDED.					
80-211-Maintenance	1999M.1C.80-211	5093917	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-914-02EXTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 8 - RIGHT WING					
80-212-Maintenance	1999M.1C.80-212	5093918	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-916-02INTERNAL - ZONAL (GV): FAIRING FLAP SUPPORT NO. 8 - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FAIRING FLAP SUPPORT NO. 8 - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. <i>ACCESS NOTE:</i> FLAPS EXTENDED, INSIDE OF FAIRING.					
80-213-Maintenance	1999M.1C.80-213	5093919	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-918-02EXTERNAL - ZONAL (GV): REAR SPAR TO LANDING GEAR SUPPORT BEAM - RIGHT WING					
80-214-Maintenance	1999M.1C.80-214	5093920	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-922-02EXTERNAL - ZONAL (GV): INBOARD SPOILER NO. 7 - RIGHT WING					
80-215-Maintenance	1999M.1C.80-215	5093921	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-924-02EXTERNAL - ZONAL (GV): INBOARD FLAPS - RIGHT WING					
80-216-Maintenance	1999M.1C.80-216	5093922	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-928-02EXTERNAL - ZONAL (GV): REAR SPAR TO T.E. - OUTBD OF INBD FLAP - INBD OF FIXED T.E. - R. WING. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE REAR SPAR TO TRAILING EDGE - OUTBOARD OF INBOARD FLAP - INBOARD OF FIXED TRAILING EDGE - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 18000 FC/6 YR IS SATISFIED BY THIS ZONAL INSPECTION. <i>ACCESS NOTE:</i> FLAPS DOWN, SPOILERS RAISED.					
80-217-Maintenance	1999M.1C.80-217	5093923	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-930-02EXTERNAL - ZONAL (GV): SPOILERS NO. 8, 9, 10, 11, 12 - RIGHT WING					
80-218-Maintenance	1999M.1C.80-218	5093924	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-932-02EXTERNAL - ZONAL (GV): OUTBOARD FLAPS - RIGHT WING					
80-219-Maintenance	1999M.1C.80-219	5093925	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-934-02EXTERNAL - ZONAL (GV): FIXED TRAILING EDGE - RIGHT WING					
80-220-Maintenance	1999M.1C.80-220	5093926	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-938-02INTERNAL - ZONAL (GV): FIXED TRAILING EDGE - R. WING. PERFORM AN INTERNAL ZONAL INSPECTION (GV) OF THE FIXED TRAILING EDGE - RIGHT WING. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 36000 FC/12 YR IS SATISFIED BY THIS ZONAL INSPECTION. <i>ACCESS NOTE:</i> AILERON CONTROL AREA ONLY.					



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-221-Maintenance	1999M.1C.80-221	5093927	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 57-940-02EXTERNAL - ZONAL (GV): AILERON - RIGHT WING					
80-222-Maintenance	1999M.1C.80-222	5093928	12/12/2016	11/21/2017	11/21/2017
<i>Description:</i> 70-802-01EXTERNAL - ZONAL (GV): ENGINE NO. 1. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF ENGINE NO. 1. (EZAP) INTERVAL NOTE: THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION.					
80-223-Maintenance	1999M.1C.80-223	5093929	12/12/2016	03/10/2017	03/10/2017
<i>Description:</i> 70-806-01EXTERNAL - ZONAL (GV): THRUST REVERSER - ENGINE NO. 1					
80-224-Maintenance	1999M.1C.80-224	5093930	12/12/2016	03/08/2017	03/08/2017
<i>Description:</i> 70-808-01EXTERNAL - ZONAL (GV): THRUST REVERSER - ENGINE NO. 1. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE THRUST REVERSER - ENGINE NO. 1. (EZAP) INTERVAL NOTE: THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: INNER AND OUTER EXTERIOR SURFACES.					
80-225-Maintenance	1999M.1C.80-225	5093931	12/12/2016	03/03/2017	03/03/2017
<i>Description:</i> 70-812-02EXTERNAL - ZONAL (GV): ENGINE NO. 2. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE ENGINE NO. 2. (EZAP) INTERVAL NOTE: THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION.					
80-226-Maintenance	1999M.1C.80-226	5093932	12/12/2016	03/10/2017	03/10/2017
<i>Description:</i> 70-816-02EXTERNAL - ZONAL (GV): THRUST REVERSER - ENGINE NO. 2					
80-227-Maintenance	1999M.1C.80-227	5093933	12/12/2016	03/03/2017	03/03/2017
<i>Description:</i> 70-818-02EXTERNAL - ZONAL (GV): THRUST REVERSER - ENGINE NO. 2. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE THRUST REVERSER - ENGINE NO. 2. (EZAP) INTERVAL NOTE: THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION. ACCESS NOTE: INNER AND OUTER EXTERIOR SURFACES.					
80-228-Maintenance	1999M.1C.80-228	5093934	12/12/2016	04/24/2017	04/24/2017
<i>Description:</i> 110010 : GENERAL VISUAL INSPECTION OF PLACARDS FOR LEGIBLTY AND GENERAL CONDITION					
80-229-Maintenance	1999M.1C.80-229	5093935	12/12/2016	03/14/2017	03/14/2017
<i>Description:</i> 257002: GENERAL VISUAL INSPECTION OF GALLEY LATCHS AND PROPER SEALING OF TRASH CONTAINERS					
80-230-Maintenance	1999M.1C.80-230	5093936	12/12/2016	03/14/2017	03/14/2017
<i>Description:</i> 257003: GENERAL VISUAL INSPECTION OF CHAIR FRAMES, ATTACHMENT FITTINGS, RECLINE MECHANISM, ETC. WITH UNITS IN PLACE					
80-231-Maintenance	1999M.1C.80-231	5093937	12/12/2016	03/14/2017	03/14/2017
<i>Description:</i> 257004: GENERAL VISUAL INSPECTION OF DIVAN FRAMES, ATTACHMENT FITTINGS, SEAT BELT ATTACHMENTS, ETC. WITH UNITS IN PLACE					
80-232-Maintenance	1999M.1C.80-232	5093938	12/12/2016	01/05/2018	01/08/2018
<i>Description:</i> 257005: GENERAL VISUAL INSPECTION OF BED FRAME AND ATTACHMENT FITTINGS WITH UNIT IN PLACE					
80-233-Maintenance	1999M.1C.80-233	5093939	12/12/2016	03/14/2017	03/14/2017
<i>Description:</i> 257006: GENERAL VISUAL INSPECTION OF HINGE AND LATCHES WITH UNITS IN PLACE					



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
805-234-Mx Interiors <i>Description:</i> 257007: FUNCTIONAL CHECK OF TOILET SHROUD BLOW-OUT PANELS	1999M.1C.805-234	5093940	12/12/2016	06/20/2018	06/21/2018
805-235-Mx Interiors <i>Description:</i> 257008: GENERAL VISUAL INSPECTION OF CABIN DOORS FOR PROPER TRACKING AND LATCHING, OPERATIONAL CHECK OF DOOR POSITION INDICATION SYSTEM AND FUNCTIONAL CHECK OF BLOW-OUT PANELS	1999M.1C.805-235	5093941	12/12/2016	06/20/2018	06/21/2018
80-236-Maintenance <i>Description:</i> 26-13-01: FUNCTIONALLY CHECK EXTINGUISHER MONITOR UNIT PER WALTER KIDDE DOCUMENT R-6179 OR R-6664, PARAGRAPH 5.7 FOR HOLLINGSEAD INSTALLED FIRE BOTTLE (HIGH RATE DISCHARGE)	1999M.1C.80-236	5093942	12/12/2016	03/16/2017	03/16/2017
80-237-Maintenance <i>Description:</i> 267003: OPERATIONAL CHECK CABIN AND LAVATORY SMOKE DETECTORS	1999M.1C.80-237	5093943	12/12/2016	02/23/2017	02/23/2017
80-238-Maintenance <i>Description:</i> 267004: FUNCTIONAL CHECK SMOKE DETECTION SYSTEM SENSORS	1999M.1C.80-238	5093944	12/12/2016	02/23/2017	02/23/2017
80-239-Maintenance <i>Description:</i> 32-085-00: DETAILED INSPECTION AXLE	1999M.1C.80-239	5093945	12/12/2016	08/25/2018	
80-240-Maintenance <i>Description:</i> 357001: GENERAL VISUAL INSPECTION OF PASSENGER OXYGEN PALLET ATTACH ANGLES AND FITTINGS FOR GENERAL CONDITION	1999M.1C.80-240	5093946	12/12/2016	04/04/2017	04/04/2017
80-241-Maintenance <i>Description:</i> 357002: OPERATIONAL CHECK OF PASSENGER OXYGEN UNIT BOX DOOR LATCHES AND GENERAL VISUAL INSPECTION OF MASK ASSEMBLIES (ALL)	1999M.1C.80-241	5093947	12/12/2016	04/16/2018	04/17/2018
701-242-SYSTEM SHOP, FABRICATE <i>Description:</i> 38-015-00: OPERATIONALLY CHECK FORWARD GRAY WATER DRAIN VALVE	1999M.1C.701-242	5093948	12/12/2016		
80-243-Maintenance <i>Description:</i> 49-120-00S: BORESCOPE INSPECTION OF THE APU.	1999M.1C.80-243	5093949	12/12/2016	08/09/2017	08/09/2017
80-244-Maintenance <i>Description:</i> 52-220-00: OPERATIONALLY CHECK RIGHT FORWARD AUTOMATIC OVERWING EMERGENCY EXIT DOOR (ACCESS 842)	1999M.1C.80-244	5093950	12/12/2016	02/23/2017	02/23/2017
80-245-Maintenance <i>Description:</i> 52-230-00 (04): DETAILED VISUAL INSPECTION AUTOMATIC OVERWING EMERGENCY EXIT DOOR LATCH ROLLERS, LINKS, AND PIVOT FITTINGS/JOINTS (RIGHT FORWARD) (ACCESS 842)	1999M.1C.80-245	5093951	12/12/2016	03/27/2017	03/27/2017
80-246-Maintenance	1999M.1C.80-246	5093952	12/12/2016	04/04/2017	04/04/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 52-240-00 (04): OPERATIONALLY CHECK THE FLIGHT LOCK ENGAGEMENT AND DISENGAGEMENT (ACCESS 842)</i>				
80-247-Maintenance	1999M.1C.80-247	5093953	12/12/2016	03/27/2017 03/27/2017
<i>Description: 52-250-00 (04): DETAILED VISUAL INSPECTION AUTOMATIC OVERWING EXIT DOOR FLIGHT LOCKS FOR CORROSION AND CONDITION (RIGHT FORWARD) (ACCESS 842)</i>				
80-248-Maintenance	1999M.1C.80-248	5093954	12/12/2016	04/04/2017 04/04/2017
<i>Description: 52-260-00 (04): INSPECT (GENERAL VISUAL) AUTOMATIC EMERGENCY EXIT DOOR PRESSURE SEALS FOR DEGRADATION (ACCESS 842)</i>				
80-249-Maintenance	1999M.1C.80-249	5093955	12/12/2016	04/04/2017 04/04/2017
<i>Description: 539101: GENERAL VISUAL INSPECTION OF SATCOM ANTENNAS FOR ACCIDENTAL DAMAGE AND ENVIRONMENTAL DETERIORATION</i>				
80-250-Maintenance	1999M.1C.80-250	5093956	12/12/2016	04/04/2017 04/04/2017
<i>Description: 539102: GENERAL VISUAL INSPECTION OF VIDEO CAMERAS FOR ACCIDENTAL DAMAGE AND ENVIRONMENTAL DETERIORATION</i>				
80-Maintenance	1999M.1C.80	5094056	12/12/2016	04/04/2017 04/04/2017
<i>Description: 25-150-00INSPECT (GENERAL VISUAL) THE ELECTRONIC COMPARTMENT MOISTURE SHROUDS FOR CONDITION AND SECURITY.</i>				
80-1-Maintenance	1999M.1C.80-1	5094057	12/12/2016	01/04/2018 01/05/2018
<i>Description: 25-230-00INSPECT (DETAILED) THE FWD ENTRY DOOR EMERGENCY ESCAPE SYSTEMS, INCLUDING DOOR OPENINGS AND SLIDE COMPONENTS.</i>				
80-2-Maintenance	1999M.1C.80-2	5094058	12/12/2016	01/04/2018 01/05/2018
<i>Description: 25-230-00INSPECT (DETAILED) THE FWD SERVICE DOOR EMERGENCY ESCAPE SYSTEMS, INCLUDING DOOR OPENINGS AND SLIDE COMPONENTS.</i>				
805-3-Mx Interiors	1999M.1C.805-3	5094059	12/12/2016	06/20/2018 06/21/2018
<i>Description: 25-230-00INSPECT (DETAILED) THE AFT ENTRY DOOR EMERGENCY ESCAPE SYSTEMS, INCLUDING DOOR OPENINGS AND SLIDE COMPONENTS.</i>				
80-4-Maintenance	1999M.1C.80-4	5094060	12/12/2016	01/04/2018 01/05/2018
<i>Description: 25-230-00INSPECT (DETAILED) THE AFT SERVICE DOOR EMERGENCY ESCAPE SYSTEMS, INCLUDING DOOR OPENINGS AND SLIDE COMPONENTS.</i>				
80-5-Maintenance	1999M.1C.80-5	5094061	12/12/2016	11/22/2017 11/22/2017
<i>Description: 26-020-00RESTORE SMOKE DETECTOR GRILL BY CLEANING.</i>				
80-6-Maintenance	1999M.1C.80-6	5094062	12/12/2016	03/27/2017 03/27/2017
<i>Description: 27-026-01LUBRICATE THE LEFT WING AILERON MECHANICAL CONTROL PATH AND AILERON POWER CONTROL UNITS.</i>				
80-7-Maintenance	1999M.1C.80-7	5094063	12/12/2016	03/27/2017 03/27/2017
<i>Description: 27-026-02LUBRICATE THE RIGHT WING AILERON MECHANICAL CONTROL PATH.</i>				
80-8-Maintenance	1999M.1C.80-8	5094064	12/12/2016	03/08/2017 03/08/2017
<i>Description: 27-034-01DETAILED VISUAL INSPECTION OF THE LEFT WING AILERON BALANCE BAY SEALS.</i>				
80-9-Maintenance	1999M.1C.80-9	5094065	12/12/2016	03/08/2017 03/08/2017
<i>Description: 27-034-02DETAILED VISUAL INSPECTION OF THE RIGHT WING AILERON BALANCE BAY SEALS.</i>				
80-10-Maintenance	1999M.1C.80-10	5094066	12/12/2016	03/27/2017 03/27/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 27-132-00CHECK FLAP POWER DRIVE UNIT OIL LEVEL AND SERVICE AS REQUIRED.</i>					
80-11-Maintenance	1999M.1C.80-11	5094067	12/12/2016	03/28/2017	03/28/2017
<i>Description: 27-136-01LUBRICATE THE LEFT WING FLAP SKEW SENSOR MECHANISM.</i>					
80-12-Maintenance	1999M.1C.80-12	5094068	12/12/2016	04/04/2017	04/04/2017
<i>Description: 27-136-02LUBRICATE THE RIGHT WING FLAP SKEW SENSOR MECHANISM.</i>					
80-13-Maintenance	1999M.1C.80-13	5094069	12/12/2016	03/28/2017	03/28/2017
<i>Description: 27-138-00LUBRICATE THE LH WING FLAP DRIVE TORQUE TUBE COUPLINGS.</i>					
80-14-Maintenance	1999M.1C.80-14	5094070	12/12/2016	03/28/2017	03/28/2017
<i>Description: 27-138-00LUBRICATE THE RH WING FLAP DRIVE TORQUE TUBE COUPLINGS.</i>					
80-15-Maintenance	1999M.1C.80-15	5094071	12/12/2016	03/28/2017	03/28/2017
<i>Description: 27-140-01CHECK THE LEFT WING FLAP DRIVE TRANSMISSION OIL LEVEL AND SERVICE AS REQUIRED.</i>					
80-16-Maintenance	1999M.1C.80-16	5094072	12/12/2016	03/28/2017	03/28/2017
<i>Description: 27-140-02CHECK THE RIGHT WING FLAP DRIVE TRANSMISSION OIL LEVEL AND SERVICE AS REQUIRED.</i>					
80-17-Maintenance	1999M.1C.80-17	5094073	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-144-00LUBRICATE THE LEFT WING FLAP TRANSMISSION UNIVERSAL JOINTS</i>					
80-18-Maintenance	1999M.1C.80-18	5094074	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-144-00LUBRICATE THE RIGHT WING FLAP TRANSMISSION UNIVERSAL JOINTS</i>					
80-19-Maintenance	1999M.1C.80-19	5094075	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-146-00LUBRICATE THE LEFT WING FLAP BALLSCREW ACTUATORS.</i>					
80-20-Maintenance	1999M.1C.80-20	5094076	12/12/2016	04/04/2017	04/04/2017
<i>Description: 27-146-00LUBRICATE THE RIGHT WING FLAP BALLSCREW ACTUATORS.</i>					
80-21-Maintenance	1999M.1C.80-21	5094077	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-150-00LUBRICATE THE LEFT WING FLAP DRIVE TORQUE TUBE SUPPORTS</i>					
80-22-Maintenance	1999M.1C.80-22	5094078	12/12/2016	04/04/2017	04/04/2017
<i>Description: 27-150-00LUBRICATE THE RIGHT WING FLAP DRIVE TORQUE TUBE SUPPORTS</i>					
80-23-Maintenance	1999M.1C.80-23	5094079	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-152-01LUBRICATE THE #4 FLAP TRANSMISSION ANGLE/TEE GEARBOX UNIVERSAL JOINTS.</i>					
80-24-Maintenance	1999M.1C.80-24	5094080	12/12/2016	04/04/2017	04/04/2017
<i>Description: 27-152-02LUBRICATE THE #5 FLAP TRANSMISSION ANGLE/TEE GEARBOX UNIVERSAL JOINTS.</i>					
80-25-Maintenance	1999M.1C.80-25	5094081	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-176-01LUBRICATE THE LEFT WING #4 INBOARD FLAP TRACK ATTACHMENT FITTINGS.</i>					
80-26-Maintenance	1999M.1C.80-26	5094082	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-176-02LUBRICATE THE RIGHT WING #5 INBOARD FLAP TRACK ATTACHMENT FITTINGS.</i>					
80-27-Maintenance	1999M.1C.80-27	5094083	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-182-00LUBRICATE THE SPOILER MIXER.</i>					
80-28-Maintenance	1999M.1C.80-28	5094084	12/12/2016	03/29/2017	03/29/2017
<i>Description: 27-182-01LUBRICATE THE LEFT WING SPOILER MECHANICAL CONTROL PATH.</i>					
80-29-Maintenance	1999M.1C.80-29	5094085	12/12/2016	03/30/2017	03/30/2017
<i>Description: 27-182-02LUBRICATE THE RIGHT WING SPOILER MECHANICAL CONTROL PATH.</i>					
80-30-Maintenance	1999M.1C.80-30	5094086	12/12/2016	03/30/2017	03/30/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 27-186-00LUBRICATE THE SPEEDBRAKE LEVER NO-BACK BRAKE.</i>				
80-31-Maintenance	1999M.1C.80-31	5094087	12/12/2016	03/30/2017 03/30/2017
<i>Description: 27-220-01LUBRICATE THE LEFT WING LEADING EDGE SLAT ROLLERS.</i>				
80-32-Maintenance	1999M.1C.80-32	5094088	12/12/2016	03/30/2017 03/30/2017
<i>Description: 27-220-02LUBRICATE THE RIGHT WING LEADING EDGE SLAT ROLLERS.</i>				
80-33-Maintenance	1999M.1C.80-33	5094089	12/12/2016	03/30/2017 03/30/2017
<i>Description: 27-222-01LUBRICATE THE LEFT WING LEADING EDGE SLAT TRACKS.</i>				
80-34-Maintenance	1999M.1C.80-34	5094090	12/12/2016	03/30/2017 03/30/2017
<i>Description: 27-222-02LUBRICATE THE RIGHT WING LEADING EDGE SLAT TRACKS.</i>				
80-35-Maintenance	1999M.1C.80-35	5094091	12/12/2016	03/30/2017 03/30/2017
<i>Description: 27-226-00PERFORM A DETAILED VISUAL INSPECTION OF ALL EXPOSED PORTIONS OF THE LH WING FLIGHT CONTROL CABLE RUNS</i>				
80-36-Maintenance	1999M.1C.80-36	5094092	12/12/2016	04/05/2017 04/05/2017
<i>Description: 28-20-04 PATS- Cabin Air Filter (F3, F53) Restore Cabin Air Filters (F3,F53) by Cleaning or Replacement. Refer to AMMS Task 28-22-01-160-801.</i>				
80-37-Maintenance	1999M.1C.80-37	5094093	12/12/2016	04/05/2017 04/05/2017
<i>Description: 28-20-05 PATS - Bleed Air Filter (F1, F2, F51, F52) Restore Bleed Air Filters (F1, F2, F51, F52) by Cleaning or Replacement. Refer to AMMS Task 28-21-04-160-801</i>				
80-38-Maintenance	1999M.1C.80-38	5094094	12/12/2016	06/19/2017 09/07/2017
<i>Description: 32-200-00PERFORM A FUNCTIONAL CHECK OF THE NOSE LANDING GEAR MANUAL EXTENSION SYSTEM.</i>				
80-39-Maintenance	1999M.1C.80-39	5094095	12/12/2016	06/19/2017 06/19/2017
<i>Description: 32-220-00PERFORM A FUNCTIONAL CHECK OF LEFT MAIN LANDING GEAR MANUAL EXTENSION SYSTEM AND ALTERNATE EXTENSION BYPASS VALVE.</i>				
80-40-Maintenance	1999M.1C.80-40	5094096	12/12/2016	06/19/2017 06/19/2017
<i>Description: 32-220-00PERFORM A FUNCTIONAL CHECK OF RIGHT MAIN LANDING GEAR MANUAL EXTENSION SYSTEM AND ALTERNATE EXTENSION BYPASS VALVE.</i>				
80-41-Maintenance	1999M.1C.80-41	5094097	12/12/2016	03/08/2017 03/08/2017
<i>Description: 32-440-00PERFORM A DETAIL VISUAL INSPECTION OF THE EXPOSED PORTIONS OF THE LANDING GEAR SYSTEM CONTROL CABLES.</i>				
80-42-Maintenance	1999M.1C.80-42	5094098	12/12/2016	03/30/2017 03/30/2017
<i>Description: 32-806-01EXTERNAL - ZONAL (GV): LEFT MAIN LANDING GEAR AND LANDING GEAR DOORS. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE LEFT MAIN LANDING GEAR AND LANDING GEAR DOORS. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/3 YR IS SATISFIED BY THIS ZONAL INSPECTION</i>				
80-43-Maintenance	1999M.1C.80-43	5094099	12/12/2016	03/30/2017 03/30/2017
<i>Description: 32-810-02EXTERNAL - ZONAL (GV):RIGHT MAIN LANDING GEAR AND LANDING GEAR DOORS. PERFORM AN EXTERNAL ZONAL INSPECTION (GV) OF THE RIGHT MAIN LANDING GEAR AND LANDING GEAR DOORS. (EZAP) THE EZAP INSPECTION REQUIREMENT WITH INTERVAL 5500 FC/30 MO IS SATISFIED BY THIS ZONAL INSPECTION</i>				
80-44-Maintenance	1999M.1C.80-44	5094100	12/12/2016	03/08/2017 03/08/2017
<i>Description: 49-010-00GENERAL VISUAL INSPECTION OF THE APU MOUNTS FOR GENERAL CONDITION AND SECURITY OF INSTALLATION.</i>				
80-45-Maintenance	1999M.1C.80-45	5094101	12/12/2016	03/30/2017 03/30/2017
<i>Description: 52-010-00LUBRICATE THE FWD ENTRY DOOR HANDLE, LATCH MECHANISMS AND THE TORQUE TUBE HANDLE BOX BEARINGS AND THE FWD ENTRY DOOR STOP RODS.</i>				



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
80-46-Maintenance	1999M.1C.80-46	5094102	12/12/2016	03/30/2017	03/30/2017
<i>Description:</i> 52-010-00LUBRICATE THE FWD SERVICE DOOR HANDLE, LATCH MECHANISMS AND THE TORQUE TUBE HANDLE BOX BEARINGS					
80-47-Maintenance	1999M.1C.80-47	5094103	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 52-010-00LUBRICATE THE AFT ENTRY DOOR HANDLE, LATCH MECHANISMS AND THE TORQUE TUBE HANDLE BOX BEARINGS					
80-48-Maintenance	1999M.1C.80-48	5094104	12/12/2016	04/04/2017	04/04/2017
<i>Description:</i> 52-010-00LUBRICATE THE AFT SERVICE DOOR HANDLE, LATCH MECHANISMS AND THE TORQUE TUBE HANDLE BOX BEARINGS					
80-49-Maintenance	1999M.1C.80-49	5094105	12/12/2016	03/30/2017	03/30/2017
<i>Description:</i> 52-020-00LUBRICATE THE FWD ENTRY DOOR GUIDE PLATE AND ARM ASSEMBLIES, TORQUE TUBE BUSHINGS, THE UPPER AND LOWER HINGE ARMS, GATE HINGES AND THE BODY TORQUE TUBE FOR THE FORWARD DOOR ONLY.					
Count: 252			252	250	
Task Card: 1C.80-107.NR-1		Drawing: N/A	04/05/2017	11/21/2017	
<i>Description:</i> RIGHT A/C BAY PANEL 192BR AFT FLANGE HAS CORROSION.					
80-334-Maintenance	1999M.1C.80-107.NR-1.80-334	5097838	04/05/2017	11/20/2017	11/21/2017
<i>Description:</i> RIGHT A/C BAY PANEL 192BR AFT FLANGE HAS CORROSION.					
Count: 1			1	1	
Task Card: 1C.80-107.NR-2		Drawing: N/A	04/05/2017	04/13/2017	
<i>Description:</i> RIGHT A/C BAY DOOR 192CR RUBBER CLAMP ON DUCT IS DISPLACED.					
80-335-Maintenance	1999M.1C.80-107.NR-2.80-335	5097839	04/05/2017	04/13/2017	04/13/2017
<i>Description:</i> RIGHT A/C BAY DOOR 192CR RUBBER CLAMP ON DUCT IS DISPLACED.					
Count: 1			1	1	
Task Card: 1C.80-107.NR-3		Drawing: N/A	04/05/2017	01/10/2018	
<i>Description:</i> RIGHT A/C BAY DOOR 192CR AFT BULKHEAD WALL INVESTIGATE PREVIOUS REPAIR CRACKED.					
80-336-Maintenance	1999M.1C.80-107.NR-3.80-336	5097840	04/05/2017	01/09/2018	01/10/2018
<i>Description:</i> RIGHT A/C BAY DOOR 192CR AFT BULKHEAD WALL INVESTIGATE PREVIOUS REPAIR CRACKED.					
Count: 1			1	1	
Task Card: 1C.80-109.NR-1		Drawing: N/A	04/27/2017	01/11/2018	
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION AROUND COCKPIT SLIDING WINDOWS, WIPERS AND ALONG FS 270 BODY SEAM.					
80-367-Maintenance	1999M.1C.80-109.NR-1.80-367	5098445	04/27/2017	01/10/2018	01/11/2018
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION AROUND COCKPIT SLIDING WINDOWS, WIPERS AND ALONG FS 270 BODY SEAM.					
Count: 1			1	1	



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-111.NR-1	Drawing: N/A	04/27/2017		01/16/2018
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION ON FUSELAGE SEAM ABOVE WINDOW LINE FROM FS270-FS360 AND AROUND L/H WINDOWS AS WELL AS AROUND THE VHF ANTENNA ON TOP OF FUSELAGE.				
80-371-Maintenance	1999M.1C.80-111.NR-1.80-371	5098453	04/27/2017	01/13/2018 01/16/2018
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION ON FUSELAGE SEAM ABOVE WINDOW LINE FROM FS270-FS360 AND AROUND L/H WINDOWS AS WELL AS AROUND THE VHF ANTENNA ON TOP OF FUSELAGE.				
Count: 1			1	1
Task Card: 1C.80-111.NR-2	Drawing: N/A	11/22/2017		01/02/2018
<i>Description:</i> During investigation of corrosion on NR 5098453 a possible hole and suspect repair was noted on the top of the fuselage between FS 601 & FS 616 and S- 4R & S-5R.				
606-377-SHEET METAL SHOP, Mx	1999M.1C.80-111.NR-2.606-37 7	5105406	11/22/2017	12/22/2017 01/02/2018
<i>Description:</i> During investigation of corrosion on NR 5098453 a possible hole and suspect repair was noted on the top of the fuselage between FS 601 & FS 616 and S- 4R & S-5R.				
Count: 1			1	1
Task Card: 1C.80-115.NR-1	Drawing: N/A	04/27/2017		
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION ON FUSELAGE SEAM ABOVE WINDOW LINE FROM FS360 TO THE AFT DOOR AS WELL AS AROUND THE AFT ANTENNA.				
80-372-Maintenance	1999M.1C.80-115.NR-1.80-372	5098454	04/27/2017	01/10/2018 01/11/2018
<i>Description:</i> MULTIPLE SIGNS OF SURFACE CORROSION ON FUSELAGE SEAM ABOVE WINDOW LINE FROM FS360 TO THE AFT DOOR AS WELL AS AROUND THE AFT ANTENNA.				
Count: 1			1	1
Task Card: 1C.80-123.NR-1	Drawing: N/A	03/16/2017		04/04/2017
<i>Description:</i> APU DOOR ALL 3- DOOR STOPS HAVE CORROSION.				
80-282-Maintenance	1999M.1C.80-123.NR-1.80-282	5097103	03/16/2017	04/04/2017 04/04/2017
<i>Description:</i> APU DOOR ALL 3- DOOR STOPS HAVE CORROSION.				
Count: 1			1	1
Task Card: 1C.80-124.NR-1	Drawing: N/A	04/27/2017		05/11/2017
<i>Description:</i> L/H AND R/H ELEVATOR ACTUATOR INSIDE ACCESS DOOR 318BR ARE SHOWING SIGNS OF LEAKING.				
80-365-Maintenance	1999M.1C.80-124.NR-1.80-365	5098430	04/27/2017	05/11/2017 05/11/2017
<i>Description:</i> L/H AND R/H ELEVATOR ACTUATOR INSIDE ACCESS DOOR 318BR ARE SHOWING SIGNS OF LEAKING.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-129.NR-1 Drawing: N/A 03/16/2017 04/18/2017				
<i>Description: RT PYLON DIAGONAL BRACE FITTING SEALER IS CRACKED OPEN AT BOTTOM ON LT AND RT LOWER AREA.</i>				
80-279-Maintenance	1999M.1C.80-129.NR-1.80-279	5097099	03/16/2017	04/18/2017
<i>Description: RT PYLON DIAGONAL BRACE FITTING SEALER IS CRACKED OPEN AT BOTTOM ON LT AND RT LOWER AREA.</i>				
Count: 1			1	1
Task Card: 1C.80-136.NR-1 Drawing: N/A 03/16/2017 11/28/2017				
<i>Description: BAD NUTPLATE ON PANEL #343DB AT RT TAIL.</i>				
801-268-Maintenance	1999M.1C.80-136.NR-1.801-268	5096735	03/16/2017	11/22/2017
<i>Description: BAD NUTPLATE ON PANEL #343DB AT RT TAIL.</i>				
Count: 1			1	1
Task Card: 1C.80-136.NR-2 Drawing: N/A 03/16/2017 04/11/2017				
<i>Description: WIRE HARNESS CLAMP BOOT TORN/WORN UNDER R/H ENGINE FORWARD STRUT FAIRING ACCESS PANEL 441BL.</i>				
80-277-Maintenance	1999M.1C.80-136.NR-2.80-277	5096873	03/16/2017	04/11/2017
<i>Description: WIRE HARNESS CLAMP BOOT TORN/WORN UNDER R/H ENGINE FORWARD STRUT FAIRING ACCESS PANEL 441BL.</i>				
Count: 1			1	1
Task Card: 1C.80-140.NR-1 Drawing: N/A 04/27/2017 01/11/2018				
<i>Description: TOP OF DORSAL L/E HAS 5 EA SMALL AREAS OF LIGHT CORROSION (MARKED IN RED).</i>				
80-375-Maintenance	1999M.1C.80-140.NR-1.80-375	5098495	04/27/2017	01/10/2018
<i>Description: TOP OF DORSAL L/E HAS 5 EA SMALL AREAS OF LIGHT CORROSION (MARKED IN RED).</i>				
Count: 1			1	1
Task Card: 1C.80-142.NR-1 Drawing: N/A 03/29/2017 11/21/2017				
<i>Description: Due to extensive surface corrosion on all brite work, perform polish of brite work</i>				
801-348-Maintenance	1999M.1C.80-142.NR-1.801-348	5097866	03/29/2017	05/08/2017
<i>Description: Due to extensive surface corrosion on all brite work, perform polish of brite work</i>				
Count: 1			1	1
Task Card: 1C.80-142.NR-2 Drawing: N/A 04/27/2017 01/10/2018				
<i>Description: VERTICAL STAB L/E BETWEEN 322A AND 322C HAS BAD/DETERIORATED PAINT.</i>				
80-368-Maintenance	1999M.1C.80-142.NR-2.80-368	5098450	04/27/2017	01/10/2018
<i>Description: VERTICAL STAB L/E BETWEEN 322A AND 322C HAS BAD/DETERIORATED PAINT.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-142.NR-3		Drawing: N/A		04/27/2017
<i>Description:</i> VERTICAL STAB L/H SIDE AFT OF DORSAL (321A) HAS AREA OF FLAKING PAINT & LIGHT CORROSION.				
80-369-Maintenance	1999M.1C.80-142.NR-3.80-369	5098451	04/27/2017	01/10/2018 01/11/2018
<i>Description:</i> VERTICAL STAB L/H SIDE AFT OF DORSAL (321A) HAS AREA OF FLAKING PAINT & LIGHT CORROSION.				
Count: 1			1	1
Task Card: 1C.80-145.NR-1		Drawing: N/A		04/27/2017 05/11/2017
<i>Description:</i> RUDDER MAIN (LOWER) PCE IS LEAKING.				
80-366-Maintenance	1999M.1C.80-145.NR-1.80-366	5098431	04/27/2017	05/11/2017 05/11/2017
<i>Description:</i> RUDDER MAIN (LOWER) PCE IS LEAKING.				
Count: 1			1	1
Task Card: 1C.80-145.NR-2		Drawing: N/A		04/27/2017 01/05/2018
<i>Description:</i> PANEL BELOW RUDDER MAIN PCU HAS PRIMER DETERIORATED FROM SKYDROL LEAK (PRIMER ONLY INTERNAL PANEL)				
80-373-Maintenance	1999M.1C.80-145.NR-2.80-373	5098492	04/27/2017	01/04/2018 01/05/2018
<i>Description:</i> PANEL BELOW RUDDER MAIN PCU HAS PRIMER DETERIORATED FROM SKYDROL LEAK (PRIMER ONLY INTERNAL PANEL)				
Count: 1			1	1
Task Card: 1C.80-145.NR-3		Drawing: N/A		04/27/2017 11/02/2017
<i>Description:</i> RUDDER L/E BELOW MAIN PCU REQUIRES CLEANING OF SKYDROLFROM LEAK.				
80-374-Maintenance	1999M.1C.80-145.NR-3.80-374	5098493	04/27/2017	10/31/2017 11/02/2017
<i>Description:</i> RUDDER L/E BELOW MAIN PCU REQUIRES CLEANING OF SKYDROLFROM LEAK.				
Count: 1			1	1
Task Card: 1C.80-148.NR-1		Drawing: N/A		04/27/2017 01/10/2018
<i>Description:</i> VERTICAL STAB TIP L/E HAS PAINT ERROSION.				
80-376-Maintenance	1999M.1C.80-148.NR-1.80-376	5098496	04/27/2017	01/10/2018 01/10/2018
<i>Description:</i> VERTICAL STAB TIP L/E HAS PAINT ERROSION.				
Count: 1			1	1
Task Card: 1C.80-149.NR-1		Drawing: N/A		03/16/2017
<i>Description:</i> SURFACE CORROSION ON LEFT HORIZONTAL STABILIZER LEADING EDGE SKIN.				
606-278-SHEET METAL SHOP, Mx	1999M.1C.80-149.NR-1.606-27	5096874	03/16/2017	
	8			
<i>Description:</i> SURFACE CORROSION ON LEFT HORIZONTAL STABILIZER LEADING EDGE SKIN.				
Count: 1			1	0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-152.NR-1 Drawing: N/A 04/10/2017 05/08/2017				
<i>Description:</i> LEFT HORIZONTAL STAB SLIDING BLADE SEAL CRACKED.				
80-361-Maintenance	1999M.1C.80-152.NR-1.80-361	5098247	04/10/2017	05/08/2017
<i>Description:</i> LEFT HORIZONTAL STAB SLIDING BLADE SEAL CRACKED.				
Count: 1			1	1
Task Card: 1C.80-152.NR-2 Drawing: N/A 04/27/2017 01/05/2018				
<i>Description:</i> VERTICAL STAB L/H SIDE ANGLE ON TOP OF FUSELAGE BEHIND PNLS 323AL, 323BL, 323CL & 324AL HAS FLAKING PAINT/BARE METAL.				
80-370-Maintenance	1999M.1C.80-152.NR-2.80-370	5098452	04/27/2017	01/04/2018
<i>Description:</i> VERTICAL STAB L/H SIDE ANGLE ON TOP OF FUSELAGE BEHIND PNLS 323AL, 323BL, 323CL & 324AL HAS FLAKING PAINT/BARE METAL.				
Count: 1			1	1
Task Card: 1C.80-153.NR-1 Drawing: N/A 03/16/2017 01/11/2018				
<i>Description:</i> LT HORIZONTAL STAB TRAILING EDGE TOP SKIN FASTENERS CORRODED.				
80-269-Maintenance	1999M.1C.80-153.NR-1.80-269	5096736	03/16/2017	01/10/2018
<i>Description:</i> LT HORIZONTAL STAB TRAILING EDGE TOP SKIN FASTENERS CORRODED.				
Count: 1			1	1
Task Card: 1C.80-153.NR-2 Drawing: N/A 03/16/2017 04/11/2017				
<i>Description:</i> LEFT ELEVATOR UPPER SEALS DETERIORATED.				
80-273-Maintenance	1999M.1C.80-153.NR-2.80-273	5096740	03/16/2017	04/11/2017
<i>Description:</i> LEFT ELEVATOR UPPER SEALS DETERIORATED.				
Count: 1			1	1
Task Card: 1C.80-154.NR-1 Drawing: N/A 03/16/2017 01/10/2018				
<i>Description:</i> EVIDENCE OF CORROSION ON LEFT ELEVATOR SKINS AT FORWARD SPAR.				
80-272-Maintenance	1999M.1C.80-154.NR-1.80-272	5096739	03/16/2017	01/09/2018
<i>Description:</i> EVIDENCE OF CORROSION ON LEFT ELEVATOR SKINS AT FORWARD SPAR.				
Count: 1			1	1
Task Card: 1C.80-155.NR-1 Drawing: N/A 03/16/2017 01/11/2018				
<i>Description:</i> LT HORIZONTAL STAB TIP CORRODED.				
80-271-Maintenance	1999M.1C.80-155.NR-1.80-271	5096738	03/16/2017	01/10/2018
<i>Description:</i> LT HORIZONTAL STAB TIP CORRODED.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-156.NR-1		Drawing: N/A		03/16/2017	
<i>Description:</i> SURFACE CORROSION ON RT HORIZONTAL STABILIZER LEADING EDGE SKIN.					
606-275-SHEET METAL SHOP, Mx	1999M.1C.80-156.NR-1.606-27 5	5096744	03/16/2017		
<i>Description:</i> SURFACE CORROSION ON RT HORIZONTAL STABILIZER LEADING EDGE SKIN.					
Count: 1			1	0	
Task Card: 1C.80-161.NR-1		Drawing: N/A		03/16/2017	04/11/2017
<i>Description:</i> RT ELEVATOR UPPER SEALS AND LOWER INBOARD SEALS DETERIORATED.					
80-266-Maintenance	1999M.1C.80-161.NR-1.80-266	5096733	03/16/2017	04/11/2017	04/11/2017
<i>Description:</i> RT ELEVATOR UPPER SEALS AND LOWER INBOARD SEALS DETERIORATED.					
Count: 1			1		1
Task Card: 1C.80-161.NR-2		Drawing: N/A		03/16/2017	01/10/2018
<i>Description:</i> EVIDENCE OF CORROSION ON RT ELEVATOR AT FORWARD SPAR ON FORWARD SKIN TOP AND BOTTOM.					
80-267-Maintenance	1999M.1C.80-161.NR-2.80-267	5096734	03/16/2017	01/09/2018	01/10/2018
<i>Description:</i> EVIDENCE OF CORROSION ON RT ELEVATOR AT FORWARD SPAR ON FORWARD SKIN TOP AND BOTTOM.					
Count: 1			1		1
Task Card: 1C.80-162.NR-1		Drawing: N/A		03/16/2017	
<i>Description:</i> RH HORIZONTAL STABILIZER TIP CORRODED.					
606-263-SHEET METAL SHOP, Mx	1999M.1C.80-162.NR-1.606-26 3	5096728	03/16/2017		
<i>Description:</i> RH HORIZONTAL STABILIZER TIP CORRODED.					
Count: 1			1		0
Task Card: 1C.80-163.NR-1		Drawing: N/A		04/05/2017	04/13/2017
<i>Description:</i> LT SLIDING WINDOW HAS CORROSION ON FRAME @ THE AFT LOWER CORNER, CAN BE SEEN BY LOOKING OUT THE WINDOW FROM PILOT SEAT.					
80-333-Maintenance	1999M.1C.80-163.NR-1.80-333	5097834	04/05/2017	04/13/2017	04/13/2017
<i>Description:</i> LT SLIDING WINDOW HAS CORROSION ON FRAME @ THE AFT LOWER CORNER, CAN BE SEEN BY LOOKING OUT THE WINDOW FROM PILOT SEAT.					
Count: 1			1		1
Task Card: 1C.80-164.NR-1		Drawing: N/A		03/16/2017	11/07/2017
<i>Description:</i> PILOTS SLIDING WINDOW WILL NOT LOCK IN THE OPEN POSITION.					
801-255-Maintenance	1999M.1C.80-164.NR-1.801-25 5	5096683	03/16/2017	11/04/2017	11/07/2017
<i>Description:</i> PILOTS SLIDING WINDOW WILL NOT LOCK IN THE OPEN POSITION.					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-164.NR-2		Drawing: N/A		03/16/2017	04/04/2017
<i>Description: CO-PILOTS SLIDING WINDOW LATCH MECHANISM BARELY CATCHES RIG, NEEDS CHECKED.</i>					
80-256-Maintenance	1999M.1C.80-164.NR-2.80-256	5096684	03/16/2017	04/04/2017	04/04/2017
<i>Description: CO-PILOTS SLIDING WINDOW LATCH MECHANISM BARELY CATCHES RIG, NEEDS CHECKED.</i>					
Count: 1			1		1
Task Card: 1C.80-165.NR-1		Drawing: N/A		04/05/2017	04/13/2017
<i>Description: PILOT AND COPILOTS SLIDING WINDOW SILL DRAINS ARE CLOGGED.</i>					
80-351-Maintenance	1999M.1C.80-165.NR-1.80-351	5097930	04/05/2017	04/13/2017	04/13/2017
<i>Description: PILOT AND COPILOTS SLIDING WINDOW SILL DRAINS ARE CLOGGED.</i>					
Count: 1			1		1
Task Card: 1C.80-165.NR-2		Drawing: N/A		04/10/2017	01/05/2018
<i>Description: PILOT AND COPILOTS SLIDING WINDOW SILL DRAINS ARE CLOGGED.</i>					
80-364-Maintenance	1999M.1C.80-165.NR-2.80-364	5098252	04/10/2017	01/04/2018	01/05/2018
<i>Description: PILOT AND COPILOTS SLIDING WINDOW SILL DRAINS ARE CLOGGED.</i>					
Count: 1			1		1
Task Card: 1C.80-170.NR-1		Drawing: N/A		03/16/2017	
<i>Description: SURFACE CORROSION ON POLISHED SKIN LOCATED ON LEFT WING INBOARD LEADING EDGE.</i>					
606-258-SHEET METAL SHOP, Mx	1999M.1C.80-170.NR-1.606-258	5096687	03/16/2017		
	8				
<i>Description: SURFACE CORROSION ON POLISHED SKIN LOCATED ON LEFT WING INBOARD LEADING EDGE.</i>					
Count: 1			1		0
Task Card: 1C.80-170.NR-2		Drawing: N/A		03/16/2017	05/05/2017
<i>Description: SCRATCHES ON LEFT WING LEADING EDGE UPPER SURFACE INBOARD OF NACELLE STRUT.</i>					
80-259-Maintenance	1999M.1C.80-170.NR-2.80-259	5096691	03/16/2017	05/05/2017	05/05/2017
<i>Description: SCRATCHES ON LEFT WING LEADING EDGE UPPER SURFACE INBOARD OF NACELLE STRUT.</i>					
Count: 1			1		1
Task Card: 1C.80-170.NR-3		Drawing: N/A		07/03/2018	07/26/2018
<i>Description: UPPER L/H NACELLE PANEL 431CR HAS BROKEN BONDING STRAP.</i>					
801-380-Maintenance	1999M.1C.80-170.NR-3.801-380	5111959	07/03/2018	07/25/2018	07/26/2018
	0				
<i>Description: UPPER L/H NACELLE PANEL 431CR HAS BROKEN BONDING STRAP.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-170.NR-4		Drawing: N/A		08/15/2018
<i>Description:</i> Found Inboard wing leading edge, Air supply ducts (L/H and R/H) to have corroded band clamps and plating flaking off of clamps.				
801-381-Maintenance	1999M.1C.80-170.NR-4.801-38 1	5114612	08/15/2018	
<i>Description:</i> Found Inboard wing leading edge, Air supply ducts (L/H and R/H) to have corroded band clamps and plating flaking off of clamps.				
Count: 1			1	0
Task Card: 1C.80-171.NR-1		Drawing: N/A		03/16/2017
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP L/E HAS TOW EACH BONDING WIRES AT ATTACH ROD AREAS THAT ARE FRAYING AND CORRODED.				
80-300-Maintenance	1999M.1C.80-171.NR-1.80-300	5097330	03/16/2017	04/25/2017
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP L/E HAS TOW EACH BONDING WIRES AT ATTACH ROD AREAS THAT ARE FRAYING AND CORRODED.				
Count: 1			1	1
Task Card: 1C.80-171.NR-2		Drawing: N/A		03/23/2017
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP L/E HAS TWO EACH BONDING WIRES AT ATTACH ROD AREA'S THAT ARE FRAYING AND CORRODED.				
80-318-Maintenance	1999M.1C.80-171.NR-2.80-318	5097650	03/23/2017	05/08/2017
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP L/E HAS TWO EACH BONDING WIRES AT ATTACH ROD AREA'S THAT ARE FRAYING AND CORRODED.				
Count: 1			1	1
Task Card: 1C.80-172.NR-1		Drawing: N/A		03/16/2017
<i>Description:</i> L/H WING UPPER SURFACE L/E SKIN JUST AFT OF KRUGER FLAPS HAS "NO STEP" DECAL THAT IS DETERIATED AND FADED.				
80-298-Maintenance	1999M.1C.80-172.NR-1.80-298	5097327	03/16/2017	
<i>Description:</i> L/H WING UPPER SURFACE L/E SKIN JUST AFT OF KRUGER FLAPS HAS "NO STEP" DECAL THAT IS DETERIATED AND FADED.				
Count: 1			1	0
Task Card: 1C.80-172.NR-2		Drawing: N/A		03/16/2017
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP LOWER EXTERNAL SKIN HAS AREAS OF BARE METAL EXPOSED (WORN PROTECTIVE COATING).				
80-299-Maintenance	1999M.1C.80-172.NR-2.80-299	5097329	03/16/2017	01/10/2018
<i>Description:</i> L/H WING #1 L/E KRUGER FLAP LOWER EXTERNAL SKIN HAS AREAS OF BARE METAL EXPOSED (WORN PROTECTIVE COATING).				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-172.NR-3 Drawing: N/A 03/23/2017 01/11/2018				
<i>Description: L/H WING UPPER SURFACE L/E SKIN JUST AFT OF KRUGER FLAPS HAS "NO STEP" DECAL THAT IS DETERIATED AND FADED.</i>				
80-316-Maintenance	1999M.1C.80-172.NR-3.80-316	5097648	03/23/2017	01/11/2018
<i>Description: L/H WING UPPER SURFACE L/E SKIN JUST AFT OF KRUGER FLAPS HAS "NO STEP" DECAL THAT IS DETERIATED AND FADED.</i>				
Count: 1			1	1
Task Card: 1C.80-172.NR-4 Drawing: N/A 03/23/2017 01/11/2018				
<i>Description: L/H WING #1 L/E KRUGER FLAP LOWER EXTERNAL SKIN HAS AREAS OF BARE METAL EXPOSED (WORN PROTECTIVE COATING).</i>				
80-317-Maintenance	1999M.1C.80-172.NR-4.80-317	5097649	03/23/2017	01/11/2018
<i>Description: L/H WING #1 L/E KRUGER FLAP LOWER EXTERNAL SKIN HAS AREAS OF BARE METAL EXPOSED (WORN PROTECTIVE COATING).</i>				
Count: 1			1	1
Task Card: 1C.80-174.NR-1 Drawing: N/A 03/16/2017				
<i>Description: L/H WING, FIX L/E UPPER SURFACE, SKIN AT MOST O/B END BEHIND #1 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
80-295-Maintenance	1999M.1C.80-174.NR-1.80-295	5097320	03/16/2017	01/10/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE, SKIN AT MOST O/B END BEHIND #1 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
Count: 1			1	1
Task Card: 1C.80-174.NR-2 Drawing: N/A 03/16/2017				
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #2 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
80-296-Maintenance	1999M.1C.80-174.NR-2.80-296	5097325	03/16/2017	01/10/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #2 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
Count: 1			1	1
Task Card: 1C.80-174.NR-3 Drawing: N/A 03/16/2017				
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #3 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
80-297-Maintenance	1999M.1C.80-174.NR-3.80-297	5097326	03/16/2017	01/10/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #3 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-174.NR-4		Drawing: N/A		03/23/2017	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST O/B END BEHIND #1 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>					
80-313-Maintenance	1999M.1C.80-174.NR-4.80-313	5097645	03/23/2017	01/11/2018	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST O/B END BEHIND #1 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>					
Count: 1			1		1
Task Card: 1C.80-174.NR-5		Drawing: N/A		03/23/2017	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST O/B END BEHIND #1 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED FIBERS.</i>					
80-314-Maintenance	1999M.1C.80-174.NR-5.80-314	5097646	03/23/2017	01/10/2018	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END OF #2 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED METAL.</i>					
Count: 1			1		1
Task Card: 1C.80-174.NR-6		Drawing: N/A		03/23/2017	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #3 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED METAL.</i>					
80-315-Maintenance	1999M.1C.80-174.NR-6.80-315	5097647	03/23/2017	01/10/2018	01/11/2018
<i>Description: L/H WING, FIX L/E UPPER SURFACE SKIN AT MOST I/B END BEHIND #3 L/E SLAT HAS PROTECTIVE COATING WORN OFF WITH EXPOSED METAL.</i>					
Count: 1			1		1
Task Card: 1C.80-176.NR-1		Drawing: N/A		03/16/2017	01/11/2018
<i>Description: L/H WING #1 L/E SLAT T/E LOWER SURFACE AT MOST O/B END HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>					
80-289-Maintenance	1999M.1C.80-176.NR-1.80-289	5097313	03/16/2017	01/10/2018	01/11/2018
<i>Description: L/H WING #1 L/E SLAT T/E LOWER SURFACE AT MOST O/B END HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>					
Count: 1			1		1
Task Card: 1C.80-176.NR-10		Drawing: N/A		03/23/2017	01/11/2018
<i>Description: L/H WING #2 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>					
80-310-Maintenance	1999M.1C.80-176.NR-10.80-310	5097642	03/23/2017	01/10/2018	01/11/2018
<i>Description: L/H WING #2 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-176.NR-11 Drawing: N/A 03/23/2017 01/11/2018				
<i>Description: L/H WING #3 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-311-Maintenance	1999M.1C.80-176.NR-11.80-31 1	5097643	03/23/2017	01/10/2018 01/11/2018
<i>Description: L/H WING #3 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1
Task Card: 1C.80-176.NR-12 Drawing: N/A 03/23/2017 01/11/2018				
<i>Description: L/H WING #4 L/E SLAT T/E WEDGE LWR O/B END HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-312-Maintenance	1999M.1C.80-176.NR-12.80-31 2	5097644	03/23/2017	01/10/2018 01/11/2018
<i>Description: L/H WING #4 L/E SLAT T/E WEDGE LWR O/B END HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1
Task Card: 1C.80-176.NR-2 Drawing: N/A 03/16/2017				
<i>Description: L/H WING #1 L/E SLAT T/E LOWER SURFACE AT CENTER AREA ABOVE ACTUATOR HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-290-Maintenance	1999M.1C.80-176.NR-2.80-290	5097314	03/16/2017	01/10/2018 01/11/2018
<i>Description: L/H WING #1 L/E SLAT T/E LOWER SURFACE AT CENTER AREA ABOVE ACTUATOR HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1
Task Card: 1C.80-176.NR-3 Drawing: N/A 03/16/2017 01/10/2018				
<i>Description: L/H WING #1 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-291-Maintenance	1999M.1C.80-176.NR-3.80-291	5097316	03/16/2017	01/10/2018 01/10/2018
<i>Description: L/H WING #1 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1
Task Card: 1C.80-176.NR-4 Drawing: N/A 03/16/2017				
<i>Description: L/H WING #2 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-292-Maintenance	1999M.1C.80-176.NR-4.80-292	5097317	03/16/2017	01/10/2018 01/11/2018
<i>Description: L/H WING #2 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-176.NR-5		Drawing: N/A		03/16/2017
<i>Description:</i> L/H WING #2 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
80-293-Maintenance	1999M.1C.80-176.NR-5.80-293	5097318	03/16/2017	01/10/2018 01/11/2018
<i>Description:</i> L/H WING #2 L/E SLAT T/E WEDGE LOWER O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
Count: 1			1	1
Task Card: 1C.80-176.NR-6		Drawing: N/A		03/16/2017
<i>Description:</i> L/H WING #4 L/E SLAT T/E WEDGE LOWER O/B END HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
80-294-Maintenance	1999M.1C.80-176.NR-6.80-294	5097319	03/16/2017	01/10/2018 01/11/2018
<i>Description:</i> L/H WING #4 L/E SLAT T/E WEDGE LOWER O/B END HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
Count: 1			1	1
Task Card: 1C.80-176.NR-7		Drawing: N/A		03/23/2017
<i>Description:</i> L/H WING #1 L/E SLAT T/E LWR SURFACE AT MOST O/B END HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
80-307-Maintenance	1999M.1C.80-176.NR-7.80-307	5097636	03/23/2017	01/11/2018 01/11/2018
<i>Description:</i> L/H WING #1 L/E SLAT T/E LWR SURFACE AT MOST O/B END HAS A WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
Count: 1			1	1
Task Card: 1C.80-176.NR-8		Drawing: N/A		03/23/2017
<i>Description:</i> L/H WING #1 L/E SLAT T/E LWR SURFACE AT CENTER AREA ABOVE ACTUATOR HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
80-308-Maintenance	1999M.1C.80-176.NR-8.80-308	5097637	03/23/2017	01/11/2018 01/11/2018
<i>Description:</i> L/H WING #1 L/E SLAT T/E LWR SURFACE AT CENTER AREA ABOVE ACTUATOR HAS WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
Count: 1			1	1
Task Card: 1C.80-176.NR-9		Drawing: N/A		03/23/2017
<i>Description:</i> L/H WING #1 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
80-309-Maintenance	1999M.1C.80-176.NR-9.80-309	5097639	03/23/2017	01/10/2018 01/11/2018
<i>Description:</i> L/H WING #1 L/E SLAT T/E WEDGE LWR O/B CENTER AND I/B AFT EDGES HAVE WORN PROTECTIVE COATING WITH BARE METAL EXPOSED.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-177.NR-1		Drawing: N/A		03/16/2017	
<i>Description: L/H WING LOWER CENTER FUEL TANK AREA, TWO EACH FUEL TANK ACCESS PLATES SHOW EVIDENCE OF LEAKING (O/B AND CENTER PLATES).</i>					
80-283-Maintenance	1999M.1C.80-177.NR-1.80-283	5097247	03/16/2017	10/31/2017	11/02/2017
<i>Description: L/H WING LOWER CENTER FUEL TANK AREA, TWO EACH FUEL TANK ACCESS PLATES SHOW EVIDENCE OF LEAKING (O/B AND CENTER PLATES).</i>					
Count: 1			1		1
Task Card: 1C.80-177.NR-2		Drawing: N/A		03/16/2017	01/11/2018
<i>Description: L/H WING LOWER CENTER FUEL TANK AREA HAS DETERIORATED SUMP DRAIN DECAL.</i>					
80-284-Maintenance	1999M.1C.80-177.NR-2.80-284	5097248	03/16/2017	01/11/2018	01/11/2018
<i>Description: L/H WING LOWER CENTER FUEL TANK AREA HAS DETERIORATED SUMP DRAIN DECAL.</i>					
Count: 1			1		1
Task Card: 1C.80-178.NR-1		Drawing: N/A		03/16/2017	06/06/2018
<i>Description: L/H WING LOWER SURFACE AFT OF #1 L/E SLAT HAS DETERIORATED DECAL FOR SURGE TANK DRAIN.</i>					
80-285-Maintenance	1999M.1C.80-178.NR-1.80-285	5097249	03/16/2017	06/06/2018	06/06/2018
<i>Description: L/H WING LOWER SURFACE AFT OF #1 L/E SLAT HAS DETERIORATED DECAL FOR SURGE TANK DRAIN.</i>					
Count: 1			1		1
Task Card: 1C.80-180.NR-1		Drawing: N/A		03/16/2017	01/11/2018
<i>Description: RT HORIZONTAL STAB TRAILING EDGE FASTENERS CORRODED TOP SKIN.</i>					
801-264-Maintenance	1999M.1C.80-180.NR-1.801-264	5096729	03/16/2017	01/11/2018	01/11/2018
<i>Description: RT HORIZONTAL STAB TRAILING EDGE FASTENERS CORRODED TOP SKIN.</i>					
Count: 1			1		1
Task Card: 1C.80-180.NR-2		Drawing: N/A		03/16/2017	01/10/2018
<i>Description: RT HORIZONTAL STAB STATIC WICK BASES CORRODED.</i>					
80-265-Maintenance	1999M.1C.80-180.NR-2.80-265	5096730	03/16/2017	01/02/2018	01/10/2018
<i>Description: RT HORIZONTAL STAB STATIC WICK BASES CORRODED.</i>					
Count: 1			1		1
Task Card: 1C.80-187.NR-1		Drawing: N/A		03/23/2017	01/10/2018
<i>Description: L/H WING I/B AFT FLAP LWR SURFACE SKIN HAS CHIPPING PROTECTIVE COATINGS.</i>					
80-331-Maintenance	1999M.1C.80-187.NR-1.80-331	5097677	03/23/2017	01/10/2018	01/10/2018
<i>Description: L/H WING I/B AFT FLAP LWR SURFACE SKIN HAS CHIPPING PROTECTIVE COATINGS.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-187.NR-2	Drawing: N/A	03/23/2017		11/02/2017
<i>Description: L/H WING I/B AFT FLAP I/B TRACK CUT OUT AND O/B TRACK CUT OUT HAVE O/B SEALS THAT ARE TORN AND FRAYED.</i>				
80-332-Maintenance	1999M.1C.80-187.NR-2.80-332	5097678	03/23/2017	10/31/2017 11/02/2017
<i>Description: L/H WING I/B AFT FLAP I/B TRACK CUT OUT AND O/B TRACK CUT OUT HAVE O/B SEALS THAT ARE TORN AND FRAYED.</i>				
Count: 1			1	1
Task Card: 1C.80-188.NR-1	Drawing: N/A	03/23/2017		01/11/2018
<i>Description: L/H WING #6 SPOILER LWR SKIN SURFACE HAS CHIPPED PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
80-330-Maintenance	1999M.1C.80-188.NR-1.80-330	5097676	03/23/2017	01/10/2018 01/11/2018
<i>Description: L/H WING #6 SPOILER LWR SKIN SURFACE HAS CHIPPED PROTECTIVE COATING WITH BARE METAL EXPOSED.</i>				
Count: 1			1	1
Task Card: 1C.80-189.NR-1	Drawing: N/A	04/05/2017		04/25/2017
<i>Description: LT I/B FLAP, AFT FLAP LOWER SURFACE HAS MANY (22) DENTS AND FINISH HAS BEEN COMPROMISED.</i>				
80-339-Maintenance	1999M.1C.80-189.NR-1.80-339	5097843	04/05/2017	04/25/2017 04/25/2017
<i>Description: LT I/B FLAP, AFT FLAP LOWER SURFACE HAS MANY (22) DENTS AND FINISH HAS BEEN COMPROMISED.</i>				
Count: 1			1	1
Task Card: 1C.80-19.NR-1	Drawing: N/A	04/05/2017		04/18/2017
<i>Description: LH OB IB FLAP MAIN CARRIAGE SEAL RETAINER MISSING.</i>				
80-337-Maintenance	1999M.1C.80-19.NR-1.80-337	5097841	04/05/2017	04/18/2017 04/18/2017
<i>Description: LH OB IB FLAP MAIN CARRIAGE SEAL RETAINER MISSING.</i>				
Count: 1			1	1
Task Card: 1C.80-190.NR-1	Drawing: N/A	03/23/2017		05/08/2017
<i>Description: L/H WING #1 SPOILER O/B BONDING WIRE IS CORRODED.</i>				
80-324-Maintenance	1999M.1C.80-190.NR-1.80-324	5097668	03/23/2017	05/08/2017 05/08/2017
<i>Description: L/H WING #1 SPOILER O/B BONDING WIRE IS CORRODED.</i>				
Count: 1			1	1
Task Card: 1C.80-190.NR-2	Drawing: N/A	03/23/2017		04/25/2017
<i>Description: L/H WING #5 SPOILER ACTUATOR TO SPOILER ATTACH POINT BEARING AREA HAS RADIAL PLAY AT SPOILER.</i>				
80-325-Maintenance	1999M.1C.80-190.NR-2.80-325	5097669	03/23/2017	04/25/2017 04/25/2017
<i>Description: L/H WING #5 SPOILER ACTUATOR TO SPOILER ATTACH POINT BEARING AREA HAS RADIAL PLAY AT SPOILER.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-190.NR-3 Drawing: N/A 03/23/2017 04/25/2017				
<i>Description: L/H WING #4 SPOILER ACTUATOR TO SPOILER ATTACH POINT BEARING AREA HAS RADIAL PLAY AT SPOILER.</i>				
80-326-Maintenance	1999M.1C.80-190.NR-3.80-326	5097670	03/23/2017	04/25/2017 04/25/2017
<i>Description: L/H WING #4 SPOILER ACTUATOR TO SPOILER ATTACH POINT BEARING AREA HAS RADIAL PLAY AT SPOILER.</i>				
Count: 1			1	1
Task Card: 1C.80-190.NR-4 Drawing: N/A 03/23/2017 04/13/2017				
<i>Description: L/H WING #4 SPOILER ACTUATOR HAS A HYD LEAK.</i>				
80-327-Maintenance	1999M.1C.80-190.NR-4.80-327	5097671	03/23/2017	04/13/2017 04/13/2017
<i>Description: L/H WING #4 SPOILER ACTUATOR HAS A HYD LEAK.</i>				
Count: 1			1	1
Task Card: 1C.80-190.NR-5 Drawing: N/A 03/23/2017 04/13/2017				
<i>Description: L/H WING #5 SPOILER ACTUATOR HAS A HYD LEAK.</i>				
80-328-Maintenance	1999M.1C.80-190.NR-5.80-328	5097672	03/23/2017	04/13/2017 04/13/2017
<i>Description: L/H WING #5 SPOILER ACTUATOR HAS A HYD LEAK.</i>				
Count: 1			1	1
Task Card: 1C.80-191.NR-1 Drawing: N/A 04/05/2017 04/25/2017				
<i>Description: LT #4 SPOILER HAS PLAY WHERE ACTUATOR ATTACHES TO SPOILER.</i>				
80-340-Maintenance	1999M.1C.80-191.NR-1.80-340	5097844	04/05/2017	04/25/2017 04/25/2017
<i>Description: LT #4 SPOILER HAS PLAY WHERE ACTUATOR ATTACHES TO SPOILER.</i>				
Count: 1			1	1
Task Card: 1C.80-191.NR-2 Drawing: N/A 04/05/2017 04/25/2017				
<i>Description: LT #5 SPOILER HAS PLAY WHERE ACTUATOR ATTACHES TO SPOILER.</i>				
80-341-Maintenance	1999M.1C.80-191.NR-2.80-341	5097845	04/05/2017	04/25/2017 04/25/2017
<i>Description: LT #5 SPOILER HAS PLAY WHERE ACTUATOR ATTACHES TO SPOILER.</i>				
Count: 1			1	1
Task Card: 1C.80-192.NR-1 Drawing: N/A 04/05/2017 01/11/2018				
<i>Description: LT O/B FLAP, UPPER O/B TRAILING EDGE RIVET HEADS ARE CORRODED.</i>				
80-338-Maintenance	1999M.1C.80-192.NR-1.80-338	5097842	04/05/2017	01/10/2018 01/11/2018
<i>Description: LT O/B FLAP, UPPER O/B TRAILING EDGE RIVET HEADS ARE CORRODED.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-193.NR-1 Drawing: N/A 03/23/2017 04/13/2017				
<i>Description: L/H WING T/E AT O/B AREA HAS I/B STATIC WICK IS DETERIORATED.</i>				
80-323-Maintenance	1999M.1C.80-193.NR-1.80-323	5097667	03/23/2017	04/13/2017
<i>Description: L/H WING T/E AT O/B AREA HAS I/B STATIC WICK IS DETERIORATED.</i>				
Count: 1			1	1
Task Card: 1C.80-195.NR-1 Drawing: N/A 03/23/2017 04/25/2017				
<i>Description: L/H AILERON MOST O/B L/E BONDING WIRE TO FIX WING IS CORRODED AND BIRD CAGED.</i>				
80-319-Maintenance	1999M.1C.80-195.NR-1.80-319	5097663	03/23/2017	04/25/2017
<i>Description: L/H AILERON MOST O/B L/E BONDING WIRE TO FIX WING IS CORRODED AND BIRD CAGED.</i>				
Count: 1			1	1
Task Card: 1C.80-195.NR-2 Drawing: N/A 03/23/2017 04/25/2017				
<i>Description: L/H AILERON MOST I/B L/E BONDING WIRE TO FIX WING IS CORRODED AND BIRD CAGED.</i>				
80-320-Maintenance	1999M.1C.80-195.NR-2.80-320	5097664	03/23/2017	04/25/2017
<i>Description: L/H AILERON MOST I/B L/E BONDING WIRE TO FIX WING IS CORRODED AND BIRD CAGED.</i>				
Count: 1			1	1
Task Card: 1C.80-195.NR-3 Drawing: N/A 03/23/2017 10/19/2017				
<i>Description: L/H AILERON L/E MOST I/B FWD COVER TAPE IS LOOSE FROM THE FWD SPAR.</i>				
80-321-Maintenance	1999M.1C.80-195.NR-3.80-321	5097665	03/23/2017	05/08/2017
<i>Description: L/H AILERON L/E MOST I/B FWD COVER TAPE IS LOOSE FROM THE FWD SPAR.</i>				
Count: 1			1	1
Task Card: 1C.80-195.NR-4 Drawing: N/A 03/23/2017 01/11/2018				
<i>Description: L/H AILERON L/E LWR SIDE BALANCE PANEL AREAS HAVE AREAS OF WORN PROTECTIVE COATINGS WITH BARE METAL.</i>				
80-322-Maintenance	1999M.1C.80-195.NR-4.80-322	5097666	03/23/2017	01/10/2018
<i>Description: L/H AILERON L/E LWR SIDE BALANCE PANEL AREAS HAVE AREAS OF WORN PROTECTIVE COATINGS WITH BARE METAL.</i>				
Count: 1			1	1
Task Card: 1C.80-196.NR-1 Drawing: N/A 03/16/2017				
<i>Description: RIGHT WING LEADING EDGE CORRODED INBD OF NACELLE STRUT.</i>				
606-260-SHEET METAL SHOP, Mx	1999M.1C.80-196.NR-1.606-26	5096692	03/16/2017	
	0			
<i>Description: RIGHT WING LEADING EDGE CORRODED INBD OF NACELLE STRUT.</i>				
Count: 1			1	0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-196.NR-2 Drawing: N/A 03/16/2017 05/05/2017				
<i>Description:</i> SCRATCHES ON RIGHT WING LEADING EDGE UPPER SURFACE INBOARD OF NACELLE STRUT.				
80-261-Maintenance	1999M.1C.80-196.NR-2.80-261	5096693	03/16/2017	05/05/2017
<i>Description:</i> SCRATCHES ON RIGHT WING LEADING EDGE UPPER SURFACE INBOARD OF NACELLE STRUT.				
Count: 1			1	1
Task Card: 1C.80-198.NR-1 Drawing: N/A 04/05/2017 04/25/2018				
<i>Description:</i> RIGHT WING OTBD KRUGER FLAP TOP RUB PAD WORN.				
80-343-Maintenance	1999M.1C.80-198.NR-1.80-343	5097847	04/05/2017	04/25/2018
<i>Description:</i> RIGHT WING OTBD KRUGER FLAP TOP RUB PAD WORN.				
Count: 1			1	1
Task Card: 1C.80-198.NR-2 Drawing: N/A 04/05/2017 01/10/2018				
<i>Description:</i> RIGHT WING OTBD KRUGER FLAP TOP AREA HAS COSMETIC PAINT MISSING.				
80-344-Maintenance	1999M.1C.80-198.NR-2.80-344	5097848	04/05/2017	01/10/2018
<i>Description:</i> RIGHT WING OTBD KRUGER FLAP TOP AREA HAS COSMETIC PAINT MISSING.				
Count: 1			1	1
Task Card: 1C.80-203.NR-1 Drawing: N/A 03/16/2017 11/07/2017				
<i>Description:</i> RH WING LWR CENTER FUEL TANK AREA HAS MOST O/B FUEL TANK ACCESS PLATE THAT SHOWS EVIDENCE OF LEAKING.				
80-286-Maintenance	1999M.1C.80-203.NR-1.80-286	5097298	03/16/2017	10/31/2017
<i>Description:</i> RH WING LWR CENTER FUEL TANK AREA HAS MOST O/B FUEL TANK ACCESS PLATE THAT SHOWS EVIDENCE OF LEAKING.				
Count: 1			1	1
Task Card: 1C.80-203.NR-2 Drawing: N/A 04/05/2017 11/07/2017				
<i>Description:</i> R/H WING LWR CENTER FUEL TANK AREA HAS MOST O/B FUEL TANK ACCESS PLATE THAT SHOWS EVIDENCE OF LEAKING.				
80-304-Maintenance	1999M.1C.80-203.NR-2.80-304	5097631	04/05/2017	11/04/2017
<i>Description:</i> R/H WING LWR CENTER FUEL TANK AREA HAS MOST O/B FUEL TANK ACCESS PLATE THAT SHOWS EVIDENCE OF LEAKING.				
Count: 1			1	1
Task Card: 1C.80-215.NR-1 Drawing: N/A 04/05/2017 04/25/2017				
<i>Description:</i> RIGHT WING INBD LOWER FLAP HAS MULTIPLE DENTS ON BOTTOM.				
80-345-Maintenance	1999M.1C.80-215.NR-1.80-345	5097849	04/05/2017	04/25/2017
<i>Description:</i> RIGHT WING INBD LOWER FLAP HAS MULTIPLE DENTS ON BOTTOM.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-215.NR-2		Drawing: N/A		04/05/2017	04/13/2017
<i>Description:</i> RIGHT WING INBD AND OTBD FLAP TRACKS NEED CLEANING.					
80-346-Maintenance	1999M.1C.80-215.NR-2.80-346	5097850	04/05/2017	04/13/2017	04/13/2017
<i>Description:</i> RIGHT WING INBD AND OTBD FLAP TRACKS NEED CLEANING.					
Count: 1			1		1
Task Card: 1C.80-217.NR-1		Drawing: N/A		04/05/2017	04/13/2017
<i>Description:</i> RIGHT WING SPOILERS 8,9,10, & 11 ACTUATORS HAVE HYDRAULIC LEAKS.					
80-342-Maintenance	1999M.1C.80-217.NR-1.80-342	5097846	04/05/2017	04/13/2017	04/13/2017
<i>Description:</i> RIGHT WING SPOILERS 8,9,10, & 11 ACTUATORS HAVE HYDRAULIC LEAKS.					
Count: 1			1		1
Task Card: 1C.80-222.NR-1		Drawing: N/A		03/16/2017	01/09/2018
<i>Description:</i> #1 ENGINE INLET LIP CORRPDED					
801-252-Maintenance	1999M.1C.80-222.NR-1.801-25 2	5096677	03/16/2017	01/08/2018	01/09/2018
<i>Description:</i> #1 ENGINE INLET LIP CORRPDED					
Count: 1			1		1
Task Card: 1C.80-222.NR-2		Drawing: N/A		03/16/2017	01/04/2018
<i>Description:</i> #1 ENGINE C-DUCT AFT PANELS CORRODED					
80-253-Maintenance	1999M.1C.80-222.NR-2.80-253	5096678	03/16/2017	01/02/2018	01/04/2018
<i>Description:</i> #1 ENGINE C-DUCT AFT PANELS CORRODED					
Count: 1			1		1
Task Card: 1C.80-222.NR-3		Drawing: N/A		03/16/2017	03/28/2018
<i>Description:</i> #1 ENGINE PYLON AFT FAIRING INBD CORRODED					
80-254-Maintenance	1999M.1C.80-222.NR-3.80-254	5096679	03/16/2017	03/27/2018	03/28/2018
<i>Description:</i> #1 ENGINE PYLON AFT FAIRING INBD CORRODED					
Count: 1			1		1
Task Card: 1C.80-222.NR-4		Drawing: N/A		03/16/2017	01/09/2018
<i>Description:</i> #2 ENGINE INLET LTP HAS CORROSION ON IT.					
801-262-Maintenance	1999M.1C.80-222.NR-4.801-26 2	5096697	03/16/2017	01/08/2018	01/09/2018
<i>Description:</i> #2 ENGINE INLET LTP HAS CORROSION ON IT.					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-224.NR-1				
Drawing: N/A		03/16/2017		04/24/2017
<i>Description: #1 ENGINE C-DUCT, FIREWALL SEALANT BROKEN AND MISSING ON BOTH HEAT SHIELDS.</i>				
80-270-Maintenance	1999M.1C.80-224.NR-1.80-270	5096737	03/16/2017	04/24/2017
<i>Description: #1 ENGINE C-DUCT, FIREWALL SEALANT BROKEN AND MISSING ON BOTH HEAT SHIELDS.</i>				
Count: 1			1	1
Task Card: 1C.80-224.NR-2				
Drawing: N/A		03/16/2017		08/10/2017
<i>Description: FOUND ALL LEFT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.</i>				
80-287-Maintenance	1999M.1C.80-224.NR-2.80-287	5097303	03/16/2017	08/10/2017
<i>Description: FOUND ALL LEFT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.</i>				
Count: 1			1	1
Task Card: 1C.80-224.NR-3				
Drawing: N/A		03/23/2017		01/05/2018
<i>Description: FOUND ALL LEFT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.</i>				
80-305-Maintenance	1999M.1C.80-224.NR-3.80-305	5097632	03/23/2017	01/03/2018
<i>Description: FOUND ALL LEFT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.</i>				
Count: 1			1	1
Task Card: 1C.80-226.NR-1				
Drawing: N/A		03/16/2017		10/19/2017
<i>Description: LEFT ENGINE T/R DOORS #2 AND #10 BUMPER PADS MISSING.</i>				
80-280-Maintenance	1999M.1C.80-226.NR-1.80-280	5097100	03/16/2017	08/10/2017
<i>Description: LEFT ENGINE T/R DOORS #2 AND #10 BUMPER PADS MISSING.</i>				
Count: 1			1	1
Task Card: 1C.80-226.NR-2				
Drawing: N/A		03/16/2017		04/18/2017
<i>Description: LEFT ENGINE AFT PYLON LINK FITTING, SEALANT CRACKED AND MISSING.</i>				
80-281-Maintenance	1999M.1C.80-226.NR-2.80-281	5097102	03/16/2017	04/18/2017
<i>Description: LEFT ENGINE AFT PYLON LINK FITTING, SEALANT CRACKED AND MISSING.</i>				
Count: 1			1	1
Task Card: 1C.80-227.NR-1				
Drawing: N/A		03/16/2017		04/24/2017
<i>Description: RT T/R C-DUCT HEAT SHIELD FIRE WALL SEALANT CRACKED AND HACKING OFF ON INSIDE AREA.</i>				
80-274-Maintenance	1999M.1C.80-227.NR-1.80-274	5096741	03/16/2017	04/24/2017
<i>Description: RT T/R C-DUCT HEAT SHIELD FIRE WALL SEALANT CRACKED AND HACKING OFF ON INSIDE AREA.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-227.NR-2 Drawing: N/A 03/16/2017 04/13/2017				
<i>Description:</i> FOUND ALL RIGHT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.				
80-288-Maintenance	1999M.1C.80-227.NR-2.80-288	5097305	03/16/2017	04/13/2017 04/13/2017
<i>Description:</i> FOUND ALL RIGHT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.				
Count: 1			1	1
Task Card: 1C.80-227.NR-3 Drawing: N/A 03/23/2017 08/10/2017				
<i>Description:</i> FOUND ALL RIGHT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.				
80-306-Maintenance	1999M.1C.80-227.NR-3.80-306	5097633	03/23/2017	08/10/2017 08/10/2017
<i>Description:</i> FOUND ALL RIGHT ENGINE T/R BLOCKER DOOR STRUTS CORRODED.				
Count: 1			1	1
Task Card: 1C.80-237.NR-1 Drawing: N/A 03/16/2017 01/05/2018				
<i>Description:</i> DURING OP CHECK OF LAV SMOKE DETECTORS- AFT LAV SONALERT FAILED.				
80-257-Maintenance	1999M.1C.80-237.NR-1.80-257	5096685	03/16/2017	01/04/2018 01/05/2018
<i>Description:</i> DURING OP CHECK OF LAV SMOKE DETECTORS- AFT LAV SONALERT FAILED.				
Count: 1			1	1
Task Card: 1C.80-239.NR-1 Drawing: N/A 04/10/2017 01/04/2018				
<i>Description:</i> LH AND RH NOSE GEAR OUTBOARD WHEEL BEARINGS ARE CORRODED.				
80-357-Maintenance	1999M.1C.80-239.NR-1.80-357	5098243	04/10/2017	01/03/2018 01/04/2018
<i>Description:</i> LH AND RH NOSE GEAR OUTBOARD WHEEL BEARINGS ARE CORRODED.				
Count: 1			1	1
Task Card: 1C.80-239.NR-2 Drawing: N/A 04/10/2017 04/18/2017				
<i>Description:</i> NOSE GEAR AXLE INNER SURFACE IS CAKED WITH A HARD PACKED CLAY SUBSTANCE. UNABLE TO INSPECT.				
80-358-Maintenance	1999M.1C.80-239.NR-2.80-358	5098244	04/10/2017	04/18/2017 04/18/2017
<i>Description:</i> NOSE GEAR AXLE INNER SURFACE IS CAKED WITH A HARD PACKED CLAY SUBSTANCE. UNABLE TO INSPECT.				
Count: 1			1	1
Task Card: 1C.80-241.NR-1 Drawing: N/A 03/16/2017 04/16/2018				
<i>Description:</i> 80 EACH OXYGEN MASKS HAVE DETERIOATING HOSES ON PASSENGER MASKS.				
80-276-Maintenance	1999M.1C.80-241.NR-1.80-276	5096794	03/16/2017	04/13/2018 04/16/2018
<i>Description:</i> 80 EACH OXYGEN MASKS HAVE DETERIOATING HOSES ON PASSENGER MASKS.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-241.NR-2 Drawing: N/A 06/06/2018 06/21/2018				
<i>Description:</i> Forward entertainment room has two oxygen mask boxes that will not completely open. (Interior panel cover interference)				
805-379-Mx Interiors	1999M.1C.80-241.NR-2.805-37 9	5110359	06/06/2018	06/20/2018 06/21/2018
<i>Description:</i> Forward entertainment room has two oxygen mask boxes that will not completely open. (Interior panel cover interference)				
Count: 1			1	1
Task Card: 1C.80-248.NR-1 Drawing: N/A 04/10/2017 01/04/2018				
<i>Description:</i> RT FWD EMER EXIT LOWER HINGED PANEL AFT HINGE IS BROKEN & THE FWD & MIDDLE HINGES ARE LOOSE, PANEL IS NO LONGER SECURE.				
80-354-Maintenance	1999M.1C.80-248.NR-1.80-354	5098239	04/10/2017	01/03/2018 01/04/2018
<i>Description:</i> RT FWD EMER EXIT LOWER HINGED PANEL AFT HINGE IS BROKEN & THE FWD & MIDDLE HINGES ARE LOOSE, PANEL IS NO LONGER SECURE.				
Count: 1			1	1
Task Card: 1C.80-249.NR-1 Drawing: N/A 04/10/2017 01/02/2018				
<i>Description:</i> RT SATCOM ANTENNA IS MISSING PAINT EXOSING ANTENNA MATERIAL.				
80-355-Maintenance	1999M.1C.80-249.NR-1.80-355	5098241	04/10/2017	12/22/2017 01/02/2018
<i>Description:</i> RT SATCOM ANTENNA IS MISSING PAINT EXOSING ANTENNA MATERIAL.				
Count: 1			1	1
Task Card: 1C.80-249.NR-2 Drawing: N/A 04/10/2017 01/11/2018				
<i>Description:</i> RT SATCOM ANTENNA DOUBLER HAS SIGNS OF SURFACE CORROSION.				
80-356-Maintenance	1999M.1C.80-249.NR-2.80-356	5098242	04/10/2017	01/11/2018 01/11/2018
<i>Description:</i> RT SATCOM ANTENNA DOUBLER HAS SIGNS OF SURFACE CORROSION.				
Count: 1			1	1
Task Card: 1C.80-250.NR-1 Drawing: N/A 04/05/2017 04/13/2017				
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN L/H AND R/H MLG VIDEO CAMERA EXTERNAL LENSES ARE DIRTY AND CLOUDY.				
80-349-Maintenance	1999M.1C.80-250.NR-1.80-349	5097928	04/05/2017	04/13/2017 04/13/2017
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN L/H AND R/H MLG VIDEO CAMERA EXTERNAL LENSES ARE DIRTY AND CLOUDY.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-250.NR-2		Drawing: N/A		04/05/2017	01/10/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN L/H AND R/H MLG VIDEO CAMERA EXTERNAL SURFACE HAS CHIPPED PROTECTIVE COATINGS.					
80-350-Maintenance	1999M.1C.80-250.NR-2.80-350	5097929	04/05/2017	01/10/2018	01/10/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN L/H AND R/H MLG VIDEO CAMERA EXTERNAL SURFACE HAS CHIPPED PROTECTIVE COATINGS.					
Count: 1			1		1
Task Card: 1C.80-250.NR-3		Drawing: N/A		04/10/2017	06/06/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN LH AND RH MLG VIDEO CAMERA EXTERNAL LENS ARE DIRTY AND CLOUDY.					
80-362-Maintenance	1999M.1C.80-250.NR-3.80-362	5098250	04/10/2017	06/05/2018	06/06/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN LH AND RH MLG VIDEO CAMERA EXTERNAL LENS ARE DIRTY AND CLOUDY.					
Count: 1			1		1
Task Card: 1C.80-250.NR-4		Drawing: N/A		04/10/2017	06/06/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN LH AND RH MLG VIDEO CAMERA EXTERNAL SURFACE HAS CHIPPED PROTECTIVE COATINGS.					
80-363-Maintenance	1999M.1C.80-250.NR-4.80-363	5098251	04/10/2017	06/05/2018	06/06/2018
<i>Description:</i> LWR FUSELAGE 06:00 POSITION BETWEEN LH AND RH MLG VIDEO CAMERA EXTERNAL SURFACE HAS CHIPPED PROTECTIVE COATINGS.					
Count: 1			1		1
Task Card: 1C.80-3.NR-1		Drawing: N/A		03/23/2018	03/29/2018
<i>Description:</i> Remove serviceable R1 door slide girt bar from BBJ-737 Serial No. 32806 Tail No. VP-CBB for use on R1 door slide of BBJ-737 Serial No. 3770 Tail No. N380BJ.					
205-378-INTERIOR INSTALL, Mx	1999M.1C.80-3.NR-1.205-378	5109727	03/23/2018	03/28/2018	03/29/2018
<i>Description:</i> Remove serviceable R1 door slide girt bar from BBJ-737 Serial No. 32806 Tail No. VP-CBB for use on R1 door slide of BBJ-737 Serial No. 3770 Tail No. N380BJ.					
Count: 1			1		1
Task Card: 1C.80-47.NR-1		Drawing: N/A		03/23/2017	04/13/2017
<i>Description:</i> AFT ENTRY DOOR LOWER HINGE LINK BEARING WILL NOT TAKE GREASE.					
80-329-Maintenance	1999M.1C.80-47.NR-1.80-329	5097673	03/23/2017	04/13/2017	04/13/2017
<i>Description:</i> AFT ENTRY DOOR LOWER HINGE LINK BEARING WILL NOT TAKE GREASE.					
Count: 1			1		1
Task Card: 1C.80-53.NR-1		Drawing: N/A		03/16/2017	01/04/2018
<i>Description:</i> FWD ENTRY DOOR CENTERING GUIDE NYLON TRACK WORN.					
80-301-Maintenance	1999M.1C.80-53.NR-1.80-301	5097331	03/16/2017	01/03/2018	01/04/2018
<i>Description:</i> FWD ENTRY DOOR CENTERING GUIDE NYLON TRACK WORN.					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 1C.80-53.NR-2 Drawing: N/A 03/16/2017 01/05/2018				
<i>Description: FWD ENTRY DOOR CENTERING GUIDE GUIDE STUD GOUGED.</i>				
80-302-Maintenance	1999M.1C.80-53.NR-2.80-302	5097332	03/16/2017	01/04/2018 01/05/2018
<i>Description: FWD ENTRY DOOR CENTERING GUIDE GUIDE STUD GOUGED.</i>				
Count: 1			1	1
Task Card: 1C.80-53.NR-3 Drawing: N/A 03/16/2017 01/05/2018				
<i>Description: L/H FWD ENTRY DOOR IS OUT OF RIG AS GUIDE BALL AND NYLON TRACK PADS ARE WORN EXCESSIVELY.</i>				
80-303-Maintenance	1999M.1C.80-53.NR-3.80-303	5097333	03/16/2017	01/04/2018 01/05/2018
<i>Description: L/H FWD ENTRY DOOR IS OUT OF RIG AS GUIDE BALL AND NYLON TRACK PADS ARE WORN EXCESSIVELY.</i>				
Count: 1			1	1
Task Card: 1C.80-78.NR-1 Drawing: N/A 04/10/2017 01/04/2018				
<i>Description: FWD CARGO DOOR, SMALL EXTERNAL SPRING LOADED FINGER ACCESS DOOR HAS CORROSION AROUND LOCK.</i>				
80-360-Maintenance	1999M.1C.80-78.NR-1.80-360	5098246	04/10/2017	01/03/2018 01/04/2018
<i>Description: FWD CARGO DOOR, SMALL EXTERNAL SPRING LOADED FINGER ACCESS DOOR HAS CORROSION AROUND LOCK.</i>				
Count: 1			1	1
Task Card: 1C.80-83.NR-1 Drawing: N/A 04/05/2017 04/23/2018				
<i>Description: AFT PASSENGER DOOR FORWARD LOWER BRACKET CRACKED.</i>				
80-347-Maintenance	1999M.1C.80-83.NR-1.80-347	5097851	04/05/2017	04/23/2018 04/23/2018
<i>Description: AFT PASSENGER DOOR FORWARD LOWER BRACKET CRACKED.</i>				
Count: 1			1	1
Task Card: 1C.80-96.NR-1 Drawing: N/A 04/10/2017 01/11/2018				
<i>Description: FWD RADOME EXTERNAL FWD SURFACE HAS NUMEROUS CHIPS IN PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS.</i>				
80-359-Maintenance	1999M.1C.80-96.NR-1.80-359	5098245	04/10/2017	01/11/2018 01/11/2018
<i>Description: FWD RADOME EXTERNAL FWD SURFACE HAS NUMEROUS CHIPS IN PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS.</i>				
Count: 1			1	1
Task Card: 1C.80-99.NR-1 Drawing: N/A 04/05/2017 04/13/2017				
<i>Description: AIRSTAIRS CUTOUT AREA HAS LARGE AIR DUCT CHAFFING FWD AIRSTAIR DOOR TRACK.</i>				
80-352-Maintenance	1999M.1C.80-99.NR-1.80-352	5097931	04/05/2017	04/13/2017 04/13/2017
<i>Description: AIRSTAIRS CUTOUT AREA HAS LARGE AIR DUCT CHAFFING FWD AIRSTAIR DOOR TRACK.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 1C.80-99.NR-2		Drawing: N/A		04/05/2017	04/18/2017
<i>Description: E AND E COMPARTMENT AT 06:00 POSITION HAS DEBRIS AND DUST BUNNIES IN THE BILGE AREA.</i>					
80-353-Maintenance	1999M.1C.80-99.NR-2.80-353	5097932	04/05/2017	04/18/2017	04/18/2017
<i>Description: E AND E COMPARTMENT AT 06:00 POSITION HAS DEBRIS AND DUST BUNNIES IN THE BILGE AREA.</i>					
Count: 1			1		1
Task Card: 32		Drawing: N/A		09/26/2016	07/01/2017
<i>Description: PERFORM ENGINE RUN</i>					
80-Maintenance	1999M.32.80	5092065	09/26/2016	09/28/2016	10/21/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00</i>					
80-1-Maintenance	1999M.32.80-1	5092077	09/26/2016	10/05/2016	10/21/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 4OCT2016.</i>					
80-2-Maintenance	1999M.32.80-2	5092368	10/10/2016	10/13/2016	10/21/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 11OCT2016.</i>					
80-3-Maintenance	1999M.32.80-3	5092369	10/10/2016	10/21/2016	10/21/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 18OCT2016.</i>					
80-4-Maintenance	1999M.32.80-4	5092743	10/27/2016	10/28/2016	10/28/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 27OCT2016.</i>					
80-5-Maintenance	1999M.32.80-5	5092835	11/02/2016	11/07/2016	04/07/2017
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 3NOV2016.</i>					
80-6-Maintenance	1999M.32.80-6	5092836	11/02/2016	11/11/2016	11/11/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 10NOV2016.</i>					
80-7-Maintenance	1999M.32.80-7	5092837	11/02/2016	11/17/2016	11/17/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 17NOV2016.</i>					
80-8-Maintenance	1999M.32.80-8	5092838	11/02/2016	12/05/2016	12/05/2016
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 24NOV2016.</i>					
80-9-Maintenance	1999M.32.80-9	5099901	06/28/2017	07/01/2017	07/01/2017
<i>Description: PERFORM ENGINE RUN IAW 71-00-00, DUE 30JUN2016.</i>					
Count: 10			10		10
Task Card: 71-00-03-600-806-F00		Drawing: NA		12/22/2017	04/25/2018
<i>Description: 71-00-03-600-806-F00</i>					
801-Maintenance	1999M.71-00-03-600-806-F00.8 01	5106525	12/22/2017	04/17/2018	04/25/2018
<i>Description: 71-00-03-600-806-F00 - ENGINE PRESERVATION</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 8 <i>Description: CMS Troubleshooting</i>					
	Drawing: N/A	12/12/2016		06/21/2018	
505-AVIONICS, Mx	1999M.8.50	5093719	12/12/2016	06/20/2018	06/21/2018
<i>Description: Perform CMS Troubleshooting</i>					
Count: 1		1		1	
Task Card: 89.01 <i>Description: Incoming / Departure Inspection, Aircraft Protection and Handling and Maintenance Planning</i>					
	Drawing: N/A	09/08/2016			
80-Maintenance	1999M.89.01.80	5091297	09/08/2016	10/05/2016	10/21/2016
<i>Description: PERFORM PRELIMINARY INSPECTION - COMPLETE FORMS CCA-QUA-019 AND CCA-QUA-020 AS NECESSARY</i>					
Count: 1		1		1	
Task Card: 89.01.80.NR-1 <i>Description: RADOME HAS EROSION AND CORROSION ON DIVERTER STRIPS</i>					
	Drawing: N/A	03/16/2017		01/11/2018	
80-6-Maintenance	1999M.89.01.80.NR-1.80-6	5094489	03/16/2017	01/10/2018	01/11/2018
<i>Description: RADOME HAS EROSION AND CORROSION ON DIVERTER STRIPS</i>					
Count: 1		1		1	
Task Card: 89.01.80.NR-10 <i>Description: EXCESSIVE DIRT ON UPPER SURFACE OF HORIZONTAL STAB AND ELEVATORS</i>					
	Drawing: N/A	02/14/2017		11/17/2017	
80-15-Maintenance	1999M.89.01.80.NR-10.80-15	5094498	02/14/2017	11/16/2017	11/17/2017
<i>Description: EXCESSIVE DIRT ON UPPER SURFACE OF HORIZONTAL STAB AND ELEVATORS</i>					
Count: 1		1		1	
Task Card: 89.01.80.NR-100 <i>Description: ENTRY WAY CEILING PANEL HAS DAMAGE</i>					
	Drawing: N/A	02/14/2017		11/17/2017	
80-105-Maintenance	1999M.89.01.80.NR-100.80-105	5094590	02/14/2017	11/17/2017	11/17/2017
<i>Description: ENTRY WAY CEILING PANEL HAS DAMAGE</i>					
Count: 1		1		1	
Task Card: 89.01.80.NR-101 <i>Description: ENTRY WAY WOOD PANEL HAS MULTIPLE WOOD DAMAGES</i>					
	Drawing: N/A	02/14/2017		11/17/2017	
80-106-Maintenance	1999M.89.01.80.NR-101.80-106	5094591	02/14/2017	11/17/2017	11/17/2017
<i>Description: ENTRY WAY WOOD PANEL HAS MULTIPLE WOOD DAMAGES</i>					
Count: 1		1		1	



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-102		Drawing: N/A		02/14/2017	11/17/2017
<i>Description:</i> ENTRY WAY FLOOR HAS MULTIPLE DAMAGES					
80-107-Maintenance	1999M.89.01.80.NR-102.80-107	5094592	02/14/2017	11/17/2017	11/17/2017
<i>Description:</i> ENTRY WAY FLOOR HAS MULTIPLE DAMAGES					
Count: 1			1		1
Task Card: 89.01.80.NR-103		Drawing: N/A			
<i>Description:</i> Remove left and right leading edge slats for vendor repair per Boeing recommendation. Install left and right leading edge slats upon return from vendor.					
80-108-Maintenance	1999M.89.01.80.NR-103.80-108	5106606	01/03/2018		
<i>Description:</i> Remove left and right leading edge slats for vendor repair per Boeing recommendation. Install left and right leading edge slats upon return from vendor.					
Count: 1			1		0
Task Card: 89.01.80.NR-104		Drawing: N/A		05/16/2018	
<i>Description:</i> REMOVE LEFT AND RIGHT HORIZONTAL STABILIZER LEADING EDGE SKINS FOR EVALUATION AT REPAIR VENDOR DUE TO CORROSION					
801-109-Maintenance	1999M.89.01.80.NR-104.801-109	5110572	05/16/2018		
<i>Description:</i> REMOVE LEFT AND RIGHT HORIZONTAL STABILIZER LEADING EDGE SKINS FOR EVALUATION AT REPAIR VENDOR DUE TO CORROSION					
Count: 1			1		0
Task Card: 89.01.80.NR-11		Drawing: N/A		03/16/2017	
<i>Description:</i> CORROSION ON LAV SERVICE DOOR AND LOCK					
80-16-Maintenance	1999M.89.01.80.NR-11.80-16	5094499	03/16/2017	08/25/2018	
<i>Description:</i> CORROSION ON LAV SERVICE DOOR AND LOCK					
Count: 1			1		0
Task Card: 89.01.80.NR-12		Drawing: N/A		02/14/2017	01/02/2018
<i>Description:</i> LOCK MISSING ON HIGH PRESSURE AIR SUPPLY SERVICE DOOR					
80-17-Maintenance	1999M.89.01.80.NR-12.80-17	5094500	03/16/2017	12/22/2017	01/02/2018
<i>Description:</i> LOCK MISSING ON HIGH PRESSURE AIR SUPPLY SERVICE DOOR					
Count: 1			1		1
Task Card: 89.01.80.NR-13		Drawing: N/A		03/16/2017	11/02/2017
<i>Description:</i> SEVERAL COMPONENTS IN MLG WELL HAVE CORROSION					
80-18-Maintenance	1999M.89.01.80.NR-13.80-18	5094501	03/16/2017	10/31/2017	11/02/2017
<i>Description:</i> SEVERAL COMPONENTS IN MLG WELL HAVE CORROSION					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-14 <i>Description: LH & RH MLG DOORS HAVE CORROSION ON HARDWARE</i>				
80-19-Maintenance	1999M.89.01.80.NR-14.80-19	5094502	03/16/2017	05/11/2017
<i>Description: LH & RH MLG DOORS HAVE CORROSION ON HARDWARE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-15 <i>Description: EXCESSIVE DIRT IN MLG WHEEL WELL</i>				
80-20-Maintenance	1999M.89.01.80.NR-15.80-20	5094503	02/14/2017	11/16/2017
<i>Description: EXCESSIVE DIRT IN MLG WHEEL WELL</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-16 <i>Description: INSIDE APU DOOR FULL OF WATER, BIRD FEATHERS & DROPPINGS</i>				
80-21-Maintenance	1999M.89.01.80.NR-16.80-21	5094504	03/16/2017	04/14/2017
<i>Description: INSIDE APU DOOR FULL OF WATER, BIRD FEATHERS & DROPPINGS</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-17 <i>Description: RH WING ACCESS PANEL I/B HAS FUEL LEAK</i>				
80-22-Maintenance	1999M.89.01.80.NR-17.80-22	5094505	03/16/2017	11/04/2017
<i>Description: RH WING ACCESS PANEL I/B HAS FUEL LEAK</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-18 <i>Description: LH WING ACCESS PANELS (2 EA) HAS FUEL LEAK</i>				
80-23-Maintenance	1999M.89.01.80.NR-18.80-23	5094506	03/16/2017	04/04/2017
<i>Description: LH WING ACCESS PANELS (2 EA) HAS FUEL LEAK</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-19 <i>Description: #1 & #2 T/R BLOCKER DOOR DRAG LINKS ARE CORRODED</i>				
80-24-Maintenance	1999M.89.01.80.NR-19.80-24	5094507	03/16/2017	04/13/2017
<i>Description: #1 & #2 T/R BLOCKER DOOR DRAG LINKS ARE CORRODED</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-2 <i>Description: DELAMINATION ON PILOTS SIDE WINDOWS</i>				
80-7-Maintenance	1999M.89.01.80.NR-2.80-7	03/16/2017	04/24/2017	04/24/2017
<i>Description: DELAMINATION ON PILOTS SIDE WINDOWS</i>				
Count: 1		1		1
Task Card: 89.01.80.NR-20 <i>Description: ALL STATIC PORTS SHOW SIGNS OF CORROSION</i>				
80-25-Maintenance	1999M.89.01.80.NR-20.80-25	03/16/2017	04/14/2017	04/14/2017
<i>Description: ALL STATIC PORTS SHOW SIGNS OF CORROSION</i>				
Count: 1		1		1
Task Card: 89.01.80.NR-21 <i>Description: LH & RH HORIZONTAL STAB L/E ARE CORRODED</i>				
606-26-SHEET METAL SHOP, Mx	1999M.89.01.80.NR-21.606-26	03/16/2017	08/22/2018	08/23/2018
<i>Description: LH & RH HORIZONTAL STAB L/E ARE CORRODED</i>				
Count: 1		1		1
Task Card: 89.01.80.NR-22 <i>Description: NOSE LANDING GEAR TIRES ARE CRACKED</i>				
80-27-Maintenance	1999M.89.01.80.NR-22.80-27	03/16/2017	04/14/2017	04/14/2017
<i>Description: NOSE LANDING GEAR TIRES ARE CRACKED</i>				
Count: 1		1		1
Task Card: 89.01.80.NR-23 <i>Description: RH NAV LENS HAS MOISTURE INSIDE</i>				
80-28-Maintenance	1999M.89.01.80.NR-23.80-28	03/16/2017	04/14/2017	04/14/2017
<i>Description: RH NAV LENS HAS MOISTURE INSIDE</i>				
Count: 1		1		1
Task Card: 89.01.80.NR-24 <i>Description: LH CABIN WINDOW #4, 7, 14, & 24 ARE SCRATCHED</i>				
801-29-Maintenance	1999M.89.01.80.NR-24.801-29	03/30/2017	05/05/2017	05/05/2017
<i>Description: LH CABIN WINDOW #4, 7, 14, & 24 ARE SCRATCHED</i>				
Count: 1		1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-25 <i>Description: LH #5 SPOILER ACTUATOR IS LEAKING</i>	Drawing: N/A	02/14/2017		04/14/2017	
80-30-Maintenance <i>Description: LH #5 SPOILER ACTUATOR IS LEAKING</i>	1999M.89.01.80.NR-25.80-30	5094513	03/16/2017	04/14/2017	04/14/2017
Count: 1			1		1
Task Card: 89.01.80.NR-26 <i>Description: CO-PILOTS SEAT CUSHION TORN</i>	Drawing: N/A	02/14/2017		11/02/2017	
80-31-Maintenance <i>Description: CO-PILOTS SEAT CUSHION TORN</i>	1999M.89.01.80.NR-26.80-31	5094514	02/14/2017	10/30/2017	11/02/2017
Count: 1			1		1
Task Card: 89.01.80.NR-27 <i>Description: EXCESSIVE DIRT IN RH & LH FLAP WELLS</i>	Drawing: N/A	02/14/2017		11/17/2017	
80-32-Maintenance <i>Description: EXCESSIVE DIRT IN RH & LH FLAP WELLS</i>	1999M.89.01.80.NR-27.80-32	5094515	02/14/2017	11/16/2017	11/17/2017
Count: 1			1		1
Task Card: 89.01.80.NR-28 <i>Description: G-5 GALLEY WORK LIGHT HAS STAIN</i>	Drawing: N/A	02/14/2017		11/02/2017	
80-33-Maintenance <i>Description: G-5 GALLEY WORK LIGHT HAS STAIN</i>	1999M.89.01.80.NR-28.80-33	5094516	02/14/2017	10/30/2017	11/02/2017
Count: 1			1		1
Task Card: 89.01.80.NR-29 <i>Description: G-5 GALLEY COUNTER TOP HAS SEVERAL CRACKS</i>	Drawing: N/A	02/14/2017		11/02/2017	
80-34-Maintenance <i>Description: G-5 GALLEY COUNTER TOP HAS SEVERAL CRACKS</i>	1999M.89.01.80.NR-29.80-34	5094517	02/14/2017	10/30/2017	11/02/2017
Count: 1			1		1
Task Card: 89.01.80.NR-3 <i>Description: FOUR UPPER COCKPIT WINDOWS ARE DELAMINATED</i>	Drawing: N/A	03/16/2017		04/24/2017	
80-8-Maintenance <i>Description: FOUR UPPER COCKPIT WINDOWS ARE DELAMINATED</i>	1999M.89.01.80.NR-3.80-8	5094491	03/16/2017	04/24/2017	04/24/2017
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-30		Drawing: N/A		02/14/2017	11/02/2017
<i>Description: G-5 GALLEY HAS SEVERAL CRACKS AND CHIPS ON SEVERAL DOORS</i>					
80-35-Maintenance	1999M.89.01.80.NR-30.80-35	5094518	02/14/2017	10/30/2017	11/02/2017
<i>Description: G-5 GALLEY HAS SEVERAL CRACKS AND CHIPS ON SEVERAL DOORS</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-31		Drawing: N/A		02/14/2017	01/09/2018
<i>Description: G-5 GALLEY OVEN BRAKE MISSING SCREW</i>					
80-36-Maintenance	1999M.89.01.80.NR-31.80-36	5094519	02/14/2017	01/08/2018	01/09/2018
<i>Description: G-5 GALLEY OVEN BRAKE MISSING SCREW</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-32		Drawing: N/A		02/14/2017	11/17/2017
<i>Description: ALL FOOD TRAYS ARE IN DISREPAIR</i>					
80-37-Maintenance	1999M.89.01.80.NR-32.80-37	5094520	02/14/2017	11/16/2017	11/17/2017
<i>Description: ALL FOOD TRAYS ARE IN DISREPAIR</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-33		Drawing: N/A		02/14/2017	11/17/2017
<i>Description: G-5 GALLEY NEEDS CLEANING</i>					
80-38-Maintenance	1999M.89.01.80.NR-33.80-38	5094521	02/14/2017	11/16/2017	11/17/2017
<i>Description: G-5 GALLEY NEEDS CLEANING</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-34		Drawing: N/A		02/14/2017	
<i>Description: LH FLIGHT ATTENDANT SEAT HAS A</i>					
80-39-Maintenance	1999M.89.01.80.NR-34.80-39	5094522	02/14/2017	08/25/2018	
<i>Description: LH FLIGHT ATTENDANT SEAT HAS A</i>					
Count: 1			1		0
Task Card: 89.01.80.NR-35		Drawing: N/A		02/14/2017	01/04/2018
<i>Description: LH AFT FLIGHT ATTENDANT SEAT HAS TWO DIFFERENT SEAT BELTS</i>					
80-40-Maintenance	1999M.89.01.80.NR-35.80-40	5094523	02/14/2017	01/03/2018	01/04/2018
<i>Description: LH AFT FLIGHT ATTENDANT SEAT HAS TWO DIFFERENT SEAT BELTS</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-36		Drawing: N/A		02/14/2017	
<i>Description: LH CABIN ENTERTAINMENT SYSTEM HAS SEVERAL CHIPS AND CRACKS & MISSING DOOR</i>					
80-41-Maintenance	1999M.89.01.80.NR-36.80-41	5094524	02/14/2017	11/16/2017	11/17/2017
<i>Description: LH CABIN ENTERTAINMENT SYSTEM HAS SEVERAL CHIPS AND CRACKS & MISSING DOOR</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-37		Drawing: N/A		02/14/2017	
<i>Description: G-5 GALLEY NEEDS CLEANING</i>					
80-42-Maintenance	1999M.89.01.80.NR-37.80-42	5094525	02/14/2017	11/16/2017	11/17/2017
<i>Description: G-5 GALLEY NEEDS CLEANING</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-38		Drawing: N/A		02/14/2017	11/17/2017
<i>Description: LH #3 WINDOW SHADE HAS SCRATCH</i>					
80-43-Maintenance	1999M.89.01.80.NR-38.80-43	5094526	02/14/2017	11/16/2017	11/17/2017
<i>Description: LH #3 WINDOW SHADE HAS SCRATCH</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-39		Drawing: N/A		02/14/2017	11/17/2017
<i>Description: ALL WINDOW SHADES NEED CLEANING AND INSPECTION FOR APPROPRIATE FUNCTIONS</i>					
80-44-Maintenance	1999M.89.01.80.NR-39.80-44	5094527	02/14/2017	11/16/2017	11/17/2017
<i>Description: ALL WINDOW SHADES NEED CLEANING AND INSPECTION FOR APPROPRIATE FUNCTIONS</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-4		Drawing: N/A		03/16/2017	04/11/2017
<i>Description: CORROSION ON L1 ENTRY DOOR HANDLE</i>					
801-9-Maintenance	1999M.89.01.80.NR-4.801-9	5094492	03/16/2017	04/11/2017	04/11/2017
<i>Description: CORROSION ON L1 ENTRY DOOR HANDLE</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-40		Drawing: N/A		02/14/2017	11/17/2017
<i>Description: RH SIDE FWD CLOSET ON AFT GALLEY AREA HAS MULTIPLE SCRATCHES AND DENTS</i>					
80-45-Maintenance	1999M.89.01.80.NR-40.80-45	5094528	02/14/2017	11/16/2017	11/17/2017
<i>Description: RH SIDE FWD CLOSET ON AFT GALLEY AREA HAS MULTIPLE SCRATCHES AND DENTS</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-41				
<i>Description: AFT GALLEY AREA LOOKING FWD RH BULKHEAD HAS DAMAGE</i>				
80-46-Maintenance	1999M.89.01.80.NR-41.80-46	5094529	02/14/2017	11/16/2017 11/17/2017
<i>Description: AFT GALLEY AREA LOOKING FWD RH BULKHEAD HAS DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-42				
<i>Description: AFT GALLEY AREA LH BULKHEAD HAS DAMAGE</i>				
80-47-Maintenance	1999M.89.01.80.NR-42.80-47	5094530	02/14/2017	11/16/2017 11/17/2017
<i>Description: AFT GALLEY AREA LH BULKHEAD HAS DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-43				
<i>Description: LH AFT ENTERTAINMENT CLOSET HAS MULTIPLE DAMAGES</i>				
80-48-Maintenance	1999M.89.01.80.NR-43.80-48	5094531	02/14/2017	11/16/2017 11/17/2017
<i>Description: LH AFT ENTERTAINMENT CLOSET HAS MULTIPLE DAMAGES</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-44				
<i>Description: RH AFT AREA CENTER TABLE CUP HOLDER NEEDS NEW CORK</i>				
80-49-Maintenance	1999M.89.01.80.NR-44.80-49	5094532	02/14/2017	11/16/2017 11/17/2017
<i>Description: RH AFT AREA CENTER TABLE CUP HOLDER NEEDS NEW CORK</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-45				
<i>Description: RH AFT AREA #17 AND #18 SEAT REST LEGS ARE LOOSE</i>				
80-50-Maintenance	1999M.89.01.80.NR-45.80-50	5094533	02/14/2017	01/10/2018 01/11/2018
<i>Description: RH AFT AREA #17 AND #18 SEAT REST LEGS ARE LOOSE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-46				
<i>Description: RH AFT SEATING AREA ALL</i>				
80-51-Maintenance	1999M.89.01.80.NR-46.80-51	5094534	02/14/2017	08/25/2018
<i>Description: RH AFT SEATING AREA ALL</i>				
Count: 1			1	0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-47 Drawing: N/A Description: AFT CABIN AREA AFT CARPET HAS GAP AND NEEDS CLEANING				
80-52-Maintenance	1999M.89.01.80.NR-47.80-52	5094535	02/14/2017	11/16/2017 11/17/2017
Description: AFT CABIN AREA AFT CARPET HAS GAP AND NEEDS CLEANING				
Count: 1			1	1
Task Card: 89.01.80.NR-48 Drawing: N/A Description: AFT CABIN AREA SEATING AREA ALL TV MONITORS NEED CHECK AND ADJUSTMENT. SEATS 11-18				
80-53-Maintenance	1999M.89.01.80.NR-48.80-53	5094538	02/14/2017	11/16/2017 11/17/2017
Description: AFT CABIN AREA SEATING AREA ALL TV MONITORS NEED CHECK AND ADJUSTMENT. SEATS 11-18				
Count: 1			1	1
Task Card: 89.01.80.NR-49 Drawing: N/A Description: AFT CABIN AREA, ALL CEILING PANELS NEED CLEANING				
80-54-Maintenance	1999M.89.01.80.NR-49.80-54	5094539	02/14/2017	11/16/2017 11/17/2017
Description: AFT CABIN AREA, ALL CEILING PANELS NEED CLEANING				
Count: 1			1	1
Task Card: 89.01.80.NR-5 Drawing: N/A Description: WATER SERVICE DOOR AND LOCK ARE CORRODED				
80-10-Maintenance	1999M.89.01.80.NR-5.80-10	5094493	03/16/2017	08/25/2018
Description: WATER SERVICE DOOR AND LOCK ARE CORRODED				
Count: 1			1	0
Task Card: 89.01.80.NR-50 Drawing: N/A Description: AFT CABIN AREA MULTIPLE LIFE VEST STORAGE HAS LOOSE VELCRO (NEED TO CHECK ALL)				
80-55-Maintenance	1999M.89.01.80.NR-50.80-55	5094540	02/14/2017	11/16/2017 11/17/2017
Description: AFT CABIN AREA MULTIPLE LIFE VEST STORAGE HAS LOOSE VELCRO (NEED TO CHECK ALL)				
Count: 1			1	1
Task Card: 89.01.80.NR-51 Drawing: N/A Description: AFT CABIN AREA LH DIVAN MATERIAL HAS DAMAGE				
80-56-Maintenance	1999M.89.01.80.NR-51.80-56	5094541	02/14/2017	11/16/2017 11/17/2017
Description: AFT CABIN AREA LH DIVAN MATERIAL HAS DAMAGE				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-52 Drawing: N/A 02/14/2017 <i>Description: AFT CABIN ARE LH SIDE EMERGENCY LIGHTS ARE LOOSE</i>				
80-57-Maintenance	1999M.89.01.80.NR-52.80-57	5094542	02/14/2017	
<i>Description: AFT CABIN ARE LH SIDE EMERGENCY LIGHTS ARE LOOSE</i>				
Count: 1			1	0
Task Card: 89.01.80.NR-53 Drawing: N/A 02/14/2017 11/17/2017 <i>Description: ALL WOOD ON AFT CABIN NEEDS CLEANING AND DETAILING</i>				
80-58-Maintenance	1999M.89.01.80.NR-53.80-58	5094543	02/14/2017	11/16/2017 11/17/2017
<i>Description: ALL WOOD ON AFT CABIN NEEDS CLEANING AND DETAILING</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-54 Drawing: N/A 02/14/2017 11/17/2017 <i>Description: AFT LAV FLOOR HAS MULTIPLE DAMAGES</i>				
80-59-Maintenance	1999M.89.01.80.NR-54.80-59	5094544	02/14/2017	11/16/2017 11/17/2017
<i>Description: AFT LAV FLOOR HAS MULTIPLE DAMAGES</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-55 Drawing: N/A 02/14/2017 <i>Description: AFT LAV ALL DECOMPRESSION PANELS ARE LOOSE</i>				
80-60-Maintenance	1999M.89.01.80.NR-55.80-60	5094545	02/14/2017	
<i>Description: AFT LAV ALL DECOMPRESSION PANELS ARE LOOSE</i>				
Count: 1			1	0
Task Card: 89.01.80.NR-56 Drawing: N/A 02/14/2017 11/17/2017 <i>Description: AFT LAV SINK NEEDS CLEANING AND POLISHING</i>				
80-61-Maintenance	1999M.89.01.80.NR-56.80-61	5094546	02/14/2017	11/16/2017 11/17/2017
<i>Description: AFT LAV SINK NEEDS CLEANING AND POLISHING</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-57 Drawing: N/A 02/14/2017 11/17/2017 <i>Description: AFT LAV COUNTER TOP HAS EVIDENCE OF DAMAGE</i>				
80-62-Maintenance	1999M.89.01.80.NR-57.80-62	5094547	02/14/2017	11/16/2017 11/17/2017
<i>Description: AFT LAV COUNTER TOP HAS EVIDENCE OF DAMAGE</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-58 <i>Description: AFT LAV DOOR HAS MULTIPLE DAMAGES ON WOOD TRIM</i>				
80-63-Maintenance	1999M.89.01.80.NR-58.80-63	Drawing: N/A	02/14/2017	11/17/2017
<i>Description: AFT LAV DOOR HAS MULTIPLE DAMAGES ON WOOD TRIM</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-59 <i>Description: RH AFT LAV NEEDS GENERAL CLEANING</i>				
80-64-Maintenance	1999M.89.01.80.NR-59.80-64	Drawing: N/A	02/14/2017	11/16/2017
<i>Description: RH AFT LAV NEEDS GENERAL CLEANING</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-6 <i>Description: LH & RH WING L/E AND WINGLETS L/E HAVE CORROSION</i>				
606-11-SHEET METAL SHOP, Mx	1999M.89.01.80.NR-6.606-11	Drawing: N/A	03/16/2017	
<i>Description: LH & RH WING L/E AND WINGLETS L/E HAVE CORROSION</i>				
Count: 1			1	0
Task Card: 89.01.80.NR-60 <i>Description: MASTER LAV FLOOR HAS MULTIPLE DAMAGES</i>				
80-65-Maintenance	1999M.89.01.80.NR-60.80-65	Drawing: N/A	02/14/2017	11/17/2017
<i>Description: MASTER LAV FLOOR HAS MULTIPLE DAMAGES</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-61 <i>Description: MASTER LAV VALANCE PANEL IS NOT INSTALLED</i>				
80-66-Maintenance	1999M.89.01.80.NR-61.80-66	Drawing: N/A	02/14/2017	11/17/2017
<i>Description: MASTER LAV VALANCE PANEL IS NOT INSTALLED</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-62 <i>Description: MASTER LAV DECO PANEL IS MISSING</i>				
80-67-Maintenance	1999M.89.01.80.NR-62.80-67	Drawing: N/A	02/14/2017	11/17/2017
<i>Description: MASTER LAV DECO PANEL IS MISSING</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-63 <i>Description: MASTER LAV SINK NEEDS CLEANING AND POLISHING</i>	Drawing: N/A	02/14/2017		
80-68-Maintenance <i>Description: MASTER LAV SINK NEEDS CLEANING AND POLISHING</i>	1999M.89.01.80.NR-63.80-68	5094553	02/14/2017	11/17/2017
Count: 1			1	1
Task Card: 89.01.80.NR-64 <i>Description: MASTER LAV VANITY NEEDS CLEANING AND HAS VARIOUS VINYL DAMAGE</i>	Drawing: N/A	02/14/2017		11/17/2017
80-69-Maintenance <i>Description: MASTER LAV VANITY NEEDS CLEANING AND HAS VARIOUS VINYL DAMAGE</i>	1999M.89.01.80.NR-64.80-69	5094554	02/14/2017	11/17/2017
Count: 1			1	1
Task Card: 89.01.80.NR-65 <i>Description: MASTER LAV COUNTER HAS MULTIPLE DAMAGES</i>	Drawing: N/A	02/14/2017		11/17/2017
80-70-Maintenance <i>Description: MASTER LAV COUNTER HAS MULTIPLE DAMAGES</i>	1999M.89.01.80.NR-65.80-70	5094555	02/14/2017	11/17/2017
Count: 1			1	1
Task Card: 89.01.80.NR-66 <i>Description: MASTER LAV NEEDS GENERAL CLEANING</i>	Drawing: N/A	02/14/2017		11/17/2017
80-71-Maintenance <i>Description: MASTER LAV NEEDS GENERAL CLEANING</i>	1999M.89.01.80.NR-66.80-71	5094556	02/14/2017	11/17/2017
Count: 1			1	1
Task Card: 89.01.80.NR-67 <i>Description: MASTER LAV BIDET HAS MULTIPLE DAMAGES AND NEEDS CLEANING</i>	Drawing: N/A	02/14/2017		11/17/2017
80-72-Maintenance <i>Description: MASTER LAV BIDET HAS MULTIPLE DAMAGES AND NEEDS CLEANING</i>	1999M.89.01.80.NR-67.80-72	5094557	02/14/2017	11/17/2017
Count: 1			1	1
Task Card: 89.01.80.NR-68 <i>Description: MASTER LAV DOOR HAS MULTIPLE DAMAGES ON THE WOOD</i>	Drawing: N/A	02/14/2017		11/17/2017
80-73-Maintenance <i>Description: MASTER LAV DOOR HAS MULTIPLE DAMAGES ON THE WOOD</i>	1999M.89.01.80.NR-68.80-73	5094558	02/14/2017	11/17/2017
Count: 1			1	1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-69 <i>Description: MASTER BEDROOM CEILING PANEL HAS DAMAGE ON LH AFT OF PANEL</i>	Drawing: N/A	02/14/2017		11/17/2017	
80-74-Maintenance	1999M.89.01.80.NR-69.80-74	5094559	02/14/2017	11/17/2017	11/17/2017
<i>Description: MASTER BEDROOM CEILING PANEL HAS DAMAGE ON LH AFT OF PANEL</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-7 <i>Description: #1 AND #2 ENGINE INLETS HAVE CORROSION ON L/E</i>	Drawing: N/A	03/16/2017		01/02/2018	
801-12-Maintenance	1999M.89.01.80.NR-7.801-12	5094495	03/16/2017	12/22/2017	01/02/2018
<i>Description: #1 AND #2 ENGINE INLETS HAVE CORROSION ON L/E</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-70 <i>Description: MASTER BEDROOM LH NIGHTSTAND HAS LOOSE COVER</i>	Drawing: N/A	02/14/2017		11/17/2017	
80-75-Maintenance	1999M.89.01.80.NR-70.80-75	5094560	02/14/2017	11/17/2017	11/17/2017
<i>Description: MASTER BEDROOM LH NIGHTSTAND HAS LOOSE COVER</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-71 <i>Description: MASTER BEDROOM HEADBOARD HAS FABRIC DAMAGE</i>	Drawing: N/A	02/14/2017		11/17/2017	
80-76-Maintenance	1999M.89.01.80.NR-71.80-76	5094561	02/14/2017	11/17/2017	11/17/2017
<i>Description: MASTER BEDROOM HEADBOARD HAS FABRIC DAMAGE</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-72 <i>Description: MASTER BEDROOM BED UP AND DOWN MECHANISM IS BROKEN</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-77-Maintenance	1999M.89.01.80.NR-72.80-77	5094562	02/14/2017	12/01/2017	12/01/2017
<i>Description: MASTER BEDROOM BED UP AND DOWN MECHANISM IS BROKEN</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-73 <i>Description: MASTER BEDROOM DOOR HAS MULTIPLE DAMAGES ON DOOR TRIM</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-78-Maintenance	1999M.89.01.80.NR-73.80-78	5094563	02/14/2017	12/01/2017	12/01/2017
<i>Description: MASTER BEDROOM DOOR HAS MULTIPLE DAMAGES ON DOOR TRIM</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: 89.01.80.NR-74 <i>Description: LH HALL SIDE LEDGES HAVE MULTIPLE DAMAGES</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-79-Maintenance	1999M.89.01.80.NR-74.80-79	5094564	02/14/2017	12/01/2017	12/01/2017
<i>Description: LH HALL SIDE LEDGES HAVE MULTIPLE DAMAGES</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-75 <i>Description: LH FORWARD DIVAN HAS FABRIC DAMAGE</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-80-Maintenance	1999M.89.01.80.NR-75.80-80	5094565	02/14/2017	12/01/2017	12/01/2017
<i>Description: LH FORWARD DIVAN HAS FABRIC DAMAGE</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-76 <i>Description: RH AND LH EXIT WINDOW SHADE HAS DAMAGE</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-81-Maintenance	1999M.89.01.80.NR-76.80-81	5094566	02/14/2017	12/01/2017	12/01/2017
<i>Description: RH AND LH EXIT WINDOW SHADE HAS DAMAGE</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-77 <i>Description: FWD CABIN CEILING PANEL HAS MULTIPLE INCONSISTANT GAPS</i>	Drawing: N/A	02/14/2017		12/05/2017	
80-82-Maintenance	1999M.89.01.80.NR-77.80-82	5094567	02/14/2017	12/01/2017	12/05/2017
<i>Description: FWD CABIN CEILING PANEL HAS MULTIPLE INCONSISTANT GAPS</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-78 <i>Description: FWD CABIN CARPET HAS A GAP ALL AROUND</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-83-Maintenance	1999M.89.01.80.NR-78.80-83	5094568	02/14/2017	12/01/2017	12/01/2017
<i>Description: FWD CABIN CARPET HAS A GAP ALL AROUND</i>					
Count: 1			1		1
Task Card: 89.01.80.NR-79 <i>Description: FWD CABIN SEATING AREA, ALL SEATS HAVE DAMAGE BY THE HAND REST</i>	Drawing: N/A	02/14/2017		12/01/2017	
80-84-Maintenance	1999M.89.01.80.NR-79.80-84	5094569	02/14/2017	12/01/2017	12/01/2017
<i>Description: FWD CABIN SEATING AREA, ALL SEATS HAVE DAMAGE BY THE HAND REST</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-8				
<i>Description: #1 AND #2 ENGINE EXHAUST BRIGHT WORK HAVE CORROSION</i>				
80-13-Maintenance	1999M.89.01.80.NR-8.80-13	5094496	03/16/2017	05/05/2017
<i>Description: #1 AND #2 ENGINE EXHAUST BRIGHT WORK HAVE CORROSION</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-80				
<i>Description: FWD CABIN SEATS NEED CHECK FOR OPERATION ITSELF</i>				
80-85-Maintenance	1999M.89.01.80.NR-80.80-85	5094570	02/14/2017	12/01/2017
<i>Description: FWD CABIN SEATS NEED CHECK FOR OPERATION ITSELF</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-81				
<i>Description: FWD CABIN SEAT TV MONITOR NEEDS CHECK AND TEST</i>				
80-86-Maintenance	1999M.89.01.80.NR-81.80-86	5094571	02/14/2017	12/01/2017
<i>Description: FWD CABIN SEAT TV MONITOR NEEDS CHECK AND TEST</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-82				
<i>Description: FWD CABIN CEILING PANEL NEEDS ADJUSTMENT AND CLEANING</i>				
80-87-Maintenance	1999M.89.01.80.NR-82.80-87	5094572	02/14/2017	12/01/2017
<i>Description: FWD CABIN CEILING PANEL NEEDS ADJUSTMENT AND CLEANING</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-83				
<i>Description: FWD CABIN SEATING AREA LIFE VEST STORAGE NEEDS RE-GLUE</i>				
80-88-Maintenance	1999M.89.01.80.NR-83.80-88	5094573	02/14/2017	12/01/2017
<i>Description: FWD CABIN SEATING AREA LIFE VEST STORAGE NEEDS RE-GLUE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-84				
<i>Description: FWD CABIN SEAT LIFE VEST ALL NEED ADJUSTMENT</i>				
80-89-Maintenance	1999M.89.01.80.NR-84.80-89	5094574	02/14/2017	12/01/2017
<i>Description: FWD CABIN SEAT LIFE VEST ALL NEED ADJUSTMENT</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-85 <i>Description: FWD CABIN RH #2 CONFERENCE TABLE NEEDS NEW CORK</i>				
80-90-Maintenance	1999M.89.01.80.NR-85.80-90	5094575	02/14/2017	12/01/2017
<i>Description: FWD CABIN RH #2 CONFERENCE TABLE NEEDS NEW CORK</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-86 <i>Description: FWD CABIN TV MONITOR STORAGE HAS LEATHER DAMAGE</i>				
80-91-Maintenance	1999M.89.01.80.NR-86.80-91	5094576	02/14/2017	12/01/2017
<i>Description: FWD CABIN TV MONITOR STORAGE HAS LEATHER DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-87 <i>Description: FWD CABIN #3 WINDOW SHADE HAS DAMAGE</i>				
80-92-Maintenance	1999M.89.01.80.NR-87.80-92	5094577	02/14/2017	12/01/2017
<i>Description: FWD CABIN #3 WINDOW SHADE HAS DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-88 <i>Description: FWD CABIN LH SIDE LEDGE HAS DAMAGE</i>				
80-93-Maintenance	1999M.89.01.80.NR-88.80-93	5094578	02/14/2017	12/01/2017
<i>Description: FWD CABIN LH SIDE LEDGE HAS DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-89 <i>Description: FWD CABIN RH SIDE LEDGE HAS MULTIPLE DAMAGE</i>				
80-94-Maintenance	1999M.89.01.80.NR-89.80-94	5094579	02/14/2017	12/01/2017
<i>Description: FWD CABIN RH SIDE LEDGE HAS MULTIPLE DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-9 <i>Description: APU INLET HAS EXCESSIVE BIRD DROPPINGS INSIDE</i>				
80-14-Maintenance	1999M.89.01.80.NR-9.80-14	5094497	03/16/2017	04/04/2017
<i>Description: APU INLET HAS EXCESSIVE BIRD DROPPINGS INSIDE</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-90				
Drawing: N/A		02/14/2017		11/02/2017
<i>Description: LH FWD CABIN CREDENZA HAS MULTIPLE DAMAGES</i>				
80-95-Maintenance	1999M.89.01.80.NR-90.80-95	5094580	02/14/2017	10/30/2017
<i>Description: LH FWD CABIN CREDENZA HAS MULTIPLE DAMAGES</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-91				
Drawing: N/A		02/14/2017		11/17/2017
<i>Description: LH FWD CREDENZA NEEDS CLEANING</i>				
80-96-Maintenance	1999M.89.01.80.NR-91.80-96	5094581	02/14/2017	11/17/2017
<i>Description: LH FWD CREDENZA NEEDS CLEANING</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-92				
Drawing: N/A		02/14/2017		11/02/2017
<i>Description: LH FWD FREEZER HAS EVIDENCE OF CORROSION</i>				
80-97-Maintenance	1999M.89.01.80.NR-92.80-97	5094582	03/16/2017	10/30/2017
<i>Description: LH FWD FREEZER HAS EVIDENCE OF CORROSION</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-93				
Drawing: N/A		02/14/2017		11/02/2017
<i>Description: LH FWD FREEZER NEEDS CLEANING AND INSPECTION</i>				
80-98-Maintenance	1999M.89.01.80.NR-93.80-98	5094583	02/14/2017	10/30/2017
<i>Description: LH FWD FREEZER NEEDS CLEANING AND INSPECTION</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-94				
Drawing: N/A		02/14/2017		11/17/2017
<i>Description: FWD CABIN, ALL WINDOW SHADES NEED CLEANING AND INSPECTION</i>				
80-99-Maintenance	1999M.89.01.80.NR-94.80-99	5094584	02/14/2017	11/17/2017
<i>Description: FWD CABIN, ALL WINDOW SHADES NEED CLEANING AND INSPECTION</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-95				
Drawing: N/A		02/14/2017		11/17/2017
<i>Description: LH FWD CABIN VALANCE PANEL IS LOOSE</i>				
80-100-Maintenance	1999M.89.01.80.NR-95.80-100	5094585	02/14/2017	11/17/2017
<i>Description: LH FWD CABIN VALANCE PANEL IS LOOSE</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: 89.01.80.NR-96 <i>Description: LH CABIN ENTRY DOOR BULKHEAD HAS TRIM DAMAGE</i>				
80-101-Maintenance	1999M.89.01.80.NR-96.80-101	5094586	02/14/2017	10/30/2017
<i>Description: LH CABIN ENTRY DOOR BULKHEAD HAS TRIM DAMAGE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-97 <i>Description: RH CREW REST PANEL LOOSE</i>				
80-102-Maintenance	1999M.89.01.80.NR-97.80-102	5094587	02/14/2017	11/17/2017
<i>Description: RH CREW REST PANEL LOOSE</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-98 <i>Description: RH CREW CLOSET HAS MULTIPLE DAMAGES</i>				
80-103-Maintenance	1999M.89.01.80.NR-98.80-103	5094588	02/14/2017	10/30/2017
<i>Description: RH CREW CLOSET HAS MULTIPLE DAMAGES</i>				
Count: 1			1	1
Task Card: 89.01.80.NR-99 <i>Description: CREW REST AREA FLOOR NEEDS CLEANING</i>				
80-104-Maintenance	1999M.89.01.80.NR-99.80-104	5094589	02/14/2017	
<i>Description: CREW REST AREA FLOOR NEEDS CLEANING</i>				
Count: 1			1	0
Task Card: 9 <i>Description: 50HZ Converter P/N 4C3500-3A-NBH-1991</i>				
505-AVIONICS, Mx	1999M.9.50	5093720	12/12/2016	11/21/2017
<i>Description: Procure and Install 50HZ Converter P/N 4C3500-3A-NBH-1991</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: A1 <i>Description: A1 Check</i>	Drawing: N/A	12/12/2016		06/06/2018
505-AVIONICS, Mx <i>Description: 33 010-00-02: OPERATIONAL CHECK EMERGENCY LIGHTS</i>	1999M.1A.50 5093721	12/12/2016	02/23/2017	02/23/2017
80-Maintenance <i>Description: 32 010-01-01: CLEAN LEFT MAIN LANDING GEAR ASSEMBLY SHOCK STRUT</i>	1999M.1A.80 5093722	12/12/2016	03/23/2017	03/23/2017
80-1-Maintenance <i>Description: 32 010-02-01: CLEAN RIGHT MAIN LANDING GEAR ASSEMBLY SHOCK STRUT</i>	1999M.1A.80-1 5093723	12/12/2016	03/23/2017	03/23/2017
80-2-Maintenance <i>Description: 32 030-01-01: LUBRICATE LEFT MAIN LANDING GEAR ASSEMBLY</i>	1999M.1A.80-2 5093724	12/12/2016	03/23/2017	03/23/2017
80-3-Maintenance <i>Description: 32 030-02-01: LUBRICATE RIGHT MAIN LANDING GEAR ASSEMBLY</i>	1999M.1A.80-3 5093725	12/12/2016	03/23/2017	03/23/2017
80-4-Maintenance <i>Description: 32 060-00-01: CLEAN NOSE LANDING GEAR SHOCK STRUT</i>	1999M.1A.80-4 5093726	12/12/2016	03/23/2017	03/23/2017
80-5-Maintenance <i>Description: 32 080-00-01: LUBRICATE NOSE LANDING GEAR ASSEMBLY</i>	1999M.1A.80-5 5093727	12/12/2016	03/23/2017	03/23/2017
80-6-Maintenance <i>Description: 32 270-01-01: VISUAL CHECK LEFT BRAKE WEAR PINS FOR MINIMUM EXTENSION</i>	1999M.1A.80-6 5093728	12/12/2016	02/23/2017	02/23/2017
80-7-Maintenance <i>Description: 32 270-02-01: VISUAL CHECK RIGHT BRAKE WEAR PINS FOR MINIMUM EXTENSION</i>	1999M.1A.80-7 5093729	12/12/2016	02/23/2017	02/23/2017
80-8-Maintenance <i>Description: 32 800-00-01: EXTERNAL ZONAL INSPECTION (GV) NOSE LANDING GEAR AND LANDING GEAR DOORS (EZAP)</i>	1999M.1A.80-8 5093730	12/12/2016	03/13/2017	03/13/2017
80-9-Maintenance <i>Description: 32 804-01-01: EXTERNAL ZONAL INSPECTION (GV) LEFT MAIN LANDING GEAR AND LANDING GEAR DOORS</i>	1999M.1A.80-9 5093731	12/12/2016	03/13/2017	03/13/2017
80-10-Maintenance <i>Description: 32 808-02-01: EXTERNAL ZONAL INSPECTION (GV) RIGHT MAIN LANDING GEAR AND LANDING GEAR DOORS</i>	1999M.1A.80-10 5093732	12/12/2016	03/13/2017	03/13/2017
80-11-Maintenance <i>Description: 33 090-00-01: GENERAL VISUAL INSPECTION OF THE TRANSPARENT FAIRING LENS LOCATED ON THE FORWARD LEADING E...</i>	1999M.1A.80-11 5093733	12/12/2016	03/23/2017	03/23/2017
80-12-Maintenance <i>Description: 53 800-00-01: EXTERNAL ZONAL INSPECTION (GV) LOWER FUSELAGE (EZAP)</i>	1999M.1A.80-12 5093734	12/12/2016	04/03/2017	04/03/2017
80-13-Maintenance <i>Description: 53 812-00-01: INTERNAL ZONAL INSPECTION (GV) FORWARD CARGO COMPARTMENT - SECTION 43, STATION 396 TO FORW...</i>	1999M.1A.80-13 5093735	12/12/2016	03/16/2017	03/16/2017
80-14-Maintenance <i>Description: 53 830-00-01: INTERNAL ZONAL INSPECTION (GV) AFT CARGO COMPARTMENT - SECTION 46 AND 47 (PART), STATION 7...</i>	1999M.1A.80-14 5093736	12/12/2016	03/16/2017	03/16/2017
80-15-Maintenance <i>Description: 53 844-00-01: EXTERNAL ZONAL INSPECTION (GV) WING TO BODY FAIRING</i>	1999M.1A.80-15 5093737	12/12/2016	02/23/2017	02/23/2017
80-16-Maintenance	1999M.1A.80-16 5093738	12/12/2016	02/23/2017	02/23/2017



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 53 894-00-01: EXTERNAL ZONAL INSPECTION (GV) FUSELAGE</i>				
80-17-Maintenance	1999M.1A.80-17	5093739	12/12/2016	03/02/2017 03/02/2017
<i>Description: 55 800-00-01: EXTERNAL ZONAL INSPECTION (GV) VERTICAL FIN AND HORIZONTAL STABILIZER</i>				
80-18-Maintenance	1999M.1A.80-18	5093740	12/12/2016	04/03/2017 04/03/2017
<i>Description: 57 802-01-01: EXTERNAL ZONAL INSPECTION (GV) LEFT WING</i>				
80-19-Maintenance	1999M.1A.80-19	5093741	12/12/2016	04/03/2017 04/03/2017
<i>Description: 57 872-02-01: EXTERNAL ZONAL INSPECTION (GV) RIGHT WING</i>				
80-20-Maintenance	1999M.1A.80-20	5093742	12/12/2016	03/23/2017 03/23/2017
<i>Description: 57 950-01-01: EXTERNAL ZONAL INSPECTION LEFT WINGLET</i>				
80-21-Maintenance	1999M.1A.80-21	5093743	12/12/2016	04/03/2017 04/03/2017
<i>Description: 57 960-02-01: EXTERNAL ZONAL INSPECTION RIGHT WINGLET</i>				
80-22-Maintenance	1999M.1A.80-22	5093744	12/12/2016	03/07/2017 03/07/2017
<i>Description: 70 800-01-01: EXTERNAL ZONAL INSPECTION (GV) NO. 1 ENGINE AND STRUT FAIRINGS</i>				
80-23-Maintenance	1999M.1A.80-23	5093745	12/12/2016	02/28/2017 02/28/2017
<i>Description: 70 810-02-01: EXTERNAL ZONAL INSPECTION (GV) NO. 2 ENGINE AND STRUT FAIRINGS</i>				
80-24-Maintenance	1999M.1A.80-24	5093746	12/12/2016	06/05/2018 06/06/2018
<i>Description: 050011: A1 Check Completed</i>				
80-25-Maintenance	1999M.1A.80-25	5093747	12/12/2016	02/23/2017 02/23/2017
<i>Description: 267002: GENERAL VISUAL INSPECTION OF SMOKE DETECTOR ANNUNCIATION FOR GENERAL CONDITION, OPERATIONAL CHECK ANNUNCIATOR PANEL AND OPERATIONAL CHECK LAVATORY AND GALLEY IONIZATION TYPE DETECTORS.</i>				
Count: 27			27	27
Task Card: A1.50.NR-1				
		Drawing: N/A	01/02/2018	01/10/2018
<i>Description: DURING TEST OF EMERGENCY LIGHTS MANY LIGHTS THROUGHOUT AIRCRAFT FAILED. LH & RH OVERWING & CABIN FLOOR EMER LIGHTS.</i>				
505-26-AVIONICS, Mx	1999M.A1.50.NR-1.505-26	5096676	01/02/2018	01/09/2018 01/10/2018
<i>Description: DURING TEST OF EMERGENCY LIGHTS MANY LIGHTS THROUGHOUT AIRCRAFT FAILED. LH & RH OVERWING & CABIN FLOOR EMER LIGHTS.</i>				
Count: 1			1	1
Task Card: A1.80-10.NR-1				
		Drawing: N/A	03/16/2017	10/19/2017
<i>Description: R/H MLG I/B DOOR SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
80-31-Maintenance	1999M.A1.80-10.NR-1.80-31	5097221	03/16/2017	05/11/2017 10/19/2017
<i>Description: R/H MLG I/B DOOR SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: A1.80-10.NR-2 Drawing: N/A 03/16/2017 05/11/2017 <i>Description: R/H MLG CENTER DOOR, FWD AND AFT SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
80-32-Maintenance	1999M.A1.80-10.NR-2.80-32	5097223	03/16/2017	05/11/2017
<i>Description: R/H MLG CENTER DOOR, FWD AND AFT SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
Count: 1			1	1
Task Card: A1.80-10.NR-3 Drawing: N/A 03/16/2017 04/05/2017 <i>Description: R/H MLG MAIN INNER LOWER STRUT, CHROME AREA HAS VERY DIRTY AND STICK SURFACE.</i>				
80-33-Maintenance	1999M.A1.80-10.NR-3.80-33	5097227	03/16/2017	04/05/2017
<i>Description: R/H MLG MAIN INNER LOWER STRUT, CHROME AREA HAS VERY DIRTY AND STICK SURFACE.</i>				
Count: 1			1	1
Task Card: A1.80-10.NR-4 Drawing: N/A 03/16/2017 04/25/2017 <i>Description: R/H MLG O/B, CENTER, AND I/B DOORS HAVE CORRODED BONDING WIRES (GREEN THROUGH OUT).</i>				
80-34-Maintenance	1999M.A1.80-10.NR-4.80-34	5097228	03/16/2017	04/25/2017
<i>Description: R/H MLG O/B, CENTER, AND I/B DOORS HAVE CORRODED BONDING WIRES (GREEN THROUGH OUT).</i>				
Count: 1			1	1
Task Card: A1.80-10.NR-5 Drawing: N/A 03/16/2017 04/18/2017 <i>Description: R/H MLG MAIN STRUT I/B UP LOCK ROLLER AND ATTACH BOLT ARE RUSTY AND CORRODED.</i>				
80-35-Maintenance	1999M.A1.80-10.NR-5.80-35	5097229	03/16/2017	04/18/2017
<i>Description: R/H MLG MAIN STRUT I/B UP LOCK ROLLER AND ATTACH BOLT ARE RUSTY AND CORRODED.</i>				
Count: 1			1	1
Task Card: A1.80-10.NR-6 Drawing: N/A 03/16/2017 04/11/2017 <i>Description: R/H MLG MAIN STRUT UPPER AFT TRUNION AREA LARGE SUPPORT CLAMP ON HYD LINE BRACKET HAS MIGRATING RUBBER SEAL.</i>				
80-36-Maintenance	1999M.A1.80-10.NR-6.80-36	5097230	03/16/2017	04/11/2017
<i>Description: R/H MLG MAIN STRUT UPPER AFT TRUNION AREA LARGE SUPPORT CLAMP ON HYD LINE BRACKET HAS MIGRATING RUBBER SEAL.</i>				
Count: 1			1	1
Task Card: A1.80-15.NR-1 Drawing: N/A 03/16/2017 01/10/2018 <i>Description: LARGE AREA OF PAINT MISSING IN RIGHT HAND ACM INLET.</i>				
80-28-Maintenance	1999M.A1.80-15.NR-1.80-28	5096695	03/16/2017	01/10/2018
<i>Description: LARGE AREA OF PAINT MISSING IN RIGHT HAND ACM INLET.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: A1.80-16.NR-1	Drawing: N/A	03/16/2017		01/10/2018	
<i>Description: BARE ALUMINIUM SKIN/PAINT & PRIMER MISSING AFT FS 1016 AFT PRESSURE BULKHEAD BOTTOM SKIN.</i>					
80-27-Maintenance	1999M.A1.80-16.NR-1.80-27	5096686	03/16/2017	01/10/2018	01/10/2018
<i>Description: BARE ALUMINIUM SKIN/PAINT & PRIMER MISSING AFT FS 1016 AFT PRESSURE BULKHEAD BOTTOM SKIN.</i>					
Count: 1			1		1
Task Card: A1.80-20.NR-1	Drawing: N/A	03/16/2017		01/11/2018	
<i>Description: L/H WINGLET UPPER SURFACE SKIN HAS AREAS OF CHIPPED PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS (GRAPHITE).</i>					
80-48-Maintenance	1999M.A1.80-20.NR-1.80-48	5097311	03/16/2017	01/10/2018	01/11/2018
<i>Description: L/H WINGLET UPPER SURFACE SKIN HAS AREAS OF CHIPPED PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS (GRAPHITE).</i>					
Count: 1			1		1
Task Card: A1.80-20.NR-2	Drawing: N/A	03/16/2017		08/06/2018	
<i>Description: L/H WINGLET L/E NAV LIGHT LENS IS YELLOWING AND HAS SMALL CRACK ON UPPER SURFACE.</i>					
80-49-Maintenance	1999M.A1.80-20.NR-2.80-49	5097312	03/16/2017	07/25/2018	08/06/2018
<i>Description: L/H WINGLET L/E NAV LIGHT LENS IS YELLOWING AND HAS SMALL CRACK ON UPPER SURFACE.</i>					
Count: 1			1		1
Task Card: A1.80-20.NR-3	Drawing: N/A	03/23/2017		01/11/2018	
<i>Description: L/H WINGLET UPPER SURFACE SKIN HAS AREAS OF CHIPPED PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS (GRAPHITE).</i>					
80-50-Maintenance	1999M.A1.80-20.NR-3.80-50	5097634	03/23/2017	01/10/2018	01/11/2018
<i>Description: L/H WINGLET UPPER SURFACE SKIN HAS AREAS OF CHIPPED PROTECTIVE COATING WITH AREAS OF EXPOSED FIBERS (GRAPHITE).</i>					
Count: 1			1		1
Task Card: A1.80-20.NR-4	Drawing: N/A	03/23/2017		04/04/2017	
<i>Description: L/H WINGLET L/E NAV LIGHT LENS IS YELLOWING AND HAS SMALL CRACK ON UPPER SURFACE.</i>					
80-51-Maintenance	1999M.A1.80-20.NR-4.80-51	5097635	03/23/2017	04/04/2017	04/04/2017
<i>Description: L/H WINGLET L/E NAV LIGHT LENS IS YELLOWING AND HAS SMALL CRACK ON UPPER SURFACE.</i>					
Count: 1			1		1
Task Card: A1.80-23.NR-1	Drawing: N/A	03/16/2017		01/02/2018	
<i>Description: #2 T/R NACELL IS PITTED AND CORRODED AROUND POLISHED AREA.</i>					
80-29-Maintenance	1999M.A1.80-23.NR-1.80-29	5096699	03/16/2017	12/22/2017	01/02/2018
<i>Description: #2 T/R NACELL IS PITTED AND CORRODED AROUND POLISHED AREA.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: A1.80-23.NR-2		Drawing: N/A		03/16/2017	03/28/2018
<i>Description: #2 AFT LOWER PYLON TRAILING EDGE IS MISSING PAINT AND CORRODED.</i>					
80-30-Maintenance	1999M.A1.80-23.NR-2.80-30	5096700	03/16/2017	03/27/2018	03/28/2018
<i>Description: #2 AFT LOWER PYLON TRAILING EDGE IS MISSING PAINT AND CORRODED.</i>					
Count: 1			1		1
Task Card: A1.80-3.NR-1		Drawing: N/A		03/23/2017	04/13/2017
<i>Description: GREASE ZERK MISSING FROM R/H WHEEL WELL AFT WING ATTACH FITTING.</i>					
80-52-Maintenance	1999M.A1.80-3.NR-1.80-52	5097662	03/23/2017	04/13/2017	04/13/2017
<i>Description: GREASE ZERK MISSING FROM R/H WHEEL WELL AFT WING ATTACH FITTING.</i>					
Count: 1			1		1
Task Card: A1.80-8.NR-1		Drawing: N/A		03/16/2017	01/10/2018
<i>Description: L/H AND R/H NLG DOORS, INNER SKIN SURFACES AT FWD AND REAR UP STOP PADS HAVE BARE EXPOSED GRAPHITE AROUND PADS.</i>					
80-42-Maintenance	1999M.A1.80-8.NR-1.80-42	5097241	03/16/2017	01/10/2018	01/10/2018
<i>Description: L/H AND R/H NLG DOORS, INNER SKIN SURFACES AT FWD AND REAR UP STOP PADS HAVE BARE EXPOSED GRAPHITE AROUND PADS.</i>					
Count: 1			1		1
Task Card: A1.80-8.NR-2		Drawing: N/A		03/16/2017	04/05/2017
<i>Description: NLG STRUT UPPER FWD SIDE HAS A DETERIORATED ADEL CLAMP FOR A HYRDAULIC LINE.</i>					
80-43-Maintenance	1999M.A1.80-8.NR-2.80-43	5097242	03/16/2017	04/05/2017	04/05/2017
<i>Description: NLG STRUT UPPER FWD SIDE HAS A DETERIORATED ADEL CLAMP FOR A HYRDAULIC LINE.</i>					
Count: 1			1		1
Task Card: A1.80-8.NR-3		Drawing: N/A		03/16/2017	
<i>Description: NLG STRUT, AT LOWER FWD SIDE HAS AREAS OF MISSING PROTECTIVE COATING (PAINT) WITH AREAS OF BARE METAL EXPOSED.</i>					
80-44-Maintenance	1999M.A1.80-8.NR-3.80-44	5097243	03/16/2017	01/10/2018	01/10/2018
<i>Description: NLG STRUT, AT LOWER FWD SIDE HAS AREAS OF MISSING PROTECTIVE COATING (PAINT) WITH AREAS OF BARE METAL EXPOSED.</i>					
Count: 1			1		1
Task Card: A1.80-8.NR-4		Drawing: N/A		03/16/2017	
<i>Description: L/H AND R/H NLG STEERING ACTUATORS HAVE EVIDENCE OF HYDRAULIC LEAKS.</i>					
80-45-Maintenance	1999M.A1.80-8.NR-4.80-45	5097244	03/16/2017	05/05/2017	05/05/2017
<i>Description: L/H AND R/H NLG STEERING ACTUATORS HAVE EVIDENCE OF HYDRAULIC LEAKS.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: A1.80-8.NR-5		Drawing: N/A		03/16/2017
<i>Description: NLG WHEEL WELL, AFT PRESSURE BULKHEAD FWD SIDE IN R/H CORNER AREA HAS EVIDENCE OF HYDRAULIC LINES LEAKING AT HYDRAULIC SWIVELS.</i>				
80-46-Maintenance	1999M.A1.80-8.NR-5.80-46	5097245	03/16/2017	05/08/2017 05/08/2017
<i>Description: NLG WHEEL WELL, AFT PRESSURE BULKHEAD FWD SIDE IN R/H CORNER AREA HAS EVIDENCE OF HYDRAULIC LINES LEAKING AT HYDRAULIC SWIVELS.</i>				
Count: 1			1	1
Task Card: A1.80-8.NR-6		Drawing: N/A		03/16/2017
<i>Description: L/H AND R/H NLG TIRES HAVE EVIDENCE OF WEATHER CRACKING IN TIRE TREADS.</i>				
80-47-Maintenance	1999M.A1.80-8.NR-6.80-47	5097246	03/16/2017	04/18/2017 04/18/2017
<i>Description: L/H AND R/H NLG TIRES HAVE EVIDENCE OF WEATHER CRACKING IN TIRE TREADS.</i>				
Count: 1			1	1
Task Card: A1.80-9.NR-1		Drawing: N/A		03/16/2017
<i>Description: L/H MLG MAIN STRUT I/B UP LOCK ROLLER AND ATTACH BOLT ARE RUSTY AND CORRODED.</i>				
80-37-Maintenance	1999M.A1.80-9.NR-1.80-37	5097231	03/16/2017	04/18/2017 04/18/2017
<i>Description: L/H MLG MAIN STRUT I/B UP LOCK ROLLER AND ATTACH BOLT ARE RUSTY AND CORRODED.</i>				
Count: 1			1	1
Task Card: A1.80-9.NR-2		Drawing: N/A		03/16/2017
<i>Description: L/H MLG O/B, CENTER AND I/B DOORS HAVE CORRODED BONDING WIRE.</i>				
80-38-Maintenance	1999M.A1.80-9.NR-2.80-38	5097232	03/16/2017	04/25/2017 04/25/2017
<i>Description: L/H MLG O/B, CENTER AND I/B DOORS HAVE CORRODED BONDING WIRE.</i>				
Count: 1			1	1
Task Card: A1.80-9.NR-3		Drawing: N/A		03/16/2017
<i>Description: L/H MLG MAIN LOWER STRUT CHROME AREA IS STICKY AND DIRTY.</i>				
80-39-Maintenance	1999M.A1.80-9.NR-3.80-39	5097233	03/16/2017	04/05/2017 04/05/2017
<i>Description: L/H MLG MAIN LOWER STRUT CHROME AREA IS STICKY AND DIRTY.</i>				
Count: 1			1	1
Task Card: A1.80-9.NR-4		Drawing: N/A		03/16/2017
<i>Description: L/H MLG CENTER DOOR FWD AND AFT SUPPORT RODS AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
80-40-Maintenance	1999M.A1.80-9.NR-4.80-40	5097239	03/16/2017	05/11/2017 05/11/2017
<i>Description: L/H MLG CENTER DOOR FWD AND AFT SUPPORT RODS AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: A1.80-9.NR-5	Drawing: N/A	03/16/2017		05/11/2017	
<i>Description: L/H MLG I/B DOOR, SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>					
80-41-Maintenance	1999M.A1.80-9.NR-5.80-41	5097240	03/16/2017	05/11/2017	05/11/2017
<i>Description: L/H MLG I/B DOOR, SUPPORT ROD AND ROD END BEARINGS ARE RUSTY AND CORRODED.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-1		Drawing: N/A		10/26/2016
<i>Description: Preservation Maintenance Costs</i>				
801-Maintenance	1999M.AWR-1.801	5092735	10/26/2016	
<i>Description: Time and Materials required for placing the aircraft in to preservation storage while awaiting the materials and components necessary for the accomplishment of heavy maintenance check.</i>				
801-1-Maintenance	1999M.AWR-1.801-1	5092736	10/26/2016	01/10/2017 01/10/2017
<i>Description: PERFORM APU PRESERVATION IAW 49-11-00-600-802</i>				
801-2-Maintenance	1999M.AWR-1.801-2	5092737	10/26/2016	01/10/2017 01/10/2017
<i>Description: PERFORM ENGINE #1 PRESERVATION IAW 71-00-03-600-802-F00</i>				
801-3-Maintenance	1999M.AWR-1.801-3	5092738	10/26/2016	01/10/2017 04/07/2017
<i>Description: PERFORM ENGINE #1 PRESERVATION IAW 71-00-03-600-802-F00</i>				
801-4-Maintenance	1999M.AWR-1.801-4	5094471	12/29/2016	01/10/2017 01/10/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED</i>				
801-5-Maintenance	1999M.AWR-1.801-5	5094472	12/29/2016	01/12/2017 01/12/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED</i>				
801-6-Maintenance	1999M.AWR-1.801-6	5094473	12/29/2016	01/23/2017 01/23/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED</i>				
801-7-Maintenance	1999M.AWR-1.801-7	5094474	12/29/2016	01/27/2017 01/27/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED</i>				
801-8-Maintenance	1999M.AWR-1.801-8	5095860	01/31/2017	02/03/2017 02/03/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED DUE 1FEB17.</i>				
801-9-Maintenance	1999M.AWR-1.801-9	5095861	01/31/2017	02/09/2017 02/09/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED DUE 8FEB17.</i>				
801-10-Maintenance	1999M.AWR-1.801-10	5095862	01/31/2017	02/16/2017 02/16/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED DUE 15FEB17.</i>				
801-11-Maintenance	1999M.AWR-1.801-11	5095863	01/31/2017	04/13/2017 04/13/2017
<i>Description: APPLY POWER AND CYCLE AIRCRAFT SYSTEMS AS REQUIRED DUE 22FEB17.</i>				
801-12-Maintenance	1999M.AWR-1.801-12	5096308	02/17/2017	02/28/2017 02/28/2017
<i>Description: PERFORM APU DEPRESERVATION IAW 49-11-00-600-804.</i>				
801-13-Maintenance	1999M.AWR-1.801-13	5098893	05/09/2017	07/01/2017 07/01/2017
<i>Description: Accomplish Depreservation of an Engine #1, which was Preserved from One Month to Not More Than One Year (Engine On Wing) IAW 71-00-03-600-813-F00.</i>				
801-14-Maintenance	1999M.AWR-1.801-14	5098894	05/09/2017	07/01/2017 07/01/2017
<i>Description: Accomplish Depreservation of an Engine #2, which was Preserved from One Month to Not More Than One Year (Engine On Wing) IAW 71-00-03-600-813-F00.</i>				
801-15-Maintenance	1999M.AWR-1.801-15	5098895	05/09/2017	07/01/2017 07/01/2017
<i>Description: Accomplish APU Depreservation IAW 49-11-00-600-804.</i>				
801-16-Maintenance	1999M.AWR-1.801-16	5100860	07/28/2017	08/10/2017 08/11/2017
<i>Description: TASK 71-00-03-600-807-F00 Preservation Renewal of an Engine for Not More Than One Month (Engine on Wing)</i>				
801-17-Maintenance	1999M.AWR-1.801-17	5101885	08/30/2017	08/31/2017 10/19/2017
<i>Description: PERFORM Preservation-Renewal of an Engine for Not More Than One Month (Engine on Wing) TASK 71-00-03-600-807-F00 ON ENGINE #1 & ENGINE #2.</i>				



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
801-18-Maintenance <i>Description: PERFORM ENGINE #1 PRESERVATION FOR NOT MORE THAN THREE MONTHS IAW 71-00-03-600-809-F00</i>	1999M.AWR-1.801-18	5103575	10/25/2017	11/20/2017 11/21/2017
801-19-Maintenance <i>Description: PERFORM ENGINE #2 PRESERVATION FOR NOT MORE THAN THREE MONTHS IAW 71-00-03-600-809-F00</i>	1999M.AWR-1.801-19	5103576	10/25/2017	11/20/2017 11/21/2017
801-20-Maintenance <i>Description: PERFORM APU PRESERVATION IAW 49-11-00-600-802</i>	1999M.AWR-1.801-20	5103577	10/25/2017	11/20/2017 11/21/2017
801-22-Maintenance <i>Description: Preservation plastic is blowing off engine inlets with aircraft parked outside.</i>	1999M.AWR-1.801-22	5106197	12/15/2017	01/11/2018 01/11/2018
Count: 22			22	21
Task Card: AWR-1.801.NR-1 <i>Description: During engine runs noted that batteries were indicated a discharge.</i>		Drawing: N/A	11/07/2017	01/12/2018
801-21-Maintenance <i>Description: During engine runs noted that batteries were indicated a discharge.</i>	1999M.AWR-1.801.NR-1.801-2 1	5103654	11/07/2017	01/11/2018 01/12/2018
Count: 1			1	1
Task Card: AWR-1.801-16.NR-1 <i>Description: APU BLEED AIR VALVE SHUT OFF DURING ENGINE RUN AND WOULD NOT RESET.</i>		Drawing: N/A	08/29/2017	
801-17-Maintenance <i>Description: APU BLEED AIR VALVE SHUT OFF DURING ENGINE RUN AND WOULD NOT RESET.</i>	1999M.AWR-1.801-16.NR-1.801-17	5101196	08/29/2017	
Count: 1			1	0
Task Card: AWR-1.801-3.NR-1 <i>Description: APU, GENERATOR OIL FILTER BYPASS INDICATOR COMING APART.</i>		Drawing: N/A	03/16/2017	04/18/2017
801-13-Maintenance <i>Description: APU, GENERATOR OIL FILTER BYPASS INDICATOR COMING APART.</i>	1999M.AWR-1.801-3.NR-1.801-13	5096688	03/16/2017	04/18/2017 04/18/2017
Count: 1			1	1
Task Card: AWR-1.801-3.NR-2 <i>Description: BIRD FEATHERS AND RESIDUE IN APU OIL COOLER AND AIR EXHAUST DUCT.</i>		Drawing: N/A	03/16/2017	04/04/2017
801-14-Maintenance <i>Description: BIRD FEATHERS AND RESIDUE IN APU OIL COOLER AND AIR EXHAUST DUCT.</i>	1999M.AWR-1.801-3.NR-2.801-14	5096689	03/16/2017	04/04/2017 04/04/2017
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-10		Drawing: N/A		11/13/2017
<i>Description: Add workscope from CAMO till Jan 2018</i>				
207-INTERIOR INSTALL, AWR	1999M.AWR-10.207	5105027	11/13/2017	01/09/2018 01/10/2018
<i>Description: MODIFY AND RE-IDENTIFY EACH AFFECTED CABIN ATTENDANT SEAT- EASA 2016-0163</i>				
207-1-INTERIOR INSTALL, AWR	1999M.AWR-10.207-1	5105028	11/13/2017	01/09/2018 01/10/2018
<i>Description: REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION- EASA 2016-0167</i>				
207-2-INTERIOR INSTALL, AWR	1999M.AWR-10.207-2	5105029	11/13/2017	01/11/2018 01/12/2018
<i>Description: *DETAILED INSPECTION OF GALLEYS ATTACH BRACKETS, TIE-RODS, FITTINGS AND HARDWARE. GENERAL VISUAL INSPECTION OF LATCHES, HINGES AND GENERAL CONDITION WITH UNITS REMOVED" - 539108</i>				
507-AVIONICS, AWR	1999M.AWR-10.507	5105030	11/13/2017	01/04/2018 01/05/2018
<i>Description: REPLACE EACH AUTO-THROTTLE COMPUTER WITH A UNIT THAT HAS THE NEW SOFTWARE INSTALLED (FOR AEROPLANES THAT HAVE A GE AVIATION SYSTEMS LLC AUTO-THROTTLE COMPUTER INSTALLED)-EASA 2014-0093 R1</i>				
507-1-AVIONICS, AWR	1999M.AWR-10.507-1	5105031	11/13/2017	01/04/2018 01/05/2018
<i>Description: *AUTO FLIGHT - REMOVE ANY AUTOTHROTTLE COMPUTER, PART NUMBER (P/N) 760SUE1-1, 760SUE2-2, 760SUE2-3, OR 760SUE2-4 & INSTALL A NEW OR REWORKED AUTOTHROTTLE COMPUTER, P/N 760SUE2-5 AT THE E1-1 ELECTRONICS SHELF."- FAA 2014-16-14</i>				
507-2-AVIONICS, AWR	1999M.AWR-10.507-2	5105032	11/13/2017	01/12/2018 01/16/2018
<i>Description: REVIEW CENTER TANK FUEL BOOST PUMP AUTOMATIC SHUTOFF SYSTEM - 28-AWL-19</i>				
507-3-AVIONICS, AWR	1999M.AWR-10.507-3	5105033	11/13/2017	01/04/2018 01/05/2018
<i>Description: FUNCTIONALLY TEST CENTER TANK FUEL BOOST PUMP POWER FAILED ON PROTECTION SYSTEM. - 28-AWL-23</i>				
507-4-AVIONICS, AWR	1999M.AWR-10.507-4	5105034	11/13/2017	01/09/2018 01/10/2018
<i>Description: UPGRADE EGPWS SOFTWARE- 34-046-01S</i>				
507-5-AVIONICS, AWR	1999M.AWR-10.507-5	5105035	11/13/2017	01/11/2018 01/12/2018
<i>Description: UPDATE NAV DATABASE- 347101</i>				
507-6-AVIONICS, AWR	1999M.AWR-10.507-6	5105036	11/13/2017	01/04/2018 01/05/2018
<i>Description: AUTOFLIGHT - AUTOTHROTTLE SYSTEM - AUTOTHROTTLE COMPUTER REPLACEMENT, ALERT SERVICE BULLETIN- ASB 737-22A1215</i>				
507-7-AVIONICS, AWR	1999M.AWR-10.507-7	5105037	11/13/2017	06/01/2018 06/04/2018
<i>Description: CORROSION PROTECTION OF THE ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL - FAA 2005-18-23</i>				
807-MAINTENANCE, AWR	1999M.AWR-10.807	5105038	11/13/2017	01/12/2018 01/16/2018
<i>Description: RESTORE MAIN BATTERY- 24-120-00 (001.1)</i>				
807-1-MAINTENANCE, AWR	1999M.AWR-10.807-1	5105039	11/13/2017	01/12/2018 01/16/2018
<i>Description: RESTORE AUXILIARY BATTERY- 24-120-00 (002.1)</i>				
807-2-MAINTENANCE, AWR	1999M.AWR-10.807-2	5105040	11/13/2017	01/04/2018 01/05/2018
<i>Description: *RESTORE FORWARD ENTRY ESCAPE SLIDE AT THE MANUFACTURER'S RECOMMENDED INTERVAL."- 25-240-00 (001.1)</i>				
807-3-MAINTENANCE, AWR	1999M.AWR-10.807-3	5105041	11/13/2017	11/22/2017 11/22/2017
<i>Description: WEIGHT CHECK FORWARD LAVATORY FIRE EXTINGUISHER- 26-290-00 (001.1)</i>				
807-4-MAINTENANCE, AWR	1999M.AWR-10.807-4	5105042	11/13/2017	01/09/2018 01/10/2018



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: *DETAILED INSPECTION (COCKPIT) PORTABLE HALON EXTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION* - 26-450-00 (001.1)</i>				
807-5-MAINTENANCE, AWR	1999M.AWR-10.807-5	5105043	11/13/2017	01/09/2018 01/10/2018
<i>Description: *DETAILED INSPECTION AFT GALLEY CABINET PORTABLE HALON XTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION.* - 26-450-00 (002.1)</i>				
807-6-MAINTENANCE, AWR	1999M.AWR-10.807-6	5105044	11/13/2017	01/09/2018 01/10/2018
<i>Description: *DETAILED INSPECTION FWD ENTRY DOOR PORTABLE HALON EXTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION.* - 26-450-00 (003.1)</i>				
807-7-MAINTENANCE, AWR	1999M.AWR-10.807-7	5105045	11/13/2017	01/09/2018 01/10/2018
<i>Description: INSPECT (DETAILED) THE PORTABLE WATER FIRE EXTINGUISHERS CONDITION. (IF INSTALLED).- 26-470-00</i>				
807-8-MAINTENANCE, AWR	1999M.AWR-10.807-8	5105046	11/13/2017	01/04/2018 01/05/2018
<i>Description: *HYDROSTATIC TEST PORTABLE WATER FIRE EXTINGUISHER (OFF AIRCRAFT , IF INSTALLED)* - 26-481-00 (002.1)</i>				
807-9-MAINTENANCE, AWR	1999M.AWR-10.807-9	5105047	11/13/2017	01/09/2018 01/10/2018
<i>Description: *OPERATIONAL CHECK STANDBY RUDDER SYSTEM TO INCLUDE OBSERVING LOW PRESSURE LIGHT ILLUMINATION AND THEN EXTINGUISHING.* - 29-230-00</i>				
807-10-MAINTENANCE, AWR	1999M.AWR-10.807-10	5105048	11/13/2017	01/09/2018 01/10/2018
<i>Description: FUNCTIONAL CHECK LANDING GEAR CONTROL CABLE TENSION - 323106</i>				
807-11-MAINTENANCE, AWR	1999M.AWR-10.807-11	5105049	11/13/2017	01/09/2018 01/10/2018
<i>Description: HYDROSTATIC TEST CREW OXYGEN CYLINDER- 35-031-00 (001.1)</i>				
807-12-MAINTENANCE, AWR	1999M.AWR-10.807-12	5105050	11/13/2017	01/09/2018 01/10/2018
<i>Description: HYDROSTATIC TEST RIGHT SIDE PASSENGER OXYGEN BOTTLE- 350451 (001.1)</i>				
807-13-MAINTENANCE, AWR	1999M.AWR-10.807-13	5105051	11/13/2017	01/09/2018 01/10/2018
<i>Description: HYDROSTATIC TEST LEFT SIDE PASSENGER OXYGEN BOTTLE- 350451 (002.1)</i>				
807-14-MAINTENANCE, AWR	1999M.AWR-10.807-14	5105052	11/13/2017	
<i>Description: ENGINES COMPRESSOR WASH - 72-00-00</i>				
807-15-MAINTENANCE, AWR	1999M.AWR-10.807-15	5105053	11/13/2017	01/04/2018 01/05/2018
<i>Description: ASSOCIATED AIR CENTER - PASSENGER OXYGEN SYSTEM - LEAK CHECK, SERVICE BULLETIN- SB 9737B3503</i>				
807-16-MAINTENANCE, AWR	1999M.AWR-10.807-16	5105054	11/13/2017	11/20/2017 11/21/2017
<i>Description: FUNCTIONALLY CHECK THE LEFT ENGINE FORWARD STRUT AND AFT STRUT FAIRING DRAINS.- 54-090-01</i>				
807-17-MAINTENANCE, AWR	1999M.AWR-10.807-17	5105055	11/13/2017	11/20/2017 11/21/2017
<i>Description: FUNCTIONALLY CHECK THE RIGHT ENGINE FORWARD STRUT AND AFT STRUT FAIRING DRAINS.- 54-090-02</i>				
807-18-MAINTENANCE, AWR	1999M.AWR-10.807-18	5105056	11/13/2017	01/04/2018 01/05/2018
<i>Description: *DETAILED INSPECTION TO PREVENT AN UNDETECTED FAILURE OF THE PRIMARY LOAD PATH FOR THE BALLSCREW IN THE DRIVE MECHANISM OF THE HSTA AND SUBSEQUENT WEAR AND FAILURE OF THE SECONDARY LOAD PATH IN ACCORDANCE WITH SERVICE BULETIN 737-27A1277 R2" - "FAA 2011-27-03 PARA (G)(1)(I)(1)"</i>				
807-19-MAINTENANCE, AWR	1999M.AWR-10.807-19	5105057	11/13/2017	06/06/2018 06/07/2018
<i>Description: *DETAILED VISUAL INSPECTION OF THE STABILIZER TRIM JACKSCREW, BALLNUT, BALLNUT RETURN TUBES AND THE UPPER AND LOWER GIMBALL PINS.* - 27-110-00</i>				
807-20-MAINTENANCE, AWR	1999M.AWR-10.807-20	5105058	11/13/2017	01/09/2018 01/10/2018



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: "TO PREVENT FAILURE OF THE DRAIN TUBE ASSEMBLIES AND CLAMPS ON THE AFT FAIRINGS OF THE ENGINE STRUTS" - FAA 2012-23-08</i>				
807-21-MAINTENANCE, AWR <i>Description: 25-290-00 (001.1) RESTORE #1 COCKPIT LIFE JACKET</i>	1999M.AWR-10.807-21	5105059	11/13/2017	03/22/2018 03/27/2018
807-22-MAINTENANCE, AWR <i>Description: 25-290-00 (002.1) RESTORE #2 COCKPIT LIFE JACKET</i>	1999M.AWR-10.807-22	5105060	11/13/2017	03/22/2018 03/27/2018
807-23-MAINTENANCE, AWR <i>Description: 25-290-00 (003.1) RESTORE #3 COCKPIT LIFE JACKET</i>	1999M.AWR-10.807-23	5105061	11/13/2017	03/22/2018 03/27/2018
807-24-MAINTENANCE, AWR <i>Description: 25-290-00 (004.1) RESTORE #4 COCKPIT LIFE JACKET</i>	1999M.AWR-10.807-24	5105062	11/13/2017	03/22/2018 03/27/2018
807-25-MAINTENANCE, AWR <i>Description: 25-290-00 (009.1) RESTORE #1 AFT ATTENDANT SEAT LIFE JACKET</i>	1999M.AWR-10.807-25	5105063	11/13/2017	03/22/2018 03/27/2018
807-26-MAINTENANCE, AWR <i>Description: 25-290-00 (010.1) RESTORE #2 AFT ATTENDANT SEAT LIFE JACKET</i>	1999M.AWR-10.807-26	5105064	11/13/2017	06/20/2018 06/21/2018
807-27-MAINTENANCE, AWR <i>Description: 25-290-00 (011.1) RESTORE FWD CABIN R/H DIVAN #1 LIFE JACKET</i>	1999M.AWR-10.807-27	5105065	11/13/2017	03/22/2018 03/27/2018
807-28-MAINTENANCE, AWR <i>Description: 25-290-00 (012.1) RESTORE FWD CABIN R/H DIVAN #2 LIFE JACKET</i>	1999M.AWR-10.807-28	5105066	11/13/2017	03/22/2018 03/27/2018
807-29-MAINTENANCE, AWR <i>Description: 25-290-00 (013.1) RESTORE FWD CABIN R/H DIVAN #3 LIFE JACKET</i>	1999M.AWR-10.807-29	5105067	11/13/2017	03/22/2018 03/27/2018
807-30-MAINTENANCE, AWR <i>Description: 25-290-00 (014.1) RESTORE FWD CABIN MAIN SEATS #1 LIFE JACKET</i>	1999M.AWR-10.807-30	5105068	11/13/2017	03/22/2018 03/27/2018
807-31-MAINTENANCE, AWR <i>Description: 25-290-00 (015.1) RESTORE FWD CABIN MAIN SEATS #2 LIFE JACKET</i>	1999M.AWR-10.807-31	5105069	11/13/2017	03/22/2018 03/27/2018
807-32-MAINTENANCE, AWR <i>Description: 25-290-00 (016.1) RESTORE FWD CABIN MAIN SEATS #3 LIFE JACKET</i>	1999M.AWR-10.807-32	5105070	11/13/2017	03/22/2018 03/27/2018
807-33-MAINTENANCE, AWR <i>Description: 25-290-00 (017.1) RESTORE FWD CABIN MAIN SEATS #4 LIFE JACKET</i>	1999M.AWR-10.807-33	5105071	11/13/2017	03/22/2018 03/27/2018
807-34-MAINTENANCE, AWR <i>Description: 25-290-00 (018.1) RESTORE FWD CABIN MAIN SEATS #5 LIFE JACKET</i>	1999M.AWR-10.807-34	5105072	11/13/2017	03/22/2018 03/27/2018
807-35-MAINTENANCE, AWR <i>Description: 25-290-00 (019.1) RESTORE FWD CABIN MAIN SEATS #6 LIFE JACKET</i>	1999M.AWR-10.807-35	5105073	11/13/2017	03/22/2018 03/27/2018
807-36-MAINTENANCE, AWR <i>Description: 25-290-00 (020.1) RESTORE FWD CABIN MAIN SEATS #7 LIFE JACKET</i>	1999M.AWR-10.807-36	5105074	11/13/2017	03/22/2018 03/27/2018
807-37-MAINTENANCE, AWR <i>Description: 25-290-00 (021.1) RESTORE FWD CABIN MAIN SEATS #8 LIFE JACKET</i>	1999M.AWR-10.807-37	5105075	11/13/2017	03/22/2018 03/27/2018
807-38-MAINTENANCE, AWR <i>Description: 25-290-00 (022.1) RESTORE FWD CABIN MAIN SEATS #9 LIFE JACKET</i>	1999M.AWR-10.807-38	5105076	11/13/2017	03/22/2018 03/27/2018
907-QC, AWR	1999M.AWR-10.907	5105077	11/13/2017	01/05/2018 01/08/2018



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: *CHECK RECORDS TO DETERMINE IF AN AFFECTED HORIZONTAL STABILIZER IS INSTALLED AND IF ANY HORIZONTAL STABILIZER HAS BEEN EXCHANGED, AND ACCOMPLISH ALL APPLICABLE RELATED INVESTIGATIVE ACTIONS AND ACCOMPLISH INSPECTION OF THE HORIZONTAL STABILIZER IDENTIFICATION PLATE TO DETERMINE IF ANY AFFECTED HORIZONTAL STABILIZER IS INSTALLED" - "FAA 2016-13-16 PARA (G) (1)"</i>				
907-1-QC, AWR	1999M.AWR-10.907-1	5105078	11/13/2017	01/05/2018 01/08/2018
<i>Description: *HIGH FREQUENCY EDDY CURRENT INSPECTION FOR ANY CRACK OF THE HORIZONTAL STABILIZER REAR SPAR UPPER CHORD AND APPLICABLE CORRECTIVE ACTIONS (IF, DURING ANY ACTION REQUIRED BY PARA (G)(1)(I) OR (G)(1)(II) ANY AFFECTED HORIZONTAL STABILIZER IS FOUND)"- "FAA 2016-13-16 PARA (G)(2)"</i>				
801-2-Maintenance	1999M.AWR-10.801-2	5105079	11/21/2017	11/22/2017 11/22/2017
<i>Description: *PERFORM EXTERNAL GENERAL VISUAL INSPECTION OF SKIN PANEL FROM BS 259 TO 360 BETWEEN S-14L AND S-24L" - 53-010-00 FRR (009-1)</i>				
507-65-AVIONICS, AWR	1999M.AWR-10.507-65	5105305	12/09/2017	12/09/2017 12/09/2017
<i>Description: MASTER BEDROOM BED HEADREST HAVE SCRATCHES</i>				
507-66-AVIONICS, AWR	1999M.AWR-10.507-66	5105306	12/09/2017	12/09/2017 12/09/2017
<i>Description: MASTER BEDROOM OUTBOARD LAMP COVER HAVE DENT</i>				
507-67-AVIONICS, AWR	1999M.AWR-10.507-67	5105307	12/09/2017	12/09/2017 12/09/2017
<i>Description: HALLWAY LONGITUD BLKH DECO PANEL HAVE LUMP (BUBBLE)</i>				
507-68-AVIONICS, AWR	1999M.AWR-10.507-68	5105308	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM DOOR MOULDING HAVE SCRATCHES AFT AND FWD</i>				
507-69-AVIONICS, AWR	1999M.AWR-10.507-69	5105309	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM DOOR FACE SIDE HAVE MAJOR SCRATCH</i>				
507-70-AVIONICS, AWR	1999M.AWR-10.507-70	5105310	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM HEADLINER DIRTY (ALL) AND HAVE LEATHER CUT</i>				
507-71-AVIONICS, AWR	1999M.AWR-10.507-71	5105311	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM UNEVEN HEADLINER PANEL</i>				
507-72-AVIONICS, AWR	1999M.AWR-10.507-72	5105312	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM FWD L/H HEADLINER PANEL BOWED IN THE FWD SIDE</i>				
507-73-AVIONICS, AWR	1999M.AWR-10.507-73	5105313	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV DOOR SCRATCHES & SCRAPES ON EDGE OF DOOR & GUEST ROOM SIDE</i>				
507-74-AVIONICS, AWR	1999M.AWR-10.507-74	5105314	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV SHOWER TOE KICK UNEVEN</i>				
507-75-AVIONICS, AWR	1999M.AWR-10.507-75	5105315	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV RUG SHORT BY SHOWER AREA</i>				
507-76-AVIONICS, AWR	1999M.AWR-10.507-76	5105316	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV VANITY LOWER CLOSEOUT LOOSE</i>				
507-77-AVIONICS, AWR	1999M.AWR-10.507-77	5105317	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV VANITY COUNTERTOP O/B EDGE CHIPPED</i>				
507-78-AVIONICS, AWR	1999M.AWR-10.507-78	5105318	12/09/2017	12/09/2017 12/09/2017
<i>Description: HEADLINERS ON GUEST ROOM LAV DIRTY & UNEVEN FROM SIDEWALL</i>				
507-79-AVIONICS, AWR	1999M.AWR-10.507-79	5105319	12/09/2017	12/09/2017 12/09/2017
<i>Description: GUEST ROOM LAV DOOR FRAME DIRTY & SCRATCHED</i>				
507-80-AVIONICS, AWR	1999M.AWR-10.507-80	5105320	12/09/2017	12/09/2017 12/09/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> GUEST ROOM O/B FWD COMPARTMENT DOOR UNEVEN				
507-81-AVIONICS, AWR	1999M.AWR-10.507-81	5105321	12/09/2017	12/09/2017
<i>Description:</i> GUEST ROOM SCRATCH ON FWD DECO O/B				
507-82-AVIONICS, AWR	1999M.AWR-10.507-82	5105322	12/09/2017	12/09/2017
<i>Description:</i> GUEST ROOM FWD WALL TOE KICK SCRATCHED				
507-83-AVIONICS, AWR	1999M.AWR-10.507-83	5105323	12/09/2017	12/09/2017
<i>Description:</i> GUEST ROOM LAV O/B MID COMPARTMENT DIFFICULTIES OPENING				
507-84-AVIONICS, AWR	1999M.AWR-10.507-84	5105324	12/09/2017	12/09/2017
<i>Description:</i> GUEST ROOM LAV TOILET LID LEATHER SCRATCHED				
507-85-AVIONICS, AWR	1999M.AWR-10.507-85	5105325	12/09/2017	12/09/2017
<i>Description:</i> GUEST ROOM LAV TOILET SHROUD CHIPPED & DAMAGED SHROUD TOP SIDE				
507-86-AVIONICS, AWR	1999M.AWR-10.507-86	5105326	12/09/2017	12/09/2017
<i>Description:</i> HALLWAY SIDELEDGE VARIOUS DOOR HAVE SCRATCHES ON TOP EDGE 7EA.				
507-87-AVIONICS, AWR	1999M.AWR-10.507-87	5105327	12/09/2017	12/09/2017
<i>Description:</i> HALLWAY SIDEWALL #2 HAVE LEATHER CUT, DIRTY AND UNEVEN				
507-88-AVIONICS, AWR	1999M.AWR-10.507-88	5105328	12/09/2017	12/09/2017
<i>Description:</i> HALLWAY WINDOW LENS HAVE SCRATCHES 7EA.				
507-89-AVIONICS, AWR	1999M.AWR-10.507-89	5105329	12/09/2017	12/09/2017
<i>Description:</i> HALLWAY SIDELEDGE TOP HAVE SCRATCHES AND CHIPPED				
507-90-AVIONICS, AWR	1999M.AWR-10.507-90	5105330	12/12/2017	12/12/2017
<i>Description:</i> FWD HALLWAY LONGITUD BLKH HAVE SCRATCHES AND DENT				
507-91-AVIONICS, AWR	1999M.AWR-10.507-91	5105331	12/12/2017	12/12/2017
<i>Description:</i> HALLWAY #1 SIDEWALL HAVE UNEVEN WITH DINING ROOM HEADLINER AND THE FWD SIDEWALL				
507-92-AVIONICS, AWR	1999M.AWR-10.507-92	5105332	12/12/2017	12/12/2017
<i>Description:</i> HALLWAY VALANCE PANEL #1 HAVE LEATHER CUT AND UNEVEN				
507-93-AVIONICS, AWR	1999M.AWR-10.507-93	5105333	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM ALL CEILING PANEL UNEVEN AND DIRTY LEATHER CUT				
507-94-AVIONICS, AWR	1999M.AWR-10.507-94	5105334	12/12/2017	12/12/2017
<i>Description:</i> AFT BLKH DINING ROOM (ROUND) HAVE SCRATCHES				
507-95-AVIONICS, AWR	1999M.AWR-10.507-95	5105335	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM AFT CENTER SECT HAVE SCRATCHES IN THE I/B ARMREST AND SHROUD COVER LOOSE (NO VELCRO)				
507-96-AVIONICS, AWR	1999M.AWR-10.507-96	5105336	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM FWD CENTER SEAT SHROUD COVER LOOSE (VELCRO LOOSE)				
507-97-AVIONICS, AWR	1999M.AWR-10.507-97	5105337	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM AFT R/H SEAT SHROUD COVER LOOSE (VELCOR LOOSE)				
507-98-AVIONICS, AWR	1999M.AWR-10.507-98	5105338	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM AFT R/H SEAT SHROUD COVER LOOSE (VELCOR LOOSE)				
507-99-AVIONICS, AWR	1999M.AWR-10.507-99	5105339	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM TABLE LEATHER HAVE SCRATCHES				
507-100-AVIONICS, AWR	1999M.AWR-10.507-100	5105340	12/12/2017	12/12/2017
<i>Description:</i> DINING ROOM FWD SIDE CARPET HAVE STAIN				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
507-101-AVIONICS, AWR <i>Description: DINING ROOM L/H EMERGENCY EXIT WINDOW SHADE IS BROKE (MANUAL) AND WINDOW LENS HAVE SCRATCH</i>	1999M.AWR-10.507-101	5105341		12/12/2017	12/12/2017
507-102-AVIONICS, AWR <i>Description: DINING ROOM R/H EMERGENCY EXIT WINDOW SHADE HAVE SCRATCH</i>	1999M.AWR-10.507-102	5105342		12/12/2017	12/12/2017
507-103-AVIONICS, AWR <i>Description: DINING ROOM R/H EMERGENCY EXIT AFT SURROUND HAVE SCRATCH LEATHER</i>	1999M.AWR-10.507-103	5105343		12/12/2017	12/12/2017
507-104-AVIONICS, AWR <i>Description: DINING ROOM R/H EMERGENCY EXIT BOTTOM PULL COVER HAVE CRACK MULTIPLE AREA AND FINISH BROKEN</i>	1999M.AWR-10.507-104	5105344		12/12/2017	12/12/2017
507-105-AVIONICS, AWR <i>Description: CONFERENCE ROOM/DINING ROOM #6 WINDOW HAVE SCRATCH AND PAINT INSIDE THE WINDOW PEELING</i>	1999M.AWR-10.507-105	5105345		12/12/2017	12/12/2017
507-106-AVIONICS, AWR <i>Description: DINING ROOM L/H #1 SIDEWALL LEATHER CUT</i>	1999M.AWR-10.507-106	5105346		12/12/2017	12/12/2017
507-107-AVIONICS, AWR <i>Description: CONFERENCE ROOM L/H SIDELEDGE HAVE INLAY LOOSE AND CHIPPED ALL AROUND AND CRACK</i>	1999M.AWR-10.507-107	5105347		12/12/2017	12/12/2017
507-108-AVIONICS, AWR <i>Description: CONFERENCE ROOM L/H SIDELEDGE AFT DOOR HAVE SCRATCH</i>	1999M.AWR-10.507-108	5105348		12/12/2017	12/12/2017
507-109-AVIONICS, AWR <i>Description: CONFERENCE ROOM L/H SIDELEDGE DECO PANEL HAVE SCRATCHES</i>	1999M.AWR-10.507-109	5105349		12/12/2017	12/12/2017
507-110-AVIONICS, AWR <i>Description: CONFERENCE ROOM L/H WINDOW LENS #1, 2, 4 & 5 HAVE SCRATCHES</i>	1999M.AWR-10.507-110	5105350		12/12/2017	12/12/2017
507-111-AVIONICS, AWR <i>Description: CONFERENCE ROOM CENTER DIVIDED WALL HAVE SCRATCHES</i>	1999M.AWR-10.507-111	5105351		12/12/2017	12/12/2017
507-112-AVIONICS, AWR <i>Description: CONFERENCE ROOM ALL HEADLINER PANEL HAVE SCRATCH, CUT AND DIRTY</i>	1999M.AWR-10.507-112	5105352		12/12/2017	12/12/2017
507-113-AVIONICS, AWR <i>Description: CONFERENCE ROOM L/H #1 SIDEWALL HAVE LEATHER CUT</i>	1999M.AWR-10.507-113	5105353		12/12/2017	12/12/2017
807-39-MAINTENANCE, AWR <i>Description: 25-290-00 (023.1) RESTORE FWD CABIN L/H DIVAN #1 LIFE JACKET</i>	1999M.AWR-10.807-39	5106620	01/03/2018	06/20/2018	06/21/2018
807-40-MAINTENANCE, AWR <i>Description: 25-290-00 (024.1) RESTORE FWD CABIN L/H DIVAN #2 LIFE JACKET</i>	1999M.AWR-10.807-40	5106621	01/03/2018	06/20/2018	06/21/2018
807-41-MAINTENANCE, AWR <i>Description: 25-290-00 (025.1) RESTORE FWD CABIN L/H DIVAN #3 LIFE JACKET</i>	1999M.AWR-10.807-41	5106622	01/03/2018	03/22/2018	03/27/2018
807-42-MAINTENANCE, AWR <i>Description: 25-290-00 (026.1) RESTORE AFT CABIN L/H DIVAN #1 LIFE JACKET</i>	1999M.AWR-10.807-42	5106623	01/03/2018	03/22/2018	03/27/2018
807-43-MAINTENANCE, AWR <i>Description: 25-290-00 (027.1) RESTORE AFT CABIN L/H DIVAN #2 LIFE JACKET</i>	1999M.AWR-10.807-43	5106624	01/03/2018	03/22/2018	03/27/2018
807-44-MAINTENANCE, AWR <i>Description: 25-290-00 (028.1) RESTORE AFT CABIN L/H DIVAN #3 LIFE JACKET</i>	1999M.AWR-10.807-44	5106625	01/03/2018	03/22/2018	03/27/2018
807-45-MAINTENANCE, AWR	1999M.AWR-10.807-45	5106626	01/03/2018	03/22/2018	03/27/2018



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 25-290-00 (029.1) RESTORE AFT CABIN MAIN SEATS #1 LIFE JACKET</i>				
807-46-MAINTENANCE, AWR	1999M.AWR-10.807-46	5106627	01/03/2018	06/20/2018 06/21/2018
<i>Description: 25-290-00 (030.1) RESTORE AFT CABIN MAIN SEATS #2 LIFE JACKET</i>				
807-47-MAINTENANCE, AWR	1999M.AWR-10.807-47	5106628	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (031.1) RESTORE AFT CABIN MAIN SEATS #3 LIFE JACKET</i>				
807-48-MAINTENANCE, AWR	1999M.AWR-10.807-48	5106629	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (032.1) RESTORE AFT CABIN MAIN SEATS #4 LIFE JACKET</i>				
807-49-MAINTENANCE, AWR	1999M.AWR-10.807-49	5106630	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (033.1) RESTORE AFT CABIN MAIN SEATS #5 LIFE JACKET</i>				
807-50-MAINTENANCE, AWR	1999M.AWR-10.807-50	5106631	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (034.1) RESTORE AFT CABIN MAIN SEATS #6 LIFE JACKET</i>				
807-51-MAINTENANCE, AWR	1999M.AWR-10.807-51	5106632	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (035.1) RESTORE AFT CABIN MAIN SEATS #7 LIFE JACKET</i>				
807-52-MAINTENANCE, AWR	1999M.AWR-10.807-52	5106633	01/03/2018	03/22/2018 03/27/2018
<i>Description: 25-290-00 (036.1) RESTORE AFT CABIN MAIN SEATS #8 LIFE JACKET</i>				
807-53-MAINTENANCE, AWR	1999M.AWR-10.807-53	5106655	01/04/2018	03/21/2018 03/22/2018
<i>Description: 25-300-00 (001.1) RESTORE MID AREA LIFE RAFT</i>				
807-54-MAINTENANCE, AWR	1999M.AWR-10.807-54	5106656	01/04/2018	03/21/2018 03/22/2018
<i>Description: 25-300-00 (002.1) RESTORE FORWARD ENTRY LIFE RAFT</i>				
807-55-MAINTENANCE, AWR	1999M.AWR-10.807-55	5106657	01/04/2018	03/21/2018 03/22/2018
<i>Description: 25-300-00 (003.1) RESTORE AFT CLUB AREA LIFE RAFT</i>				
807-56-MAINTENANCE, AWR	1999M.AWR-10.807-56	5106658	01/04/2018	03/21/2018 03/22/2018
<i>Description: 25-300-00 (004.1) RESTORE MID AREA LIFE RAFT</i>				
807-57-MAINTENANCE, AWR	1999M.AWR-10.807-57	5106659	01/04/2018	03/26/2018 03/27/2018
<i>Description: 25-390-00 REPLACE THE EMERGENCY FLASHLIGHT (NON-RECHARGEABLE) BATTERIES AT THE MANUFACTURER'S RECOMMENDED INTERVAL.</i>				
807-58-MAINTENANCE, AWR	1999M.AWR-10.807-58	5106660	01/04/2018	03/26/2018 03/27/2018
<i>Description: 25-410-00 (001.1) RESTORE COCKPIT (PBE) SMOKE HOOD</i>				
807-59-MAINTENANCE, AWR	1999M.AWR-10.807-59	5106661	01/04/2018	06/22/2018 06/25/2018
<i>Description: 25-410-00 (002.1) RESTORE FWD (PBE) SMOKE HOOD</i>				
807-60-MAINTENANCE, AWR	1999M.AWR-10.807-60	5106662	01/04/2018	01/04/2018 01/05/2018
<i>Description: 25-420-00 (001.1) RESTORE FWD FIRST AID KIT</i>				
807-61-MAINTENANCE, AWR	1999M.AWR-10.807-61	5106663	01/04/2018	01/04/2018 01/05/2018
<i>Description: 25-420-00 (002.1) RESTORE AFT FIRST AID KIT</i>				
807-62-MAINTENANCE, AWR	1999M.AWR-10.807-62	5106664	01/04/2018	01/09/2018 01/10/2018
<i>Description: 25-430-00 (001.1) RESTORE MEDICAL KIT</i>				
Count: 126			102	125



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-10.507-2.NR-1		Drawing: N/A		01/08/2018
<i>Description: Master Caution lights do not illuminate as required during test of center tank fuel boost pump automatic shutoff system.</i>				
505-116-AVIONICS, Mx	1999M.AWR-10.507-2.NR-1.50 5-116	5106688	01/08/2018	
<i>Description: Master Caution lights do not illuminate as required during test of center tank fuel boost pump automatic shutoff system.</i>				
Count: 1		1		0
Task Card: AWR-10.807-11.NR-1		Drawing: N/A		12/29/2017
<i>Description: Found Capt O2 mask box has broken door.</i>				
807-114-MAINTENANCE, AWR	1999M.AWR-10.807-11.NR-1.8 07-114	5106535	12/29/2017	04/13/2018 04/16/2018
<i>Description: Found Capt O2 mask box has broken door.</i>				
Count: 1		1		1
Task Card: AWR-10.807-18.NR-1		Drawing: N/A		01/04/2018
<i>Description: Corrosion was found on the horizontal stab trim actuator jack screw.</i>				
801-115-Maintenance	1999M.AWR-10.807-18.NR-1.8 01-115	5106595	01/04/2018	01/04/2018 01/05/2018
<i>Description: Corrosion was found on the horizontal stab trim actuator jack screw.</i>				
Count: 1		1		1
Task Card: AWR-10.807-21.NR-1		Drawing: N/A		11/20/2017
<i>Description: During removal of life vests, found 21 undocumented life vests. All removed life vest (41 total) have serviceable due dates expired.</i>				
805-63-Mx Interiors	1999M.AWR-10.807-21.NR-1.8 05-63	5105175	11/20/2017	08/10/2018 08/10/2018
<i>Description: During removal of life vests, found 21 undocumented life vests. All removed life vest (41 total) have serviceable due dates expired.</i>				
Count: 1		1		1
Task Card: AWR-11		Drawing: AWR-11		
<i>Description: Aircraft Parking and Storage Charges 30 day rotations charges of \$10,500 per 30 days</i>				
250-PMO2 Risk		0		
<i>Description: Aircraft Parking and Storage Charges</i>				
Count: 1		0		0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-12		Drawing: AWR-12		
<i>Description:</i> Due to serviceable right antenna not being available, design and perform procedures to deactivate the Satcom system before next flight				
250-PMO2 Risk	0			
<i>Description:</i> Risk				
507-AVIONICS, AWR	1999M.AWR-12.507	5105999	12/01/2017	01/11/2018 01/12/2018
<i>Description:</i> cap and stow wiring to deactivate Satcom system				
607-SHEET METAL SHOP, AWR	1999M.AWR-12.607	5106000	12/01/2017	01/09/2018 01/10/2018
<i>Description:</i> Fabricate external doubler as cover plate and install				
Count: 3		2		2
Task Card: AWR-13		Drawing: N/A		03/12/2018 03/16/2018
<i>Description:</i> Engine pressurization 3/8/2018				
807-MAINTENANCE, AWR	1999M.AWR-13.807	5109467	03/12/2018	03/15/2018 03/16/2018
<i>Description:</i> Engine pressurization 3/8/2018 IAW 71-00-03-600-809-F00				
Count: 1		1		1
Task Card: AWR-14		Drawing: AWR-14		
<i>Description:</i> Master tank evaluation and storage at Aloft AeroArchitects				
800-2-ADMIN,MAINTENANCE	0			
<i>Description:</i> Master tank storage at Aloft AeroArchitects from April 23, 2018 till June 27, 2018				
800-3-ADMIN,MAINTENANCE	0			
<i>Description:</i> Master tank storage at Aloft AeroArchitects from June 25, 2018 till July 25, 2018				
800-ADMIN,MAINTENANCE	0			
<i>Description:</i> Master tank evaluation at Aloft AeroArchitects				
Count: 3		0		0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-15		Drawing: AWR-15		
<i>Description: Added work tasks from revised due list dated 06-Jun-2018</i>				
180-MX Planning / Scheduling	0			
<i>Description: 89.01</i>				
507-1-AVIONICS, AWR	1999M.AWR-15.507-1	5112363	06/28/2018	07/23/2018 07/24/2018
<i>Description: FAA 2016-07-16 PARA (G)(1)- "GENERAL VISUAL INSPECTION OF THE ORIENTATION OF THE COIL CORD CONNECTOR KEYWAYS ON THE CAPTAIN'S AND FIRST OFFICER'S SIDES OF THE FLIGHT COMPARTMENT AND TURN THE RECEPTACLE CONNECTOR TO THE CORRECT POSITION, IF THE ORIENTATION IS NOT AT THE SPECIFIED POSITION (A/C GROUP 1, CONFIGURATION 1) (RESTATEMENT OF PARA (G)(1) OF FAA AD 2013-26-08)"</i>				
507-2-AVIONICS, AWR	1999M.AWR-15.507-2	5112364	06/28/2018	07/23/2018 07/24/2018
<i>Description: "FAA 2016-07-16 PARA (G)(2)-REPLACE THE COIL CORDS WITH NEW COIL CORDS ON BOTH SIDES OF THE FLIGHT DECK (A/C GROUP 1, CONFIGURATION 1) (RESTATEMENT OF PARA (G)(2) OF FAA AD 2013-26-08)"</i>				
507-3-AVIONICS, AWR	1999M.AWR-15.507-3	5112365	06/28/2018	07/03/2018 07/10/2018
<i>Description: FAA 2017-04-06- APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016"</i>				
507-4-AVIONICS, AWR	1999M.AWR-15.507-4	5112366	06/28/2018	07/03/2018 07/10/2018
<i>Description: FAA 2018-03-04 PARA (G)-DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED</i>				
507-5-AVIONICS, AWR	1999M.AWR-15.507-5	5112367	06/28/2018	07/05/2018 07/10/2018
<i>Description: 23-050-00-FUNCTIONAL CHECK OF THE VOICE RECORDER FOR AUDIO FIDELITY</i>				
507-6-AVIONICS, AWR	1999M.AWR-15.507-6	5112368	06/28/2018	07/06/2018 07/10/2018
<i>Description: 33-020-00:OPERATIONAL CHECK FLIGHT DECK EMERGENCY LIGHTING SWITCH "ON" AND "ARMED" POSITION AND ATTENDANT PANEL EMERGENCY LIGHTING SWITCH "ON" POSITION.</i>				
507-7-AVIONICS, AWR	1999M.AWR-15.507-7	5112369	06/28/2018	07/06/2018 07/10/2018
<i>Description: 33-060-00-RESTORE EMERGENCY LIGHTING BATTERY PACK (TWO OR MORE COMPLETE DEEP CYCLES) BATTERY CAPACITY TO REQUIRED STANDARD</i>				
507-8-AVIONICS, AWR	1999M.AWR-15.507-8	5112370	06/28/2018	07/10/2018 07/11/2018
<i>Description: 34-010-00-FUNCTIONAL LEAK CHECK OF THE CAPTAIN'S PITOT SYSTEM .(NOTE: TASK MEETS INTENT OF FAR 91.411)</i>				
507-9-AVIONICS, AWR	1999M.AWR-15.507-9	5112371	06/28/2018	07/10/2018 07/11/2018
<i>Description: 34-020-00-FUNCTIONAL LEAK CHECK OF THE FIRST OFFICER'S PITOT SYSTEM . (TASK MEETS INTENT OF FAR 91.411)</i>				
507-10-AVIONICS, AWR	1999M.AWR-15.507-10	5112372	06/28/2018	07/11/2018 07/12/2018
<i>Description: 34-030-00-FUNCTIONAL LEAK CHECK OF THE STANDBY PITOT SYSTEM . (TASK MEETS INTENT OF FAR 91.411)</i>				
507-11-AVIONICS, AWR	1999M.AWR-15.507-11	5112373	06/28/2018	07/10/2018 07/11/2018
<i>Description: 34-040-00-FUNCTIONAL LEAK CHECK OF THE CAPTAIN'S STATIC SYSTEM . (TASK MEETS INTENT OF FAR 91.411)</i>				
507-12-AVIONICS, AWR	1999M.AWR-15.507-12	5112374	06/28/2018	07/10/2018 07/11/2018
<i>Description: 34-050-00-FUNCTIONAL LEAK CHECK OF THE FIRST OFFICER'S STATIC SYSTEM . (TASK MEETS INTENT OF FAR 91.411)</i>				
507-13-AVIONICS, AWR	1999M.AWR-15.507-13	5112375	06/28/2018	07/10/2018 07/11/2018
<i>Description: 34-060-00-FUNCTIONAL LEAK CHECK OF THE STANDBY STATIC SYSTEM . (TASK MEETS INTENT OF FAR 91.411)</i>				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
507-14-AVIONICS, AWR	1999M.AWR-15.507-14	5112376	06/28/2018	08/17/2018	
<i>Description: Avionics access for required tasks- avionics MX</i>					
805-Mx Interiors	1999M.AWR-15.805	5112377	06/28/2018	07/23/2018	07/24/2018
<i>Description: *FAA 2017-18-12 PARA (I)-INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M*</i>					
805-1-Mx Interiors	1999M.AWR-15.805-1	5112378	06/28/2018	07/19/2018	07/20/2018
<i>Description: 25-370-00:VISUALLY CHECK ALL DETACHABLE EMERGENCY EQUIPMENT (GLOVES, SMOKE GOGGLES, CRASH AXE, FLASH LIGHTS, FIRST AID KITS, AND MEDICAL KITS, AS APPLICABLE) FOR CONDITION AND PRESENCE.</i>					
805-2-Mx Interiors	1999M.AWR-15.805-2	5112379	06/28/2018	07/19/2018	07/20/2018
<i>Description: 25-400-00: INSPECT (DETAILED) THE SMOKE HOODS FOR CONDITION</i>					
805-3-Mx Interiors	1999M.AWR-15.805-3	5112380	06/28/2018	08/21/2018	08/23/2018
<i>Description: 257019: CLEAN/REPLACE ENTERTAINMENT CABINET AND SATCOM EQUIPMENT RACK FLAME ARRESTORS*</i>					
805-4-Mx Interiors	1999M.AWR-15.805-4	5112381	06/28/2018	08/21/2018	08/23/2018
<i>Description: 257020-CLEAN ENTERTAINMENT EQUIPMENT COOLING FANS</i>					
805-5-Mx Interiors	1999M.AWR-15.805-5	5112382	06/28/2018		
<i>Description: 25-240-00 (003.1):RESTORE AFT ENTRY ESCAPE SLIDE AT THE MANUFACTURER'S RECOMMENDED INTERVAL.</i>					
805-6-Mx Interiors	1999M.AWR-15.805-6	5112383	06/28/2018	07/19/2018	07/20/2018
<i>Description: 26-290-00 (002.1): WEIGHT CHECK VIP LAVATORY FIRE EXTINGUISHER</i>					
805-7-Mx Interiors	1999M.AWR-15.805-7	5112384	06/28/2018	07/19/2018	07/20/2018
<i>Description: 26-290-00 (003.1):WEIGHT CHECK PASSENGER LAVATORY FIRE EXTINGUISHER</i>					
805-8-Mx Interiors	1999M.AWR-15.805-8	5112385	06/28/2018	08/03/2018	08/03/2018
<i>Description: 26-481-00 (003.1): HYDROSTATIC TEST AFT CABIN PORTABLE WATER EXTINGUISHER</i>					
805-9-Mx Interiors	1999M.AWR-15.805-9	5112386	06/28/2018		
<i>Description: Cabin access for required tasks- interior MX</i>					
807-MAINTENANCE, AWR	1999M.AWR-15.807	5112387	06/28/2018		
<i>Description: *FAA 2004-05-19 PARA (D): INSPECT REAR SPAR ATTACH PINS AND FRONT SPAR ATTACH BOLTS (AD 2013-07-07 AFFECTS CERTAIN REQUIREMENTS OF THIS AD) REPLACED</i>					
807-1-MAINTENANCE, AWR	1999M.AWR-15.807-1	5112388	06/28/2018	07/09/2018	07/10/2018
<i>Description: FAA 2006-21-01 PART 2- FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - REPETITIVE LUBRICATION</i>					
807-2-MAINTENANCE, AWR	1999M.AWR-15.807-2	5112389	06/28/2018		
<i>Description: FAA 2013-06-05 PARA (U) (1)-*REPLACE REPLACING THE LEFT AND RIGHT ELEVATOR TAB CONTROL MECHANISMS WITH ELEVATOR TAB CONTROL MECHANISMS THAT HAVE THE MODIFIED ATTACH LUGS THE LEFT AND RIGHT ELEVATOR TAB CONTROL MECHANISMS WITH ELEVATOR TAB CONTROL MECHANISMS THAT HAVE NEW MACHINED AFT ATTACH LUGS, FOR AIRPLANES HAVING LINE NUMBERS 1 THROUGH 3909 INCLUSIVE.</i>					
807-3-MAINTENANCE, AWR	1999M.AWR-15.807-3	5112390	06/28/2018	08/21/2018	08/23/2018
<i>Description: 50014: C/W A3 CHECK</i>					
807-4-MAINTENANCE, AWR	1999M.AWR-15.807-4	5112391	06/28/2018		
<i>Description: 81001:PERFORM WEIGHT CHECK OF AIRCRAFT</i>					
807-5-MAINTENANCE, AWR	1999M.AWR-15.807-5	5112392	06/28/2018		

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> 26-351-00 (001.1): HYDROSTATIC TEST LRD2 CARGO HALON FIRE EXTINGUISHER BOTTLE				
807-6-MAINTENANCE, AWR	1999M.AWR-15.807-6	5112393	06/28/2018	08/15/2018 08/16/2018
<i>Description:</i> 26-351-00 (002.1): HYDROSTATIC TEST LRD1 CARGO HALON FIRE EXTINGUISHER				
807-7-MAINTENANCE, AWR	1999M.AWR-15.807-7	5112394	06/28/2018	07/10/2018 07/11/2018
<i>Description:</i> 28-AWL-05 PATS: DETAILED INSPECTION OF THE BLEED AIR SOLENOID VALVE, DUAL CHECK VALVE, VENTURI AND PLUMBING FOR DETERIORATION, CORROSION, EVIDENCE OF OVERHEATING OR LEAKAGE. INSPECT IMMEDIATE SURROUNDING STRUCTURE FOR SIGNS OF HEAT DAMAGE AND/OR DISCOLORATION DUE TO HEAT DAMAGE.				
807-8-MAINTENANCE, AWR	1999M.AWR-15.807-8	5112395	06/28/2018	08/27/2018
<i>Description:</i> 28-AWL-01 PATS: DETAILED INSPECTION OF THE CRITICAL WIRE HARNESS SEPARATION, BRACKETS, CLAMPS, SHIELDING, SHIELDING TERMINATION POINTS, DIELECTRIC SLEEVING, AND ROUTING (EWIS)				
807-9-MAINTENANCE, AWR	1999M.AWR-15.807-9	5112396	06/28/2018	08/21/2018 08/22/2018
<i>Description:</i> 28-AWL-02 PATS: DETAILED INSPECTION OF ALL AFS COMPONENTS (INCLUDING VALVE PLATE, FILL/TRANSFER/VENT LINES) BONDING JUMPERS AND GROUNDING STUDS FOR MISSING OR DAMAGE HARDWARE, CORROSION, FRAYING OR LOOSE PHYSICAL CONNECTIONS				
807-10-MAINTENANCE, AWR	1999M.AWR-15.807-10	5112397	06/28/2018	08/21/2018 08/22/2018
<i>Description:</i> 28-AWL-03 PATS: DETAILED INSPECTION OF DRY BAY WIRING HARNESS ROUTING, CLAMPING, AND ATTACHING BRACKETS FOR CONTAMINATION BY FUEL OR FUEL VAPOR, PHYSICAL DAMAGE, CRACKING AND SECURITY. INSPECT DRY BAY VALVE ACTUATORS FOR SIGNS OF OVERHEATING, PHYSICAL DAMAGE, OR CRACKING. INSPECT DRY BAY DUAL REDUNDANT BONDING JUMPERS FOR CORROSION, MECHANICAL WEAR, FRAYING AND SECURITY (EWIS)				
807-11-MAINTENANCE, AWR	1999M.AWR-15.807-11	5112398	06/28/2018	08/22/2018 08/23/2018
<i>Description:</i> 28-00-02 PATS: INSPECT AFS ELECTRICAL COMPONENT CONNECTORS AND CABLES FOR CHAFFING, FRAYED LEADS, BENT PINS, CORROSION, CHAFFING AND CONDITION. REPAIR OR REPLACE IF REQUIRED				
807-12-MAINTENANCE, AWR	1999M.AWR-15.807-12	5112399	06/28/2018	
<i>Description:</i> 28-20-02-01 PATS: OPERATIONAL CHECK OF THE CENTER WING TANK FLOAT SWITCHES BY REMOVING FROM CENTER WING TANK (CWT) AND VERIFY OPERATION WITH OHMMETER (FS4/FS5 OR FS6/FS7)				
807-13-MAINTENANCE, AWR	1999M.AWR-15.807-13	5112400	06/28/2018	
<i>Description:</i> 28-AWL-06 PATS: *ATTACHING BRACKETS FOR PHYSICAL DAMAGE, CRACKING, AND SECURITY. (EWIS) INSPECT CENTER WING TANK FILL VALVE ACTUATORS FOR SIGNS OF OVERHEAT,PHYSICAL DAMAGE, OR CRACKING. INSPECT CENTER WING TANK UPPER AND LOWER FLOAT SWITCHES FOR SECURITY,PHYSICAL DAMAGE, CRACKING OR LEAKAGE. INSPECT CENTER WING TANK (AFS ASSOCIATED) DUAL REDUNDANT BONDING JUMPERS FOR CORROSION, MECHANICAL WEAR, FRAYING AND SECURITY. *				
807-14-MAINTENANCE, AWR	1999M.AWR-15.807-14	5112401	06/28/2018	08/21/2018 08/22/2018
<i>Description:</i> 28-AWL-04 PATS: FUNCTIONAL CHECK TO VERIFY THE 10 PSID DIFFERENTIAL PRESSURE RELIEF VALVE FREELY OPENS AND CLOSES RELATIVE TO AMBIENT PRESSURE.				
807-15-MAINTENANCE, AWR	1999M.AWR-15.807-15	5112402	06/28/2018	08/23/2018
<i>Description:</i> 28-00-01 PATS: PERFORM A GENERAL VISUAL INSPECTION OF AFS PLACARDS AND DECALS.				
807-16-MAINTENANCE, AWR	1999M.AWR-15.807-16	5112403	06/28/2018	08/21/2018 08/22/2018
<i>Description:</i> 28-20-02 PATS:OPERATIONAL CHECK (FS1,FS2,FS3,FS51, FS52,FS53) OF THE FLOAT SWITCHES BY REMOVING FROM MASTER CELL AND VERIFY OPERATION WITH OHMMETER.				
807-17-MAINTENANCE, AWR	1999M.AWR-15.807-17	5112404	06/28/2018	
<i>Description:</i> Exterior access for required tasks- MX				
907-QC, AWR	1999M.AWR-15.907	5112405	06/28/2018	08/22/2018
<i>Description:</i> EASA 2018-0109:NO. 1 ENGINE - ENGINE - FAN BLADES - INSPECTION				



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
907-1-QC, AWR <i>Description:</i> EASA 2018-0109:NO. 2 ENGINE - ENGINE - FAN BLADES - INSPECTION	1999M.AWR-15.907-1 5112406	06/28/2018	08/22/2018	08/23/2018
907-4-QC, AWR <i>Description:</i> FAA 2018-09-51-E NO. 1 ENGINE - EMERGENCY AD - ENGINE - FAN BLADE DOVETAIL - INSPECTION	1999M.AWR-15.907-4 5112407	06/28/2018	08/04/2018	08/06/2018
907-5-QC, AWR <i>Description:</i> FAA 2018-09-51-E NO. 2 ENGINE - EMERGENCY AD - ENGINE - FAN BLADE DOVETAIL - INSPECTION	1999M.AWR-15.907-5 5112408	06/28/2018	08/04/2018	08/06/2018
907-6-QC, AWR <i>Description:</i> "FAA 2018-10-11 PARA (G)" NO. 1 ENGINE - PERFORM AN ULTRASONIC INSPECTION (USI) OR EDDY CURRENT INSPECTION (ECI) OF THE CONCAVE AND CONVEX SIDES OF THE FAN BLADE DOVETAIL AND REPLACE THE FAN BLADE WITH A PART ELIGIBLE FOR INSTALLATION (IF ANY UNSERVICEABLE INDICATION IS FOUND DURING THE INSPECTIONS)	1999M.AWR-15.907-6 5112409	06/28/2018	08/22/2018	08/23/2018
907-7-QC, AWR <i>Description:</i> "FAA 2018-10-11 PARA (G)" NO. 2 ENGINE - PERFORM AN ULTRASONIC INSPECTION (USI) OR EDDY CURRENT INSPECTION (ECI) OF THE CONCAVE AND CONVEX SIDES OF THE FAN BLADE DOVETAIL AND REPLACE THE FAN BLADE WITH A PART ELIGIBLE FOR INSTALLATION (IF ANY UNSERVICEABLE INDICATION IS FOUND DURING THE INSPECTIONS)	1999M.AWR-15.907-7 5112410	06/28/2018	08/22/2018	08/23/2018
907-8-QC, AWR <i>Description:</i> EASA 2018-0109: NO. 1 ENGINE - ENGINE - FAN BLADES - INSPECTION	1999M.AWR-15.907-8 5112411	06/28/2018	08/06/2018	08/06/2018
907-9-QC, AWR <i>Description:</i> EASA 2018-0109: NO. 2 ENGINE - ENGINE - FAN BLADES - INSPECTION	1999M.AWR-15.907-9 5112412	06/28/2018	08/06/2018	08/06/2018
Count: 51		50		37
Task Card: AWR-15.507-6.NR-1				
<i>Description:</i> Several emergency lights including L9150, L9152, L9154, L/H overwing escape ground illumination light, and 3 hall aisle lights do not illuminate during 33-020-00 Operational check of emergency lighting.		Drawing: N/A	07/06/2018	07/24/2018
505-18-AVIONICS, Mx <i>Description:</i> Several emergency lights including L9150, L9152, L9154, L/H overwing escape ground illumination light, and 3 hall aisle lights do not illuminate during 33-020-00 Operational check of emergency lighting.	1999M.AWR-15.507-6.NR-1.50 5-18	5112645	07/06/2018	07/24/2018
Count: 1		1		1
Task Card: AWR-15.805-1.NR-1				
<i>Description:</i> FIRST OFFICER'S FLASHLIGHT BROKEN. REQUIRES REPLACEMENT.		Drawing: N/A	08/21/2018	
805-24-Mx Interiors <i>Description:</i> FIRST OFFICER'S FLASHLIGHT BROKEN. REQUIRES REPLACEMENT.	1999M.AWR-15.805-1.NR-1.80 5-24	5113121	08/21/2018	
Count: 1		1		0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-15.807-2.NR-1		Drawing: N/A		07/20/2018	
<i>Description:</i> Hardware on both left and right elevator attachment points and actuator attachment points corroded.(parts ordered against task card 5112389)					
801-22-Maintenance	1999M.AWR-15.807-2.NR-1.80 1-22	5113119	07/20/2018		
<i>Description:</i> Hardware on both left and right elevator attachment points and actuator attachment points corroded. (parts ordered against task card 5112389)					
Count: 1		1		0	
Task Card: AWR-15.807-2.NR-2		Drawing: N/A		07/20/2018	
<i>Description:</i> Both left and right elevator tab lock actuators wet with fluid.					
801-23-Maintenance	1999M.AWR-15.807-2.NR-2.80 1-23	5113120	07/20/2018		
<i>Description:</i> Both left and right elevator tab lock actuators wet with fluid.					
Count: 1		1		0	
Task Card: AWR-15.807-2.NR-3		Drawing: N/A		08/13/2018	
<i>Description:</i> Found RH lower access panel 343BB had damage at screw hole, when panel was to be [REDACTED] for reinstallation.					
801-25-Maintenance	1999M.AWR-15.807-2.NR-3.80 1-25	5114550	08/13/2018		
<i>Description:</i> Found RH lower access panel 343BB had damage at screw hole, when panel was to be [REDACTED] for reinstallation.					
Count: 1		1		0	
Task Card: AWR-15.807-8.NR-1		Drawing: N/A		07/11/2018	07/16/2018
<i>Description:</i> Found numerous areas of the Patts critical wire harness in the aft pit to be riding on frame rails.					
505-19-AVIONICS, Mx	1999M.AWR-15.807-8.NR-1.50 5-19	5112788	07/11/2018	07/13/2018	07/16/2018
<i>Description:</i> Found numerous areas of the Patts critical wire harness in the aft pit to be riding on frame rails.					
Count: 1		1			1
Task Card: AWR-15.807-8.NR-2		Drawing: N/A		07/11/2018	07/13/2018
<i>Description:</i> MAIN ELECTRONIC COMPARTMENT,AUXILIARY FUEL SYSTEM COMPUTER (AFSC) ,WIRE HARNESS BEHIND THE AFSC TOO CLOSE TO BASE/ AC STRUCTURE.					
505-20-AVIONICS, Mx	1999M.AWR-15.807-8.NR-2.50 5-20	5112792	07/11/2018	07/12/2018	07/13/2018
<i>Description:</i> MAIN ELECTRONIC COMPARTMENT,AUXILIARY FUEL SYSTEM COMPUTER (AFSC) ,WIRE HARNESS BEHIND THE AFSC TOO CLOSE TO BASE/ AC STRUCTURE.					
Count: 1		1			1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-15.807-8.NR-3		Drawing: N/A		07/11/2018	07/13/2018
<i>Description: Found wire bundle rubbing fiberglass duct at the L/H Aft corner of the forward pit.</i>					
505-21-AVIONICS, Mx	1999M.AWR-15.807-8.NR-3.50 5-21	5112793	07/11/2018	07/12/2018	07/13/2018
<i>Description: Found wire bundle rubbing fiberglass duct at the L/H Aft corner of the forward pit.</i>					
Count: 1			1		1
Task Card: AWR-16		Drawing: N/A		08/07/2018	08/10/2018
<i>Description: Due to life vests being changed on non routines, print and document replacements on customer camp cards. 25-290-00 (008.1) and 25-290-00 (009.1)</i>					
907-QC, AWR	1999M.AWR-16.907	5113731	08/07/2018	08/09/2018	08/10/2018
<i>Description: Due to life vests being changed on non routines, print and document replacements on customer camp cards. 25-290-00 (008.1) and 25-290-00 (009.1)</i>					
Count: 1			1		1
Task Card: AWR-17		Drawing: N/A		08/22/2018	
<i>Description: Remove aircraft engines and APU from pressurization</i>					
801-Maintenance	1999M.AWR-17.801	5115583	08/22/2018		
<i>Description: Engine depressurization IAW 71-00-03-600-809-F00</i>					
801-1-Maintenance	1999M.AWR-17.801-1	5115584	08/22/2018		
<i>Description: APU depressurization IAW AMM</i>					
Count: 2			2		0



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-2		Drawing: N/A		12/12/2016	01/09/2018
<i>Description: Items from Due list dated 27Oct2016, work order # 161027CBB</i>					
801-Maintenance	1999M.AWR-2.801	5093748	12/12/2016	01/08/2018	01/09/2018
<i>Description: EASA 2016-0164 PARA (1) VISUAL INSPECTION OF EACH AFFECTED CABIN ATTENDANT SEAT</i>					
801-1-Maintenance	1999M.AWR-2.801-1	5093749	12/12/2016	01/08/2018	01/09/2018
<i>Description: EASA 2016-0167 PARA (1) REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION</i>					
801-2-Maintenance	1999M.AWR-2.801-2	5093750	12/12/2016	01/08/2018	01/09/2018
<i>Description: EASA 2016-0163 PARA (1) MODIFY AND RE-IDENTIFY EACH AFFECTED CABIN ATTENDANT SEAT</i>					
801-3-Maintenance	1999M.AWR-2.801-3	5093751	12/12/2016	11/28/2017	11/28/2017
<i>Description: FLIGHT CONTROLS- RIDDER AND RUDDER TRIM CONTROL SYSTEM- WIRE BUNDLE W443 AND LEFT FORWARD RUDDER QUADRANT CLEARANCE INSPECTION, SERVICE BULLETIN</i>					
801-4-Maintenance	1999M.AWR-2.801-4	5093752	12/12/2016	04/05/2017	04/05/2017
<i>Description: ASB 737-57A1327 WINGS- LEADING EDGE AND LEADING EDGE DEVICES- KRUEGER FLAP INSPECTION, ALERT SERVICE BULLETIN</i>					
801-5-Maintenance	1999M.AWR-2.801-5	5093753	12/12/2016	01/04/2018	01/05/2018
<i>Description: AUTOFLIGHT - AUTOTHROTTLE SYSTEM - AUTOTHROTTLE COMPUTER REPLACEMENT, ALERT SERVICE BULLETIN</i>					
801-6-Maintenance	1999M.AWR-2.801-6	5093754	12/12/2016	04/14/2017	04/14/2017
<i>Description: LUBRICATE TO PREVENT AN UNDETECTED FAILURE OF THE PRIMARY LOAD PATH FOR THE BALLSCREW IN THE DRIVE MECHANISM OF THE HSTA AND SUBSEQUENT WEAR AND FAILURE OF THE SECONDARY LOAD PATH IN ACCORDANCE SERVICE BULLETIN 737-27A1277 R2</i>					
Count: 7			7		7
Task Card: AWR-2.801-1.NR-1		Drawing: N/A		03/16/2017	04/04/2017
<i>Description: FOUND THE REMAINS OF TWO BIRDS IN THE INLET SECTION OF THE APU WHILE ACCESSING FOR THE BORESCOPE INSPECTION.</i>					
801-7-Maintenance	1999M.AWR-2.801-1.NR-1.801-7	5097219	03/16/2017	04/04/2017	04/04/2017
<i>Description: FOUND THE REMAINS OF TWO BIRDS IN THE INLET SECTION OF THE APU WHILE ACCESSING FOR THE BORESCOPE INSPECTION.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-3		Drawing: N/A		12/01/2016	12/30/2016
<i>Description: Perform weekly engine runs</i>					
801-Maintenance	1999M.AWR-3.801	5093390	12/01/2016	12/06/2016	12/06/2016
<i>Description: Perform weekly engine runs- 01DEC2016</i>					
801-1-Maintenance	1999M.AWR-3.801-1	5093391	12/01/2016	12/12/2016	12/12/2016
<i>Description: Perform weekly engine runs- 08DEC2016</i>					
801-2-Maintenance	1999M.AWR-3.801-2	5093392	12/01/2016	12/30/2016	12/30/2016
<i>Description: Perform weekly engine runs- 15DEC2016</i>					
801-3-Maintenance	1999M.AWR-3.801-3	5093393	12/01/2016	12/30/2016	12/30/2016
<i>Description: Perform weekly engine runs- 22DEC2016</i>					
801-4-Maintenance	1999M.AWR-3.801-4	5093394	12/01/2016	12/30/2016	12/30/2016
<i>Description: Perform weekly engine runs- 29DEC2016</i>					
Count: 5		5		5	
Task Card: AWR-4		Drawing: N/A		02/16/2017	
<i>Description: Exterior Removals and Access</i>					
801-Maintenance	1999M.AWR-4.801	5096283	02/16/2017		
<i>Description: Exterior Removals and Access</i>					
80-5-Maintenance	1999M.AWR-4.80-5	5097108			
<i>Description: CENTER MID CEILING LINER HAS A 4 INCH TEAR.</i>					
Count: 2		1		0	
Task Card: AWR-4.80.NR-1		Drawing: N/A		03/16/2017	
<i>Description: HORIZONTAL STABILIZER PANEL 333CB HAS A MISSING NUTPLATE.</i>					
80-1-Maintenance	1999M.AWR-4.80.NR-1.80-1	5096795	03/16/2017	11/22/2017	11/22/2017
<i>Description: HORIZONTAL STABILIZER PANEL 333CB HAS A MISSING NUTPLATE.</i>					
Count: 1		1		1	
Task Card: AWR-4.80.NR-10		Drawing: N/A		03/23/2017	
<i>Description: FWD PIT FWD #1 FLOOR BOARD- 1 BROKEN NUTPLATE.</i>					
80-10-Maintenance	1999M.AWR-4.80.NR-10.80-10	5097638	03/23/2017	11/06/2017	11/07/2017
<i>Description: FWD PIT FWD #1 FLOOR BOARD- 1 BROKEN NUTPLATE.</i>					
Count: 1		1		1	
Task Card: AWR-4.80.NR-11		Drawing: N/A		03/23/2017	
<i>Description: THREE NUTPLATES FOUND BROKEN IN FWD BAGGAGE PIT.</i>					
80-11-Maintenance	1999M.AWR-4.80.NR-11.80-11	5097657	04/05/2017	11/06/2017	11/07/2017
<i>Description: THREE NUTPLATES FOUND BROKEN IN FWD BAGGAGE PIT.</i>					
Count: 1		1		1	



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-4.80.NR-12		Drawing: N/A		03/23/2017	01/04/2018
<i>Description:</i> BROKEN NUTPLATE FOUND UNDER R/H WING T/E PANEL 661BB.					
80-12-Maintenance	1999M.AWR-4.80.NR-12.80-12	5097659	03/23/2017	01/03/2018	01/04/2018
<i>Description:</i> BROKEN NUTPLATE FOUND UNDER R/H WING T/E PANEL 661BB.					
Count: 1			1		1
Task Card: AWR-4.80.NR-13		Drawing: N/A		03/23/2017	03/28/2018
<i>Description:</i> 5 BROKEN NUT PLATES IN AFT BAGGAGE. 3 ON UPPER SIDE WALL BETWEEN STA 727C - 727F. 1 UNDER FLOOR AT STA747 LH SIDE RAIL.					
80-13-Maintenance	1999M.AWR-4.80.NR-13.80-13	5097660	03/23/2017	03/27/2018	03/28/2018
<i>Description:</i> 5 BROKEN NUT PLATES IN AFT BAGGAGE. 3 ON UPPER SIDE WALL BETWEEN STA 727C - 727F. 1 UNDER FLOOR AT STA747 LH SIDE RAIL.					
Count: 1			1		1
Task Card: AWR-4.80.NR-14		Drawing: N/A		04/05/2017	01/04/2018
<i>Description:</i> CORROSION INDICATION NOTED ON RIGHT LOWER SEAM FORWARD OF THE FORWARD CARGO DOOR.					
80-14-Maintenance	1999M.AWR-4.80.NR-14.80-14	5097909	04/05/2017	01/03/2018	01/04/2018
<i>Description:</i> CORROSION INDICATION NOTED ON RIGHT LOWER SEAM FORWARD OF THE FORWARD CARGO DOOR.					
Count: 1			1		1
Task Card: AWR-4.80.NR-15		Drawing: N/A		10/08/2017	01/10/2018
<i>Description:</i> ELEVATOR FEEL COMPUTER WET WITH HYDRAULIC FLUID					
80-15-Maintenance	1999M.AWR-4.80.NR-15.80-15	5102900	10/08/2017	01/10/2018	01/10/2018
<i>Description:</i> ELEVATOR FEEL COMPUTER WET WITH HYDRAULIC FLUID					
Count: 1			1		1
Task Card: AWR-4.80.NR-16		Drawing: N/A		12/05/2017	01/10/2018
<i>Description:</i> PANEL 192F (BETWEEN AC PACK DOORS) HAS CORROSION ON TOP SIDE OF THE MIDDLE ANTENNA					
606-16-SHEET METAL SHOP, Mx	1999M.AWR-4.80.NR-16.606-1	5102901	12/05/2017	01/09/2018	01/10/2018
	6				
<i>Description:</i> PANEL 192F (BETWEEN AC PACK DOORS) HAS CORROSION ON TOP SIDE OF THE MIDDLE ANTENNA					
Count: 1			1		1
Task Card: AWR-4.80.NR-17		Drawing: N/A		10/08/2017	
<i>Description:</i> RIGHT HORIZONTAL STAB BLADE SEAL HAS A BROKEN TEFLON GUIDE					
80-17-Maintenance	1999M.AWR-4.80.NR-17.80-17	5102902	10/08/2017	01/04/2018	01/05/2018
<i>Description:</i> RIGHT HORIZONTAL STAB BLADE SEAL HAS A BROKEN TEFLON GUIDE					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-4.80.NR-18		Drawing: N/A		10/10/2017	01/10/2018
<i>Description: RIGHT SATCOM ANTENNA CANNON PLUG ON THE AIRCRAFT SIDE IS HEAVILY CORRODED.</i>					
80-18-Maintenance	1999M.AWR-4.80.NR-18.80-18	5102904	10/10/2017	01/09/2018	01/10/2018
<i>Description: RIGHT SATCOM ANTENNA CANNON PLUG ON THE AIRCRAFT SIDE IS HEAVILY CORRODED.</i>					
Count: 1			1		1
Task Card: AWR-4.80.NR-19		Drawing: N/A		10/16/2017	01/11/2018
<i>Description: Nose Radome diverter strip at 3 o'clock position has broken fastener in insert at 3rd position from front of strip.</i>					
80-19-Maintenance	1999M.AWR-4.80.NR-19.80-19	5103113	10/16/2017	01/10/2018	01/11/2018
<i>Description: Nose Radome diverter strip at 3 o'clock position has broken fastener in insert at 3rd position from front of strip.</i>					
Count: 1			1		1
Task Card: AWR-4.80.NR-2		Drawing: N/A		03/16/2017	01/11/2018
<i>Description: LH HORIZONTAL TRANSITION PANEL 333AB RUBBER WIPER RETAINER IS CORRODED.</i>					
801-2-Maintenance	1999M.AWR-4.80.NR-2.801-2	5096796	03/16/2017	01/10/2018	01/11/2018
<i>Description: LH HORIZONTAL TRANSITION PANEL 333AB RUBBER WIPER RETAINER IS CORRODED.</i>					
Count: 1			1		1
Task Card: AWR-4.80.NR-20		Drawing: N/A		10/16/2017	01/05/2018
<i>Description: Found paint like substance leaking from cracks in the surface of panel 322C on the leading edge of the vertical stabilizer.</i>					
80-20-Maintenance	1999M.AWR-4.80.NR-20.80-20	5103117	10/16/2017	01/04/2018	01/05/2018
<i>Description: Found paint like substance leaking from cracks in the surface of panel 322C on the leading edge of the vertical stabilizer.</i>					
Count: 1			1		1
Task Card: AWR-4.80.NR-21		Drawing: N/A		12/11/2017	06/15/2018
<i>Description: Corrosion under DME antenna on panel 192 F</i>					
606-21-SHEET METAL SHOP, Mx	1999M.AWR-4.80.NR-21.606-2	5103728	12/11/2017	06/14/2018	06/15/2018
	1				
<i>Description: Corrosion under DME antenna on panel 192 F</i>					
Count: 1			1		1
Task Card: AWR-4.80.NR-22		Drawing: N/A		11/20/2017	01/11/2018
<i>Description: APU bleed duct in horizontal stab bay fwd of panel 311AL has incorrectly oriented clamp.</i>					
80-22-Maintenance	1999M.AWR-4.80.NR-22.80-22	5105184	11/20/2017	01/11/2018	01/11/2018
<i>Description: APU bleed duct in horizontal stab bay fwd of panel 311AL has incorrectly oriented clamp.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-4.80.NR-3		Drawing: N/A		03/16/2017	11/22/2017
<i>Description:</i> HORIZONTAL STABILIZER PANEL 333CB HAS A MISSING NUTPLATE.					
801-3-Maintenance	1999M.AWR-4.80.NR-3.801-3	5096810	03/16/2017	11/22/2017	11/22/2017
<i>Description:</i> HORIZONTAL STABILIZER PANEL 333CB HAS A MISSING NUTPLATE.					
Count: 1			1		1
Task Card: AWR-4.80.NR-4		Drawing: N/A		03/16/2017	04/24/2017
<i>Description:</i> LEFT ENGINE PYLON PANEL #431CR, BONDING STRAP HAS BROKEN WIRES.					
80-4-Maintenance	1999M.AWR-4.80.NR-4.80-4	5096875	03/16/2017	04/24/2017	04/24/2017
<i>Description:</i> LEFT ENGINE PYLON PANEL #431CR, BONDING STRAP HAS BROKEN WIRES.					
Count: 1			1		1
Task Card: AWR-4.80.NR-6		Drawing: N/A		03/16/2017	04/04/2017
<i>Description:</i> BIRD NESTING MATERIAL PACKED INTO LEFT AND RIGHT AILERON PCU CAVITY.					
80-6-Maintenance	1999M.AWR-4.80.NR-6.80-6	5097110	03/16/2017	04/04/2017	04/04/2017
<i>Description:</i> BIRD NESTING MATERIAL PACKED INTO LEFT AND RIGHT AILERON PCU CAVITY.					
Count: 1			1		1
Task Card: AWR-4.80.NR-7		Drawing: N/A		03/16/2017	04/25/2018
<i>Description:</i> FLOOR BEAM IN AFT PIT STA 807 HAS MISDRILLED HOLES IN IT ON THE LEFT SIDE.					
80-7-Maintenance	1999M.AWR-4.80.NR-7.80-7	5097220	03/16/2017	04/24/2018	04/25/2018
<i>Description:</i> FLOOR BEAM IN AFT PIT STA 807 HAS MISDRILLED HOLES IN IT ON THE LEFT SIDE.					
Count: 1			1		1
Task Card: AWR-4.80.NR-8		Drawing: N/A		03/16/2017	11/02/2017
<i>Description:</i> AFT BAGGAGE RH FWD CEILING PANEL IS TORN IN SEVERAL PLACES P/N 453A2210-244.					
80-8-Maintenance	1999M.AWR-4.80.NR-8.80-8	5097294	03/16/2017	10/31/2017	11/02/2017
<i>Description:</i> AFT BAGGAGE RH FWD CEILING PANEL IS TORN IN SEVERAL PLACES P/N 453A2210-244.					
Count: 1			1		1
Task Card: AWR-4.80.NR-9		Drawing: N/A		03/16/2017	11/07/2017
<i>Description:</i> FWD PIT FWD #1 FLOOR BOARD 1- BROKEN NUTPLATE.					
80-9-Maintenance	1999M.AWR-4.80.NR-9.80-9	5097315	03/16/2017	11/04/2017	11/07/2017
<i>Description:</i> FWD PIT FWD #1 FLOOR BOARD 1- BROKEN NUTPLATE.					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-5		Drawing: N/A		02/15/2017
<i>Description: Cabin Removal and Reinstallation</i>				
205-INTERIOR INSTALL, Mx	1999M.AWR-5.20	5096267	02/15/2017	
<i>Description: Cabin Removal and Reinstallation</i>				
205-1-INTERIOR INSTALL, Mx	1999M.AWR-5.205-1	5096415	12/09/2017	
<i>Description: Part #: 145252455-1 (CREW REST ACCESORIES CABINET) removed on task ID: 5096267</i> LOOSE TOE KICK				
205-2-INTERIOR INSTALL, Mx	1999M.AWR-5.20-2	5096419		
<i>Description: Part #: N/A (R/H #4 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC				
205-3-INTERIOR INSTALL, Mx	1999M.AWR-5.20-3	5096421		
<i>Description: Part #: N/A (L/H #3 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC				
205-4-INTERIOR INSTALL, Mx	1999M.AWR-5.20-4	5096422		
<i>Description: Part #: N/A (L/H #6 VALANCE PANEL) removed on task ID: 5096267</i> LOOSE TRIM				
205-5-INTERIOR INSTALL, Mx	1999M.AWR-5.20-5	5096423		
<i>Description: Part #: N/A (R/H #6 VALANCE PANEL) removed on task ID: 5096267</i> LOOSE TRIM & STAINS ON FABRIC				
205-6-INTERIOR INSTALL, Mx	1999M.AWR-5.20-6	5096424		
<i>Description: Part #: N/A (R/H #5 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC				
205-7-INTERIOR INSTALL, Mx	1999M.AWR-5.20-7	5096425		
<i>Description: Part #: N/A (R/H #2 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC & WOOD TRIM CHIPPED				
205-8-INTERIOR INSTALL, Mx	1999M.AWR-5.20-8	5096426		
<i>Description: Part #: N/A (R/H #3 VALANCE PANEL) removed on task ID: 5096267</i> MATERIAL DAMAGE ON SIDE				
205-9-INTERIOR INSTALL, Mx	1999M.AWR-5.20-9	5096427		
<i>Description: Part #: N/A (CLUB LOUNGE R/H AFT STORAGE CABINETS) removed on task ID: 5096267</i> SCRATCHES & BROKEN EDGE & LOOSE TRIM				
205-10-INTERIOR INSTALL, Mx	1999M.AWR-5.20-10	5096429		
<i>Description: Part #: MSA-005-094-4300AA (R/H#5 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES				
205-11-INTERIOR INSTALL, Mx	1999M.AWR-5.20-11	5096430		
<i>Description: Part #: MSA-005-094-3900M (R/H#1 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES				
205-12-INTERIOR INSTALL, Mx	1999M.AWR-5.20-12	5096431		
<i>Description: Part #: MSA-005-094-3900M (L/H#1 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES				
205-13-INTERIOR INSTALL, Mx	1999M.AWR-5.20-13	5096432		
<i>Description: Part #: MSA-005-094-4100AD (L/H#5 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES				
205-14-INTERIOR INSTALL, Mx	1999M.AWR-5.20-14	5096433		
<i>Description: Part #: MSA-005-094-4300Y (R/H# 3 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-15-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-4300Y (R/H# 4 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-15	5096434			
205-16-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-4300Z (L/H# 3 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-16	5096436			
205-17-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-3900M (R/H#2 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-17	5096439			
205-18-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-3900M (L/H#2 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-18	5096442			
205-19-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-095-1700A (R/H# 9WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-19	5096460			
205-20-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-095-1700B (L/H#7 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-20	5096461			
205-21-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-4300AB (R/H#6 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-21	5096462			
205-22-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-4100AC (R/H#7 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-22	5096463			
205-23-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-3800R (L/H#6 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-23	5096464			
205-24-INTERIOR INSTALL, Mx <i>Description: Part #: MSA-005-094-3800Q (R/H#8 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-24	5096465			
205-25-INTERIOR INSTALL, Mx <i>Description: Part #: N/A (L/H #4 WINDOW SHADE) removed on task ID: 5096267</i> SCRATCHES THROUGHOUT LENSES & IDENTIFICATION STICKER MISSING	1999M.AWR-5.20-25	5096466			
205-26-INTERIOR INSTALL, Mx <i>Description: Part #: 145252201-302 (MAIN LOUNGE R/H#1 CEILING PANEL) removed on task ID: 5096267</i> FABRIC STAINS	1999M.AWR-5.20-26	5096475			
205-27-INTERIOR INSTALL, Mx <i>Description: Part #: 145252201-318 (MAIN LOUNGE R/H#9 CEILING PANEL) removed on task ID: 5096267</i> LIGHT LENSE LOOSE	1999M.AWR-5.20-27	5096483			
205-28-INTERIOR INSTALL, Mx <i>Description: Part #: 145252207-201 (L/H#7 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC	1999M.AWR-5.20-28	5096493			
205-29-INTERIOR INSTALL, Mx <i>Description: Part #: 145252207-604 (R/H#9 VALANCE PANEL) removed on task ID: 5096267</i> STAINS ON FABRIC	1999M.AWR-5.20-29	5096494			
205-30-INTERIOR INSTALL, Mx	1999M.AWR-5.20-30	5096495			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: 145252207-607 (R/H#7 VALANCE PANEL) removed on task ID: 5096267 STAINS ON FABRIC				
205-31-INTERIOR INSTALL, Mx	1999M.AWR-5.20-31	5096511		
<i>Description:</i> Part #: 145252207-606 (R/H#10 VALANCE PANEL) removed on task ID: 5096267 STAINS ON FABRIC				
205-32-INTERIOR INSTALL, Mx	1999M.AWR-5.20-32	5096512		
<i>Description:</i> Part #: 145252207-203 (L/H#9 VALANCE PANEL) removed on task ID: 5096267 STAINS ON FABRIC				
205-33-INTERIOR INSTALL, Mx	1999M.AWR-5.20-33	5096513		
<i>Description:</i> Part #: 145252207-401 (VIP LAV VALANCE PANEL) removed on task ID: 5096267 STAINS ON FABRIC				
205-34-INTERIOR INSTALL, Mx	1999M.AWR-5.20-34	5096514		
<i>Description:</i> Part #: 145252207-501 (AFT LAV VALANCE PANEL) removed on task ID: 5096267 STAINS ON FABRIC				
205-35-INTERIOR INSTALL, Mx	1999M.AWR-5.20-35	5096515		
<i>Description:</i> Part #: MSA-005-094-3900M (ENTRYWAY L/H#1 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT LENSES				
205-36-INTERIOR INSTALL, Mx	1999M.AWR-5.20-36	5096516		
<i>Description:</i> Part #: MSA-005-095-1900M (CREW REST R/H #1 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT LENSES				
205-37-INTERIOR INSTALL, Mx	1999M.AWR-5.20-37	5096517		
<i>Description:</i> Part #: MSA-005-094-3725H (CREW REST R/H #2 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT LENSES				
205-38-INTERIOR INSTALL, Mx	1999M.AWR-5.20-38	5096518		
<i>Description:</i> Part #: N/A (L-1 DOOR SURROUND SEAL) removed on task ID: 5096267 DIRTY				
205-39-INTERIOR INSTALL, Mx	1999M.AWR-5.20-39	5096519		
<i>Description:</i> Part #: 145252201-203 (CREW REST R/H AFT PANEL) removed on task ID: 5096267 STAINS				
205-40-INTERIOR INSTALL, Mx	1999M.AWR-5.20-40	5096520		
<i>Description:</i> Part #: 411A2211-33A (L1 DOOR AFT DOOR SURROUND) removed on task ID: 5096267 DAMAGED LEATHER & STAINS				
205-41-INTERIOR INSTALL, Mx	1999M.AWR-5.20-41	5096521		
<i>Description:</i> Part #: 411A2211-51B (LI UPPER DOOR SURROUND) removed on task ID: 5096267 DAMAGED LEATHER & STAINS				
205-42-INTERIOR INSTALL, Mx	1999M.AWR-5.20-42	5096522		
<i>Description:</i> Part #: N/A (R-1 DOOR SURROUND SEAL) removed on task ID: 5096267 DIRTY				
205-43-INTERIOR INSTALL, Mx	1999M.AWR-5.20-43	5096524		
<i>Description:</i> Part #: N/A (ENTRYWAY CURTAIN) removed on task ID: 5096267 DIRTY				
205-44-INTERIOR INSTALL, Mx	1999M.AWR-5.20-44	5096525		
<i>Description:</i> Part #: N/A (ENTRYWAY L/H AFT CEILING PANEL) removed on task ID: 5096267 DIRTY				
205-45-INTERIOR INSTALL, Mx	1999M.AWR-5.20-45	5096526		
<i>Description:</i> Part #: 411A2212-13A (R1 DOOR SURROUND FWD) removed on task ID: 5096267 DIRTY & LEATHER DISCOLORATION				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-46-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2212-17A (R-1 AFT DOOR SURROUND) removed on task ID: 5096267 DIRTY & LEATHER DISCOLORATION	1999M.AWR-5.20-46	5096527			
205-47-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A3210-4A (COCKPIT ENTRYWAY CEILING PANEL) removed on task ID: 5096267 LEATHER SCRATCHES	1999M.AWR-5.20-47	5096528			
205-48-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CREW REST R/H CEILING PANEL) removed on task ID: 5096267 DIRTY & LEATHER SCRATCHED	1999M.AWR-5.20-48	5096530			
205-49-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2212-38B (R 1 DOOR UPPER SURROUND) removed on task ID: 5096267 DIRTY & LEATHER SCRATCHED	1999M.AWR-5.20-49	5096533			
205-50-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MAIN LOUNGE L/H FWD BUFFET CABINET) removed on task ID: 5096267 CORROSION IN UPPER AND BOTTOM OF INSIDE OF CHILLER	1999M.AWR-5.20-50	5096596		12/01/2017	12/01/2017
205-51-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145253107 (MAIN LOUNGE L/H FWD BUFFET CABINET UPPER SECTION) removed on task ID: 5096267 CRACKED VENNER AND SCRATCHES	1999M.AWR-5.20-51	5096597			
205-52-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252443 (MAIN LOUNGE R/H FWD DIVAN SURROUND ASSY) removed on task ID: 5096267 THERAPEUDIC AIR LINE BROKEN & VENNER DAMAGE & INK MARKS ON ARMREST LEATHER	1999M.AWR-5.20-52	5096598			
205-53-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252457-1843 (L/H FWD STORAGE CABINET ASSY / FWD VEST) removed on task ID: 5096267 BROKEN VENNEER ON LOWER SECTION & DIRTY GROSS POINT ON THE INSIDE & DENTS ON UPPER SECTION OF CABINET	1999M.AWR-5.20-53	5096599			
205-54-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A3220-6A (ENTRYWAY CENTER HEADLINER) removed on task ID: 5096267 DIRTY LEATHER	1999M.AWR-5.20-54	5096602			
205-55-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CREW REST OVERHEAD COMPARTMENT) removed on task ID: 5096267 CHIPPED VENNEER & STAINS ON GROSS POINT	1999M.AWR-5.20-55	5096603			
205-56-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CREW REST SIDELEDGE) removed on task ID: 5096267 CLEAR COATING PEELING	1999M.AWR-5.20-56	5096604			
205-57-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252417-1 (MAIN LOUNGE R/H FWD POCKET DOOR BLKD ASSY) removed on task ID: 5096267 SCRATCHES ON VENNEER	1999M.AWR-5.20-57	5096605			
205-58-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MAIN LOUNGE FWD POCKET DOOR) removed on task ID: 5096267 SCRATCHES ON DOOR KNOB	1999M.AWR-5.20-58	5096606			
205-59-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MAIN LOUNGE L/H FWD BUFFET CABINET LIGHT LENSE) removed on task ID: 5096267 LIGHT LENSE CRACKED IN 2 PLACES & DIRTY	1999M.AWR-5.20-59	5096607			
205-60-INTERIOR INSTALL, Mx	1999M.AWR-5.20-60	5096608			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: N/A (MAIN LOUNGE L/H FWD BUFFET CABINET BOTTOM CLOSEOUT) removed on task ID: 5096267 DIRTY RUG & CRACKED VENNEER				
205-61-INTERIOR INSTALL, Mx	1999M.AWR-5.20-61	5096609		
<i>Description:</i> Part #: N/A (MAIN LOUNGE FWD THRESHOLD) removed on task ID: 5096267 DIRTY & SCRATCHES				
205-62-INTERIOR INSTALL, Mx	1999M.AWR-5.20-62	5096610		
<i>Description:</i> Part #: N/A (ENTRYWAY CURTAIN WOOD TRACK) removed on task ID: 5096267 CRACKED IN 2 PLACES AND CHIPPED WOOD				
205-63-INTERIOR INSTALL, Mx	1999M.AWR-5.20-63	5096611		
<i>Description:</i> Part #: N/A (L1 DOOR FWD SURROUND) removed on task ID: 5096267 DIRTY				
205-64-INTERIOR INSTALL, Mx	1999M.AWR-5.20-64	5096618		
<i>Description:</i> Part #: 145252415-1 (ENTRYWAY LONGITUNIAL BULKHEAD) removed on task ID: 5096267 SCRATCHES ON VENNEER & LOOSE TRIM				
205-65-INTERIOR INSTALL, Mx	1999M.AWR-5.20-65	5096636		
<i>Description:</i> Part #: N/A (R/H #2 SIDELEDGE) removed on task ID: 5096267 DAMAGED VENNEER				
205-66-INTERIOR INSTALL, Mx	1999M.AWR-5.20-66	5096637		
<i>Description:</i> Part #: 145252433-4 (L/H #2 SIDELEDGE) removed on task ID: 5096267 LEATHER DAMAGED & DIRTY				
205-67-INTERIOR INSTALL, Mx	1999M.AWR-5.20-67	5096638		
<i>Description:</i> Part #: N/A (L/H FWD POCKET DOOR RECEIVING BULKHEAD) removed on task ID: 5096267 SCRATCHED VENNEER				
205-68-INTERIOR INSTALL, Mx	1999M.AWR-5.20-68	5096640		
<i>Description:</i> Part #: 145253107-3 (MAIN LOUNGE L/H BUFFET MID SECTION) removed on task ID: 5096267 DIRTY				
205-69-INTERIOR INSTALL, Mx	1999M.AWR-5.20-69	5096641		
<i>Description:</i> Part #: 145253107-4 (MAIN LOUNGE L/H FWD BUFFET CABINET BOTTOM SECTION) removed on task ID: 5096267 DIRTY & SCRATCHES ON DOOR KNOBS				
205-70-INTERIOR INSTALL, Mx	1999M.AWR-5.20-70	5096642		
<i>Description:</i> Part #: N/A (MAIN LOUNGE L/H AFT BUFFET CABINET COUNTERTOP) removed on task ID: 5096267 DIRTY				
205-71-INTERIOR INSTALL, Mx	1999M.AWR-5.20-71	5096643		
<i>Description:</i> Part #: N/A (MAIN LOUNGE L/H UPPER EQUIPMENT RAIL ABOVE BUFFET) removed on task ID: 5096267 DIRTY				
205-72-INTERIOR INSTALL, Mx	1999M.AWR-5.20-72	5096645		
<i>Description:</i> Part #: N/A (MAIN LOUNGE L/H BUFFET AFT CABINET TOP SECTION) removed on task ID: 5096267 DIRTY				
205-73-INTERIOR INSTALL, Mx	1999M.AWR-5.20-73	5096647		
<i>Description:</i> Part #: 145252435 (MAIN LOUNGE R/H OVER WING SIDELEDGE) removed on task ID: 5096267 DIRTY & SCRATCHED VENNEER				
205-74-INTERIOR INSTALL, Mx	1999M.AWR-5.20-74	5096649		
<i>Description:</i> Part #: MSA-005-094-4775A (L/H PASSAGEWAY #1 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-75-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4000D (L/H PASSAGEWAY #3 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-75	5096650			
205-76-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4300G (L/H PASSAGEWAY #6 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-76	5096651			
205-77-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4125B (L/H PASSAGEWAY #2 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-77	5096652			
205-78-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4300W (L/H PASSAGEWAY #5 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-78	5096653			
205-79-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (PASSAGEWAY L/H #4 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-79	5096654			
205-80-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-095-1900M (CLUB LOUNGE L/H # 11 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-80	5096655			
205-81-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE L/H #10 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-81	5096656			
205-82-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4300AC (CLUB LOUNGE L/H #7 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-82	5096657			
205-83-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE L/H #9 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-83	5096658			
205-84-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE L/H #8 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-84	5096659			
205-85-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE R/H #3 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-85	5096661			
205-86-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE R/H #6 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-86	5096664			
205-87-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE R/H #2 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-87	5096665			
205-88-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE R/H #5 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-88	5096666			
205-89-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-3900M (CLUB LOUNGE R/H #4 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-89	5096667			



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-90-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-095-2100D (AFT LAV R/H WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-90	5096668			
205-91-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-095-1900M (VIP LAV #1 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-91	5096669			
205-92-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-095-2100E (CLUB LOUNGE R/H # 1 WINDOW SHADE) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-92	5096670			
205-93-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252435 (MAIN LOUNGE R/H #6 SIDELEDGE) removed on task ID: 5096267 STAINS ALL OVER PANEL & TOE KICK &	1999M.AWR-5.20-93	5096672			
205-94-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252435 (MAIN LOUNGE R/H #5 SIDELEDGE) removed on task ID: 5096267 STAINS ALL OVER PANEL & TOE KICK & SCRATCHES ON TRIM	1999M.AWR-5.20-94	5096673			
205-95-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252435 (MAIN LOUNGE R/H #4 SIDELEDGE) removed on task ID: 5096267 STAINS ALL OVER PANEL & TOE KICK & SCRATCHES ON TRIM	1999M.AWR-5.20-95	5096674			
205-96-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145253107-2 (MAIN LOUNGE L/H BUFFET AFT CABINET LOWER SECTION) removed on task ID: 5096267 SCRATCHES ON VENNEER & DIRTY ON TOP	1999M.AWR-5.20-96	5096675			
205-97-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252435 (MAIN LOUNGE L/H #1 SIDELEDGE) removed on task ID: 5096267 SCRATCHES ON VENNEER & CLEAR COATING PEELING OFF & STAINS ON LEATHER	1999M.AWR-5.20-97	5096680			
205-98-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252445 (MAIN LOUNGE L/H #4 SIDELEDGE) removed on task ID: 5096267 SCRATCHES ON VENNEER & STAINS ON LEATHER	1999M.AWR-5.20-98	5096682			
205-99-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252435 (MAIN LOUNGE L/H # 3 SIDELEDGE) removed on task ID: 5096267 CUTS & STAINS ON LEATHER & DIRTY	1999M.AWR-5.20-99	5096690			
205-100-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CREW REST CARPET & PAD) removed on task ID: 5096267 DIRTY & LOTS OF STAINS	1999M.AWR-5.20-100	5096712			
205-101-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252439 (L/H OVER WING SIDELEDGE) removed on task ID: 5096267 DIRTY RUG AND LEATHER	1999M.AWR-5.205-101	5096713	01/04/2018	06/20/2018	06/21/2018
205-102-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-406 (L/H #16 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-102	5096771			
205-103-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-404 (L/H #14 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-103	5096772			
205-104-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-402 (L/H #12 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-104	5096773			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-105-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-401 (L/H #11 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-105	5096774			
205-106-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-403 (L/H #13 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-106	5096775			
205-107-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-405 (L/H #15 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-107	5096776			
205-108-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-407 (L/H #17 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-108	5096777			
205-109-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-807 (L/H #21 CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-109	5096779			
205-110-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-814 (R/H #7 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-110	5096780			
205-111-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-803 (L/H # 19 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-111	5096781			
205-112-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-805 (L/H # 20 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-112	5096782			
205-113-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-802 (R/H #1 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-113	5096783			
205-114-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-809 (L/H #22 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-114	5096784			
205-115-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-808 (R/H #4 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-115	5096785			
205-116-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-806 (R/H #3 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-116	5096786			
205-117-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-804 (R/H #2 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-117	5096787			
205-118-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-801 (L/H # 18 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-118	5096788			
205-119-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-810 (R/H #5 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-119	5096789			
205-120-INTERIOR INSTALL, Mx	1999M.AWR-5.20-120	5096790			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: 145252203-812 (R/H #6 CEILING PANEL (CLUB LOUNGE)) removed on task ID: 5096267 DIRTY				
205-121-INTERIOR INSTALL, Mx	1999M.AWR-5.20-121	5096811		
<i>Description:</i> Part #: MSA-005-094-4125A (MASTER BEDROOM #2 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT LENSES				
205-122-INTERIOR INSTALL, Mx	1999M.AWR-5.20-122	5096812		
<i>Description:</i> Part #: MSA-005-094-4775B (MASTER BEDROOM #1 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT THE LENSES				
205-123-INTERIOR INSTALL, Mx	1999M.AWR-5.20-123	5096815		
<i>Description:</i> Part #: 145252203-811 (CLUB LOUNGE L/H #23 CEILING PANEL) removed on task ID: 5096267 DIRTY				
205-124-INTERIOR INSTALL, Mx	1999M.AWR-5.20-124	5096817		
<i>Description:</i> Part #: 145252203-815 (CLUB LOUNGE L/H #24 CEILING PANEL) removed on task ID: 5096267 DIRTY				
205-125-INTERIOR INSTALL, Mx	1999M.AWR-5.20-125	5096821		
<i>Description:</i> Part #: 145252204-506 (MASTER BEDROOM # 3 CEILING PANEL) removed on task ID: 5096267 DIRTY				
205-126-INTERIOR INSTALL, Mx	1999M.AWR-5.20-126	5096824		
<i>Description:</i> Part #: 145252204-504 (MASTER BEDROOM # 2 CEILING PANEL) removed on task ID: 5096267 DIRTY				
205-127-INTERIOR INSTALL, Mx	1999M.AWR-5.20-127	5096828		
<i>Description:</i> Part #: 145252204-502 (MASTER BEDROOM # 1 CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-128-INTERIOR INSTALL, Mx	1999M.AWR-5.20-128	5096831		
<i>Description:</i> Part #: 145252204-508 (MASTER BEDROOM AFT CENTER CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-129-INTERIOR INSTALL, Mx	1999M.AWR-5.20-129	5096832		
<i>Description:</i> Part #: 145252204-501 (MASTER BEDROOM I/B # 1 CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-130-INTERIOR INSTALL, Mx	1999M.AWR-5.20-130	5096835		
<i>Description:</i> Part #: 145252203-507 (MASTER BEDROOM I/B # 4 CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-131-INTERIOR INSTALL, Mx	1999M.AWR-5.20-131	5096844		
<i>Description:</i> Part #: 145252439 (PASSAGEWAY # 1 SIDELEDGE) removed on task ID: 5096267 DIRTY & DAMAGED VENNEER & LOOSE DECOMPRESION PANEL THROUGHOUT & DIRTY TOE KICKS				
205-132-INTERIOR INSTALL, Mx	1999M.AWR-5.20-132	5096845		
<i>Description:</i> Part #: 145252439 (PASSAGEWAY # 2 SIDELEDGE) removed on task ID: 5096267 DIRTY & LOOSE DECOMPRESION PANEL THROUGHOUT & DIRTY TOE KICKS				
205-133-INTERIOR INSTALL, Mx	1999M.AWR-5.20-133	5096846		
<i>Description:</i> Part #: 145252439 (PASSAGEWAY # 3 SIDELEDGE) removed on task ID: 5096267 DIRTY & LOOSE DECOMPRESION PANEL THROUGHOUT & DIRTY TOE KICKS & DAMAGED VENNEER				
205-134-INTERIOR INSTALL, Mx	1999M.AWR-5.20-134	5096847		
<i>Description:</i> Part #: 145252439 (PASSAGEWAY # 4 SIDELEDGE) removed on task ID: 5096267 DIRTY & LOOSE DECOMPRESION PANEL THROUGHOUT & DIRTY TOE KICKS & DAMAGED VENNEER				
205-135-INTERIOR INSTALL, Mx	1999M.AWR-5.20-135	5096848		



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: 145252203-503 (MASTER BEDROOM I/B #2 CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-136-INTERIOR INSTALL, Mx	1999M.AWR-5.20-136			5096849
<i>Description:</i> Part #: 145252203-505 (MASTER BEDROOM I/B #3 CEILING PANEL) removed on task ID: 5096267 DIRTY & DAMAGED MATERIAL				
205-137-INTERIOR INSTALL, Mx	1999M.AWR-5.20-137			5096850
<i>Description:</i> Part #: 145252447 (CLUB LOUNGE L/H #2 SIDELEDGE) removed on task ID: 5096267 DIRTY GROSSPOINT INSIDE COMPARTMENTS				
205-138-INTERIOR INSTALL, Mx	1999M.AWR-5.20-138			5096851
<i>Description:</i> Part #: 145252441 (CLUB LOUNGE R/H # 3 SIDELEDGE) removed on task ID: 5096267 DIRTY TOE KICKS & DAMAGED VENNEER & DECOMPRESION PANEL LOOSE & DAMAGED THROUGHOUT SIDELEDGE				
205-139-INTERIOR INSTALL, Mx	1999M.AWR-5.20-139			5096852
<i>Description:</i> Part #: 145252441 (CLUB LOUNGE R/H # 2 SIDELEDGE) removed on task ID: 5096267 DIRTY TOE KICKS & DAMAGED VENNEER & DECOMPRESION PANEL LOOSE & DAMAGED THROUGHOUT SIDELEDGE				
205-140-INTERIOR INSTALL, Mx	1999M.AWR-5.20-140			5096853
<i>Description:</i> Part #: 145252441 (CLUB LOUNGE R/H # 1 SIDELEDGE) removed on task ID: 5096267 DIRTY TOE KICKS & DAMAGED VENNEER & DECOMPRESION PANEL LOOSE & DAMAGED THROUGHOUT SIDELEDGE & MISSING COVER ON OUTLET & PHONE IN COMPARTMENT IS OUT OF PLACE				
205-141-INTERIOR INSTALL, Mx	1999M.AWR-5.20-141			5096854
<i>Description:</i> Part #: 145252441 (CLUB LOUNGE L/H # 1 SIDELEDGE) removed on task ID: 5096267 DIRTY TOE KICK & SCRATCHES IN OUTLETS COVERS & DAMAGE LEATHER & DAMAGED VENNEER & DECOMPRESION PANEL LOOSE & OXYGEN THERAPEUTIC COVER DAMAGED				
205-142-INTERIOR INSTALL, Mx	1999M.AWR-5.20-142			5096855
<i>Description:</i> Part #: 145252441 (CLUB LOUNGE L/H # 3 SIDELEDGE) removed on task ID: 5096267 DIRTY TOE KICK & DIRTY INSIDE & SCRATCHES ON VENNEER				
205-143-INTERIOR INSTALL, Mx	1999M.AWR-5.20-143			5096856
<i>Description:</i> Part #: N/A (CLUB LOUNGE R/H FWD EQUIPMENT STORAGE CABINET) removed on task ID: 5096267 DAMAGED VENNEER & LOOSE TRIMS & NEEDS CLEANING				
205-144-INTERIOR INSTALL, Mx	1999M.AWR-5.20-144			5096982
<i>Description:</i> Part #: N/A (L/H AFT FWD GALLEY TOP SECTION) removed on task ID: 5096267 DIRTY INSIDE & SCRATCHES ON DOORS EDGES & MISSING HARDWARE ON TOP DOOR HINGE				
205-145-INTERIOR INSTALL, Mx	1999M.AWR-5.20-145			5096983
<i>Description:</i> Part #: N/A (CLUB LOUNGE AFT POCKET DOOR) removed on task ID: 5096267 SCRATCH ON VENNEER				
205-146-INTERIOR INSTALL, Mx	1999M.AWR-5.20-146			5096984
<i>Description:</i> Part #: 145252427-1 (CLUB LOUNGE AFT POCKET DOOR HEADERS AND TRACK) removed on task ID: 5096267 SCRATCH ON VENNEER				
205-147-INTERIOR INSTALL, Mx	1999M.AWR-5.20-147			5096985
<i>Description:</i> Part #: 145252427-1 (CLUB LOUNGE AFT POCKET DOOR LONGITUNIAL BULKHEAD) removed on task ID: 5096267 SCRATCH ON VENNEER				
205-148-INTERIOR INSTALL, Mx	1999M.AWR-5.20-148			5096986
<i>Description:</i> Part #: N/A (R/H AFT FWD GALLEY LOWER SECTION) removed on task ID: 5096267 DIRTY INSIDE & CORROSION ON BOTTOM & ICE DRAWER DRAIN PLUG SEALED UP & SCRATCHED VENNEER & DIRTY ON TOP				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-149-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV DOOR) removed on task ID: 5096267 VENNEER CLEAR PEALING & SCRATCHES	1999M.AWR-5.20-149	5096996			
205-150-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145251709-17 (CABIN POWER CIRCUIT BREAKER PANEL) removed on task ID: 5096267 DAMAGED FACE PLATE	1999M.AWR-5.20-150	5096999			
205-151-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CLUB LOUNGE TO AFT GALLEY THRESHOLD) removed on task ID: 5096267 DIRTY & SCRATCHES ALL OVER	1999M.AWR-5.20-151	5097002			
205-152-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (L2 DOOR SURROUND SEAL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-152	5097004			
205-153-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (R2 DOOR SURROUND SEAL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-153	5097006			
205-154-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A3420-18B (AFT GALLEY CENTER CEILING PANEL) removed on task ID: 5096267 DIRTY LIGHT LENSE & DIRTY THROUGHOUT & AIR VENTS DIRTY	1999M.AWR-5.20-154	5097010			
205-155-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM DOOR) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING & VENNEER CRACKED IN SEVERAL PLACES	1999M.AWR-5.20-155	5097011			
205-156-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2213-19A (L2 AFT DOOR SURROUND) removed on task ID: 5096267 DIRTY & CRACKED PAINT	1999M.AWR-5.20-156	5097012			
205-157-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2214-15A (R2 AFT DOOR SURROUND) removed on task ID: 5096267 DIRTY & CRACKED PAINT	1999M.AWR-5.20-157	5097014			
205-158-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2214-22B (R2 DOOR FWD DOOR SURROUND) removed on task ID: 5096267 DIRTY & CRACKED PAINT	1999M.AWR-5.20-158	5097015			
205-159-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2213-24B (L2 DOOR FWD SURROUND) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-159	5097016			
205-160-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2213-22B (L2 DOOR UPPER DOOR SURROUND) removed on task ID: 5096267 DIRTY & LIGHT LENSE LOOSE	1999M.AWR-5.20-160	5097017			
205-161-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 411A2214-19B (R2 DOOR UPPER DOOR SURROUND) removed on task ID: 5096267 DIRTY & LIGHT LENSE LOOSE & CRACKED PAINT & SMOKE DETECTOR PAINT CHIPPED	1999M.AWR-5.20-161	5097018			
205-162-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (AFT GALLEY FWD CENTER PANEL) removed on task ID: 5096267 DIRTY & CRACKED PANEL 2 PL	1999M.AWR-5.20-162	5097019			
205-163-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 14800(Q25) (MASTER BEDROOM QUEEN BED) removed on task ID: 5096267 DIRTY GROSSPOINT & DIRTY DRAWER COMPARTMENTS & MISSING HARDWARE ON INNER FLOOR CLOSEOUTS & DITY LEATHER ON DRAWER FACES	1999M.AWR-5.20-163	5097020			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-164-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM I/B NIGHTSTAND) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING & DIRTY TOE KICK & DIRTY LEATHER	1999M.AWR-5.20-164	5097027			
205-165-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (PASSAGEWAY #3 CENTER PARTITION BULKHEAD) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING & DOOR RECEIVING LATCH DIRTY	1999M.AWR-5.20-165	5097028			
205-166-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (PASSAGEWAY FWD CURVED PARTITION BULKHEAD) removed on task ID: 5096267 INNER DECO PANEL BUBBLING & BROKEN & SWITCH NOT SITTING FLUSH	1999M.AWR-5.20-166	5097029			
205-167-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM TO PASSAGEWAY THRESHOLD) removed on task ID: 5096267 SCRATCHES THROUGHOUT	1999M.AWR-5.20-167	5097030			
205-168-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX SIDEWALL) removed on task ID: 5096267 DIRTY MATERIAL & SCRATCHES THROUGHOUT WINDOW	1999M.AWR-5.20-168	5097036			
205-169-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-813 (GALLEY COMPLEX CEILING PANEL) removed on task ID: 5096267 DIRTY MATERIAL	1999M.AWR-5.20-169	5097037			
205-170-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX SIDEWALL BOTTOM PANEL) removed on task ID: 5096267 DIRTY MATERIAL	1999M.AWR-5.20-170	5097038			
205-171-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX DOOR HEADER) removed on task ID: 5096267 SCRATCH ON VENNEER	1999M.AWR-5.20-171	5097039			
205-172-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX DOOR) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING & DOOR KNOB LOOSE	1999M.AWR-5.20-172	5097040			
205-173-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252419-2 (VIP SUITE O/B BULKHEAD) removed on task ID: 5096267 SCRATCHES ON VENNEER & DECO PANEL MATERIAL DIRTY & DAMAGED	1999M.AWR-5.20-173	5097041			
205-174-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX O/B SHELF) removed on task ID: 5096267 DIRTY MATERIAL & WOOD TRIM DAMAGED AND LOOSE	1999M.AWR-5.20-174	5097042			
205-175-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (GALLEY COMPLEX COAT ROD) removed on task ID: 5096267 DIRTY MATERIAL	1999M.AWR-5.20-175	5097044			
205-176-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252475-1 (GALLEY COMPLEX FWD ENTERTAINMENT CLOSET) removed on task ID: 5096267 VENNEER SCRATCHED & DIRTY INSIDE	1999M.AWR-5.20-176	5097045			
205-177-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 60190-0 (MASTER BEDROOM AFT MONITOR) removed on task ID: 5096267 BIG BURN SPOT ON CENTER OF MONITOR & SCRATCHES ALL AROUND	1999M.AWR-5.20-177	5097046			
205-178-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252201-602 (VIP LAV R/H # 1 CEILING PANEL) removed on task ID: 5096267 DIRTY MATERIAL	1999M.AWR-5.20-178	5097048			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-179-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252201-604 (VIP LAV R/H #2 CEILING PANEL) removed on task ID: 5096267 DIRTY MATERIAL	1999M.AWR-5.20-179	5097052			
205-180-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM SIDELEDGE) removed on task ID: 5096267 LEATHER MATERIAL PELED & DAMAGE ON LEATHER & LOOSE DECOMPRESSION PANELS THROUGHOUT & DENTS ON TOP VENNEER & DIRTY TOE KICK RUG & MISSING TWO SCREWS OUT OF FOUR	1999M.AWR-5.20-180	5097053			
205-181-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252421-1 (MASTER BEDROOM FWD CENTER BULKHEAD) removed on task ID: 5096267 DIRTY & LOOSE DECO PANEL	1999M.AWR-5.20-181	5097054			
205-182-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252419-16 (MAIN LOUNGE R/H AFT MONITOR SHROUD COVER BULKHEAD) removed on task ID: 5096267 SCRATCHES ON VENNEER & LOOSE TRIM	1999M.AWR-5.20-182	5097055			
205-183-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252461 (MASTER BEDROOM R/H NIGHTSTAND) removed on task ID: 5096267 SCRATCHES ON VENNEER & VENNEER CLEAR COAT PEALING & DIRTY LEATHER	1999M.AWR-5.20-183	5097056			
205-184-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (L2 FWD ENTRYWAY BULKHEAD) removed on task ID: 5096267 SCRATCHES ON EDGE OF VENNEER	1999M.AWR-5.20-184	5097057			
205-185-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252475-1 (GALLEY COMPLEX AFT CLOSET) removed on task ID: 5096267 CHIPPED VENNEER & VENNEER CLEAR COAT PEALING & DENTS ON CORNER TRIM & DIRTY GROSS POINT INSIDE	1999M.AWR-5.20-185	5097058			
205-186-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252471-1 (MASTER BEDROOM AFT CLOSET ASSY) removed on task ID: 5096267 DIRTY TOE KICK & SCRATCHES ON VENNEER	1999M.AWR-5.20-186	5097061			
205-187-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252471-1 (MASTER BEDROOM AFT O/B CLOSET ASSY) removed on task ID: 5096267 INSIDE GROSS POINT DIRTY COAT ROD HAS NUMEROUS SCRATCHES & SCRATCHES ON VENNEER	1999M.AWR-5.20-187	5097062			
205-188-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV TO PASSAGEWAY THRESHOLD) removed on task ID: 5096267 SCRATCHES ALL OVER	1999M.AWR-5.20-188	5097063			
205-189-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV TO MASTER BEDROOM THRESHOLD) removed on task ID: 5096267 SCRATCHES ALL OVER	1999M.AWR-5.20-189	5097064			
205-190-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MAIN LOUNGE AFT BULKHEAD TOE KICK CARPET) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-190	5097065			
205-191-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM AFT POCKET DOOR) removed on task ID: 5096267 SCRATCHES ON VENNEER & VENNEER CLEAR COAT PEALING & VENNEER CRACKING IN SOME SPOTS	1999M.AWR-5.20-191	5097066			
205-192-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-192	5097067			
205-193-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-603 (VIP LAV CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-193	5097068			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-194-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145253105 (G4 B GALLEY) removed on task ID: 5096267 SCRATCHES ON VENNEER & SEVERAL SCRATCHES ON COUNTERTOP AND CRACKS & SEVERAL DRAWERS HAVE SLIDE BEARINGS MISSING	1999M.AWR-5.20-194	5097069			
205-195-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV VANITY FWD CLOSEOUT) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING	1999M.AWR-5.20-195	5097070			
205-196-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV ENTRY BULKHEAD) removed on task ID: 5096267 VENNEER CHIPPED & VENNEER CRACKED ON TOP	1999M.AWR-5.20-196	5097071			
205-197-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (AFT LAV DOOR) removed on task ID: 5096267 VENNEER CLEAR COAT PEALING & CRACKS ON VENNEER	1999M.AWR-5.20-197	5097072			
205-198-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-703 (AFT LAV CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-198	5097073			
205-199-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (AFT LAV MIRROR) removed on task ID: 5096267 DIRTY & SCRATCHES	1999M.AWR-5.20-199	5097074			
205-200-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM CARPET & PAD) removed on task ID: 5096267 DIRTY & STAINS	1999M.AWR-5.20-200	5097075			
205-201-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-704 (AFT LAV CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-201	5097076			
205-202-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252203-701 (AFT LAV CEILING PANEL) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-202	5097077			
205-203-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252201-702 (AFT LAV CEILING PANEL) removed on task ID: 5096267 DIRTY & DENTS	1999M.AWR-5.20-203	5097078			
205-204-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252402-3 (AFT LAV TOE KICK) removed on task ID: 5096267 SCRATCHES & CRACKS	1999M.AWR-5.20-204	5097079			
205-205-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (AFT LAV DOOR HEADER) removed on task ID: 5096267 SCRATCHES	1999M.AWR-5.20-205	5097080			
205-206-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145254401-6 (VIP LAV TOILET SHROUD TOP COVER & CUSHIONS) removed on task ID: 5096267 CUSHIONS LEATHERS CUTS & SEAT RING CRACKED & DIRTY	1999M.AWR-5.20-206	5097081			
205-207-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV TOILET) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-207	5097082			
205-208-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252402-3 (VIP LAV SHOWER TOE KICK) removed on task ID: 5096267 SCUFFS & SCRATCHES	1999M.AWR-5.20-208	5097083			



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

	Task Card #	Task ID	Opened	RTS	Closed
205-209-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252401-3 (VIP LAV TOILET SHROUD FWD END CABINET) removed on task ID: 5096267 SCRATCHES ON VENNEER & DIRTY INSIDE & SCRATCHES ON INSIDE OF TOP DOOR	1999M.AWR-5.20-209	5097084			
205-210-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252401-5 (VIP LAV TOILET SHROUD) removed on task ID: 5096267 DAMAGED VENNEER & DIRTY	1999M.AWR-5.20-210	5097085			
205-211-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145252402-3 (VIP LAV TOE KICK) removed on task ID: 5096267 DIRTY	1999M.AWR-5.20-211	5097086			
205-212-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (CLUB LOUNGE FWD BULKHEAD TOE KICK RUG) removed on task ID: 5096267 DIRTY & STAINS	1999M.AWR-5.20-212	5097087			
205-213-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER BEDROOM TO VIP LAV HEADER) removed on task ID: 5096267 VENNEER SCRATCHES	1999M.AWR-5.20-213	5097088			
205-214-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 14524303-1 (VIP LAV SHOWER UPPER SURROUND) removed on task ID: 5096267 VENNEER SCRATCHES	1999M.AWR-5.20-214	5097089			
205-215-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV BIDET CLOSEOUT) removed on task ID: 5096267 DIRTY LEATHER	1999M.AWR-5.20-215	5097090			
205-216-INTERIOR INSTALL, Mx <i>Description:</i> Part #: MSA-005-094-4050C (VIP LAV # 2 WINDOW SHADE) removed on task ID: 5096267 SCRATCHES THROUGHOUT LENSES	1999M.AWR-5.20-216	5097091			
205-217-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145254401-2 (VIP LAV SIDELEDGE) removed on task ID: 5096267 DIRTY LEATHER & VENNEER SCRATCHES	1999M.AWR-5.20-217	5097092			
205-218-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV BIDET) removed on task ID: 5096267 DIRTY & SCRATCHES	1999M.AWR-5.20-218	5097093			
205-219-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 145254401-4 (VIP LAV TOILET SHROUD AFT CABINET) removed on task ID: 5096267 DIRTY & SCRATCHES ON VENNEER & DAMAGED VENNEER & DAMAGED LEATHER	1999M.AWR-5.20-219	5097094			
205-220-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (VIP LAV WOOD FLOORING) removed on task ID: 5096267 SCRATCHES & DIRTY	1999M.AWR-5.20-220	5097095			
205-221-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (AFT LAV VANITY) removed on task ID: 5096267 SCRATCHES ON VENNEER & DIRTY INSIDE	1999M.AWR-5.20-221	5097096			
205-222-INTERIOR INSTALL, Mx <i>Description:</i> Part #: 14524303-1 (VIP LAV SHOWER BOTTOM SURROUND) removed on task ID: 5096267 SCRATCHES ON VENNEER & VENNEER CHIPPED	1999M.AWR-5.20-222	5097097			
205-223-INTERIOR INSTALL, Mx <i>Description:</i> Part #: N/A (MASTER LAV FWD BULKHEAD TOE KICK) removed on task ID: 5096267 SCRATCHES ON VENNEER & VENNEER CRACKED	1999M.AWR-5.20-223	5097098			
205-224-INTERIOR INSTALL, Mx	1999M.AWR-5.20-224	5097122			



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: N/A (VIP LAV VANITY) removed on task ID: 5096267 SCRATCH VENNEER & VENNEER CLEAR COAT PEALING & DIRTY INSIDE				
205-225-INTERIOR INSTALL, Mx	1999M.AWR-5.20-225	5097123		
<i>Description:</i> Part #: 145252425-1 (CLUB LOUNGE FWD BULKHEAD) removed on task ID: 5096267 VENNEER SCRATCHES				
205-226-INTERIOR INSTALL, Mx	1999M.AWR-5.20-226	5097185		
<i>Description:</i> Part #: N/A (G1 GALLEY FLOOR TRIMS) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT				
205-227-INTERIOR INSTALL, Mx	1999M.AWR-5.20-227	5097186		
<i>Description:</i> Part #: 145252425-1 (AFT LAV AFT BULKHEAD) removed on task ID: 5096267 SCRATCHES ON VENNEER				
205-228-INTERIOR INSTALL, Mx	1999M.AWR-5.20-228	5097187		
<i>Description:</i> Part #: N/A (PASSAGEWAY VIP LAV ENTRY AFT BULKHEAD) removed on task ID: 5096267 SCRATCHES & DIRTY TOE KICK RUG				
205-229-INTERIOR INSTALL, Mx	1999M.AWR-5.20-229	5097188		
<i>Description:</i> Part #: N/A (PASSAGEWAY CARPET AND PAD) removed on task ID: 5096267 LOTS OF DIRT & STAINS				
205-230-INTERIOR INSTALL, Mx	1999M.AWR-5.20-230	5097189		
<i>Description:</i> Part #: N/A (CLUB LOUNGE CARPET AND PAD) removed on task ID: 5096267 LOTS OF DIRT & STAINS				
205-231-INTERIOR INSTALL, Mx	1999M.AWR-5.20-231	5097195		
<i>Description:</i> Part #: N/A (G1 GALLEY) removed on task ID: 5096267 RUSTED SCREWS ON BOTTOM FLOOR FITTINGS & CRACKED COUNTERTOP & SCRATCHES ON TRIM & SCRATCHES ON VENNEER				
205-232-INTERIOR INSTALL, Mx	1999M.AWR-5.20-232	5097199		
<i>Description:</i> Part #: N/A (L1 DOOR THRESHOLD) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT				
205-233-INTERIOR INSTALL, Mx	1999M.AWR-5.20-233	5097200		
<i>Description:</i> Part #: N/A (R1 DOOR THRESHOLD) removed on task ID: 5096267 DIRTY & SCRATCHES THROUGHOUT & 2 BROKEN INSERTS				
205-234-INTERIOR INSTALL, Mx	1999M.AWR-5.20-234	5097202		
<i>Description:</i> Part #: N/A (COCKPIT ENTRYWAY CEILING PANEL) removed on task ID: 5096267 DIRTY & LOOSE TRIMS & SCRATCHES				
205-235-INTERIOR INSTALL, Mx	1999M.AWR-5.20-235	5097203		
<i>Description:</i> Part #: N/A (COCKPIT THRESHOLD) removed on task ID: 5096267 CHIPPED PAINT & DIRTY & SCRATCHES				
205-236-INTERIOR INSTALL, Mx	1999M.AWR-5.20-236	5097204		
<i>Description:</i> Part #: N/A (COCKPIT DOOR) removed on task ID: 5096267 CHIPPED VENNEER VENNEER CLEARCOAT PEALING				
205-237-INTERIOR INSTALL, Mx	1999M.AWR-5.20-237	5097205		
<i>Description:</i> Part #: N/A (FWD LAV DOOR) removed on task ID: 5096267 SCRATCHED TRIMS & DOOR KNOB PLATING WORN OUT				
205-238-INTERIOR INSTALL, Mx	1999M.AWR-5.20-238	5097211		
<i>Description:</i> Part #: 411A2211-25A (L1 DOOR SURROUND FWD LOWER) removed on task ID: 5096267 DAMAGED LEATHER & DIRTY				
205-239-INTERIOR INSTALL, Mx	1999M.AWR-5.20-239	5097212		



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> Part #: 411A2211-23A (L1 DOOR SURROUND FWD MID) removed on task ID: 5096267 DAMAGED LEATHER & DIRTY				
205-240-INTERIOR INSTALL, Mx	1999M.AWR-5.20-240	5097213		
<i>Description:</i> Part #: N/A (FWD LAV THRESHOLD) removed on task ID: 5096267 SCRATCHES THROUGHOUT PLATING & DIRTY				
205-241-INTERIOR INSTALL, Mx	1999M.AWR-5.20-241	5097214		
<i>Description:</i> Part #: NA (LH #1 DOOR THRESHOLD) removed on task ID: 5096267 DIRTY				
205-242-INTERIOR INSTALL, Mx	1999M.AWR-5.20-242	5097215		
<i>Description:</i> Part #: NA (MASTER BEDROOM TO LAV DOOR STOP) removed on task ID: 5096267 SCRATCHES IN PLATING				
205-243-INTERIOR INSTALL, Mx	1999M.AWR-5.20-243	5097216		
<i>Description:</i> Part #: NA (LH1 BELOW EXIT SIGN (DOOR)) removed on task ID: 5096267 CRACKS IN WOOD				
205-244-INTERIOR INSTALL, Mx	1999M.AWR-5.20-244	5097218		
<i>Description:</i> Part #: NA (CREW LAV TOILET SHROUD/ CLOSEOUT) removed on task ID: 5096267 CRACKS IN PAINT AND REALLY DIRTY				
205-249-INTERIOR INSTALL, Mx	1999M.AWR-5.20-249	5097358		
<i>Description:</i> Part #: 411A2219-26 (R2 DOOR AFT THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-250-INTERIOR INSTALL, Mx	1999M.AWR-5.20-250	5097359		
<i>Description:</i> Part #: 411A2219-26 (R2 DOOR FWD THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-251-INTERIOR INSTALL, Mx	1999M.AWR-5.20-251	5097360		
<i>Description:</i> Part #: 000284330 (R2 DOOR CENTER THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-252-INTERIOR INSTALL, Mx	1999M.AWR-5.20-252	5097361		
<i>Description:</i> Part #: 411A2219-27 (L2 DOOR AFT THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-253-INTERIOR INSTALL, Mx	1999M.AWR-5.20-253	5097362		
<i>Description:</i> Part #: 411A2219-25 (L2 DOOR FWD THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-254-INTERIOR INSTALL, Mx	1999M.AWR-5.20-254	5097363		
<i>Description:</i> Part #: N/A (L2 DOOR CENTER THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-255-INTERIOR INSTALL, Mx	1999M.AWR-5.20-255	5097364		
<i>Description:</i> Part #: N/A (L1 THRESHOLD) removed on task ID: 5096267 SCRATCHES				
205-256-INTERIOR INSTALL, Mx	1999M.AWR-5.20-256	5097368		
<i>Description:</i> Part #: N/A (COCKPIT ENTRYWAY CARPET & THRESHOLD) removed on task ID: 5096267 SCRATCHES				
Count: 253		3		2



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-5.20.NR-245		Drawing: N/A		03/16/2017	11/02/2017
<i>Description:</i> Part #: NA (MAIN LOUNGE CARPET AND PAD) removed on task ID: 5096267 DIRTY AND LOTS OF STAINS					
205-245-INTERIOR INSTALL, Mx	1999M.AWR-5.20.NR-245.20-2 45	5097222	03/16/2017	10/30/2017	11/02/2017
<i>Description:</i> Part #: NA (MAIN LOUNGE CARPET AND PAD) removed on task ID: 5096267 DIRTY AND LOTS OF STAINS					
Count: 1			1		1
Task Card: AWR-5.20.NR-246		Drawing: N/A		03/16/2017	11/02/2017
<i>Description:</i> Part #: NA (ENTRYWAY WOOD FLOORING) removed on task ID: 5096267 SCRATCHES AND CHIPS AND SOME PIECES ARE BROKE IN HALF					
205-246-INTERIOR INSTALL, Mx	1999M.AWR-5.20.NR-246.20-2 46	5097225	03/16/2017	10/30/2017	11/02/2017
<i>Description:</i> Part #: NA (ENTRYWAY WOOD FLOORING) removed on task ID: 5096267 SCRATCHES AND CHIPS AND SOME PIECES ARE BROKE IN HALF					
Count: 1			1		1
Task Card: AWR-5.20.NR-247		Drawing: N/A		03/16/2017	11/02/2017
<i>Description:</i> Part #: NA (SHOWER AND HALLWAY WOOD TRIMS 2EA.) removed on task ID: 5096267 CRACK IN WOOD					
205-247-INTERIOR INSTALL, Mx	1999M.AWR-5.20.NR-247.20-2 47	5097226	03/16/2017	10/30/2017	11/02/2017
<i>Description:</i> Part #: NA (SHOWER AND HALLWAY WOOD TRIMS 2EA.) removed on task ID: 5096267 CRACK IN WOOD					
Count: 1			1		1
Task Card: AWR-5.20.NR-248		Drawing: N/A		03/16/2017	
<i>Description:</i> Part #: NA (R1 DOOR THRESHOLD) removed on task ID: 5096267 FWD INSERT PULLED OUT OF THE FLOOR					
205-248-INTERIOR INSTALL, Mx	1999M.AWR-5.20.NR-248.20-2 48	5097250	03/16/2017	01/03/2018	01/04/2018
<i>Description:</i> Part #: NA (R1 DOOR THRESHOLD) removed on task ID: 5096267 FWD INSERT PULLED OUT OF THE FLOOR					
Count: 1			1		1
Task Card: AWR-6		Drawing: N/A		02/21/2017	04/13/2018
<i>Description:</i> Floor Board Removal and Reinstallation					
801-Maintenance	1999M.AWR-6.801	5096325	02/21/2017	04/12/2018	04/13/2018
<i>Description:</i> Floor Board Removal and Reinstallation					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-6.80.NR-1		Drawing: N/A		03/16/2017	11/07/2017
<i>Description: MANY SCREWS HAD TO BE DRILLED AND CAPTIVE NUTS DAMAGED DURING THE REMOVAL OF THE CABIN FLOORBOARDS.</i>					
80-1-Maintenance	1999M.AWR-6.80.NR-1.80-1	5097334	03/16/2017	11/06/2017	11/07/2017
<i>Description: MANY SCREWS HAD TO BE DRILLED AND CAPTIVE NUTS DAMAGED DURING THE REMOVAL OF THE CABIN FLOORBOARDS.</i>					
Count: 1			1		1
Task Card: AWR-6.80.NR-2		Drawing: N/A		04/27/2017	04/16/2018
<i>Description: NUMEROUS FLOORBOARDS ARE DAMAGED BEYOND LIMIT. NEED SENT OUT FOR REPAIR.</i>					
80-2-Maintenance	1999M.AWR-6.80.NR-2.80-2	5098497	04/27/2017	04/13/2018	04/16/2018
<i>Description: NUMEROUS FLOORBOARDS ARE DAMAGED BEYOND LIMIT. NEED SENT OUT FOR REPAIR.</i>					
Count: 1			1		1
Task Card: AWR-6.80.NR-3		Drawing: N/A		04/27/2017	05/09/2018
<i>Description: NUMEROUS FLOORBOARDS DAMAGED OR MISSING INSERTS.</i>					
80-3-Maintenance	1999M.AWR-6.80.NR-3.80-3	5098498	04/27/2017	05/09/2018	05/09/2018
<i>Description: NUMEROUS FLOORBOARDS DAMAGED OR MISSING INSERTS.</i>					
Count: 1			1		1
Task Card: AWR-6.80.NR-4		Drawing: N/A		10/13/2017	06/26/2018
<i>Description: FLOORBOARD AT AFT ENTRY (L2) DOOR HA ONE INSERT WITH DRILLED OFF SCREW AND ONE DAMAGED INSERT.</i>					
80-4-Maintenance	1999M.AWR-6.80.NR-4.80-4	5102903	10/13/2017	06/25/2018	06/26/2018
<i>Description: FLOORBOARD AT AFT ENTRY (L2) DOOR HA ONE INSERT WITH DRILLED OFF SCREW AND ONE DAMAGED INSERT.</i>					
Count: 1			1		1
Task Card: AWR-7		Drawing: N/A		02/21/2017	
<i>Description: PATS Tanks Removal and Reinstallation</i>					
801-Maintenance	1999M.AWR-7.801	5096324	02/21/2017		
<i>Description: PATS Tanks Removal and Reinstallation</i>					
Count: 1			1		0
Task Card: AWR-7.80.NR-1		Drawing: N/A		03/16/2017	07/27/2018
<i>Description: FORWARD AUX FUEL TANKS - MAIN FUEL LINE AND VENT LINE HAS SEALANT ON MAIN FITTINGS AND FUEL LINES TO PREVENT LEAKAGE.</i>					
80-1-Maintenance	1999M.AWR-7.80.NR-1.80-1	5096749	03/16/2017	07/27/2018	07/27/2018
<i>Description: FORWARD AUX FUEL TANKS - MAIN FUEL LINE AND VENT LINE HAS SEALANT ON MAIN FITTINGS AND FUEL LINES TO PREVENT LEAKAGE.</i>					
Count: 1			1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-7.80.NR-10 Drawing: N/A 04/10/2017 07/24/2018				
<i>Description: #5 AUX FUEL TANK AFT FAILED CELL CORE VACUUM LEAK TEST 28-00-03.</i>				
80-10-Maintenance	1999M.AWR-7.80.NR-10.80-10	5098248	04/10/2017	07/24/2018 07/24/2018
<i>Description: #5 AUX FUEL TANK AFT FAILED CELL CORE VACUUM LEAK TEST 28-00-03.</i>				
Count: 1			1	1
Task Card: AWR-7.80.NR-11 Drawing: N/A 04/10/2017 07/10/2018				
<i>Description: FWD AUX FUEL SYSTEM SHROUD DRAIN LINE IN LH MLG WELL FWD SIDE IS LEAKING.</i>				
80-11-Maintenance	1999M.AWR-7.80.NR-11.80-11	5098249	04/10/2017	07/05/2018 07/10/2018
<i>Description: FWD AUX FUEL SYSTEM SHROUD DRAIN LINE IN LH MLG WELL FWD SIDE IS LEAKING.</i>				
Count: 1			1	1
Task Card: AWR-7.80.NR-12 Drawing: N/A 04/27/2017 11/02/2017				
<i>Description: LEFT WING INBRD & OTBRD FLAP TRACKS NEED CLEANING.</i>				
80-12-Maintenance	1999M.AWR-7.80.NR-12.80-12	5098424	04/27/2017	10/31/2017 11/02/2017
<i>Description: LEFT WING INBRD & OTBRD FLAP TRACKS NEED CLEANING.</i>				
Count: 1			1	1
Task Card: AWR-7.80.NR-13 Drawing: N/A 04/27/2017 05/10/2017				
<i>Description: #6 AUX FUEL TANK HAS DENT LESS THAN 1" FROM CORNER & PAINT THAT NEEDS REMOVED & TOUCHED UP.</i>				
80-13-Maintenance	1999M.AWR-7.80.NR-13.80-13	5098425	04/27/2017	05/10/2017 05/10/2017
<i>Description: #6 AUX FUEL TANK HAS DENT LESS THAN 1" FROM CORNER & PAINT THAT NEEDS REMOVED & TOUCHED UP.</i>				
Count: 1			1	1
Task Card: AWR-7.80.NR-14 Drawing: N/A 04/27/2017 07/24/2018				
<i>Description: #3 AUX FUEL TANK PAINT NEEDS TOUCH UP.</i>				
80-14-Maintenance	1999M.AWR-7.80.NR-14.80-14	5098426	04/27/2017	07/24/2018 07/24/2018
<i>Description: #3 AUX FUEL TANK PAINT NEEDS TOUCH UP.</i>				
Count: 1			1	1
Task Card: AWR-7.80.NR-15 Drawing: N/A 04/27/2017 11/17/2017				
<i>Description: #4 AUX TANK HAS DENTS IN THE RIGHT CORNER AFT SIDE & PAINT THAT NEEDS REMOVED & TOUCHED UP.</i>				
80-15-Maintenance	1999M.AWR-7.80.NR-15.80-15	5098499	04/27/2017	11/15/2017 11/17/2017
<i>Description: #4 AUX TANK HAS DENTS IN THE RIGHT CORNER AFT SIDE & PAINT THAT NEEDS REMOVED & TOUCHED UP.</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-7.80.NR-16 Drawing: N/A 11/06/2017 11/21/2017				
<i>Description:</i> Holes missing in floor beam for Aft baggage avionics rack LH Side Frame 807				
80-16-Maintenance	1999M.AWR-7.80.NR-16.80-16	5103093	11/06/2017	11/20/2017 11/21/2017
<i>Description:</i> Holes missing in floor beam for Aft baggage avionics rack LH Side Frame 807				
Count: 1			1	1
Task Card: AWR-7.80.NR-17 Drawing: N/A 11/02/2017 08/23/2018				
<i>Description:</i> Found structural tube fitting sheared on the inside of the #4 Pats tank (top left tube inside the R/H access panel) in the Fwd cargo compartment.				
80-17-Maintenance	1999M.AWR-7.80.NR-17.80-17	5103730	11/02/2017	08/21/2018 08/23/2018
<i>Description:</i> Found structural tube fitting sheared on the inside of the #4 Pats tank (top left tube inside the R/H access panel) in the Fwd cargo compartment.				
Count: 1			1	1
Task Card: AWR-7.80.NR-2 Drawing: N/A 03/16/2017 05/05/2017				
<i>Description:</i> #3A FORWARD AUX TANK FUEL SHROUD FITTING HAS FUEL DRAINING FROM IT.				
80-2-Maintenance	1999M.AWR-7.80.NR-2.80-2	5096754	03/16/2017	05/05/2017 05/05/2017
<i>Description:</i> #3A FORWARD AUX TANK FUEL SHROUD FITTING HAS FUEL DRAINING FROM IT.				
Count: 1			1	1
Task Card: AWR-7.80.NR-3 Drawing: N/A 03/16/2017				
<i>Description:</i> DURING TEST OF PATS TANKS FOUND AFT TANK DID NOT INDICATE LOW IN THE REQUIRED 9 TO 15 MINUTES AFTER THE DRY INDICATION WAS NOTED.				
80-3-Maintenance	1999M.AWR-7.80.NR-3.80-3	5096791	03/16/2017	
<i>Description:</i> DURING TEST OF PATS TANKS FOUND AFT TANK DID NOT INDICATE LOW IN THE REQUIRED 9 TO 15 MINUTES AFTER THE DRY INDICATION WAS NOTED.				
Count: 1			1	0
Task Card: AWR-7.80.NR-4 Drawing: N/A 03/16/2017 11/22/2017				
<i>Description:</i> DURING TEST OF PATS TANK FOUND FUEL LEAKING FROM SHROUD DRAIN MAST.				
80-4-Maintenance	1999M.AWR-7.80.NR-4.80-4	5096792	03/16/2017	11/22/2017 11/22/2017
<i>Description:</i> DURING TEST OF PATS TANK FOUND FUEL LEAKING FROM SHROUD DRAIN MAST.				
Count: 1			1	1
Task Card: AWR-7.80.NR-5 Drawing: N/A 03/16/2017 08/06/2018				
<i>Description:</i> CABIN MANAGEMENT EQUIPMENT IN AFT PIT REQUIRES REMOVAL FOR PATS TANK ACCESS.				
80-5-Maintenance	1999M.AWR-7.80.NR-5.80-5	5096793	03/16/2017	08/04/2018 08/06/2018
<i>Description:</i> CABIN MANAGEMENT EQUIPMENT IN AFT PIT REQUIRES REMOVAL FOR PATS TANK ACCESS.				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-7.80.NR-6		Drawing: N/A		03/16/2017
<i>Description:</i> DURING REMOVAL OF AFT PATS TANKS FOUND MOLD IN POTABLE WATER LINES AT SANITIZER.				
701-6-SYSTEM SHOP, FABRICATE	1999M.AWR-7.80.NR-6.701-6	5096876	03/16/2017	
<i>Description:</i> DURING REMOVAL OF AFT PATS TANKS FOUND MOLD IN POTABLE WATER LINES AT SANITIZER.				
Count: 1		1		0
Task Card: AWR-7.80.NR-7		Drawing: N/A		03/16/2017
<i>Description:</i> CARGO NET TIE DOWN FITTING IN THE AFT PIT IS MISSING 2EA NUTPLATES FWD OF CARGO DOOR TOP FITTINGS.				
80-7-Maintenance	1999M.AWR-7.80.NR-7.80-7	5097101	03/16/2017	04/04/2017
<i>Description:</i> CARGO NET TIE DOWN FITTING IN THE AFT PIT IS MISSING 2EA NUTPLATES FWD OF CARGO DOOR TOP FITTINGS.				
Count: 1		1		1
Task Card: AWR-7.80.NR-8		Drawing: N/A		04/05/2017
<i>Description:</i> #5 AUX FUEL TANK AFT FAILED CELL CORE VACUUM LEAK TEST 28-00-03.				
80-8-Maintenance	1999M.AWR-7.80.NR-8.80-8	5097926	04/05/2017	05/08/2017
<i>Description:</i> #5 AUX FUEL TANK AFT FAILED CELL CORE VACUUM LEAK TEST 28-00-03.				
Count: 1		1		1
Task Card: AWR-7.80.NR-9		Drawing: N/A		04/05/2017
<i>Description:</i> FWD AUX FUEL SYSTEM SHROUD DRAIN LINE IN L/H MLG WELL FWD SIDE IS LEAKING.				
80-9-Maintenance	1999M.AWR-7.80.NR-9.80-9	5097927	04/05/2017	11/22/2017
<i>Description:</i> FWD AUX FUEL SYSTEM SHROUD DRAIN LINE IN L/H MLG WELL FWD SIDE IS LEAKING.				
Count: 1		1		1
Task Card: AWR-7.801.NR-17		Drawing: N/A		07/11/2018
<i>Description:</i> Inspected #5 tank after removal and found a broken bonding bracket on the Aft RH side of the tank.				
801-18-Maintenance	1999M.AWR-7.801.NR-17.801-18	5112670	07/11/2018	07/19/2018
<i>Description:</i> Inspected #5 tank after removal and found a broken bonding bracket on the Aft RH side of the tank.				
Count: 1		1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: AWR-8		Drawing: AWR-8		
<i>Description:</i> Due to change in MX program comply with added work cards from CAMP				
801-35-Maintenance	0			
<i>Description:</i> budget				
801-Maintenance	1999M.AWR-8.801	5098378	04/18/2017	04/26/2017 04/26/2017
<i>Description:</i> COMPLY WITH EASA 2016-0167 PARA (1) REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION.				
801-1-Maintenance	1999M.AWR-8.801-1	5098379	04/18/2017	04/26/2017 04/26/2017
<i>Description:</i> COMPLY WITH EASA 2016-0163 APPLIANCE AD- EQUIPMENT/FURNISHINGS- CABIN ATTENDANT SEAT- MODIFICATION/REPLACEMENT.				
801-2-Maintenance	1999M.AWR-8.801-2	5098380	04/18/2017	04/26/2017 04/26/2017
<i>Description:</i> COMPLY WITH EASA 2014-0093 R1 PARA (1) AUTOFLIGHT - AUTOTHROTTLE SYSTEM - AUTOTHROTTLE COMPUTER REPLACEMENT, ALERT SERVICE BULLETIN				
801-3-Maintenance	1999M.AWR-8.801-3	5098381	04/18/2017	04/26/2017 04/26/2017
<i>Description:</i> COMPLY WITH FAA 2011-20-10 PARA (G) FLIGHT CONTROLS- RUDDER AND RUDDER TRIM CONTROL SYSTEM- WIRE BUNDLE W443 AND LEFT FORWARD RUDDER QUADRANT CLEARANCE INSPECTION, SERVICE BULLETIN				
801-4-Maintenance	1999M.AWR-8.801-4	5098382	04/18/2017	01/03/2018 01/05/2018
<i>Description:</i> COMPLY WITH FAA 2011-26-09 TO PREVENT FAILURE OF THE FIRE SEAL				
801-5-Maintenance	1999M.AWR-8.801-5	5098383	04/18/2017	04/26/2017 04/26/2017
<i>Description:</i> COMPLY WITH FAA 2011-27-03 PARA (G)(1)(2) LUBRICATE TO PREVENT AN UNDETECTED FAILURE OF THE PRIMARY LOAD PATH FOR THE BALLSCREW IN THE DRIVE MECHANISM OF THE HSTA AND SUBSEQUENT WEAR AND FAILURE OF THE SECONDARY LOAD PATH IN ACCORDANCE SERVICE BULLETIN 737-27A1277 R2.				
801-6-Maintenance	1999M.AWR-8.801-6	5098384	04/18/2017	05/01/2017 05/01/2017
<i>Description:</i> COMPLY WITH FAA 2016-18-01 PARA (G) LUBRICATE THE FORWARD AND AFT TRUNNION PIN ASSEMBLIES OF THE LEFT AND RIGHT MLG AND REPEAT				
801-7-Maintenance	1999M.AWR-8.801-7	5098385	04/18/2017	01/03/2018 01/05/2018
<i>Description:</i> COMPLY WITH FAA 2012-02-14 PARA (G) PERFORM TO PREVENT A FIRE IN THE FAN COMPARTMENT (A FIRE ZONE) FROM MIGRATING THROUGH THE SEAL TO A FLAMMABLE FLUID IN THE THRUST REVERSER ACTUATOR COMPARTMENT A ONE-TIME DETAILED INSPECTION TO DETERMINE THE COLOR OF THE AERO/FIRE SEALS OF THE BLOCKER DOORS ON THE THRUST REVERSER TORQUE BOXES ON THE ENGINES.				
801-8-Maintenance	1999M.AWR-8.801-8	5098386	04/18/2017	01/03/2018 01/05/2018
<i>Description:</i> COMPLY WITH FAA 2016-18-01 PARA (H) GENERAL VISUAL INSPECTION OF THE LEFT & RIGHT MLG AT THE FORWARD & AFT TRUNION PIN LOCATIONS AND THE VISIBLE SURFACES FOR SIGNS OF CORROSION OR CHROME PLATING DAMAGE & LUBRICATE THE FORWARD AND AFT TRUNION PIN ASSEMBLIES AND REPEAT (A/C GROUPS 1 & 2 CONFIGURATION 1, A/C 3 IN SB 737-32-1448 R1)				
801-9-Maintenance	1999M.AWR-8.801-9	5098387	04/18/2017	05/09/2017 05/09/2017
<i>Description:</i> COMPLY WITH FAA 2008-11-08 (F) TABLE 2 and FAA 2008-11-08 (F) TABLE 3 DETAIL INSPECTION DETECT AND CORRECT CRACKING IN THE VINYL INTERLAYER OR DAMAGE TO THE STRUCTURAL INNER GLASS PANES OF THE FLIGHT DECK NO.2, NO.4 AND NO.5 WINDOWS FOR CRACKING AND DAMAGE IN THE VINYL INTERLAYER AND GLASS PANES FOR FLIGHT DECK NUMBER 4 WINDOW, DETAIL INSPECTION DETECT AND CORRECT CRACKING IN THE VINYL INTERLAYER OR DAMAGE TO THE STRUCTURAL INNER GLASS PANES OF THE FLIGHT DECK NO.2, NO.4 AND NO.5 WINDOWS FOR CRACKING AND DAMAGE IN THE VINYL INTERLAYER AND GLASS PANES FOR FLIGHT DECK NUMBER 5 WINDOW				
801-10-Maintenance	1999M.AWR-8.801-10	5098388	04/18/2017	05/01/2017 05/01/2017



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> COMPLY WITH FAA 2015-08-07 PARA (G) INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011				
801-11-Maintenance	1999M.AWR-8.801-11	5098389	04/18/2017	05/08/2017
<i>Description:</i> COMPLY WITH FAA 2015-08-07 PARA (H) REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES				
801-12-Maintenance	1999M.AWR-8.801-12	5098390	04/18/2017	05/01/2017
<i>Description:</i> COMPLY WITH FAA 2016-13-16 PARA (G)(1) RECORDS CHECK TO DETERMINE IF AN AFFECTED HORIZONTAL STABILIZER IS INSTALLED AND IF ANY HORIZONTAL STABILIZER HAS BEEN EXCHANGED, AND ACCOMPLISH ALL APPLICABLE RELATED INVESTIGATIVE ACTIONS AND INSPECTION OF THE HORIZONTAL STABILIZER IDENTIFICATION PLATE TO DETERMINE IF ANY AFFECTED HORIZONTAL STABILIZER IS INSTALLED				
801-13-Maintenance	1999M.AWR-8.801-13	5098391	04/18/2017	05/01/2017
<i>Description:</i> COMPLY WITH FAA 2016-13-16 PARA (G)(2) HIGH FREQUENCY EDDY CURRENT INSPECTION FOR ANY CRACK OF THE HORIZONTAL STABILIZER REAR SPAR UPPER CHORD AND APPLICABLE CORRECTIVE ACTIONS (IF, DURING ANY ACTION REQUIRED BY PARA (G)(1)(I) OR (G)(1)(II) ANY AFFECTED HORIZONTAL STABILIZER IS FOUND)				
801-14-Maintenance	1999M.AWR-8.801-14	5098392	04/18/2017	02/16/2018
<i>Description:</i> COMPLY WITH FAA AD 2013-02-05 (G) & (J) INSTALL INSTRUMENTS - TO PREVENT FAILURE OF THE FLIGHTCREW TO RECOGNIZE AND REACT TO A VALID CABIN ALTITUDE WARNING HORN TWO WARNING LEVEL INDICATOR LIGHTS ON EACH OF THE P1-3 AND P3-1 INSTRUMENT PANELS IN THE FLIGHT COMPARTMENT, AND, AS APPLICABLE, REPLACE THE EXISTING P5-16 AND P5-10 PANELS, PERFORM INSTRUMENTS - TO PREVENT FAILURE OF THE FLIGHTCREW TO RECOGNIZE AND REACT TO A VALID CABIN ALTITUDE WARNING HORN THE ACTIONS SPECIFIED IN PARAGRAPHS (J)(1), (J)(2), AND (J)(3) OF THIS AD				
801-15-Maintenance	1999M.AWR-8.801-15	5098393	04/18/2017	05/10/2017
<i>Description:</i> COMPLY WITH ASB 737-22A1215 AUTOFLIGHT - AUTOTHROTTLE SYSTEM - AUTOTHROTTLE COMPUTER REPLACEMENT, ALERT SERVICE BULLETIN				
801-16-Maintenance	1999M.AWR-8.801-16	5098394	04/18/2017	05/01/2017
<i>Description:</i> COMPLY WITH ASB 737-57A1327 R1 WINGS - LEADING EDGE AND LEADING EDGE DEVICES - KRUEGER FLAP INSPECTION, ALERT SERVICE BULLETIN				
801-17-Maintenance	1999M.AWR-8.801-17	5098395	04/18/2017	05/01/2017
<i>Description:</i> COMPLY WITH ASB 737-29A1119 R1 HYDRAULIC POWER - HYDRAULIC SYSTEMS A AND B - WIRE BUNDLES AND HYDRAULIC TUBE CLAMP INSTALLATION, ALERT SERVICE BULLETIN				
801-18-Maintenance	1999M.AWR-8.801-18	5098396	04/18/2017	01/04/2018
<i>Description:</i> COMPLY WITH SB 9737B3503 ASSOCIATED AIR CENTER - PASSENGER OXYGEN SYSTEM - LEAK CHECK, SERVICE BULLETIN				
801-19-Maintenance	1999M.AWR-8.801-19	5098397	04/18/2017	11/22/2017
<i>Description:</i> COMPLY WITH 26-450-00 (001.1) DETAILED INSPECTION (COCKPIT) PORTABLE HALON EXTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION				
801-20-Maintenance	1999M.AWR-8.801-20	5098398	04/18/2017	11/22/2017
<i>Description:</i> COMPLY WITH 26-450-00 (003.1) DETAILED INSPECTION FWD ENTRY DOOR PORTABLE HALON EXTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION.				
801-21-Maintenance	1999M.AWR-8.801-21	5098399	04/18/2017	05/01/2017
<i>Description:</i> COMPLY WITH 27-102-00 LUBRICATE STABILIZER TRIM ACTUATOR AND ACTUATOR GIMBAL PINS AND BALLNUT				
801-22-Maintenance	1999M.AWR-8.801-22	5098400	04/18/2017	11/06/2017



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> COMPLY WITH 323106 FUNCTIONAL CHECK LANDING GEAR CONTROL CABLE TENSION				
801-23-Maintenance	1999M.AWR-8.801-23	5098401	04/18/2017	05/01/2017 05/01/2017
<i>Description:</i> COMPLY WITH 10536-0214 NO. 1 ENGINE - INSPECTION ON WING (NON ROUTINE) OF OUTBOARD FWD LUG BUSHING MIGRATION				
801-24-Maintenance	1999M.AWR-8.801-24	5098402	04/18/2017	05/01/2017 05/01/2017
<i>Description:</i> COMPLY WITH 23-060-00 OPERATIONAL CHECK OF THE ULB				
801-25-Maintenance	1999M.AWR-8.801-25	5098403	04/18/2017	05/09/2017 05/09/2017
<i>Description:</i> COMPLY WITH 34-110-00 FUNCTIONAL CHECK AIRCRAFT'S ATC SYSTEM (NOTE: TASK MEETS INTENT OF FAR 91.413)				
801-26-Maintenance	1999M.AWR-8.801-26	5098404	04/18/2017	05/09/2017 05/09/2017
<i>Description:</i> COMPLY WITH 341105 TEST STANDBY ALTIMETER INDICATOR PER FAR 91.411				
801-27-Maintenance	1999M.AWR-8.801-27	5098405	04/18/2017	05/09/2017 05/09/2017
<i>Description:</i> COMPLY WITH 341111 TEST NO. 1 ATC TRANSPONDER PER FAR 91.413				
801-28-Maintenance	1999M.AWR-8.801-28	5098406	04/18/2017	05/09/2017 05/09/2017
<i>Description:</i> COMPLY WITH 341112 TEST NO. 2 ATC TRANSPONDER PER FAR 91.413				
801-29-Maintenance	1999M.AWR-8.801-29	5098407	04/18/2017	
<i>Description:</i> COMPLY WITH 50014 A3 CHECK				
801-30-Maintenance	1999M.AWR-8.801-30	5098408	04/18/2017	05/01/2017 05/01/2017
<i>Description:</i> COMPLY WITH 53-070-00 INSPECT (INTERNAL-GENERAL VISUAL) AREA FORWARD OF NOSE WHEEL WELL INSPECT FUSELAGE LOWER LOBE FROM STA 178 BULKHEAD TO CANTED BULKHEAD (STA 224.8 TO 227.8), INCLUDING BULKHEADS, SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, FORWARD ACCESS DOOR CUTOUT, AND NOSE WHEEL WELL CUTOUT				
801-31-Maintenance	1999M.AWR-8.801-31	5098409	04/18/2017	05/01/2017 05/01/2017
<i>Description:</i> COMPLY WITH 53-120-00 INSPECT (INTERNAL-GENERAL VISUAL ELECTRICAL/ELECTRONIC COMPARTMENT, STATION 294.5 TO 396 INCLUDING: 1. SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, CIRCUMFERENTIAL SKIN AND STRINGER SPLICES, BULKHEAD AT STA. 294.5; 2. EE COMPARTMENT DOOR AND AIRSTAIRS DOOR CUTOUT SURROUND STRUCTURE; 3. FORWARD ENTRY AND GALLEY DOOR CUTOUT SURROUND STRUCTURE (PORTION IN LOWER LOBE).				
801-32-Maintenance	1999M.AWR-8.801-32	5098410	04/18/2017	01/12/2018 01/16/2018
<i>Description:</i> COMPLY WITH 24-120-00 (001.1) RESTORE MAIN BATTERY				
801-33-Maintenance	1999M.AWR-8.801-33	5098411	04/18/2017	01/12/2018 01/16/2018
<i>Description:</i> COMPLY WITH 24-120-00 (002.1) RESTORE AUXILIARY BATTERY				
801-34-Maintenance	1999M.AWR-8.801-34	5098412	04/18/2017	01/04/2018 01/05/2018
<i>Description:</i> COMPLY WITH Discrepancy 151207-1 (Replace second Antenna, MEL Item, ref 23-18-CAT D).				
801-35-Maintenance	1999M.AWR-8.801-35	5105526		01/11/2018 01/11/2018
<i>Description:</i> During passenger O2 system leak check, found to leak beyond allowable limits				
Count: 37			35	35



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed	
Task Card: AWR-8.801-18.NR-2		Drawing: N/A		12/04/2017	04/16/2018
<i>Description: During passenger O2 system leak check , found leak rate to be beyond limits</i>					
801-36-Maintenance	1999M.AWR-8.801-18.NR-2.80 1-36	5105550	12/04/2017	04/13/2018	04/16/2018
<i>Description: During passenger O2 system leak check , found leak rate to be beyond limits</i>					
Count: 1			1		1
Task Card: AWR-9		Drawing: N/A		05/24/2017	10/19/2017
<i>Description: Customer request- perform test 5 engine runs</i>					
807-MAINTENANCE, AWR	1999M.AWR-9.807	5099187	05/24/2017	05/31/2017	10/19/2017
<i>Description: Customer request- perform test 5 engine runs</i>					
Count: 1			1		1
Task Card: HIRF/L Inspections		Drawing: N/A		12/12/2016	03/16/2017
<i>Description: HIRF/L Inspections</i>					
505-AVIONICS, Mx	1999M.4A.50	5093957	12/12/2016	03/16/2017	03/16/2017
<i>Description: 20-020-00:GENERAL VISUAL INSPECTION OF HIRF/L SENSITIVE WIRE RUNS INSIDE THE PRESSURE VESSEL. LOOK FOR OBVIOUS DAMAGE AND CONDITION OF SECURITY OF WIRE RUNS</i>					
505-1-AVIONICS, Mx	1999M.4A.50-1	5093958	12/12/2016	03/14/2017	03/14/2017
<i>Description: 20-050-00: DETAILED VISUAL INSPECTION OF HIRF/L SENSITIVE CONNECTORS INSIDE THE PRESSURE VESSEL. DURING THE INSPECTION DO NOT DISCONNECT CONNECTORS. LOOK FOR CONDITION, SECURITY, AND SIGNS OF CORROSION</i>					
505-2-AVIONICS, Mx	1999M.4A.50-2	5093959	12/12/2016	03/14/2017	03/14/2017
<i>Description: 20-060-00: FUNCTIONAL CHECK OF HIRF/L. SENSITIVE CONNECTORS INSIDE THE PRESSURE VESSEL BY DC RESISTANCE CHECK FROM BACKSHELL TO GROUND.</i>					
505-3-AVIONICS, Mx	1999M.4A.50-3	5093960	12/12/2016	03/14/2017	03/14/2017
<i>Description: 20-070-00: DETAILED VISUAL INSPECTION OF THE HIRF/L SENSITIVE PIG TAILS INSIDE THE PRESSURE VESSEL. LOOK FOR CONDITION OF SECURITY AND SIGNS OF CORROSION.</i>					
Count: 4			4		4



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: Monthly		Drawing: N/A		12/12/2016
<i>Description: Monthly Check</i>				
505-AVIONICS, Mx	1999M.1D.50	5093961	12/12/2016	02/23/2017 02/23/2017
<i>Description: 24-100-00: OPERATIONAL CHECK OF THE STANDBY POWER CONTROL UNIT (SPCU).</i>				
505-1-AVIONICS, Mx	1999M.1D.50-1	5093962	12/12/2016	02/23/2017 02/23/2017
<i>Description: 34-50-05: ACCOMPLISH VOR CHECK AS PER FAR 91.171 (A)(2).</i>				
505-2-AVIONICS, Mx	1999M.1D.50-2	5093963	12/12/2016	03/14/2017 03/14/2017
<i>Description: 34-BBJ-01: SERVICE HEADS UP DISPLAY OVERHEAD UNIT DESICCANT CAPSULE</i>				
805-Mx Interiors	1999M.1D.805	5093964	12/12/2016	06/27/2018 06/28/2018
<i>Description: 267001: GENERAL VISUAL INSPECTION ALL PORTABLE FIRE EXTINGUISHERS FOR LOCATION, GENERAL CONDITION AND CHARGE INDICATION</i>				
80-1-Maintenance	1999M.1D.80-1	5093965	12/12/2016	03/27/2017 03/27/2017
<i>Description: 32-350-00: CHECK NOSE AND MAIN LANDING GEAR TIRES FOR PROPER INFLATION, SERVICE AS REQUIRED</i>				
80-2-Maintenance	1999M.1D.80-2	5093966	12/12/2016	04/14/2017 04/14/2017
<i>Description: 32-360-00: VISUAL CHECK NOSE AND MAIN LANDING GEAR TIRES AND WHEELS FOR CONDITION AND WEAR.</i>				
80-3-Maintenance	1999M.1D.80-3	5093967	12/12/2016	03/27/2017 03/27/2017
<i>Description: 32-430-00: VISUAL CHECK OF THE TAIL SKID CRUSHABLE CARTRIDGE FOR EVIDENCE OF A TAIL STRIKE</i>				
80-4-Maintenance	1999M.1D.80-4	5093968	12/12/2016	
<i>Description: 050002: MONTHLY CHECK COMPLETED.</i>				
Count: 8			8	7



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: OOP		Drawing: N/A		12/12/2016
<i>Description: Perform Customer Requested Out of Phase Inspection Tasks</i>				
505-AVIONICS, Mx	1999M.3A.50	5093982	12/12/2016	01/08/2018 01/09/2018
<i>Description: 34-046-01S UPGRADE EGPWS SOFTWARE</i>				
505-1-AVIONICS, Mx	1999M.3A.50-1	5093983	12/12/2016	
<i>Description: 347101 UPDATE NAV DATABASE</i>				
80-Maintenance	1999M.3A.80	5093984	12/12/2016	02/23/2017 10/19/2017
<i>Description: 25-380-00 OPERATIONALLY CHECK THE EMERGENCY FLASHLIGHTS.</i>				
80-1-Maintenance	1999M.3A.80-1	5093985	12/12/2016	01/11/2018 01/12/2018
<i>Description: 25-390-00: REPLACE THE EMERGENCY FLASHLIGHT (NON-RECHARGEABLE) BATTERIES AT THE MANUFACTURER'S RECOMMENDED INTERVAL.</i>				
805-2-Mx Interiors	1999M.3A.805-2	5093986	12/12/2016	06/22/2018 06/25/2018
<i>Description: 25-410-00 (002.1) RESTORE FWD (PBE) SMOKE HOOD</i>				
80-3-Maintenance	1999M.3A.80-3	5093987	12/12/2016	01/09/2018 01/10/2018
<i>Description: 25-420-00 (001.1) RESTORE FWD FIRST AID KIT</i>				
80-4-Maintenance	1999M.3A.80-4	5093988	12/12/2016	01/09/2018 01/10/2018
<i>Description: 25-420-00 (002.1) RESTORE AFT FIRST AID KIT</i>				
80-5-Maintenance	1999M.3A.80-5	5093989	12/12/2016	01/08/2018 01/09/2018
<i>Description: 25-430-00 (001.1) RESTORE MEDICAL KIT</i>				
80-7-Maintenance	1999M.3A.80-7	5093990	12/12/2016	11/21/2017 11/21/2017
<i>Description: 26-450-00 (002.1): DETAILED INSPECTION AFT GALLEY CABINET PORTABLE HALON EXTINGUISHER FOR PROPER PRESSURE (IF GAUGE INSTALLED), WEIGHT, AND CONDITION.</i>				
80-9-Maintenance	1999M.3A.80-9	5093991	12/12/2016	11/22/2017 11/22/2017
<i>Description: 26-470-00: INSPECT (DETAILED) THE PORTABLE WATER FIRE EXTINGUISHERS CONDITION. (IF INSTALLED).</i>				
80-10-Maintenance	1999M.3A.80-10	5093992	12/12/2016	01/02/2018 01/04/2018
<i>Description: 26-481-00 (002.1): HYDROSTATIC TEST PORTABLE WATER FIRE EXTINGUISHER (OFF AIRCRAFT , IF INSTALLED)</i>				
80-12-Maintenance	1999M.3A.80-12	5093993	12/12/2016	08/21/2018 08/23/2018
<i>Description: 28-10-01 PATS PERFORM CORE VACUUM CHECK OF INDIVIDUAL AUXILIARY FUEL CELLS</i>				
80-13-Maintenance	1999M.3A.80-13	5093994	12/12/2016	04/04/2017 04/04/2017
<i>Description: 28-10-02 PATS: DETAILED INSPECTION AUXILIARY FUEL CELL EXTERIOR STRUCTURE (INCLUDING DOORS/PANELS) FOR DAMAGE AND CONDITION</i>				
80-14-Maintenance	1999M.3A.80-14	5093995	12/12/2016	05/02/2018 05/10/2018
<i>Description: 28-130-00 (001.1): REPLACE EMERGENCY FUEL SHUTOFF BATTERY</i>				
80-15-Maintenance	1999M.3A.80-15	5093996	12/12/2016	04/04/2017 04/04/2017
<i>Description: 28-20-06 PATS: GENERAL VISUAL INSPECTION OF THE AUXILIARY FUEL SYSTEM CELL INTERNAL HORIZONTAL AND VERTICAL STRUCTURAL TUBES AND ALL ATTACHMENTS FOR CRACKS AND LOOSE FASTNERS.</i>				
80-21-Maintenance	1999M.3A.80-21	5094003	12/12/2016	03/03/2017 03/03/2017
<i>Description: 29-230-00: OPERATIONAL CHECK STANDBY RUDDER SYSTEM TO INCLUDE OBSERVING LOW PRESSURE LIGHT ILLUMINATION AND THEN EXTINGUISHING.</i>				
805-22-Mx Interiors	1999M.3A.805-22	5094004	12/12/2016	08/25/2018



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> 33-010-010 REPLACE SELF - ILLUMINATED EXIT SIGNS				
80-23-Maintenance	1999M.3A.80-23	5094005	12/12/2016	04/13/2018 04/16/2018
<i>Description:</i> 350451 (001.2) DISCARD NO. 1 PASSENGER OXYGEN BOTTLE				
80-24-Maintenance	1999M.3A.80-24	5094006	12/12/2016	04/13/2018 04/16/2018
<i>Description:</i> 350451 (002.2) DISCARD NO. 2 PASSENGER OXYGEN BOTTLE				
80-25-Maintenance	1999M.3A.80-25	5094007	12/12/2016	04/04/2017 04/04/2017
<i>Description:</i> 53-110-00: INSPECT (INTERNAL-GENERAL VISUAL) PASSENGER COMPARTMENT FLOOR STRUCTURE IN WET AREA (WITHIN APPROXIMATELY 20 INCHES FROM DOORS, GALLEYS AND LAVS) FROM LOWER LOBE.				
80-26-Maintenance	1999M.3A.80-26	5094008	12/12/2016	03/16/2017 03/16/2017
<i>Description:</i> 53-130-00: INSPECT (INTERNAL-GENERAL VISUAL) FORWARD CARGO COMPARTMENT SKIN PANELS (SKINS, FRAMES AND STRINGERS). [NOTE: INSPECTION INCLUDES THE CIRCUMFERENTIAL SKIN AND STRINGER SPLICE AT STA 500E FOR THE -900ER MODELS].				
80-27-Maintenance	1999M.3A.80-27	5094009	12/12/2016	03/16/2017 03/16/2017
<i>Description:</i> 53-160-00: INSPECT (INTERNAL-GENERAL VISUAL) FORWARD BILGE SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, AND CARGO DOOR CUTOUT SURROUND STRUCTURE IN BILGE. [NOTE: INSPECTION INCLUDES THE CIRCUMFERENTIAL SKIN AND STRINGER SPLICE AT STA 500E FOR THE -900ER MODELS]				
80-28-Maintenance	1999M.3A.80-28	5094010	12/12/2016	03/16/2017 03/16/2017
<i>Description:</i> 53-170-00: INSPECT (INTERNAL-GENERAL VISUAL) AREA AFT OF FORWARD CARGO COMPARTMENT, INCLUDING SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, CIRCUMFERENTIAL SKIN AND STRINGER SPLICES AND FORWARD SIDE OF STA 540 BULKHEAD AND BULKHEAD SPLICES				
80-29-Maintenance	1999M.3A.80-29	5094011	12/12/2016	04/04/2017 04/04/2017
<i>Description:</i> 53-230-00: INSPECT (INTERNAL-GENERAL VISUAL) AFT CARGO COMPARTMENT INCLUDING: 1. SIDE SKIN PANELS (SKIN, FRAMES, STRINGERS), CIRCUMFERENTIAL SKIN AND STRINGER SPLICES; [NOTE: LOCATED AT STA 7271 FOR -900ER AND 727L FOR -900ER MODELS]; 2. STRINGER 18 STRAP AT SIDE OF BODY; 3. STRINGER 18A WEB, CHORD AND LINKS; 4. AFT SIDE OF STA 727 BULKHEAD AND PRESSURE WEB.				
80-30-Maintenance	1999M.3A.80-30	5094012	12/12/2016	04/04/2017 04/04/2017
<i>Description:</i> 53-250-00: INSPECT (INTERNAL-GENERAL VISUAL) AFT BILGE SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, CIRCUMFERENTIAL SKIN AND STRINGER SPLICES, [NOTE: LOCATED AT STA 727I FOR -900ER AND 727L FOR -900ER MODELS]; STA 727 BULKHEAD AND PRESSURE WEB, AND CARGO DOOR CUTOUT SURROUND STRUCTURE IN BILGE.				
80-31-Maintenance	1999M.3A.80-31	5094013	12/12/2016	04/04/2017 04/04/2017
<i>Description:</i> 53-260-00: INSPECT (INTERNAL-GENERAL VISUAL) AREA AFT OF CARGO COMPARTMENT INCLUDING: 1. SKIN PANELS (SKINS, FRAMES, STRINGERS), LONGITUDINAL LAP SPLICES, CIRCUMFERENTIAL SKIN AND STRINGER SPLICES; 2. AFT ENTRY AND GALLEY DOOR CUTOUT SURROUND STRUCTURE IN LOWER LOBE; 3. STA 1016 BULKHEAD, INCLUDING CHORDS, PRESSURE WEB, STIFFENERS, CHORD/WEB ATTACHMENTS; 4. STRINGER SPLICE FITTINGS AND TENSION BOLTS AT STA 1016.				
80-32-Maintenance	1999M.3A.80-32	5094014	12/12/2016	04/21/2017 04/21/2017
<i>Description:</i> 53-380-00: INSPECT (INTERNAL-GENERAL VISUAL) PASSENGER COMPARTMENT FLOOR STRUCTURE IN WET AREA (WITHIN APPROXIMATELY 20 INCHES FROM DOORS, GALLEYS AND LAVS AND THE FLOOR STRUCTURE BELOW THE DOOR TO AND INCLUDING THE FIRST FRAME FROM THE DOOR).				



Work Order Detail

Project: 1999M
Aircraft: 737 - 32806
Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
80-33-Maintenance <i>Description:</i> 53-390-00: INSPECT (INTERNAL-GENERAL VISUAL) PASSENGER COMPARTMENT FLOOR STRUCTURE WET AREA (WITHIN APPROXIMATELY 20 INCHES FROM DOORS, GALLEYS AND LAVS AND THE FLOORS STRUCTURE BELOW THE DOOR TO AND INCLUDING THE FIRST FRAME FROM THE DOOR).	1999M.3A.80-33	5094015	12/12/2016	04/05/2017 04/05/2017
80-34-Maintenance <i>Description:</i> 53-814-00: INTERNAL ZONAL INSPECTION (GV) AREA ABOVE FORWARD CARGO COMPARTMENT - SECTION 43, STATION 396 TO FORWARD CARGO COMPARTMENT AFT BULKHEAD	1999M.3A.80-34	5094016	12/12/2016	04/04/2017 04/04/2017
80-35-Maintenance <i>Description:</i> 53-820-00: INTERNAL ZONAL INSPECTION (GV) AREA BELOW THE FORWARD CARGO COMPARTMENT - SECTION 43, STATION 396 TO FORWARD CARGO COMPARTMENT AFT BULKHEAD (EZAP)	1999M.3A.80-35	5094017	12/12/2016	03/16/2017 03/16/2017
80-36-Maintenance <i>Description:</i> 53-822-00: INTERNAL ZONAL INSPECTION (GV) AIR CONDITIONING DISTRIBUTION BAY - SECTION 43, FORWARD CARGO COMPARTMENT TO STATION 540 (EZAP)	1999M.3A.80-36	5094018	12/12/2016	03/16/2017 03/16/2017
80-37-Maintenance <i>Description:</i> 53-826-00: INTERNAL ZONAL INSPECTION (GV) PRESSURE DECK ABOVE THE MAIN LANDING GEAR WHEEL WELL - SECTION 44, STATION 663.75 TO STATION 727 (EZAP)	1999M.3A.80-37	5094019	12/12/2016	
80-38-Maintenance <i>Description:</i> 53-832-00: INTERNAL ZONAL INSPECTION (GV) AFT CARGO COMPARTMENT - SECTION 46 AND 47, (PART) STATION 727 TO STATION 947.5	1999M.3A.80-38	5094020	12/12/2016	04/04/2017 04/04/2017
80-39-Maintenance <i>Description:</i> 53-840-00: INTERNAL ZONAL INSPECTION (GV) AREA BELOW THE AFT CARGO COMPARTMENT - SECTION 46 AND 47 (PART), STATION 727 TO STATION 947.5 (EZAP)	1999M.3A.80-39	5094021	12/12/2016	04/04/2017 04/04/2017
80-40-Maintenance <i>Description:</i> 539108: DETAILED INSPECTION OF GALLEYS ATTACH BRACKETS, TIE-RODS, FITTINGS AND HARDWARE. GENERAL VISUAL INSPECTION OF LATCHES, HINGES AND GENERAL CONDITION WITH UNITS REMOVED	1999M.3A.80-40	5094022	12/12/2016	01/08/2018 01/09/2018
80-41-Maintenance <i>Description:</i> 55-080-01: INSPECT (INTERNAL-GENERAL VISUAL) LEFT HORIZONTAL STABILIZER FRONT SPAR TERMINAL FITTINGS AND CENTER SECTION FRONT SPAR LUGS-	1999M.3A.80-41	5094023	12/12/2016	04/21/2017 04/21/2017
80-42-Maintenance <i>Description:</i> 55-080-02: INSPECT (INTERNAL-GENERAL VISUAL) RIGHT HORIZONTAL STABILIZER FRONT SPAR TERMINAL FITTINGS AND CENTER SECTION FRONT SPAR LUGS-	1999M.3A.80-42	5094024	12/12/2016	04/21/2017 04/21/2017
80-43-Maintenance <i>Description:</i> 55-120-01: INSPECT (INTERNAL-GENERAL VISUAL) LEFT HORIZONTAL STABILIZER REAR SPAR TERMINAL FITTINGS AND CENTER SECTION REAR SPAR LUGS-	1999M.3A.80-43	5094025	12/12/2016	04/21/2017 04/21/2017
80-44-Maintenance <i>Description:</i> 55-120-02: INSPECT (INTERNAL-GENERAL VISUAL) RIGHT HORIZONTAL STABILIZER REAR SPAR TERMINAL FITTINGS AND CENTER SECTION REAR SPAR LUGS-	1999M.3A.80-44	5094026	12/12/2016	04/21/2017 04/21/2017
80-45-Maintenance <i>Description:</i> 57-030-00: INSPECT (EXTERNAL-GENERAL VISUAL) AFT SIDE OF REAR SPAR, INCLUDING KEEL BEAM STIFFENERS AT BL 6.2, AND SIDE OF BODY REAR SPAR TERMINAL FITTING.	1999M.3A.80-45	5094027	12/12/2016	04/05/2017 04/05/2017
80-46-Maintenance	1999M.3A.80-46	5094028	12/12/2016	04/05/2017 04/05/2017



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description: 57-050-00: INSPECT (INTERNAL-GENERAL VISUAL) FORWARD SIDE OF FRONT SPAR, INCLUDING SIDE OF BODY/TERMINAL FITTING ATTACHMENTS</i>				
80-47-Maintenance	1999M.3A.80-47	5094029	12/12/2016	
<i>Description: 72-00-00: ENGINES COMPRESSOR WASH</i>				
Count: 42		42		38
Task Card: OOP.80-1.NR-1		Drawing: N/A	11/20/2017	01/05/2018
<i>Description: During replacement of AirStair outer door lockpin found locking mechanism contacting door warning proximity sensor wiring.</i>				
80-55-Maintenance	1999M.OOP.80-1.NR-1.80-55	5103068	11/20/2017	01/04/2018 01/05/2018
<i>Description: During replacement of AirStair outer door lockpin found locking mechanism contacting door warning proximity sensor wiring.</i>				
Count: 1		1		1
Task Card: OOP.80-12.NR-1		Drawing: N/A	08/06/2018	08/09/2018
<i>Description: remove batteries for FOM</i>				
801-56-Maintenance	1999M.OOP.80-12.NR-1.801-56	5113678	08/06/2018	08/08/2018 08/09/2018
<i>Description: remove batteries for FOM</i>				
Count: 1		1		1
Task Card: OOP.80-13.NR-1		Drawing: N/A	03/16/2017	06/08/2018
<i>Description: #7 AUX TANK HAS A DENT IN ONE OF THE CORNERS.</i>				
80-49-Maintenance	1999M.OOP.80-13.NR-1.80-49	5097217	03/16/2017	06/06/2018 06/08/2018
<i>Description: #7 AUX TANK HAS A DENT IN ONE OF THE CORNERS.</i>				
Count: 1		1		1
Task Card: OOP.80-13.NR-2		Drawing: N/A	04/05/2017	05/07/2018
<i>Description: ALL 3 TANKS EXTERIOR RIVETS ON EDGES ARE SHOWING SIGNS OF CHAFFING SEE RED MARKED RIVETS.</i>				
80-50-Maintenance	1999M.OOP.80-13.NR-2.80-50	5097852	04/05/2017	05/05/2018 05/07/2018
<i>Description: ALL 3 TANKS EXTERIOR RIVETS ON EDGES ARE SHOWING SIGNS OF CHAFFING SEE RED MARKED RIVETS.</i>				
Count: 1		1		1
Task Card: OOP.80-13.NR-3		Drawing: N/A	04/05/2017	11/22/2017
<i>Description: FWD BAY AFT TANK WIRE HARNESS 22248-29 IS MISSING CHAFING SLEEVE NEED REPLACED AND BARE WIRE INSULATIONS EXPOSED.</i>				
80-51-Maintenance	1999M.OOP.80-13.NR-3.80-51	5097853	04/05/2017	11/22/2017 11/22/2017
<i>Description: FWD BAY AFT TANK WIRE HARNESS 22248-29 IS MISSING CHAFING SLEEVE NEED REPLACED AND BARE WIRE INSULATIONS EXPOSED.</i>				
Count: 1		1		1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: OOP.80-32.NR-1 Drawing: N/A 04/27/2017 04/26/2018				
<i>Description: FOUND CORRISION ON TWO SEAT TRACKS AND 11 SETS OF SEATTRACK HARDWARE LOCATED BETWEEN FS 727B TO 727G.</i>				
80-52-Maintenance	1999M.OOP.80-32.NR-1.80-52	5098427	04/27/2017	04/25/2018 04/26/2018
<i>Description: FOUND CORRISION ON TWO SEAT TRACKS AND 11 SETS OF SEATTRACK HARDWARE LOCATED BETWEEN FS 727B TO 727G.</i>				
Count: 1			1	1
Task Card: OOP.80-32.NR-2 Drawing: N/A 04/27/2017 01/05/2018				
<i>Description: FOUND 2 FLOOR PANELS BETWEEN FS 727B AND 727G THAT HAVE INSERTS PULLED OUT OF THE PANEL AND ARE STILL SCREWED TO FRAME.</i>				
80-53-Maintenance	1999M.OOP.80-32.NR-2.80-53	5098428	04/27/2017	01/04/2018 01/05/2018
<i>Description: FOUND 2 FLOOR PANELS BETWEEN FS 727B AND 727G THAT HAVE INSERTS PULLED OUT OF THE PANEL AND ARE STILL SCREWED TO FRAME.</i>				
Count: 1			1	1
Task Card: OOP.80-32.NR-3 Drawing: N/A 04/27/2017 11/07/2017				
<i>Description: FOUND MINOR SURFACE CORROSION AND PAINT MISSING FROM THE L/H AFT DOOR (L2) BASEBOARD WHERE IT CONNECTS FLOOR STRUCTURE.</i>				
80-54-Maintenance	1999M.OOP.80-32.NR-3.80-54	5098429	04/27/2017	11/06/2017 11/07/2017
<i>Description: FOUND MINOR SURFACE CORROSION AND PAINT MISSING FROM THE L/H AFT DOOR (L2) BASEBOARD WHERE IT CONNECTS FLOOR STRUCTURE.</i>				
Count: 1			1	1
Task Card: OOP.80-34.NR-1 Drawing: N/A 03/16/2017 11/07/2017				
<i>Description: 5 BROKEN NUTPLATE IN FWD PIT AREA (MARKED).</i>				
80-48-Maintenance	1999M.OOP.80-34.NR-1.80-48	5097104	03/16/2017	11/06/2017 11/07/2017
<i>Description: 5 BROKEN NUTPLATE IN FWD PIT AREA (MARKED).</i>				
Count: 1			1	1



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
Task Card: SB's and AD's		Drawing: N/A	12/12/2016	
<i>Description: Perform requested Service Bulletins and AD's</i>				
80-Maintenance	1999M.2A.80	5093969	12/12/2016	01/13/2018 01/16/2018
<i>Description: 737-28A1248 R3: FUEL - ENGINE FUEL FEED SYSTEM - CENTER FUEL TANK, FUEL PUMPS - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED PUMP ON) - RELAYS INSTALLATION, ALERT SERVICE BULLETIN</i>				
80-1-Maintenance	1999M.2A.80-1	5093970	12/12/2016	
<i>Description: 737-55A1097 TBL 1.1: PERFORM STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR UPPER CHORD INSPECTION, ALERT SERVICE BULLETIN HORIZONTAL STABILIZER IDENTIFICATION, OPTION 1: RECORDS CHECK OR OPTION 2: HORIZONTAL STABILIZER IDENTIFICATION PLATE INSPECTION (GROUP 1)</i>				
80-2-Maintenance	1999M.2A.80-2	5093971	12/12/2016	03/09/2017 03/09/2017
<i>Description: 737-55A1097 TBL 1.3 & 4: PERFORM STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR UPPER CHORD INSPECTION, ALERT SERVICE BULLETIN AN HFEC INSPECTION OF THE HORIZONTAL STABILIZER REAR SPAR UPPER CHORD FOR ANY CRACK (OPTION 1: TO DETECT ANY CRACK 0.100 INCH OR GREATER) OR (OPTION 2: TO DETECT ANY CRACK 0.200 INCH OR GREATER) (GROUP 1)</i>				
80-3-Maintenance	1999M.2A.80-3	5093972	12/12/2016	03/09/2017 03/09/2017
<i>Description: 737-55A1097 TBL 1.4: CHORD INSPECTION, ALERT SERVICE BULLETIN PART 2: HORIZONTAL STABILIZER IDENTIFICATION PLATE INSPECTION (FOR PRODUCTION HORIZONTAL STABILIZER NOT EXCHANGED AND SERIAL NUMBER UNKNOWN) (GROUP 1)</i>				
80-4-Maintenance	1999M.2A.80-4	5093973	12/12/2016	03/09/2017 03/09/2017
<i>Description: 737-55A1097 TBL 1.5: PERFORM STABILIZERS - HORIZONTAL STABILIZER - REAR SPAR UPPER CHORD INSPECTION, ALERT SERVICE BULLETIN OPTION 1: MAINTENANCE RECORDS TO FIND THE ORIGINAL DELIVERED AIRPLANE FOR THE HORIZONTAL STABILIZER OR OPTION 2: HORIZONTAL STABILIZER IDENTIFICATION PLATE INSPECTION (FOR ANY HORIZONTAL STABILIZER EXCHANGED AND INSTALLED HORIZONTAL STABILIZER SERIAL NUMBER UNKNOWN) (GROUP 1)</i>				
80-5-Maintenance	1999M.2A.80-5	5093974	12/12/2016	08/14/2017 08/14/2017
<i>Description: 737-55A1097 TBL 1.7: CHORD INSPECTION, ALERT SERVICE BULLETIN HORIZONTAL STABILIZER IDENTIFICATION PLATE INSPECTION (IF HORIZONTAL STABILIZER IS FROM AIRPLANE LINE NUMBER 379-1117, 1119-1782, 1784-2504, OR 2506-4484 OR FROM UNKNOWN AIRPLANE) (GROUP 1)</i>				
80-6-Maintenance	1999M.2A.80-6	5093975	12/12/2016	04/04/2017 04/04/2017
<i>Description: 737-SL-53-064: MISSING FASTNERS COMMON TO BS 360 SHEAR TIE BETWEEN STRINGER 14R AND STRINGER 15R, SERVICE LETTER</i>				
80-8-Maintenance	1999M.2A.80-8	5093976	12/12/2016	04/19/2017 04/19/2017
<i>Description: EASA 2014-0142 R1 (1): ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS</i>				
80-9-Maintenance	1999M.2A.80-9	5093977	12/12/2016	05/10/2017 05/10/2017
<i>Description: EASA 2016-0024 PARA (1): INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART</i>				
80-10-Maintenance	1999M.2A.80-10	5093978	12/12/2016	05/10/2017 05/10/2017



Work Order Detail

Project: 1999M
 Aircraft: 737 - 32806
 Repair Station: 166-CAY-AMO-20

Task Card #	Task ID	Opened	RTS	Closed
<i>Description:</i> EASA 2016-0024 PARA (2.1);REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2				
80-11-Maintenance	1999M.2A.80-11	5093979	12/12/2016	01/11/2018 01/12/2018
<i>Description:</i> EASA 2016-0024 PARA (2.3) REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1				
80-12-Maintenance	1999M.2A.80-12	5093980	12/12/2016	03/27/2017 03/27/2017
<i>Description:</i> FAA 2006-21-01 PART 1: FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - MEASURE THE FREEPLAY OF BOTH AILERON CONTROL BALANCE TABS				
80-13-Maintenance	1999M.2A.80-13	5093981	12/12/2016	04/14/2017 04/14/2017
<i>Description:</i> FAA 2006-21-01 PART 2: FLIGHT CONTROLS - AILERON AND AILERON TRIM CONTROL SYSTEM - REPETATIVE LUBRICATION				
80-17-Maintenance	1999M.2A.80-17	5093997	12/12/2016	06/06/2018 06/07/2018
<i>Description:</i> FAA 2013-02-05 PARA (G): INSTALL INSTRUMENTS - TO PREVENT FAILURE OF THE FLIGHTCREW TO RECOGNIZE AND REACT TO A VALID CABIN ALTITUDE WARNING HORN TWO WARNING LEVEL INDICATOR LIGHTS ON EACH OF THE P1-3 AND P3-1 INSTRUMENT PANELS IN THE FLIGHT COMPARTMENT, AND, AS APPLICABLE, REPLACE THE EXISTING P5-16 AND P5-10 PANELS				
80-18-Maintenance	1999M.2A.80-18	5093998	12/12/2016	06/04/2018 06/05/2018
<i>Description:</i> FAA 2013-08-01 DETECT AND CORRECT DAMAGE TO THE FIRE SEALS				
80-19-Maintenance	1999M.2A.80-19	5093999	12/12/2016	04/20/2017 04/20/2017
<i>Description:</i> FAA 2015-21-10 FUEL - REVISE THE MAINTENANCE OR INSPECTION PROGRAM				
80-20-Maintenance	1999M.2A.80-20	5094000	12/12/2016	01/08/2018 01/09/2018
<i>Description:</i> FAA 2016-11-20 PARA (G) INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUME SEAL IN ACCORDANCE WITH B/E AEROSPACE SB 119003-35-011 REV.000.				
Count: 17			17	16
Task Card: Service Check		Drawing: N/A	12/12/2016	06/06/2018
<i>Description:</i> Service Check				
80-Maintenance	1999M.1E.80	5094001	12/12/2016	06/05/2018 06/06/2018
<i>Description:</i> 05000: SERVICE CHECK COMPLETED.				
80-1-Maintenance	1999M.1E.80-1	5094002	12/12/2016	04/05/2017 04/05/2017
<i>Description:</i> 25-250-00: VISUALLY CHECK ALL EMERGENCY ESCAPE SLIDE PRESSURE BOTTLES FOR PROPER PRESSURE				
Count: 2			2	2
Task Card: Service Check.80-1.NR-1		Drawing: N/A	03/23/2017	04/12/2017
<i>Description:</i> AILERON POWER OUTPUT LEVER WILL NOT TAKE GREASE.				
80-2-Maintenance	1999M.Service Check.80-1.NR-1.80-2	5097658	03/23/2017	04/12/2017 04/12/2017
<i>Description:</i> AILERON POWER OUTPUT LEVER WILL NOT TAKE GREASE.				
Count: 1			1	1