

**Bell Helicopter Miami, Inc.**  
 2011 South Perimeter Road, Suite L  
 Fort Lauderdale, Florida 33309  
 Phone: (954)-491-5071, Fax: (954)-771-4692, Email: [REDACTED]



**Hyperion Air**  
 Mr. Larry Visoski

**Tuesday, April 03, 2018**  
 Make / Model: BELL / 430  
 Serial Number: 49078  
 Registration: N331JE  
 Total Time: -

| Item                  | Description  | Parts              | Labor              |
|-----------------------|--|--------------------|--------------------|
| 1                     | Cost estimate to remove and replace pilot side heated windshield with new. | \$32,818.00        | \$10,764.00        |
| 2                     | Estimated Consumables / Hazardous Waste                                    | \$980.00           | \$0.00             |
| 3                     | Estimated Freight Charge   | \$450.00           | \$0.00             |
| <b>SUB-TOTAL</b>      |  | <b>\$34,248.00</b> | <b>\$10,764.00</b> |
| <b>ESTIMATE TOTAL</b> |  | <b>\$45,012.00</b> |                    |

*Note: This is a cost estimate for the above statement of work and should be used for budgetary purposes only. All work will be invoiced on a time and materials basis. This estimate is subject to records verification and aircraft condition at time of service. This estimate does not include any hidden damages and or discrepancies found. Any additional work will be quoted on a time and materials basis. This estimate is valid for 30 days and subject to price increase.*