



Maintenance Due List with Related FOR SELECTED ITEMS ONLY

Sort By ATA Code

Include only mandatory service information not yet accomplished

Projected Through:

9882.8 Hours TT
4502 Landings

09 May 2019 Date
7595 APU Hours
30 APU Cycles

N120JE

Hours 9807.8
Landings 4457
Hour Meter 9807.8

Phone: [REDACTED]

Log Date -- 26 Jan 2019

Analyst: Richard Reynolds
Phone: [REDACTED]

Aircraft Make Gulfstream
Aircraft Model GIV
Aircraft Serial No. 1085
Airworthiness Date 16 Dec 1988
Regulation 91.409f3

COMPONENT TIMES

Position	Logbook	Description	Serial Number	Total Time	Total Cycles	TSO	CSO
1	Engine	Rolls Royce TAY611-8 (GIV)	16291	9696.9	4402	2574.0	1144
2	Engine	Rolls Royce TAY611-8 (GIV)	16292	9716.8	4408	2574.0	1144
1	APU	Honeywell GTCP36-150[G]	P-465-C	7535.0	0		

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number	Serial Number	TSNHR	TSNLD	TSNMO	TSOHR	TSOLD							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref	Event Category		@= Adjustments										

245051	AC / DC Power Distribution System - Functional Test								9208.4 4232					8.0
Airframe							36 MOS	25 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM	Functional/Ops Test (F)												

270221	Stall Barrier Dump Valve - Operational Test								9208.4 4232					
Airframe							36 MOS	09 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM	Functional/Ops Test (O)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	291057	Airframe	Combined / Flight Hydraulic System Reservoir - Filling Procedures		1.00
Mandatory Related Codes Totals:					1.00

Code	Description							Frequency (**=Initial)	C/W Hrs/Cyc/Dt	Next Due (* =Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

272038	Rudder Pedals - Lubrication								9208.4 4232						1.0
Airframe								36 MOS	11 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Lubrication/Serviceing (L)												

275009	Flap Actuator Yoke (Left Inboard) - Inspection								9208.4 4232						1.0
Airframe								36 MOS	09 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	275003	Airframe	Flap (Left) - Removal / Installation				\$0.00	4.00
						Mandatory Related Codes Totals:	\$0.00	4.00

275010	Flap Actuator Yoke (Right Inboard) - Inspection								9208.4 4232						1.0
Airframe								36 MOS	09 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	275004	Airframe	Flap (Right) - Removal / Installation				\$0.00	4.00
						Mandatory Related Codes Totals:	\$0.00	4.00

275011	Flap Actuator Yoke (Left Outboard) - Inspection								9208.4 4232						1.0
Airframe								36 MOS	09 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	275003	Airframe	Flap (Left) - Removal / Installation				\$0.00	4.00
						Mandatory Related Codes Totals:	\$0.00	4.00

275012	Flap Actuator Yoke (Right Outboard) - Inspection								9208.4 4232						1.0
Airframe								36 MOS	09 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description				Parts Cost	Labor Hours
	275004	Airframe	Flap (Right) - Removal / Installation				\$0.00	4.00
						Mandatory Related Codes Totals:	\$0.00	4.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)		
	MM Ref		Event Category		@= Adjustments									

275027 Flap Actuator Bushing (Left) - Lubrication 9208.4 2.0
 4232
 Airframe 36 MOS 10 Mar 31 Mar 51 Days
 2016 2019
 GIV AMM Lubrication/Serviceing (L)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
275003	Airframe	Flap (Left) - Removal / Installation	\$0.00	4.00
275005	Airframe	Inboard Flap Actuator (Left) - Removal / Installation	\$0.00	4.00
275007	Airframe	Outboard Flap Actuator (Left) - Removal / Installation	\$0.00	4.00
Mandatory Related Codes Totals:			\$0.00	12.00

275028 Flap Actuator Bushing (Right) - Lubrication 9208.4 2.0
 4232
 Airframe 36 MOS 10 Mar 31 Mar 51 Days
 2016 2019
 GIV AMM Lubrication/Serviceing (L)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
275004	Airframe	Flap (Right) - Removal / Installation	\$0.00	4.00
275006	Airframe	Inboard Flap Actuator (Right) - Removal / Installation	\$153,156.00	4.00
275008	Airframe	Outboard Flap Actuator (Right) - Removal / Installation	\$182,188.50	4.00
Mandatory Related Codes Totals:			\$335,344.50	12.00

280005 Fuel Control System - Functional Test 9208.4 6.0
 4232
 Airframe 36 MOS 25 Mar 31 Mar 51 Days
 2016 2019
 GIV AMM Functional/Ops Test (F)

320004 Main Landing Gear (Left) - Lubrication 9803.6 1.0
 4453
 Airframe 4 MOS 03 Dec 30 Apr 81 Days
 2018 2019
 GIV AMM Lubrication/Serviceing (L)

320005 Main Landing Gear (Right) - Lubrication 9803.6 1.0
 4453
 Airframe 4 MOS 03 Dec 30 Apr 81 Days
 2018 2019
 GIV AMM Lubrication/Serviceing (L)

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs	
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO								
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type				Ops Number(s)			
	MM Ref		Event Category		@= Adjustments										
320006	Nose Gear - Lubrication								9803.6 4453						1.0
Airframe								4 MOS	03 Dec 2018	30 Apr 2019		81 Days			
	GIV AMM		Lubrication/Serviceing (L)												
351007	Crew Oxygen System (Observer) - Operational Test								9735.6 4425						0.5
Airframe								12 MOS	04 Apr 2018	30 Apr 2019		81 Days			
			Functional/Ops Test (O)												
532007	Forward Cabin Compartment Below Floor - Inspection								9208.4 4232						8.0
Airframe								36 MOS	17 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												
532009	Midcabin Compartment Below Floor - Inspection								9208.4 4232						10.0
Airframe								36 MOS	17 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												
532011	Aft Cabin Compartment Below Floor - Inspection								9528.6 4352						7.0
Airframe								24 MOS	08 Apr 2017	30 Apr 2019*		81 Days			
	GIV AMM		Special Inspection (R)												
551023	Horizontal Stabilizer / Elevator (Interior / Exterior) (Left) - Inspection								9208.4 4232						20.0
Airframe								36 MOS	11 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									

551024	Horizontal Stabilizer / Elevator (Interior / Exterior) (Right) - Inspection								9208.4 4232						20.0
Airframe								36 MOS	11 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

553007	Vertical Stabilizer / Rudder (Internal) - Inspection								9208.4 4232						40.0
Airframe								36 MOS	15 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	551001	Airframe	Horizontal Stabilizer - Removal / Installation	\$0.00	100.00
Mandatory Related Codes Totals:				\$0.00	100.00

571011	Wing Front Beam Hi-Lite Collars (Left) - Inspection								9208.4 4232						22.0
Airframe								36 MOS	10 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	280018	Airframe	Fuel Tank (Left) - Leak Check		4.00
	574005	Airframe	Wing Leading Edge (Left Inboard) - Removal / Installation	\$0.00	10.00
	574011	Airframe	Wing Leading Edge (Left Center) - Removal / Installation	\$0.00	10.00
	574017	Airframe	Wing Leading Edge (Left Outboard) - Removal / Installation	\$0.00	10.00
Mandatory Related Codes Totals:				\$0.00	34.00

571012	Wing Front Beam Hi-Lite Collars (Right) - Inspection								9208.4 4232						22.0
Airframe								36 MOS	10 Mar 2016	31 Mar 2019		51 Days			
	GIV AMM		Special Inspection (R)												

Mandatory Related Codes:	Code	Logbook	Description	Parts Cost	Labor Hours
	280019	Airframe	Fuel Tank (Right) - Leak Check		4.00
	574006	Airframe	Wing Leading Edge (Right Inboard) - Removal / Installation	\$0.00	10.00
	574012	Airframe	Wing Leading Edge (Right Center) - Removal / Installation	\$0.00	10.00
	574018	Airframe	Wing Leading Edge (Right Outboard) - Removal / Installation	\$0.00	10.00
Mandatory Related Codes Totals:				\$0.00	34.00

Code	Description							Frequency (* = Initial)	C/W Hrs/Cyc/Dt	Next Due (* = Adj)	Next Due Airframe	Time Remains	Approx Price	Code Manhrs
	Part Number		Serial Number		TSNHR	TSNLD	TSNMO							
Logbook	TAG	MOD	H/W	S/W	TSOHR	TSOLD	TSOMO	Date Type			Ops Number(s)			
	MM Ref		Event Category		@= Adjustments									

571025 Wing Tank Interior (Left) - Inspection 9208.4 28.0
 4232
 Airframe 36 MOS 18 Mar 31 Mar 51 Days
 2016 2019
 GIV AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
280010	Airframe	Defueling Procedures		4.00
280018	Airframe	Fuel Tank (Left) - Leak Check		4.00
284135	Airframe	Fuel Quantity Probe No. 1 (Left) - Removal / Installation	\$2,010.91	2.00
571003	Airframe	Wing Fasteners Cadmium Plating Degradation - Check (Left)		28.00
Mandatory Related Codes Totals:			\$2,010.91	38.00

571026 Wing Tank Interior (Right) - Inspection 9208.4 28.0
 4232
 Airframe 36 MOS 15 Mar 31 Mar 51 Days
 2016 2019
 GIV AMM Special Inspection (R)

Mandatory Related Codes:

Code	Logbook	Description	Parts Cost	Labor Hours
280010	Airframe	Defueling Procedures		4.00
280019	Airframe	Fuel Tank (Right) - Leak Check		4.00
284136	Airframe	Fuel Quantity Probe No. 1 (Right) - Removal / Installation	\$2,010.91	2.00
571004	Airframe	Wing Fasteners Cadmium Plating Degradation - Check (Right)		28.00
Mandatory Related Codes Totals:			\$2,010.91	38.00

TOTAL APPROXIMATE PRICE AND CODE MANHOURS FOR ATAs 05-96 \$0.00 539.50

TOTAL APPROXIMATE PRICE AND CODE MANHOURS FOR ATAs 97-99 \$0.00 0.00