

**From:** [REDACTED] <[REDACTED]>

**To:** Jeffrey Epstein <jeevacation@gmail.com>

**Cc:** Rich Kahn <[REDACTED]>, Anna <[REDACTED]>

**Subject:** GSJ Heli Pad

**Date:** Thu, 27 Oct 2016 14:42:28 +0000

**Attachments:** GSJ\_Heli\_Pad\_EB.JPG; GSJ\_Heli\_Pad\_EB2.JPG

---

Jeffrey

Attached photo's of Heli Pad for your reference

as you can see there are multiple issues with finish.

1. Heavy Material who supplied the concrete, screwed up the recipe by adding too much retarder to the mix.
2. Not enough mix to finish pour.

I have spoken to EB this morning, they will be forwarding an outline on how they propose to address the above issues

I would recommend we self perform Hut Pad and find another contractor to erect Hut when we have the go ahead

regards

[REDACTED]

[REDACTED]