

From: Lvjet <[REDACTED]>
To: jeevacation@gmail.com
Subject: G550
Date: Fri, 18 Mar 2016 03:50:43 +0000

Jeffrey,

Ali's spec sheet is vague, need more details if possible. I don't see 5112 having HAPP for avionics, don't see the engines on Corp Care.,

Differences

AvPro 5017

Year Build 2003 C of A / in service 2004

Enrolled Corporate Care, Engines Declared Task orientated Maintenance program, On Condition., (I'll verify with Kathleen what this means).

HAPP Honeywell Avionics Protection Plan

Sythic Vision, Yes

SAT TV

Xm Weather option

Due 144 month Mid 2016

ConCave Side window panels

unsure if APU is on MSP Mx Service Plan

Perlman 5112 (may have these options, I don't see in Spec sheet Ali sent to me)

Year build 2006 in service 9/2006

No HAPP in Spec Sheet

No Corp Care

Don't see mention of Snthic Vision

No Mention of Wx Weather

Due 144 Month in 2 years

unsure if APU is MSP Mx Service Plan