

**From:** LAllenby <[REDACTED]>  
**To:** "jeffrey E." <jeevacation@gmail.com>  
**Cc:** NYC - Richard Kahn <[REDACTED]>, "Allenby, Leighton" <[REDACTED]>  
**Subject:** Re: LSJ Plate Work  
**Date:** Mon, 03 Aug 2015 13:59:57 +0000

---

Yes,  
I discussed this with Gene at length and this is our only option. Can they proceed?

Leighton Allenby  
Director of Properties  
[REDACTED]  
[REDACTED]

On Aug 3, 2015, at 9:39 AM, jeffrey E. <[jeevacation@gmail.com](mailto:jeevacation@gmail.com)> wrote:

is that what you are reccomending?

On Mon, Aug 3, 2015 at 9:38 AM, LAllenby <[REDACTED]> wrote:

Good Morning Anna-  
Upon reviewing and inspecting the inside of the compartments, forward of the engine room, we have come up with a quotation for repairing all the "wasted" plate. Approximately 160 square feet of plate has to be cut out and replaced. The square footage equals 848LBS x \$45 per pound the total would be \$38,160 (This price includes all labor and material). We will also have to remove both keel coolers due to their location with the plate that has to be cut out. We will also have to fabricate two new boxes in which they sit and then remount these boxes once the new plate is welded into place. The price for this is \$5850 includes labor and material. Two water tight bulkheads are also compromised and several areas will need to be "cropped" out and replaced. Labor and materials is \$3380. We will also "plug weld" 12 more additional areas that have deteriorated and need to be addressed. These two compartments have been inspected by both Gabriel, the project manager, and Bosco. In addition, the emergency bilge pump system needs to be renewed and it is our recommendation to have Bosco undertake this job. Please note that we have not charged any additional lay days and will continue not to. The areas that need to be cut out and replaced are very confined and difficult to work in. With the savings on lay days it is over \$3500 so we will not be able to move on our final quotation. I have also attached a few pictures.....

Total for labor and material.....\$47,390

Leighton Allenby  
Director of Properties

On Aug 3, 2015, at 9:21 AM, jeffrey E. <[jeevacation@gmail.com](mailto:jeevacation@gmail.com)> wrote:

that is only the problem,, is there a proposal for solution, ? please try to add action steps to issues, telling me only that there is a problem is time consumig

On Mon, Aug 3, 2015 at 9:13 AM, LAllenby <[REDACTED]> wrote:

The hull is compromised - rusted through in areas on his map.

Leighton Allenby  
Director of Properties

On Aug 3, 2015, at 9:09 AM, Richard Kahn <[REDACTED]> wrote:

Bosco email off point. Disappointed with bosco on every step of this barge overhaul and concerned he is not best person to care for and operate moving forward. To many surprises and then an excuse and disclaimer each time. As I am sure you will say we have no choice I wanted to confirm we shall proceed with latest Change order for 47,390

Please advise  
Thank you

Sent from my iPhone

Begin forwarded message:

**From:** Leighton Allenby <[REDACTED]>  
**Date:** July 31, 2015 at 3:49:39 PM EDT  
**To:** Richard Kahn <[REDACTED]>  
**Subject:** Fwd: LSJ Plate Work

FYI

Leighton Allenby  
Director of Properties

----- Forwarded message -----

From: **Bill Hague** <[REDACTED]>

Date: Fri, Jul 31, 2015 at 3:09 PM

Subject: RE: LSJ Plate Work

To: [REDACTED], [REDACTED]

Understood.

Gabe, one of his hands and I went over all the remaining cavities/compartments and found only a half dozen minor and repairable spots in the hull plating. The bulkheads show staggered severe pits/holes that also can be dealt with reasonably.

I agree about the surveyor.

Also, your email ended up in my junk mail. I have added you to my contacts to avoid that in the future. I regret the delay in responding.

For your information, I contacted a Navy colleague and asked for the present contractors information concerning construction of the latest Navy LCM8's

I did this to quantify your question about replacement costs of the Barge. I was Referred to Kvichak Marine in Seattle. Art Parker there said my guess of 2 million is likely low. A build that heavy is likely a 3 to 4 million dollar job in his opinion. His company is bidding on the Caiman design 60 and 70 for the USN.

Good Day

Boscoe

---

From: [REDACTED]

Date: Fri, 31 Jul 2015 12:22:37 -0400

Subject: Re: LSJ Plate Work

To: [jeevacation@gmail.com](mailto:jeevacation@gmail.com); [REDACTED]

CC: [REDACTED]; [REDACTED]

Hello Anna and Boscoe,

Can you please go over every inch of Big D and determine when the bleeding to Mr. Epstein is going to stop.

I know I am coming in late in the last quarter but there should have been a survey recommended so this additional work outside of the original budget didn't occur and a 10 to 15% mic added for unforeseen. I see no other option but to

recommend to Mr. Epstein and Richard that this

work be completed. Please thank Gabriel for the savings on the lay days

**Mr. Epstein and Richard,  
I this additional \$47,390 expenditure approved?**

**Best,  
Leighton**

Good Morning Anna-

Upon reviewing and inspecting the inside of the compartments, forward of the engine room, we have come up with a quotation

for repairing all the "wasted" plate. Approximately 160 square feet of plate has to be cut out and replaced. The square footage equals

848LBS x \$45 per pound the total would be \$38,160 (This price includes all labor and material). We will also have to remove both keel

coolers due to their location with the plate that has to be cut out. We will also have to fabricate two new boxes in which they sit and

then remount these boxes once the new plate is welded into place. The price for this is \$5850 includes labor and material. Two water

tight bulkheads are also compromised and several areas will need to be "cropped" out and replaced. Labor and materials is \$3380.

We will also "plug weld" 12 more additional areas that have deteriorated and need to be addressed.

These two compartments have

been inspected by both Gabriel, the project manager, and Bosco. In addition, the emergency bilge pump system needs to be renewed

and it is our recommendation to have Bosco undertake this job. Please note that we have not charged any additional lay days and

will continue not to. The areas that need to be cut out and replaced are very confined and difficult to work in. With the savings on lay

days it is over \$3500 so we will not be able to move on our final quotation. I have also attached a few pictures.....

Total for labor and material.....\$47,390

Leighton Allenby

Director of Properties

[REDACTED]

On Fri, Jul 31, 2015 at 11:43 AM, Ann Rodriquez <[REDACTED]> wrote:

Ann R.

Begin forwarded message:

**From:** gene kral <[genekralusvi@yahoo.com](mailto:genekralusvi@yahoo.com)>

**Date:** July 31, 2015 at 11:19:19 AM AST

**To:** Ann Rodriquez <[REDACTED]>


**Subject:** Fw: LSJ Plate Work

**Reply-To:** gene kral <[genekralusvi@yahoo.com](mailto:genekralusvi@yahoo.com)>


Good Morning Anna-

Upon reviewing and inspecting the inside of the compartments, forward of the engine room, we have come up with a quotation for repairing all the "wasted" plate. Approximately 160 square feet of plate has to be cut out and replaced. The square footage equals 848LBS x \$45 per pound the total would be \$38,160 (This price includes all labor and material). We will also have to remove both keel coolers due to their location with the plate that has to be cut out. We will also have to fabricate two new boxes in which they sit and then remount these boxes once the new plate is welded into place. The price for this is \$5850 includes labor and material. Two water tight bulkheads are also compromised and several areas will need to be "cropped" out and replaced. Labor and materials is \$3380. We will also "plug weld" 12 more additional areas that have deteriorated and need to be addressed. These two compartments have been inspected by both Gabriel, the project manager, and Bosco. In addition, the emergency bilge pump system needs to be renewed and it is our recommendation to have Bosco undertake this job. Please note that we have not charged any additional lay days and will continue not to. The areas that need to be cut out and replaced are very confined and difficult to work in. With the savings on lay days it is over \$3500 so we will not be able to move on our final quotation. I have also attached a few pictures.....


Total for labor and material.....\$47,390



<resized2.jpg>



<resized5.jpg>



<resized7.jpg><resized8.jpg>



<resized10.jpg>

<resized12.jpg>



<resized8.jpg>

<resized2.jpg>

<resized5.jpg>

<resized7.jpg>



<resized12.jpg>

<resized10.jpg>



--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved