

From: Larry Visoski <[REDACTED]>

To: Je vacation <jeevacation@gmail.com>

Subject: Flagpole

Date: Wed, 25 Feb 2015 23:28:27 +0000

Found blown tweeter on North side of pool, speaker sounds flat,. Tried other speaker to prove its speaker, Jermaine indicated Speaker fell down hill.,

Found tweeter wire not connected to amp.,

Reduced Gain on Mid amps,. Was overpowering tweeters.,

Buzz in system could main ground to Cabana power,. Since buzz is not reduced with volume,. Only amp gain reduces buzz.,

I think we should replace the entire blown speaker, since it rolled down the hill?

Let me know if it sounds any better?

Thx

Sent from my iPhone