

From: Darren Indyke <[REDACTED]>

To: Jeffrey Epstein <jeevacation@gmail.com>

Subject: Fwd: Found Leak-pics

Date: Tue, 11 Jan 2011 19:50:55 +0000

Inline-Images: IMG_20110111_115915.jpg; 039.JPG; 038.JPG

Sent from my iPhone

Begin forwarded message:

From: Wendy Martinez <[REDACTED]>

Date: January 11, 2011 2:17:11 PM EST

To: Darren Indyke <[REDACTED]>

Subject: Fwd: Found Leak-pics

----- Forwarded message -----

From: Wendy Martinez <[REDACTED]>

Date: Tue, Jan 11, 2011 at 12:16 PM

Subject: Found Leak-pics

To: Karen <[REDACTED]>

Here are pics of the location of the leak and the actual leak inside the wall from the camera. It is the top of the water hammer arrestor that is split. Can be fixed by Marty cutting the pipe and replacing the cap. New insulation (and more of it) is recommended by Marty.

The wall and insulation are soaked and with our frigid temps we are concerned that more will be damaged with the exposure. The air inside the wall is reading 30 degrees with the outside temp in the Estancia reading 18 - 23 degrees.

A 2'x3' hole will need to be put in the wall. Marty will be gone next week but is available this week to fix it.

Thank you

Wendy



