

From: Jeffrey Epstein <jeevacation@gmail.com>
To: Brice Gordon <[REDACTED]>
Subject: Re: Heating coil inspection
Date: Wed, 05 Jun 2013 16:36:51 +0000

ok

On Wed, Jun 5, 2013 at 9:41 AM, Brice Gordon <[REDACTED]> wrote:
Jeffrey

attached photo's of the #3 heating coil that services the living room gallery/hallway, Main house and an estimate to inspect remaining coils from JBH, cost \$1214.91
Estimate includes inspection (one man) and log/report with pictures
The #3 coil developed a split a couple weeks ago, flooding the number one basement, fortunately minor damage to unit occurred
JBH inspected and it appears at some point the coil has frozen weakening the copper pipe, which after time split.
The damage was probably sustained when the property lost power for over a week during the winter 2010/2011

The main living room unit, which is adjacent to #3 also show signs of freeze damage, this coil has been isolated
please note these coils are under pressure and if one should burst during the night, damage could be substantial

can we proceed

--
Brice Gordon

[REDACTED]
[REDACTED]

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein
Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved