

From: Larry Visoski <[REDACTED]>
To: Je vacation <jeevacation@gmail.com>
Cc: Rich Kahn <[REDACTED]>
Subject: G550 update
Date: Fri, 11 Jan 2019 17:48:32 +0000

Jeffrey

The G550 is working normal now,

Pete disconnected the Left Battery, turned on the external battery switch, and the R/H battery came on line normal, he proceeded to hook up the L/H battery, and all battery's stayed on line,.

He Shut down the plane completely, and turned both battery's on,,, all was normal,

Only a guess, since you recommended to look at the battery contacts, I'm guessing, the plane needed to energize or Pull a Battery relay closed, after the install of the New Battery Control Relay,

Westfield is still going to come to Teterboro to review all what Pete troubleshot, to make sure we are good,.

Dave and I will Arrive Newark tonight at 8pm,..

All is a go for LSJ tomorrow at this time .,

Let me know when you want wheels up to LSJ tomorrow?

Thx

Larry

Sent from my iPad