

From: Kyle reavis <[REDACTED]>
To: J <jeevacation@gmail.com>
Cc: Richard Kahn <[REDACTED]>
Subject: Re: ???????
Date: Fri, 11 Jan 2019 12:01:57 +0000

There was a drip I noticed coming out of the door frame 1.5 months ago and I got Brice to get Reefco to look at this unit. They came out the next day and told him it was fixed. This is news to me and I will set up Jays plaster crew to patch the wall as soon as the lines are replaced. Going now to look at this.

Kyle

On Thu, Jan 10, 2019 at 8:44 AM J <jeevacation@gmail.com> wrote:

From: LSJ GSJ <[REDACTED]>
Subject: Re: Cabana 4
Date: January 10, 2019 at 7:02:49 AM EST
To: Richard Kahn <[REDACTED]>
Cc: Stephanie Remington <[REDACTED]>, Brice Gordon <[REDACTED]>, [REDACTED]

Good Morning Rich

Cabana 4 is non operational

Found a slow leak in refrigeration lines of the mini split AC, we have opened the wall up, framing is saturated, will need to be dried out, before repair can be completed

Cabana 2 will be used for guests, everything is working

Thanks

Karen

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved