

From: Richard Kahn <[REDACTED]>
To: Jeffrey Epstein <jeevacation@gmail.com>
Subject: Fwd: LSJ
Date: Tue, 08 Jan 2019 23:56:27 +0000

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue, 4th Floor
New York, NY 10022
tel [REDACTED]
fax [REDACTED]
cell [REDACTED]

Begin forwarded message:

From: <[REDACTED]>
Subject: LSJ
Date: January 8, 2019 at 3:43:33 PM EST
To: "Richard Kahn" <[REDACTED]>

Richard:

Photo 9039 is a leak originating from one of the two PX units on the skid. This leak has been there since before Gemini got involved. We wanted to complete all the other upgrades to the unit before taking this one on.

Photo 9040 is a leak from the new cartridge filter housing. We reported this at the time of commissioning. We filed a warranty claim with the manufacturer on behalf of LSJ but they were late in getting the new seal sent to us. We had planned on changing this seal when we were last on island but the seal showed up a week later. We will be addressing this leak when we return to install the new intake pump station the week of January 21st.

Do you have any update on the status of the new fiber optic cable? This needs to be in place and terminated before we get there to permit the control system to be finalized.

Dean

-----Original Message-----
From: Richard Kahn <[REDACTED]>

Sent: Tuesday, January 8, 2019 12:23 PM

To: [REDACTED]

Subject:

Good afternoon. I visited LSJ yesterday and noticed a few spots with water leaking. Can you please explain so I can understand better. Thank you.